

04057763

PERIODIC MANDATORY VEHICLE
INSPECTION CERTIFICATE

Manitoba

W06-1

Vehicle Safety
Box 45064 Regent Postal Out
Winnipeg, MB, R2C 5C7
1-204-985-0920Manitoba
C050645

Date Inspection Started DAY 10 MO. 11 YR. 25	Station Number A1531411	Station Name 5496633 Manitoba	City Winnipeg
Date Inspection Completed DAY 11 MO. 11 YR. 25	Mechanic Number M171712	Mechanic Signature <i>[Signature]</i>	Station Phone Number 204-999-3179
Inspection Expiry Date DAY 31 MO. 11 YR. 26	Vehicle Owner Paragon Express Holdings Ltd.		
	Address 95 Amberstone Road Winnipeg MB R2P1K9		
☒ Pass/Safe Vehicle	Licence Number NWX 1 P 1 A Fed	NSC #	Odometer Reading 776916
☒ Fail/Unsafe Vehicle	Vehicle Identification Number 11X1P1B1D1P191X1L1D161618151419	Make Peterbilt	Model 579
☒ Fail/Hazardous	☒ Confirmed legible Vehicle Identification Number on vehicle	Year 2020	Unit #

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

Truck ☐ GWR KGS ☒ Truck Tractor ☐ Trailer ☐ Semi-Trailer ☐ Bus ☐ School Bus ☐ Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section																																																																							
X		Section 1 - Power Train: Defects (if any)																																																																							
X		Section 2 Suspension: Defects (if any)																																																																							
X	XX	Section 3 - Brake Systems: 3H (3A) Defects (if any) Circle Brake Type 15(E) All Drive Brake Shoe Lining thickness 2/16" 15(F) All Drive Brake Drum diameter 16620" 15(F) RFD wheel Seal Leaking																																																																							
X		Section 4 - Steering: Defects (if any)																																																																							
X		Section 5 - Instruments & Auxiliary Equipment: Defects (if any) 1(B) Fire Extinguisher Empty																																																																							
X	X	Section 6 - Lamps: Defects (if any) 1(G) Hazard Warning Lamps not working 1(L) License Plate light not working																																																																							
X	X	Section 7 - Electrical System: Defects (if any) 2(A) All Battery cables corrosion																																																																							
X	X	Section 8 - Body: Defects (if any) 13(B) Front Windshield crack																																																																							
X	X	Section 9 - Tire & Wheel: Defects (if any) 4(A) check all tire Air Pressure low																																																																							
		<table border="1"> <thead> <tr> <th rowspan="2">Axle</th> <th colspan="4">Tread Depth</th> <th colspan="4">Air Pressure</th> </tr> <tr> <th colspan="2">Initial</th> <th colspan="2">Corrected</th> <th colspan="2">Initial PSI</th> <th colspan="2">Corrected PSI</th> </tr> <tr> <th></th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>8</td> <td>8</td> <td></td> <td></td> <td>95</td> <td>95</td> <td>100</td> <td>100</td> </tr> <tr> <td>2</td> <td>12</td> <td>12</td> <td>8</td> <td>12</td> <td>90</td> <td>90</td> <td>90</td> <td>80</td> </tr> <tr> <td>3</td> <td>12</td> <td>12</td> <td>12</td> <td>12</td> <td>80</td> <td>90</td> <td>90</td> <td>85</td> </tr> <tr> <td>4</td> <td>1</td> <td>1</td> <td>1</td> <td>1</td> <td>1</td> <td>1</td> <td>1</td> <td>1</td> </tr> <tr> <td>5</td> <td>1</td> <td>1</td> <td>1</td> <td>1</td> <td>1</td> <td>1</td> <td>1</td> <td>1</td> </tr> </tbody> </table>	Axle	Tread Depth				Air Pressure				Initial		Corrected		Initial PSI		Corrected PSI			L	R	L	R	L	R	L	R	1	8	8			95	95	100	100	2	12	12	8	12	90	90	90	80	3	12	12	12	12	80	90	90	85	4	1	1	1	1	1	1	1	1	5	1	1	1	1	1	1	1	1
Axle	Tread Depth				Air Pressure																																																																				
	Initial		Corrected		Initial PSI		Corrected PSI																																																																		
	L	R	L	R	L	R	L	R																																																																	
1	8	8			95	95	100	100																																																																	
2	12	12	8	12	90	90	90	80																																																																	
3	12	12	12	12	80	90	90	85																																																																	
4	1	1	1	1	1	1	1	1																																																																	
5	1	1	1	1	1	1	1	1																																																																	
X		Section 10 - Coupling Devices: Defects (if any)																																																																							

- THIS INSPECTION IS NOT A WARRANTY -
This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks: All Repair Done by Anytime Truck and Trailer

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: *Chirpless Kumar*

Date: 10/11/25