Service History Customer Report
Equipment No. WTR43

Description: Mitsubishi FN Rigid Water Cart

Make: Mitsubishi

Model: FN

Serial No.: JLFFN62FK0KJ10026

Registration: XB37PY

Registration Expiry: 30/04/2027

Date	Job Number	Eng. Hours	Job Description
04/03/2024	3	6452.00	B SERVICE AND REAR AXLE MUDGUARD REPAIR
			Comment: COMPLETED 250 HR B SERVICE AND ADJUSTED REAR RUBBER MUDGUARDS TO PREVENT FROM RUBBING ON TYRES.
13/03/2024	102	6452.00	RECTIFY OVERHEATING AND TRANSMISSION OIL LEAK
			Comment: RGM TECHNICIANS, REPLACE ADBLUE PUMP CONTROLER REMOVED EXHAUST MANIFOLD, MACHINED WARPAGE AND REFITTED TO ENGINE WITH NEW GASKETS AND STUDS REMOVED TRANSMISSION, SEPERATED TORQUE CONVERTOR, TORQUE CONVERTER OVERHAULED AT Heavy TRANSMISSION REPAIRS IN BRISBANE, NEW SEALS INSTALLED TO TRANSMISSION PUMP.
26/06/2024	952	6546.00	CARRY OUT DEFECT REPAIRS AS PER PRESTART BOOK
			Comment: REPLACED OLD UHF WITH NEW GME SET. DIAGNOSED AND REPAIRED A/C SYSTEM NOT GETTING COLD. DIAGNOSED AND RECTIFIED LEAKING ACTUATORS ON REAR SPRAYS. CHECK WIRING TO LH REAR TAILLIGHT ASSEMBLY (INTERMITTENTLY WORKING) CHECKED DRIVER SEAT OPERATION, LUBRICATED SLIDES AND BASE LOCKING MECHANISM. REMOVE AND REPLACED FOR 3 X SPRAYS. 27.06.24 - Service call to site (AG yard) to wash evaporator in water cart. Tested air conditioning operation. 27.06.24 - Service call to site to inspect aircon fault. Carried out tests and found evaporator blocked. Fit new UHF and test. Inspect light fault and source parts to repair.
16/07/2024	1128	6590.00	DEFECTS FROM OFF HIRE INSPECTION 16/07/24
			Comment: COMPLETED OFF HIRE INSPECTION. RECTIFIED ADBLUE LEAKING FROM SIGHT GUAGE ON ADBLUE TANK. ADJUSTED CAB LOCK DOWN ASSEMBLY. REPLACED STROBE LIGHT. WASHED, DETAILED AND GREASED MACHINE. COMPLETED ON HIRE INSPECTION. INSTALLED NEW WASH DOWN HOSE REEL AND PLUMBED IN WITH NEW FITTINGS.

Service History Customer Report
Equipment No. WTR43

Description: Mitsubishi FN Rigid Water Cart

Make: Mitsubishi

Model: FN

Serial No.: JLFFN62FK0KJ10026

Registration: XB37PY

Registration Expiry: 30/04/2027

			REMOVED WATER CANNON ROTATION MOTOR, CLEANED AND RESEALED. INSTALLED BACK ONTO CANNON AND TESTED CORRECT OPERATION. REPLACED REVERSE CAMERA AND MONTOR.
23/09/2024	3027	6590.00	DEFECTS FROM OFF HIRE 23/09/24
			Comment: COMPLETED OFF HIRE INSPECTION. REPLACED WHEEL CHOCKS. WASHED, DETAILED AND GREASED MACHINE. COMPLETED ON HIRE INSPECTION.
19/12/2024	4253	7028.00	CARRY OUT B SERVICE
			Comment: AG EQUIP COMPLETED B SERVICE. REPAIRED WATER FUEL SENSOR WIRING. REPAIRED RH FRONT WATER SPRAYER. FILLED AND TESTED OPERATION OF ALL VALVES - ALL OK.
20/12/2024	4265	7029.00	DEFECT REPAIRS FROM OFF HIRE INSPECTION 19.12.24
			Comment: COMPLETED OFF HIRE INSPECTION. REPAIRED CRACKED MUDGUARD BRACKET. REPLACED BLOWN HEADLIGHT BULB AND POLISHED HEADLIGHT LENSES. WASHED, DETAILED AND GREASED MACHINE. COMPLETED ON HIRE INSPECTION.
29/01/2025	4561	7038.00	DEFECTS FROM OFF HIRE INSPECTION 24/01/25
			Comment: COMPLETED OFF HIRE INSPECTION. REPLACED PUMP SEAL ON WATER TANK. REMOVED WATER PUMP, STRIPED AND INSPECTED. TEST OPERATION OF ALL SPRAYS. FOUND CANNON FAULTY. REPLACED CANNON MOTOR AND TESTED. INVESTIGATED ENGINE LIGHT ON. INSPECTED EXHAUST BRAKE LINKAGES (UNDER BOOST). TEST DROVE TO FAULT FIND SHIFT FAULT, ADJUSTED TRANS OIL LEVEL TO CORRECT HOT LEVEL - SLOW/HARSH IN TO 1ST GEAR. ONGOING INVESTIGATION. REMOVED IMPELLER HOUSING AND ADJUSTED TO SUIT PIPE WORK, INSTALLED PUMP AND PIPEWORK AND DRIVE SHAFT. REPLACED SIGHT TUBES ON WATER TANK AND SET UP TO FILL WITH WATER. INSPECTED A/C SYSTEM, RECOVERED GAS, PRESSURE TESTED TO 250PSI FOR 45 MINS, HELD OK, VAC'D AND LEFT FOR 30 MINS, TESTED OK. RECHARGED WITH R134A (80GM SHORT ON CHARGE). RECTIFIED LOOSE SEAT BASE. WASHED, DETAILED AND GREASED MACHINE. COMPLETED ON HIRE INSPECTION.

Service History Customer Report
Equipment No. WTR43

Description: Mitsubishi FN Rigid Water Cart

Make: Mitsubishi

Model: FN

Serial No.: JLFFN62FK0KJ10026

Registration: XB37PY

Registration Expiry: 30/04/2027

31/03/2025	5174	7051.00	DEFECTS FROM OFF HIRE INSPECTION 28.03.25
			Comment: COMPLETED OFF HIRE INSPECTION. WASHED, DETAILED AND GREASED MACHINE. COMPLETED ON HIRE INSPECTION. REMOVED AND REPLACED BATTERIES. REPAIRED DOOR RUBBER. STRAIGHTENED CAB LOCK DOWN.
26/05/2025	5817	7051.00	ENGINE LIGHT ON DASH AND ENGINE HAS DERATED
			Comment: 16.06.25 CARRIED OUT TEST'S & FOUND FAULT WITH NOX SENSOR. SENSOR CHANGED OUT WITH NEW ONE.
17/06/2025	6113	7174.60	DEFECTS FROM OFF HIRE INSPECTION 17.06.25
			Comment: COMPLETED OFF HIRE INSPECTION REPLACED START ISOLATOR. ACES TECHNICIAN DIAGNOSED AND RECTIFIED ENGINE LIGHT ON. REPLACED FIRST AID KIT. FABRICATED AND FIT REPLACEMENT CAB LATCH. INVESTIGATE AND REPAIR AIR LEAK. FABRICATED NEW FAN SHROUD BRACKET MOUNT. REPAIRED FAN GUARD. PAINT. REFIT. REPAIRED RUST ON R.O.P. REPLACED FIRE EXTINGUISHER. WASHED, DETAILED AND GREASED MACHINE COMPLETED ON HIRE INSPECTION
27/08/2025	7215	7185.00	DEFECTS FROM OFF HIRE INSPECTION 27.08.25
			Comment: COMPLETED OFF HIRE INSPECTION AIRCON NOT COLD - ACES REPAIRED. REPAIRED BENT CAB LATCH, NOW LOCKING. WWASHED, DETAILED& GREASED MACHINE COMPLETED ON HIRE INSPECTION REPLACED FRONT CAB BUSHES. REPAIRED GRILL RPLACED UHF MOUNT & ARIAL
15/09/2025	7712	7185.00	WATER CANON FAULT
			Comment: AUTO ELECTRICAN ATTENDED SITE, REPAIRED FAULT WITH PROXYS
18/09/2025	7752	7222.50	DEFECTS REPAIRS FROM OFF HIRE INSPECTION 18.08.25
			Comment: COMPLETED OFF HIRE INSPECTION ENGINE LIGHT ON - SERVICE COMPLETED & RECTIFIED LIGHT REPLACED MISSING GROMMET IN BUNK AREA & REATTACHED

Service History Customer Report
Equipment No. WTR43

Description: Mitsubishi FN Rigid Water Cart

Make: Mitsubishi

Model: FN

Serial No.: JLFFN62FK0KJ10026

Registration: XB37PY

Registration Expiry: 30/04/2027

			LOOSE COVERING WASHED, DETAILED & GREASED MACHINE COMPLETED ON HIRE INSPECTION
01/09/2025	7755	7222.50	250HR SERVICE COMPLETED 29.09.25
			Comment: 250HR SERVICE CARRIED OUT
08/10/2025	8062	7230.00	DEFECTS, REPAIRS FROM OFF HIRE INSPECTION 8.10.25
			Comment: COMPLETED OFF HRIE INSPECTION REPAIRED AIR LEAKS OUTSIDE FIRE EXTINGUSHER BAGS REPLACED SECURED LOOSE ITEMS IN CABIN O & M MANUAL REPLACED WIPER BLADES REPLACED REPLACED CANNON SWITCH SCREW LOOSE RH TRIM INSIDE DOOR - REPLACED / TIGHTENED WASHED, DETAILED & GREASED MACHINE COMPLETED ON HIRE INSPECTION
23/10/2025	8281	7230.00	DIAGNOSE AND RECTIFY ENGINE LIGHT FAULT ON DASH
			Comment: SERVICE CALL TO SITE AND INSPECTED FAULT WITH ADBLUE. CARRIED OUT TESTING AND FOUND ADBLUE INJECTOR NOT OPERATING. CUSTOMER TO REMOVE MANIFOLD AND CLEANED. SERVICE CALL BACK TO SITE, CARRIED OUT FURTHER TESTING ON ADBLUE/DPF SYSTEM. FOUND VALVE INCORRECTLY RE-ASSEMBLED. CARRIED OUT TESTS, FOUND A BLOCKAGE STILL IN THE SYSTEM. CUSTOMER TO SOURCE PARTS
06/01/2026	9216	7230.00	ON HIRE INSPECTION AND REPAIRS
			Comment: COMPLETED OF HIRE INSPECTION INSPECTED PTO NOT WORKING / FITTER FOUND LEFT TO RIGHT MOTOR DAMAGED - REPAIRED MOTOR. FITTED NEW HEADLIGHTS REMOVED & REPLACE DAMAGED STICKERS WASHED, DETAILED & GREASED MACHINE. COMPLETED ON HIRE INSPECTION
02/02/2026	9591	7322.00	DEFECT REPAIRS FROM OFF HIRE INSPECTION 2.02.26
			Comment: COMPLETED OFF HIRE INSPECTION WASHED, DETAILED & GREASED MACHINE COMPLETED ON HIRE INSPECTION REPAIRED WATER CANNON CONTROL PANEL.
24/02/2026	9845	7322.00	CALL OUT TO MACHINE IN LIMP MODE

Service History Customer Report
Equipment No. WTR43

Description: Mitsubishi FN Rigid Water Cart

Make: Mitsubishi

Model: FN

Serial No.: JLFFN62FK0KJ10026

Registration: XB37PY

Registration Expiry: 30/04/2027

			Comment: ACES ATTENDED SITE TO REPAIR LIMP MODE.
09/04/2026	10492	7347.00	DEFECT REPAIRS FROM OFF HIRE INSPECTION 9.04.26
			Comment: COMPLETED OFF HIRE INSPECTION LH AM\FM SPEAKER NOT WORKING. - REPAIRED LH ROOF LIGHT OUT - REPLACED LATCH ON HOSE REEL MISSING ROLL PIN - REPLACED AIR CLEANER DIRTY - BLOWN OUT CHECK HOSES ARE IN TRUCK - CONFIRMED CHECK FOR ANY DAMAGES TO HOSES & SEALS ARE INSIDE COUPLINGS - YES CONFIRMED TEST ALL WATER SPRAYS - ALL WORKING WASHED / DETAILED & GREASED MACHINE COMPLETED ON HIRE INSPECTION
16/04/2026	10588	7347.00	FAULT CODES - CALL OUT
			Comment: FITTER ATTENDED SITE / FOUND FAULT IN EARTH LEADS / CLEANED ALL TERMINALS & SURFACES / RECONNECTED - TESTED OK
26/05/2026	11142	7518.00	DEFECT REPAIRS FROM OFF HIRE INSPECTION 26.05.26
			Comment: COMPLETED OFF HIRE INSPECTION CAB HOLD DOWN LATCH IS BENT UP - LATCHED REPLACED AIRCON BELT LOOSE - RECTIFIED FAULT CODES - SPEED SENSORS - REPAIRED WATER PUMP TAIL SHAFT NOT GOOD - TO BE REPAIRED ON RETURN OF NEXT HIRE REPAIRED AIR LEAKS WASHED DETAILED & GREASED MACHINE COMPLETED ON HIRE INSPECTION
26/05/2026	11143	7518.00	MACHINE IS DUE FOR A 250HR SERVICE
			Comment: 250HR SERVICE & INSPECTION COMPLETED
03/06/2026	11343	7518.00	ENGINE LIGHT CAME ON WHEN DRIVING TO ROCKY
			Comment: REO HEAVY EQUIPMENT Travel to site, Gracemere roundabout. Reconnect earth cables correctly. Connect diagnostic computer and read fault codes, found 2BAD06 code, NOX issue. Return to workshop with asset and check condition of sensors and doser unit, found all ok. Advise customer this fault relates to an internal ECU code that will need to be rectified by Daimler to remove code and stop light

Service History Customer Report
Equipment No. WTR43

Description: Mitsubishi FN Rigid Water Cart
Make: Mitsubishi
Model: FN

Serial No.: JLFFN62FK0KJ10026
Registration: XB37PY
Registration Expiry: 30/04/2027

			flashing. Asset should not de-rate with this code.
10/06/2026	11456	7518.00	CHECK OVER AND REPAIR DEFECTS
			Comment: COMPLETED OFF HIRE INSPECTION REPAIRED HORN RECTIFIED ENGINE LIGHT ON DASH ACES REPAIRED - NO POWER TO ECM PLUG & PORT WASHED, DETAILED & GREASED MACHINE COMPLETED OFF HIRE INSPECTION
21/09/2026	12879	7518.00	CHECK OVER & REPAIR ANY DEFECTS FOR COI 23.9.26
			Comment: CHECK OVER & REPAIR ANY DEFECTS FOR COI ON WEDNESDAY 23.10.26
02/10/2026	13086	7518.00	DEFECT REPAIRS FROM OFF HIRE INSPECTION 2.10.26
			Comment: COMPLETE ON HIRE INSPECTION CHECK ALL HOSES ARE IN TRUCK CHECK HOSES FOR DAMAGE & CHECK SEALS ARE INSIDE COUPLINGS TEST ALL WATER SPRAYS WASH, DETAIL & GREASE MACHINE. COMPLETE ON HIRE INSPECTION
07/10/2026	13112	7608.00	DEFECT REPAIRS FROMOFF HIRE INSPECTION 2.10.26
			Comment: COMPLETED OFF HIRE INSPECTION WASHED, DETAILED & GREASED MACHINE CHECKED HOSES ARE IN TRUCK - CHECKED HOSES FOR DAMAGES & SEALS ARE INSIDE COUPLINGS. - CHECKED - TEST ALL WATER SPRAYS - CHECKED COMPLETED ON HIRE INSPECTION