

3916015

INSPECTION CERTIFICATE

Manitoba

Winnipeg, MB, R2C 5G7  
1-204-985-0920

Manitoba

|                      |           |           |           |
|----------------------|-----------|-----------|-----------|
| Section<br>Rejected  | 23<br>DAY | 12<br>MO. | 24<br>YR. |
| Section<br>Completed | 02<br>DAY | 01<br>MO. | 25<br>YR. |
| Section<br>Priority  | 31<br>DAY | 01<br>MO. | 26<br>YR. |

|                 |                       |                    |                    |      |           |
|-----------------|-----------------------|--------------------|--------------------|------|-----------|
| Station Number  | A6007                 | Station Name       | Northline Service  | City | St. James |
| Mechanic Number | M75911                | Mechanic Signature | <i>[Signature]</i> |      |           |
| Vehicle Owner   | D.M.G. Transport Ltd. |                    |                    |      |           |
| Address         |                       |                    |                    |      |           |
| City            | Province              | Postal Code        | Phone              |      |           |

|                     |                                                                                                |                   |       |       |                  |         |            |                                                                    |
|---------------------|------------------------------------------------------------------------------------------------|-------------------|-------|-------|------------------|---------|------------|--------------------------------------------------------------------|
| Pass/Safe Vehicle   | Licence Number                                                                                 | NOPLATE           | Prov. | NSC # | Odometer Reading | 19885   | Odom. Type | <input checked="" type="checkbox"/> km <input type="checkbox"/> mi |
| Fail/Unsafe Vehicle | Vehicle Identification Number                                                                  | 1FUDF6CK26DU62704 | Make  | FRT   | Model            | Classic | Year       | 06                                                                 |
| Fail/Hazardous      | <input checked="" type="checkbox"/> Confirmed legible Vehicle Identification Number on vehicle |                   |       |       |                  |         |            |                                                                    |

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

|       |      |     |                                                   |                                  |                                       |                              |                                     |                                    |
|-------|------|-----|---------------------------------------------------|----------------------------------|---------------------------------------|------------------------------|-------------------------------------|------------------------------------|
| Truck | GVWR | KGS | <input checked="" type="checkbox"/> Truck Tractor | <input type="checkbox"/> Trailer | <input type="checkbox"/> Semi-Trailer | <input type="checkbox"/> Bus | <input type="checkbox"/> School Bus | <input type="checkbox"/> Coach Bus |
|-------|------|-----|---------------------------------------------------|----------------------------------|---------------------------------------|------------------------------|-------------------------------------|------------------------------------|

of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section

Section 1 - Power Train: Defects (if any) Flex pipe leaking under cab

Section 2 Suspension: Defects (if any)

Section 3 - Brake Systems: 3H 3A Brake Inspection Type: A B C D E Circle appropriate Letter for Internal Brake Component Inspection

| Axle              | Lining |     | Drum/Rotor |        | Stroke |       |
|-------------------|--------|-----|------------|--------|--------|-------|
|                   | L      | R   | L          | R      | L      | R     |
| 1                 | 5/8    | 5/8 | 15.068     | 15.067 | 1"     | 1"    |
| 2                 | 3/4    | 3/4 | 16.545     | 16.545 | 1.25"  | 1.25" |
| 3                 | 3/4    | 3/4 | 16.816     | 16.544 | 1.25"  | 1.25" |
| 4                 |        |     |            |        |        |       |
| 5                 |        |     |            |        |        |       |
| Final Measurement |        |     |            |        |        |       |

Section 4 - Steering: Defects (if any)

Section 5 - Instruments & Auxiliary Equipment: Defects (if any) Wiper blades worn

Section 6 - Lamps: Defects (if any)

Section 7 - Electrical System: Defects (if any)

Section 8 - Body: Defects (if any) Center hood cable broken

Section 9 - Tire & Wheel: Defects (if any) Low tire pressures

Section 10 - Coupling Devices: Defects (if any)

| Axle | Tread Depth |    |           |    | Air Pressure |    |           |     |
|------|-------------|----|-----------|----|--------------|----|-----------|-----|
|      | Initial     |    | Corrected |    | Initial      |    | Corrected |     |
|      | L           | R  | L         | R  | L            | R  | L         | R   |
| 1    | 13          | 14 |           |    | 80           | 95 | 100       | 100 |
| 2    | 20          | 23 | 22        | 23 | 100          | 80 | 95        | 85  |
| 3    | 21          | 22 | 22        | 22 | 90           | 90 | 90        | 80  |
| 4    |             |    |           |    |              |    |           |     |
| 5    |             |    |           |    |              |    |           |     |

Section 10 - Coupling Devices: Defects (if any)