04008195

PERIODIC MANDATORY VEHICLE INSPECTION CERTIFICATE

Manitoba

X03-1

Vehicle Standards and Inspections
Box 45064 Regent Postal Outlet
Winnipeg, MB, R2C 5C7
1-204-985-0920

Manitoba A992018

Date Inspection Started	07 DAY	03 MO.	26 YR.
Date Inspection Completed	07 DAY	03 MO.	26 YR.
Inspection Expiry Date	31 DAY	03 MO.	27 YR.

Station Number: A61183 — Station Name: Friends Truck Ser... — City:

Mechanic Number: M1447 — Mechanic Signature: Prem Singh — Station Phone Number: 2046880413

Vehicle Owner: BENNINGTON FINANCIAL CORP.

Address: — City: — Province: — Postal Code: — Phone: 2045691602

☐ Pass/Safe Vehicle
☐ Fail/Unsafe Vehicle
☐ Fail/Hazardous

Licence Number: GAS289 — Prov.: MB — NSC #: MB10010124 — Odometer Reading: 1456362 — Odom. Type: ☒ km ☐ mi

Vehicle Identification Number: 3AKJGLD19GSHE2583 — Make: FL — Model: Cascadia — Year: 2016 — Unit #: 4190

☐ Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

____Truck GVWR 11110 KGS X Truck Tractor ____Trailer ____Semi-Trailer ____Bus ____School Bus ____Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section
X	X	**Section 1 - Power Train:** Defects (if any) 2.-c) Exhaust Stack Pipe clamp loose 4.-b) Iv.- #3 yoke moving by hand More than 3mm
		Section 2 Suspension: Defects (if any) 4.-c) Left Steer Rear Spring bushing worn
X	X	
		Section 3 - Brake Systems: 3H 3A (Circle Brake Type)
X	X	Defects (if any): 13-a) Both C/Gland hand corroded 13-e) An air leak by the LRD air bag Fitting
		Section 4 - Steering: Defects (if any)
X		
		Section 5 - Instruments & Auxiliary Equipment: Defects (if any) 8.-a) i.- windshield defroster inoperative
X	XX	**Section 6 - Lamps:** Defects (if any) 1.-f) Right Front signal inoperative 1.-L) Inoperative 1.-N) Left Fog lamp inoperative
X	X	
		Section 7 - Electrical System: Defects (if any)
X		
		Section 8 - Body: Defects (if any) 13.-b) Left side Cracked
X	X	
		Section 9 - Tire & Wheel: Defects (if any)
X		
		Section 10 - Coupling Devices: Defects (if any) 7.-a) Improperly adjusted
X	X	

Brake Inspection Type: A B C D E (Circle appropriate Letter for Internal Brake Component Inspection)

	Lining		Drum/Rotor		Stroke	
Axle	L	R	L	R	L	R
1	9/16"	3/4"			1.25"	1.25"
2	3/4"	3/4"			1.5"	1.5"
3	11/16"	3/4"			1.5"	1.5"
4						
5						
	Final Measurement					

	Tread Depth								Air Pressure							
	32 Initial				Corrected				Initial				Corrected			
Axle	L		R		L		R		L		R		L		R	
1		11	13							100	100					
2	21	23	22	22					100	100	100	100				
3	21	22	22	21					100	100	100	100				
4																
5																

- THIS INSPECTION IS NOT A WARRANTY -

This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks: Last Pull Wheels Safety #A98859

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: _____ Date: _____
Signature

FVS0022-01-(R-09/15)

Ce document peut être obtenu en français sur demande.

COPY IN CAB - PLEASE ENSURE CERTIFICATE IS SIGNED - NOT FOR REGISTRATION

20372138 MCC ©2023. All rights reserved. — 9355

20372136 1.00 ©2023. All rights reserved. — 9355