



Vehicle Standards and Inspection

X03-1

## Power Unit Inspection Certificate

This Certificate is issued under the authority of the Province of Saskatchewan

**A182110**

Station #: 71450

Station Name: Somerville Farms (2014) Ltd

Technician #: 91614

Technician Name: Craig Skjei

Signing Officer #: 90018

Signing Officer Name: Matthew Kerek

Customer Details:

Name: Samiam Farming LTD

Address: Eatonia Box 97, Eatonia, Saskatchewan, S0L-0Y0

Inspection Completed Date: 03Mar2026

Inspection Expiry Date: 30Sep2026

Vehicle Details:

VIN: 1FUPBSEB5VL553756

Odometer Reading: 417905 km

Year: 1997

Vehicle Make/Model: FREIGHTLINER/HEAVY VEHICLE

Plate: 099mtw

Jurisdiction: Saskatchewan

Unit:

Message(s): VIN has been validated.

This certificate does not warranty or guarantee the condition of this vehicle's components and systems for any period of time.



Vehicle Standards and Inspection

## Power Unit Record of Inspection

The Record of Inspection must be given to the customer regardless of whether the vehicle passes or fails.

Station #: 71450

Station Name: Somerville Farms (2014) Ltd

Technician #: 91614

Technician Name: Craig Skjei

Signing Officer #: 90018

Signing Officer Name: Matthew Kerek

**Customer Details:**

Name: Samiam Farming LTD

Address: Eatonia Box 97, Eatonia, Saskatchewan, S0L-0Y0

**Vehicle Details:**

VIN: 1FUPBSEB5VL553756

Odometer Reading: 417905 km

Year: 1997

Vehicle Make/Model: FREIGHTLINER HEAVY VEHICLE

**Inspection Details:**

Pass	Rejected	Corrected	Req Attn	DRIVERS COMPARTMENT	Comments
x				Vehicle Identification (5)	
x				Sun Visor Interior (8)	
x				Horn Operation (5)	
x				Mirrors (8)	
x				Windshield Wipers/Washers (8)	
x				Windshield Defroster/Heater (8)	
x				Windshield/Other Glass (8)	
x				Gear Position Indicator & Neutral Switch (1)	
x				Instrument Lamps (6)	
x				Accessibility Features/Equip (5)	
x				Auxiliary Heaters (5)	
x				Auxiliary Drive Controls (5)	
x				Emergency Exits (8)	
x				Floor/Step Well Covering (8)	
x				Service/Exit Doors (8)	
x				Indicator Lamps (5)	
x				Instruments/Gauges (5)	
x				Switches (7)	
x				Brake Pedal/Actuator (3)	
x				Clutch/Clutch Pedal (1)	

x				Fire Extinguisher/Hazard Kit (5)	
x				Seats/Seat Belts/SRS (8)	
x				Steering Column/Components (4)	
x				Auxiliary Controls/Equip (5)	
x				Speedometer/Odometer (5)	
x				Steering Lash/Travel (5)	
x				Accelerator Pedal/Actuator (1)	
x				Engine Shut Down Control (1)	
x				Engine Start Feature (1)	
x				Body Interior/Fixtures (8)	

Pass	Rejected	Corrected	Req Attn	BODY EXTERIOR	Comments
x				Lamps (6)	
x				Headlamp Aim (6)	
x				Reflex Reflectors (6)	
x				Retro Reflective Markings (6)	
x				Body/Bumpers (8)	
x				Trailer Hitch (10)	
x				Cab Grab Handles/Steps (8)	
x				Attached Equipment (8)	
x				Cargo Bodies/Vessels (8)	
x				Sun Visor Exterior (8)	
x				Mud Flaps/Fenders (8)	
x				Trailer Power Cord (7)	
x				Chain/Headache Rack (5)	
x				Auxiliary Compartments (8)	
x				Hybrid Vehicle Drive Systems (1)	
x				Unitized Body Elements (8)	

Pass	Rejected	Corrected	Req Attn	ENGINE COMPARTMENT	Comments
x				Cab/Hood Safety Catches (8)	
x				Power Steering System (4)	
x				Fuel System (1)	
x				Battery/Wiring Condition (7)	
x				Air Suspended Cab (8)	
x				Cab Mounts (8)	
x				Drive Belts (1)	

Pass	Rejected	Corrected	Req Attn	CHASSIS	Comments
x				Hyd Brake System/Components (3.1)	

x				Air Brake System/Components (3.2)	
x				Wheel Bearings (9)	
x				King Pins/Ball Joints (4)	
x				Steering Linkage (4)	
x				Tires/Wheels (9)	
x				Self-Steering Axle (4)	
x				Engine/Transmission Mounts (1)	
x				Frame/Crossmembers/Mounts (8)	
		x		Suspension/Axles (2)	Air Supply Leak Repaired Leak
x				Drive Shaft/Universal Joints (1)	
x				Exhaust/Emission System (1)	

**Brake/Tire Measurements**

**Axle 1-Pass**

Wheel1-On : Tire Tread Depth: 14 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 15 mm • Cam Rotation: 77.0 degrees • Brake Stroke: 45 mm

Wheel2-On : Tire Tread Depth: 14 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 15 mm • Cam Rotation: 79.0 degrees • Brake Stroke: 45 mm

**Axle 2-Pass**

Wheel1 : Tire Tread Depth: 17 mm

Brake(1): No Brake

N/A

Wheel2-On : Tire Tread Depth: 17 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 14 mm • Cam Rotation: 91.0 degrees • Brake Stroke: 44 mm

Wheel3-On : Tire Tread Depth: 17 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 14 mm • Cam Rotation: 88.0 degrees • Brake Stroke: 42 mm

Wheel4 : Tire Tread Depth: 17 mm

Brake(1): No Brake

N/A

PASS - vehicle passes inspection	Decal # A182110	Inspection Completed Date: 03Mar2026
----------------------------------	-----------------	--------------------------------------