



Vehicle Standards and Inspection

### Semi-Trailer Inspection Certificate

This Certificate is issued under the authority of the Province of Saskatchewan

Decal # A333641

Station #: 71709

Station Name: Redhead Equipment

Technician #: 87734

Technician Name: Cale Boehm

Signing Officer #: 92422

Signing Officer Name: Kassey Kohl

Customer Details:

Name: Hillsvale Farming Co.Ltd

Address: P.O. Box 518, Cut Knife, Saskatchewan, S0M 0N0

Inspection Completed Date: 11Jun2026

Inspection Expiry Date: 30Jun2027

Vehicle Details:

VIN: 1P9RS53F68S477214

Hubometer Reading:

Year: 2008

Vehicle Make/Model: MUVALL TRAILER/TRAILER

Plate:

Jurisdiction:

Unit:

Message(s): VIN has been validated.

This certificate does not warranty or guarantee the condition of this vehicle's components and systems for any period of time.



Vehicle Standards and Inspection

### Semi-Trailer Record of Inspection

The Record of Inspection must be given to the customer regardless of whether the vehicle passes or fails.

Station #: 71709	Station Name: Redhead Equipment
Technician #: 87734	Technician Name: Cale Boehm
Signing Officer #: 92422	Signing Officer Name: Kasey Kohl

Customer Details:	
Name: Hillsvale Farming Co.Ltd	Address: P.O. Box 518, Cut Knife, Saskatchewan, S0M 0N0

Vehicle Details:	
VIN: 1P9RS53F68S477214	Hubometer Reading:
Year: 2008	Vehicle Make/Model: MUVALL TRAILER TRAILER

Inspection Details:

Pass	Rejected	Corrected	Req Attn	DRIVERS COMPARTMENT	Comments
x				Vehicle Identification (5)	
x				Fire Extinguisher (5)	
x				Auxiliary Controls/Equip (5)	

Pass	Rejected	Corrected	Req Attn	BODY EXTERIOR	Comments
x				Lamps (6)	
x				Reflex Reflectors (6)	
x				Retro Reflective Markings (6)	
x				Trailer Hitch (10)	
x				Attached Equipment (8)	
x				Cargo Bodies/Vessels (8)	
x				Mud Flaps/Fenders (8)	
x				Landing Gear (8)	
x				Rear Impact Guard (8)	
x				Trailer Power Cord (7)	

Pass	Rejected	Corrected	Req Attn	ENGINE COMPARTMENT	Comments
x				Fuel System (1)	
x				Battery/Wiring Condition (7)	

Pass	Rejected	Corrected	Req Attn	CHASSIS	Comments
x				Hyd Brake System/Components (3.1)	
		x		Air Brake System/Components (3.2)	RC BRAKE SHOES RUNNING OUTSIDE OF DRUM, RF BRAKE CHAMBER ROD TOO LONG, RR ABS CABLE NOT SECURE, RR SLACK ADJUSTER DOESN'T LOCK
x				Elec Brake System/Components (3.1)	
		x		Wheel Bearings (9)	LC AND RR WHEEL BEARINGS LOOSE
x				Tires/Wheels (9)	
x				Self-Steering Axle (2&4)	
x				Frame/Crossmembers/Mounts (8)	
x				Suspension/Axles (2)	
x				Exhaust/Emission System (1)	
x				Sliding Axle Assembly (if equipped) (8)	

#### Brake/Tire Measurements

##### Axle 1-Pass

Wheel1 : Tire Tread Depth: 10 mm

Brake(1): No Brake

N/A

Wheel2-On : Tire Tread Depth: 10 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 16 mm • Cam Rotation: 67.0 degrees • Brake Stroke: 46 mm

Wheel3-On : Tire Tread Depth: 7 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 17 mm • Cam Rotation: 66.0 degrees • Brake Stroke: 45 mm

Wheel4 : Tire Tread Depth: 7 mm

Brake(1): No Brake

N/A

##### Axle 2-Pass

Wheel1 : Tire Tread Depth: 8 mm

Brake(1): No Brake

N/A

Wheel2-On : Tire Tread Depth: 11 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 17 mm • Cam Rotation: 62.0 degrees • Brake Stroke: 47 mm

Wheel3-Off : Tire Tread Depth: 9 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 16 mm • Brake Drum/Rotor: 16.574 in • Brake Stroke: 46 mm

Wheel4 : Tire Tread Depth: 11 mm

Brake(1): No Brake

N/A

##### Axle 3-Pass

Wheel1 : Tire Tread Depth: 6 mm

Brake(1): No Brake

N/A

Wheel2-On : Tire Tread Depth: 8 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 16 mm • Cam Rotation: 67.0 degrees • Brake Stroke: 46 mm

Wheel3-On : Tire Tread Depth: 8 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 17 mm • Cam Rotation: 63.0 degrees • Brake Stroke: 45 mm

Wheel4 : Tire Tread Depth: 12 mm

Brake(1): No Brake

N/A

PASS - vehicle passes inspection

Decal # A333641

Inspection Completed Date: 11Jun2026

One or more wheels were removed for inspection. Warning: Wheel nuts **MUST** be **RE-TORQUED** within 100-150 km.  
Failure to do so may result in damage or serious injury.