

  
STATUS

✓ Done

ESTIMATED TIME

1h

WORK TYPE

Reactive

REQUEST

#2721236

DESCRIPTION

Replaced site glass assembly 125 gallon

ASSIGNEES

 Billy  
Lomusico

CATEGORIES

Water system

LOCATION



ASSET

MT 104

WORK ORDER INFO

Created by: Billy Lomusico on 12/18/2023, 5:49 AM

Last updated on 12/18/2023, 5:49 AM

Completed on 12/18/2023, 5:49 AM

Requested by Josh Gonzales - TexCrete on 12/12/2023, 2:05 PM

WORK ORDER HISTORY

Josh Gonzales -  requested the work order

12/12/2023, 2:05 PM

Billy Lomusico created work order

12/18/2023, 5:49 AM

Billy Lomusico logged time 30m 00s (Work).

12/18/2023, 5:49 AM

Billy Lomusico logged time and was assigned to this work order.

12/18/2023, 5:49 AM

Billy Lomusico completed the work order.

12/18/2023, 5:49 AM

---

Signed off by

Date