

03961656

PERIODIC MANDATORY VEHICLE INSPECTION CERTIFICATE

Manitoba



Y01-6

Vehicle Standards and Ins Box 45064 Regent Postal O Winnipeg, MB, R2C 5C7 1-204-985-0920

Manitoba

A998731

Date Inspection Started: 04 DAY, 06 MO, 25 YR. Station Number: A11776. Station Name: Trappend Transport Ltd. City: [blank].
 Date Inspection Completed: 18 DAY, 06 MO, 25 YR. Mechanic Number: M7729. Mechanic Signature: [Signature]. Station Phone Number: 204-697-5500.
 Inspection Expiry Date: 30 DAY, 06 MO, 26 YR. Vehicle Owner: Trappend Transport Ltd.
 License Number: CRC789. Prov: MB. NSC #: MB029015. Odometer Reading: 1153477. Odom. Type: km mi.
 Vehicle Identification Number: 1XP4D49X11C1155778. Make: Pete. Model: 386. Year: 12. Unit #: 13.
 Pass/Safe Vehicle
 Fail/Unsafe Vehicle
 Fail/Hazardous
 Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

Truck GVWR KGS Truck Tractor Trailer Semi-Trailer Bus School Bus Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section
X		Section 1 - Power Train: Defects (if any) X-4C Rear driveshaft Tube cracked. X-4A #2, #3 w joints have play.
X	X	Section 2 Suspension: Defects (if any) X-5F leveling Valve leaking X-2B Oil Drive Bushings worn out. X-5B LR air bag worn out.
X	X	Section 3 - Brake Systems: 3H (3A) Brake Inspection Type: A B C (D) E Circle appropriate Letter for Internal Brake Component Inspection Defects (if any) Circle Brake Type X-18C All Drive Rotors worn out X-13E air leak at Treadle valve
X		Section 4 - Steering: Defects (if any)
X		Section 5 - Instruments & Auxiliary Equipment: Defects (if any)
X		Section 6 - Lamps: Defects (if any)
X		Section 7 - Electrical System: Defects (if any)
X	X	Section 8 - Body: Defects (if any) X-3F Cab shell leaking X-13B Both windshields cracked.
X		Section 9 - Tire & Wheel: Defects (if any)
X	X	Section 10 - Coupling Devices: Defects (if any) X-7D 5th wheel need adjustment

Axle	Tread Depth				Air Pressure			
	Initial		Corrected		Initial		Corrected	
	L	R	L	R	L	R	L	R
1	11	12			100	100		
2	14	14	14		90	90	90	90
3	13	14	19	18	90	90	90	90
4								
5								

- THIS INSPECTION IS NOT A WARRANTY - This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: Signature Date:

PRESENT THIS COPY WHEN REGISTERING VEHICLE