04048824 **PERIODIC MANDATORY VEHICLE INSPECTION CERTIFICATE**

Manitoba Y02-1

Vehicle Standards and Inspection
Box 45064 Regent Postal Office
Winnipeg, MB, R2C 5C7
1-204-985-0920

Manitoba

DECAL

C000195

Date Inspection Started	05 (DAY)	08 (MO.)	05 (YR.)
Date Inspection Completed	05 (DAY)	08 (MO.)	05 (YR.)
Inspection Expiry Date	31 (DAY)	08 (MO.)	06 (YR.)

Station Number: A4389 — Station Name: Alijon Enterprises — City:

Mechanic Number: M7154 — Mechanic Signature: [signature] — Station Phone Number: (204) 955-5594

Vehicle Owner: No Limits Underground LTD

Address: — City: — Province: — Postal Code: — Phone:

- [x] Pass/Safe Vehicle
- [ ] Fail/Unsafe Vehicle
- [ ] Fail/Hazardous

Licence Number: GUF943 — Prov.: MB — NSC #: MB1815375 — Odometer Reading: 96399 — Odom. Type: [x] km [ ] mi

Vehicle Identification Number: 5KNNAEDA7AAAA9011 — Make: w/star — Model: 4900 — Year: 11 — Unit #: S-01

[ ] Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

___Truck GVWR KGS X Truck Tractor ___Trailer ___Semi-Trailer ___Bus ___School Bus ___Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section
X		Section 1 - Power Train: Defects (if any) - D 4,H Front diff sweating
X		Section 2 Suspension: Defects (if any)
X		Section 3 - Brake Systems: 3H 3A (Circle Brake Type) Defects (if any)
X		Section 4 - Steering: Defects (if any)
X		Section 5 - Instruments & Auxiliary Equipment: Defects (if any)
X		Section 6 - Lamps: Defects (if any)
X		Section 7 - Electrical System: Defects (if any)
X		Section 8 - Body: Defects (if any) - D 8,H Pass door cond.
X		Section 9 - Tire & Wheel: Defects (if any)
X		Section 10 - Coupling Devices: Defects (if any)

Brake Inspection Type: A B C D E — Circle appropriate Letter for Internal Brake Component Inspection

Axle	Lining L	Lining R	Drum/Rotor L	Drum/Rotor R	Stroke L	Stroke R
1	9/16	9/16	15.078	15.079	1 1/4	1 1/4
2	1/8	1/8	16.561	16.559	1 1/4	1 1/4
3	1/8	1/8	16.596	16.555	1 1/4	1 1/4
4						
5						
	Final Measurement					

Axle	Tread Depth Initial 1/32 L		R		Corrected L		R		Air Pressure Initial L		R		Corrected L		R	
1		18	18							100	100					
2	9	8	8	8					100	100	100	100				
3	24	24	18	16					100	100	100	100				
4																
5																

- THIS INSPECTION IS NOT A WARRANTY -
This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: _____ Signature — Date: _____

FVS0022-01-(R-09/15)

Ce document peut être obtenu en français sur demande

COPY IN CAB - PLEASE ENSURE CERTIFICATE IS SIGNED - NOT FOR REGISTRATION