

03976387

PERIODIC MANDATORY VEHICLE INSPECTION CERTIFICATE



Vehicle Surveys and Inspections  
Box 45064 Regent Postal Outlet  
Winnipeg, MB, R2C 5C7  
1-204-985-0920



Date Inspection Started: 28 08 25  
 Date Inspection Completed: 28 08 25  
 Inspection Expiry Date: 31 08 26

Station Number: A5329 Station Name: Parkville Trailers Inc.  
 Mechanic Number: M5343 Mechanic Signature: M. Popay  
 Vehicle Owner: BNM Works Inc.  
 Address: \_\_\_\_\_ City: \_\_\_\_\_ Province: \_\_\_\_\_ Postal Code: \_\_\_\_\_ Phone: \_\_\_\_\_

A969117

Pass/Safe Vehicle  
 Fail/Unsafe Vehicle  
 Fail/Hazardous

License Number: TGB434 Prov. MB NSC # \_\_\_\_\_ Odometer Reading: N/A  
 Vehicle Identification Number: 2A9D7B7327A003787 Make: Ayrnes Model: Dump Year: 07 Unit #: ED05  
 Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

Truck  GVWR \_\_\_\_\_ KGS \_\_\_\_\_ Truck Tractor \_\_\_\_\_ Trailer \_\_\_\_\_ Semi-Trailer  Bus \_\_\_\_\_ School Bus \_\_\_\_\_ Coach Bus \_\_\_\_\_

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section
		Section 1 - Power Train: Defects (if any)
X		Section 2 Suspension: Defects (if any)
X	X	Section 3 - Brake Systems: 3H 3A Defects (if any): 3A = 2 fittings on tank - leaking Bolts on air tank - loose B. PPV - missing 20. ABS - disconnected Brake Inspection Type: A (B) C D E Circle appropriate Letter for Internal Brake Component Inspection
		Section 4 - Steering: Defects (if any)
		Section 5 - Instruments & Auxiliary Equipment: Defects (if any)
X		Section 6 - Lamps: Defects (if any)
X		Section 7 - Electrical System: Defects (if any)
X		Section 8 - Body: Defects (if any)
X		Section 9 - Tire & Wheel: Defects (if any)
X		Section 10 - Coupling Devices: Defects (if any)

Axle	Lining		Drum/Rotor		Stroke	
	L	R	L	R	L	R
1	10/16	7/16	16,540	16,565	1,5	1,5
2	11/16	11/16	16,530	16,530	1,5	1,5
3	8/16	9/16	16,560	16,560	1,5	1,5
4						
5						
Final Measurement						

Axle	Tread Depth				Air Pressure			
	Initial		Corrected		Initial		Corrected	
	L	R	L	R	L	R	L	R
1	8	7	7	7	100	100	100	100
2	14	18	2	9	100	100	100	100
3	15	15	15	15	100	100	100	100
4								
5								

- THIS INSPECTION IS NOT A WARRANTY -  
This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks: \_\_\_\_\_

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: \_\_\_\_\_ Signature \_\_\_\_\_ Date: \_\_\_\_\_