

03963418

PERIODIC MANDATORY VEHICLE
INSPECTION CERTIFICATE

Manitoba

2014

Vehicle Standards and Inspection
Box 40064 Regent Postal Centre
Winnipeg, MB, R0C 5C7
1-204-985-0855

Manitoba

Date Inspection Started 12 09 25
Date Inspection Completed 17 09 25
Inspection Expiry Date 30 09 26

Station Number A6213 Station Name BVS Transport Inc.
Mechanic Number MS820 Mechanic Signature [Signature]
Vehicle Owner BVS Transport Inc.
Address Box 369 ST. ADOLPHE MB R5A 1A2
City ST. ADOLPHE Province MB Postal Code R5A 1A2 Phone

A956892

☒ Pass/Safe Vehicle
☒ Fail/Unsafe Vehicle
☐ Fail/Hazardous

Licence Number N/A Prov. NSC #
Vehicle Identification Number 2L0H63022A1F059794 Make KIA Model 1000 Year 15 Unit #
☒ Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

Truck ☐ GVWR ☐ KGS Truck Tractor ☐ Trailer ☐ Semi-Trailer ☐ Bus ☐ School Bus ☐ Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section

P	R	Section	Defects (if any)
		Section 1 - Power Train: Defects (if any)	
		Section 2 Suspension: Defects (if any)	
X		Section 3 - Brake Systems: 3H	3A-15 B 3A-15 C 3A-15 F
		Section 4 - Steering: Defects (if any)	
		Section 5 - Instruments & Auxiliary Equipment: Defects (if any)	
X		Section 6 - Lamps: Defects (if any)	6-1 H 6-1 L
		Section 7 - Electrical System: Defects (if any)	
		Section 8 - Body: Defects (if any)	
X		Section 9 - Tire & Wheel: Defects (if any)	9-4A + - 10% True Pressures

Brake Inspection Type: A B C D E Circle appropriate Letter for Internal Brake Component Inspection

Axle	Lining		Drum/Rotor		Stroke	
	L	R	L	R	L	R
1	5/8	13/16	16.500	16.500	1 1/2	1 1/2
2	5/8	9/16	16.500	16.500	3/4	1 1/2
3						
4						
5						

Final Measurement

Axle	Tread Depth				Air Pressure			
	Initial		Corrected		Initial		Corrected	
	L	R	L	R	L	R	L	R
1	11	11	15	15	92	89	96	94
2	13	14	12	13	99	80	95	98
3								
4								
5								

Section 10 - Coupling Devices: Defects (if any)

- THIS INSPECTION IS NOT A WARRANTY -

This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by:

Signature

Date:

Ce document peut être obtenu en français sur demande.

FVS0022-01-(R-09/15)

PRESENT THIS COPY WHEN REGISTERING VEHICLE

2037238 MCC 0023 All rights reserved. - 9365