04036664

PERIODIC MANDATORY VEHICLE INSPECTION CERTIFICATE

Manitoba

Vehicle Standards and Inspections
Box 45064 Regent Postal Outlet
Winnipeg, MB, R2C 5C7
1-204-985-0920

DECAL

Manitoba

C043362

	DAY	MO.	YR.
Date Inspection Started	31	01	06
Date Inspection Completed	06	02	06
Inspection Expiry Date	28	02	07

Station Number: A6444 — Station Name: B.M.R — City: Shilo

Mechanic Number: 0404215 — Mechanic Signature — Station Phone Number: 204-730-[illegible]91

Vehicle Owner: [illegible] landscaping.

Address — City: Brandon — Province: MB. — Postal Code — Phone

- [X] Pass/Safe Vehicle
- [X] Fail/Unsafe Vehicle
- [ ] Fail/Hazardous

Licence Number: PKN180 — Prov.: MB — NSC # — Odometer Reading: 659 471 — Odom. Type: [X] km [ ] mi

Vehicle Identification Number: 1HSNVSTTET[illegible]176D — Make: [illegible] — Model: [illegible] — Year: 12 — Unit #: T58

[X] Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

__X__ Truck — GVWR ____ KGS — ____ Truck Tractor — ____ Trailer — ____ Semi-Trailer — ____ Bus — ____ School Bus — ____ Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section
X		**Section 1 - Power Train:** Defects (if any) Item 2.P- wheel lug clamp broken. Item 6.P- Transmission oil leak on shift valve.
X		**Section 2 Suspension:** Defects (if any) Item 5.B- N3L air bag rotten.
X		**Section 3 - Brake Systems:** 3H 3A — Defects (if any) — Circle Brake Type. Item 14.B- N3R brake shoe(s) worn. Item 5.B- N3L, N3R slack adjuster(s) worn out.
		Brake Inspection Type: A B C D E — Circle appropriate Letter for Internal Brake Component Inspection
		Section 4 - Steering: Defects (if any)
		Section 5 - Instruments & Auxiliary Equipment: Defects (if any)
X		**Section 6 - Lamps:** Defects (if any) Item 4.P- rear work light broken.
		Section 7 - Electrical System: Defects (if any)
X		**Section 8 - Body:** Defects (if any)
	X	**Section 9 - Tire & Wheel:** Defects (if any) Item 5.D- NIC, N1R tube leaking at wheel drum.
X		**Section 10 - Coupling Devices:** Defects (if any)

Axle	Lining L	Lining R	Drum/Rotor L	Drum/Rotor R	Stroke L	Stroke R
1	7/16	5/16	16.54	16.57	1.5	1.5
2	9/16	1/2	16.57	16.57	1.5	1.5
3	9/16	5/8	16.55	16.56	1.5	1.5
4						
5						
	Final Measurement					

Axle	Tread Depth Initial L	Tread Depth Initial R	Tread Depth Corrected L	Tread Depth Corrected R	Air Pressure Initial L	Air Pressure Initial R	Air Pressure Corrected L	Air Pressure Corrected R
1	[illegible]	9	[illegible]	[illegible]	[illegible]	100	[illegible]	[illegible]
2	11/32	15/32	[illegible]	[illegible]	100	100	[illegible]	[illegible]
3	9/32	9/32	[illegible]	[illegible]	100	100	[illegible]	[illegible]
4	[illegible]	[illegible]	[illegible]	[illegible]	100	100	[illegible]	[illegible]
5	[illegible]	[illegible]	[illegible]	[illegible]	[illegible]	[illegible]	[illegible]	[illegible]

- THIS INSPECTION IS NOT A WARRANTY -

This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks: Wheels leaned to South side.

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: _____ Signature — Date: _____

S0022-01-(R-09/15)

COPY IN CAB - PLEASE ENSURE CERTIFICATE IS SIGNED

Ce document peut être obtenu en français sur demande