

CUSTOMER #: A13080

18383T

5717 E. Margaret Dr.

Terre Haute, IN 47803

(812) 233-6406 / (888) 482-6225

WWW.VOMACTRUCK.COM



SHORT HAUL INC

HERB

6671 E COUNTY ROAD 300 N

GREENSBURG, IN 47240

HOME: 317-435-4841 CONT: 317-435-4841

BUS:

CELL:

SERVICE ADVISOR: 312 BRADLY WALLACE

PAGE 1

REMIT TO: 10000 State Hwy. 57 Evansville, IN 47725

COLOR		YEAR	MAKE/MODEL		VIN		UNIT #	MILEAGE IN/ OUT		TAG
		16	MACK CXU613		1M1AW21YXGM052211			538035/538035		T2211
DEL DATE		PROD. DATE	WARR. EXP.	PROMISED		PO NO.		RATE	PAYMENT	INV. DATE
01JAN15 DD				13:17 29SEP19		100		0.00	CHG	30SEP19
R.O. OPENED			READY		OPTIONS:					

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
A CHECK AND ADVISE FOR ENGINE WHITE SMOKING AND LOSING COOLANT							
CAUSE: #3 intake valve failure							
99-000-0001 CHECK AND ADVISE FOR WHITE SMOKING							
				327 CPE	47.46		
				332 CPE	0.54		
					48.00		
16	BD-BD1019	(BD1019-1)NC	BRAKE CLNR,1		14.73	3.75	60.00
2	995487	FLANGE SCREW			0.86	0.79	1.58
1	85020890	CYLINDER HEAD, EXCH			6303.44	5004.93	5004.93
	CORE CHARGE C					1100.00	1100.00
1	85151095	TURBO KIT			5435.19	4315.54	4315.54
	CORE CHARGE C					660.00	660.00
1	85144517	UNIT INJECTOR KIT			3527.98	2799.98	2799.98
	CORE CHARGE C					1980.00	1980.00
1	85114535	FILTER KIT			165.15	118.91	118.91
1	21937298	COOLANT FILTER			13.16	9.48	9.48
1	20824906	OIL PUMP			1111.20	882.29	882.29
	CORE CHARGE C					220.00	220.00
1	85132267	OIL COOLER			1461.77	1160.65	1160.65
1	22696506	PIPE			69.45	55.14	55.14
1	22998076	OIL FILTER HOUSING			1036.79	823.21	823.21
6	22879256	CAMSHAFT BEARING KIT			24.62	19.55	117.30
1	22879257	CAMSHAFT BEARING KIT			101.46	80.56	80.56
6	22522229	CYLINDER LINER KIT			1368.66	1086.72	6520.32
1	22522221	DECARBONIZING KIT			1395.48	1108.01	1108.01
7	23070440	MAIN BEARING KIT			63.15	50.14	350.98
1	21948261	THRUST WASHER			91.91	72.98	72.98
6	21610676	BIG-END BEARING KIT			63.29	50.25	301.50
40	DEL1300	DELVAC 1300 SUPER			2.93	2.93	117.20
38	21345131	FLANGE SCREW			8.64	7.95	302.10
3	BD-KP87610	RADIAL BRISTLE DISC + 3 G			71.88	18.49	55.47
1	VN1206	DPF			3810.00	1651.00	1651.00
1	21756506	MUFFLER			3593.12	2245.70	2245.70
1	BD-214211	LUBRIPLATE 105 GREASE, 16			73.95	19.02	19.02

VoMac Truck Sales & Service, Inc.

1255 S. Commerce Dr.
Seymour, IN 47274
812-523-4400
888-699-6225

12242 Declaration Dr.
New Haven, IN. 46774
260-749-5061
800-824-9354

1879 S. Old US 41
Vincennes, IN. 47791
812-882-1730
800-869-6225

10000 State Hwy. 57
Evansville, IN. 47725
812-253-0025
800-776-6225

STATEMENT OF DISCLAIMER

The factory warranty constitutes all of the warranties with respect to the sale of this item/items. The Seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item/items.

Thank You!

DESCRIPTION	TOTALS
LABOR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES	
TOTAL CHARGES	
LESS	
SALES TAX	
PLEASE PAY THIS AMOUNT	

CUSTOMER #: A13080

18383T

5717 E. Margaret Dr.
Terre Haute, IN 47803

SHORT HAUL INC
HERB

INVOICE


(812) 233-6406 / (888) 482-6225
WWW.VOMACTRUCK.COM

6671 E COUNTY ROAD 300 N
GREENSBURG, IN 47240
HOME: 317-435-4841 CONT: 317-435-4841
BUS: CELL:

PAGE 2

REMIT TO: 10000 State Hwy. 57 Evansville, IN 47725

SERVICE ADVISOR: 312 BRADLY WALLACE

COLOR	YEAR	MAKE/MODEL	VIN	UNIT #	MILEAGE IN/ OUT	TAG	
	16	MACK CXU613	1M1AW21YXGM052211		538035/538035	T2211	
DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
01JAN15 DD			13:17 29SEP19	100	0.00	CHG	30SEP19

R.O. OPENED	READY	OPTIONS:
14:19 22AUG19	11:01 30SEP19	

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
1	20876840	CONNECTING ROD			631.21	501.18	501.18
		CORE CHARGE C				132.00	132.00
1	984740	FLANGE SCREW			1.32	1.22	1.22
-1	20876840	CORE RETURN			132.00	132.00	-132.00
1	21613426	THERMOSTAT			148.69	118.06	118.06
12	21344787	FLANGE SCREW			19.41	15.41	184.92
4	21528673	SHOULDER SCREW			55.75	44.27	177.08
2	FUL75120-1	5/32 RED PER FT			1.35	0.85	1.70
1	85148633	SEALANT			86.66	68.81	68.81
8	8192804	FLANGE SCREW			3.84	3.05	24.40
1	1677370	SEALING RING			4.63	3.67	3.67
5	980881	CABLE TIE			1.31	1.04	5.20
2	984741	FLANGE SCREW			3.31	3.04	6.08
1	975697	O-RING			7.66	6.08	6.08
1	1547254	SEALING RING			13.92	11.05	11.05
2	1547253	SEALING RING			23.67	18.80	37.60
4	471626	RUBBER MOULDING			15.92	12.64	50.56
1	1547252	SEALING RING			9.47	7.52	7.52
1	21294062	GASKET			120.56	95.73	95.73
1	21434720	CONNECTION PIPE			32.48	25.79	25.79
1	20430678	RUBBER MOULDING			25.29	20.08	20.08
1	21574409	GASKET			61.69	48.98	48.98
2	977935	GASKET			11.11	8.82	17.64
1	21293367	SEALING STRIP			165.07	131.07	131.07
1	21780376	SEALING RING			14.71	11.68	11.68
1	949656	O-RING			4.38	3.48	3.48
2	982724	GASKET			7.98	6.34	12.68
10	RC-AFRNA053	ROAD CHOICE NOAT			12.00	8.57	85.70
2	979097	GASKET			6.36	5.05	10.10
6	994445	FLANGE SCREW			1.08	1.00	6.00
2	BD-BD1019	(BD1019-1)NC BRAKE CLNR,1			14.73	3.75	7.50
2	RC-AFRNA053	ROAD CHOICE NOAT			12.00	8.57	17.14
1	22275838	SEALING RING			8.72	6.93	6.93
4	21092243	SEALING RING			7.70	6.11	24.44

VoMac Truck Sales & Service, Inc.

1255 S. Commerce Dr.
Seymour, IN 47274
812-523-4400
888-699-6225

12242 Declaration Dr.
New Haven, IN. 46724
260-749-5061
800-824-9354

1879 S. Old US 41
Vincennes, IN. 47591
812-882-1730
800-869-6225

10000 State Hwy. 57
Evansville, IN. 47725
812-253-0025
800-776-6225

STATEMENT OF DISCLAIMER

The factory warranty constitutes all of the warranties with respect to the sale of this item/items. The Seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item/items.

Thank You!

DESCRIPTION	TOTALS
LABOR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES	
TOTAL CHARGES	
LESS	
SALES TAX	
PLEASE PAY THIS AMOUNT	

CUSTOMER #: A13080

18383T

5717 E. Margaret Dr.
Terre Haute, IN 47803

SHORT HAUL INC
HERB

INVOICE



(812) 233-6406 (888) 482-6225
WWW.VOMACTRUCK.COM



6671 E COUNTY ROAD 300 N
GREENSBURG, IN 47240
HOME:317-435-4841 CONT:317-435-4841
BUS: CELL:

PAGE 3

REMIT TO: 10000 State Hwy. 57 Evansville, IN 47725

SERVICE ADVISOR: 312 BRADLY WALLACE

COLOR	YEAR	MAKE/MODEL	VIN	UNIT #	MILEAGE IN/ OUT	TAG	
	16	MACK CXU613	1M1AW21YXGM052211		538035/538035	T2211	
DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
01JAN15 DD			13:17 29SEP19	100	0.00	CHG	30SEP19

R.O. OPENED	READY	OPTIONS:
14:19 22AUG19	11:01 30SEP19	

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
1	21737481	FUEL FILTER INSERT			32.95	28.07	28.07
10	BD-C24706	CABLE TIE BLACK 3/16 X 15			0.38	0.35	3.50
1	BD-24147	NO. 16 WORM GEAR CLAMP PR			5.70	1.47	1.47
1	25100042	FILTER CARTRIDGE			111.97	79.95	79.95
2	21021850	V-CLAMP			40.32	32.01	64.02
1	21021852	V-CLAMP			34.53	27.41	27.41
3	60111689	HEX. SOCKET SCREW			2.83	2.60	7.80
1	21376801	SEALING PLATE			27.77	22.05	22.05
2	21095726	GASKET			21.07	16.73	33.46
1	21095721	GASKET			12.59	10.00	10.00
20	BD-C24706	CABLE TIE BLACK 3/16 X 15			0.38	0.35	7.00
1	85124753	KIT			404.45	321.13	321.13
1	20532891	GASKET			22.03	17.50	17.50
1	22877306	SEPARATOR			640.78	508.78	508.78
1	471708	RUBBER MOULDING			5.66	4.49	4.49
-1	20824906	CORE RETURN			220.00	220.00	-220.00
-1	85144517	CORE RETURN			1980.00	1980.00	-1980.00
-1	85151095	CORE RETURN			660.00	660.00	-660.00
-1	85020890	CORE RETURN			1100.00	1100.00	-1100.00
4	VALVE DAMAGEDVALVE				25.00	25.00	100.00
1	21761097	HOSE			44.03	34.96	34.96

538035 PRESSURIZED COOLING SYSTEM. FOUND LOOSING COOLANT INTERNALLY. REMOVED OIL PAN. FOUND COOLANT IN PAN. REMOVED HEAD. #3 CYLINDER LINER CRACKED. DISASSEMBLED ENGINE. CLEANED UP. INSTALLED NEW MAIN BEARINGS. INSTALLED NEW CYLINDER KITS WITH NEW RODS. INSTALLED REMAN HEAD, OIL PUMP, TURBO, AND INJECTORS. REPLACED OIL COOLER AND CAM BEARINGS. FOUND OIL FILTER HOUSING LEAKING. REPLACED. RUN OVERHEAD. CHANGED OIL AND ALL FILTERS. DPF AND CATALYST. REPLACED. RAN STATIONARY REGEN AND TEST DROVE.

B** LEFT STEER AXLE BRAKE SHOE BROKEN
5 AIR SYSTEM

332 CPE 1.50	174.00	174.00
2 8235*XK2124719E* REMAN SHOE KIT	201.70	100.65
		201.30

VoMac Truck Sales & Service, Inc.

1255 S. Commerce Dr.
Seymour, IN 47274
812-523-4400
888-699-6225

12242 Declaration Dr.
New Haven, IN. 46774
260-749-5061
800-824-9354

1879 S. Old US 41
Vincennes, IN. 47591
812-882-1730
800-869-6225

10000 State Hwy. 57
Evansville, IN. 47725
812-253-0025
800-776-6225

STATEMENT OF DISCLAIMER
The factory warranty constitutes all of the warranties with respect to the sale of this item/items. The Seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item/items.

Thank You!

DESCRIPTION	TOTALS
LABOR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES	
TOTAL CHARGES	
LESS	
SALES TAX	
PLEASE PAY THIS AMOUNT	

CUSTOMER #: A13080

18383T

VOMAC TRUCK Sales & Service, Inc.

SHORT HAUL INC

HERB

6671 E COUNTY ROAD 300 N

GREENSBURG, IN 47240

HOME: 317-435-4841 CONT: 317-435-4841

BUS:

CELL:

INVOICE



5717 E. Margaret Dr.
Terre Haute, IN 47803
(812) 233-6406 / (888) 482-6225
WWW.VOMACTRUCK.COM



PAGE 4

REMIT TO: 10000 State Hwy. 57 Evansville, IN 47725

SERVICE ADVISOR: 312 BRADLY WALLACE

COLOR	YEAR	MAKE/MODEL	VIN	UNIT #	MILEAGE IN/ OUT	TAG	
	16	MACK CXU613	1M1AW21YXGM052211		538035/538035	T2211	
DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
01JAN15 DD			13:17 29SEP19	100	0.00	CHG	30SEP19

R.O. OPENED	READY	OPTIONS:
14:19 22AUG19	11:01 30SEP19	

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
				CORE CHARGE C		88.00	88.00
				2 745*818278N* RELEASE SPRING	10.74	6.41	12.82
538035 WHEN TEST DRIVING HEARD NOISE IN BRAKES. FOUND LEFT STEER AXLE BRAKE BROKEN. REPLACED BOTH STEER AXLE SHOES AND ALSO GREASE CHASSIS.							

VoMac Truck Sales & Service, Inc.

1255 S. Commerce Dr.
Seymour, IN 47274
812-523-4400
888-699-6225

1879 S. Old US 41
Vincennes, IN 47591
812-682-1730
800-869-6225

12242 Declaration Dr.
New Haven, IN 46774
260-749-5061
800-824-9354

10000 State Hwy. 57
Evansville, IN 47725
812-253-0025
800-776-6225

STATEMENT OF DISCLAIMER

The factory warranty constitutes all of the warranties with respect to the sale of this item/items. The Seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item/items.

Thank You!

DESCRIPTION	TOTALS
LABOR AMOUNT	5742.00
PARTS AMOUNT	31477.63
GAS, OIL, LUBE	0.00
SUBLET AMOUNT	0.00
MISC. CHARGES	75.00
TOTAL CHARGES	37294.63
LESS	0.00
SALES TAX	0.00
PLEASE PAY THIS AMOUNT	37294.63

CUSTOMER #: A13080

34024T

5717 E. Margaret Dr.
Terre Haute, IN 47803

SHORT HAUL INC
HERB

INVOICE

(812) 233-6406 (888) 482-6225
WWW.VOMACTRUCK.COM

6671 E COUNTY ROAD 300 N
GREENSBURG, IN 47240

PAGE 1

REMIT TO: 10000 State Hwy. 57 Evansville, IN 47725

HOME: 317-435-4841 CONT: 317-435-4841

BUS: CELL: SERVICE ADVISOR: 245 ANTHONY CIARAVINO

COLOR	YEAR	MAKE/MODEL		VIN	UNIT #	MILEAGE IN/ OUT	TAG
	16	MACK CXU613		1M1AW21YXGM052211		921365/921365	T2211
DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
01JAN15 DD			15:00 08OCT24	100	0.00	CHG	09OCT24

R.O. OPENED	READY	OPTIONS:			
19:11 01OCT24	08:13 09OCT24				
LINE OPCODE	TECH TYPE	HOURS	LIST	NET	TOTAL

A DIAG AND ESTIMATE FOR CLE/ATC/LIGHTNING BOLT/ ABS

99-000-0001 DIAG AND ESTIMATE FOR

CLE/ATC/LIGHTNING BOLT/ ABS

310 CPE 2.00

338.00 338.00

921365 #310 Connected to PTT and found multiple active and inactive faults. I started with active fault for ABS wheel speed sensor left steer axle. I unplugged the connector and tested chassis harness side and found no issues but the WSS is open circuit and will need to be replaced. While there I looked at the new steer axle brake chambers that got installed and found the clevis is only held on by about 1 or 2 threads and about to come off which will make driver loose front brakes. The rod on the brake chambers have been cut to short or wrong chambers have been installed and it does not look safe. I then moved on to fault codes for nox sensors and there is 4 fault codes active 2 for inlet and 2 for outlet and all these faults are for internal failure of nox sensors and both will need to be replaced. I then moved on to active fault for EGR flow where I performed the EGR flow test and found the cooler is restricted and not dropping turbo speed properly. Unit will need the EGR cooler and updated venturi tube replaced (both are original). Next fault was inactive for camshaft position sensor but with 15k counts, I tested the engine harness and found no issues but there is rubbed spots in the harness but we could start by replacing the camshaft position sensor and seeing how it performs. Next fault was active fault for #6 injector which is currently active even though unit is not missing, I performed cylinder balance test and found multiple cylinders with large differences but still within spec. I would like to remove #6 injector and inspect it along with the harness. If injectors appear to be old may think about replacing all injectors but the engine brake rockers will need to be inspected as well. Last I found a large coolant leak so I pressure tested system and found the radiator is cracked on drivers side and the water filter is also leaking around the seal.

B DIAG AND ESTIMATE AC FAN CONTROL NOT OPERATING CORRECTLY

VoMac Truck Sales & Service, Inc.

1255 S. Commerce Dr.
Seymour, IN 47274
812-823-4400
888-699-6225

12242 Declaration Dr.
New Haven, IN. 46774
260-749-5081
800-824-9354

1879 S. Old US 41
Vincennes, IN. 47591
812-882-1730
800-869-6225

10000 State Hwy. 57
Evansville, IN. 47725
812-253-0025
800-776-6225

STATEMENT OF DISCLAIMER

The factory warranty constitutes all of the warranties with respect to the sale of this item/items. The Seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item/items.

Thank You!

DESCRIPTION	TOTALS
LABOR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES	
TOTAL CHARGES	
LESS	
SALES TAX	
PLEASE PAY THIS AMOUNT	

CUSTOMER #: A13080

34024T

5717 E. Margaret Dr.

Terre Haute, IN 47803

(812) 233-6406 (888) 482-6225

WWW.VOMACTRUCK.COM



SHORT HAUL INC

HERB

6671 E COUNTY ROAD 300 N

GREENSBURG, IN 47240

HOME: 317-435-4841 CONT: 317-435-4841

BUS:

CELL:

PAGE 2

REMIT TO: 10000 State Hwy. 57 Evansville, IN 47725

SERVICE ADVISOR: 245 ANTHONY CIARAVINO

COLOR	YEAR	MAKE/MODEL		VIN		UNIT #	MILEAGE IN/ OUT		TAG
	16	MACK CXU613		1M1AW21YXGM052211			921365/921365		T2211
DEL DATE	PROD. DATE	WARR. EXP.	PROMISED		PO NO.	RATE	PAYMENT	INV. DATE	
01JAN15 DD			15:00 08OCT24		100	0.00	CHG	09OCT24	

R.O. OPENED	READY	OPTIONS:
19:11 01OCT24	08:13 09OCT24	

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

99-000-0001 DIAG AND ESTIMATE AC FAN CONTROL NOT OPERATING CORRECTLY

310 CPE 1.50

253.50 253.50

921365 #310 After testing the blower motor operation I found the issue appeared to be in the controller. I removed dash panels and controller and found the climate control unit has shorted out and the pins in the blower connection have melted, unit will need a new controller and new pins and connector installed on the dash harness.

C** REPLACE LEFT STEER AXLE WHEEL SPEED SENSOR

99-000-0001 REPLACE LEFT STEER AXLE WHEEL SPEED SENSOR

313 CPE 1.00

169.00 169.00

1 24344608 SENSOR

157.82

71.33 71.33

10 BD-C24706 CABLE TIE BLACK 3/16 X 15

0.63

0.56 5.60

1 FREIGHT FREIGHT

20.00

20.00 20.00

921365 313 Went to remove wheel speed sensor and found it was seized up in spindle. Removed wheel, backed off brake, removed drum and had to remove hub. Was able to get sensor out. Cleaned hole, installed new sensor. Installed hub and torqued to spec. Installed drum and wheel torqued lug nuts. Adjusted brake abs light is now out.

D** REPLACE BOTH NOX SENSORS

99-000-0001 REPLACE BOTH NOX SENSORS

313 CPE 1.50

253.50 253.50

1 22303390 SENSOR

805.62

559.92 559.92

CORE CHARGE C

99.00 99.00

1 22303391 SENSOR

805.62

559.92 559.92

CORE CHARGE C

99.00 99.00

20 BD-C24706 CABLE TIE BLACK 3/16 X 15

0.63

0.56 11.20

-1 22303390 CORE RETURN

99.00

99.00 -99.00

-1 22303391 CORE RETURN

99.00

99.00 -99.00

921365 313 Removed both inlet and outlet nox sensors and replaced with new. Performed data reset and ran regen.

VoMac Truck Sales & Service, Inc.

 1255 S. Commerce Dr.
Seymour, IN 47274
812-523-4400
888-699-6225

 12242 Declaration Dr.
New Haven, IN. 46774
260-749-5061
800-824-9354

 1879 S. Old US 41
Vincennes, IN. 47591
812-882-1730
800-869-6225

 10000 State Hwy. 57
Evansville, IN. 47725
812-253-0025
800-776-6225

STATEMENT OF DISCLAIMER
The factory warranty constitutes all of the warranties with respect to the sale of this item/items. The Seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item/items.

Thank You!

DESCRIPTION	TOTALS
LABOR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES	
TOTAL CHARGES	
LESS	
SALES TAX	
PLEASE PAY THIS AMOUNT	

CUSTOMER #: A13080

34024T

5717 E. Margaret Dr.

Terre Haute, IN 47803

(812) 233-6406 |(888) 482-6225

WWW.VOMACTRUCK.COM



SHORT HAUL INC

HERB

6671 E COUNTY ROAD 300 N

GREENSBURG, IN 47240

HOME:317-435-4841 CONT:317-435-4841

BUS:

CELL:

PAGE 3

REMIT TO: 10000 State Hwy. 57 Evansville, IN 47725

SERVICE ADVISOR: 245 ANTHONY CIARAVINO

COLOR	YEAR	MAKE/MODEL	VIN	UNIT #	MILEAGE IN/ OUT	TAG	
	16	MACK CXU613	1M1AW21YXGM052211		921365/921365	T2211	
DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
01JAN15 DD			15:00 08OCT24	100	0.00	CHG	09OCT24

R.O. OPENED READY OPTIONS:

19:11 01OCT24 08:13 09OCT24

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

E** REPLACE RADIATOR AND WATER FILTER

99-000-0001 REPLACE RADIATOR AND WATER FILTER

313 CPE 3.96

328 CPE 2.04

6.00

1014.00 1014.00

1 21590718 HEAT EXCHANGER

257.26 178.80 178.80

1 FREIGHT FREIGHT

25.00 25.00 25.00

1 21053033 HOSE

37.70 26.20 26.20

2 1675066 SEALING RING

7.56 5.25 10.50

1 21096684 O-RING

2.72 1.89 1.89

1 21937298 COOLANT FILTER

21.20 12.57 12.57

3 MBL123130 M-ATF D/M CASE 6X1UQL .RL

12.82 7.82 23.46

921365 328 Pulled the radiator out of the truck. 313 Transferred parts to new radiator and installed coolant pack. When installing the skid plate under radiator found that the power steering cooler was bent and busted. Installed new power steering cooler and filled fluid

F** REPLACE EGR COOLER WITH NEW PRESSURE SENSOR AND VENTURI TUBE

99-000-0001 REPLACE EGR COOLER WITH NEW PRESSURE

SENSOR AND VENTURI TUBE

313 CPE 5.00

845.00 845.00

1 85136428 EGR COOLER

2760.92 1918.90 1918.90

CORE CHARGE C

275.00 275.00

1 21434720 CONNECTION PIPE

43.62 30.32 30.32

1 85137676 INSTALLATION KIT

202.70 140.88 140.88

1 85149707 SPARE PARTS KIT

933.22 648.61 648.61

-1 85136428 CORE RETURN

275.00 275.00 -275.00

921365 313 Disconnected and removed turbo, removed egr c pipe.

Removed egr cooler, installed new egr cooler with new connection pipe.

Installed c pipe with new gaskets and clamps. Installed turbo, hooked

up all lines. Removed and installed new venturi pipe and egr

differential pressure sensor. Performed data reset

G** PULL AND CHECK #6 INJECTOR AND EXHAUST ROCKERS

VoMac Truck Sales & Service, Inc.

1255 S. Commerce Dr.
Seymour, IN 47274
812-523-4400
888-699-6225

12242 Declaration Dr.
New Haven, IN. 46774
260-749-5061
800-824-9354

1879 S. Old US 41
Vincennes, IN. 47591
812-882-1730
800-869-6225

10000 State Hwy. 57
Evansville, IN. 47725
812-253-0025
800-776-6225

STATEMENT OF DISCLAIMER

The factory warranty constitutes all of the warranties with respect to the sale of this item/items. The Seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item/items.

DESCRIPTION	TOTALS
LABOR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES	
TOTAL CHARGES	
LESS	
SALES TAX	
PLEASE PAY THIS AMOUNT	

Thank You!

CUSTOMER #: A13080

34024T

5717 E. Margaret Dr.

Terre Haute, IN 47803

(812) 233-6406 (888) 482-6225

WWW.VOMACTRUCK.COM



SHORT HAUL INC

HERB

6671 E COUNTY ROAD 300 N

GREENSBURG, IN 47240

HOME:317-435-4841 CONT:317-435-4841

BUS: CELL:

PAGE 4

REMIT TO: 10000 State Hwy. 57 Evansville, IN 47725

SERVICE ADVISOR: 245 ANTHONY CIARAVINO

COLOR	YEAR	MAKE/MODEL	VIN	UNIT #	MILEAGE IN/ OUT	TAG	
	16	MACK CXU613	1M1AW21YXGM052211		921365/921365	T2211	
DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
01JAN15 DD			15:00 08OCT24	100	0.00	CHG	09OCT24

R.O. OPENED		READY	OPTIONS:				
19:11 01OCT24		08:13 09OCT24					
LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL

99-000-0001 PULL AND CHECK #6 INJECTOR AND EXHAUST ROCKERS

313 CPE 7.00

1 85020428 UNIT INJECTOR, REMAN
CORE CHARGE C

2 1677370 SEALING RING

1 20526428 SEALING RING

1 21515329 INJECTOR SLEEVE

6 21406640 ROCKER ARM

CORE CHARGE C

1 FREIGHT FREIGHT

-1 85020428 CORE RETURN

1 BD-BD1019 (BD1019-1)NC BRAKE CLNR,1

1 8192804 FLANGE SCREW

-6 21406640 CORE RETURN

2 PSNAFC11100F 50/50 ELC NOAT

921365 313 Removed valve cover, pulled rocker shaft. Inspected all rockers found all six plunger to be cracked. Pulled number six injector and found it was bad. Pulled cup, cleaned bore. Installed new cup and injector and torqued to spec with new hold down bolts. Removed and installed all six exhaust rockers with new. Installed rocker shaft and torqued to spec. Ran overhead, installed valve cover. Programmed injector trim code, pumped coolant back into truck. Primed fuel system and started the truck. Checked for leaks and didn't see any at this time.

H** REPLACE CAM SHAFT SENSOR AND PIG TAIL

99-000-0001 REPLACE CAM SHAFT SENSOR AND PIG TAIL

313 CPE 1.00

1 21426987 SPEED SENSOR

1 85130732 CONNECTOR

2 TERM SEAL TERMINAL

921365 313 Removed interior center hump. Removed and installed new cam shaft sensor with new pigtail and reassembled interior.

VoMac Truck Sales & Service, Inc.

1255 S. Commerce Dr.
Seymour, IN 47274
812-523-4400
888-699-6225

12242 Declaration Dr.
New Haven, IN 46774
260-749-5061
800-824-9354

1879 S. Old US 41
Vincennes, IN 47591
812-882-1730
800-869-6225

10000 State Hwy. 57
Evansville, IN 47725
812-253-0025
800-776-6225

STATEMENT OF DISCLAIMER

The factory warranty constitutes all of the warranties with respect to the sale of this item/items. The Seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item/items.

Thank You!

DESCRIPTION	TOTALS
LABOR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES	
TOTAL CHARGES	
LESS	
SALES TAX	
PLEASE PAY THIS AMOUNT	

CUSTOMER #: A13080

34024T

5717 E. Margaret Dr.

Terre Haute, IN 47803

(812) 233-6406 (888) 482-6225

WWW.VOMACTRUCK.COM



SHORT HAUL INC

HERB

6671 E COUNTY ROAD 300 N

GREENSBURG, IN 47240

HOME: 317-435-4841 CONT: 317-435-4841

BUS:

CELL:

SERVICE ADVISOR: 245 ANTHONY CIARAVINO

PAGE 5

REMIT TO: 10000 State Hwy. 57 Evansville, IN 47725

COLOR	YEAR	MAKE/MODEL	VIN	UNIT #	MILEAGE IN/ OUT	TAG	
	16	MACK CXU613	1M1AW21YXGM052211		921365/921365	T2211	
DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
01JAN15 DD			15:00 08OCT24	100	0.00	CHG	09OCT24

R.O. OPENED	READY	OPTIONS:
19:11 01OCT24	08:13 09OCT24	

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

I** REPLACE HVAC CONTROLLER AND BLOWER MOTOR PLUG. ALL THE PINS ARE MELTED OUT

99-000-0001 REPLACE HVAC CONTROLLER AND BLOWER

MOTOR PLUG. ALL THE PINS ARE MELTED OUT

313 CPE 1.00

1 20992943 CONTROL UNIT

258.56

169.00

169.00

2 7526*12064999* LOCK SECONDARY TERMINAL

5.30

3.68

7.36

1 7526*12162595* TERMINAL FEMALE

2.74

1.90

1.90

7 7526*12015858* TERMINAL FEMALE

1.44

1.00

7.00

1 20897122 CONNECTOR

7.92

5.50

5.50

921365 313 Installed blower motor connector with new pins.

Installed hvac controller and all is now working as should.

J** REPLACE BATTERIES

99-000-0001 REPLACE BATTERIES

313 CPE 0.50

84.50

84.50

4 1726*M311000* GROUP 31 BATTERY

183.28

105.95

423.80

CORE CHARGE C

118.80

118.80

-4 1726*M311000* CORE RETURN

29.70

29.70

-118.80

921365 313 Charged batteries and tested each battery and found that all four batteries were bad. Removed batteries cleaned all terminals and installed new batteries and sprayed terminals with battery protector

VoMac Truck Sales & Service, Inc.

1255 S. Commerce Dr.
Seymour, IN 47274
812-623-4400
888-699-6225

12242 Declaration Dr.
New Haven, IN. 46774
260-749-5061
800-824-9354

1879 S. Old US 41
Vincennes, IN. 47591
812-882-1730
800-869-6225

10000 State Hwy. 57
Evansville, IN. 47725
812-253-0025
800-776-6225

STATEMENT OF DISCLAIMER

The factory warranty constitutes all of the warranties with respect to the sale of this item/items. The Seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item/items.

Thank You!

DESCRIPTION	TOTALS
LABOR AMOUNT	4478.50
PARTS AMOUNT	8833.75
GAS, OIL, LUBE	0.00
SUBLET AMOUNT	0.00
MISC. CHARGES	100.00
TOTAL CHARGES	13412.25
LESS	0.00
SALES TAX	0.00
PLEASE PAY THIS AMOUNT	13412.25