

03757112

PERIODIC MANDATORY VEHICLE INSPECTION CERTIFICATE



Vehicle Standards and Inspection  
Box 45064 Regent Postal Outlet  
Winnipeg, MB, R2C 5C7  
1-204-985-0920

DECAI  
Manitoba  
A833204

Date Inspection Started: DAY 21, MO. 05, YR. 215  
 Date Inspection Completed: DAY 28, MO. 05, YR. 215  
 Inspection Expiry Date: DAY 31, MO. 05, YR. 216

Station Number: A152145  
 Station Name: Pagan Point Colony  
 City: Souda West  
 Station Phone Number: 2672476

Mechanic Number: M187106  
 Mechanic Signature: [Signature]  
 Station Phone Number: 2672476

Vehicle Owner: Milltown Colony Farms LTD  
 Address: Box 250  
 City: Elsie, Province: MB, Postal Code: R0H 0H0, Phone: [Blank]

Pass/Safe Vehicle  
 Fail/Unsafe Vehicle  
 Fail/Hazardous

Licence Number: SM23711, Prov. MB, NSC # [Blank], Odometer Reading [Blank], Odom. Type [km/mi]

Vehicle Identification Number: QWVVF101B1B41X16029175, Make: Niss, Model: Step Down, Year: 1997, Unit # [Blank]

Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

Truck  GVWR [ ] KGS  Truck Tractor  Trailer  Semi-Trailer  Bus  School Bus  Coach Bus

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section																																																														
		Section 1 - Power Train: Defects (if any)																																																														
X		Section 2 Suspension: Defects (if any)																																																														
X		Section 3 - Brake Systems: 3H (3A) Defects (if any) Circle Brake Type																																																														
		Brake Inspection Type: A B C D E Circle appropriate Letter for Internal Brake Component Inspection																																																														
		<table border="1"> <thead> <tr> <th rowspan="2">Axle</th> <th colspan="2">Lining</th> <th colspan="2">Drum/Rotor</th> <th colspan="2">Stroke</th> </tr> <tr> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>3/8</td> <td>3/8</td> <td>16.58</td> <td>16.57</td> <td>1.5</td> <td>1.5</td> </tr> <tr> <td>2</td> <td>7/16</td> <td>3/8</td> <td>16.59</td> <td>16.59</td> <td>1.5</td> <td>1.5</td> </tr> <tr> <td>3</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table>	Axle	Lining		Drum/Rotor		Stroke		L	R	L	R	L	R	1	3/8	3/8	16.58	16.57	1.5	1.5	2	7/16	3/8	16.59	16.59	1.5	1.5	3							4							5																				
Axle	Lining			Drum/Rotor		Stroke																																																										
	L	R	L	R	L	R																																																										
1	3/8	3/8	16.58	16.57	1.5	1.5																																																										
2	7/16	3/8	16.59	16.59	1.5	1.5																																																										
3																																																																
4																																																																
5																																																																
		Section 4 - Steering: Defects (if any)																																																														
X		Section 5 - Instruments & Auxiliary Equipment: Defects (if any)																																																														
X	X	Section 6 - Lamps: Defects (if any) b) type marking (front right)																																																														
		Section 7 - Electrical System: Defects (if any)																																																														
X	X	Section 8 - Body: Defects (if any) d) bent broken (cracked - front lift)																																																														
X	X	Section 9 - Tire & Wheel: Defects (if any) b) condition - (flat spot)																																																														
		<table border="1"> <thead> <tr> <th rowspan="2">Axle</th> <th colspan="4">Tread Depth</th> <th colspan="4">Air Pressure</th> </tr> <tr> <th colspan="2">Initial</th> <th colspan="2">Corrected</th> <th colspan="2">Initial</th> <th colspan="2">Corrected</th> </tr> <tr> <th></th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>7m</td> <td>2m</td> <td>2m</td> <td>2m</td> <td>100</td> <td>100</td> <td>100</td> <td>100</td> </tr> <tr> <td>3</td> <td>2m</td> <td>2m</td> <td>2m</td> <td>2m</td> <td>100</td> <td>100</td> <td>100</td> <td>100</td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table>	Axle	Tread Depth				Air Pressure				Initial		Corrected		Initial		Corrected			L	R	L	R	L	R	L	R	1	7m	2m	2m	2m	100	100	100	100	3	2m	2m	2m	2m	100	100	100	100	4									5								
Axle	Tread Depth				Air Pressure																																																											
	Initial		Corrected		Initial		Corrected																																																									
	L	R	L	R	L	R	L	R																																																								
1	7m	2m	2m	2m	100	100	100	100																																																								
3	2m	2m	2m	2m	100	100	100	100																																																								
4																																																																
5																																																																
X		Section 10 - Coupling Devices: Defects (if any)																																																														

- THIS INSPECTION IS NOT A WARRANTY -  
 This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks: [Blank]

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition