

04050812

PERIODIC MANDATORY VEHICLE INSPECTION CERTIFICATE

Manitoba

Vehicle Standards and Ins. Div. 45024 Regent Postal C. Winnipeg, MB, R2G 1G7 1-204-985-0920

Manitoba

C005908

Date Inspection Started 02 10 25 DAY MO. YR.

Station Number A5302 VIRDEN TRUCK & TRAIL

Date Inspection Completed 03 10 25 DAY MO. YR.

Mechanic Number 1106216 Station Name City (204) 748-6887 Station Phone Number

Inspection Expiry Date 31 10 26 DAY MO. YR.

Vehicle Owner BOYES CONTRACTING Address BOX 63 HARTNEY MB Postal Code R0M 0X0 Phone

Pass/Safe Vehicle  Fail/Unsafe Vehicle  Fail/Hazardous  Confirmed legible Vehicle Identification Number on vehicle  Licence Number C6W1157 Prov. MB NSC # MB1203540 Odometer Reading 755,520 Odom. Type km mi Vehicle Identification Number 11XK1D1B01XX15J97816169 Make KW Model T800 Year 05 Unit # 9

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

Truck  GVWR  KGS  Truck Tractor  Trailer  Semi-Trailer  Bus  School Bus  Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

Mark "X" under "B" when item Defective "XX" under "B" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section

X Section 1 - Power Train: Defects (if any)

X Section 2 Suspension: Defects (if any)

X X Section 3 - Brake Systems: 3H 3A Defects (if any) Circle Brake Type

16 D BRAKE ADJUSTER INOPERATIVE  
19 D ABS MODULATOR VALVE LEAKING

Brake Inspection Type: A B C D E Circle appropriate Letter for Internal Brake Component Inspection

Axle	Lining		Drum/Rotor		Stroke		
	L	R	L	R	L	R	
1	.70	.50	16.51	16.52	1	1	
2	.59	.60	16.54	16.54	1.25	1.25	
3	.73	.58	16.52	16.56	1.25	1.25	
4							
5							
Final Measurement						1 INCHES	

X Section 4 - Steering: Defects (if any)

X Section 5 - Instruments & Auxiliary Equipment: Defects (if any)

X X Section 6 - Lamps: Defects (if any)

1B P-SIDE HEADLAMP CRACK  
11 LICENSE PLATE LAMP INOPERATIVE

X Section 7 - Electrical System: Defects (if any)

X X Section 8 - Body: Defects (if any)

13B WINDSHIELD CRACK LONGER THAN LEGAL LIMIT.

X Section 9 - Tire & Wheel: Defects (if any)

Axle	Tread Depth				Air Pressure			
	Initial		Corrected		Initial		Corrected	
	L	R	L	R	L	R	L	R
1	15	15			100	100		
2	24	20	20	20	100	100	100	100
3	15	19	14	15	100	100	100	100
4								
5								

X Section 10 - Coupling Devices: Defects (if any)

- THIS INSPECTION IS NOT A WARRANTY - prescribed by the Vehicle Safety Inspection Regulation but does not