

03981520

PERIODIC MANDATORY VEHICLE
INSPECTION CERTIFICATE

Manitoba

Vehicle Standards and Inspections
Box 45064 Regent Postal Outlet
Winnipeg, MB, R2C 5C7
1-204-985-0920

Manitoba

Date Inspection Started DAY: 28 MO: 07 YR: 25	Station Number A0420	Station Name Irwin Auto LTD	City Saskatoon	A976029
Date Inspection Completed DAY: 06 MO: 08 YR: 25	Mechanic Number L0641	Mechanic Signature <i>[Signature]</i>	City Saskatoon	Station Phone Number 204-662-4524
Inspection Expiry Date DAY: 31 MO: 08 YR: 26	Vehicle Owner Fiasco Farms LTD			
	Address Box 119 Melita MB R0M 1T0 204-522-6040			
<input checked="" type="checkbox"/> Pass/Safe Vehicle <input checked="" type="checkbox"/> Fail/Unsafe Vehicle <input type="checkbox"/> Fail/Hazardous	Licence Number Z315H1	Prov. MB	NSC #	Odometer Reading
	Vehicle Identification Number 2C92322E3E1086617	Make Canca	Model Grain	Year 2013
	<input checked="" type="checkbox"/> Confirmed legible Vehicle Identification Number on vehicle			

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

Truck GVWR KGS Truck Tractor Trailer Semi-Trailer Bus School Bus Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section
X		Section 1 - Power Train: Defects (if any)
X		Section 2 Suspension: Defects (if any)
X	X	Section 3 - Brake Systems: 3H 3A Defects (if any) Circle Brake Type 3A-13-e air leak at tank 3A-14-a brake pot leaking 3A-15-e drums fast spin 3A-16-a screws seized
X		Section 4 - Steering: Defects (if any)
X		Section 5 - Instruments & Auxiliary Equipment: Defects (if any)
X	X	Section 6 - Lamps: Defects (if any) 6-1-2 side marker missing 6-1-1 license plate light rings
X		Section 7 - Electrical System: Defects (if any)
X		Section 8 - Body: Defects (if any)
X	X	Section 9 - Tire & Wheel: Defects (if any) 9-4-a low tire pressure
X		Section 10 - Coupling Devices: Defects (if any)

Axle	Tread Depth				Air Pressure			
	Initial		Corrected		Initial		Corrected	
	L	R	L	R	L	R	L	R
1	12	15	19	19	100	100	93	0
2	16	15	16	17	90	0	93	90
3	14	14	14	13	90	85	93	93
4								
5								

- THIS INSPECTION IS NOT A WARRANTY -
This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: Signature Date:

PRESENT THIS COPY WHEN REGISTERING VEHICLE

2013 Canca 2013 MCC © 2023. All rights reserved. - 9355