

# EM Work Order History By Equipment

Equipment:

All Work Orders

All Categories

| ----- Standard Maintenance ----- |                                   |               |      |                       | Date   |          |          |          |            |
|----------------------------------|-----------------------------------|---------------|------|-----------------------|--------|----------|----------|----------|------------|
| WO                               | Item                              | Group         | Item | Cost Code             | In/Out | Status   | Complete | Odometer | Hour Meter |
| Equipment:                       |                                   | Tractor 3630T |      |                       |        |          |          |          |            |
| 8435                             | 1 9/30/16 Right window latch brc  |               |      | 210 Operators Station | I      | COMPLETE | 07/19/18 |          | 2,400      |
| 8594                             | 1 PM-1 (645 hrs)                  | PM-1          | 1    | 90 PM                 | I      | COMPLETE | 11/01/16 |          | 645        |
| 9289                             | 1 PM-1 (931 hrs)                  | PM-1          | 1    | 90 PM                 | I      | COMPLETE | 05/03/17 |          | 931        |
| 9670                             | 1 PM-1 (1,210 hrs)                | PM-1          | 1    | 90 PM                 | I      | COMPLETE | 06/22/17 |          | 1,210      |
| 10193                            | 1 PM-1 (1541 HRS)                 | PM-1          | 1    | 90 PM                 | I      | COMPLETE | 08/21/17 |          | 1,541      |
| 10437                            | 1 leaking pipe plug               |               |      | 150 Hyd System        | I      | COMPLETE | 10/03/17 |          | 1,780      |
| 10491                            | 1 PM-1 (1777 hrs)                 | PM-1          | 1    | 90 PM                 | I      | COMPLETE | 10/09/17 |          | 1,777      |
| 10511                            | 1 PM-2 (1777 hrs)                 | PM-2          | 1    | 90 PM                 | I      | COMPLETE | 10/12/17 |          | 1,777      |
|                                  | 2 PM-3 (1777 hrs)                 | PM-3          | 1    | 90 PM                 | I      | COMPLETE | 10/12/17 |          | 1,777      |
| 10780                            | 1 PM-1 (1,992 hrs.)               | PM-1          | 1    | 90 PM                 | I      | COMPLETE | 11/21/17 |          | 1,992      |
| 10811                            | 1 Replace engine fan belts        |               |      | 140 Cooling System    | I      | COMPLETE | 11/29/17 |          | 2,027      |
| 11721                            | 1 Replace LH rear track           |               |      | 190 Undercarriage     | I      | COMPLETE | 05/16/18 |          | 2,195      |
|                                  | 2 Replace mid-rollers ( 4 )       |               |      | 190 Undercarriage     | I      | COMPLETE | 05/22/18 |          | 2,200      |
| 11898                            | 1 PM-1                            | PM-1          | 1    | 90 PM                 | I      | COMPLETE | 06/07/18 |          | 2,230      |
| 12053                            | 1 PM-2                            | PM-2          | 1    | 90 PM                 | I      | COMPLETE | 06/26/18 |          | 2,299      |
| 12171                            | 1 Replace RH rear track           |               |      | 190 Undercarriage     | I      | COMPLETE | 07/18/18 |          | 2,458      |
| 12235                            | 1 PM-1/Elliott/2485 hrs.          | PM-1          | 1    | 90 PM                 | I      | COMPLETE | 07/25/18 |          | 2,485      |
| 12472                            | 1 Replace LH front track          |               |      | 190 Undercarriage     | I      | COMPLETE | 08/28/18 |          | 2,660      |
| 12710                            | 1 PM-1                            | PM-1          | 1    | 90 PM                 | I      | COMPLETE | 09/26/18 |          | 2,781      |
| 12803                            | 1 Replace RH front track          |               |      | 190 Undercarriage     | I      | COMPLETE | 10/15/18 |          | 2,848      |
| 12869                            | 1 Replace hyd steering cylinder I |               |      | 150 Hyd System        | I      | COMPLETE | 10/25/18 |          | 2,928      |
| 13133                            | 1 PM-1                            | PM-1          | 1    | 90 PM                 | I      | COMPLETE | 12/05/18 |          | 3,128      |
| 13249                            | 1 PM-2                            | PM-2          | 1    | 90 PM                 | I      | COMPLETE | 01/16/19 |          | 3,171      |
|                                  | 2 PM-3                            | PM-3          | 1    | 90 PM                 | I      | COMPLETE | 01/16/19 |          | 3,171      |
| 13868                            | 1 PM-1                            | PM-1          | 1    | 90 PM                 | I      | COMPLETE | 05/15/19 |          | 3,365      |
| 14783                            | 1 PM-1                            | PM-1          | 1    | 90 PM                 | I      | COMPLETE | 09/06/19 |          | 3,718      |
| 14996                            | 1 PM-2                            | PM-2          | 1    | 90 PM                 | I      | COMPLETE | 09/26/19 |          | 3,775      |
| 15462                            | 1 PM-1                            | PM-1          | 1    | 90 PM                 | I      | COMPLETE | 12/03/19 |          | 4,058      |
| 16555                            | 1 PM-1                            | PM-1          | 1    | 90 PM                 | I      | COMPLETE | 06/02/20 |          | 4,277      |
| 16699                            | 1 PM-1                            | PM-1          | 1    | 90 PM                 | I      | COMPLETE | 06/17/20 |          | 4,162      |
|                                  | 2 PM-2                            | PM-2          | 1    | 90 PM                 | I      | COMPLETE | 06/17/20 |          | 4,162      |
|                                  | 3 PM-3                            | PM-3          | 1    | 90 PM                 | I      | COMPLETE | 06/17/20 |          | 4,162      |
|                                  | 4 Repair Hitch                    |               |      | 170 Frame / Body      | I      | COMPLETE | 06/17/20 |          | 4,162      |
|                                  | 5 Replace Wiring Harness          |               |      | 180 Electrical        | I      | COMPLETE | 06/17/20 |          | 4,162      |
|                                  | 6 Replace Wiper                   |               |      | 210 Operators Station | I      | COMPLETE | 06/17/20 |          | 4,162      |
|                                  | 7 Replace Fan & Components        |               |      | 140 Cooling System    | I      | COMPLETE | 06/17/20 |          | 4,162      |
|                                  | 8 Upgrade Hydraulic Pump          |               |      | 150 Hyd System        | I      | COMPLETE | 06/17/20 |          | 4,162      |
|                                  | 9 Replace Lights                  |               |      | 180 Electrical        | I      | COMPLETE | 06/17/20 |          | 4,162      |
|                                  | 10 Replace Mirrors                |               |      | 210 Operators Station | I      | COMPLETE | 06/17/20 |          | 4,162      |
|                                  | 11 Replace Sterring Sensor        |               |      | 180 Electrical        | I      | COMPLETE | 06/17/20 |          | 4,162      |
|                                  | 12 Replace Brakes                 |               |      | 300 Brakes            | I      | COMPLETE | 06/17/20 |          | 4,162      |
|                                  | 13 Upgrades                       |               |      | 170 Frame / Body      | I      | COMPLETE | 06/17/20 |          | 4,162      |
|                                  | 14 Repair Undercarriage - Midro   |               |      | 190 Undercarriage     | I      | COMPLETE | 06/17/20 |          | 4,162      |
|                                  | 15 Replace Hydraulic Hoses / Lii  |               |      | 150 Hyd System        | I      | COMPLETE | 06/17/20 |          | 4,162      |
| 16963                            | 1 PM-1                            | PM-1          | 1    | 90 PM                 | I      | COMPLETE | 07/20/20 |          | 4,400      |
| 17656                            | 1 PM-1                            | PM-1          | 1    | 90 PM                 | I      | COMPLETE | 10/14/20 |          | 4,709      |

# EM Work Order History By Equipment

Equipment:

All Work Orders

All Categories

| ----- Standard Maintenance ----- |                                    |               |      |                          | Date   |          |          |             |            |
|----------------------------------|------------------------------------|---------------|------|--------------------------|--------|----------|----------|-------------|------------|
| WO                               | Item                               | Group         | Item | Cost Code                | In/Out | Status   | Complete | Odometer    | Hour Meter |
| Equipment:                       |                                    | Tractor 3630T |      |                          |        |          |          | - Continued |            |
| 17656                            | 2 PM-2                             | PM-2          | 1    | 90 PM                    | I      | COMPLETE | 10/14/20 |             | 4,709      |
| 18781                            | 1 PM-1                             | PM-1          | 1    | 90 PM                    | I      | COMPLETE | 04/30/21 |             | 5,020      |
| 19173                            | 1 Replace Hydraulic & Transmis     |               |      | 150 Hyd System           | I      | COMPLETE | 06/17/21 |             | 5,226      |
| 19282                            | 1 PM-1                             | PM-1          | 1    | 90 PM                    | I      | COMPLETE | 07/01/21 |             | 5,282      |
| 19314                            | 1 Replace 1 Track                  |               |      | 190 Undercarriage        | I      | COMPLETE | 07/06/21 |             | 5,301      |
| 19513                            | 1 R&I Left Rear Track              |               |      | 190 Undercarriage        | I      | COMPLETE | 07/28/21 |             | 5,380      |
| 19564                            | 1 return hose blown at articulatio |               |      | 150 Hyd System           | I      | COMPLETE | 08/05/21 |             |            |
| 19575                            | 1 R&I Right Rear Track SN: TM1     |               |      | 190 Undercarriage        | I      | COMPLETE | 07/15/21 |             | 5,311      |
| 19768                            | 1 PM-1                             | PM-1          | 1    | 90 PM                    | I      | COMPLETE | 08/25/21 |             | 5,488      |
|                                  | 2 PM-2                             | PM-2          | 1    | 90 PM                    | I      | COMPLETE | 08/25/21 |             | 5,488      |
| 20157                            | 1 shift control quit upshifting    |               |      | 210 Operators Station    | I      | COMPLETE | 11/01/21 |             |            |
| 20425                            | 1 PM-1                             | PM-1          | 1    | 90 PM                    | I      | COMPLETE | 11/17/21 |             | 5,949      |
|                                  | 2 PM-2                             | PM-2          | 1    | 90 PM                    | I      | COMPLETE | 11/17/21 |             | 5,949      |
|                                  | 3 PM-3                             | PM-3          | 1    | 90 PM                    | I      | COMPLETE | 11/17/21 |             | 5,949      |
| 21063                            | 1 Check over                       |               |      | 170 Frame / Body         | I      | COMPLETE | 03/25/22 |             | 6,087      |
|                                  | 2 new master switch                |               |      | 170 Frame / Body         | I      | COMPLETE | 03/25/22 |             | 6,087      |
|                                  | 3 R+ R left mirror                 |               |      | 170 Frame / Body         | I      | COMPLETE | 03/25/22 |             | 6,087      |
|                                  | 4 Right hand Fan guard             |               |      | 140 Cooling System       | I      | COMPLETE | 03/25/22 |             | 6,087      |
|                                  | 5 Steering shaft update            |               |      | 210 Operators Station    | I      | COMPLETE | 03/25/22 |             | 6,087      |
|                                  | 6 R+ R two bogies                  |               |      | 190 Undercarriage        | I      | COMPLETE | 03/25/22 |             | 6,087      |
|                                  | 7 Paint / Decal                    |               |      | 170 Frame / Body         | I      | COMPLETE | 03/25/22 |             | 6,087      |
|                                  | 8 R&R Rt. Hand Turn Signal         |               |      | 180 Electrical           | I      | COMPLETE | 03/25/22 |             | 6,087      |
|                                  | 9 R&I (4) Idlers                   |               |      | 190 Undercarriage        | I      | COMPLETE | 03/25/22 |             | 6,087      |
|                                  | 10 Rebuild Differentials / Rick M. |               |      | 130 Power Train          | I      | COMPLETE | 03/25/22 |             | 6,087      |
|                                  | 11 Latch                           |               |      | 170 Frame / Body         | I      | COMPLETE | 03/25/22 |             | 6,087      |
|                                  | 12 Track Guard Delete Kit          |               |      | 190 Undercarriage        | I      | COMPLETE | 03/25/22 |             | 6,087      |
| 21847                            | 1 Replace Air Filters              |               |      | 90 PM                    | I      | COMPLETE | 05/20/22 |             |            |
| 21922                            | 1 PM-1                             | PM-1          | 1    | 90 PM                    | I      | COMPLETE | 05/24/22 |             | 6,295      |
| 22661                            | 1 PM-2                             | PM-2          | 1    | 90 PM                    | I      | COMPLETE | 07/19/22 |             | 6,460      |
| 22949                            | 1 Wash                             |               |      | 170 Frame / Body         | I      | COMPLETE | 08/19/22 |             |            |
| 23014                            | 1 PM-1                             | PM-1          | 1    | 90 PM                    | I      | COMPLETE | 08/16/22 |             | 6,597      |
| 23253                            | 1 Rear light pigtail ripped out    |               |      | 180 Electrical           | I      | COMPLETE | 10/07/22 |             |            |
|                                  | 2 monitor gone, exchange with o    |               |      | 180 Electrical           | I      | COMPLETE | 10/07/22 |             |            |
|                                  | 3 Replace bolts in driveshaft looq |               |      | 130 Power Train          | I      | COMPLETE | 10/07/22 |             |            |
| 23304                            | 1 Hyd leak                         |               |      | 170 Frame / Body         | I      | COMPLETE | 09/15/22 |             | 6,623      |
| 24188                            | 1 PM-1                             | PM-1          | 1    | 90 PM                    | I      | COMPLETE | 11/14/22 |             | 6,876      |
| 25257                            | 1 PM-2                             | PM-2          | 1    | 90 PM                    | I      | COMPLETE | 03/29/23 |             | 6,916      |
|                                  | 2 PM-3                             | PM-3          | 1    | 90 PM                    | I      | COMPLETE | 03/29/23 |             | 6,916      |
| 25645                            | 1 Replace alternator               |               |      | 180 Electrical           | I      | PENDING  |          |             |            |
| 25701                            | 1 Wash for Repairs                 |               |      | 170 Frame / Body         | I      | PENDING  |          |             |            |
| WA48758                          | 1 Replaced hydraulic hose          |               |      | 150 Hyd System           | I      | COMPLETE | 04/21/17 |             | 886        |
| WV40650                          | 1 Installed reman injector & clear |               |      | 120 Fuel System          | I      | COMPLETE | 10/24/16 |             | 644        |
| WV40712                          | 1 Replaced fuel pump relay         |               |      | 120 Fuel System          | I      | COMPLETE | 10/28/16 |             | 667        |
| WV40864                          | 1 T/S engine/ECM                   |               |      | 160 Engine               | I      | COMPLETE | 11/15/16 |             | 732        |
| WV42521                          | 1 Flashed updated aftertreatmer    |               |      | 110 Air Intake / Exhaust | I      | COMPLETE | 06/20/17 |             | 1,168      |
| WV42723                          | 1 Installed new right rear track   |               |      | 190 Undercarriage        | I      | COMPLETE | 07/11/17 |             | 1,302      |

# EM Work Order History By Equipment

Equipment:

All Work Orders

All Categories

| WO         | Item                               | Group         | Item | Cost Code                | In/Out | Status   | Date<br>Complete | Odometer | Hour Meter  |
|------------|------------------------------------|---------------|------|--------------------------|--------|----------|------------------|----------|-------------|
| Equipment: |                                    | Tractor 3630T |      |                          |        |          |                  |          | - Continued |
| WV42949    | 1 HOOK UP SCRAPER                  |               |      | 170 Frame / Body         | I      | COMPLETE | 07/31/17         |          | 1,448       |
| WV43262    | 1 Replace boogie wheel             |               |      | 190 Undercarriage        | I      | COMPLETE | 09/01/17         |          | 1,568       |
| WV48179    | 1 T-S Engine Fault Code Alarm      |               |      | 180 Electrical           | I      | COMPLETE | 04/29/19         |          | 3,343       |
| WV48515    | 1 R&I Left Rear Track              |               |      | 190 Undercarriage        | I      | COMPLETE | 06/06/19         |          | 3,408       |
| WV49193    | 1 REPLACE TRACK - RIGHT RI         |               |      | 190 Undercarriage        | I      | COMPLETE | 08/02/19         |          | 3,607       |
| WV49314    | 1 Repair Wiring / Fuse             |               |      | 180 Electrical           | I      | COMPLETE | 08/15/19         |          | 3,633       |
| WV49416    | 1 Repair Hydraulic Leak            |               |      | 150 Hyd System           | I      | COMPLETE | 08/23/19         |          | 3,679       |
| WV49424    | 1 T-S Engine                       |               |      | 160 Engine               | I      | COMPLETE | 09/03/19         |          | 3,713       |
|            | 2 R&I Fan Belts                    |               |      | 140 Cooling System       | I      | COMPLETE | 09/03/19         |          | 3,713       |
|            | 3 Install Reman Injector           |               |      | 160 Engine               | I      | COMPLETE | 09/03/19         |          | 3,713       |
| WV49610    | 1 Repair Hydraulic Leak            |               |      | 150 Hyd System           | I      | COMPLETE | 09/10/19         |          | 3,750       |
| WV49818    | 1 Repair Hydraulic Leak            |               |      | 150 Hyd System           | I      | COMPLETE | 09/27/19         |          | 3,810       |
| WV52048    | 1 T-S Fan Belts                    |               |      | 140 Cooling System       | I      | COMPLETE | 05/07/20         |          | 4,243       |
| WV52811    | 1 Install Tracks                   |               |      | 190 Undercarriage        | I      | COMPLETE | 07/15/20         |          | 4,381       |
| WV52947    | 1 R&I Track                        |               |      | 170 Frame / Body         | I      | COMPLETE | 07/24/20         |          | 4,417       |
| WV53007    | 1 Replace Left Rear Track          |               |      | 190 Undercarriage        | I      | COMPLETE | 08/03/20         |          | 4,443       |
|            | 2 Repair Hydraulics                |               |      | 150 Hyd System           | I      | COMPLETE | 08/03/20         |          | 4,443       |
| WV53315    | 1 Repair Engine                    |               |      | 180 Electrical           | I      | COMPLETE | 08/31/20         |          | 4,559       |
| WV53971    | 1 Tighten Tracks                   |               |      | 190 Undercarriage        | I      | COMPLETE | 10/28/20         |          | 4,714       |
| WV54634    | 1 Perform Upgrades and Update      |               |      | 170 Frame / Body         | I      | COMPLETE | 01/19/21         |          | 4,868       |
|            | 2 PM-2                             | PM-2          | 1    | 90 PM                    | I      | COMPLETE | 01/19/21         |          | 4,868       |
|            | 3 PM-3                             | PM-3          | 1    | 90 PM                    | I      | COMPLETE | 01/19/21         |          | 4,868       |
|            | 4 R&I Rear Differential - Replace  |               |      | 130 Power Train          | I      | COMPLETE | 01/19/21         |          | 4,868       |
|            | 5 Replace Wiper Arm                |               |      | 210 Operators Station    | I      | COMPLETE | 01/19/21         |          | 4,868       |
|            | 6 Replace (1) Midroller / Left Fr. |               |      | 190 Undercarriage        | I      | COMPLETE | 01/19/21         |          | 4,868       |
| MTS-38044  | 1 Updates and Upgrades             |               |      | 170 Frame / Body         | I      | COMPLETE | 02/26/21         |          | 4,847       |
| SC00004662 | 1 R&I Starter                      |               |      | 180 Electrical           | I      | COMPLETE | 02/24/21         |          | 4,873       |
| SC00078981 | 1 Travel                           |               |      | 80 TRAVEL                | I      | COMPLETE | 07/30/21         |          | 5,340       |
|            | 2 Replace Rt. Rear Track           |               |      | 190 Undercarriage        | I      | COMPLETE | 07/30/21         |          | 5,340       |
| SC00087873 | 1 Travel                           |               |      | 80 TRAVEL                | I      | COMPLETE | 08/24/21         |          | 5,321       |
|            | 2 Repair Track Tension Sensor      |               |      | 190 Undercarriage        | I      | COMPLETE | 08/24/21         |          | 5,321       |
| SC00110843 | 1 Travel                           |               |      | 80 TRAVEL                | I      | COMPLETE | 11/12/21         |          | 5,809       |
|            | 2 R&I Starter with Reman           |               |      | 180 Electrical           | I      | COMPLETE | 11/12/21         |          | 5,809       |
|            | 3 Order DPF for Donnie to Instal   |               |      | 110 Air Intake / Exhaust | I      | COMPLETE | 11/12/21         |          | 5,809       |
| SC00133150 | 1 Travel                           |               |      | 80 TRAVEL                | I      | COMPLETE | 12/10/21         |          | 6,026       |
|            | 2 Update Transmission              |               |      | 130 Power Train          | I      | COMPLETE | 12/10/21         |          | 6,026       |
|            | 3 Replace DPF with Reman           |               |      | 110 Air Intake / Exhaust | I      | COMPLETE | 12/10/21         |          | 6,026       |
|            | 4 Replace Radiator Grill           |               |      | 170 Frame / Body         | I      | COMPLETE | 12/10/21         |          | 6,026       |
| SC00135029 | 1 Travel                           |               |      | 80 TRAVEL                | I      | COMPLETE | 11/17/21         |          | 5,943       |
|            | 2 Replace Right Rear Track Ten:    |               |      | 190 Undercarriage        | I      | COMPLETE | 11/17/21         |          | 5,943       |
| SC00146594 | 1 Travel                           |               |      | 80 TRAVEL                | I      | COMPLETE | 12/16/21         |          | 6,084       |
|            | 2 Replace ARD Head                 |               |      | 110 Air Intake / Exhaust | I      | COMPLETE | 12/16/21         |          | 6,084       |
| SC00193641 | 1 Travel                           |               |      | 80 TRAVEL                | I      | COMPLETE | 04/26/22         |          | 6,144       |
|            | 2 R&I NOX Sensor                   |               |      | 110 Air Intake / Exhaust | I      | COMPLETE | 04/26/22         |          | 6,144       |
|            | 3 Repair Transmission Leak         |               |      | 130 Power Train          | I      | COMPLETE | 04/26/22         |          | 6,144       |
| SC00214029 | 1 Travel                           |               |      | 80 TRAVEL                | I      | COMPLETE | 06/13/22         |          | 6,272       |



## EM Work Order History By Equipment

Equipment:

All Work Orders

All Categories

| ----- Standard Maintenance ----- |                            |       |      |                      | Date   |          |          |             |            |
|----------------------------------|----------------------------|-------|------|----------------------|--------|----------|----------|-------------|------------|
| WO                               | Item                       | Group | Item | Cost Code            | In/Out | Status   | Complete | Odometer    | Hour Meter |
| Equipment: Tractor 3630T         |                            |       |      |                      |        |          |          | - Continued |            |
| SC00214029                       | 2 Replace Right Rear Track |       | 190  | Undercarriage        | I      | COMPLETE | 06/13/22 |             | 6,272      |
| SC00239817                       | 1 Travel                   |       | 80   | TRAVEL               | I      | COMPLETE | 07/28/22 |             | 6,485      |
|                                  | 2 Repair No-Start          |       | 180  | Electrical           | I      | COMPLETE | 07/28/22 |             | 6,485      |
| SC00243241                       | 1 Travel                   |       | 80   | TRAVEL               | I      | COMPLETE | 07/28/22 |             | 6,486      |
|                                  | 2 Replace Left Rear Track  |       | 190  | Undercarriage        | I      | COMPLETE | 07/28/22 |             | 6,486      |
| SC00255737                       | 1 Travel                   |       | 80   | TRAVEL               | I      | COMPLETE | 08/18/22 |             | 6,598      |
|                                  | 2 Repair Hydraulic Leak    |       | 150  | Hyd System           | I      | COMPLETE | 08/18/22 |             | 6,598      |
| SC00283121                       | 1 Travel                   |       | 80   | TRAVEL               | I      | COMPLETE | 11/17/22 |             | 6,806      |
|                                  | 2 Repair Software          |       | 180  | Electrical           | I      | COMPLETE | 11/17/22 |             | 6,806      |
|                                  | 3 Repair Aftertreatment    |       | 110  | Air Intake / Exhaust | I      | COMPLETE | 11/17/22 |             | 6,806      |
|                                  | 4 Repair Hydraulic Leak    |       | 150  | Hyd System           | I      | COMPLETE | 11/17/22 |             | 6,806      |
| SC00311408                       | 1 Travel                   |       | 80   | TRAVEL               | I      | COMPLETE | 12/06/22 |             | 6,876      |
|                                  | 2 Repair Emissions         |       | 110  | Air Intake / Exhaust | I      | COMPLETE | 12/06/22 |             | 6,876      |

