Allclass

Postville Pty Ltd T/As Allclass ABN 23 057 201 626

Address: 16 Parade Ground Place, Wacol QLD 4076
Postal: PO Box 347 Mt Ommaney QLD 4074
Phone: 07 3279 3300
Email: admin@allclass.com.au
Web: www.allclass.com.au

SERVICE TAX INVOICE

Customer Account No.

Deliver To:

Document No.:	***01 - 2372892***
Document Date:	23/03/2026
Repair Order No.:	591437
Rego No.:	9222C0
Make:	Kubota
Model:	KX080-3SGLA
Serial No.:	28371
Stock No.:	
Hrs/Bales	3001
Delivery Date:	20/06/2022
Warranty Expiry:	20/06/2022
P/Order No.:	
Page:	1 of 2
Payment Type/Terms:	Account - 30 Days EOM

KX080-3S1000

Carry out 3000 hr Service ***$480.00***
Change engine oil & filter
Change fuel filter
Clean fuel/water seperator
Change fuel/water seperator o-ring
Change final drive oils
Change inner & outer air filters
Change fan belt
Change air con belt
Change air con filters
Change coolant
Change hydraulic oil
Change hydraulic filters
Change hyd return tank o-ring
Change pilot o-ring
Blow out radiator
Jack up machine
Check tracks & rollers
Adjust track tensions
Check over machine
Greased machine
Next service is due at 3250 hrs

Part Number	Part Description	Quantity	Nett Value	Total Cost
1G772-97010	V-BELT	1.00	35.56	35.56
3A111-19130	ELEMENT (INNER)	1.00	79.07	79.07
859800-26110	ELEMENT OUTER AIR	1.00	84.10	84.10
CON	CONSUMABLES	1.00	20.00	20.00
COOLANT	XEREX G05 RTU VAL-940-28	10.50	10.00	105.00

Allclass

Postville Pty Ltd T/As Allclass ABN 23 057 201 626
Address: 16 Parade Ground Place, Wacol QLD 4076
Postal: PO Box 347 Mt Ommaney QLD 4074
Phone: 07 3279 3300
Email: admin@allclass.com.au
Web: www.allclass.com.au

SERVICE TAX INVOICE

Customer Account No.:

Deliver To:

Document No.:	***01 - 2372892***
Document Date:	23/03/2026
Repair Order No.:	591437
Rego No.:	9222C0
Make:	Kubota
Model:	KX080-3SGLA
Serial No.:	28371
Stock No.:	
Hrs/Bales	3001
Delivery Date:	20/06/2022
Warranty Expiry:	20/06/2022
P/Order No.:	
Page:	2 of 2
Payment Type/Terms:	Account - 30 Days EOM

ENVIRO	ENVIRONMENTAL LEVY	1.00	17.00	17.00
HH166-43560	"""ELEMENT-FUEL FILTER"""	1.00	44.74	44.74
HH1C0-32430	CARTRIDGE (OIL FILTER)	1.00	26.31	26.31
OIL1	HYDRAULIC OIL 68	75.00	7.00	525.00
OIL2A	CK-4 DIESELOIL VAL-1376IBC	11.00	9.50	104.50
OIL3	80/90 GEAR OIL	3.00	10.38	31.14
R1411-64930	ELEMENT	1.00	86.42	86.42
R1411-64940	O RING	1.00	37.40	37.40
RD451-51930	O RING	1.00	8.16	8.16
RD809-62130	"""ASSY-FILTER(SUCTION)"""	1.00	305.37	305.37
RD809-62150	O RING	1.00	17.45	17.45
RD809-62240	"""CARTRIDGE-FILTER"""	1.00	273.15	273.15
RD819-42790	V-BELT	1.00	72.26	72.26
T0270-67060	FILTER	1.00	129.95	129.95
		19.00		***$2,002.58***

TRAVEL

Travel to site on 17/3/26 ***$120.00***
185 Samford Rd, Enoggera

#INSPECT

Diagnose lights not working ***$160.00***
Inspect front lights, no issues found - operator did not know where the switch was for front lights.
Inspect beacon light, fouhd power getting to plug. Beacon wasnt onsite for testing - might be an issue with plug or beacon light.
Inspect boom light, found power getting to plug, inspected light & found there was no globe onside light.

Sub Total for All:	$2,762.58
Rounding:	$0.00
GST:	$276.26
Total:	$3,038.84

Bank Account Details for Direct Payments: Advisor: Shaun Ehrich
Bank: Westpac Branch: Mt Ommaney
BSB: 034108 Account No.: 751696 Account Name: Postville Pty Ltd T/A Allclass
Please reference this bank deposit by Invoice Number

Our Standard Terms of Business apply.Please refer to our standard terms of business which are available upon request and/or on allclass.com.au. Without limiting our standard terms of business, title in goods sold by us remains vested with us until such goods have been paid for in full in cleared funds. Please also note: (1) A person should not use, or allow another person to use, plant supplied by Allclass: (a) prior to receiving and having understood the applicable operator manuals, and any other information about how to safely and correctly use the plant; (b) if they are not suitably competent to use the plant; (c) without ensuring a thorough risk assessment has been carried out which has regard to all aspects of the plant including any modifications made to the plant; (d) without ensuring they are familiar with all modifications made to the plant; (e) if the plant has a fault and/or defect; and (f) in a manner that is not in accordance with applicable laws and the applicable manufacturer requirements; and (2) Used/ second-hand plant supplied by Allclass is supplied in an “as is condition".