



Vehicle History

Vehicle Details

Registration	454QBB	Next Service	Litres	
Make	40' TRI AXLE SKEL	Rego Due	Trans	N/A
Model		Engine #	Air	Yes
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	SEMITRAILER
Colour		Odometer	Prod	

Invoice No.	Date	Odometer	Description	Type
60755	31/03/2025	368557	C SERVICE	Invoice

PARK TRAILER IN WORKSHOP
CARRY OUT C SERVICE AS PER SERVICE SHEET
APPLY AIR TO TRAILER
TEST LIGHTING FUNCTION
LIFT TRAILER WITH HOIST
CHECK SUSPENSION COMPONENTS
CHECK KING PIN BOLT TENSION
CHECK SKID PLATE
CHECK THE UNDERCARRIAGE OF THE TRAILER
CARRY OUT GREASING OF AXLES
CARRY OUT DE-ADJUSTMENT OF BRAKES
REMOVE HUB CAPS AND REMOVE BEARING ADJUSTMENT NUTS
REMOVE BEARINGS FROM HUBS
CLEAN STUB AXLES AND APPLY NEW FILM OF GREASE TO STUB AXLES
CLEAN BEARINGS IN TURBO WASH
CLEAN HUBS OF GREASE AND REPACK HUBS AS REQUIRED
REMOVED BEARINGS FROM PARTS WASHER BLOW OUT WITH AIR AND REPACK BEARINGS
INSTALL BEARINGS TO HUBS
INSTALL INNER HUB SEALS
INSTALL HUBS TO THE TRAILER AND TENSION-BEARING ADJUSTMENT NUTS
SECURE BEARING ADJUSTMENT NUTS WITH RETAINERS
REINSTALL HUB CAPS TO AXLES AND TENSION HUB CAPS
CARRY OUT ADJUSTMENT OF BRAKES
LOWER TRAILER
CHECK WHEEL NUT TENSION
CHECK ALL LIVERY INCLUDING MUDFLAPS AND DECAL
INSPECT MARKER PLATES INCLUDING CON SIGN, CHEVRONS, AND OVERTAKE SIGNAGE
CHECK TOP DECK OF TRAILER FOR ALL FUNCTIONALITY
APPLY SERVICE STICKER
COMPLETE PAPERWORK
CLEAN WORK AREA
MOVE TRAILER OUT OF WORKSHOP
NOTE
REPACK NOT NECESSARY

**HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD -
STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS
WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.
PHONE THE STORE FOR PRICING ON - 07 3260 8950**

Vehicle Details

Registration	454QBB	Next Service	Litres	
Make	40' TRI AXLE SKEL	Rego Due	Trans	N/A
Model		Engine #	Air	Yes
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	SEMITRAILER
Colour		Odometer	Prod	

Invoice No.	Date	Odometer	Description	Type
-------------	------	----------	-------------	------

RECEIVE A \$25 DISCOUNT FOR ANY POSITIVE GOOGLE REVIEW ON OUR COMPANY GOOGLE WEBPAGE - HEAVY VEHICLE WORKSHOP

60246	05/12/2024	35341	DEFECTS	Invoice
-------	------------	-------	---------	---------

REPLACED RH CENTRE INDICATOR LIGHT AND HOUSING
 REPLACED RH #3 SIDE MARKER LIGHT AND HOUSING
 REPAIRED LH #5 SIDE MARKER LIGHT WIRING
HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE CHRIS FOR PRICING ON - 07 3260 8950

59343	05/06/2024	30838	A SERVICE	Invoice
-------	------------	-------	-----------	---------

PARK TRAILER IN WORKSHOP
 CARRY OUT A SERVICE AS PER SERVICE SHEET
 APPLY AIR TO TRAILER
 TEST LIGHTING FUNCTION
 LIFT TRAILER WITH HOIST
 CHECK WHEEL BEARINGS FOR MOVEMENT
 CHECK SUSPENSION COMPONENTS
 CHECK KING PIN BOLT TENSION
 CHECK SKID PLATE
 CHECK THE UNDERCARRIAGE OF THE TRAILER
 CARRY OUT GREASING OF AXLES
 CARRY OUT ADJUSTMENT OF BRAKES
 LOWER TRAILER
 CHECK WHEEL TENSION
 CHECK WHEEL BEARING GREASE FOR CONTAMINANTS
 CHECK ALL LIVERY INCLUDING MUDFLAPS AND DECAL
 INSPECT MARKER PLATES INCLUDING CON SIGN, CHEVRONS, AND OVERTAKE SIGNAGE
 CHECK TOP DECK OF TRAILER FOR ALL FUNCTIONALITY
 APPLY SERVICE STICKER
 COMPLETE PAPERWORK
 CLEAN WORK AREA
 MOVE TRAILER OUT OF WORKSHOP
 NOTE
 SOME OF THE TYRES ON LHS MAY NEED REPLACING
 BEARING GREASE STARTING TO DISCOLOUR - RECCOMEND RE-PACK AT NEXT SERVICE

HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE JEFF FOR PRICING ON - 07 3260 8950

58792	26/02/2024	29265	C SERVICE	Invoice
-------	------------	-------	-----------	---------

PARK TRAILER IN WORKSHOP
 CARRY OUT C SERVICE AS PER SERVICE SHEET
 APPLY AIR TO TRAILER
 TEST LIGHTING FUNCTION
 LIFT TRAILER WITH HOIST
 CHECK SUSPENSION COMPONENTS

Vehicle Details

Registration	454QBB	Next Service	Litres	
Make	40' TRI AXLE SKEL	Rego Due	Trans	N/A
Model		Engine #	Air	Yes
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	SEMITRAILER
Colour		Odometer	Prod	
		6FC3344DAKS000188		
		368557		

Invoice No.	Date	Odometer	Description	Type
			CHECK KING PIN BOLT TENSION CHECK SKID PLATE CHECK THE UNDERCARRIAGE OF THE TRAILER CARRY OUT GREASING OF AXLES CARRY OUT DE-ADJUSTMENT OF BRAKES REMOVE HUB CAPS AND REMOVE BEARING ADJUSTMENT NUTS REMOVE BEARINGS FROM HUBS CLEAN STUB AXLES AND APPLY NEW FILM OF GREASE TO STUB AXLES CLEAN BEARINGS IN TURBO WASH CLEAN HUBS OF GREASE AND REPACK HUBS AS REQUIRED REMOVED BEARINGS FROM PARTS WASHER BLOW OUT WITH AIR AND REPACK BEARINGS INSTALL BEARINGS TO HUBS INSTALL INNER HUB SEALS INSTALL HUBS TO THE TRAILER AND TENSION-BEARING ADJUSTMENT NUTS SECURE BEARING ADJUSTMENT NUTS WITH RETAINERS REINSTALL HUB CAPS TO AXLES AND TENSION HUB CAPS CARRY OUT ADJUSTMENT OF BRAKES LOWER TRAILER CHECK WHEEL NUT TENSION CHECK ALL LIVERY INCLUDING MUDFLAPS AND DECAL INSPECT MARKER PLATES INCLUDING CON SIGN, CHEVRONS, AND OVERTAKE SIGNAGE CHECK TOP DECK OF TRAILER FOR ALL FUNCTIONALITY APPLY SERVICE STICKER COMPLETE PAPERWORK CLEAN WORK AREA ***** DIDN'T REQUIRE A RE-PACK ADJUSTED 1 X BEARING REPLACED 2 X TYRES AND TENSIONED ALL WHEEL NUTS PARKED TRAILER ON STREET AS SHED 24 WAS LOCKED ***** NOTE- 2ND AND 3RD AXLE BRAKES MAY NEED RE-LINE IN NEXT COUPLE OF SERVICES <u>HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.</u>	

58268	05/12/2023	28290	A SERVICE	Invoice
			COLLECTED TRAILER FROM SHED 24 PARK TRAILER IN WORKSHOP CARRY OUT A SERVICE AS PER SERVICE SHEET APPLY AIR TO TRAILER TEST LIGHTING FUNCTION LIFT TRAILER WITH HOIST CHECK WHEEL BEARINGS FOR MOVEMENT CHECK SUSPENSION COMPONENTS CHECK KING PIN BOLT TENSION CHECK SKID PLATE CHECK THE UNDERCARRIAGE OF THE TRAILER CARRY OUT GREASING OF AXLES CARRY OUT ADJUSTMENT OF BRAKES LOWER TRAILER	

Vehicle Details

Registration	454QBB	Next Service	Litres	
Make	40' TRI AXLE SKEL	Rego Due	Trans	N/A
Model		Engine #	Air	Yes
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	SEMITRAILER
Colour		Odometer	Prod	

Invoice No.	Date	Odometer	Description	Type
CHECK WHEEL TENSION CHECK WHEEL BEARING GREASE FOR CONTAMINANTS CHECK ALL LIVERY INCLUDING MUDFLAPS AND DECAL INSPECT MARKER PLATES INCLUDING CON SIGN, CHEVRONS, AND OVERTAKE SIGNAGE CHECK TOP DECK OF TRAILER FOR ALL FUNCTIONALITY APPLY SERVICE STICKER COMPLETE PAPERWORK CLEAN WORK AREA ***** ADJUSTED WHEEL BEARINGS REPLACED 2 SIDE MARKER HOUSINGS REPLACED 1 WHOLE HELLA MARKER STRIP AND FIT 1 2ND HAND TYRE TAKEN FROM ANOTHER BT VEHICLE TENSIONED ALL WHEEL NUTS <u>HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.</u>				
56469	19/04/2023	22239	A SERVICE + REPAIRS	Invoice
COLLECTED TRAILER FROM SHED 24 BROUGHT INTO WORKSHOP CARRIED OUT A SERVICE TIGHTENED LHF ROCKER BOX PIVOT BOLT REPLACED RHS MARKER LIGHTS RETURNED TRAILER TO SHED 24				
55618	29/12/2022	18682	C SERVICE AND REPAIRS	Invoice
MOVED TRAILER FROM BUCCINI YARD INTO WORKSHOP CARRIED OUT C SERVICE STRIPPED DOWN FOR RE-PACK REMOVE HUBS FROM TRAILER CLEAN HUBS REPACKED BEARINGS ADJUSTED BRAKES DROVE TRAILER BACK TO BUCCINI YARD				
54445	29/06/2022	9905	CARRY OUT A SERVICE	Invoice
COLLECTED TRAILER FROM SHED 24 CARRIED OUT A SERVICE REPLACED LABEL HOLDER ADJUSTED #1 AXLE WHEEL BEARINGS ADJUSTED LH #2 AXLE WHEEL BEARINGS CHECKED / REPLACED U/S RH RED LED TAIL LAMP INSERT / TEST - ALL OK TIDIED UP WIRING AT VARIOUS OTHER LOCATIONS ON TRAILER RETURNED TRAILER TO SHED 24				

Vehicle Details

Registration	454QBB	Next Service	Litres	
Make	40' TRI AXLE SKEL	Rego Due	Trans	N/A
Model		Engine #	Air	Yes
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	SEMITRAILER
Colour		Odometer	Prod	

Invoice No.	Date	Odometer	Description	Type
53182	16/11/2021	47740	CARRY OUT C SERVICE	Invoice
BROUGHT TRAILER INTO WORKSHOP CARRIED OUT C SERVICE ON TRAILER ADJUSTED ALL WHEEL BEARINGS REPLACED HUBOMETER REMOVED, REPLACED AND REWIRED FOUR SIDE MARKER LIGHTS AS REQUIRED TESTED OPERATION OF ALL LIGHTS - ALL OK PARKED TRAILER ON STREET FOR COLLECTION NOTE: FRONT TOOLBOX LOCK MISSING				
51643	03/03/2021	45989	A SERVICE	Invoice
DATE WORK CARRIED OUT: 03/03/2021 WORK CARRIED OUT: CARRIED OUT A SERVICE DEFECTS NOTED - NONE NOTED				
51169	30/12/2020	45602	A SERVICE	Invoice
DATE WORK CARRIED OUT: 30/12/2020 WORK CARRIED OUT: CARRIED OUT A SERVICE				
50721	20/10/2020		INSPECT TRAILER FOR FAULTS	Invoice
DATE WORK CARRIED OUT: 20/10/2020 WORK CARRIED OUT: RE-INSPECTED TRAILER RE-ADJUSTED BRAKES CREATED FAULT REPORT FITTED NEW TRAILER PLUG				
50331	26/08/2020	45034	REPAIRS NOTED ON SERVICE	Invoice
DATE WORK CARRIED OUT: 28/8/2020 - 10/9/2020 WORK CARRIED OUT: REVISED FAULTS LIST ALL BRAKES LOW				

Vehicle Details

Registration	454QBB	Next Service	Litres	
Make	40' TRI AXLE SKEL	Rego Due	Trans	N/A
Model		Engine #	Air	Yes
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	SEMITRAILER
Colour		Odometer	Prod	

Invoice No.	Date	Odometer	Description	Type
TORQUE ROD BUSHES 1ST AXLE REQUIRE REPLACEMENT ALL HUB SEALS LEAKING EXCEPT FOR LH 1ST AXLE AND L/H 2ND AXLE ELECTRICAL PLUG REQUIRES REPLACEMENT RELAY VALVE REMOVED - REPLACED LEAKING 2ST AXLE TORQUE ROD MOUNTS UNDER SPRING CRACKED UNDERNEATH - WELD 3RD AXLE LHS ROD MOUNTS UNDER SPRING CRACKED UNDERNEATH - WELD 1ST AXLE REQUIRES BRAKE DRUMS - REQUIRES REPLACING STRIP ALL BEARING OFF TRAILER AND WRAP BEARINGS CLEANED HUBS AND REMOVE BRAKES CLEANED AXLES REMOVED REMAINING HUB SEALS REMOVED & REPLACE BRAKE VALVES AND NEW VALVE TO TRAILER REPLACED #1 AXLE RADIUS ROD BUSHES & BOLTS REPLACED #1 BRAKE DRUMS, SHOES, SEALS & CARRIER REPLACED #2 & #2 SEALS REPLACED ALL WHEEL BEARINGS ADJUSTED WHEEL BEARINGS AND BRAKES FITTED ALL HUBCAPS RE-ALIGNED RH #1 AXLE WHEELS CHECKED RH ROCKER BOX BUSHES FITTED REAR REFLECTORS				
50269	05/08/2020	45033	PARTS LIST	Invoice
DATE WORK CARRIED OUT: 05/08/2020 WORK CARRIED OUT: REMOVED PARTS ON LIST FOR SAMPLES CLEANED - FOR P/N'S				
50148	30/07/2020	45032	CARRY OUT A SERVICE	Invoice
DATE WORK CARRIED OUT: 29/07/2020 WORK CARRIED OUT: CARRIED OUT A SERVICE AS PER SERVICE SHEET & INSPECTION FURTHER REPAIRS REQUIRED - BENT PIN IN LIGHT SOCKET WHEEL SEALS LEAKING - FR SIDE, MR SIDE, RR SIDE, LR SIDE BRAKE SHOES GETTING LOW - ALL OVER RELAY VALVE ON FRONT AIR TANK LEAKING RECOMMEND CHANGE LOWER BUSHES RHS LH & RH TORQUE ROD BUSHES WORN				

Vehicle Details

Registration	454QBB	Next Service		Litres	
Make	40' TRI AXLE SKEL	Rego Due		Trans	N/A
Model		Engine #		Air	Yes
Model Series		VIN	6FC3344DAKS000188	Cyl	0
Model Code		Build Date		Body	SEMITRAILER
Colour		Odometer	368557	Prod	

Invoice No.	Date	Odometer	Description	Type
-------------	------	----------	-------------	------