

CUSTOMER #: 13339

Repairs

INVOICE #
71120



JIM HOLT
PO BOX 353

REDWATER, AB T0A 2W0

HOME: CONT:N/A

BUS: CELL:

PAGE 1

ROADRUNNERS EQUIPMENT SALES
SERVICE & MANUFACTURING (2005) LTD.
Hwy 642 & Range Road 254 • Box 3146 • Morinville, AB T8R 1S2
Phone: (780) 939-3188 • Fax: (780) 939-7197
Auto Center: (780) 939-4250 • Towing Dispatch: (780) 939-4251
www.roadrunnerstirecraft.com

SERVICE ADVISOR: 5 DEREK SCHLACHTER

UNIT NO.	YEAR	MAKE/MODEL		VIN	LICENSE	ODOMETER IN/ OUT		TAG
	99	VOLVO/GM HEAVY TRUCK		4VG7DBJH9XN782368	14K208	1/767933		TJIM
IN SVC. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	CUST. PAY LABOUR RATE	PAYMENT	INV. DATE	
01JAN99 DD			17:30 23JUN16		149.00	CASH	12JUL16	

R.O. OPENED READY OPTIONS:

14:07 16JUN16 16:39 12JUL16

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

A Commercial Vehicle Inpection
T20 Commercial Vehicle Inpection
42 CPW 0.00
1 277111-642 GREASE, TUBE
1 cvip

Volvo

10.56	250.00	8.94	250.00
-------	--------	------	--------

B CHECK UNIT FOR AIR LEAKS
1000 MISCELLANEOUS
25 CPW 1.50
1 OR289714X QR VALVE
1 25- found QR valve above first diff. removed and ordered new.
found air leak at valve on left side of framerail by tranny.

Heavy Truck

75.35	193.50	59.20	193.50
-------	--------	-------	--------

C CHECK CLUTCH (SLAVE CYLINDER LEAKING)
1000 MISCELLANEOUS
42 CPW 4.00
1 8089526 SLAVE CYLINDER
1 8076327 HOSE ASSEM
1 KF528 SUPER HE
13 83-6029 TIE WRAP 15
1 1573872 COVER
1 replace for leaking slave cylinder. line also leaking near crip
on hydraulic line near slave cylinder. over lay new line. secure to old
line. attempt to bleed clutch. would not bleed manually. install power
bleeder. bleed ok. test ok.

590.60	516.00	407.80	516.00
208.19		143.75	143.75
22.53		18.02	18.02
0.31		0.26	3.38
13.13		10.50	10.50

D** CVIP REPAIRS
T20 Commercial Vehicle Inpection
38 CPW 10.62
42 CPW 4.38
15.00
1 46412 RED 2-1/2" MARKER LAMP
2 H41736 GLADHAND SEAL
1 H284358 GOVERNOR

7.24	1935.00	6.34	1935.00
2.24		1.96	3.92
35.01		27.51	27.51

 MAXXFORCE 24 HOUR TOWING & RECOVERY	STATEMENT OF DISCLAIMER The factory warranty constitutes all of the warranties with respect to the sale of this item/items. The Seller hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item/items.	JOB COMPLETION DATE RECEIVED ABOVE DESCRIBED MACHINE WITH EQUIPMENT INTACT / CHARGES FOR MATERIAL AND LABOR HEREBY ACCEPTED.	DESCRIPTION LABOUR AMOUNT PARTS AMOUNT GAS, OIL, LUBE SUBLET AMOUNT MISC. CHARGES TOTAL CHARGES LESS INSURANCE SALES TAX PLEASE PAY THIS AMOUNT	TOTALS
	CUSTOMER SIGNATURE	SERVICE MANAGER	SIGNATURE	DATE

I.S.T. NO. 82645 1346 RT 0001

Copyright 2014 CDE Global, LLC SERVICE INVOICE TYPE 2 - S12C - IMAGING

CUSTOMER COPY

13339

INVOICE #

71120

INVOICE

ROADRUNNERS EQUIPMENT SALES
SERVICE & MANUFACTURING (2005) LTD.

Hwy 642 & Range Road 254 · Box 3146 · Morinville, AB T8R 1S2

Phone: (780) 939-3188 · Fax: (780) 939-7197

Auto Center: (780) 939-4250 · Towing Dispatch: (780) 939-4251

www.roadrunnerstirecraft.com

PAGE 2

SERVICE ADVISOR: 5 DEREK SCHLACHTER

CONT:N/A

CELL:

UNIT NO.	YEAR	MAKE/MODEL		VIN	LICENSE	ODOMETER IN/ OUT		TAG
	99	VOLVO/GM HEAVY TRUCK		4VG7DBJH9XN782368	14K208	1/767933		TJIM
C. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	CUST. PAY LABOUR RATE	PAYMENT	INV. DATE	
N99 DD			17:30 23JUN16		149.00	CASH	12JUL16	

R.O. OPENED: 7 16JUN16 16:39 12JUL16

OPTIONS:

OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
1	3929131	WHEEL SEAL		78.35	61.56	61.56
4	79590	BRAKE CLEAN		5.85	5.04	20.16
1	AS1136	SLACK ADJUSTER		200.89	157.84	157.84
1	AS1133	SLACK ADJUSTER		200.89	157.84	157.84
1	382-8036	KIT, HUB SEAL		76.00	59.71	59.71
1	1469-6B	ELBOW		7.38	6.24	6.24
1	1469-6A	FITTING ELBOW 90 DG 6X1/8		7.04	6.16	6.16
3	1492-8C	FITTING PIPE- AIR		14.18	11.34	34.02
1	8073380	AIR TANK STRAP		125.18	86.44	86.44
1	110-BA 1/4 X 1/8	NPT HEX BUSHING		1.80	1.58	1.58
1	1229D2942	RING		0.95	0.57	0.57
1	11904 3/8	NPT FITTING		13.72	11.61	11.61
9	1649492C2	NUT		19.03	11.42	102.78
1	330-3009	GASKET		5.84	5.11	5.11
1	CS3149	CAMSHAFT LOCK		3.44	3.01	3.01
1	FLT3030SCB20	CHAMBER		85.75	49.01	49.01
1	ZBRAS3000	CLEVIS		18.35	11.58	11.58
1	MSA500	SLACK ARM BUSHING		6.48	5.67	5.67
10	1229G2971	WASHER		0.45	0.23	2.30

42 change gladhand seals. repair light on headach rack. change
governor. diag for poor function of heater. cables seized/stuck.
further diag needed. diag for no low air buzzer. buzzer in dash. remove
and inspect. needs cluster. cluster slow to respond when key turned on
odometer replace right steer slack.38- replaced rm wheel seal, rf
steer wheel seal, replaced air tank strap, replaced the relay valve,
replace lr slack adjuster, replaced lr brake pot,

CUSTOMER PAY SHOP/ENVIRO FOR REPAIR ORDER

289.45

ROADRUNNERS TOWING DECK & WRECKER

SERVICE, RECOVERY & WINCH OUT

24 HR SERVICE

780-939-4251

DRIVE SAFE

AND THANK YOU FOR YOUR BUSINESS

STATEMENT OF DISCLAIMER The factory warranty constitutes all of the warranties with respect to the sale of this item/items. The Seller hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item/items.	O U T	JOB COMPLETION DATE RECEIVED ABOVE DESCRIBED MACHINE WITH EQUIPMENT INTACT / CHARGES FOR MATERIAL AND LABOR HEREBY ACCEPTED.	DESCRIPTION		TOTALS
			LABOUR AMOUNT		2894.50
			PARTS AMOUNT		1472.55
			GAS, OIL, LUBE		0.00
			SUBLET AMOUNT		0.00
			MISC. CHARGES		289.45
			TOTAL CHARGES		4656.50
			LESS INSURANCE		0.00
			SALES TAX		232.83
			PLEASE PAY THIS AMOUNT		4889.33

NO. 82645 1346 RT 0001

© 2014 CDK Global, LLC SERVICE INVOICE TYPE 2 - SZC - IMAGING

CUSTOMER COPY