

# Experian AutoCheck Report

Report run: 08/24/2026 15:16:36 EDT

## 2006 Great Dane Semi-Trailer Van

|                       |                   |
|-----------------------|-------------------|
| VIN:                  | 1GRAA06226S702091 |
| Class:                | Trailer           |
| Country of Assembly:  | United States     |
| Estimated In Service: | 06/02/2005        |

Owners - 2



Vehicle Usage  
Lease

AutoCheck Score Not Available

## AutoCheck Score

### Vehicle History at a Glance

|                                                                                                 |                                                                      |                                                  |
|-------------------------------------------------------------------------------------------------|----------------------------------------------------------------------|--------------------------------------------------|
| <br>State Title Brand<br><br>CLEAN                                                              | <br>Auction Brand / Issues<br><br>NO ISSUE                           | <br>Accident / Damage<br><br>DAMAGE REPORTED     |
| <br>Open Recall Check<br>Recall Information not received from manufacturer<br><br>NOT AVAILABLE | <br>Insurance Loss / Transfer<br><br>NO ISSUE                        | <br>Odometer Check<br><br>NO ISSUE               |
| <br>Certified Pre-Owned<br><br>NO CPO INFO AVAILABLE                                            | <br>Service / Repair<br>6 Service Record(s) Reported<br><br>NO ISSUE | <br>Additional History<br><br>NO ISSUES REPORTED |



### This vehicle is not eligible for Buyback Protection

Due to the vehicle's history showing no reported major state title brands. [Terms & Conditions](#)

Learn More



### Accident & Damage

The diagram shows a top-down view of a car. A large blue rounded rectangle is centered over the car's body, containing a white exclamation mark icon and the text "Point of Impact Not Available". Below the car, there are four status icons arranged in a 2x2 grid. Each icon is a light gray silhouette of a car with a specific feature highlighted in blue. The top-left icon shows a blue circle on the driver's side floor, with the text "Airbag Deployed" below it. The top-right icon shows a blue starburst on the front left corner, with the text "Structural Damage" below it. The bottom-left icon shows a blue outline of the car's roof and pillars, with the text "Overturned" below it. The bottom-right icon shows a blue circle with an exclamation mark on the front windshield, with the text "Unknown" below it.



No odometer brands, rollbacks, rollover or tampering has been reported to AutoCheck from state Division of Motor Vehicles (DMV) or auction sources. AutoCheck also examined the sequence of reported odometer readings to determine if there are any potential discrepancies.



Below are the historical events for this vehicle listed in chronological order.

**Vehicle:** 2006 Great Dane (1GRAA06226S702091) **Report Run Date:** 08/24/2026 15:16:36 EDT

## Owner 1

Usage: Personal

## Owner 2

Usage: Lease

| Event Date | Location   | Odometer | Data Source         | Details                                    |
|------------|------------|----------|---------------------|--------------------------------------------|
| 04/25/2014 | APOPKA, FL |          | Motor Vehicle Dept. | Registration Event/Renewal                 |
| 05/29/2014 | APOPKA, FL |          | Motor Vehicle Dept. | Registration Event/Renewal                 |
| 08/21/2014 | APOPKA, FL |          | Motor Vehicle Dept. | Registration Event/Renewal(Leased Vehicle) |
| 08/22/2014 | APOPKA, FL |          | Motor Vehicle Dept. | Title(Title #:0116015461) (Leased Vehicle) |
| 10/23/2014 | APOPKA, FL |          | Motor Vehicle Dept. | Registration Event/Renewal                 |
| 01/14/2015 | APOPKA, FL |          | Motor Vehicle Dept. | Registration Event/Renewal                 |

