

COPY

Invoice To

Engine Model:	SIGNATURE/ISX/QSX	Eng No:	79873668	Equip Make:	KENWORTH
FleetNo:		Reg No:	304TWP	Cust Ord NO:	
Date in Service:	12/04/16	KLMS:	261121	HRS:	22009
Repair Date:	06/01/22	Chassis NO:	452561	Currency:	AUD
C.O.No.	6568666	Work ordNo.	2726919	Facility	137

Complaint:

Adblue Faults

Cause:

Doser pump blocked on air solenoid

Correction:

Guidanz SO Number: 279792

Hrs/Klms: 22,009 hrs / 261,121 klms

- Doser pump blocked on air solenoid.
- Flush air side and wet side.
- Purge wet side and replace inlet filter fitting.
- Replace tank filter.
- Run flow test system, all ok.
- Clear fault codes.
- Replace radiator cap at the request of the driver, cap leaking.

Banking Details

Cummins South Pacific Pty Ltd
Australia and New Zealand Banking Group Limited (ANZ)
Level 4, 100 Queen Street, Melbourne VIC 3000
Account No: 836551902 BSB:013 479
Swift Code: ANZBAU3M

Include Account and Invoice Numbers in Payment Reference

Description	Operation	Unit price	Qty	
Labour				
320.00	3	160.00	2.00	
320.00	LABOUR TOTAL			
Material				
AE9976132	CAP-RADIATOR 15PSI	29.29	1	29.29



Cummins South Pacific Pty. Ltd. WORKSHOP TAX INVOICE

INVOICE NUMBER 9216971
INVOICE DATE 07/01/22
PAGE 2

Customer

<i>Description</i>	<i>Operation</i>	<i>Unit price</i>	<i>Qty</i>	<i>Extension</i>
5264404	CONNECTOR, QCK DISCONNECT	96.26	1	96.26
HHW0116	FILTER, INTANK ADBLUE	54.92	1	54.92
MATERIAL TOTAL				180.47
SUB-TOTAL				500.47
G.S.T				50.05
INVOICE TOTAL				550.52