



## Vehicle History

### Vehicle Details

Registration	339SHS	Next Service	Litres	
Make	VOLVO	Rego Due	Trans	N/A
Model	FE SERIES	Engine #	Air	Yes
Model Series		VIN	Cyl	0
Model Code	MINI LIFTER	Build Date	Body	TRUCK
Colour	White	Odometer/Hr	Prod	2007

Invoice No.	Date	Odometer / Hours	Description	Type
61236	17/07/2025	726780/905	JUMP START	Invoice

TRAVEL TO SHED 24  
JUMP START TRUCK OUT BACK OF SHED 24  
CHECK CHARGE RATE  
RETURN TO WORKSHOP  
\*\*\*RECEIVE A \$25 DISCOUNT FOR ANY POSITIVE GOOGLE REVIEW ON OUR COMPANY GOOGLE WEBPAGE - HEAVY VEHICLE WORKSHOP\*\*\*  
**HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE THE STORE FOR PRICING ON - 07 3260 8950**

60986	23/05/2025	726780/905	FIX AIR LEAK	Invoice
-------	------------	------------	--------------	---------

FIX AIR LEAK IN SEAT  
**HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE THE STORE FOR PRICING ON - 07 3260 8950**  
\*\*\*RECEIVE A \$25 DISCOUNT FOR ANY POSITIVE GOOGLE REVIEW ON OUR COMPANY GOOGLE WEBPAGE - HEAVY VEHICLE WORKSHOP\*\*\*

60922	12/05/2025	725298/905	DEFECTS	Invoice
-------	------------	------------	---------	---------

HAMMAR REPAIRS

1. 82758 339SHS STARTING AND FUNCTION FAULTS Starting and function faults
2. Repair wiring in rear cabinet.
3. Replace damaged sensor cable and test.
4. M12 PUR cable 10m

60861	28/04/2025	725298/905	HAMMAR REPAIRS	Invoice
-------	------------	------------	----------------	---------

82612 339SHS CALIBRATE AND TEST LIFT Calibrate and test lift.  
LABOUR Replaced damaged rear stabiliser proximity switch. Inspect wiring in rear cabinet and return to standard. Repair wiring on relay base. Calibrate unit and test lift.  
614-413 PROXIMITY SENSOR M18, LONG

**HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND**

## Vehicle Details

<b>Registration</b>	339SHS	<b>Next Service</b>	<b>Litres</b>	
<b>Make</b>	VOLVO	<b>Rego Due</b>	<b>Trans</b>	N/A
<b>Model</b>	FE SERIES	<b>Engine #</b>	<b>Air</b>	Yes
<b>Model Series</b>		<b>VIN</b>	<b>Cyl</b>	0
<b>Model Code</b>	MINI LIFTER	<b>Build Date</b>	<b>Body</b>	TRUCK
<b>Colour</b>	White	<b>Odometer/Hr</b>	<b>Prod</b>	2007

Invoice No.	Date	Odometer / Hours	Description	Type
<b><u>MACHINERY AS WELL AS FITTING &amp; BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE THE STORE FOR PRICING ON - 07 3260 8950</u></b> ***RECEIVE A \$25 DISCOUNT FOR ANY POSITIVE GOOGLE REVIEW ON OUR COMPANY GOOGLE WEBPAGE - HEAVY VEHICLE WORKSHOP***				
60818	14/04/2025	725298/905	DEFECTS	Invoice
REPAIR STAINLESS BOX				
60726	25/03/2025	725298/905	DEFECTS	Invoice
CHECKED FOR CRANE FAULT TESTED FUNCTION DISCONNECTED PLUG FROM EMERGENCY FIT TO NORMAL OPERATION TESTED FUNCTIONS OPEN ELECTRICAL BOX TESTSED WIRING, FUSES AND RELAYS FOUND RELAYS OVER HEATING + INCORRECT RELAYS 12V+24V <b><u>HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES &amp; MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING &amp; BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE THE STORE FOR PRICING ON - 07 3260 8950</u></b> ***RECEIVE A \$25 DISCOUNT FOR ANY POSITIVE GOOGLE REVIEW ON OUR COMPANY GOOGLE WEBPAGE - HEAVY VEHICLE WORKSHOP***				
60495	06/02/2025	725298/905	A SERVICE	Invoice
PARK VEHICLE IN WORKSHOP CARRY OUT A SERVICE AS PER SERVICE SHEET CARRY OUT WALK AROUND VISUAL INSPECTION SECURE HOIST ON TRUCK CHECK ALL LIGHTS INCLUDING ALL REVERSE LAMPS AND BEEPERS CHECK WIPER AND WASHER OPERATION CHECK BATTERY LEVELS, TERMINALS AND CLAMPS LIFT CAB/BONNET TO ACCESS ENGINE BAY CHECK ALL BELTS AND MOUNTS LIFT TRUCK ON HOIST CARRY OUT VISUAL INSPECTION OF UNDER CARRIAGE (DRIVE LINE AND SUSPENSION COMPONENTS) ADJUST BRAKES AND CHECK BRAKE THICKNESSES CHECK AND ADJUST CLUTCH IF APPLICABLE CHECK GEAR BOX OIL LEVEL AND QUALITY CHECK DIFF OIL LEVEL AND QUALITY CARRY OUT GREASING OF TRUCK LOWER TRUCK CHECK ENGINE OIL TOP UP COOLANT IF REQUIRED LOWER CAB/BONNET AND SECURE IN PLACE FIT SERVICE STICKER COMPLETE PAPERWORK NOTE REPLACED RH TOP ROOF LIGHT BULB REPLACED LH FRONT TWIST LOCK FIT RH REAR NEW TAILLIGHT WIRED UP TAILLIGHTS ON BOTH SIDES				

**Vehicle Details**

<b>Registration</b>	339SHS	<b>Next Service</b>	<b>Litres</b>	
<b>Make</b>	VOLVO	<b>Rego Due</b>	<b>Trans</b>	N/A
<b>Model</b>	FE SERIES	<b>Engine #</b>	<b>Air</b>	Yes
<b>Model Series</b>		<b>VIN</b>	<b>Cyl</b>	0
<b>Model Code</b>	MINI LIFTER	<b>Build Date</b>	<b>Body</b>	TRUCK
<b>Colour</b>	White	<b>Odometer/Hr</b>	<b>Prod</b>	2007

Invoice No.	Date	Odometer / Hours	Description	Type
DRILLED HOLES INTO ALLY SHEET TO MAKE TAILLIGHT FIT SOLDERED ALL WIRES AND TESTED - ALL OKAY ZIP TIE TAILLIGHT HARNESS THROW OUT RUBBISH TEST LIGHTS - ALL OKAY RETURN VEHICLE TO BT YARD  <b><u>HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES &amp; MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING &amp; BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE COREY FOR PRICING ON - 07 3260 8950</u></b>				
60143	14/11/2024	724212/905	PARTS NOT ON JOB 59687	Invoice
59867	24/09/2024	724212/905	A SERVICE	Invoice

PARK VEHICLE IN WORKSHOP  
CARRY OUT A SERVICE AS PER SERVICE SHEET  
CARRY OUT WALK AROUND VISUAL INSPECTION  
SECURE HOIST ON TRUCK  
CHECK ALL LIGHTS INCLUDING ALL REVERSE LAMPS AND BEEPERS  
CHECK WIPER AND WASHER OPERATION  
CHECK BATTERY LEVELS, TERMINALS AND CLAMPS  
LIFT CAB/BONNET TO ACCESS ENGINE BAY  
CHECK ALL BELTS AND MOUNTS  
LIFT TRUCK ON HOIST  
CARRY OUT VISUAL INSPECTION OF UNDER CARRIAGE (DRIVE LINE AND SUSPENSION COMPONENTS)  
ADJUST BRAKES AND CHECK BRAKE THICKNESSES  
CHECK AND ADJUST CLUTCH IF APPLICABLE  
CHECK GEAR BOX OIL LEVEL AND QUALITY  
CHECK DIFF OIL LEVEL AND QUALITY  
CARRY OUT GREASING OF TRUCK  
LOWER TRUCK  
CHECK ENGINE OIL  
TOP UP COOLANT IF REQUIRED  
LOWER CAB/BONNET AND SECURE IN PLACE  
FIT SERVICE STICKER  
COMPLETE PAPERWORK  
NOTE  
TOPPED UP ENGINE OIL  
STRAIGHTENED RH TOP TWISTLOCK HANDLE  
REPLACED RH #2 DIFF MUDGUARD + HANGING BRACKETS  
REFITTED MUDFLAP + LOOP KIT TO MUDGUARD  
CHECKED AND CLEANED OUT LH BLOCKED WASHER HOSE  
CHECKED FOR EXHAUST LEAK AFTER MUFFLER  
REMOVE AND CLEAN SILENCER ON AIR DRYER  
STRAIGHTEN MARKER LIGHT BRACKET  
REPLACED LH WIPER BLADE  
REPLACED RH MIRROR COVER  
REPLACED DRIVERS SIDE HEADLIGHT  
REPLACE GEAR KNOB ASSEMBLY  
REFIT AIR LINES ON HIGH RANGE SWITCH ETC.  
REMOVE CLUTCH PEDAL RUBBER + FIT NEW ONE  
DISPOSE OF OLD PARTS AND PACKAGING  
REMOVED RH DOOR SEAL + COVER

## Vehicle Details

<b>Registration</b>	339SHS	<b>Next Service</b>	<b>Litres</b>	
<b>Make</b>	VOLVO	<b>Rego Due</b>	<b>Trans</b>	N/A
<b>Model</b>	FE SERIES	<b>Engine #</b>	<b>Air</b>	Yes
<b>Model Series</b>		<b>VIN</b>	<b>Cyl</b>	0
<b>Model Code</b>	MINI LIFTER	<b>Build Date</b>	<b>Body</b>	TRUCK
<b>Colour</b>	White	<b>Odometer/Hr</b>	<b>Prod</b>	2007

Invoice No.	Date	Odometer / Hours	Description	Type
			<p>ATTEMPTED TO FIT NEW DOOR SEAL  REMOVED STEERING WHEEL  FITTED SWITCHES TO NEW STEERING WHEEL  FITTED NEW STEERING WHEEL TO VEHICLE  REMOVED EXHAUST PIPE FROM MUFFLER TO EXHAUST STACKER  REPAIRED CAB FOR WINDSCREEN  SPRAYED WINDSCREEN FRAME WITH RUST CONVERTER  BOGGED WINDSCREEN FRAME  SANDED FRAME + SHAPED TO SUIT WINDSCREEN  MASKED ROOF LIGHTS + COVERED HOOD LINING  PRIMED REPAIRED SURFACE  PAINTED SURFACE WITH WHITE PAINT  REMOVED MASKING  REMOVED SIDE LOADER CONTROL BOX DOOR  STRAIGHTENED CONTROL BOX AND DOOR PANEL  REPAIRED DOOR HINGE  REFITTED DOOR  FIT HORN PAD  FIT GEAR SHIFTER SHROUD AND BOUT  FIT DOOR SEAL  FIT REPAIRED EXHAUST  REFIT ALL REMOVED TRIM RETURN VEHICLE TO BT YARD  <b><u>HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES &amp; MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING &amp; BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE JEFF FOR PRICING ON - 07 3260 8950</u></b></p>	

59165	02/05/2024	716187/905	C SERVICE + FIT RAILS	Invoice
			<p>PARK VEHICLE IN WORKSHOP  CARRY OUT C SERVICE AS PER SERVICE SHEET  CARRY OUT WALK AROUND VISUAL INSPECTION  SECURE HOIST ON TRUCK  CHECK ALL LIGHTS INCLUDING ALL REVERSE LAMPS AND BEEPERS  CHECK WIPER AND WASHER OPERATION  CHECK BATTERY LEVELS, TERMINALS AND CLAMPS  LIFT CAB/BONNET TO ACCESS ENGINE BAY  REPLACE CABIN AND ENGINE AIR FILTERS  CHECK ALL BELTS AND MOUNTS  LIFT TRUCK ON HOIST  CARRY OUT VISUAL INSPECTION OF UNDERCARRIAGE (DRIVE LINE AND SUSPENSION COMPONENTS)  DRAIN ENGINE OIL AND CHANGE FILTER  ADJUST BRAKES AND CHECK BRAKE THICKNESSES  CHECK AND ADJUST CLUTCH IF APPLICABLE  CHECK GEARBOX OIL LEVEL AND QUALITY REPLACE IF REQUIRED  CHECK DIFF OIL LEVEL AND QUALITY REPLACE IF REQUIRED  CARRY OUT GREASING OF TRUCK  LOWER TRUCK  FIL ENGINE OIL AND CHECK ENGINE OIL  TOP-UP COOLANT IF REQUIRED  LOWER CAB/BONNET AND SECURE IN PLACE  FIT SERVICE STICKER  COMPLETE PAPERWORK  REMOVE HOIST  FIT RAILINGS/GUARD RAILS</p>	

**Vehicle Details**

Registration	339SHS	Next Service	Litres	
Make	VOLVO	Rego Due	Trans	N/A
Model	FE SERIES	Engine #	Air	Yes
Model Series		VIN	Cyl	0
Model Code	MINI LIFTER	Build Date	Body	TRUCK
Colour	White	Odometer/Hr	Prod	2007

Invoice No.	Date	Odometer / Hours	Description	Type
RE-ATTACH HANDLE CARRY OUT SERVICE ON LIFTER ENGINE REMOVE CHAINS FIT NEW CHAINS REMOVE AND REPLACE WINDSCREEN WIPER BLADES REMOVE AND REPLACE FUEL FILTER HOUSING CLEAN OUT BLOCKED WATER JETS TEST DROVE VEHICLE FILLED UP OIL FILLED UP COOLANT REMOVE PINS OUT OF CHAINS DROPPED CHAINS TO ATLAS STRAIGHTEN SIDE LOADER HYDRAULIC BLOCK GUARD WELD GUARD TO REAR OF CRANE HOUSING WELDED REAR BRACKET ON PAINTED WELDS FIT CHAINS AND NEW HAMMER LOCKS TO TRUCK DRILL HOLES AND FIT BOLTS TO SLEEVES  <b><u>HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES &amp; MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING &amp; BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE JEFF FOR PRICING ON - 07 3260 8950</u></b>				
59164	02/05/2024	708961/905	LABOUR - BUCCINI	Invoice
INSPECT RAILINGS  <b><u>HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES &amp; MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING &amp; BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE JEFF FOR PRICING ON - 07 3260 8950</u></b>				
59053	08/04/2024	708961/905	STRIP AN FITS	Invoice
2 X STRIP AND FITS 2 NEW ROAD WAY TENSIONED ALL WHEELNUTS <b><u>HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES &amp; MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING &amp; BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE JEFF FOR PRICING ON - 07 3260 8950</u></b>				
58760	22/02/2024	700815/905	PUNCTURE REPAIR	Invoice
1 X PUNCTURE REPAIR TO VEHICLE <b><u>HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING &amp; BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.</u></b>				

## Vehicle Details

Registration	339SHS	Next Service	Litres	
Make	VOLVO	Rego Due	Trans	N/A
Model	FE SERIES	Engine #	Air	Yes
Model Series		VIN	Cyl	0
Model Code	MINI LIFTER	Build Date	Body	TRUCK
Colour	White	Odometer/Hr	Prod	2007

Invoice No.	Date	Odometer / Hours	Description	Type
58667	08/02/2024	698092/905	AIR LEAK	Invoice
<p>INSPECT AIR LEAK  REMOVE SEAT BASE  MOVE SEAT FORWARD  REMOVE HOSE FIT JOINER AS NO HOSE IN STOCK  TEST OPERATION - ALL OK</p> <p><b><u>HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING &amp; BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.</u></b></p>				
58529	22/01/2024	695758/905	A SERVICE	Invoice
<p>PARK VEHICLE IN WORKSHOP  CARRY OUT A SERVICE AS PER SERVICE SHEET  CARRY OUT WALK AROUND VISUAL INSPECTION  SECURE HOIST ON TRUCK  CHECK ALL LIGHTS INCLUDING ALL REVERSE LAMPS AND BEEPERS  CHECK WIPER AND WASHER OPERATION  CHECK BATTERY LEVELS, TERMINALS AND CLAMPS  LIFT CAB/BONNET TO ACCESS ENGINE BAY  CHECK ALL BELTS AND MOUNTS  LIFT TRUCK ON HOIST  CARRY OUT VISUAL INSPECTION OF UNDER CARRIAGE (DRIVE LINE AND SUSPENSION COMPONENTS)  ADJUST BRAKES AND CHECK BRAKE THICKNESSES  CHECK AND ADJUST CLUTCH IF APPLICABLE  CHECK GEAR BOX OIL LEVEL AND QUALITY  CHECK DIFF OIL LEVEL AND QUALITY  CARRY OUT GREASING OF TRUCK  LOWER TRUCK  CHECK ENGINE OIL  TOP UP COOLANT IF REQUIRED  LOWER CAB/BONNET AND SECURE IN PLACE  FIT SERVICE STICKER  COMPLETE PAPERWORK  *****  WINDSCREEN HAS 5 CHIPS  RHS KINGPIN HAS A LITTLE MOVEMENT ( MONITOR)  CENTRE BEARINGS ON TAIL SHAFT NEED REPLACING  REMOVED TAIL SHAFT AND SPLIT INTO SECTIONS  REMOVED REAR CENTRE BEARING FROM SHAFT, FOUND SHAFT HAD ABOUT 3MM OF WEAR - SHAFT NEEDS TO BE REPLACED.  REMOVED AND REPLACED FRONT CENTRE BEARING  RE-FIT FRONT SECTION OF TAIL SHAFT TO TRUCK</p> <p><b><u>HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING &amp; BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.</u></b></p>				
58545	18/01/2024	695758/905	REPAIR TAILSHAFT	Invoice
<p>REMOVED FRONT SECTION OF TAILSHAFT FROM TRUCK AND GOT ALL PARTS TOGETHER TO BE SENT AWAY  FITTED TAILSHAFT ASSEMBLIES AND CENTRE BEARINGS - TEST DROVE VEHICLE  TRACED ALL CRANE CIRCUITS AS REQUIRED TO COMPLETE REAR LIFTER WIRING A REQUIRED AND TEST -</p>				



**Vehicle Details**

Registration	339SHS	Next Service	Litres	
Make	VOLVO	Rego Due	Trans	N/A
Model	FE SERIES	Engine #	Air	Yes
Model Series		VIN	Cyl	0
Model Code	MINI LIFTER	Build Date	Body	TRUCK
Colour	White	Odometer/Hr	Prod	2007

Invoice No.	Date	Odometer / Hours	Description	Type
ALL OK NOTE - UNSURE IF LIFTER / CRANES WILL REQUIRE RESET / RECALIBRATE NEEDS TO BE TESTED AT YARD WITH LOADED 20FT BOX ETC WITH TRAINED OPERATOR  <b><u>HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING &amp; BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.</u></b>				

58450	09/01/2024	695758/905	ATTEND TO REMOTE AND REPLACE	Invoice
REMOVED BROKEN CONTROL BOX AT RHR, AS REQUIRED GOT PART ON BT ACCOUNT FROM HAMMAR AUSTRALIA FOR REPLACEMENT CABLE GLANDS X 4 1 X NEW PVC BOX ALSO FOUND / FIXED LOOSE BATTERY RETAINERS ON THE REMOTE CONTROL REMOVED FRONT SECTION OF TAIL SHAFT FROM TRUCK AND GOT ALL PARTS TOGETHER TO BE SENT AWAY  ***** REMOVED THE FRONT SECTION OF THE TAIL SHAFT FROM THE TRUCK AND GOT ALL PARTS TOGETHER TO BE SENT AWAY. ***** REMOVED BROKEN CONTROL BOX AT RHR AS REQUIRED - GOT PARTS ON BUCCINI ACCOUNT FROM HAMMAR AUSTRALIA FOR REPLACEMENT CABLE GLANDS X4 AND 1 NEW PVC BOX. ALSO FOUND + FIXED LOOSE BATTERY RESTAINERS ON REMOTE CONTROL.  <b><u>HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING &amp; BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.</u></b>				

58418	02/01/2024	695705/905	TOP UP ENGINE OIL	Invoice
TOP UP ENGINE OIL  <b><u>HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING &amp; BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.</u></b>				

58356	18/12/2023	694361/905	REPLACE 2 X STEER TYRES	Invoice
PICKED UP TRUCK FROM BUCCINI YARD REPLACED 2 X TYRES 2 X BALANCING BAGS TENSIONED ALL WHEEL NUTS  <b><u>HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING &amp; BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.</u></b>				

## Vehicle Details

Registration	339SHS	Next Service	Litres	
Make	VOLVO	Rego Due	Trans	N/A
Model	FE SERIES	Engine #	Air	Yes
Model Series		VIN	Cyl	0
Model Code	MINI LIFTER	Build Date	Body	TRUCK
Colour	White	Odometer/Hr	Prod	2007

Invoice No.	Date	Odometer / Hours	Description	Type
58249	01/12/2023	688759/905	SLEEVE FLYWHEEL TO ACCEPT NEW	Invoice

WENT TO FIT THE NEW SPIKOT BEARING INTO THE FLYWHEEL AND FOUND IT WAS A VERY LOOSE FIT. CHECKED WITH WRECKERS FLYWHEELS AVAILABLE, HAD THE FLYWHEEL SLEEVED TO SUIT SPIKOT BEARING.  
CHECKED ALL OK.  
INV 57907 JOB 57585

58126	17/11/2023	688759/905	REMOVE LHR WHEELS	Invoice
-------	------------	------------	-------------------	---------

TRAVEL TO BUCCINI  
REMOVE LHR WHEELS, RETURN TO THE WORKSHOP  
REMOVE TYRES AND FIT NEW ONES  
TAKE BACK TO THE YARD  
FIT WHEELS AND TORQUE WHEEL NUTS

**EAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.**

58122	16/11/2023	688535	TOP UP OIL	Invoice
-------	------------	--------	------------	---------

JACK UP CAB  
TOP UP ENGINE OIL  
LOWER CAB DOWN

**HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.**

58099	15/11/2023	688334	AIR LEAK UNDER THE RHF SEAT	Invoice
-------	------------	--------	-----------------------------	---------

DIAGNOSE AIR LEAK  
REMOVE DRIVERS SEAT BASE  
CUT AIRLINES AND PUT JOINER ON  
RE-FIT DRIVERS SEAT BASE - ALL GOOD

**HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.**

58004	01/11/2023	0	WELD EXHAUST BRACKET	Invoice
-------	------------	---	----------------------	---------

BROUGHT VEHICLE INTO WORKSHOP  
REMOVED BOLTS FROM BRACKET  
CLEANED BROKEN BRACKET BEFORE WELD  
WELDED BRACKET  
PAINTED BRACKET



**Vehicle Details**

Registration	339SHS	Next Service	Litres	
Make	VOLVO	Rego Due	Trans	N/A
Model	FE SERIES	Engine #	Air	Yes
Model Series		VIN	Cyl	0
Model Code	MINI LIFTER	Build Date	Body	TRUCK
Colour	White	Odometer/Hr	Prod	2007

Invoice No.	Date	Odometer / Hours	Description	Type
-------------	------	------------------	-------------	------

BOLTED BACK TO ENGINE  
TOOK TRUCK BACK TO BUCCINI

**HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.**

57982	30/10/2023	685706	NEW TYRES X 4	Invoice
-------	------------	--------	---------------	---------

TYRE PRESSURE CHECK  
4 X NEW TYRES 275/70R22.5 TRAILER TYRES  
4 X STRIP AND FIT  
4 X TYRE DISPOSAL  
TENSIONED ALL WHEEL NUTS

**HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.**

57811	09/10/2023	662284	STRIP AND QUOTE TO REPAIR DAMAGED	Invoice
-------	------------	--------	-----------------------------------	---------

CLAIM NUMBER VL40237308  
REMOVE THE FRONT BUMPER BAR AND OTHER PIECES  
STRAIGHTEN UP THE BENT BRACKET  
REMOVE BOTH HEADLIGHTS  
REMOVE GRILL  
REMOVE THE FRONT BUMPER FROM THE TRUCK  
REMOVE GRILL FROM FRONT BUMPER  
REFIT RH HEADLIGHT AND REPLACED LH HEADLIGHT AS IT WAS BROKEN  
REMOVED AND REPLACED BADLY DAMAGED LHF METAL CORNER (INFILL PANEL)  
REFIT BUMPER BAR TO TRUCK WITH ZIP TIES AND SECURED IT  
DROP TRUCK BACK TO BUCCINI  
QUOTED UP TO CARRY OUT PERMANENT REPAIR.  
FITTED ACCESSORIES TO FRONT BUMPER BAR & GRILLE  
FITTED FRONT BAR  
FITTED FRONT GRILLE & STRAIGHTENED BENT BRACKETS  
ATTEMPTED TO STRAIGHTEN LOWER STEEL BAR  
REPAIRED LH HEADLIGHT WIRING  
FITTED NEW HEADLIGHTS  
FITTED NEW D/G FLIP SIGN  
FITTED NUMBER PLATE  
FITTED PLASTIC PANELS  
FITTED CIRCUIT BOARD TO LH HEADLIGHT ASSEMBLY  
CLEANED RH HEADLIGHT LENSE

FITTED GRIP TAPE TO THE TOP OF FRONT BAR

**HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.**

**Vehicle Details**

<b>Registration</b>	339SHS	<b>Next Service</b>	<b>Litres</b>	
<b>Make</b>	VOLVO	<b>Rego Due</b>	<b>Trans</b>	N/A
<b>Model</b>	FE SERIES	<b>Engine #</b>	<b>Air</b>	Yes
<b>Model Series</b>		<b>VIN</b>	<b>Cyl</b>	0
<b>Model Code</b>	MINI LIFTER	<b>Build Date</b>	<b>Body</b>	TRUCK
<b>Colour</b>	White	<b>Odometer/Hr</b>	<b>Prod</b>	2007

Invoice No.	Date	Odometer / Hours	Description	Type
57818	27/09/2023	679988	REPLACE LHS HEAD LIGHT CIRCUIT	Invoice

CHECKED SMALL ENGINE WIRING ISSUES,

REMOVED WIRING HARNESS & CHECKED WIRING

FITTED NEW IGNITION SWITCH AND PUT LIFTER MOTOR BACK TO ORIGINAL OEM WIRING.

OBTAINED WIRING DIAGRAMS FROM HAMAR TO ASSIST IN GETTING THE WIRING CONFIGURED CORRECTLY.

TRACED/COMPLETED REINSTALATION OF WIRING AND CONTROLS FOR NEW LIFTER ENGINE TO WORK WITH HAMAR REMOTE CONTROLS AND E STOPS.

TETSED OPERATION ALL OK.

CHECKED HEADLIGHT NOT WORKING, REMOVED AND REPLACED INTERNAL CIRCUIT BOARD ON LIGHT. ALL OK.

57722	20/09/2023	679997	B SERVICE	Invoice
-------	------------	--------	-----------	---------

CARRY OUT B SERVICE AS PER SERVICE SHEET

PARK VEHICLE IN WORKSHOP

CARRY OUT WALK AROUND VISUAL INSPECTION

SECURE HOIST ON TRUCK

CHECK ALL LIGHTS INCLUDING ALL REVERSE LAMPS AND BEEPERS

CHECK WIPER AND WASHER OPERATION

CHECK BATTERY LEVELS, TERMINALS AND CLAMPS

LIFT CAB/BONNET TO ACCESS ENGINE BAY

REPLACE CABIN AND ENGINE AIR FILTERS

CHECK ALL BELTS AND MOUNTS

LIFT TRUCK ON HOIST

CARRY OUT VISUAL INSPECTION OF UNDERCARRIAGE (DRIVE LINE AND SUSPENSION COMPONENTS)

DRAIN ENGINE OIL AND CHANGE FILTER

ADJUST BRAKES AND CHECK BRAKE THICKNESSES

CHECK AND ADJUST CLUTCH IF APPLICABLE

CHECK GEARBOX OIL LEVEL AND QUALITY REPLACE IF REQUIRED

CHECK DIFF OIL LEVEL AND QUALITY REPLACE IF REQUIRED

CARRY OUT GREASING OF TRUCK

LOWER TRUCK

FIL ENGINE OIL AND CHECK ENGINE OIL

TOP-UP COOLANT IF REQUIRED

LOWER CAB/BONNET AND SECURE IN PLACE

FIT SERVICE STICKER

COMPLETE PAPERWORK

REMOVE HOIST

**HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.**

57907	07/09/2023	0	GEARBOX REMOVAL	Invoice
-------	------------	---	-----------------	---------

TEST DROVE TRUCK FOR GRATING GEARS.

DIAGNOSED THAT THE 4TH AND 8TH GEARS GRATE BADLY AND THE LOWER GEARS ARE HARD TO SELECT.

CALLED AROUND FOR A GOOD USED GEARBOX, THEY WERE OVERPRICED. OBTAINED PERMISSION TO

REMOVE THE GEARBOX AND HAVE IT OVERHAULED.

REMOVED THE GEARBOX AND SENT OUT FOR REPAIRS.

REMOVED THE CLUTCH AND FLYWHEEL. SENT FLYWHEEL OUT FOR SKIMING.

**Vehicle Details**

<b>Registration</b>	339SHS	<b>Next Service</b>	<b>Litres</b>	
<b>Make</b>	VOLVO	<b>Rego Due</b>	<b>Trans</b>	N/A
<b>Model</b>	FE SERIES	<b>Engine #</b>	<b>Air</b>	Yes
<b>Model Series</b>		<b>VIN</b>	<b>Cyl</b>	0
<b>Model Code</b>	MINI LIFTER	<b>Build Date</b>	<b>Body</b>	TRUCK
<b>Colour</b>	White	<b>Odometer/Hr</b>	<b>Prod</b>	2007

Invoice No.	Date	Odometer / Hours	Description	Type
ORDERED IN A NEW CLUTCH AND ASSOCIATED COMPONENTS. REFITTED THE FLYWHEEL AND TORQUED BOLTS TO SPEC. FITTED NEW CLUTCH. FITTED NEW CLUTCH RELEASE FORK. REFITTED THE GEARBOX AND ITEMS REMOVED TO REMOVE IT. FILLED THE GEARBOX WITH GEAR OIL . TEST DROVE TRUCK AND RETURNED TO THE YARD.				
57409	30/07/2023	671299	REPAIR TWIST LOCKS	Invoice
FREE OFF SEIZED REAR TWIST LOCKS				
57181	11/07/2023	675298	TOP UP ENGINE OIL	Invoice
CHECK AND TOP UP ENGINE OIL IN LIFTER ENGINE				
56961	30/06/2023	0	SUPPLY SERVICE FILTERS	Invoice
SUPPLY SERVICE FILTERS				
57085	26/06/2023	671299	FIX RHR TWISTLOCK HANDLE	Invoice
FIX RHR TWISTLOCK HANDLE AND FIT MOVE CONTAINER OVER WITH LIFTER FOR LHR TWISTLOCK TO FIT				
57215	14/06/2023	669448	A SERVICE	Invoice
PARK TRAILER IN WORKSHOP CARRY OUT A SERVICE AS PER SERVICE SHEET  <ul style="list-style-type: none"><li>• APPLY AIR TO TRAILER</li><li>• TEST LIGHTING FUNCTION</li><li>• LIFT TRAILER WITH HOIST</li><li>• CHECK WHEEL BEARINGS FOR MOVEMENT</li><li>• CHECK SUSPENSION COMPONENTS</li><li>• CHECK KING PIN BOLT TENSION</li><li>• CHECK SKID PLATE</li><li>• CHECK UNDERCARRAGE OF TRAILER</li><li>• CARRY OUT GREASING OF AXLES</li><li>• CARRY OUT ADJUSTMENT OF BRAKES</li><li>• LOWER TRAILER</li><li>• CHECK WHEEL TENSION</li><li>• CHECK WHEEL BEARING GREASE FOR CONTAMINANTS</li><li>• CHECK ALL LIVERY INCLUDING MUDFLAPS AND DECAL</li><li>• INSPECT MARKER PLATES INCLUDING CON SIGN, CHEVERONS AND OVER TAKE SIGNAGE</li><li>• CHECK TOP DECK OF TRAILER FOR ALL FUNCTIONALITY</li><li>• APPLY SERVICE STICKER</li><li>• COMPLETE PAPER WORK</li><li>• CLEAN WORK AREA</li><li>• MOVE TRAILER OUT OF WORKSHOP</li></ul> NOTE - REAR CENTRE BEARING HAS MOVEMENT, RECOMMEND REPLACING . GEAR BOX OUTPUT SHAFT HAS A LITTLE MOVEMENT (MONITER) REAR SPRING BUSHES ON FIRST AXLE WORN, REPLACE WHEN IN FOR PANEL REPAIRS				

**Vehicle Details**

<b>Registration</b>	339SHS	<b>Next Service</b>	<b>Litres</b>	
<b>Make</b>	VOLVO	<b>Rego Due</b>	<b>Trans</b>	N/A
<b>Model</b>	FE SERIES	<b>Engine #</b>	<b>Air</b>	Yes
<b>Model Series</b>		<b>VIN</b>	<b>Cyl</b>	0
<b>Model Code</b>	MINI LIFTER	<b>Build Date</b>	<b>Body</b>	TRUCK
<b>Colour</b>	White	<b>Odometer/Hr</b>	<b>Prod</b>	2007

Invoice No.	Date	Odometer / Hours	Description	Type
KINGPINS HAVE A LITTLE MOVEMENT (MONITER)  LEFT HAND SIDE HEADLIGHT NOT WORKING (FIXED) LEFT HAND SIDE FRONT INDICATOR NOT WORKING (FIXED) WIPER BLADES NEED REPLACING MULTIPLE SMALL CRACKS IN WINDSCREEN FRONT BAR CRACKED				
56829	05/06/2023	667412	BROKEN TWIST LOCK HANDLES	Invoice
REMOVE BROKEN TWIST LOCK HANDLES CUT 12MM ROUND BAR TO 150MM LENGTHS WELD BOLTS TO ENDS FITTED THE MADE UP HANDLES HIT REAR STABILISER PIN IN FIT END CAPS TEST - ALL OK				
56656	15/05/2023	0	LIFTER MOTOR NOT STARTING	Invoice
INSPECT MINI LIFTER NOT STARTING TEST BATTERY REMOVE AND REPLACE BATTERY TEST OPERATION - ALL OK				
56418	13/04/2023	657037	C SERVICE	Invoice
BROUGHT VEHICLE INTO WORKSHOP CARRIED OUT C SERVICE NOTE- KINGPINS HAVE A LITTLE MOVEMENT - MONITOR TAILSHAFT REAR CENTRE BEARING HAS SOME MOVEMENT, WILL NEED REPLACING NEXT SERVICE AIR HORN LEAKING AIR				
56347	30/03/2023	534490	JALTEST SCAN	Invoice
BROUGHT VEHICLE INTO WORKSHOP CARRIED OUT JALTEST SCAN ON TRUCK ECU'S TO ASSESS VARIOUS FAULT CODES INCLUDING EBS/ABS ERROR ORANGE WARNING FOUND / REVEALED INTERMITTENT EBS WHEEL SPED SENSOR ERROR ON RHS ( COULD BE FRONT OR REAR WHEELS) RESET / RE- CALIBRATED EBS SETTINGS AS REQUIRED AND TEST - ALL OK AS PER CONVERSATION WITH COL McCULLOUGH AND DRIVER EBS "ERROR" NEEDS TO BE MONITORED FOR POSSIBLE RE-OCCURENCE				
56337	29/03/2023	654613	BROKEN EXHAUST STACKER	Invoice
REMOVED BROKEN AND BENT EXHAUST STACKER CUT AND WELD REPAIR TO EXHAUST STACKER ASSEMBLED EXHAUST STACKER TO TRUCK				
56287	23/03/2023	653198	JUMP START LIFTER MOTOR	Invoice
JUMP START THE LIFTER MOTOR DRIVER CAME BACK AFTER 30MINUTES AS THE BATTERY WAS FLAT AGAIN SWAPPED BATTERY WITH ANOTHER OLD FULLY CHARGED BATTERY				
55102	16/03/2023	625053	NO AIR CON AND WIPERS DON'T WORK	Invoice

**Vehicle Details**

<b>Registration</b>	339SHS	<b>Next Service</b>	<b>Litres</b>	
<b>Make</b>	VOLVO	<b>Rego Due</b>	<b>Trans</b>	N/A
<b>Model</b>	FE SERIES	<b>Engine #</b>	<b>Air</b>	Yes
<b>Model Series</b>		<b>VIN</b>	<b>Cyl</b>	0
<b>Model Code</b>	MINI LIFTER	<b>Build Date</b>	<b>Body</b>	TRUCK
<b>Colour</b>	White	<b>Odometer/Hr</b>	<b>Prod</b>	2007

Invoice No.	Date	Odometer / Hours	Description	Type
10/10/2022 ORDERED PARTS -925053KMS CHECKED A/C - FOUND A/C LOW ON GAS TRACED / LOCATED LEAK AT U/S A/C PIPE / HOSE ASSY FROM DRYER TO CONDENSOR 28/10/2022 629009KMS REMOVED / REPAIRED LEAKING A/C DISCHARGE HOSE AS REQUIRED / REFIT BRAZED TO FIX EVACUATED / REGASSED A/C AND TEST - ALL OK				
56215	16/03/2023	652797	A/C NOT WORKING	Invoice
REMOVED / REFITTED COMPLETE DASH ASSEMBLIES AND PANELS TO ACCESS / REPLACE U/S A/C FAN BLOWER AND RESISTOR RECHECKED A/C OPERATION AFTER COMPLETION OF RE-INSTALLATION - ALL OK DROVE TRUCK BACK TO BUCCINI YARD				
55964	14/02/2023	646914	TOP UP LIFTER MOTOR OIL	Invoice
TOP UP LIFTER MOTOR OIL 2 LTS				
55931	09/02/2023	646159	REMOVE AND REPAIR BROKEN TWIST	Invoice
DRIVER CAME IN REMOVED BROKEN TWIST LOCK TO REPAIR FITTED NEW HANDLE AND ROLL PIN RE-ASSEMBLED TWIST LOCK TO TRUCK				
55770	18/01/2023	642134	CARRY OUT REPAIRS - GEAR SHIFT	Invoice
DIAGNOSE GEAR SELECTOR ISSUE SELECTOR CABLE RETAINING CLIP HAS FALLEN OUT AND WILL NEED TO BE REPLACED. SELECTOR CABLE LOCATED ON TOP OF A/BOX PART ORDERED FROM SYDNEY PARK IN WORKSHOP JACK UP THE CAB REMOVE EXHAUST, FLEX AND EXHAUST BENDS REMOVE TAIL SHAFT REMOVE YOLK, YOLK WAS STUCK ON THE SHAFT SPLINES REMOVE CENTRE BEARING, CENTRE BEARING WAS SEIZED ON THE SHAFT, SOAKED IN ROST OFF REFIT NEW CENTRE BEARING REFIT YOLK TEST DROVE TRUCK ON HIGHWAY TO CHECK FOR ANY TAILSHAFT ISSUES - ALL OK RETURNED TRUCK TO BUCCINI YARD				
55575	20/12/2022	639708	CARRY OUT B SERVICE	Invoice
BROUGHT VEHICLE INTO WORKSHOP CARRIED OUT B SERVICE PRIMED FUEL SYSTEM REMOVED LIFT CHAINS REMOVED MUFFLERS AND EXHAUST PIPE REMOVED LH REAR STEER SPRING EYE BUSH REPLACED RADIATOR HEADER TANK REPLACED FRONT INDICATOR BULBS REPLACED FRONT PARK LIGHT BULBS ENGINE OIL AND FILTER CHANGE ON SMALL ENGINE @ REPLACED LH REAR SPRING EYE BUSH AND RR FITTED SHACKLES REPLACED STREER SWAYBAR DROP ARM BUSHES				

**Vehicle Details**

<b>Registration</b>	339SHS	<b>Next Service</b>	<b>Litres</b>	
<b>Make</b>	VOLVO	<b>Rego Due</b>	<b>Trans</b>	N/A
<b>Model</b>	FE SERIES	<b>Engine #</b>	<b>Air</b>	Yes
<b>Model Series</b>		<b>VIN</b>	<b>Cyl</b>	0
<b>Model Code</b>	MINI LIFTER	<b>Build Date</b>	<b>Body</b>	TRUCK
<b>Colour</b>	White	<b>Odometer/Hr</b>	<b>Prod</b>	2007

Invoice No.	Date	Odometer / Hours	Description	Type
REPOSITIONED SWAYBAR REPLACED STEER SPRING BUMP STOPS REPLACED RHS FRONT MUDGUARD AND 4 X HANGERS REPLACED/WELDED MUFFLER REFITTED MUFFLER ON VEHICLE FITTED EXHAUST PIPE, HEATSHIELD AND COVER PLATE FITTED LIFT CHAINS AND SHACKLES FITTED LIFT CHAIN COVERS CLEANED FADED HEADLIGHTS REMOVED AND FIT NEW WASHER MOTOR NOTE NEW MUFFLER ON ORDER EX SWEDEN				
55424	24/11/2022	634390	REPAIR OIL LEAK	Invoice
COLLECTED VEHICLE FROM YARD CHECKED FOR REAR MODULE LEAK FOUND REAR CRANE STABILIZER LEG LAEKING REMOVED TOP COVER CLEAN AREA TIGHTENED LOOSE HYDRAULIC FITTING TESTED OPERATION REFITTED COVER DRAINED OIL FROM STABILIZER LEG PARKED ON STREET				
55210	21/10/2022	627475	TOPPED UP ENGINE OIL	Invoice
JACK UP THE CAB TOPPED UP ENGINE OIL				
54997	21/09/2022	621996	LIFTER MOTOR CUTTING OUT	Invoice
MADE TESTS/CHECKS TO HAMMER KOHLER ENGINE CUTTING OUT/ NOT RUNNING PROPERLY REMOVED SPARK PLUGS AND REPLACED AS REQUIRED HAD TO LOOSEN ENGINE BOLTS TO ALLOW SOME MOVEMENT TO GET REAR SPARK PLUG IN/OUT TIDIED UP / REPAIRED REAR CRANE SENSOR WIRING BROKEN RE-CHECKED ENGINE START/STOP AND LIFTER/CRANE FUNCTION - ALL OK				
54889	31/08/2022	618778	JUMP START LIFTER MOTOR	Invoice
DROVE TO BUCCINI YARD JUMP STARTED LIFTER MOTOR				
54877	29/08/2022	618778	JUMP START LIFTER MOTOR	Invoice
DROVE TO BUCCINI YARD JUMP STARTED LIFTER MOTOR				
54896	29/08/2022	618931	TOP UP ENGINE OIL	Invoice
TOPPED UP ENGINE OIL				
54878	29/08/2022	618931	JUMP START LIFTER MOTOR	Invoice
BROUGHT VEHICLE INTO WORKSHOP REMOVE BROKEN TWIST LOCK KNOCK OUT BROKEN ROLL PIN AND HANDLE				



**Vehicle Details**

<b>Registration</b>	339SHS	<b>Next Service</b>	<b>Litres</b>	
<b>Make</b>	VOLVO	<b>Rego Due</b>	<b>Trans</b>	N/A
<b>Model</b>	FE SERIES	<b>Engine #</b>	<b>Air</b>	Yes
<b>Model Series</b>		<b>VIN</b>	<b>Cyl</b>	0
<b>Model Code</b>	MINI LIFTER	<b>Build Date</b>	<b>Body</b>	TRUCK
<b>Colour</b>	White	<b>Odometer/Hr</b>	<b>Prod</b>	2007

Invoice No.	Date	Odometer / Hours	Description	Type
REFIT NEW HANDLE BAR TO TWIST LOCK FIT TWIST LOCK BACK TO THE TRUCK STRAIGHTENED AND REPAIRED DAMAGED BRACKET ON TRAY OF TRUCK WITH WELDER AND OXY PAINTED AREAS THAT HAD BEEN WELDED DROVE TRUCK BACK TO BUCCINI				
54737	11/08/2022	615374	WENT TO BUCCINI YARD & JUMP	Invoice
WENT DOWN TO BUCCINI YARD JUMP STARTED BOTH THE TRUCK AND THE LIFTER MOTOR DROVE BACK TO THE WORKSHOP				
54324	20/06/2022	0	WIPER BLADE	Invoice
REPLACED WIPER BLADES				
54123	20/06/2022	609508	TWIST LOCK HANDLE	Invoice
INSPECTED TWIST LOCK AND FOUND CLEVIS PIN STILL IN PLACE BUT HANDLE BROKEN. INSPECTED HANDLE WHERE IT BROKE, THE ORIGINAL CRACK IS OLD AND DISCOLOURED MAYBE FATIGUED. KNOCKED OUT CLEVIS PIN AND FITTED NEW TWIST LOCK HANDLE, KNOCKED CLEVIS PIN BACK INTO POSITON. CHECKED OPERATION ALL OK.				
54336	13/06/2022	614983	BREAKDOWN AT CANBERRA ST /	Invoice
DROVE TO BREAKDOWN AT CANBERRA STREET FOUND GEAR SELECTOR CABLE SNAPPED PUT TRUCK BACK INTO NEUTRAL MANUALLY AND STARTED TRUCK FORCED TRUCK INTO 3RD GEAR MANUALLY AND GOT DRIVER TO DRIVE TRUCK BACK TO THE WORKSHOP FOR FURTHER INVESTIGATION REMOVE ALL TRIM AROUND CENTRE CONSOLE DISCONNECTED SELECTOR ROD FROM GEAR STICK REMOVE CLIP ON END OF GROMMIT AND REMOVE ENTIRE ROD FROM TRUCK RE-FIT GEAR SELECTOR ROD AND CABLE FIT CABLE AND SWIVEL TO GEAR SHIFTER  TILT CAB AND CONNECT ALL CLAMPS RE-FIT CENTRE CONSOLE TRIM AND BRACKETS AND BOLTS RUBBER BOOT AND CENTRE CONSOLE WILL NEED REPLACING EVENTUALLY AS THEY ARE CRACKED AND WON'T SIT IN PLACE PROPERLY - OK FOR NOW TEST DRIVE TRUCK CHECKED FOR GEARSHIFT FAULT REMOVED GEARSTICK COVER AND MOUNTING CHECKED OPERATION FOUND NO ADJUSTMENT LEFT ON CABLES REMOVED ROSE JOINT AT GEARBOX REFITTED GEAR SELECTOR INSIDE CAB FIT NEW ROSE JOINT TO GEARBOX SELECTOR CABLE AND RE-CONNECTED CABLE TO GEARBOX TESTED TRUCK TO SEE IF IT WOULD SELECT GEARS- COULDN'T SELECT ANY GEARS CHECKED / MADE UP AND FITTED STEEL SLEEVE TO REVERSE CABLE SELECTOR ROSE JOINT AS REQUIRED TO TAKE OUT EXCESSIVE MOVEMENT CHECKED GEAR LINKAGE FAULT FITTED WASHERS FOR ROSE JOINT SPACER ADJUSTED LINKAGE TESTED OPERATION				

**Vehicle Details**

<b>Registration</b>	339SHS	<b>Next Service</b>	<b>Litres</b>	
<b>Make</b>	VOLVO	<b>Rego Due</b>	<b>Trans</b>	N/A
<b>Model</b>	FE SERIES	<b>Engine #</b>	<b>Air</b>	Yes
<b>Model Series</b>		<b>VIN</b>	<b>Cyl</b>	0
<b>Model Code</b>	MINI LIFTER	<b>Build Date</b>	<b>Body</b>	TRUCK
<b>Colour</b>	White	<b>Odometer/Hr</b>	<b>Prod</b>	2007

Invoice No.	Date	Odometer / Hours	Description	Type
REPAIRED AIR LEAK BEHIND SEAT TEST DROVE VEHICLE DROPPED TRUCK BACK TO THE YARD				

<b>54229</b>	<b>25/05/2022</b>	<b>613621</b>	<b>A SERVICE / BROKE DOWN AT YARD</b>	<b>Invoice</b>
PICK UP TRUCK FROM YARD CARRIED OUT A SERVICE TOPPED UP ENGINE OIL AND COOLANT  NOTES: LARGE STONE CHIP PASSENGER SIDE FRONT SPRING BUMP STOPS U/S CENTRE BEARING HAS MOVEMENT - MONITOR NEXT SERVICE				

<b>53904</b>	<b>21/03/2022</b>	<b>604925</b>	<b>GEARBOX ISSUES</b>	<b>Invoice</b>
21/3/2022 - CHECKED REVERSE ALARM "STUCK" ON - FOUND TO BE TRANSMISSION GEARBOX STUCK IN REVERSE WAS ABLE TO GET TRANSMISSION TO GO INTO NEUTRAL EVENTUALLY AND FOUND REVERSE ALARM SYSTEM ALL OK MECHANICAL AND OR TRANSMISSION GEARBOX OT CLUTCH FAULT EVIDENT CHECKED OVER TRUCK FOR GEARBOX FAULT AS IT WAS GOING INTO FIRST GEAR BY ITSELF FOUND GEARBOX PRESSURIZING SOMEHOW AS AIR IS LEAKING OUT OF THE BREATHER AND OIL WEEPS FORMING FROM MULTIPLE PLACE ON GEARBOX ALSO FOUND CLUTCH WAS TAKING OFF VERY LOW FROM THE GROUND NOTICED THE GEARBOX OUTPUT SHAFT SEAL IS LEAKING BADLY AND REQUIRES REPLACING - THIS IS LIKELY CAUSED BY THE CENTRE BEARING BEING HEAVILY WORN REPAIRED AIR LEAK A DRIVER SEAT FOUND GEARBOX BREATHER LEAKING AIR, PUSHED OIL OUT OF SELECTOR SEAL - GEARBOX HAS PRESSURIZED AIR IN IT 22/3/2022 - TEST DROVE VEHICLE AND INSPECTED FOR GEARBOX FAULT REMOVED CLUTCH SLAVE CYLINDER AIRLINE AND CHECKED FUNCTIONS FOR GEARBOX STILL PRESSURIZING FOUND GEARBOX SELECTOR UNIT LEAKING 23/3/2022 - CHECKED GEARBOX SPLITTER HOUSING FOR AIR BYPASSING CHECKED AIRLINES AT SHIFTER HOUSING 28/3/2022 - REPLACED LIFTER ENGINE BATTERY - FAILED 29/3/2022 - CLEARED GEARBOX GASKET SURFACES FITTED GEARSTICK REMOTE SHIFTER REPLACED GEARBOX AIR SHIFT VALVE BLOCK REFITTED ALL AIR LINES AND WIRING TESTED OPERATION - ALL OK 30/3/2022 - REMOVED VALVE AT REAR OF GEARBOX REPLACED INTERNAL SEAL REFITTED VALVE STARTED ENGINE AND CHECKED OPERATION CHECKED TRANSMISSION OIL LEVEL - ALL OK CLEANED DOWN OIL LEAKS AND TEST DROVE VEHICLE - ALL OK				

**Vehicle Details**

<b>Registration</b>	339SHS	<b>Next Service</b>	<b>Litres</b>	
<b>Make</b>	VOLVO	<b>Rego Due</b>	<b>Trans</b>	N/A
<b>Model</b>	FE SERIES	<b>Engine #</b>	<b>Air</b>	Yes
<b>Model Series</b>		<b>VIN</b>	<b>Cyl</b>	0
<b>Model Code</b>	MINI LIFTER	<b>Build Date</b>	<b>Body</b>	TRUCK
<b>Colour</b>	White	<b>Odometer/Hr</b>	<b>Prod</b>	2007

Invoice No.	Date	Odometer / Hours	Description	Type
53880	17/03/2022	604285	AIRBAGS LEAKING	Invoice
<p>17/3/2022 ATTENDED BREAKDOWN AT BUCCINI YARD CUT OFF AIR SUPPLY TO LH AIRBAG DROVE VEHICLE TO WORKSHOP REMOVED #1 DIFF AIRBAGS HAD NO AIR AND THATS WHY COULDN'T GET IT OUT OF GEAR FRONT AIR BAG HAD HOLES AND WERE LEAKING AIR</p> <p>BACK TO WORKSHOP AND REMOVED AIR BAGS INSTALLED NEW AIRBAGS AND SCANNED AND RECALIBRATED AIR DRYER PARKSIDE REAR MARKER REPLACED</p>				
53865	16/03/2022	604221	CARRY OUT C SERVICE	Invoice
<p>16/3/2022 CARRIED OUT C SERVICE REPLACED DIFF OIL NOTE: GEARBOX OUTPUT SHAFT - NUT LOOSE BOTH CENTRE BEARINGS U/S 1ST DRIVE AIRBAGS U/S - REPLACED FRONT SPRING BUMP STOPS U/S LEFT REAR MARKER LIGHT OUT</p>				
53806	07/03/2022	602797	BROKEN TWIST LOCK	Invoice
<p>7/3/2022 REPAIR BROKEN TWIST LOCK TWIST LOCK HOUSING NEEDS TO BE BENT BACK FOUND HANDLE WAS BROKEN ON THE TWIST LOCK FIT USED HANDLE ON TWIST LOCK AND TESTED OPERATION - ALL OK TOP UP ENGINE OIL ON THE LIFTER MOTOR</p>				
53602	25/01/2022	905	ELECTRICAL REPAIRS	Invoice
<p>25/1/2022 - MADE TESTS THAT COULD POSSIBLY CAUSE ENGINE TO LOSE POWER UNDER LOAD CLEANED PARTIALLY BLOCKED INNER &amp; OUTER AIR FILTER ELEMENTS &amp; THEN FOUND ENGINE PERFORMANCE WAS BETTER ENGINE WAS STILL UNDER POWERING UNDER LOAD WITH 20FT BOX LOADED REMOVED FRONT SPARK PLUG &amp; FOUND PLUG PARTLY CLOGGED UP</p> <p>28/1/2022 - REMOVED STARTER MOTOR &amp; RELAY TO ENABLE ACCESS, REMOVAL OF 4 X ENGINE HOLD DOWN MOUNTING BOLTS/NUTS TO ALLOW REMOVAL OF CONCEALED REAR SPARK PLUG FITTED 2 NEW SPARK PLUGS STRAIGHTENED &amp; REPAIRED REAR ENGINE PLATE BORED OUT REAR SPARK PLUG ACCESS HOLE IN REAR BUMP PLATE TO ALLOW QUICK REMOVAL OF SPARK PLUG IN FUTURE. REFIT ALL REMOVED PARTS/BOLTS/STARTER AND RELAY OF CARRIED OUT "UNLOADED" START, RUN,STOP OF ENGINE- ALL OK TRUCK NOW NEEDS CONTAINER LEFT TEST TO CHECK ENGINE POWER AGAIN - TESTED ALL OK</p>				
53539	17/01/2022	593431	LOW OIL LEVEL	Invoice

**Vehicle Details**

<b>Registration</b>	339SHS	<b>Next Service</b>	<b>Litres</b>	
<b>Make</b>	VOLVO	<b>Rego Due</b>	<b>Trans</b>	N/A
<b>Model</b>	FE SERIES	<b>Engine #</b>	<b>Air</b>	Yes
<b>Model Series</b>		<b>VIN</b>	<b>Cyl</b>	0
<b>Model Code</b>	MINI LIFTER	<b>Build Date</b>	<b>Body</b>	TRUCK
<b>Colour</b>	White	<b>Odometer/Hr</b>	<b>Prod</b>	2007

Invoice No.	Date	Odometer / Hours	Description	Type
TRUCK CAME IN WITH LOW ENGINE OIL TOPPED UP ENIGNE OIL AND VISUAL CHECK FOR LEAKS - ALL OK				
53217	23/11/2021	588850	LH STEP	Invoice
REMOVE DAMAGED LHS STEP AND STRIP OFF TOP STEP GRILL. PRIME AND PAINT NEW STEP SURROUND AND STEP. FIT NEW STEP SURROUND TO VEHICLE AND ATTACHED STEP GRILLS. TESTED OPERATION AND PARKED ON STREET				
53216	22/11/2021	588850	LIFTER MOTOR EXHAUST	Invoice
REPLACED MUFFLER ON LIFTER MOTOR REMOVED OLD MUFFLER FROM VEHICLE CLEANED UP SURFACES FOR NEW GASKETS AND MUFFLER FITMENT HELLI-COIL THE STUD HOLE AFTER DUE TO OLD STUD SNAPPING AND SEIZED FIT NEW MUFFLER AND TESTED OPERATION OF LIFTER MOTOR - ALL OK				
52986	14/10/2021	578753	REPAIRS	Invoice
TILTED THE CAB AND INSPECTED FOR A NOISE WHEN THE ENGINE IS RUNNING, FOUND THAT THE A/C COMPRESSOR HAS SEIZED. RECLAIMED REMAINING A/C GAS  REMOVE AND REPLACE SEIZED COMPRESSOR, REPLACE BELT TENSIONER AND BELT. EVACUATE, REGAS AND RECHARGE A/C SYSTEM TO CORRECT PRESSURE CHECKED A/C THERMOSTAT FOR LEAKS, FAN SPEEDS AND AIR FLOW FROM VENTS - ALL OK				
52677	16/08/2021	578753	LIFTER MOTOR SERVICE AND REPAIRS	Invoice
CARRY OUT SERVICE ON LIFTER MOTOR FUEL TANK RUBBER STRAP WAS HANGING DOWN LOOSEENED FUEL TANK, LIFTED TANK AND REFTTED RUBBER STRAP AROUND FUEL TANK POLISHED HEADLIGHTS DEFECTS: P/S STEP TO BE REPLACED - LOWER STEP COME AWAY FROM BASE				
52695	12/08/2021	577749	LOW OIL WARNING LIGHT	Invoice
VEHICLE ARRIVED WIRH LOW OIL WARNING LIGHT ON DASH JACKED UP CAB AND INSPECTED OIL LEVELS TOPPED UP LOW OIL AND INSPECTED FOR LEAKS - ALL OK REPLACED MISSING BOLTS ON EXHAUST MOUNTING BRACKET				
52587	27/07/2021	575249	WARNING ON DASH	Invoice
VEHICLE CAME IN WITH WARNING "CHECK BRAKE SYSTEM ON NEXT STOP" WARNING ON DASH TOPPED UP ENGINE OIL AND RECHECKED - ALL OK CONNECTED JALTEST TO ASSESS BRAKE WARNING CODE ON DASH FOUND OLD CODES BUT NO NEW CODES PRESENT CLEARED ALL CODES AND RESTESTED - ALL OK				
52521	20/07/2021	869	LIFTER MOTOR ISSUES	Invoice
TRAVEL TO REDBANK TO ATTEND LIFTER MOTOR NOT STARTING FOUND FAULTY GLASS FUSE ON REAR BOAD IN BOX ENSCLOSURE FAILED REPLACED FUSE - ALL OK				

**Vehicle Details**

<b>Registration</b>	339SHS	<b>Next Service</b>	<b>Litres</b>	
<b>Make</b>	VOLVO	<b>Rego Due</b>	<b>Trans</b>	N/A
<b>Model</b>	FE SERIES	<b>Engine #</b>	<b>Air</b>	Yes
<b>Model Series</b>		<b>VIN</b>	<b>Cyl</b>	0
<b>Model Code</b>	MINI LIFTER	<b>Build Date</b>	<b>Body</b>	TRUCK
<b>Colour</b>	White	<b>Odometer/Hr</b>	<b>Prod</b>	2007

Invoice No.	Date	Odometer / Hours	Description	Type
TRAVELLED BACK TO WORKSHOP				
52281	15/06/2021	567774	LIFTER MOTOR ISSUES	Invoice
INSPECTED POSSIBLE LEAK AT LIFTER MOTOR - NO OIL ON DIPSTICK REMOVED HYDRAULIC GEAR CHANGE COVER TO INSPECT MAIN SEAL FOUND SMALL WEEP AT MAIN SEAL - MONITOR				
52222	07/06/2021	0	WORN BRAKE ROTORS	Invoice
WHILST SERVICING THE TRUCK DIAGNOSED THE BRAKE ROTORS ARE ALL BADLY WORN AND HAVE LARGE LIPS ON THEM. ALL SIX ARE IN NEED OF REPLACEMENT. ALL BRAKE BRAKE PADS AS WE UNABLE TO REUSE THE OLD ONES. REMOVED CALIPERS, HUBS AND AXLES, STRIP OFF OLD BRAKE ROTORS, INSTALL NEW BRAKE ROTORS AND REFIT HUBS. REFITTED THE CALIPERS AND INSTALLED NEW BRAKE PADS AND WEAR INDICATORS.  NOTE: THE LAZY AXLE TAKES DIFFERENT ROTORS TO THE DRIVE AND STEERING AXLES. TEST DROVE AND BEDDED IN BRAKES. OK				
52212	03/06/2021	567399	CARRY OUT B SERVICE	Invoice
CARRIED OUT A AND B SERVICE PEFORMED VALVE SET ON ENGINE REMOVED ROCKER COVER, TURNED ENGINE TO TDC NUMBER 6 AND CHECKED CHARGE AND TOLERANCES FOUND VALVES VERY LOOSE, ADJUSTED ALL VALVES TO CORRECT SPECS TURNED ENGINE OVER TO TDC NUMBER 1 AND REPEATED PROCESS ADJUSTED ALL VALVES TO COREECT SPECS VALVE CLEARANCES ALL OK CHECKED OIL AND COOLANT LEVELS AFTER REPAIRS DEFECTS: SLIGHT CRACKING AT BASES OF AIR BAGS PASSENGER SIDE STEP CRACKED BUMP STOPS WEARING DOWN - MONITOR				
52199	02/06/2021	0	BLOWN TURBO	Invoice
REMOVE TURBO AND INTAKE SYSTEM INCLUDING INTERCOOLER. HAVE INTERCOOLER CLEANED TO REMOVE BROKEN PIECES OF TURBO CHARGER. CLEAN ALL INTAKE PARTS AND PREPARE FOR REFITTING. REMOVE EXHAUST MANIFOLD AND REPLACE LEAKING EXHAUST GASKET. FIT NEW TURBO CHARGER AND REFIT INTAKE SYSTEM REMOVED FOR CLEANING. REFIT CLEANED INTER COOLER AND TEST DRIVE.				
52114	19/05/2021	564634	OIL LIGHT ON DASH	Invoice
VEHICLE CAME IN WITH OIL ENGINE LIGHT ON DASH OIL LEVEL WAS LOW - SLIGHT WEEP COMING FROM SUMP - MONITOR TOPPED UP ENGINE OIL AND TESTED OK				
52060	11/05/2021	563671	CLUTCH ACTUATOR	Invoice

**Vehicle Details**

<b>Registration</b>	339SHS	<b>Next Service</b>	<b>Litres</b>	
<b>Make</b>	VOLVO	<b>Rego Due</b>	<b>Trans</b>	N/A
<b>Model</b>	FE SERIES	<b>Engine #</b>	<b>Air</b>	Yes
<b>Model Series</b>		<b>VIN</b>	<b>Cyl</b>	0
<b>Model Code</b>	MINI LIFTER	<b>Build Date</b>	<b>Body</b>	TRUCK
<b>Colour</b>	White	<b>Odometer/Hr</b>	<b>Prod</b>	2007

Invoice No.	Date	Odometer / Hours	Description	Type
VEHICLE CAME IN LEAKING AIR INSPECTED VEHICLE AND FOUND CLUTCH LEAKING AIR UPON FURTHER INSPECTION FOUND CLUTCH SLAVE CYLINDER LEAKING REMOVED OLD CLUTCH ACTUATOR AND DICONNECTED HYDRAULIC LINES REPLACED CLUTCH ACTUATOR AND ADDED PIPE SEALANT TO FITTINGS SECURED ACTUATOR AND TIGHTENED NUTS AND BOLTS BLED CLUTCH AND CHECKED OPERATION - ALL OK				
51962	30/04/2021	561792	CARRY OUT REPAIRS	Invoice
INSPECTED DRIVERS DOOR AND FOUND GLASS BROKEN REMOVED DOOR CARD AND VACCUMED OUT BROKEN GLASS. VACCUMED OUT CAB GLASS WAS FOUND ON THE PASSENGER SIDE OF THE VEHICLE. REPLACED WINDOW GLASS ASSEMBLY AND REFITTED MOTOR, SILL PANELS AND DOOR COVER - TESTED ALL OK. LHS STEP - CRACKED QUOTED TO BE REPAIRED.				
51789	31/03/2021	557890	CARRY OUT REPAIRS	Invoice
DRIVE BROUGHT IN TRUCK WITH D/S MUDGUARD LOOSE INSPECTED AND FOUND THE BOLT SNAPPED - REPLACED BOLT AND NUT TIGHTEN BOLTS AND TESTED OK				
51785	29/03/2021	557582	CARRY OUT REPAIRS	Invoice
INSPECTED SIDE MARKER LIGHTS NOT WORKING. DIAGNOSED CORRODED WIRING AT REAR OF VEHICLE. CUT OUT CORRODED SECTION AND REPAIRED. CHECKED LIGHTS, FUSES AND RELAYS - ALL OK.				
51660	12/03/2021	554431	A SERVICE	Invoice
<b>DATE WORK CARRIED OUT:</b> 12/03/21  <b>WORK CARRIED OUT:</b> TOP UP ENGINE OIL TOP UP COOLANT CHECK FRONT TYRE PRESSURES & ADJUST TOP UP HYDRAULIC OIL REPLACE TOP LEFT HAND MARKER LIGHT  <b>DEFECTS NOTED</b>  <ul style="list-style-type: none"><li>• TOP LEFT HAND MARKER LIGHT HAD WATER IN IT. CLEAN AND REPLACE BULB</li></ul>				
51272	19/01/2021	0	OIL LEAK FROM GEARBOX	Invoice
<b>DATE WORK CARRIED OUT:</b> 19/01/2021 <b>WORK CARRIED OUT:</b> INSPECTED OIL LEAK FROM GEARBOX CLEANED TOP OF GEARBOX AND CHECKED THE TIGHTNESS OF THE BREATHER – OK				



**Vehicle Details**

<b>Registration</b>	339SHS	<b>Next Service</b>	<b>Litres</b>	
<b>Make</b>	VOLVO	<b>Rego Due</b>	<b>Trans</b>	N/A
<b>Model</b>	FE SERIES	<b>Engine #</b>	<b>Air</b>	Yes
<b>Model Series</b>		<b>VIN</b>	<b>Cyl</b>	0
<b>Model Code</b>	MINI LIFTER	<b>Build Date</b>	<b>Body</b>	TRUCK
<b>Colour</b>	White	<b>Odometer/Hr</b>	<b>Prod</b>	2007

Invoice No.	Date	Odometer / Hours	Description	Type
RAN THROUGH GEARS AND CHECKED FOR ANY LEAKS – COULDN'T FAULT AT TIME OF INSPECTION REINSPECTED FOR OIL LEAKS FOUND THAT ONE OF THE 4 RIVITS THAT HOLD THE ID TAG ONTO THE TOP OF THE GEARBOX WAS LEAKING OIL. SEALED HOLE ALL OK.				

<b>51324</b>	<b>14/01/2021</b>	<b>543586</b>	<b>A &amp; B SERVICE</b>	<b>Invoice</b>
--------------	-------------------	---------------	--------------------------	----------------

**DATE WORK CARRIED OUT:** 14/01/2021

**WORK CARRIED OUT:**

CARRIED OUT A & B SERVICE

**DEFECTS NOTED**

- SUMP PLUG – R/H SIDE THREAD STRIPPED – STILL FUNCTIONING PROPERLY
- MULTIPLE CRACKS ON MUFFLER & HOLES IN PIPE THAT GOES TO STACK @ L/H LEAF SPRING
- MOVEMENT IN KING PINS
- MOVEMENT IN R/H WHEEL BEARING (MINIMAL)
- EXTINGUISHER HAS NO DATE
- ALTERNATOR HAS A LITTLE NOISE (MONITOR)
- ALTERNATOR TENSIONER BEARINGS ON THEIR WAY OUT
- MINOR COOLANT WEEP @ THERMOSTAT HOUSING GASKET
- F/REAR AXLE, R/H SIDE MONITOR BRAKE PADS

<b>51070</b>	<b>10/12/2020</b>	<b>539402</b>	<b>REPAIRS NOTED ON SERVICE</b>	<b>Invoice</b>
--------------	-------------------	---------------	---------------------------------	----------------

**DATE WORK CARRIED OUT:** 03/12/2020 – 14/12/2020

**WORK CARRIED OUT:**

REPLACED AIR DRYER & FILTER  
REPLACED RH REAR MUDGUARD LOOP KIT  
CHECKED FOR FAULT CODES WITH COMPUTER (SOFTWARE NOT COMPATIBLE)  
AIR DRYER REQUIRES SOFTWARE TRANSFER  
REMOVED RH SEAT CUSHION  
REMOVED TAILSHAFT, GEARBOX ACCESSORIES, GEARBOX, CLUTCH & FLYWHEEL  
REPAIRED HOLES IN EXHAUST PIPE  
FITTED SEAT BASE / CUSHION & COVER  
REMOVED TANK STRAPS AND PEELED OFF OLD RUBBER BACKING PLATES  
CLEANED BACK OF STRAPS AND FITTED NEW RUBBER BACKING PLATES  
FITTED STRAPS TO TANK  
CONNECTED SCAN TOOL  
TRIED TO CALIBRATE NEW AIR DRYER  
STILL SHOWING AN ACTIVE CODE AND WARNING ON DASH  
MIGHT NEED TO BE DONE WHILST THE TRUCK IS RUNNING (TRUCK CURRENTLY DISABLED)  
FITTED NEW REPAIR SLEEVE ON THE CRANK HOWEVER IT WAS STILL STICKING OUT BEYOND THE CRANK FACE  
TRIED TO KNOCK THE LIP OFF THE INSIDE FLANGE WHICH WOULD ALLOW THE SLEEVE TO GO ON FURTHER  
HOWEVER THE SLEEVE FOLDED INSIDE THE FLYWHEEL HOUSE AND NEEDED TO COME BACK OFF WHICH DAMAGED IT  
REPLACED SEAL  
MARKED A LINE ON THE SLEEVE AND GROUND DOWN THE SLEEVE SLOWLY TO THE CORRECT SIZE  
FITTED THE SLEEVE TO THE CRANK  
CHECKED / REPLACED U/S L/H/F SIDE CLEARANCE MARKER LAMP & REFLECTOR  
TESTED – ALL OK  
FITTED REAR MAIN SEAL  
FITTED FLYWHEEL AND CLUTCH

**Vehicle Details**

<b>Registration</b>	339SHS	<b>Next Service</b>	<b>Litres</b>	
<b>Make</b>	VOLVO	<b>Rego Due</b>	<b>Trans</b>	N/A
<b>Model</b>	FE SERIES	<b>Engine #</b>	<b>Air</b>	Yes
<b>Model Series</b>		<b>VIN</b>	<b>Cyl</b>	0
<b>Model Code</b>	MINI LIFTER	<b>Build Date</b>	<b>Body</b>	TRUCK
<b>Colour</b>	White	<b>Odometer/Hr</b>	<b>Prod</b>	2007

Invoice No.	Date	Odometer / Hours	Description	Type
			FITTED GEARBOX AFTER REPAIRS AND FILLED WITH OIL FITTED TAILSHAFT AND TEST DROVE TRUCK HAD NO HIGH RANGE GEARS CHECKED GEARBOX OIL – TOPPED UP, STILL NO HIGH RANGE SUSPECT IT'S AN ISSUE WITH THE GEARBOX REMOVED THE RANGE CHANGE PISTON CAP OFF THE BACK OFF THE GEARBOX AND MOVED THE INTERNAL PISTON INTO THE HIGH RANGE POSITION STILL CAN'T GET GEAR BEN FROM BRYMAD TRUCK TRANSMISSIONS CAME OUT AND INSPECTED AND REPAIRED – ALL OK	

51011	02/12/2020	539402	C SERVICE	Invoice
<b>DATE WORK CARRIED OUT:</b> 02/12/2020 <b>WORK CARRIED OUT:</b> CARRIED OUT C SERVICE ATTEMPTED TO REMOVE AIR DRYER FILTER (SEIZED) REMOVED RH REAR MUDGUARD LOOP KIT TO BE REPLACED REMOVED LH #1 SIDE MARKER LIGHT TO BE REPLACED POLISHED HEADLIGHTS  <b>DEFECTS NOTED</b> <ul style="list-style-type: none"><li>- SMALL WINDSCREEN CHIP</li><li>- RH SEAT CUSHION &amp; COVER U/S</li><li>- RH MUDGUARD LOOP KIT U/S</li><li>- AIR DRYER ASSEMBLY NEEDS REPLACING</li><li>- LH #2 SIDE MARKER LIGHT N/W</li><li>- FUEL TANK STRAP RUBBERS U/S</li><li>- REAR MAIN SEAL LEAKING</li><li>- GEARBOX INPUT SELECTOR &amp; TOP OF BOX LEAKING OIL</li><li>- RH #2 DIFF INSIDE TYRE INSIDE TYRE LOW TREAD (POSITION 9)</li><li>- ENGINE OIL DUE @ 540000</li></ul>				

50955	24/11/2020	0	OIL LEAK	Invoice
<b>DATE WORK CARRIED OUT:</b> 24/11/2020  <b>WORK CARRIED OUT:</b> INSPECTED OIL LEAKING FROM THE GEARBOX. DEGREASED ON TOP OF THE GEARBOX. SUSPECT THAT ONE OF THE AIR ACTUATORS SEALS HAS FAILED AND IS ALLOWING COMPRESSED AIR INTO THE GEARBOX THIS IS PUSHING OIL OUT OF THE SEALS THE GEARBOX NEEDS TO BE REMOVED AND HAVE THE INPUT SHAFT SEAL CHANGED THE BANK OF AIR ACTUATORS NEEDS TO BE REMOVED AND THE FAULTY ONE REPLACED TO PREVENT THE GEARBOX GETTING PRESSURISED				

50858	11/11/2020	534867	TOP UP ENGINE OIL	Invoice
-------	------------	--------	-------------------	---------

**Vehicle Details**

<b>Registration</b>	339SHS	<b>Next Service</b>	<b>Litres</b>	
<b>Make</b>	VOLVO	<b>Rego Due</b>	<b>Trans</b>	N/A
<b>Model</b>	FE SERIES	<b>Engine #</b>	<b>Air</b>	Yes
<b>Model Series</b>		<b>VIN</b>	<b>Cyl</b>	0
<b>Model Code</b>	MINI LIFTER	<b>Build Date</b>	<b>Body</b>	TRUCK
<b>Colour</b>	White	<b>Odometer/Hr</b>	<b>Prod</b>	2007

Invoice No.	Date	Odometer / Hours	Description	Type
DATE WORK CARRIED OUT: 11/11/2020				
WORK CARRIED OUT: SHOWED THE DRIVER HOW TO JACK UP THE CAB AND CHECKED THE OIL LEVEL. TOPPED UP ENGINE OIL				
50714	03/11/2020	533122	A SERVICE	Invoice
DATE WORK CARRIED OUT: 03/11/2020				
WORK CARRIED OUT: CARRIED OUT A SERVICE AS PER HVW SERVICE SHEET				
<b>FURTHER ACTION REQUIRED -</b>				
DRIVER SEAT RIPPED SECTION OF EXHAUST BETWEEN MUFFLER AND STACK RUSTED OUT FRONT SAY BAR LINK BUSHES U/S FIRE EXTINGUISHER OUT OF DATE INNER TYRE VALVE EXTENSION MISSING X 4				
50634	08/10/2020	527651	REPLACE TWIST LOCK HANDLE	Invoice
DATE WORK CARRIED OUT: 08/10/2020				
WORK CARRIED OUT: REPLACED TWIST LOCK HANDLE				
50562	29/09/2020	526083	RR - 106225 BATTERY ISOLATOR	Invoice
DATE WORK CARRIED OUT: 29/09/2020				
WORK CARRIED OUT: REPLACED BATTERY ISOLATOR SWITCH				
RR - 106225				
50563	29/09/2020	526083	WINDOW WASHERS	Invoice
DATE WORK CARRIED OUT: 29/09/2020				

**Vehicle Details**

<b>Registration</b>	339SHS	<b>Next Service</b>	<b>Litres</b>	
<b>Make</b>	VOLVO	<b>Rego Due</b>	<b>Trans</b>	N/A
<b>Model</b>	FE SERIES	<b>Engine #</b>	<b>Air</b>	Yes
<b>Model Series</b>		<b>VIN</b>	<b>Cyl</b>	0
<b>Model Code</b>	MINI LIFTER	<b>Build Date</b>	<b>Body</b>	TRUCK
<b>Colour</b>	White	<b>Odometer/Hr</b>	<b>Prod</b>	2007

Invoice No.	Date	Odometer / Hours	Description	Type
<p>WORK CARRIED OUT: CHECKED FOR WASHER BOTTLE FAULT REMOVED LH STEP &amp; WASHER BOTTLE TEST WASHER BOTTLE MOTOR CLEAN OUT ALGAE FROM BOTTLE, REPAIRED THE TOP OF THE WASHER BOTTLE USING ALUMINIUM WEATHER PROOF TAPE.</p> <p>REFITTED BOTTLE TO VEHICLE AND FILLED WITH WASHER FLUID. CHECKED / REPLACED LEAKING/ BLOCKED WINDOW WASHER HOSES. UNBLOCKED L &amp; R WINDSCREEN NOZZLES - TEST ALL OK</p>				
50495	23/09/2020	525287	REPALCE BATTERY	Invoice
<p>DATE WORK CARRIED OUT: 23/09/2020</p> <p>WORK CARRIED OUT: REMOVED AND REPLACE 2 X FAULTY BATTERIES.</p> <p>TESTED ALL OK.</p>				
50496	23/09/2020	525094	JUMPSTART	Invoice
<p>DATE WORK CARRIED OUT: 23/09/2020</p> <p>WORK CARRIED OUT: ATTEND SITE TO JUMP START VEHICLE.</p> <p>RECOMMEND NEW BATTERIES</p>				
50487	22/09/2020	525070	JUMPSTART	Invoice
<p>DATE WORK CARRIED OUT: 22/09/2020</p> <p>WORK CARRIED OUT: ATTEND BT YARD AND JUMP START TRUCK</p> <p><b>Requirements for next service are -</b></p> <p>RECOMMEND FITTING ISOLATOR WOULD HELP KEEP THE BATTERIES CHARGED AS WELL</p>				
50438	14/09/2020	524754	JUMPSTART	Invoice

**Vehicle Details**

<b>Registration</b>	339SHS	<b>Next Service</b>	<b>Litres</b>	
<b>Make</b>	VOLVO	<b>Rego Due</b>	<b>Trans</b>	N/A
<b>Model</b>	FE SERIES	<b>Engine #</b>	<b>Air</b>	Yes
<b>Model Series</b>		<b>VIN</b>	<b>Cyl</b>	0
<b>Model Code</b>	MINI LIFTER	<b>Build Date</b>	<b>Body</b>	TRUCK
<b>Colour</b>	White	<b>Odometer/Hr</b>	<b>Prod</b>	2007

Invoice No.	Date	Odometer / Hours	Description	Type
DATE WORK CARRIED OUT: 14/09/2020				
WORK CARRIED OUT: ATTENDED YARD TO JUMP START VEHICLE				
50352	31/08/2020	524750	JUMPSTART	Invoice
DATE WORK CARRIED OUT: 31/08/2020				
WORK CARRIED OUT: ATTEND BT YARD				
JUMP STARTED VEHICLE				
50317	20/08/2020	524753	AIR FITTING - REPAIR REQUEST	Invoice
DATE WORK CARRIED OUT: 20/08/2020				
WORK CARRIED OUT: CHECKED REPAIR REQUEST BOOK.				
REPLACED INNER AIR FILTER.				
50409	18/08/2020	524752	A & B SERVICE ON TRUCK & LIFTER	Invoice
DATE WORK CARRIED OUT: 18/08/2020				
WORK CARRIED OUT: CARRIED OUT A & B SERVICE ON TRUCK & LIFTER				
DEFECTS NOTED				
- WASHER BOTTLE CRACKED				
- DRIVERS SEAT BASE – TORN				
- FRONT SWAY BAR BUSHES & LINK BUSHES				
- FRONT ROTORS WILL NEED REPLACING WHEN THE PADS - REPLACED.				
- REEF SPOILER MOUNT BRACKET - RUSTY				
50252	11/08/2020	524614	JUMP START	Invoice
DATE WORK CARRIED OUT: 11/08/2020				
WORK CARRIED OUT: TRAVEL TO SITE YARD AND JUMP START				

**Vehicle Details**

<b>Registration</b>	339SHS	<b>Next Service</b>	<b>Litres</b>	
<b>Make</b>	VOLVO	<b>Rego Due</b>	<b>Trans</b>	N/A
<b>Model</b>	FE SERIES	<b>Engine #</b>	<b>Air</b>	Yes
<b>Model Series</b>		<b>VIN</b>	<b>Cyl</b>	0
<b>Model Code</b>	MINI LIFTER	<b>Build Date</b>	<b>Body</b>	TRUCK
<b>Colour</b>	White	<b>Odometer/Hr</b>	<b>Prod</b>	2007

Invoice No.	Date	Odometer / Hours	Description	Type
50297	15/07/2020	0	REPLACE WINDSCREEN	Invoice

DATE WORK CARRIED OUT:

WORK CARRIED OUT:  
SUPPLY & FIT FRONT WINDSCREEN MK1803 & NEW MOULD

50200	09/07/2020	797	SERVICE & REPAIRS & ELECTRICAL	Invoice
-------	------------	-----	--------------------------------	---------

DATE WORK CARRIED OUT: 09/07/2020 - 28/7/2020

WORK CARRIED OUT:  
REMOVED REAR CRANE LIFT ARM DAMAGE PIPE & FITTING

REPLACED FITTINGS & PIPE  
INCORRECT PIPE WAS SUPPLIED & REMOVED  
"A" SERVICE AS PER SERVICE SCHEDULE  
REPLACE REAR CRANE TOP ARM GREASE NIPPLE  
REPAIRED REAR TWIST LOCK HOUSING  
FITTED ALL LIFT CHAINS  
ZIP TIES REAR CRANE WIRING  
TIGHTENED REAR CRANE HYDRAULIC HOSES & FITTINGS  
TESTED OPERATION - ALL OK  
REPLACED RH WIPER BLADE  
TIGHTENED LH #1 DIFF MUDGUARD POLE  
REPLACED HYDRAULIC LINE ON TRUCK LIFTER REAR MODULE TOP STEEL LINE  
INSPECT BEATING ISSUE ON TRUCK  
REMOVED DRIVERS SEAT FOR REPAIRS

REPLACED MARKER PLATES CLASS 1 300 X 300 & WARNING CLASS 1 300X400MM  
COMPLETED REMOVING GEARBOX  
REMOVE AND REPLACE BRAKE AND CLUTCH RUBBERS  
REMOVE AND REPLACE DRAG LINK ASSY  
REMOVE AND REPLACE TIE ROD ENDS  
REMOVE GEARBOX TO REMOVE REAR MAIN SEAL AND REPLACE

REPLACE TIE ROD AND WHEEL ALIGN TRUCK  
REFIT FLY WHEEL AND TENSION UP FIT UP CLUTCH PLATE

REFIT GEAR BOX BACK INTO PLACE CONNECT ALL AIR LINES BACK INTO PLACE AND GEAR LINKAGES AND SLAVE TEST OPERATION

USING JALTEST 032# SCANNER MADE TEST TO ABS BRAKE WARNING FAULT ON DASH  
TRACED ABS WIRING TO FRONT RHS SENSOR NO SIGNAL PRESENT CLEARED DIRT & DEBRIS OFF SENSOR AND CHOPPED RING PIECE  
FOUND FRONT RHS ABS SPEED SENSOR IS U/S REPLACED SENSOR ASSY & RE-CALIBRATED AS REQUIRED INCLUDING ROAD TESTING TO SEE IF ABS LIGHT STAYS ON - CLEAR NO LIGHTS ON DASH -ALL OK



Vehicle Details

Registration	339SHS	Next Service		Litres	
Make	VOLVO	Rego Due		Trans	N/A
Model	FE SERIES	Engine #		Air	Yes
Model Series		VIN	YV2VBN0CX7B473951	Cyl	0
Model Code	MINI LIFTER	Build Date	2007	Body	TRUCK
Colour	White	Odometer/Hr	726780 / 905	Prod	2007

Invoice No.	Date	Odometer / Hours	Description	Type
-------------	------	------------------	-------------	------