

DEAN'S HYDRAULIC SERVICES
84 - 96 DALTON ST (Delivery)
PO Box 435 (Postal)
PARKES NSW 2870

Company ABN 40 002 128 592

Phone # 0268622833

sales@deanhyd.com.au

Tax Invoice

Date Tax Invoice #

17/09/2025 130902

Tax Invoice To
CASH SALE

Ship To
CASH SALE

Contact	P.O. No.	Terms	Rep	Vehicle Details		Speedo	
		CASH - NO ACCO...	KEN	BV57BG		588800	
Item	Description			Qty	Rate	Tax	Amount
REPAIRS3CARRIED	REPAIRS CARRIED OUT:					GST	0.00
	* REMOVE AND REPLACE TURNTABLE TOP						
	* DISCONNECT AUTO GREASING SYSTEM FROM TURNTABLE						
LABOUR 145	LABOUR CHARGE PER HOUR - STANDARD			2.5	159.50	GST	398.75
CONSUMABLES	CONSUMABLE ITEMS			1	22.00	GST	22.00
NPN	JSK37C-D6GF JOST TURNTABLE TOP GREASLESS TOP			1	3,650.00	GST	3,650.00
	SUIT JSK37C						
FREIGHTCHARGE	FREIGHT CHARGE TO CUSTOMER			1	182.25	GST	182.25
HV-DEFECT	CLEAR VEHICLE DEFECT NOTICE No. AHV1589058 ON			1	47.00	FRE	47.00
	CLEARANCE INSPECTION REPORT No. CA2876075						

Thank you for your business

Bank Account Number 10034219 BSB 062-588

Discounts will be forfeited on accounts outside our trading terms and 5% added to unpaid amount

Please note that a payment processing fee is added to all credit card payments.

WARNING - CHECK WHEEL NUTS AFTER 5 KM OF DRIVING. WHEEL NUTS
MAY SLACKEN OFF SLIGHTLY IN THE FIRST FEW KILOMETRES.
DEAN'S HYDRAULICS SHALL NOT BE RESPONSIBLE IF THIS IS NOT DONE.

Subtotal \$3,913.36

Tax \$386.64

Total \$4,300.00

Balance Due \$4,300.00

Authorised Inspection Station Defect Notice Clearance Inspection Report

Inspection number : CA2876075 Inspection date : 17/09/2025
 Inspection status : Pass Amount paid : 47.00

Inspection station

Number : S05655
 Name : Deans Hydraulic Services
 Address : 84-96 Dalton Street
 PARKES, NSW 2870

Vehicle details

Number plate	: BV57BG	ADR category code	: HEAVY GOODS VEHICLE
Class	: Heavy Vehicle	Engine capacity	: 15200.0
Make	: WESTERN STAR	Number of cylinders	: 6
Model	: 4800FX	or rotors	
VIN/Chassis	: 5KKJAEAV29PZ07778	Motive Power	: Diesel
Engine number	: NXS32058	Sleeping berth fitted?	: Yes
Odometer reading	:	R or L hand drive?	: RIGHT
Compliance date	: 11/2009	Wheelbase	: 512.0
Manufacture year	:	Length	:
Primary colour	: WHITE	Width	:
Shape	: PRIME MOVER	Height	:
GVM	: 24500	Rear overhang(R)	:
GCM	: 90500	Projection	:
Tare weight	: 10110	Sleeping berth	:
Overall axle space	: 559	variant	
Axle code	: R14 - Rigid (incl P/M) - S, D/D	Trailer Brakes	:
No. of driven wheels	: 4	Monitoring device	: No
Total No. of seated persons	: 2	Conditions	:
No. of standing persons	:	Fittings	:

Defect notice(s) cleared
 AHV1589058

Reason for
 inspection : Defect notice clearance

Comments

Examiner's certification

I am satisfied that the vehicle I inspected is the same vehicle for which the defect notice was issued and have found that the defect(s) specified have been properly rectified and any labels affixed have been removed or defaced by me.

Examiner's
signature

: 1362

Examiner's number : E15111

Privacy Statement

Any personal information is being collected under the Road Transport Act 2013 to notify Roads and Maritime Services (RMS) in relation to the inspection of a motor vehicle. Failure to supply the information may result in a refusal to renew the registration. The information is being collected for RMS and may be disclosed in accordance with the exemptions provided under the Privacy and Personal Information Protection Act 1998. Individuals may also seek to have their personal information amended or corrected in accordance with the provisions of that Act.

Customer Copy