



Vehicle History

Vehicle Details

Registration	532QUM	Next Service	Litres	
Make	STEELBRO	Rego Due	Trans	N/A
Model	TRI AXLE SIDE	Engine #	Air	No
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	TRAILER
Colour		Odometer/Hr	Prod	

Invoice No.	Date	Odometer / Hours	Description	Type
61105	18/06/2025	484186/2748	DEFECTS	Invoice

BRING VEHICLE IN TO WORKSHOP
ESTIMATE REPAIRS ADVISED BY STEELBRO
CHECKED FOR BOOSTER LEAK
REPLACED LH #3 AXLE BRAKE BOOSTER
WHILE CHANGING BOOSTER - FOUND OTHER DEFECTS - EMAILED OFFICE
CHECKED FOR MARKER LIGHT NOT WORKING
REPLACED RH REAR SIDE MARKER LIGHT
STRAIGHTENED MOUNTING BRACKET
RECEIVE A \$25 DISCOUNT FOR ANY POSITIVE GOOGLE REVIEW ON OUR COMPANY GOOGLE WEBPAGE - HEAVY VEHICLE WORKSHOP
HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE THE STORE FOR PRICING ON - 07 3260 8950

61095	17/06/2025	491128/2748	REPAIRS	Invoice
60924	13/05/2025	491128/2748	DEFECTS	Invoice

PARKED TRAILER IN WORKSHOP
CHECKED FOR LIFT AXLE FAULT
REPLACED AIR FITTING @ ACTUATOR
STRAIGHTENED LH #3 AXLE MUDGUARD BRACKETS
FIT MUDGUARD TO LH #3 AXLE
FIT NEW MUDFLAP
PLACED BATTERY ON CHARGE
STARTED ENGINE + CHECKED ALT CHARGE RATE
RETURNED TRAILER TO SHED 24
HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE THE STORE FOR PRICING ON - 07 3260 8950
RECEIVE A \$25 DISCOUNT FOR ANY POSITIVE GOOGLE REVIEW ON OUR COMPANY GOOGLE WEBPAGE - HEAVY VEHICLE WORKSHOP

60183	25/11/2024	480711/2748	A SERVICE	Invoice
-------	------------	-------------	-----------	---------

PARK TRAILER IN WORKSHOP
CARRY OUT A SERVICE AS PER SERVICE SHEET
APPLY AIR TO TRAILER
TEST LIGHTING FUNCTION
LIFT TRAILER WITH HOIST
CHECK WHEEL BEARINGS FOR MOVEMENT
CHECK SUSPENSION COMPONENTS

Vehicle Details

Registration	532QUM	Next Service	Litres	
Make	STEELBRO	Rego Due	Trans	N/A
Model	TRI AXLE SIDE	Engine #	Air	No
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	TRAILER
Colour		Odometer/Hr	Prod	
		484186 / 2748		

Invoice No.	Date	Odometer / Hours	Description	Type
			<p>CHECK KING PIN BOLT TENSION CHECK SKID PLATE CHECK THE UNDERCARRIAGE OF THE TRAILER CARRY OUT GREASING OF AXLES CARRY OUT ADJUSTMENT OF BRAKES LOWER TRAILER CHECK WHEEL TENSION CHECK WHEEL BEARING GREASE FOR CONTAMINANTS CHECK ALL LIVERY INCLUDING MUDFLAPS AND DECAL INSPECT MARKER PLATES INCLUDING CON SIGN, CHEVRONS, AND OVERTAKE SIGNAGE CHECK TOP DECK OF TRAILER FOR ALL FUNCTIONALITY APPLY SERVICE STICKER COMPLETE PAPERWORK CLEAN WORK AREA MOVE TRAILER OUT OF WORKSHOP NOTE ADJUST FRONT WHEEL BEARINGS FRONT LEFT MUDGUARD - MINOR CRACK SURFACE RUST ON FRONT OF TRAILER ON TOP GREASED UNDERSIDE OF TRAILER RETURN TRAILER TO SHED 24</p> <p><u>HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE CHRIS FOR PRICING ON - 07 3260 8950</u></p>	
60128	12/11/2024	479866/2748	REPLACE MUDGUARD	Invoice
			<p>REMOVE AND REPLACE LEFT HAND REAR MUDGUARD <u>HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE CHRIS FOR PRICING ON - 07 3260 8950</u></p>	
60098	07/11/2024	479866/2748	AIR BAG REPLACEMENT	Invoice
			<p>AIRBAG REPLACEMENT CLEAN FITTINGS AND CHECK OVER WORK PART CHARGED TO BREAKDOWN INVOICE</p> <p><u>HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE JEFF FOR PRICING ON - 07 3260 8950</u></p>	
60083	05/11/2024	479866/2748	BRAKEDOWN	Invoice
			<p>TRAVEL TO INGRAM RD ACACIA RIDGE FOR BREAKDOWN DISCONNECTED AND FOLDED OVER AIRLINE REPLACED AND RESET AIRBAG TRAVEL BACK TO WORKSHOP</p>	

Vehicle Details

Registration	532QUM	Next Service	Litres	
Make	STEELBRO	Rego Due	Trans	N/A
Model	TRI AXLE SIDE	Engine #	Air	No
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	TRAILER
Colour		Odometer/Hr	Prod	
		484186 / 2748		

Invoice No.	Date	Odometer / Hours	Description	Type
UNPACK TOOLS COMPLETE PAPERWORK <u>HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE JEFF FOR PRICING ON - 07 3260 8950</u>				
60031	24/10/2024	465073/2748	REMOTE REPLACEMENT - supply only	Invoice
SUPPLY ONLY				
59835	12/09/2024	465073/2748	TRAIER A SERVICE	Invoice
PARK TRAILER IN WORKSHOP CARRY OUT A SERVICE AS PER SERVICE SHEET APPLY AIR TO TRAILER TEST LIGHTING FUNCTION LIFT TRAILER WITH HOIST CHECK WHEEL BEARINGS FOR MOVEMENT CHECK SUSPENSION COMPONENTS CHECK KING PIN BOLT TENSION CHECK SKID PLATE CHECK THE UNDERCARRIAGE OF THE TRAILER CARRY OUT GREASING OF AXLES CARRY OUT ADJUSTMENT OF BRAKES LOWER TRAILER CHECK WHEEL TENSION CHECK WHEEL BEARING GREASE FOR CONTAMINANTS CHECK ALL LIVERY INCLUDING MUDFLAPS AND DECAL INSPECT MARKER PLATES INCLUDING CON SIGN, CHEVRONS, AND OVERTAKE SIGNAGE CHECK TOP DECK OF TRAILER FOR ALL FUNCTIONALITY APPLY SERVICE STICKER COMPLETE PAPERWORK CLEAN WORK AREA MOVE TRAILER OUT OF WORKSHOP NOTE DIAGNOSED TRAILER AIR CONCERN REAR SUSPENSION WAS DUMPING AIR + BRAKE BOOSTER FR LEAKING INTERMITTENTLY POSSIBLE BOOSTER OR VALVE BRAKE FEEDING - REQUIRES FURTHER DIAGNOSES REPLACED R/S 1ST AXLE BRAKE BOOSTER REPLACED 2ND AXLE SHOCK ABSORBER CHECKED OVER TRAILER - FOUND MULTIPLE CRACKS AND BROKEN COMPONENTS PREPPED CRACKS AND REWELDED THEM WELDED BROKEN CROSS MEMBERS FLAT BARS <u>HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE JEFF FOR PRICING ON - 07 3260 8950</u>				
59735	22/08/2024	465073/2748	BATTERY CONCERN	Invoice
REMOVE AND REPLACE BATTERY CHECK CHARGE RATE 14.2V <u>HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND</u>				

Vehicle Details

Registration	532QUM	Next Service	Litres	
Make	STEELBRO	Rego Due	Trans	N/A
Model	TRI AXLE SIDE	Engine #	Air	No
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	TRAILER
Colour		Odometer/Hr	Prod	
		484186 / 2748		

Invoice No.	Date	Odometer / Hours	Description	Type
<u>MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE JEFF FOR PRICING ON - 07 3260 8950</u>				
59645	06/08/2024	463447/2748	GUARDS AND TWIST LOCK DAMAGED	Invoice
STRAIGHTEN BRACKETS FIT NEW GUARD REMOVE AND REPLACE BENT RHR TWIST LOCK CLEAN AREA COMPLETE PAPERWORK <u>HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE JEFF FOR PRICING ON - 07 3260 8950</u>				
59611	01/08/2024	465073/2748	ATTEND TO BURST HYDAULIC HOSE	Invoice
REPAIR BLOWN HYDRAULIC HOSE ONSITE				
59634	30/07/2024	46280/2748	REPLACE DAMAGED MUDGUARD	Invoice
REMOVE AND REPLACED DAMAGED R/R MUDGUARD. <u>HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE JEFF FOR PRICING ON - 07 3260 8950</u>				
59442	25/06/2024	457852/2748	C SERVICE	Invoice
PARK VEHICLE IN WORKSHOP CARRY OUT C SERVICE AS PER SERVICE SHEET CARRY OUT WALK AROUND VISUAL INSPECTION SECURE HOIST ON TRUCK CHECK ALL LIGHTS INCLUDING ALL REVERSE LAMPS AND BEEPERS CHECK WIPER AND WASHER OPERATION CHECK BATTERY LEVELS, TERMINALS AND CLAMPS LIFT CAB/BONNET TO ACCESS ENGINE BAY REPLACE CABIN AND ENGINE AIR FILTERS CHECK ALL BELTS AND MOUNTS LIFT TRUCK ON HOIST CARRY OUT VISUAL INSPECTION OF UNDERCARRIAGE (DRIVE LINE AND SUSPENSION COMPONENTS) DRAIN ENGINE OIL AND CHANGE FILTER ADJUST BRAKES AND CHECK BRAKE THICKNESSES CHECK AND ADJUST CLUTCH IF APPLICABLE CHECK GEARBOX OIL LEVEL AND QUALITY REPLACE IF REQUIRED CHECK DIFF OIL LEVEL AND QUALITY REPLACE IF REQUIRED CARRY OUT GREASING OF TRUCK LOWER TRUCK				

Vehicle Details

Registration	532QUM	Next Service	Litres	
Make	STEELBRO	Rego Due	Trans	N/A
Model	TRI AXLE SIDE	Engine #	Air	No
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	TRAILER
Colour		Odometer/Hr	Prod	
		484186 / 2748		

Invoice No.	Date	Odometer / Hours	Description	Type
FIL ENGINE OIL AND CHECK ENGINE OIL TOP-UP COOLANT IF REQUIRED LOWER CAB/BONNET AND SECURE IN PLACE FIT SERVICE STICKER COMPLETE PAPERWORK REMOVE HOIST NOTE REMOVED AND REPLACED REAR AXLE AIR BAGS COLLECTED PARTS FOR JOB REMOVE AND REPLACE LHM BOOSTER REMOVE AND REPLACE LHM SLACK ADJUSTER REMOVE CHAINS REMOVE AND REPLACE RHR MARKER HOLDER CLEAN TOOLS AREA <u>HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE JEFF FOR PRICING ON - 07 3260 8950</u>				
59422	19/06/2024	442904/2748	REMOTE STARTING NOT WORKING.	Invoice
INSPECT STARTING FAULT SUSPECTED SMALL ECU BATTERY - TESTED OKAY CHECKED ALL FUSES - NONE BLOWN CHECKED E-STOPS ISSUE WITH REAR CONTROL BOX SUSPECT EITHER E-STOP STUCK ON OR ISOLATOR FAULTY REMOVED AND REPLACED OLD ISOLATOR SWITCH MODIFIED BRACKET FOR THE ISOLATOR SWITCH FOUND FIEL FILTER BRACKET ON THE ENGINE WAS SNAPPED - WELDED BACK ON TESTED OPERATION OF VEHICLE - ALL OKAY <u>HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE JEFF FOR PRICING ON - 07 3260 8950</u>				
59182	08/05/2024	442904/2748	SUPPLY REMOTE BATTERIES	Invoice
SUPPLY REMOTE BATTERIES				
59130	24/04/2024	442904/2748	Vehicle attachment	Invoice
ASSESSED COOLANT BOTTLE HAD COME LOOSE AND HOSE ON COOLANT BOTTLE DAMADGED REMOVE DAMADGED HOSE FIT NEW HOSE RE-FIT COOLANT BOTTLE - ZIPTIE IN PLACE REFILL COOLANT <u>HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD -</u>				

Registration	532QUM	Next Service	Litres	
Make	STEELBRO	Rego Due	Trans	N/A
Model	TRI AXLE SIDE	Engine #	Air	No
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	TRAILER
Colour		Odometer/Hr	Prod	

Invoice No.	Date	Odometer / Hours	Description	Type
<u>STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE JEFF FOR PRICING ON - 07 3260 8950</u>				
58877	11/03/2024	442904/2748	REPLACED 3 WORN TYRES	Invoice
REMOVED AND REPLACED 3 WORN TYRES <u>HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.</u>				
58830	04/03/2024	442904/2748	C SERVICE AND HYDRAULIC RAMS	Invoice
PARK TRAILER IN WORKSHOP CARRY OUT A SERVICE AS PER SERVICE SHEET APPLY AIR TO TRAILER TEST LIGHTING FUNCTION LIFT TRAILER WITH HOIST CHECK WHEEL BEARINGS FOR MOVEMENT CHECK SUSPENSION COMPONENTS CHECK KING PIN BOLT TENSION CHECK SKID PLATE CHECK THE UNDERCARRIAGE OF THE TRAILER CARRY OUT GREASING OF AXLES CARRY OUT ADJUSTMENT OF BRAKES LOWER TRAILER CHECK WHEEL TENSION CHECK WHEEL BEARING GREASE FOR CONTAMINANTS CHECK ALL LIVERY INCLUDING MUDFLAPS AND DECAL INSPECT MARKER PLATES INCLUDING CON SIGN, CHEVRONS, AND OVERTAKE SIGNAGE CHECK TOP DECK OF TRAILER FOR ALL FUNCTIONALITY APPLY SERVICE STICKER COMPLETE PAPERWORK CLEAN WORK AREA MOVE TRAILER OUT OF WORKSHOP ***** FOUND HUB GREASE BLACK - STRIPPED DOWN FOR RE-PACK PUT BEARRINGS IN PARTS WASH FOUND 2ND AXLE RHS HUB SEAL HAD FAILED, BRAKES HAVE SOME GREASE ON THEM. CHECKED FOR REAR CRANK TOP ARM LEAKING DOWN CHECKED FOR LEAKS, CHECKED SENSORS + WIRING REMOVED HYDRAULIC BLOCK SAFETY VALVE FINISHED RE-PACK REPLACED BRAKES ON 2ND AXLE FIT NEW HYDRAULIC VALVE RETURNED TRAILER TO SHED 24 <u>HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.</u>				
58730	19/02/2024	440818/2748	VOLTAGE TEST OF BATTERY	Invoice

Vehicle Details

Registration	532QUM	Next Service	Litres	
Make	STEELBRO	Rego Due	Trans	N/A
Model	TRI AXLE SIDE	Engine #	Air	No
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	TRAILER
Colour		Odometer/Hr	Prod	
		484186 / 2748		

Invoice No.	Date	Odometer / Hours	Description	Type
CARRY OUT VOLTAGE TEST ON BATTERY - 5.2V REMOVED AND FIT BATTERY TO THE LIFTER MOTOR TESTED - OK CHECKED TO MAKE SURE ALTENATOR CHARGING BATTERY - ALL OK <u>HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.</u>				
58683	13/02/2024	440816/2748	A SERVICE + DIAGNOSE ELECTRICAL	Invoice

MOVED TRAILER FROM BUCCINI YARD INTO THE WORKSHOP
 CARRY OUT A SERVICE AS PER SERVICE SHEET
 CARRY OUT WALK AROUND VISUAL INSPECTION
 SECURE HOIST ON TRUCK
 CHECK ALL LIGHTS INCLUDING ALL REVERSE LAMPS AND BEEPERS
 CHECK WIPER AND WASHER OPERATION
 CHECK BATTERY LEVELS, TERMINALS AND CLAMPS
 LIFT CAB/BONNET TO ACCESS ENGINE BAY
 CHECK ALL BELTS AND MOUNTS
 LIFT TRUCK ON HOIST
 CARRY OUT VISUAL INSPECTION OF UNDER CARRIAGE (DRIVE LINE AND SUSPENSION COMPONENTS)
 ADJUST BRAKES AND CHECK BRAKE THICKNESSES
 CHECK AND ADJUST CLUTCH IF APPLICABLE
 CHECK GEAR BOX OIL LEVEL AND QUALITY
 CHECK DIFF OIL LEVEL AND QUALITY
 CARRY OUT GREASING OF TRUCK
 LOWER TRUCK
 CHECK ENGINE OIL
 TOP UP COOLANT IF REQUIRED
 LOWER CAB/BONNET AND SECURE IN PLACE
 FIT SERVICE STICKER

 FITTED LH #2 TWIST LOCK HANDLE
 REPLACED LH REAR TWISTLOCK DETENT
 REPLACED RH FRONT TWISTLOCK HANDLE AND DETENT
 REMOVED EXHAUST PIPE
 REMOVED FAN BELT, REPLACED AND ADJUSTED FAN BELT
 REPLACED 7 PIN ELECTRICAL SOCKET
 REPAIRED/WELDED EXHAUST PIPE
 REPLACED RIGHT HAND REAR HELLA R/A MARKER LIGHT
 STRIP AND FIT 2 X NEW TYRES
 TENSIONED ALL WHEELNUTS
 MADE VARIOUS TESTS/CHECKS TO AESSESS LIFTER FAULTS
 FOUND/REPAIRED U/S REAR CRANE BROKEN SENSOR CABLES AT FOUR PLACES/REPLACED SENSOR CABLES
 SENSOR - TEST OK
 RE-CHECKED ALL LIFTER / CRANE FUNCTIONS - ALL OK
 RETURNED TRAILER TO SHED 24

Vehicle Details

Registration	532QUM	Next Service	Litres	
Make	STEELBRO	Rego Due	Trans	N/A
Model	TRI AXLE SIDE	Engine #	Air	No
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	TRAILER
Colour		Odometer/Hr	Prod	
		484186 / 2748		

Invoice No.	Date	Odometer / Hours	Description	Type
58562	25/01/2024	438703/2462	REFIT TWIST LOCK HANDLES	Invoice
<p>REFIT 2 TWIST LOCK HANDLES AS ROLL PINS HAD BEEN SNAPPED OFF REPLACE 2 X POLL PINS</p> <p><u>HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.</u></p>				
58460	09/01/2024	437031/2462	HAND BRAKE HOT	Invoice
<p>DRIVER REPORTED RHS REAR BRAKE WERE HOTTER THAN OTHER BRAKES CHECKED BRAKE OPERATION + CHECKED FOR AIR LEAKS - ALL GOOD GREASED + ADJUSTED RHS REAR BRAKES</p> <p><u>HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.</u></p>				
58410	29/12/2023	435868/2462	REPLACE 2 WORN TYRES	Invoice
<p>REPLACE 2 WORN TYRES LHR LAZY AXLE STRIP AND FIT NEW TYRES TENSIONED ALL WHEEL NUTS</p> <p><u>HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.</u></p>				
58383	21/12/2023	435024/2462	REPLACE BLOWN RHR AXLE INNER TYRE	Invoice
<p>STRIP AND FIT NEW TYRE TENSIONED ALL WHEEL NUTS</p> <p><u>HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.</u></p>				
58322	12/12/2023	433753/2462	PUNCTURE REPAIR	Invoice
<p>CARRY OUT PUNCTURE REPAIR ON RHR INNER RE-INSTALL WHEELS AND TORQUE TO SPEC</p>				

Vehicle Details

Registration	532QUM	Next Service	Litres	
Make	STEELBRO	Rego Due	Trans	N/A
Model	TRI AXLE SIDE	Engine #	Air	No
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	TRAILER
Colour		Odometer/Hr	Prod	
		484186 / 2748		

Invoice No.	Date	Odometer / Hours	Description	Type
<u>HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.</u>				
58088	14/11/2023	430305	B SERVICE	Invoice
COLLECT TRAILER FROM BUCCINI YARD PARK VEHICLE IN WORKSHOP CARRY OUT B SERVICE AS PER SERVICE SHEET CARRY OUT WALK AROUND VISUAL INSPECTION SECURE HOIST ON TRUCK CHECK ALL LIGHTS INCLUDING ALL REVERSE LAMPS AND BEEPERS CHECK WIPER AND WASHER OPERATION CHECK BATTERY LEVELS, TERMINALS AND CLAMPS LIFT CAB/BONNET TO ACCESS ENGINE BAY REPLACE CABIN AND ENGINE AIR FILTERS CHECK ALL BELTS AND MOUNTS LIFT TRUCK ON HOIST CARRY OUT VISUAL INSPECTION OF UNDERCARRIAGE (DRIVE LINE AND SUSPENSION COMPONENTS) DRAIN ENGINE OIL AND CHANGE FILTER ADJUST BRAKES AND CHECK BRAKE THICKNESSES CHECK AND ADJUST CLUTCH IF APPLICABLE CHECK GEARBOX OIL LEVEL AND QUALITY REPLACE IF REQUIRED CHECK DIFF OIL LEVEL AND QUALITY REPLACE IF REQUIRED CARRY OUT GREASING OF TRUCK LOWER TRUCK FIL ENGINE OIL AND CHECK ENGINE OIL TOP-UP COOLANT IF REQUIRED LOWER CAB/BONNET AND SECURE IN PLACE FIT SERVICE STICKER COMPLETE PAPERWORK REMOVE HOIST ***** GROUND PAINT ON AREAS TO BE WELDED WELDED CRACKS ON TRAILER PAINTED WELDS CARRY OUT SIDE LOADER SERVICE <u>HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.</u>				

58028	03/11/2023	428558/2462	LEG FAULT	Invoice
TRAVEL TO BUCCINI INSPECT LEG FAULT FIT BOLT INTO LANDING LEG HANDLE RETURN TO WORKSHOP <u>HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS,</u>				

Vehicle Details

Registration	532QUM	Next Service	Litres	
Make	STEELBRO	Rego Due	Trans	N/A
Model	TRI AXLE SIDE	Engine #	Air	No
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	TRAILER
Colour		Odometer/Hr	Prod	
		484186 / 2748		

Invoice No.	Date	Odometer / Hours	Description	Type
<u>BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.</u>				
57862	17/10/2023	427985	TAG OUT VEHICLE	Invoice
<p>DRIVER HAVING ISSUES WITH CONTAINER LOCKING LUG ON FRONT LEFT CHAIN INSPECTED AND FOUND IT HAS FAILED AND WILL NEED REPLACING NO PARTS IN STOCK, TAGGED OUT TRAILER AT BT YARD DROVE TO SHED 24 REPLACED LIFT CHAIN CONTAINER LUGS WHEN STOCK ARRIVED. RETURNED TO WORKSHOP</p> <p><u>HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.</u></p>				
57766	05/10/2023	427219	INSPECT LIFTER NOT STARTING	Invoice
<p>INSPECT LIFTER NOT STARTING REMOVED AND REPLACED BATTERY - ALL OK</p> <p><u>HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.</u></p>				
57758	04/10/2023	427008	BREAKDOWN AT SHED 24 - SMOKING	Invoice
<p>TRAVEL TO BREAKDOWN INSPECT SMOKE EVERYWHERE FOUND COOLANT OVERFLOW CAUGHT IN FAN REMOVE COOLANT OVERFLOW TOPPED UP COOLANT IN RADIATOR RUN LIFTER TO PUT BOX ON GROUND TRAVEL BACK TO WORKSHOP ORDERED A FAN AND OVER FLOW BOTTLE TRAVEL TO BUCCINI YARD REMOVE AND REPLACE COOLANT OVERFLOW REMOVE AND REPLACE FAN RETURN TO WORKSHOP</p> <p><u>HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.</u></p>				
57709	27/09/2023	338783	BRAKES STICKING	Invoice

Vehicle Details

Registration	532QUM	Next Service	Litres	
Make	STEELBRO	Rego Due	Trans	N/A
Model	TRI AXLE SIDE	Engine #	Air	No
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	TRAILER
Colour		Odometer/Hr	Prod	
		484186 / 2748		

Invoice No.	Date	Odometer / Hours	Description	Type
<p>DIAGNOSE BRAKES STICKING ON TRUCK/TRAILER - REPLACED ABS PLUG ON 332WIF JOB 57707 DRIVER SAID ONLY HAPPENS WHEN APPLYING FOOT BRAKE</p> <p>ADJUSTED TRAILER BRAKES - FELT BETTER</p> <p>DISCONNECTED TRUCK FROM TRAILER AND TESTED TRUCK ONLY - FELT BETTER</p> <p>DROVE BACK TO SHED 24</p> <p><u>HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.</u></p>				
57641	18/09/2023	425368	LANDING LEGS BENT	Invoice
<p>TRAVELLED TO YARD LIFT TRAILER' REMOVE BENT LANDINGS LEGS HOOK UP TRUCK RETURN TO WORKSHOP MOVE TRAILER FIT NEW LANDING LEGS</p> <p>PREPARED TOOLS AND EQUIPMENT NEAR TRAILER GRINDED OFF PAINT ON THE SHAFT OF TRAILER LEGS WELDED SHAFTS TOGETHER PAINTED WELDED AREAS REMOVED BRACKETS ON OLD TRAILER LEGS MADE HOLES LARGER ON OLD BRACKETS TO FIT WITH HOLES ON ANGLE IRON GRINDED OFF PAINT TACKED AND WELDED BRACKETS TO TRAILER LEGS BOLTED ANGLE BAR TO BRACKETS PAINTED WELDED AREAS TESTED OPERATION RETURNED TO SHED 24</p> <p><u>HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.</u></p>				
57441	18/08/2023	422466	DROVE TO BUCCINI TO REPLACE ROLL	Invoice
<p>DROVE TO BUCCINI YARD SPOKE TO COL TO FIND OUT ABOUT THE FAULT DROVE BACK TO WORKSHOP TO GET TOOLS AND A NEW ROLL PIN DROVE BACK TO BUCCINI YARD AND REPLACED BROKEN ROLL PIN IN TWISTLOCK ALL OK DROVE BACK TO WORKSHOP</p>				
57560	07/08/2023		REMOVE CYLINDER HEAD AND SENT TO	Invoice

Vehicle Details

Registration	532QUM	Next Service	Litres	
Make	STEELBRO	Rego Due	Trans	N/A
Model	TRI AXLE SIDE	Engine #	Air	No
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	TRAILER
Colour		Odometer/Hr	Prod	
		484186 / 2748		

Invoice No.	Date	Odometer / Hours	Description	Type
			<p>CARRIED OUT INSPECTION OF POSSIBLE HEAD GASKET FOUND HEAD GASKET TO OF FAILED, CARRIED OUT REMOVAL OF VALVE COVER TO ACCESS HEAD BOLTS, CARRIED OUT REMOVAL OF COOLANT HOSES AND FUEL LINES, REMOVED ALTERNATOR AND FAN AND PULLEY COMPONENTS, REMOVED ENGINE HARNESSING, CARRIED OUT REMOVAL OF CYLINDER HEAD SO CYLINDER HEAD COULD BE TESTED, HEAD CYLINDER FAILED CRACK TEST AND WAS IRREPARABLE, OBTAINED PERMISSION TO FIT A NEW ENGINE. WAS INFORMED THE NEW ENGINE WOULD TAKE AT LEAST 3 MONTHS TO BECOME AVAILABLE. OBTAINED PERMISSION TO SUPPLY AND FIT A NEW CYLINDER HEAD. REMOVE 20-40 RAM TO ACCESS THE ENGINE, REMOVE ENGINE MOUNTS INSTALL HEAD BOLTS TO BLOCK, AND USE THE CHAIN TO REMOVE THE ENGINE FROM THE TRAILER FRAME, SOURCED NEW CYLINDER HEAD AND VRS GASKET KIT, CLEANED ENGINE BLOCK SURFACE, AND INSTALLED NEW CYLINDER HEAD AND NEW GASKET KIT, REMOVED INTAKE AND EXHAUST MANIFOLDS FROM OLD CYLINDER HEAD AND CLEANED SURFACES AND INSTALLED TO NEW CYLINDER HEAD, TORQUE HEAD BOLTS TO SPECIFICATION, RE-INSTALLED ENGINE TO TRAILER FRAME REPLACED ENGINE MOUNTS AND TENSIONED TO SPECIFICATION, INSTALL INJECTORS TO THE CYLINDER HEAD, INSTALL ENGINE FAN AND PULLEY COMPONENTS, INSTALL ALTERNATOR AND ENGINE HARNESSING, INSTALL COOLANT LINES, RE-INSTALLED VALVE COVERS, FILLED COOLING SYSTEM, BLEED COOLING SYSTEM, AND BLEED FUEL SYSTEM TESTED OPERATION TESTED ALL OK, RE-INSTALL HYDRAULIC PUMP AND COUPLING, RE-INSTALLED 20-40 RAM AND TESTED OPERATION AND TESTED ALL OK,</p> <p><u>HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.</u></p>	

57281	02/08/2023	422411	REPLACE LIFTER BATTERY AND HEADER	Invoice
			<p>TRAVEL TO BUCCINI YARD CHECKED LIFTER FAULTS FOUND "E" STOP ON REMOTE BROKEN AND ALSO MAIN CRANKING BATTERY DEAD FLAT (ISOLATOR HAD BEEN LEFT ON) GOT NEW "E" STOP SWITCH FROM STEELBRO SUPPLIER IN HEMMANT AND FITTED TO LIFTER REMOTE / TEST OK REMOVED / REFITTED BATTERY AFTER RECHARGE / TEST - ALL OK REMOVE AND REPLACE HEADER TANK TOPPED UP COOLANT FIT BATTERY , TEST OPERATION OF LIFTER INFORMED COL RETURN TO WORKSHOP</p> <p><u>HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.</u></p>	

57462	12/07/2023	422267	C SERVICE	Invoice
			<p>PARKED VEHICLE IN THE WORKSHOP CARRY OUT C SERVICE AS PER SERVICE SHEET</p> <ul style="list-style-type: none"> • APPLY AIR TO TRAILER • TEST LIGHTING FUNCTION • LIFT TRAILER WITH HOIST 	

Vehicle Details

Registration	532QUM	Next Service	Litres	
Make	STEELBRO	Rego Due	Trans	N/A
Model	TRI AXLE SIDE	Engine #	Air	No
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	TRAILER
Colour		Odometer/Hr	Prod	

Invoice No.	Date	Odometer / Hours	Description	Type
			<ul style="list-style-type: none">CHECK SUSPENSION COMPONENTSCHECK KING PIN BOLT TENSIONCHECK SKID PLATECHECK UNDERCARAGE OF TRAILERCARRY OUT GREASING OF AXLESCARRY OUT DE-ADJUSTMENT OF BRAKESREMOVE HUB CAPS AND REMOVE BEARING ADJUSTMENT NUTSREMOVE BEARINGS FROM HUBSCLEAN STUB AXLES AND APPLY NEW FILM OF GREASE TO STUB AXLESCLEAN BEARINGS IN TURBO WASHCLEAN HUBS OF GREASE AND REPACK HUBS AS REQUIREDREMOVED BEARINGS FROM PARTS WASHER BLOW OUT WITH AIR AND REPACK BEARINGSINSTALL BEARINGS TO HUBSINSTALL INNER HUB SEALSINSTALL HUBS TO TRAILER AND TENSION BEARING ADJUSTMENT NUTSSECURE BEARING ADJUSTMENT NUTS WITH RETAINERSREINSTALL HUB CAPS TO AXLES AND TENSION HUB CAPSCARRY OUT ADJUSTMENT OF BRAKESLOWER TRAILERCHECK WHEEL NUT TENSIONCHECK ALL LIVERY INCLUDING MUDFLAPS AND DECALINSPECT MARKER PLATES INCLUDING CON SIGN, CHEVERONS AND OVER TAKE SIGNAGECHECK TOP DECK OF TRAILER FOR ALL FUNCTIONALITYAPPLY SERVICE STICKERCOMPLETE PAPERWORKCLEAN WORK AREA	
			REPLACED LH #2 TWISTLOCK STOPPER BOLT REMOVED ALL CRANE LIFTING CHAINS TIGHTENED BRAKE BOOSTER AIRBRAKE HOSE CLAMPS	
			REPLACED LEFT HAND #2 TWIST LOCK STOPPER BOLT REMOVED ALL CRANE LIFTING CHAINS TIGHTENED BRAKE BOOSTER AIRBRAKE HOSE CLAMPS. PICKED UP EXHAUST MANIFOLD STUDS PICKED UP CHEVRONS FOR TRAILER PICKED UP CHAINS REMOVED BENT PLATES ' HEATED PLATES USED HYDRAULIC PRESS TO STRAIGHTEN BENT PLATES LET PLATES COOL PAINTED PLATES AND BOLTED IT BACK CLEANED AREAS WHERE WELDING IS TO BE PERFORMED TACK AND WELD FLATBAR UNDERNEATH TRAILER PAINTED WELDED AREA TO MATCH COLOUR FITTED CHAIN COVRES FITTED CHAIN TO CRANES REMOVED FRONT CRANE SLIDE WEAR PADS REPAIRED DAMAGED THREADS LIFTED FRONT CRANE REPLACED SLIDE WEAR PADS REMOVED BROKEN BOLT IN CRANE AND REPAIRED THREADS FITTED NEW SLIDE WEAR PAD CARRIERS REPLACED FRONT CRANE SIDE WEAR BLOCKS REMOVED BROKEN BOLTS FROM SHIM BLOCKS AND REPAIRED THREADS	

Vehicle Details

Registration	532QUM	Next Service	Litres	
Make	STEELBRO	Rego Due	Trans	N/A
Model	TRI AXLE SIDE	Engine #	Air	No
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	TRAILER
Colour		Odometer/Hr	Prod	
		484186 / 2748		

Invoice No.	Date	Odometer / Hours	Description	Type
SECURED AIRLINES AND HYDRAULIC HOSES REPLACED REAR CRANE SLIDE WEAR PAD REPLACED REAR CRANE SLIDE SIDE BLOCKS REPLACED WEAR PAD CARRIERS REMOVED BROKEN BOLTS IN CRANE FOR CARRIER MOUNTS REMOVED BROKEN BOLTS IN CRANE SHIM CARRIER TAPPED AND REPAIRED THREADS FITTED DOWEL PIN TO NEW TWISTLOCK FABRICATED/REPAIR METAL STRAP FOR BATTERY MOVED REAR CRANE FORWARD TO ACCESS BROKEN BOLT IN WEAR PAD CARRIER DRILLED OUT BROKEN BOLT REPAIRED THREAD FITTED WEAR PAD CARRIER REMOVED CAT TRACK MOUNTS FOR CRANES FITTED NEW CAT TRACK MOUNTS TO FRONT AND REAR CRANES PARKED TRAILER AT SHED 24 <u>HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, MACHINERY AND FITTING. PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.</u>				
56827	06/06/2023	0	INSPECT LIFTER ENGINE	Invoice
COLLECTED TRAILER FROM SHED 24 PARKED IN WORKSHOP CHECKED FOR COOLANT LEAK FOUND LEAK AT RH REAR OF HEAD FOUND EXHAUST MANIFOLD GASKETS LEAKING				
56721	23/05/2023	0	REPAIRS	Invoice
INSPECT LOOSE CRANE STOP FOUND BROKEN BOLTS REMOVE STOP TO BE REPAIRED FROM FRONT CRANE INSPECT COOLANT LEAK APPEARS TO BE FROM LHF SIDE OF ENGINE				
56474	19/04/2023	418065	A SERVICE	Invoice
COLLECTED TRAILER FROM BUCCINI YARD BROUGHT INTO WORKSHOP CARRIED OUT A SERVICE GREASED AND INSPECTED LIFTER NOTE- LR AIRBAG CRACKING / PERISHING AT BASE - MONITOR WHEEL BEARING GREASE GOOD TOOK TRAILER BACK TO BUCCINI YARD				
56258	20/03/2023	417320	JUMP START	Invoice
TRIED JUMP STARTING THE LIFTER BUT UNABLE TO CHECKED VOLTAGE BATTERY, DRAINED COMPLETELY SWAPPED IT WITH AN OLD BATTERY STARTED LIFTER, CHECKED VOLTAGE - ALL OK				

Vehicle Details

Registration	532QUM	Next Service	Litres	
Make	STEELBRO	Rego Due	Trans	N/A
Model	TRI AXLE SIDE	Engine #	Air	No
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	TRAILER
Colour		Odometer/Hr	Prod	

Invoice No.	Date	Odometer / Hours	Description	Type
55599	23/12/2022	414442	CARRY OUT B SERVICE	Invoice
BROUGHT VEHICLE INTO WORKSHOP CARRIED OUT B SERVICE ON TRAILER AND LIFTER MOTOR GREASED SWINGLIFTER				
55445	28/11/2022	911155	JUMP START	Invoice
JUMP START THE LIFTER MOTOR				
55299	07/11/2022	407206	TRAILER WON'T START	Invoice
TRAILER WON'T START JUMP START DIDN'T WORK REMOVE BATTERY , DROVE BACK TO WORKSHOP AND PICKED UP A NEW BATTERY DROVE BACK TO TRAILER AND FIT NEW BATTERY - ALL OK				
55200	26/10/2022	405616	MIDDLE AXLE PASSENGER SIDE BOTTOM	Invoice
MOVED TRAILER INTO WORKSHOP REMOVED 2ND AXLE LHS AIRBAG STRIPPED DOWN TRAILER FOR RE-PACK CLEANED ALL PARTS ASSOCIATED WITH RE-PACK FITTED 4 AIRBAGS FITTED BEARINGS AND SEALS TO HUBS FITTED HUBS AND ADJUSTED BEARINGS FITTED HUBS WITH SEMI FLUID GREASE FITTED HUB CAPS FITTED WHEELS NOTE- GREASE A BIT BURNT, WILL NEED A RE-PACK AT NEXT C SERVICE ADUSTED ML WHEEL BEARING				
55055	26/09/2022	406285	FLAT BATTERY	Invoice
RECHECKED START / CHARGE - REPLACED FLAT BATTERY WITH LARGER SIZE "BUCCINI" SPARE N70S BATTERY THEN CARRIED OUT RE-START AND CHARGE TEST - ALL OK				
54930	08/09/2022	398043	TOPPED UP COOLANT AND ENGINE OIL	Invoice
TOPPED UP GREEN COOLANT AND ENGINE OIL				
54922	16/08/2022	0	FIXED WIRING ON MIDDLE RH SIDE	Invoice
FIXED WIRING ON MIDDLE RH SIDE MARKER				
54670	03/08/2022	0	FITTED REMOTE BOX & CONTROLLER	Invoice
FITTED REMOTE BOX & CONTROLLER TO TRAILER AND TEST - ALL OK TOOK FROM VEHICLE 479QZK				
54472	05/07/2022	391162	CARRY OUT C SERVICE / REMOVE	Invoice

Vehicle Details

Registration	532QUM	Next Service	Litres	
Make	STEELBRO	Rego Due	Trans	N/A
Model	TRI AXLE SIDE	Engine #	Air	No
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	TRAILER
Colour		Odometer/Hr	Prod	

Invoice No.	Date	Odometer / Hours	Description	Type
COLLECTED TRAILER FROM SHED 24 CARRIED OUT C SERVICE TIGHTENED ENGINE CRADLE BOLTS GROUND CRACKS @ ENGINE CRADLE WELDED CRACKS @ FRONT OF CRADLE REMOVED CRANE LIFT CHAINS AND TOOK TO ATLAS CHAINS FOR INSPECTION. REPAIRED CRACKS IN ENGINE CRADLE REFITTED EXHAUST PIPE SUPPORT BRACKET REMOVED REAR CRANE OVERCENTRE CARTRIDGE REPLACED REAR CRANE OVERCENTRE CARTRIDGE REMOVED BROKEN BOLT IN RH REAR CRANE STOPPER FITTED NEW STOPPER, FLAG AND BOLT CHAINS ARE NOW CERTIFIED PICKED UP FROM ATLAS C HAINS AND REFITTED LIFTING CHAINS TO FRONT AND REAR CRANKS PARKED TRAILER AT SHED 24				
54208	20/06/2022	0	MODIFY RADIATOR FRAME AND	Invoice
MODIFY NEW RADIATOR FRAME AND MOUNTINGS REPAIR 2 TWIST LOCKS				
54200	23/05/2022	390902	REPAIR TWIST LOCK	Invoice
FIT NEW TWIST LOCK HANDLE FIT NEW ROLL PIN ON CHAIN				
54119	05/05/2022	0	REPAIR LEAKING RAMS	Invoice
DISCONNECTED HYDRAULIC PIPES AND SEALED THE ENDS TO PREVENT CONTAMINATION AND LOSS OF OIL. REMOVED LEAKING SEPERATOR RAMS FROM LIFTER CHASSIS AND SENT OUT FOR REPAIRING. PICKED RAMS UP ONCE REPAIRED AND REFITTED RAMS, REFITTED HYDRAULIC PIPES AND TESTED ALL OK. DELIVERED TRAILER BACK TO SHED 24.				
54081	27/04/2022	388207	REPAIR LIFTER ENGINE	Invoice
REMOVED COOLING FAN, RADIATOR AND EXPANSION TANK, DAMAGED DUE TO THE FAN BLADE BREAKING OFF SUSPECT DUE TO FATIGUE. FITTED NEW RADIATOR, FAN, FAN BELT AND EXPANSION TANK. ADJUSTED EXPANSION TANK MOUNTING TO ALLOW CLEARANCE FROM THE FAN BLADES. FILLED SYSTEM WITH COOLAND AND CHECKED FOR LEAKS ALL OK. FLOODLAMP NOT WORKING, CHECKED FOR POWER AT LAMP ZERO VOLTS, CHECKED FUSES ALL OK. MADE SOME TESTS/CHECKS TO TRACE AND LOCATE WIRING OPEN CIRCUIT, FOUND BRAKE AND REPAIRED, TESTED ALL OK.				
53990	07/04/2022	388207	B SERVICE	Invoice
CARRIED OUT B SERVICE ON TRAILER REPLACED MISSING CLEAR REFLECTOR ON FRONT OF TRAILER. TIGHTENED REAR CRANE HYDRAULIC HOSE FITTING AR HYDRAULIC BLOCK CARRIED OUT SERVICE ON TRAILER MOTOR REPLACED ALL FILTERS AND OIL REPLACED BLOWN LIGHT GLOBES AND LIFTER LIGHTS AND BEACON LIGHT INOP LHS 3RD TWIST LOCK HARD TO TURN - GREASE AND CHECK				

Vehicle Details

Registration	532QUM	Next Service	Litres	
Make	STEELBRO	Rego Due	Trans	N/A
Model	TRI AXLE SIDE	Engine #	Air	No
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	TRAILER
Colour		Odometer/Hr	Prod	

Invoice No.	Date	Odometer / Hours	Description	Type
NOTE RADIATOR LEAKING, CAUSED BY FAN BLADE FATIGUE, BROKE OFF AND A PIECE HAS PUNCTURED THE RADIATOR AND PUT A HOLE IN THE EXPANSION TANK. DEFECTS: GREASE IS STARTING TO TURN BROWN - MONITOR RIGHT FRONT TYRES ON MINIMUM TREAD LIFTING CHAINS LAST CHECKED 11/2/2020				
53875	17/03/2022	385542	TWIST LOCK	Invoice
17/3/2022 REPLACED RHR TWIST LOCK DETENT REMOVED BROKEN ROLLPIN IN TWIST LOCK				
53794	04/03/2022	0	TRAILER BOOSTER	Invoice
4/3/2022 CHECKED OVER TRAILER FOR ANY FAULTS FOUND BLOWN BRAKE BOOSTER - CAGED BOOSTER AND TURNED BODY OF BOOSTER REPLACED BOOSTER ADJUSTED BRAKES CHECKED OPERATION - ALL OK				
53518	12/01/2022	378469	WONT START FROM REMOTE	Invoice
REMOVED AND REPLACED BATTERY WITH RECHARGED SECOND HAND ONE LOCATED AND TESTED MAIN FAULT TO FAILED FUSE FOR REVERSE POLARITY START CIRCUIT INSIDE CONTROL BOX ON LHS RECHARGED FLAT BATTERY FOR LIFTER AS REQUIRED - IN SECOND HAND STOCK				
53343	07/12/2021	378467	REAR AIR BAG ISSUE	Invoice
TRAILER BROUGHT INTO WORKSHOP CHECKED FOR LHS 3RD AXLE MUDGUARD WEAR REPLACED MUDGUARD BRACKET STRIPPED BOLTS REPLACE MUDGUARD REPOSITIONED MUDGUARD 10MM HIGHER REFITTED MUDGUARD AND MUDGUARD LOOP KIT PARKED TRAILER ON STREET FOR COLLECTION				
53111	08/11/2021	2462	LIFTER MOTOR WONT START	Invoice
8/11/2021 - CHECKED AND SECURE WIRING CONNECTIONS TO LIGHTS CHECKED VARIOUS START/STOP AND RUN TO LIFTER MOTOR FIT SPARE CHARGED UP BATTERY - LIFTER MOTOR STILL WOULDNT START REPLACED BLOWN FUSES IN MOTOR CHECKED FRONT/CENTRE E STOP CIRCUITS - ALL OK 9/11/2021 - MADE FURTHER TESTS TO INTERMITTENT RUN FAULT FOUND FUEL SOLENOID TO LHS OF KABOTA ENGINE TO HAVE FAILED REMOVED AND REPLACED FUEL SOLENOID 12/11/2021 - CARRIED OUT FURTHER TESTING OF ALL LIFTER FRONT AND REAR CONTROL COMPONENTS				

Vehicle Details

Registration	532QUM	Next Service	Litres	
Make	STEELBRO	Rego Due	Trans	N/A
Model	TRI AXLE SIDE	Engine #	Air	No
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	TRAILER
Colour		Odometer/Hr	Prod	

Invoice No.	Date	Odometer / Hours	Description	Type
			TIGHTENED LOOSE FUSE HOLDERS AND CLEARED UP ALL FUSES AND CONNECTIONS BLED FUEL LINES TO INJECTORS AND HAD ENGINE START BUT DOESNT IDLE YET. 15/11/2021 - LOCATED INTERMITTENT FAULT CAUSING WRONG POWER INFORMATION REACHING FUSES/RELAYS FOUND TO BE SMALL PIECE OF SOLDER BEHIND PRINTED CIRCUIT BOARD TOUCHING ACROSS SOLDER STUD REFITTED AND SECURED ALL WIRING AND COMPONENTS CARRIED OUT EXTENSIVE TESTING OF ENGINE START/STOP/RUN AND CRANE FUNCTIONS TESTED ALL OK TRAILER HAD BROKEN TWIST LOCK HANDLE REMOVED STUCK PIN IN THE TWIST LOCK GRIND DOWN TWIST LOCK TO FIT IN TO THE NEW HANDLE REPLACED TWIST LOCK HANDLE AND TESTED ALL OK	

52833	10/09/2021	372361	FRONT AXLE MOVING	Invoice
			9/9/2021 - INSPECTED FUEL CAP NOT TIGHTENING UP REMOVED WORN CIRCULAR SEALING RING FROM FUEL CAP REPLACED LIFTER BATTERY - FAILED 10/9/2021 - INSPECTED FRONT RHS AXLE LEADING ARM BOLT SNAPPED IT RETAINERS FOUND TO HAVE EXCESSIVE PLAY REMOVED FRONT AXLE GUARDS AND MOUNTS REMOVED WHEELS FRONT FRONT AXLE AND CHECKED WHEEL BEARINGS S=LOOSED MOUNTING BOLTS ON LEADING ARMS, DROPPED BAGS AND LET BRAKES OFFF UNSED BOTTLE JACK TO DROP ARMS DOWN AND INSPECT BUSHES BUSHES OK - BOLTS IN RHS WERE LOOSE CASUING THE HANGER TO BE WORN REMOVED FRONT AXLE FROM TRAILER AND PACKED ONTO PALLET 15/9/2021 - CUT OUT RHS 1ST HANGER AND WELDED IN REPAIR PLATES GROUND DOWN WELDS AND FIT SPACER PLATES REFITTED AXLE REPLACED 1ST AXLE AIR BAG AND SHOCK ABSORBERS REFITTED AIR BAG AIR LINES'FIT RHS 1ST AXLE TRAILING ARM BOLT 21/9/2021 - REFIT BRAKE BOOSTERS AND MUDGUARDS TIGHTENED BOTTOM AIR BAG BOLTS REFIT WHEELS AND TORQUED TO SPEC REMOVED AND REPLACED STARTER MOTOR ON LIFTER ENGINE CUT EARTH WIRE AND CRIMPED ONTO A CIRCULAR TERMINAL REPLACED COOLANT HEADER TANK AND FILLED WITH COOLANT	

52448	08/07/2021	367771	C SERVICE AND SERVICE LIFTER MOTOR	Invoice
			CARRY OUT C SERVICE ON TRAILER AND LIFTER MOTOR LIFTED UP TRAILER AND STRIPED ALL WHEELS/HUB ASSEMBLIES CLEANED INSIDE OF WHEELS, BEARINGS AND STUBS LOCK NUTS REPACKED WHEEL BEARINGS WITH SEMI SYNTHETIC GREASE REFIT WHEELS AND HUBS BACK TO TRAILER ADJUSTED WHEEL BEARINGS AND TIGHTENED LOCK NUTS REPLACED THREE FLOOD LIGHT GLOBES REPAIRED REAR FLOOD LIGHTS WIRING INSIDE FEED WIRING - TESTED ALL OK DEFECTS: SLIGHT WEAR ON SKID PLATE MIDDLE LHS S CAM HAS NO GREASE NIPPLE SHOCK ABSORBER BUSHES ARE WORN AND CRACKED - MONITOR MIDDLE AND FRONT AIR BAGS CRACKED AT BASE	

52330	22/06/2021	3667802	JUMP START	Invoice
-------	------------	---------	------------	---------

Vehicle Details

Registration	532QUM	Next Service	Litres	
Make	STEELBRO	Rego Due	Trans	N/A
Model	TRI AXLE SIDE	Engine #	Air	No
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	TRAILER
Colour		Odometer/Hr	Prod	

Invoice No.	Date	Odometer / Hours	Description	Type
CONNECTED JUMP START BATTERIES TO TRAILER/LIFTER MOTOR BATTERY ISOLATOR NOT SWITCHED TO OFF POSITION JUMP STARTED VEHICLE AND LET RUN VEHICLE ALL OK				
52183	31/05/2021	0	INSPECT LANDING LEGS	Invoice
TRAILER CAME IN WITH LANDING LEGS STICKING INSPECTED LANDING LEGS - FOUND LEGS GOING DOWN SMOOTH BUT COMING BACK UP MET WITH SOME RESISTENCE REMOVED TOP COVER TO INSPECT GEARS LUBED UP AND TESTED - NO CHANGE LUBED UP LANDING LEGS SHAFT WITH DRY MOLY AND TESTED - ALL OK				
52176	31/05/2021	364780	HYDRAULIC LEAK	Invoice
INSPECTED VEHICLE FOR HYRAULIC LEAK PIPE/UNION LEAKING NEAR ENGINE FREED UP SEIZED HYDRAULIC RUNNING NUT ON FITTING TIGHTENED PIPE ASSEMBLY RECHECKED FOR LEAKS - TESTED ALL OK REPLACED BROKEN BOLT ON LHS CENTRE FRONT TWIST LOCK				
52071	12/05/2021	2388	REPLACED ESTOP	Invoice
VEHICLE CAME IN WITH LOOSE ESTOP ASSEMBLY ON MAIN KEYBOX - SECURED AND CHECKED WIRING OK REPLACED ESTOP ASSEMBLY ON FRONT CRANE AND TESTED OK				
52010	10/05/2021	360248	BATTERY REPLACEMENT	Invoice
VEHICLE CAME IN WITH SMALL ENGINE NOT STARTING CHECKED STARTER MOTOR AND GLOW PLUGS - ALL OK CHECKED ALTERNATOR CHARGE RATE - LOW REMOVED AND REPLACED BATTERY - CHARGE RATE GOOD				
51774	01/04/2021	356271	CARRY OUT REPAIRS	Invoice
DATE WORK CARRIED OUT: 26.3.2021 - 31.3.2021 WORK CARRIED OUT: INSPECTED VEHICLE AND FOUND LAZY AXLE CONTROL VALVE STICKING BETWEEN ACTUATIONS HYDRUALIC RAM MOUNTING BRACKETS LOOSE AND MOUNTS WORN - MANUFACTURED AND FITTED NEW MOUNTS AND U BOLTS. CHECKED FOR STRAIGHTNESS OF RAM - ALL OK. CLEANED AND INSPECTED SMALL LEAK FROM HYDRAULIC RAM SEAL - TO BE CHECKED NEXT SERVICE BRAKE STUCK ON - CONNECTED AIR AND INSPECTED BOOSTERS FOR LEAKS - TESTED OK GREASED SLACK ADJUSTERS AND CAM TUBE - ALL OK. TIGHTENED MUDGUARD BOLTS AND FITTED RUBBER TO MUDGUARDS TESTED AND RECHARGED MAIN CRANKING BATTERY - TESTED OK CHECKED CRANE OPERATION - FOUND REAR CRANE HAD ELECTRICAL FAULT LOCATED AND REPAIRED WIRING TO DAMAGED PRESSURE SENSOR WIRING AT PIVOT POINT - TESTED ALL OK. DEFECTS NOTED <ul style="list-style-type: none">• HYDRAULIC RAM SEALS WEEPING• FLEXI TAIL LIGHT BRACKET CRACKED• FRONT AXLE CONTROL ARM BUSHES WORN MONITOR				

Vehicle Details

Registration	532QUM	Next Service	Litres	
Make	STEELBRO	Rego Due	Trans	N/A
Model	TRI AXLE SIDE	Engine #	Air	No
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	TRAILER
Colour		Odometer/Hr	Prod	

Invoice No.	Date	Odometer / Hours	Description	Type
<ul style="list-style-type: none">AIRBAG HAVE SLIGHT CRACKS AT BASE MONITORREAR LHS AXLE INNER TYRE WORN MONITOR				
51731	22/03/2021	355829	CARRY OUT REPAIRS	Invoice
REPLACED ROLL PIN INTO CONTAINER LOCK. TESTED TO ENSURE PIN DOES NOT WALK OUT.				
51707	18/03/2021	355510	STARTING FAULT	Invoice
INSPECTED CHARGING FAULT FOUND BATTERY U/S CLEANED STARTER MOTOR TERMINALS AND SECURED CABLES CHECKED ALTERNATOR CHARGE RATE - 14.2V TOP-UP COOLANT CJCHECKED OPERATION AND STARTING - ALL OK				
51698	17/03/2021	0	WON'T START	Invoice
VEHICLE CAME IN NOT STARTING - JUMP STARTED VEHICLE STARTED AND TESTED OK				
51581	05/03/2021	0	REPAIRS TO REMOTE	Invoice
DATE WORK CARRIED OUT: 26/02/2021 WORK CARRIED OUT: CHECKED / REPAIRED BROKEN PLUG & WIRING CABLE FOR PENDANT CONTROL REUSED ORIGINAL PLUG/CLEANED OUT BROKEN WIRES & SOLDER SHORTENED LEAD BY APPROX 200MM TO GET RID OFF INTERMITTENT / BROKEN WIRING INSIDE CABLE TESTED – ALL OK				
51665	05/03/2021	353663/2350	REMOTE FAULT	Invoice
DATE WORK CARRIED OUT: 04/03/2021 - 05/03/2021 WORK CARRIED OUT: LIFTER PRESENTED WITH FAULTS IN CONNECTING TO THE REMOTE. ATTEMPTED TO CONNECT & RUN UNIT - UNSUCCESSFUL. TESTED MULTIPLE WAYS OF CONNECTING UNIT, INCL. MANUAL OVERRIDE - UNSUCCESSFUL. E-STOP UNDER START KEY DISCOVERED TO BE LOOSE. REMOVED HOUSING & COVER. TIGHENED UP E-STOP AND WAS ABLE TO CONNECT TO UNIT. FUNCTION WAS NOT AS EXPECTED. RECHECKED PENDANT CONTROL FUNCTIONS OF CRANE / MODES / COMPONENTS. FOUND AT FIRST WOULDNT WORK IN ANT MODE - RECHECKED PREVIOUS REPAIR ON PENDANT AND FOUND TO BE OK. MORE TEST TO PENDANT CONTROL FOUND THAT FRONT CRANE JOYSTICK CONTROLLER RIBBON CABLE CONNECTOR TO "Y" AXIS HAD BECOME SLIGHTLY DISLODGED OFF PCB BOARD; RECHECKED FRONT & REAR CRANE MODES / FUNCTIONS USING PENDANT CABLE CONTROLLER. ALL TESTED OK.				

Vehicle Details

Registration	532QUM	Next Service	Litres	
Make	STEELBRO	Rego Due	Trans	N/A
Model	TRI AXLE SIDE	Engine #	Air	No
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	TRAILER
Colour		Odometer/Hr	Prod	
		484186 / 2748		

Invoice No.	Date	Odometer / Hours	Description	Type
51572	26/02/2021	353655	A SERVICE	Invoice

DATE WORK CARRIED OUT: 26/02/2021

WORK CARRIED OUT:

CARRIED OUT A SERVICE
GREASED LIFTER AND TESTED – ALL OK

DEFECTS NOTED:

- RIDE HEIGHT CONTROL VALVE LEAKING
- MIDDLE AXLE LHS AIR BAG HAS A SMALL TEAR – MONITOR
- 20/40 RAM LEAKING BOTH ENDS AT FITTINGS
- FR TRAILING ARM BUSH COMPLETELY WORN – NEEDS REPLACING
- LIFTER ENGINE CHASSIS CRACKED ON TWO ENDS – RHS CROSS MOUNT
- HYDRAULIC HOSES STARTING TO PERISH – FRONT OF MOTOR NEAR PUMP
- LHR S CAM GREASE NIPPLE MISSING

51479	15/02/2021	351482	TOPPED UP HYDRAULIC OIL	Invoice
-------	------------	--------	-------------------------	---------

DATE WORK CARRIED OUT: 15/02/2021

WORK CARRIED OUT:

TOPPED UP HYDRAULIC OIL

51457	03/02/2021	0	REPLACED LIFTER BATTERY	Invoice
-------	------------	---	-------------------------	---------

DATE WORK CARRIED OUT: 03/02/2021

WORK CARRIED OUT:

REMOVED AND REPLACED LIFTER BATTERY

51287	11/01/2021	2330	REAR CRANE FAULT	Invoice
-------	------------	------	------------------	---------

DATE WORK CARRIED OUT: 11/01/2021

WORK CARRIED OUT:

INSPECTED & REPAIRED REAR CRANE WIRING FAULTS TO TOP ARM PRESSURE SENSOR
TESTED ALL CRANE FRONT/REAR FUNCTIONS – ALL OK

51099	15/12/2020	2329	LIFTER SERVICE??, DELAY IN RELEASING	Invoice
-------	------------	------	--------------------------------------	---------

DATE WORK CARRIED OUT: 15/12/2020 – 17/12/2020

WORK CARRIED OUT:

CHECKED FOR OPERATION FAULTS ON TOP ARM
SUSPECT FRONT CRANE TOP ARM SENSOR U/S
CHECKED FOR FAULT WITH FRONT CRANE TOP ARM NOT OPENING FULLY
CHECKED THE WIRING TO ANGLE SENSOR
REMOVED ANGLE SENSOR AND FITTED NEW SENSOR
CARRIED OUT FUNCTION TEST AND CHECKED FOR ANY FAULT COMING UP ON SCREEN
FOUND ALL OK!
CHECKED FOR AIR BREAKAWAY NOT WORKING PROPERLY – NO FAULT FOUND

Vehicle Details

Registration	532QUM	Next Service	Litres	
Make	STEELBRO	Rego Due	Trans	N/A
Model	TRI AXLE SIDE	Engine #	Air	No
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	TRAILER
Colour		Odometer/Hr	Prod	

Invoice No.	Date	Odometer / Hours	Description	Type
50981	25/11/2020	347136	ISOLATOR	Invoice
DATE WORK CARRIED OUT: 25/11/2020 WORK CARRIED OUT: CHECKED / FITTED BRACKETS & SWITCH FOR BATTERY ISOLATOR MADE UP CABLE FOR BATTERY SWITCH WIRED IN & CONNECTED ISOLATOR SWITCH FOR MAIN BATTERY & ECU BATTERY TESTED – ALL OK				
50980	25/11/2020	347136	A & C SERVICE	Invoice
DATE WORK CARRIED OUT: 25/11/2020 WORK CARRIED OUT: CARRIED OUT A & C SERVICE TOPPED UP ENGINE COOLANT REPLACED 1ST AXLE L/H/S GUARD POLE AND PAINTED REMOVED, STRAIGHTENED & REFITTED REAR CRANE SENSOR GUARD REPLACED DETENT BALL AND DOWEL PIN ON R/H/R TWIST LOCK WASHED DOWN ALL OIL LEAKS ON TRAILER 20-40 CYLINDERS DEGREASED AND TO BE MONITORED. REPLACED FUEL CAP				
50892	12/11/2020	345886	TEST PARK BRAKE	Invoice
DATE WORK CARRIED OUT: 12/11/2020-13/11/2020 WORK CARRIED OUT: BRING LIFTER INTO WORKSHOP TO INSPECT & TEST PARK BRAKE, AS IT WASN'T EXHAUSTING SPRAYED WITH INOX THEN TESTED , U/S BRAKE SLOW TO APPLY AIR LEAKING FROM FRONT FITTING INSTEAD OF EXHAUST PORT REPLACE SPRING BRAKE VALVE.				
50853	10/11/2020	345195	RL TAIL LIGHT	Invoice
DATE WORK CARRIED OUT: 10/11/2020 WORK CARRIED OUT: SECURED REAR LEFT TAIL LIGHT MODULE				
50820	03/11/2020	344802	LIFTER BATTERY	Invoice
DATE WORK CARRIED OUT: 03/11/2020				

Vehicle Details

Registration	532QUM	Next Service	Litres	
Make	STEELBRO	Rego Due	Trans	N/A
Model	TRI AXLE SIDE	Engine #	Air	No
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	TRAILER
Colour		Odometer/Hr	Prod	
		484186 / 2748		

Invoice No.	Date	Odometer / Hours	Description	Type
WORK CARRIED OUT: SWAPPED THE LIFTER ENGINE BATTERY TESTED ALL GOOD RECOMMEND - TRAILERS NEED ISOLATORS				
50782	29/10/2020	344710	REPAIRS	Invoice
DATE WORK CARRIED OUT: 29/10/2020 WORK CARRIED OUT: STRAIGHTENED LH FRONT CONTAINER STOPPER REPLACED ALL BENT BOLTS, WASHERS, NYLOC NUTS FITTED AND CONTAINER STOPPER. PAINTED.				
50730	23/10/2020	344282	TWISTLOCK HANDLE - RR15305	Invoice
DATE WORK CARRIED OUT: 23/10/2020 WORK CARRIED OUT: RR-15305 REPLACED BROKEN TWIST LOCK HANDLES BROKEN REFIT TWIST LOCK HANDLES WITH NEW ROLL PIN.				
50703	15/10/2020	0	LIFTER FLAT BATTERY	Invoice
DATE WORK CARRIED OUT: 15/10/2020 WORK CARRIED OUT: LIFTER ENGINE NOT STARTING FOUND BATTERY FOR LIFTER ENGINE FLAT. REPLACED WITH A GOOD 2ND HAND BATTERY				
50576	30/09/2020	343365/2292	CARRY OUT A SERVICE	Invoice
DATE WORK CARRIED OUT: 30/09/2020 WORK CARRIED OUT: COLLECT TRAILER FROM YARD CARRY OUR A SERVICE AS PER HWV SERVICE SHEET INSPECT AND GREASE LIFTER				

Vehicle Details

Registration	532QUM	Next Service	Litres	
Make	STEELBRO	Rego Due	Trans	N/A
Model	TRI AXLE SIDE	Engine #	Air	No
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	TRAILER
Colour		Odometer/Hr	Prod	

Invoice No.	Date	Odometer / Hours	Description	Type
50431	11/09/2020	341044	BROKEN ROLL PIN	Invoice

DATE WORK CARRIED OUT: 11/09/2020

WORK CARRIED OUT:
REMOVED THE BROKEN ROLL PIN ON THE CONTAINER LIFT BUCKLE
INSERTED NEW ROLL PINS
REMOVED ALL SHARP EDGES

NOTE NO FAULT REPAIR BOOK WITH TRAILER.

50407	03/09/2020		RR- 106781 TOP UP COOLANT ON	Invoice
-------	------------	--	------------------------------	---------

DATE WORK CARRIED OUT: 03/09/2020

WORK CARRIED OUT:
TOP UP LIFTER MOTOR COOLANT

RR-106781

50355	19/08/2020	339108	LIFTER BATTERY	Invoice
-------	------------	--------	----------------	---------

DATE WORK CARRIED OUT: 19/08/2020
WORK CARRIED OUT:
INSPECTED LIFTER BATTERY
FOUND IT WAS FLAT DUE TO THE KEY BEING LEFT ON
REMOVED & REPLACED BATTERY
TESTED – ALL OK

50273	17/08/2020	339105	TWIST LOCK DAMAGE	Invoice
-------	------------	--------	-------------------	---------

DATE WORK CARRIED OUT: 17/08/2020

WORK CARRIED OUT:
TRAVELLED BUCCINI YARD
INSPECTED BROKEN TWIST LOCK
REMOVED & REPLACED TWIST LOCK HANDLE

50150	30/07/2020	337853	PRE MACHINERY INSPECTION	Invoice
-------	------------	--------	--------------------------	---------

DATE WORK CARRIED OUT: 29/07/2020

Vehicle Details

Registration	532QUM	Next Service	Litres	
Make	STEELBRO	Rego Due	Trans	N/A
Model	TRI AXLE SIDE	Engine #	Air	No
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	TRAILER
Colour		Odometer/Hr	Prod	

Invoice No.	Date	Odometer / Hours	Description	Type
-------------	------	------------------	-------------	------

WORK CARRIED OUT:
COLLECTED TRAILER FROM YARD

CARRIED OUT PRE MACHINERY INSPECTION
FITTED NEW WHITE REFLECTOR RHF
FURTHER ACTION REQUIRED -

LHF GUARD BRACKET RUSTED THROUGH
ALL 3RD AXLE TYRES BALD
20-40 RAM LEAKING BOTH ENDS

50179	28/07/2020	2260	STARTING PROBLEM	Invoice
--------------	-------------------	-------------	-------------------------	----------------

DATE WORK CARRIED OUT: 28/07/2020

WORK CARRIED OUT:
CHECKED STARTING PROBLEM - FOUND MAIN CRANKING BATTERY DEAD FLAT
SWAPPED OVER BATTERY WITH SPARE & RECHARGED START/CHARGE/CRANE MODES/FUNCTIONS - ALL TESTED OK

50306	01/07/2020	331557	E-STOP FAULT	Invoice
--------------	-------------------	---------------	---------------------	----------------

DATE WORK CARRIED OUT: 12/05/2020

WORK CARRIED OUT:
INSPECT TRAILER AGAIN - REMOVED FUSE BOX COVER COULDN'T LOCATE
ANY BLOWN FUSES, HOWEVER REPLACED 4 FUSES FOR THE ECU AND E-STOP CIRCUITS.
STILL NO CHANGE FOUND IF THE OVERRIDE WAS PRESSED AND THE FRONT E-STOP
WAS PUSHED IN, YOU COULD OPERATE THE CRANES WITH THE REMOTE
ISSUE WITH THE E-STOP.
BROUGHT TRAILER TO WORKSHOP FITTED A SNAP RING TO THE BATTERY HOLDER
BRACKET AS THE ORIGINAL ONE WAS MISSING