



Vehicle History

Vehicle Details

Registration	296QWV	Next Service	Litres	
Make	KREUGER	Rego Due	Trans	N/A
Model	TRI AXLE	Engine #	Air	Yes
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	SKEL
Colour		Odometer/Hr	Prod	

Invoice No.	Date	Odometer / Hours	Description	Type
61300	29/07/2025	30541/9557	SERVICE	Invoice

PARK TRAILER IN WORKSHOP
CARRY OUT C SERVICE AS PER SERVICE SHEET
APPLY AIR TO TRAILER
TEST LIGHTING FUNCTION
LIFT TRAILER WITH HOIST
CHECK SUSPENSION COMPONENTS
CHECK KING PIN BOLT TENSION
CHECK SKID PLATE
CHECK THE UNDERCARRIAGE OF THE TRAILER
CARRY OUT GREASING OF AXLES
CARRY OUT DE-ADJUSTMENT OF BRAKES
REMOVE HUB CAPS AND REMOVE BEARING ADJUSTMENT NUTS
REMOVE BEARINGS FROM HUBS
CLEAN STUB AXLES AND APPLY NEW FILM OF GREASE TO STUB AXLES
CLEAN BEARINGS IN TURBO WASH
CLEAN HUBS OF GREASE AND REPACK HUBS AS REQUIRED
REMOVED BEARINGS FROM PARTS WASHER BLOW OUT WITH AIR AND REPACK BEARINGS
INSTALL BEARINGS TO HUBS
INSTALL INNER HUB SEALS
INSTALL HUBS TO THE TRAILER AND TENSION-BEARING ADJUSTMENT NUTS
SECURE BEARING ADJUSTMENT NUTS WITH RETAINERS
REINSTALL HUB CAPS TO AXLES AND TENSION HUB CAPS
CARRY OUT ADJUSTMENT OF BRAKES
LOWER TRAILER
CHECK WHEEL NUT TENSION
CHECK ALL LIVERY INCLUDING MUDFLAPS AND DECAL
INSPECT MARKER PLATES INCLUDING CON SIGN, CHEVRONS, AND OVERTAKE SIGNAGE
CHECK TOP DECK OF TRAILER FOR ALL FUNCTIONALITY
APPLY SERVICE STICKER
COMPLETE PAPERWORK
CLEAN WORK AREA
MOVE TRAILER OUT OF WORKSHOP
NOTE
CARRIED OUT SERVICE ON GENERATOR
FIT GLASS DOOR TO GENERATOR
REMOVED BATTERY ISOLATOR + MOUNT, REPLACED MOUNT + REFITTED
STARTED ENGINE
TESTED OPERATION
FIT NEW LOCK TO DOOR MODIFIED LOCK TO SUIT DOOR + LATCH
FIT HANDLE TO DOOR
FIT SPARE KEY AT BATTERY
REPAIRED SAFETY CABLE + FIT SPRINGS TO CABLES
REPLACED RH FRONT SIDE MARKER LIGHT AND HOUSING
REPLACED RH FRONT REFLECTOR
SECURED AIRLINES + ELECTRICAL CABLES ALONG CHASSIS

Vehicle Details

Registration	296QWV	Next Service	Litres	
Make	KREUGER	Rego Due	Trans	N/A
Model	TRI AXLE	Engine #	Air	Yes
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	SKEL
Colour		Odometer/Hr	Prod	
		30541 / 9557		

Invoice No.	Date	Odometer / Hours	Description	Type
			REPAIRED DOOR HINGE FOR GENERATOR FIT NEW M5 NUTSERT TO GENERATOR FOR GLASS DOOR REPLACED HUBOMETER ***RECEIVE A \$25 DISCOUNT FOR ANY POSITIVE GOOGLE REVIEW ON OUR COMPANY GOOGLE WEBPAGE - HEAVY VEHICLE WORKSHOP*** *****PLEASE READ***** WARRANTY ON PARTS ARE SUBJECT TO MANUFACTURERS TERMS AND CONDITIONS. <u>HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE THE STORE FOR PRICING ON - 07 3260 8950</u>	

60698	18/03/2025	30541/9557	DEFECTS	Invoice
			REMOVE, REPAIR AND REPLACE WINDOW TEST BATTERY - 9V REPLACE BATTERY CHECK OIL CHECK COOLANT <u>HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE THE STORE FOR PRICING ON - 07 3260 8950</u> ***RECEIVE A \$25 DISCOUNT FOR ANY POSITIVE GOOGLE REVIEW ON OUR COMPANY GOOGLE WEBPAGE - HEAVY VEHICLE WORKSHOP***	

59127	23/04/2024	30435/9557	C SERVICE	Invoice
			CARRIED OUT C SERVICE PARK TRAILER IN WORKSHOP CARRY OUT C SERVICE AS PER SERVICE SHEET APPLY AIR TO TRAILER TEST LIGHTING FUNCTION LIFT TRAILER WITH HOIST CHECK SUSPENSION COMPONENTS CHECK KING PIN BOLT TENSION CHECK SKID PLATE CHECK THE UNDERCARRIAGE OF THE TRAILER CARRY OUT GREASING OF AXLES CARRY OUT DE-ADJUSTMENT OF BRAKES REMOVE HUB CAPS AND REMOVE BEARING ADJUSTMENT NUTS REMOVE BEARINGS FROM HUBS CLEAN STUB AXLES AND APPLY NEW FILM OF GREASE TO STUB AXLES CLEAN BEARINGS IN TURBO WASH CLEAN HUBS OF GREASE AND REPACK HUBS AS REQUIRED REMOVED BEARINGS FROM PARTS WASHER BLOW OUT WITH AIR AND REPACK BEARINGS	

Vehicle Details

Registration	296QWV	Next Service	Litres	
Make	KREUGER	Rego Due	Trans	N/A
Model	TRI AXLE	Engine #	Air	Yes
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	SKEL
Colour		Odometer/Hr	Prod	

Invoice No.	Date	Odometer / Hours	Description	Type
			INSTALL BEARINGS TO HUBS INSTALL INNER HUB SEALS INSTALL HUBS TO THE TRAILER AND TENSION-BEARING ADJUSTMENT NUTS SECURE BEARING ADJUSTMENT NUTS WITH RETAINERS REINSTALL HUB CAPS TO AXLES AND TENSION HUB CAPS CARRY OUT ADJUSTMENT OF BRAKES LOWER TRAILER CHECK WHEEL NUT TENSION CHECK ALL LIVERY INCLUDING MUDFLAPS AND DECAL INSPECT MARKER PLATES INCLUDING CON SIGN, CHEVRONS, AND OVERTAKE SIGNAGE CHECK TOP DECK OF TRAILER FOR ALL FUNCTIONALITY APPLY SERVICE STICKER COMPLETE PAPERWORK CLEAN WORK AREA MOVE TRAILER OUT OF WORKSHOP <u>HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE JEFF FOR PRICING ON - 07 3260 8950</u>	

58696	15/02/2024	30435/9557	C SERVICE	Invoice
			CARRY OUT "C" SERVICE PARK TRAILER IN WORKSHOP CARRY OUT C SERVICE AS PER SERVICE SHEET APPLY AIR TO TRAILER TEST LIGHTING FUNCTION LIFT TRAILER WITH HOIST CHECK SUSPENSION COMPONENTS CHECK KING PIN BOLT TENSION CHECK SKID PLATE CHECK THE UNDERCARRIAGE OF THE TRAILER CARRY OUT GREASING OF AXLES CARRY OUT DE-ADJUSTMENT OF BRAKES REMOVE HUB CAPS AND REMOVE BEARING ADJUSTMENT NUTS REMOVE BEARINGS FROM HUBS CLEAN STUB AXLES AND APPLY NEW FILM OF GREASE TO STUB AXLES CLEAN BEARINGS IN TURBO WASH CLEAN HUBS OF GREASE AND REPACK HUBS AS REQUIRED REMOVED BEARINGS FROM PARTS WASHER BLOW OUT WITH AIR AND REPACK BEARINGS INSTALL BEARINGS TO HUBS INSTALL INNER HUB SEALS INSTALL HUBS TO THE TRAILER AND TENSION-BEARING ADJUSTMENT NUTS SECURE BEARING ADJUSTMENT NUTS WITH RETAINERS REINSTALL HUB CAPS TO AXLES AND TENSION HUB CAPS CARRY OUT ADJUSTMENT OF BRAKES LOWER TRAILER CHECK WHEEL NUT TENSION	

Registration	296QWV	Next Service		Litres	
Make	KREUGER	Rego Due		Trans	N/A
Model	TRI AXLE	Engine #		Air	Yes
Model Series		VIN	6FH9079GADM014754	Cyl	0
Model Code		Build Date		Body	SKEL
Colour		Odometer/Hr	30541 / 9557	Prod	

Invoice No.	Date	Odometer / Hours	Description	Type
CHECK ALL LIVERY INCLUDING MUDFLAPS AND DECAL INSPECT MARKER PLATES INCLUDING CON SIGN, CHEVRONS, AND OVERTAKE SIGNAGE CHECK TOP DECK OF TRAILER FOR ALL FUNCTIONALITY APPLY SERVICE STICKER ***** NUMBER PLATE FADED ZIP TIED DOG RATCHETS UNDER GENERATOR REPLACED FAULTY LR MARKER LIGHT				
<u>HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.</u>				
56633	11/05/2023	0	REPAIR GENSET FRAME	Invoice
REMOVE GENSET AND MOUNTING FRAME OFF THE TRAILER. REMOVE THE GENSET OFF THE FRAME. CUT DAMAGED SECTION OF THE FRAME OUT AND WELD IN NEW SECTIONS OF STEEL. REFITTED GENSET TO FRAME REFITTED ASSEMBLY TO TRAILER TIGHTENED CHAINS WITH DOG DROP TRAILER BACK TO SHED 24				
56522	18/04/2023	24836/9557	GENERAL CHECK OVER	Invoice
LOCATED GENSET AT YARD CARRIED OUT START / CHARGE / GENERAL CHECKOVER - ALL OK				
54125	04/01/2023	240920	C SERVICE AND REPAIRS	Invoice
TOWED THE TRAILER FROM SHED 24 TO THE WORKSHOP CARRIED OUT C SERVICE AND REPAIRS STRAIGHTEN LEGS AND REPLACE LEAKING SHOCKABSORBER REMOVED HUB CAPS AND FOUND GREASE NEEDS REPLACING. REMOVED HUBS, HUB SEALS AND BEARINGS. CLEANED OLD GREASE OUT OF THE BEARINGS AND HUBS. REFITTED THE BEARINGS AND FITTED NEW SEALS. FITTED NEW HUB CAP GASKETS AND FILL HUBS WITH SEM1 FLUID GREASE. REPLACED INNER TAIL LIGHT INSERT REPLACED FRONT LEFT MARKER LIGHT NOTE- LHS FRONT TYRE TYRE DAMAGED				
53932	25/03/2022	0	JUMP START	Invoice
MOTOR ON TRAILER WOULDNT START CHECK BATTERY - FLAT JUMP STARTED ENGINE AND CHECKED CHARGE RATE				

Vehicle Details

Registration	296QWV	Next Service	Litres	
Make	KREUGER	Rego Due	Trans	N/A
Model	TRI AXLE	Engine #	Air	Yes
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	SKEL
Colour		Odometer/Hr	Prod	

Invoice No.	Date	Odometer / Hours	Description	Type
ALL OK				
53499	11/01/2022	19703	A AND C SERVICE	Invoice
MOVED TRAILER INTO WORKSHOP CARRIED OUT A AND C SERVICES ON TRAILER REPLACED KING PIN AND BOLTS TIGHTENED LHS SAFETY ROPE REPLACED FRONT RHS AMBER REFLECTOR REPLACED LHS SECOND SIDE LIGHT REPLACED RHS 4TH SIDE LIGHT HOUSING REMOVED AND REPLACED LHS NUMBER PLATE WITH LED ASSEMBLY FIT RIVET TO DANGEROUS FLIP SIGN REMOVED GENERATOR FROM TRAILER PARKED TRAILER ON STREET FOR COLLECTION				
51970	30/04/2021	15923	CARRY OUT REPAIRS	Invoice
FABRICATED MOUNTING BRACKET AND FIT DANAGEROUS GOOD SIGN TO REAR OF VEHICLE INSPECTED AIRBAGS FOR LEAKS - ALL OK TIGHTENED DOCK LEVELLING VALVE HOUSING AND REPLACED DOCK LEVELING VALVE AIR FITTING - LEAKING.				
51645	04/03/2021	13970	A SERVICE	Invoice
DATE WORK CARRIED OUT: 04/03/2020 WORK CARRIED OUT: CARRIED OUT A SERVICE DEFECTS NOTED NONE NOTED				
51167	30/12/2020	11055	A SERVICE	Invoice
DATE WORK CARRIED OUT: 30/12/2020 WORK CARRIED OUT: CARRIED OUT A SERVICE				
50868	11/11/2020	9180	NUMBER PLATE LIGHT	Invoice
DATE WORK CARRIED OUT: 11/11/2020 WORK CARRIED OUT: REPLACED RH REAR NUMBER PLATE LIGHT				
50783	29/10/2020	8550	A & C SERVICES & REAPIRS	Invoice

Vehicle Details

Registration	296QWV	Next Service	Litres	
Make	KREUGER	Rego Due	Trans	N/A
Model	TRI AXLE	Engine #	Air	Yes
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	SKEL
Colour		Odometer/Hr	Prod	

Invoice No.	Date	Odometer / Hours	Description	Type
-------------	------	------------------	-------------	------

DATE WORK CARRIED OUT: 29/10/2020

WORK CARRIED OUT:

CARRIED OUT A SERVICE AS PER HVW SERVICE SHEET

CARRIED OUT C SERVICE AS PER HVW SERVICE SHEET

REMOVED RUST ARBOUR SKID PLATE

REPLACED LH #2 AXLE MUDGUARD

FURTHER ACTION REQUIRED -

LH #1 AXLE TYRE SIDE WALL DAMAGED

RH NUMBER PLATE COVER MISSING

50747	27/10/2020	8500	REAR TAIL LIGHT	Invoice
--------------	-------------------	-------------	------------------------	----------------

DATE WORK CARRIED OUT: 27/10/2020

WORK CARRIED OUT:

RIGHT REAR LED TAIL LIGHT NOT WORKING, DIAGNOSED FAULTY, REPLACED LED REAR TAIL LIGHT

ASSEMBLY, ALL OK.

50245	19/08/2020	6325	CARRY OUT SERVICE A	Invoice
--------------	-------------------	-------------	----------------------------	----------------

DATE WORK CARRIED OUT:

WORK CARRIED OUT:

CARRIED OUT A SERVICE

TOP UP HUB OIL

MR TYRE FLAT SPOT

ML TYRE FLAT SPOT

50078	20/07/2020	0	SAFETY CABLE	Invoice
--------------	-------------------	----------	---------------------	----------------

DATE WORK CARRIED OUT: 20/07/2020

WORK CARRIED OUT:

REPLACED BROKEN SAFETY CABLE L/H/S