



Vehicle History

Vehicle Details

Registration	234QXK	Next Service		Litres	
Make	KRUEGER	Rego Due	29/01/2023	Trans	N/A
Model	40' RETRACTABLE	Engine #		Air	No
Model Series		VIN	6FH9079GAEM015083	Cyl	0
Model Code		Build Date		Body	SKEL
Colour	BLUE	Odometer	71175	Prod	

Invoice No.	Date	Odometer	Description	Type
61231	17/07/2025	71175	SERVICE AND CHECKOVER - ROLL OVER	Invoice
<p>SERVICE AND CHECKOVER - ROLL OVER TRAILER COMING BACK FROM REPAIRER</p> <p>PARK TRAILER IN WORKSHOP CARRY OUT A SERVICE AS PER SERVICE SHEET APPLY AIR TO TRAILER TEST LIGHTING FUNCTION LIFT TRAILER WITH HOIST CHECK WHEEL BEARINGS FOR MOVEMENT CHECK SUSPENSION COMPONENTS CHECK KING PIN BOLT TENSION CHECK SKID PLATE CHECK THE UNDERCARRIAGE OF THE TRAILER CARRY OUT GREASING OF AXLES CARRY OUT ADJUSTMENT OF BRAKES LOWER TRAILER CHECK WHEEL TENSION CHECK WHEEL BEARING GREASE FOR CONTAMINANTS CHECK ALL LIVERY INCLUDING MUDFLAPS AND DECAL INSPECT MARKER PLATES INCLUDING CON SIGN, CHEVRONS, AND OVERTAKE SIGNAGE CHECK TOP DECK OF TRAILER FOR ALL FUNCTIONALITY APPLY SERVICE STICKER COMPLETE PAPERWORK CLEAN WORK AREA MOVE TRAILER OUT OF WORKSHOP NOTE REPLACED RH #4 SIDE MARKER LIGHT REPLACED LH #5 SIDE M,ARKER LIGHT REPLACED X4 REFLECTORS TESTED CHASSIS SLIDE OPERATION PARKED TRAILER ON STREET</p> <p>***RECEIVE A \$25 DISCOUNT FOR ANY POSITIVE GOOGLE REVIEW ON OUR COMPANY GOOGLE WEBPAGE - HEAVY VEHICLE WORKSHOP***</p> <p><u>HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE THE STORE FOR PRICING ON - 07 3260 8950</u></p>				
60393	14/01/2025	67542	LABOUR - BUCCINI	Invoice

Vehicle Details

Registration	234QXK	Next Service		Litres	
Make	KRUEGER	Rego Due	29/01/2023	Trans	N/A
Model	40' RETRACTABLE	Engine #		Air	No
Model Series		VIN	6FH9079GAEM015083	Cyl	0
Model Code		Build Date		Body	SKEL
Colour	BLUE	Odometer	71175	Prod	

Invoice No.	Date	Odometer	Description	Type
			PARK TRAILER IN WORKSHOP CARRY OUT A SERVICE AS PER SERVICE SHEET APPLY AIR TO TRAILER TEST LIGHTING FUNCTION LIFT TRAILER WITH HOIST CHECK WHEEL BEARINGS FOR MOVEMENT CHECK SUSPENSION COMPONENTS CHECK KING PIN BOLT TENSION CHECK SKID PLATE CHECK THE UNDERCARRIAGE OF THE TRAILER CARRY OUT GREASING OF AXLES CARRY OUT ADJUSTMENT OF BRAKES LOWER TRAILER CHECK WHEEL TENSION CHECK WHEEL BEARING GREASE FOR CONTAMINANTS CHECK ALL LIVERY INCLUDING MUDFLAPS AND DECAL INSPECT MARKER PLATES INCLUDING CON SIGN, CHEVRONS, AND OVERTAKE SIGNAGE CHECK TOP DECK OF TRAILER FOR ALL FUNCTIONALITY APPLY SERVICE STICKER COMPLETE PAPERWORK CLEAN WORK AREA MOVE TRAILER OUT OF WORKSHOP NOTE CHECKED OVER FOR A 4 HOUR TRIP TIGHTENED CHASSIS ROLLER BOX BOLTS	

59921	03/10/2024	57083	DEFECTS	Invoice
			REPAIR DAMAGE PARKED TRAILER IN WORKSHOP REMOVED RH #1 AXLE DAMAGED FRONT MUDGUARD BRACKET, ANTI-SAIL BRACKET AND MUDGUARD STRAIGHTENED BRACKETS REFITTED BRACKETS AND MUDFLAP RETURNED TRAILER TO SHED 24 <u>HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE JEFF FOR PRICING ON - 07 3260 8950</u>	

59884	02/10/2024	56675	A SERVICE	Invoice
			PARK TRAILER IN WORKSHOP CARRY OUT A SERVICE AS PER SERVICE SHEET APPLY AIR TO TRAILER TEST LIGHTING FUNCTION LIFT TRAILER WITH HOIST CHECK WHEEL BEARINGS FOR MOVEMENT CHECK SUSPENSION COMPONENTS CHECK KING PIN BOLT TENSION CHECK SKID PLATE CHECK THE UNDERCARRIAGE OF THE TRAILER CARRY OUT GREASING OF AXLES CARRY OUT ADJUSTMENT OF BRAKES	

Vehicle Details

Registration	234QXK	Next Service		Litres	
Make	KRUEGER	Rego Due	29/01/2023	Trans	N/A
Model	40' RETRACTABLE	Engine #		Air	No
Model Series		VIN	6FH9079GAEM015083	Cyl	0
Model Code		Build Date		Body	SKEL
Colour	BLUE	Odometer	71175	Prod	

Invoice No.	Date	Odometer	Description	Type
			LOWER TRAILER CHECK WHEEL TENSION CHECK WHEEL BEARING GREASE FOR CONTAMINANTS CHECK ALL LIVERY INCLUDING MUDFLAPS AND DECAL INSPECT MARKER PLATES INCLUDING CON SIGN, CHEVRONS, AND OVERTAKE SIGNAGE CHECK TOP DECK OF TRAILER FOR ALL FUNCTIONALITY APPLY SERVICE STICKER COMPLETE PAPERWORK CLEAN WORK AREA MOVE TRAILER OUT OF WORKSHOP NOTE ALL AIRBAGS PERISHING AT BASE - MONITOR MR SHOCK MINOR WEEP - MONITOR FL + MR TRAILING ARM BUSH HAVE MOVEMENT - REPLACE NEXT C SERVICE RE-PACK NEXT C SERVICE RUST ON UNDERSIDE OF FLOOR ABOVE 1ST AND 2ND AXLE REAR TWIST LOCK HOUSING CRACKED REPLACED 2 AMBER REFLECTORS PAINTED AND REPAIRED TWIST LOCK PEDESTALS ***THIS INVOICE INCLUDES HOURS PREVIOUSLY NOT CHARGED TO INVOICE 59824 FOR REPAIR OF ABS VALVE ON 384QYM**** <u>HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE JEFF FOR PRICING ON - 07 3260 8950</u>	
59774	29/08/2024	48886	FABRICATION	Invoice
			STRAIGHTENED HANDLE FOR CONATINER LOCK WELDED CRACKS CHANGED RIGHT RAER MUDFLAP <u>HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE JEFF FOR PRICING ON - 07 3260 8950</u>	
59443	25/06/2024	48886	WEAR PADS	Invoice
			COLLECTED TRAILER FROM BT YARD UPON COLLECTION FOUND WEAR PADS CRACKED AND HEAVILY WORN PARKED TRAILER IN WORKSOP BEGAN SEPERATING TRAILER TO ACCESS WEAR PADS - NOTICED STPO BLOCKS WELDED TO FRAME. FABRICATOR REMOVED WELDED ON STOP BLOCKS GREASED TRAILER REMOVE ROLLERS SEPERATE TRAILER DISASSEMBLE CHASSIS SLIDE REMOVED ROLLER BOXES CARRIED OUT REPAIRS TO CHASSIS FRAM ROLLERS REPLACED WEAR PADS, ROLLERS AND PINS COMPLETE PAPERWORK PARK TRAILER IN WORKSHOP	

Vehicle Details

Registration	234QXK	Next Service		Litres	
Make	KRUEGER	Rego Due	29/01/2023	Trans	N/A
Model	40' RETRACTABLE	Engine #		Air	No
Model Series		VIN	6FH9079GAEM015083	Cyl	0
Model Code		Build Date		Body	SKEL
Colour	BLUE	Odometer	71175	Prod	

Invoice No.	Date	Odometer	Description	Type
			CARRY OUT A SERVICE AS PER SERVICE SHEET APPLY AIR TO TRAILER TEST LIGHTING FUNCTION LIFT TRAILER WITH HOIST CHECK WHEEL BEARINGS FOR MOVEMENT CHECK SUSPENSION COMPONENTS CHECK KING PIN BOLT TENSION CHECK SKID PLATE CHECK THE UNDERCARRIAGE OF THE TRAILER CARRY OUT GREASING OF AXLES CARRY OUT ADJUSTMENT OF BRAKES LOWER TRAILER CHECK WHEEL TENSION CHECK WHEEL BEARING GREASE FOR CONTAMINANTS CHECK ALL LIVERY INCLUDING MUDFLAPS AND DECAL INSPECT MARKER PLATES INCLUDING CON SIGN, CHEVRONS, AND OVERTAKE SIGNAGE CHECK TOP DECK OF TRAILER FOR ALL FUNCTIONALITY APPLY SERVICE STICKER COMPLETE PAPERWORK CLEAN WORK AREA MOVE TRAILER OUT OF WORKSHOP <u>HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE JEFF FOR PRICING ON - 07 3260 8950</u>	
59421	19/06/2024	48577	LABOUR - BUCCINI	Invoice
			TRAVEL TO YARD INSPECT TRAILER NOT RETRACTING FOUND NO AIR PRESSURE TO BUTTON PLAYED WITH RIDE HIEGHT RELEASED PINS - EXTENDED TRAILER PACK UP TOOLS RETURNED TO WORKHOP <u>HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE JEFF FOR PRICING ON - 07 3260 8950</u>	
58900	13/03/2024	42659	C SERVICE	Invoice
			PARK TRAILER IN WORKSHOP CARRY OUT C SERVICE AS PER SERVICE SHEET APPLY AIR TO TRAILER TEST LIGHTING FUNCTION LIFT TRAILER WITH HOIST CHECK SUSPENSION COMPONENTS CHECK KING PIN BOLT TENSION CHECK SKID PLATE CHECK THE UNDERCARRIAGE OF THE TRAILER CARRY OUT GREASING OF AXLES CARRY OUT DE-ADJUSTMENT OF BRAKES	

Vehicle Details					
Registration	234QXK	Next Service		Litres	
Make	KRUEGER	Rego Due	29/01/2023	Trans	N/A
Model	40' RETRACTABLE	Engine #		Air	No
Model Series		VIN	6FH9079GAEM015083	Cyl	0
Model Code		Build Date		Body	SKEL
Colour	BLUE	Odometer	71175	Prod	

Invoice No.	Date	Odometer	Description	Type
			REMOVE HUB CAPS AND REMOVE BEARING ADJUSTMENT NUTS REMOVE BEARINGS FROM HUBS CLEAN STUB AXLES AND APPLY NEW FILM OF GREASE TO STUB AXLES CLEAN BEARINGS IN TURBO WASH CLEAN HUBS OF GREASE AND REPACK HUBS AS REQUIRED REMOVED BEARINGS FROM PARTS WASHER BLOW OUT WITH AIR AND REPACK BEARINGS INSTALL BEARINGS TO HUBS INSTALL INNER HUB SEALS INSTALL HUBS TO THE TRAILER AND TENSION-BEARING ADJUSTMENT NUTS SECURE BEARING ADJUSTMENT NUTS WITH RETAINERS REINSTALL HUB CAPS TO AXLES AND TENSION HUB CAPS CARRY OUT ADJUSTMENT OF BRAKES LOWER TRAILER CHECK WHEEL NUT TENSION CHECK ALL LIVERY INCLUDING MUDFLAPS AND DECAL INSPECT MARKER PLATES INCLUDING CON SIGN, CHEVRONS, AND OVERTAKE SIGNAGE CHECK TOP DECK OF TRAILER FOR ALL FUNCTIONALITY APPLY SERVICE STICKER COMPLETE PAPERWORK CLEAN WORK AREA ***** WELDED AND PAINTED CRACKS IN TWISTLOCK PEDESTALS REPLACED DOCK RUBBER ON RHS REAR REPLACED HI-VIS CHEVRONS ON REAR AND DO NOT OVERTAKE SIGN RETURNED TRAILER TO SHED 24 <u>HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.</u>	

58717	16/02/2024	41691	A SERVICE	Invoice
			DROVE TO BUCCINI YARD FOR VEHICLES TO SERVICE MOVED 234QXK INTO WORKSHOP PARK VEHICLE IN WORKSHOP CARRY OUT A SERVICE AS PER SERVICE SHEET CARRY OUT WALK AROUND VISUAL INSPECTION SECURE HOIST ON TRUCK CHECK ALL LIGHTS INCLUDING ALL REVERSE LAMPS AND BEEPERS CHECK WIPER AND WASHER OPERATION CHECK BATTERY LEVELS, TERMINALS AND CLAMPS LIFT CAB/BONNET TO ACCESS ENGINE BAY CHECK ALL BELTS AND MOUNTS LIFT TRUCK ON HOIST CARRY OUT VISUAL INSPECTION OF UNDER CARRIAGE (DRIVE LINE AND SUSPENSION COMPONENTS) ADJUST BRAKES AND CHECK BRAKE THICKNESSES CHECK AND ADJUST CLUTCH IF APPLICABLE CHECK GEAR BOX OIL LEVEL AND QUALITY CHECK DIFF OIL LEVEL AND QUALITY CARRY OUT GREASING OF TRUCK LOWER TRUCK CHECK ENGINE OIL TOP UP COOLANT IF REQUIRED LOWER CAB/BONNET AND SECURE IN PLACE FIT SERVICE STICKER COMPLETE PAPERWORK	

Vehicle Details

Registration	234QXK	Next Service		Litres	
Make	KRUEGER	Rego Due	29/01/2023	Trans	N/A
Model	40' RETRACTABLE	Engine #		Air	No
Model Series		VIN	6FH9079GAEM015083	Cyl	0
Model Code		Build Date		Body	SKEL
Colour	BLUE	Odometer	71175	Prod	

Invoice No.	Date	Odometer	Description	Type

REPLACED DG FLIP SIGN AND TIGHTENING LOOSE AIR TANK BOLTS AT REAR OF TRAILER MOVED TRAILER ONTO STREET AS THERE WAS NO ROOM AT SHED 24				
<u>HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.</u>				
57870	18/10/2023	34623	A SERVICE	Invoice
PARK TRAILER IN WORKSHOP CARRY OUT A SERVICE AS PER SERVICE SHEET APPLY AIR TO TRAILER TEST LIGHTING FUNCTION LIFT TRAILER WITH HOIST CHECK WHEEL BEARINGS FOR MOVEMENT CHECK SUSPENSION COMPONENTS CHECK KING PIN BOLT TENSION CHECK SKID PLATE CHECK THE UNDERCARRIAGE OF THE TRAILER CARRY OUT GREASING OF AXLES CARRY OUT ADJUSTMENT OF BRAKES LOWER TRAILER CHECK WHEEL TENSION CHECK WHEEL BEARING GREASE FOR CONTAMINANTS CHECK ALL LIVERY INCLUDING MUDFLAPS AND DECAL INSPECT MARKER PLATES INCLUDING CON SIGN, CHEVRONS, AND OVERTAKE SIGNAGE CHECK TOP DECK OF TRAILER FOR ALL FUNCTIONALITY APPLY SERVICE STICKER COMPLETE PAPERWORK CLEAN WORK AREA MOVE TRAILER OUT OF WORKSHOP				
<u>HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.</u>				

57961	04/10/2023	34623	SAFETY ROPE NEEDS REPLACING	Invoice
DROVE TO BUCCINI YARD FOUND AIR FITTING AND ELECTRICAL PLUG DAMAGED ATTEMPTED TO WIND LANDING LEGS UP, UNABLE TO WIND UP DISCONNECTED FROM TRAILER AND RETURNED TO WORKSHOP COLLECTED AIR FITTINGS AND TOOLS TO REMOVE LANDING LEGS RETURNED TO TRAILER AND REPLACED AIR FITTING CONNECTED TO TRAILER AND REMOVED LANDING LEGS RETURNED TO WORKSHOP AND PARKED TRAILER IN WORKSHOP FITTED CHASSIS STANDS AND DISCONNECTED TRAILER RETURNED TO BUCCINI YARD TO COLLECT DAMAGED LANDING LEG REPLACED 7 PIN ELECTRICAL SOCKET REPLACED SAFETY ROPE EYELETS/MOUNTS FITTED SPRINGS TO SAFETY ROPES				

Vehicle Details

Registration	234QXK	Next Service		Litres	
Make	KRUEGER	Rego Due	29/01/2023	Trans	N/A
Model	40' RETRACTABLE	Engine #		Air	No
Model Series		VIN	6FH9079GAEM015083	Cyl	0
Model Code		Build Date		Body	SKEL
Colour	BLUE	Odometer	71175	Prod	

Invoice No.	Date	Odometer	Description	Type
			REMOVED OLD CRACKED WELDS BY GRINDING GROUND V-GROOVE BETWEEN JOINTS GROUND OFF PAINT ON AREAS TO BE WELDED WELDED PLATES TOP AND BOTTOM PAINTED WELDED AREAS FIT NEW LEGS REMOVED PAINT ON AREAS TO BE WELDED TACKED AND WELDED BRACKETS ON LEGS PAINTED BRACKETS BOLTED BRACES ON BRACKETS MOVED TRAILER ONTO STREER <u>HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.</u>	
57491	25/08/2023	31501	REMOVE AND REPLACE LHF TWIATLOCK	Invoice
			CARRIED OUT REPLACEMENT OF DAMAGED LHF TWIST LOCK TESTED OPERATION TESTED ALL OK <u>HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.</u>	
57144	21/06/2023	25386	A SERVICE	Invoice
			BROUGHT INTO WORKSHOP CARRIED OUT A SERVICE FOUND SPLIT AIRLINE GOING INTO PUSH FITTING, CUT AIRLINE A LITTLE SHORTER AND RE-FIT, FIXED LEAK REPLACED MARKER LIGHT NOTE- 2ND AXLE RHS SHOCKY WEEPING - MONITOR BEARING GREASE STARTING TO TURN BLACK, RE-PACK AT NEXT SERVICE LANDING LEGS ARE A LITTLE BENT AND HARD TO RAISE	
56453	13/04/2023	19972	TRAILER CRABBING	Invoice
			CHECKED FOR TRAILER NOT TRACKING PROPERLY FOUND CHASSIS SLIDE GUIDES WORN REMOVED AIR LINES, STOPPER BLOCKS AND ROLLER BOXES OXY CUT WELDS FROM STOPPER BLOCK REMOVED CHASSIS FROM TRI-AXLE ASSEMBLE REMOVED GREASE FROM SLIDE PINS WELDED SLIDE PIN LOCATING POCKETS WELDED CHASSIS SLIDE WEAR PADS REPAIRED / WELDED CHASSIS GUIDE AT TRI AXLE SIDE GROUND ALL WELDS REPAIRED / WELDED CHASSIS SLIDE AT FRAME GROUND ALL WELDS REMOVED, CLEANED AND INSPECTED CHASSIS SLIDE PINS CHECKED SUSPENSION FOR MOVEMENT FOUND RH #1 AXLE TRAILING ARM PIVOT BOLT LOOSE REMOVED MUDGUARD REMOVED SEIZED NUT AND ALIGNMENT WASHERS FITTED NEW TRAILING ARM ALIGNMENT KIT	

Vehicle Details

Registration	234QXK	Next Service		Litres	
Make	KRUEGER	Rego Due	29/01/2023	Trans	N/A
Model	40' RETRACTABLE	Engine #		Air	No
Model Series		VIN	6FH9079GAEM015083	Cyl	0
Model Code		Build Date		Body	SKEL
Colour	BLUE	Odometer	71175	Prod	

Invoice No.	Date	Odometer	Description	Type
REFITTED MUDGUARDS CHECKED FOR ROLLER BOX WASHERS CHECKED FOR TRAILER NOT TRACKING PROPERLY FOUND CHASSIS SLIDE GUIDES WORN REMOVED AIRLINES, STOPPER BLOCKS AND ROLLER BOXES OXY CUT WELDS FROM STOPPER BLOCK REMOVED CHASSIS FROM TRI-AXLE ASSEMBLY REMOVED GREASE FROM SLIDE PINS WELDED SLIDE PIN LOCATING POCKETS WELDED CHASSIS SLIDE WEAR PADS MODIFIED WASHER FOR ROLLER BOX SHIMS FITTED NEW ROLLERS AND PINS TO OLLER BOXES MOUNTED ROLLER BOXES TO CHASSISASSEMBLED CHASSIS TO TRI AXLE FITTED NEW CHASSIS SLIDE LOCKING PINS AND SPRINGS TESTED OPERATION OF SLIDE FITTED STOPPER BLOCKS TO CHASSIS SLIDE TEST DROVE TRAILER AND CHECKED FOR TRACKING RETURNED TO WORKSHOP WELDED STOPPER BLOCKS PAINTED ALL WELDS AND TRAILING ARM PIVOLT BOLT RETURNED TRAILER TO SHED 24				
56333	30/03/2023	19572	C SERVICE - RE-PACK NOT REQUIRED	Invoice
BROUGHT TRAILER INTO WORKSHOP C SERVICE RE-PACK NOT REQUIRED REPAIRED 2 X LIGHTS ON REAR OF TRAILER REPAIRED NUMBER PLATE LIGHT PARKED TRAILER AT SHED 24				
55957	14/02/2023	0	FIT FIRE EXTINGUSHER BRACKET	Invoice
BROUGHT VEHICLE INTO THE WORKSHOP FITTED FIRE EXTINGUSHER BRACKET TO LANDING LEG				
55320	09/11/2022	7020	BREAK DOWN - TRAVEL TO DP WORLD	Invoice
PACK UP VAN TRAVEL TO DP WORLD AT PORT OF BRISBANE DIAGNOSE AND FOUND TRAILER LOCKING UP BRAKE, DUE TO STRETCHED AIRLINES REMOVE JOINER AND FIT LONGER HOSE TO THE FITTING - ALL OK DROVE BACK TO THE WORKSHOP				
55315	08/11/2022	6786	AIR LEAKS	Invoice
REPAIRED AIR LEAKS WITH JOINER AND NEW TRAILER SIDE MALE SUZI FITTING				
54970	15/09/2022	382	RE-ATTACH SERVICE BRAKE HOSE	Invoice
BROUGHT VEHICLE INTO WORKSHOP CHECKED FOR CHASSIS SLIDING FAULT REPAIRED AIRLEAK TESTED OPERATION				
54937	09/09/2022		A SERVICE	Invoice

Vehicle Details

Registration	234QXK	Next Service		Litres	
Make	KRUEGER	Rego Due	29/01/2023	Trans	N/A
Model	40' RETRACTABLE	Engine #		Air	No
Model Series		VIN	6FH9079GAEM015083	Cyl	0
Model Code		Build Date		Body	SKEL
Colour	BLUE	Odometer	71175	Prod	

Invoice No.	Date	Odometer	Description	Type
			BROUGHT VEHICLE INTO WORKSHOP CARRIED OUT A SERVICE REMOVE AND REPLACE HUBO TOOK BACK TO BUCCINI SHED 24	
54524	11/07/2022		TRAILER NOT RETRACTING TO 20FT	Invoice
			HUBO NOT WORKING WALKED TO BUCCINI YARD DROVE PRIME MOVER THAT WAS CONNECTED TO TRAILER BACK TO BUCCINI YARD WALKED BACK TO WORKSHOP INSPECTED TRAILER FOR NOT RETRACTING TO 20FT POSITION REMOVED BOTH REAR CHASSIS SLIDE ROLLER BOXES CUT PLATE OFF PIN - ROTATE PIN 180 DEGREES AND WELD PLATE BACK ON	
53991	06/04/2022	0	A SERVICE	Invoice
			MOVED TRAILER INTO WORKSHOP CARRIED OUT A SERVICE ADJUSTED MIDDLE AXLE LHS WHEEL BEARING REPLACED FEMALE TRAILER PLUG SOCKET REMOVED AND REPLACED NUMBER PLATE LIGHT DEFECTS: REAR AXLE AIR BAGS CRACKING AT BASE - MONITOR MIDDLE AXLE RHS SHOCK ABSORBER WEEPING - MONITOR HUBOMETER DOESNT WORK, REPLACEMENT ON ORDER.	
53874	17/03/2022	0	DIG FLIP	Invoice
			17/3/2022 SECURED DIG FLIP SIGN	
53644	02/02/2022	0	C SERVICE AND REPAIRS	Invoice
			2/2/2022 MOVED TRAILER INTO WORKSHOP 3/2/2022 CARRIED OUT C SERVICE GREASE IN 3RD AXLE REQUIRES REPLACING GREASE IN 1ST AND 2ND AXLE - OK 4/2/2022 REPACK WHEEL BEARINGS ON REAR AXLE REPLACED SAFETY CORD ON RHS OF TRAILER CHECKED OPERATION - ALL OK PARKED ON STREET	

Vehicle Details

Registration	234QXK	Next Service		Litres	
Make	KRUEGER	Rego Due	29/01/2023	Trans	N/A
Model	40' RETRACTABLE	Engine #		Air	No
Model Series		VIN	6FH9079GAEM015083	Cyl	0
Model Code		Build Date		Body	SKEL
Colour	BLUE	Odometer	71175	Prod	

Invoice No.	Date	Odometer	Description	Type
52568	28/07/2021	58916	REPAIRS TO TRAILER	Invoice
REPLACED SIDE MARKER LIGHT - DAMAGED SECURED TO TRAILER WITH RIVETS AND CONNECTED WIRING CHANGED TAIL LIGHT HOSUING AROUND TO BE THE CORRECT WAY AND TESTED OPERATION TRAILER LIGHTS ALL OK INSPECTED SLIDE PIN BUZZER FAULT REMOVED RHS SLIDE PIN PIVOT REPAIRED LEVER AND REFITTED CLEANED SLIDE PIN SWITCHES AND TESTED - ALL OK				
51742	26/03/2021	45128	REPAIRS	Invoice
DEFECTS: RHR INNER TYRE FLAT - HAS PUNCTURE - WENT TO TYRERIGHT FRONT EYE BEAM FOR TWIST LOCKS HAVE CRACKED IN STRENGTH PLATES ON BOTH SIDES - CLEANED UP AND WELDED STRENGTH PLATES INTO FRONT BEAM. TRAILER PROTECTION VALVE LEAKING ON MIDDLE AIR TANK - CHECKED FOR AIR LEAKS FOUND 2 LEAKS AT AIR VALVES ON AIR TANK - DRAINED AIR AND REMOVED VALVE FOR FURTHER INSPECTION REPLACED AIR FITTING, CLEANED UP TANK BUNG AND CHECKED FOR LEAKS - OK. RHR CENTRELIGHT FOR PARKER FAILED - REMOVED AND REPLACED TAIL LIGHT ASSEMBLIES.				
51738	22/03/2021	46912	A SERVICE	Invoice
CARRY OUT A SERVICE - 17/3/2021				
51638	05/03/2021	45128	TEST FAULTY FEMALE PLUG	Invoice
DATE WORK CARRIED OUT: 05/03/2021 WORK CARRIED OUT: TESTED FAULTY FEMALE PLUG REPLACED FEMALE SOCKET PLUG & TESTED CLEANED WITH CONTACT CLEANER AS THERE WAS GREASE IN THE SOCKET				
51219	07/01/2021	36795	BREAKDOWN	Invoice
DATE WORK CARRIED OUT: 07/01/2020 WORK CARRIED OUT: DROVE TO BREAKDOWN @ INDUSTRIAL DRIVE WILLAWONG CHECKED FOR CHASSIS NOT SLIDING FAULT CHECKED PINS, SLIDES & ROLLERS (NO FAULT FOUND) DUMPED AIR OUT OF AIRBAGS RETRACTED CHASSIS SLIDE FILLED AIRBAGS RETURNED TO WORKSHOP				

Vehicle Details

Registration	234QXK	Next Service		Litres	
Make	KRUEGER	Rego Due	29/01/2023	Trans	N/A
Model	40' RETRACTABLE	Engine #		Air	No
Model Series		VIN	6FH9079GAEM015083	Cyl	0
Model Code		Build Date		Body	SKEL
Colour	BLUE	Odometer	71175	Prod	

Invoice No.	Date	Odometer	Description	Type
NOTE: FOUND CONTAINER WAS HEAVY – RECOMMEND USING POSITION 2 ON CHASSIS SLIDE				
51146	05/01/2021	36705	LOCKING PINS	Invoice
DATE WORK CARRIED OUT: 24/12/2020 – 05/01/2020 WORK CARRIED OUT: TRAVELLED TO BREAKDOWN @ ROCKLEA INSPECTED BROKEN SLIDE LOCKING PIN REMOVED TRAILER OFF SITE AS WE WEREN'T ALLOWED TO WORK ONSITE TEMPORARILY FIT A PIPE IN THE HOLE AND SECURED FIT STRAPS TO TRAILER TO HELP SECURE R/H/S RETURNED TO WORKSHOP AND TAGGED TRAILER OUT @ BT YARD REPLACED BOTH SLIDE LOCKING PINS LUBRICATED AND TESTED PIN – ALL OK				
51173	30/12/2020	36709	A SERVICE	Invoice
DATE WORK CARRIED OUT: 30/12/2020 WORK CARRIED OUT: CARRIED OUT A SERVICE DEFECTS NOTED - LH #3 AXLE TYRE TREAD LOW (POS 9 & 10)				
50985	26/11/2020	0	SCALES	Invoice
DATE WORK CARRIED OUT: 26/11/2020 WORK CARRIED OUT: REPLACED AIRBAG WEIGH SCALE (REQUIRES CALIBRATION) TESTED OPERATION & CHECKED FOR LEAKS REPLACED RH FRONT CLEARANCE LIGHT HOUSING				
50768	28/10/2020	30316	A SERVICE & REPAIRS	Invoice
DATE WORK CARRIED OUT: 28/10/2020 WORK CARRIED OUT: CARRIED OUT A SERVICE AS PER HVW SERVICE SHEET REPLACED RH FRONT SIDE MARKER LIGHT STRAIGHTENED FRONT MARKER LIGHT BRACKETS TIGHTENED SAFETY ROPES ADJUSTED LH #3 BRAKE AXLE + rh #1 AXLE WHEEL BEARINGS STRAIGHTENED RH ##1 AXLE FRONT MUD GUARD BRACKET REPLACED D/G FLIP SIGN REPLACED 7 PIN ELECTRICAL SOCKET SECURED MARKER PLATES REPLACED LH NUMBER PLATE LIGHT				

Vehicle Details

Registration	234QXK	Next Service		Litres	
Make	KRUEGER	Rego Due	29/01/2023	Trans	N/A
Model	40' RETRACTABLE	Engine #		Air	No
Model Series		VIN	6FH9079GAEM015083	Cyl	0
Model Code		Build Date		Body	SKEL
Colour	BLUE	Odometer	71175	Prod	

Invoice No.	Date	Odometer	Description	Type
FURTHER ACTION REQUIRED - TYRE TREAD GETTING LOW POSITION 9 & 10				
50244	03/08/2020	5279	A SERVICE	Invoice
DATE WORK CARRIED OUT: 03/08/2020 WORK CARRIED OUT: CARRIED OUT A SERVICE AS ER HVW SERVICE SHEET ADJUST LHF WHEEL BEARING				
50062	17/07/2020	24973	A & C SERVICE	Invoice
DATE WORK CARRIED OUT: 17/07/2020 WORK CARRIED OUT: CARRIED OUT SERVICE A & C SERVICE REPLACED BOTH CLEAR REFLECTORS ON FRONT OF TRAILER PICKED UP AND DROPPED OFF TRAILER Requirements for next service are - INSPECT NUMBER PLATE LIGHT FLICKERING				