



Vehicle History

Vehicle Details

Registration	235QXK	Next Service	Litres	
Make	KRUEGER	Rego Due	Trans	N/A
Model	40' RETRACTABLE	Engine #	Air	No
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	SKEL
Colour		Odometer	Prod	

Invoice No.	Date	Odometer	Description	Type
61282	24/07/2025	78153	REPAIR DEFECT	Invoice
<p>PARKED TRAILER IN WORKSHOP CHECKED OUT DEFECTS REMOVED AND LUBRICATED BOLT, FIT BOLT TO LF LANDING LEG SUPPORT REPLACED LF #1 AND #2 SHOCK ABSORBERS RETURNED TO SHED 24 ***RECEIVE A \$25 DISCOUNT FOR ANY POSITIVE GOOGLE REVIEW ON OUR COMPANY GOOGLE WEBPAGE - HEAVY VEHICLE WORKSHOP*** <u>HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE THE STORE FOR PRICING ON - 07 3260 8950</u></p>				

61025	03/06/2025	73230	A SERVICE	Invoice
<p>PARK TRAILER IN WORKSHOP CARRY OUT A SERVICE AS PER SERVICE SHEET APPLY AIR TO TRAILER TEST LIGHTING FUNCTION LIFT TRAILER WITH HOIST CHECK WHEEL BEARINGS FOR MOVEMENT CHECK SUSPENSION COMPONENTS CHECK KING PIN BOLT TENSION CHECK SKID PLATE CHECK THE UNDERCARRIAGE OF THE TRAILER CARRY OUT GREASING OF AXLES CARRY OUT ADJUSTMENT OF BRAKES LOWER TRAILER CHECK WHEEL TENSION CHECK WHEEL BEARING GREASE FOR CONTAMINANTS CHECK ALL LIVERY INCLUDING MUDFLAPS AND DECAL INSPECT MARKER PLATES INCLUDING CON SIGN, CHEVRONS, AND OVERTAKE SIGNAGE CHECK TOP DECK OF TRAILER FOR ALL FUNCTIONALITY APPLY SERVICE STICKER COMPLETE PAPERWORK CLEAN WORK AREA MOVE TRAILER OUT OF WORKSHOP NOTE ML + RR SHOCKS WEARING - MONITOR UNDERSIDE OF FLOOR SURFACE RUST GREASE ROLLER AND SLACK ADJUSTERS SPRAY RUNNERS - OKAY <u>HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND</u></p>				

Vehicle Details

Registration	235QXK	Next Service	Litres	
Make	KRUEGER	Rego Due	Trans	N/A
Model	40' RETRACTABLE	Engine #	Air	No
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	SKEL
Colour		Odometer	Prod	

Invoice No.	Date	Odometer	Description	Type
-------------	------	----------	-------------	------

**MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.
PHONE THE STORE FOR PRICING ON - 07 3260 8950**

RECEIVE A \$25 DISCOUNT FOR ANY POSITIVE GOOGLE REVIEW ON OUR COMPANY GOOGLE WEBPAGE - HEAVY VEHICLE WORKSHOP

60706	20/03/2025	60585	C SERVICE	Invoice
-------	------------	-------	-----------	---------

PARK VEHICLE IN WORKSHOP
 CARRY OUT C SERVICE AS PER SERVICE SHEET
 CARRY OUT WALK AROUND VISUAL INSPECTION
 SECURE HOIST ON TRUCK
 CHECK ALL LIGHTS INCLUDING ALL REVERSE LAMPS AND BEEPERS
 CHECK WIPER AND WASHER OPERATION
 CHECK BATTERY LEVELS, TERMINALS AND CLAMPS
 LIFT CAB/BONNET TO ACCESS ENGINE BAY
 REPLACE CABIN AND ENGINE AIR FILTERS
 CHECK ALL BELTS AND MOUNTS
 LIFT TRUCK ON HOIST
 CARRY OUT VISUAL INSPECTION OF UNDERCARRIAGE (DRIVE LINE AND SUSPENSION COMPONENTS)
 DRAIN ENGINE OIL AND CHANGE FILTER
 ADJUST BRAKES AND CHECK BRAKE THICKNESSES
 CHECK AND ADJUST CLUTCH IF APPLICABLE
 CHECK GEARBOX OIL LEVEL AND QUALITY REPLACE IF REQUIRED
 CHECK DIFF OIL LEVEL AND QUALITY REPLACE IF REQUIRED
 CARRY OUT GREASING OF TRUCK
 LOWER TRUCK
 FIL ENGINE OIL AND CHECK ENGINE OIL
 TOP-UP COOLANT IF REQUIRED
 LOWER CAB/BONNET AND SECURE IN PLACE
 FIT SERVICE STICKER
 COMPLETE PAPERWORK
 REMOVE HOIST
 NOTE
 CRACK AND RUST REPAIRS
 REMOVE RHS ROLLER BOX
 CLEAN UP HOUSING AND SHIMS
 REMOVED LHS ROLLER BOX FOR SAMPLE PIN - ALSO NEEDS REPLACING
 CLEAN LHS HOUSING
 FIT NEW PINS TO HOUSING AND FIT TO TRAILER
 TIGHTEN ALL BOLTS AND GREASE PINS
 FIT ROLLER TO BOX AND BOX TO TRAILER
 TESTED OPERATION - ALL OKAY
 REPLACED RH FRONT SIDE MARKER LIGHT HOUSING AND STRAIGHTENED BRACKET
 SHORTENED RH REAR MUDFLAP
 LUBRICATED TWIST LOCKS
 REPAIRED LH FRONT LIGHT WIRING

60637	27/02/2025	60585	DEFECTS	Invoice
-------	------------	-------	---------	---------

COLLECTED TRAILER AND PARKED IN WORKSHOP
 REMOVED DAMAGED MUDGUARD
 REWELD REAR LEFT BROKEN MUD GUARD BRACKET

Vehicle Details

Registration	235QXK	Next Service	Litres	
Make	KRUEGER	Rego Due	Trans	N/A
Model	40' RETRACTABLE	Engine #	Air	No
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	SKEL
Colour		Odometer	Prod	

Invoice No.	Date	Odometer	Description	Type
			WELDED CRACKS ON REAR BROKEN ANGLE IRON BRACES REPLACE LEFT BACK GUARD REPLACE 2 MUDFLAPS	
60382	09/01/2025	60585	LUBE TWIST LOCKS	Invoice
			LUBE TWIST LOCKS INSPECT BROKEN WELD REQUESTED TRAILER TO BE RETURNED TO FIX DEFECTS <u>HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE COREY FOR PRICING ON - 07 3260 8950</u>	
59768	28/08/2024	47818	A SERVICE	Invoice
			PARK TRAILER IN WORKSHOP CARRY OUT A SERVICE AS PER SERVICE SHEET APPLY AIR TO TRAILER TEST LIGHTING FUNCTION LIFT TRAILER WITH HOIST CHECK WHEEL BEARINGS FOR MOVEMENT CHECK SUSPENSION COMPONENTS CHECK KING PIN BOLT TENSION CHECK SKID PLATE CHECK THE UNDERCARRIAGE OF THE TRAILER CARRY OUT GREASING OF AXLES CARRY OUT ADJUSTMENT OF BRAKES LOWER TRAILER CHECK WHEEL TENSION CHECK WHEEL BEARING GREASE FOR CONTAMINANTS CHECK ALL LIVERY INCLUDING MUDFLAPS AND DECAL INSPECT MARKER PLATES INCLUDING CON SIGN, CHEVRONS, AND OVERTAKE SIGNAGE CHECK TOP DECK OF TRAILER FOR ALL FUNCTIONALITY APPLY SERVICE STICKER COMPLETE PAPERWORK CLEAN WORK AREA MOVE TRAILER OUT OF WORKSHOP REPLACED FRONT AIR COUPLINGS REPLACED REAR D/G BOOKLET REPAIRED LH FRONT SIDE MARKER LIGHT BRACKET REPLACED RH FRONT LIGHT HOUSING RETURNED TRAILER TO SHED 24 <u>HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE JEFF FOR PRICING ON - 07 3260 8950</u>	
59136	24/04/2024	30521	LABOUR - BUCCINI	Invoice

Vehicle Details

Registration	235QXK	Next Service	Litres	
Make	KRUEGER	Rego Due	Trans	N/A
Model	40' RETRACTABLE	Engine #	Air	No
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	SKEL
Colour		Odometer	Prod	

Invoice No.	Date	Odometer	Description	Type
-------------	------	----------	-------------	------

CARRIED OUT A SERVICE
SLIDE PADS ON TRAILER FOR LIFTER CRACKED AND WORN

HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE JEFF FOR PRICING ON - 07 3260 8950

58302	07/12/2023	30521	SHOWED DRIVER HOW TRAILER	Invoice
-------	------------	-------	---------------------------	---------

TRAVEL TO BUCCINI YARD
SHOWED DRIVER HOW TRAILER LOCKING PIN WORKS

HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.

58303	06/12/2023	30509	REPLACE RHR TYRES X 2	Invoice
-------	------------	-------	-----------------------	---------

STRIP + FIT X 2
REPLACED BOTH RHR TYRES

HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.

58011	02/11/2023	27971	C SERVICE	Invoice
-------	------------	-------	-----------	---------

PARK VEHICLE IN WORKSHOP

CARRY OUT C SERVICE AS PER SERVICE SHEET
CARRY OUT WALK AROUND VISUAL INSPECTION
SECURE HOIST ON TRUCK
CHECK ALL LIGHTS INCLUDING ALL REVERSE LAMPS AND BEEPERS
CHECK WIPER AND WASHER OPERATION
CHECK BATTERY LEVELS, TERMINALS AND CLAMPS
LIFT CAB/BONNET TO ACCESS ENGINE BAY
REPLACE CABIN AND ENGINE AIR FILTERS
CHECK ALL BELTS AND MOUNTS
LIFT TRUCK ON HOIST
CARRY OUT VISUAL INSPECTION OF UNDERCARRIAGE (DRIVE LINE AND SUSPENSION COMPONENTS)
DRAIN ENGINE OIL AND CHANGE FILTER
ADJUST BRAKES AND CHECK BRAKE THICKNESSES
CHECK AND ADJUST CLUTCH IF APPLICABLE
CHECK GEARBOX OIL LEVEL AND QUALITY REPLACE IF REQUIRED
CHECK DIFF OIL LEVEL AND QUALITY REPLACE IF REQUIRED

Vehicle Details

Registration	235QXK	Next Service	Litres	
Make	KRUEGER	Rego Due	Trans	N/A
Model	40' RETRACTABLE	Engine #	Air	No
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	SKEL
Colour		Odometer	Prod	

Invoice No.	Date	Odometer	Description	Type
			CARRY OUT GREASING OF TRUCK LOWER TRUCK FIL ENGINE OIL AND CHECK ENGINE OIL TOP-UP COOLANT IF REQUIRED LOWER CAB/BONNET AND SECURE IN PLACE FIT SERVICE STICKER COMPLETE PAPERWORK REMOVE HOIST	
57285	18/07/2023	20163	A SERVICE	Invoice
			COLLECTED TRAILER FROM BUCCINI YARD CARRY OUT A SERVICE AS PER SERVICE SHEET <ul style="list-style-type: none">• APPLY AIR TO TRAILER• TEST LIGHTING FUCTION• LIFT TRAILER WITH HOIST• CHECK WHEEL BEARINGS FOR MOVEMENT• CHECK SUSPENSION COMPONENTS• CHECK KING PIN BOLT TENSION• CHECK SKID PLATE• CHECK UNDERCARAGE OF TRAILER• CARRY OUT GREASING OF AXLES• CARRY OUT ADJUSTMENT OF BRAKES• LOWER TRAILER• CHECK WHEEL TENSION• CHECK WHEEL BEARING GREASE FOR CONTAMINENTS• CHECK ALL LIVERY INCLUDING MUDFLAPS AND DECAL• INSPECT MARKER PLATES INCLUDING CON SIGN, CHEVERONS AND OVER TAKE SIGNAGE• CHECK TOP DECK OF TRAILER FOR ALL FUNCTIONALITY• APPLY SERVICE STICKER• COMPLETE PAPER WORK• CLEAN WORK AREA• MOVE TRAILER OUT OF WORKSHOP CHECKED LIGHTS TWIST LOCKS AND GREASED CHECK WHEEL BEARINGS - ONE LOOSE - ADJUSTED RETURNED TO BUCCINI YARD	
56311	27/03/2023	9189	A SERVICE	Invoice
			BROUGHT VEHICLE INTO WORKSHOP CARRIED OUT A SERVICE REPLACED LHS MARKER LIGHT HOUSING	
55733	11/01/2023	3590	TRAILER BRAKES NOT RELEASING	Invoice
			TRAILER BRAKES NOT RELEASING CHECKED AND FOUND AIRBAGS NOT INFLATING RESET AIRBAGS AND TESTED ALL OK	

Vehicle Details

Registration	235QXK	Next Service	Litres	
Make	KRUEGER	Rego Due	Trans	N/A
Model	40' RETRACTABLE	Engine #	Air	No
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	SKEL
Colour		Odometer	Prod	

Invoice No.	Date	Odometer	Description	Type
55325	11/11/2022		C SERVICE	Invoice
COLLECTED VEHICLE FROM SHED 24				
BROUGHT INTO WORKSHOP				
CARRIED OUT C SERVICE STRAIGHTENED RH #1 + #2 SIDE LIGHT BRACKETS WELDED / REPAIRED LH CHASSIS SLIDE PIN BRACKET REMOVED OLD LABEL HOLDERS REMOVED WHEELS, BRAKE DRUMS AND INSPECTED - WORN OUT FIT NEW ONES REMOVED HUBS INSPECTED BRAKE SHOES - WORN OUT - FIT NEW ONES CLEANED HUBS WASHED BEARINGS REMOVED AND REPLACED ROLLER PIN PACKED WHEEL BEARINGS AND HUBS WITH GREASE FITTED HUBS, DRUMS AND WHEELS CHECKED / REPLACED U/S RHS LED / CLEARANCE LAMPS X 2 RECHECKED ALL - LIGHTING OK EXCEPT RHR INSIDE LAMP (RED / STOP - TAIL - FLASHER) SOME LENS ARE OUT - ON ORDER PULLED APART CHASSIS SLIDE REPAIRED SLIDE PIN HOLES REPAIRED SLIDE WEAR PAD AT SLIDE PIN GROUND WELDS AND CHECKED FOR STRAIGHTNESS REPLACED CHASSIS SLIDE LOCKING PINS RE-FITTED AND WELDED STOPPER BLOCK CLEANED WELDS WITH DIE GRINDER REPLACED D/G FLIP SIGN FITTED RH AMBER REFLECTORS REPLACED FEMALE FRONT AIR COUPLING REPLACED RH INSIDE STOP/TAILLIGHT REPLACED HUBOMETER DROVE BACK TO SHED 24				
53985	06/04/2022	0	A SERVICE	Invoice
6/4/2022 - CARRIED OUT A SERVICE ADJUSTED ONE WHEEL BEARING REMOVED AND REPLACED 3RD AXLE RHS MUDFLAP REMOVED DAMAGED RUBER BUMP STOPS AT BACK OF TRAILER CUT NEW BUMP STOPS TO SIZE AND DRILLED NEW MOUNTING HOLES STRAIGHTENED BENT MOUNTING STUD FOR BUMP STOPS WITH OXY FIT BUMP STOPS TO TRAILER - ALL OK REMOVED AND REPLACED FRONT LHS AND REAR RHS AIR BAGS 7/4/2022 - REMOVED AND REPLACED ALL LEFT OVER AIR BAGS - FAILED TESTED FOR LEAKS - ALL OK REPLACED DANGEROUS GOODS SIGN AND BUCCINI MUDFLAP WITH SECOND HAND PARTS FIT FLAT AND SPRING WASHERS TO TO REAR AIR TANK BOLTS - LOOSE NOTE: HUBOMETER DOES NOT WORK PARKED TRAILER ON STREET FOR COLLECTION				
53694	14/02/2022	129689	TRAILER PLUG	Invoice

Vehicle Details

Registration	235QXK	Next Service	Litres	
Make	KRUEGER	Rego Due	Trans	N/A
Model	40' RETRACTABLE	Engine #	Air	No
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	SKEL
Colour		Odometer	Prod	

Invoice No.	Date	Odometer	Description	Type
14/2/2022 REPLACED TRAILER LIGHT SOCKET REPLACED FRONT RIGHT SIDE MARKER FOUND LHS MARKER LAMP MISSING AND PLUG BASE SOCKET HAD BEEN DAMAGED AND WIRING LOOSE AT REAR REPLACE SUZIE COILS				
53522	13/01/2022	126609	CHASSIS SLIDE FAULT	Invoice
CHECKED FOR GRINDING NOISE AT CHASSIS SLIDE FOUND RHS REAR ROLLER PIN OUT OF ALIGNMENT AND MISSING SHIMS SECURED AIR LINES AND ELECTRICAL CABLE AT FRONT OF TRAILER REMOVED RHS REAR TRAILER SLIDE PIN REMOVED SLIDE HOUSING FROM TRAILER AND FIT NEW PIN TO HOUSING TORQUED BOLT AND FILLED WITH GREASE TESTED OPERATION - ALL OK				
53408	21/12/2021	124822	CARRY OUT A SERVICE	Invoice
COLLECTED TRAILER FROM SHED 24 AND RETURNED TO WORKSHOP CARRIED OUT A SERVICE ON TRAILER REPLACED MISSING CLEAR REFLECTOR DEFECTS: REAR BUMP STOP RUBBERS WORN (MONITOR) DANGEROUS GOODS SIGN MISSING				
53351	06/12/2021	123336	REMOVED SHIMS	Invoice
REMOVED SHIMS ON EACH SIDE ABOVE ROLLERS ON BACK OF TRAILER TO STOP ROLLER HOUSING RUBBING				
52828	09/09/2021	115495	CARRY OUT C SERVICE	Invoice
CARRIED OUT C SERVICE ON TRAILER REPLACED KING PIN AND BOLTS REPLACED DOCK LEVELING VALVE REFITTED RHS FRONT TWIST LOCK AND REPLACED LHS TWIST LOCK REPLACED RHS 1ST AND 3RD AXLE SHOCK ABSORBERS REPLACED RHS 1ST AND 3RD AXLE TRAILER ARM BOLT WASHERS AND RETENSIONED BOLTS REPLACED AND SIDE MARKER LIGHTS TESTED - ALL OK				
52613	05/08/2021	0	MISSING ROLL PIN	Invoice
REMOVED AND REPLACED PINS AND ROLLERS GREASED UNIT - ALL OK				
52588	02/08/2021	112603	TRAILER EXTENSION REPAIRS	Invoice
INVESTIGATE NOISE AT REAR OF TRAILER WHEN EXTENDING OUT FOUND PIN WAS NOT FULLY IN WHEN EXTENDING THE TRAILER				

Vehicle Details

Registration	235QXK	Next Service	Litres	
Make	KRUEGER	Rego Due	Trans	N/A
Model	40' RETRACTABLE	Engine #	Air	No
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	SKEL
Colour		Odometer	Prod	

Invoice No.	Date	Odometer	Description	Type
THIS CAUSED A LIP ON THE EDGE GROUND DOWN SHAMFER OF AND TESTED OK NOTE: PHOTO'S SENT FOR REFERENCE				
52411	02/07/2021	106364	REPLACE DANGEROUS GOODS SIGN	Invoice
VEHICLE CAME IN WITH DAMAGED DANGEROUS GOOD SIGN SIGN WAS NOT REPAIRABLE - REMOVED AND REPLACED DANGEROUS GOOD SIGN VEHICLE ALL OK				
52226	08/06/2021	0	INSPECT FAILED 20/40 LOCKING PIN	Invoice
VEHICLE CAME IN WITH 20/40 SLIDE LOCK PIN SNAPPED REMOVED BROKEN PIN FROM HOUSING UNBOLTED THE REST OF THE PIN FROM SLACK ADJUSTER REMOVED REMAINING SHAFT AND SPRING INSPECTED AND GREASED UNIT REPLACED LOCKING PIN REASSEMBLED AND TESTED - ALL OK				
51634	04/03/2021	96319	INSPECT POSSIBLE DAMAGE TO	Invoice
DATE WORK CARRIED OUT: 04/03/2021 WORK CARRIED OUT: INSPECTED CONTAINER LOCK FOR DAMAGE AFTER GETTING CAUGHT, FOUND UNIT TO HAVE A MINOR PAINT SCRATCH, NO ISSUE WITH FUNCTIONALITY FOUND. AIR LEAK FROM AIR BAG CONTROL VALVE FOUND, TIGHTENED TO REDUCE LEAK, SEAL REQUIRED TO STOP LEAK				
51200	07/01/2021	89415	A SERVICE	Invoice
DATE WORK CARRIED OUT: 07/01/2021 WORK CARRIED OUT: CARRIED OUT A SERVICE DEFECTS NOTED <ul style="list-style-type: none">- L/H/M BOTH TYRES U/S- L/H/F OUTER TYRES U/S- MANUAL RIDE HEIGHT VALVE LEAKING- FRONT LIGHT SOCKET MISSING PINS				
50671	14/10/2020	81108	LIGHTING FAULT	Invoice
DATE WORK CARRIED OUT: 14/10/2020				

Vehicle Details

Registration	235QXK	Next Service	Litres	
Make	KRUEGER	Rego Due	Trans	N/A
Model	40' RETRACTABLE	Engine #	Air	No
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	SKEL
Colour		Odometer	Prod	

Invoice No.	Date	Odometer	Description	Type
<div> <div>WORK CARRIED OUT:</div> <div>INSPECT LIGHTING FAULT</div> <div>FOUND AND REPLACED 2 X FAULTY CLEARANCE LIGHTS AS REQUIRED</div> </div>				
50732	13/10/2020	81108	A SERVICE	Invoice
<div> <div>DATE WORK CARRIED OUT: 13/10/2020 & 16/10/2020</div> <div> <div>WORK CARRIED OUT:</div> <div>13/10</div> <div>CARRIED OUT A SERVICE AS PER HVW SERVICE SHEET</div> <div>REQUIRES REPAIRS</div> <div>L/H 2ND TYRES LOW</div> <div>SEVERAL LIGHT BRACKETS U/S</div> <div>AIRBAG</div> <div>MARKER PLATES SLIGHTLY DAMAGED</div> <div>R/H ROLLER MISSING</div> </div> <div> <div>16/10</div> <div>FIT NEW PIN AND ROLLER ASSEMBLY TO R/H/R OF TRAILER.</div> </div> </div>				