

Registration 237QXK Next Service 30/10/2020 Litres

MakeKRUEGERRego Due29/01/2021TransN/AModelATM OVER 4.5TEngine #AirYes

Model Series VIN 6FH9079GAEM015086 Cyl 0

Model CodeBuild Date2014BodyTRAILERColourBLUEOdometer55272Prod2014

| Invoice No. | Date | Odometer | Description | Туре |
|-------------|------------|----------|-------------------|---------|
| 60326 | 20/12/2024 | 55272 | STICKY TWIST LOCK | Invoice |

INSPECT STICKY TWIST LOCK AND LUBRICATE

CHECK ALL OTHER TWIST LOCKS AND LUBRICATE

TEST OPERATION - ALL OKAY

SEND DRIVER AWAY WITH VEHICLE

HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD -

STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.

PHONE CHRIS FOR PRICING ON - 07 3260 8950

60094 06/11/2024 49638 TWIST LOCK Invoice

REPLACED TWIST LOCK

HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD -

STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.

PHONE JEFF FOR PRICING ON - 07 3260 8950

60024 24/10/2024 49638 A SERVICE Invoice

PARK TRAILER IN WORKSHOP

CARRY OUT A SERVICE AS PER SERVICE SHEET

APPLY AIR TO TRAILER

TEST LIGHTING FUNCTION

LIFT TRAILER WITH HOIST

CHECK WHEEL BEARINGS FOR MOVEMENT

CHECK SUSPENSION COMPONENTS

CHECK KING PIN BOLT TENSION

CHECK SKID PLATE

CHECK THE UNDERCARRIAGE OF THE TRAILER

CARRY OUT GREASING OF AXLES

CARRY OUT ADJUSTMENT OF BRAKES

LOWER TRAILER

CHECK WHEEL TENSION

CHECK WHEEL BEARING GREASE FOR CONTAMINANTS

CHECK ALL LIVERY INCLUDING MUDFLAPS AND DECAL

INSPECT MARKER PLATES INCLUDING CON SIGN, CHEVRONS, AND OVERTAKE SIGNAGE

CHECK TOP DECK OF TRAILER FOR ALL FUNCTIONALITY

APPLY SERVICE STICKER

COMPLETE PAPERWORK

CLEAN WORK AREA

MOVE TRAILER OUT OF WORKSHOP

60029 24/10/2024 49638 DEFECTS Invoice

Registration 237QXK Next Service 30/10/2020 Litres

MakeKRUEGERRego Due29/01/2021TransN/AModelATM OVER 4.5TEngine #AirYes

Model SeriesVIN6FH9079GAEM015086Cyl0Model CodeBuild Date2014BodyTRAILER

Model CodeBuild Date2014BodyTRAILERColourBLUEOdometer55272Prod2014

Invoice No. Date Odometer Description Type

CARRY OUT REPLACEMENT OF KING PIN

CARRY OUT REPLACEMENT OF MISSING BOLT IN RHF TWIST LOCK

CARRY OUT REPLACEMENT OF RHF AMBER REFLECTOR

CARRY OUT REPLACEMENT OF RHF LIGHT HOUSING

CARRY OUT NEEDLING AND RUST CONVERTING OF RUST ONTOP OF SKID PLATE

CARRY OUT REPLACEMENT OF LHF LIGHT HOUSING

CARRY OUT STRAIGHTENING OF BENT RHF CLEARANCE LIGHT BRACKET

CARRY OUT REPLACEMENT OF DAMAGED LH #3 CLEARANCE LIGHT

CARRY OUT REPLACEMENT OF DAMAGED TAIL LIGHT ASEMBLY

CARRY OUT REPLACEMENT OF LEAKING FEMALE AIR FITTING

RETENSION AND REPAIR RH #3 MUDGUARD

CARRY OUT REPLACEMENT OF 3RD AXLE TRAILING ARM BUSHES

REFLECTOR REPLACED

SIDE LIGHT REPLACED

TAIL LIGHT REPLACED

REPLACED BOTH #3 AXLE BUSHES

HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD -

STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.

PHONE JEFF FOR PRICING ON - 07 3260 8950

59593 22/07/2024 41331 A SERVICE Invoice

PARK TRAILER IN WORKSHOP

CARRY OUT A SERVICE AS PER SERVICE SHEET

APPLY AIR TO TRAILER

TEST LIGHTING FUNCTION

LIFT TRAILER WITH HOIST

CHECK WHEEL BEARINGS FOR MOVEMENT

CHECK SUSPENSION COMPONENTS

CHECK KING PIN BOLT TENSION

CHECK SKID PLATE

CHECK THE UNDERCARRIAGE OF THE TRAILER

CARRY OUT GREASING OF AXLES

CARRY OUT ADJUSTMENT OF BRAKES

LOWER TRAILER

CHECK WHEEL TENSION

CHECK WHEEL BEARING GREASE FOR CONTAMINANTS

CHECK ALL LIVERY INCLUDING MUDFLAPS AND DECAL

INSPECT MARKER PLATES INCLUDING CON SIGN, CHEVRONS, AND OVERTAKE SIGNAGE

CHECK TOP DECK OF TRAILER FOR ALL FUNCTIONALITY

APPLY SERVICE STICKER

COMPLETE PAPERWORK

CLEAN WORK AREA

MOVE TRAILER OUT OF WORKSHOP

NOTE

AIR BAGS BEGINNING TO PERISH - MONITOR

HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD -

STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.

PHONE JEFF FOR PRICING ON - 07 3260 8950

Registration 237QXK Next Service 30/10/2020 Litres

Make KRUEGER Rego Due 29/01/2021 **Trans** N/A Model Engine # ATM OVER 4.5T Air Yes **Model Series** VIN 6FH9079GAEM015086 Cyl 0

Model CodeBuild Date2014BodyTRAILERColourBLUEOdometer55272Prod2014

| Invoice No. | Date | Odometer | Description | Туре |
|-------------|------------|----------|-------------|---------|
| 59123 | 23/04/2024 | 35163 | C SERVICE | Invoice |

CARRIED OUT TRAILER C SERVICE

GAINED ACCESS TO HUB FILL PLUGS

REPACK ALL HUBS

ADJUST WHEEL BEARINGS + FIT LOCK WASHERS & OUTER NUTS

FIT HUBCAP + LR&LM WHEELS

ADJUST BRAKES

RESET BAGS

TENSIONED ALL WHEELNUTS ON LHS

REMOVED REAR TAIL LIGHTS WIRING + AIR LINES FROM DOCKLEVELLING VALVE + DOCK RUBBERS

OXY CUT REAR TAIL LIGHT BRACKETS

REMOVED RUST FROM REAR TWIST LOCK BEAM + REAR BAR

GROUND ALL WELDS

REMOVED SEALANT FROM TAIL LIGHT BAR JOINTS

SPRAYED RUST CONVERTER ON ALL RUST SPOTS

WELDED NEW TAIL LIGHT BRACKETS TO REAR TWIST LOCK BEAM

WELDED NEW SIDE LIGHT BRACKET + WIRING MOUNTS

DRILLED HOLES IN NEW BRACKETS FOR TAIL LIGHTS

PAINTED REAR TAIL LIGHT BRACKETS + BAR

FITTED TAIL LIGHTS AND NEW SIDE LIGHTS

FITTED AIR LINES TO DOCK LEVELLING VALVE

SECURED WIRING + AIR LINES

TESTD ALL LINES - ALL OKAY

TRIED TO FIT DOCK RUBBERS - FOUND BOLTS WELDED ON WERE TOO SHORT.

CUT BOLTS OFF + WELDED 4 NEW BOLTS

PAINTED AROUND WELDS

FIT NEW DOCK RUBBERS

PARK TRAILER IN WORKSHOP

CARRY OUT C SERVICE AS PER SERVICE SHEET

APPLY AIR TO TRAILER

TEST LIGHTING FUNCTION

LIFT TRAILER WITH HOIST

CHECK SUSPENSION COMPONENTS

CHECK KING PIN BOLT TENSION

CHECK SKID PLATE

CHECK THE UNDERCARRIAGE OF THE TRAILER

CARRY OUT GREASING OF AXLES

CARRY OUT DE-ADJUSTMENT OF BRAKES

REMOVE HUB CAPS AND REMOVE BEARING ADJUSTMENT NUTS

REMOVE BEARINGS FROM HUBS

CLEAN STUB AXLES AND APPLY NEW FILM OF GREASE TO STUB AXLES

CLEAN BEARINGS IN TURBO WASH

CLEAN HUBS OF GREASE AND REPACK HUBS AS REQUIRED

REMOVED BEARINGS FROM PARTS WASHER BLOW OUT WITH AIR AND REPACK BEARINGS

INSTALL BEARINGS TO HUBS

INSTALL INNER HUB SEALS

INSTALL HUBS TO THE TRAILER AND TENSION-BEARING ADJUSTMENT NUTS

SECURE BEARING ADJUSTMENT NUTS WITH RETAINERS

REINSTALL HUB CAPS TO AXLES AND TENSION HUB CAPS

CARRY OUT ADJUSTMENT OF BRAKES

LOWER TRAILER

Colour

Registration 237QXK Next Service 30/10/2020 Litres

Odometer

MakeKRUEGERRego Due29/01/2021TransN/AModelATM OVER 4.5TEngine #AirYes

Model SeriesVIN6FH9079GAEM015086Cyl0Model CodeBuild Date2014BodyTRAILER

Invoice No. Date Odometer Description Type

55272

Prod

2014

CHECK WHEEL NUT TENSION

CHECK ALL LIVERY INCLUDING MUDFLAPS AND DECAL

INSPECT MARKER PLATES INCLUDING CON SIGN, CHEVRONS, AND OVERTAKE SIGNAGE

CHECK TOP DECK OF TRAILER FOR ALL FUNCTIONALITY

APPLY SERVICE STICKER COMPLETE PAPERWORK

CLEAN WORK AREA

MOVE TRAILER OUT OF WORKSHOP

BLUE

HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD -STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE JEFF FOR PRICING ON - 07 3260 8950

58613 31/01/2024 28824 DAMAGED TWISTLOCK Invoice

REMOVED DAMAGED TWISTLOCK

REPLACED WITH A 2ND HAND TWISTLOCK ON THE PARTS SHELF

HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.

58505 17/01/2024 24051 INSPECTED GUARD FOR DAMAGE Invoice

INSPECTED GUARD FOR DAMAGE NONE FOUND, WHERE THE WASHERS PRESS ON IT. RESURECED THE MUDGUARD WITH 2 BOLTS. NUTS AND WASHERS

HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.

58167 22/11/2023 24051 A SERVICE Invoice

COLLECTED TRAILER FROM SHED 24

PARK VEHICLE IN WORKSHOP

CARRY OUT A SERVICE AS PER SERVICE SHEET

CARRY OUT WALK AROUND VISUAL INSPECTION

SECURE HOIST ON TRUCK

CHECK ALL LIGHTS INCLUDING ALL REVERSE LAMPS AND BEEPERS

CHECK WIPER AND WASHER OPERATION

CHECK BATTERY LEVELS, TERMINALS AND CLAMPS

LIFT CAB/BONNET TO ACCESS ENGINE BAY

CHECK ALL BELTS AND MOUNTS

LIFT TRUCK ON HOIST

CARRY OUT VISUAL INSPECTION OF UNDER CARRIAGE (DRIVE LINE AND SUSPENSION COMPONENTS)

ADJUST BRAKES AND CHECK BRAKE THICKNESSES

CHECK AND ADJUST CLUTCH IF APPLICABLE

CHECK GEAR BOX OIL LEVEL AND QUALITY

Model Code

Colour

Registration 237QXK

Make KRUEGER Model

BLUE

ATM OVER 4.5T **Model Series**

Engine # VIN

Rego Due 29/01/2021

Next Service

Build Date

Odometer

6FH9079GAEM015086

30/10/2020

2014

55272

Trans

Litres

N/A

Air Yes Cyl 0

TRAILER Body Prod 2014

Invoice No. Odometer **Description Date Type**

CHECK DIFF OIL LEVEL AND QUALITY

CARRY OUT GREASING OF TRUCK

LOWER TRUCK

CHECK ENGINE OIL

TOP UP COOLANT IF REQUIRED

LOWER CAB/BONNET AND SECURE IN PLACE

FIT SERVICE STICKER COMPLETE PAPERWORK

REMOVE AND REPLACED 4 X NEW TYRES

TENSIONED ALL WHEEL NUTS

RETURNED TRAILER TO SHED 24

HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE **TODAY FOR SIZING AND PRICING.**

C SERVICE Invoice 56078 27/03/2023

MOVED TRAILER INTO WORKSHOP

CARRIED OUT C SERVICE

REPLACED CLEAR REFLECTOR AT FRONT

FIT 2 X RED REFLECTORS ON REAR BAR

REPLACED 3 X SHOCK ABSORBERS

REPLACED HUBOMETER

NOTE-

LHS REAR INNER TYRE ON MINIMUM TREAD

REAR BUMP STOPS WORN OUT

FRIONT AXLE SUSPENSION WEAR PLATE CRACKING

55138 13/10/2022 135738 REPLACED MALE SUZI FITTING ON **Invoice**

REPLACED MALE SUZI FITTING ON TRAILER

55083 05/10/2022 134215 LIGHT SOCKET **Invoice**

REPLACED LIGHT SOCKET

REPLACE KING PIN ON TRAILER Invoice 54459 22/06/2022

REMOVED AND REPLACED KING PIN ON TRAILER

TORQUED KING PIN TO 190Nm

54344 03/06/2022 **SAFETY CHECK - ROLLED OVER TRAILER** Invoice 0

WENT DOWN TO YARD TO INSPECT THE ROLLED OVER TRAILER

REAR AXLE SHOCKIES LEAKING AND MIDDLE RH

LH RIMS SCUFFED

KING PIN VERY MINOR WEAR, BOLTS ARE TORQUED TO 190NM

EVERYTHING ELSE LOOK OK

Registration 237QXK Next Service 30/10/2020 Litres

MakeKRUEGERRego Due29/01/2021TransN/AModelATM OVER 4.5TEngine #AirYes

Model Series VIN 6FH9079GAEM015086 Cyl 0

Model CodeBuild Date2014BodyTRAILERColourBLUEOdometer55272Prod2014

| Invoice No. | Date | Odometer | Description | Туре |
|-------------|------------|----------|-------------|---------|
| 53984 | 06/04/2022 | 127332 | A SERVICE | Invoice |

COLLECTED TRAILER FROM SHED 24 AND PARK TRAILER IN WORKSHOP

CARRIED OUT A SERVICE

LHS 2ND TWIST LOCK HARD TO TURN - LUBED UP

DELIEVERED TRAILER BACK TO SHED 24

DEFECTS:

FRONT RHS OUTER TYRE NEARLY BALD AND INNER ON MINIMUM TREAD

REAR RHS TYRES ON MINIMUM TREAD

REAR BUMP STOPS WORN OUT

53446 29/12/2021 120050 CARRY OUT REPAIRS Invoice

TESTED OPERATION OF TRAILER LIGHTS

TRAILER BASE PINS BENT AND SNAPPED IN HOUSING

REMOVED AND REPLACED TRAILER PLUG

TESTED OPERATION OF LIGHTS - ALL OK

REMOVED RHS 1ST AXLE MUDGUARD

REMOVED DAMAGED MUDGUARD BRACKET

HEATED AND STRAIGHTENED BRACKET

REFITTED AND WELDED RHS 1ST AXLE FRONT MUDGUARD BRACKET

PAINTED BRACKET

DRILLED NEW HOLE IN MUDGUARDS

FITTED NEW MUDGUARDS TO RHS 1ST AND 2ND AXLE

REMOVED LHS FRONT MUDFLAP AND ANTISAIL BRACKET

53409 21/12/2021 119665 CARRY OUT A & C SERVICE Invoice

COLLECTED TRAILER FROM SHED 24 AND RETURNED TO WORKSHOP

CARRIED OUT A AND C SERVICE ON TRAILER

REMOVED SAFETY ROPE (RHS) AND RHS FRONT TWIST LOCK

REMOVED DAMAGED SIDE LIGHT BRACKET AND FABRICATED NEW ONE

WELDED NEW BRACKET TO TWISTLOCK HOUSING

DRILLED HOLES FOR NEW LIGHT

TIGHTEN UP LOOSE SHOCK ABSORBER BOLTS

REMOVED AND REPLACE KING PIN - WORN

REFIT SIDE LIGHT HOUSING

REWIRED AND SECURED NEW SIDE LIGHT

52298 17/06/2021 106718 REPLACE SAFETY CABLE Invoice

REMOVED AND REPLACED WORN RHS SAFETY CABLE

51994 30/04/2021 103437 AIR BAG LEAKING/SHOCKY MOUNT Invoice

TRAILER CAME IN WITH LEAKING AIRBAG

INSPECTED RH FRONT AIRBAG - SPRAYED SOAPY WATER TO IDENTIFY FAILED AREA ON AIRBAG - FOUND NO LEAKS

PLUGGED IN WORKSHOP AIR INTO UNIT SUPPLY SIDE AND FOUND NO AIR LEAKS

SUPPLIED WORKSHOP AIR TO SIGNAL SERVICE AND FOUND FRONT RIGHT BOOSTER FAILED

WHILST TESTING AIR-BAGS AND FOUND RIGHT HAND REAR AXLE SHOCK ABSORBER HAD A CRACK IN THE TOP MOUNTING

DI-GRINDED THE CRACK DOWN AND CLEANED AREA FOR WELDING REPAIRS

WELDED CRACK ON UNIT AND PAINTED

REPLACE BOOSTER ON THE RH FRONT AXLE AND ADJUSTED TO FIT

ONCE REPLACED TESTED BOOSTER BY CONNECTING AIR TO SIGNAL JUNCTION - ALL OK NO LEAKS FOUND.

Registration 237QXK **Next Service**

30/10/2020 Litres Make KRUEGER Rego Due 29/01/2021 Trans N/A Model Engine # ATM OVER 4.5T Yes Air

VIN **Model Series** 6FH9079GAEM015086 Cyl 0

Model Code Build Date Body TRAILER 2014 Colour **BLUE** Odometer 55272 Prod 2014

Invoice No. **Date Odometer Description Type** 51652 05/03/2021 99315 **A SERVICE** Invoice

CARRY OUT A SERVICE. INCLUDES TRANSPORT TO AND FROM THE BUCCINI YARD

51442 18/02/2021 97679 LABOUR \$138.00 / HR Invoice

DATE WORK CARRIED OUT: 11/02/2021 - 18/02/2021

WORK CARRIED OUT:

REMOVED LANDING LEGS AND PUT TRAILER ON STANDS FITTED NEW LEGS AND CUT CENTRE ROLL BAR TO SUIT REMOVED OLD LANDING LEG SUPPORT BRACKETS WELDED ON SUPPORT BRACKETS TO LANDING LEGS FITTED CROSS BRACES PAINTED BRACKETS

51168 31/12/2020 93887 **A SERVICE** Invoice

DATE WORK CARRIED OUT: 30/12/2020

WORK CARRIED OUT: CARRIED OUT A SERVICE

50702 21/10/2020 89640 A & C SERVICES Invoice

DATE WORK CARRIED OUT: 20/10/2020 - 21/10/2020

WORK CARRIED OUT:

CARRIED OUT SERVICE A AS PER HVW SERVICE SHEET CARRIED OUT C SERVICE AS PER HVW SERVICE SHEET

STRAIGHTENED RH REAR TWIST LOCK HANDLE

REPLACED KING PIN & BOLTS

REMOVED LH #1AXLE LOWER SHOCK ABSORBER BROKEN BOLT

REPLACE SHOCK ABSORBER BOLT KIT REPLACED SPRING BRAKE REPLAY VALVE

CHECKED FOR AIR LEAKS

50007 **REPAIRS NOTED ON SERVICE** 03/07/2020 Invoice

DATE WORK CARRIED OUT: 02/07/2020 - 03/07/2020

WORK CARRIED OUT:

REPLACED L/H/R MUDGUARD

REPLACED BOTH MUDFLAPS

REPLACED L/H//R & R/H/M BRAKE BOOSTERS

REPLACED L/H/S MARKER LIGHT

TEMPORARILY REPAIRED R/H/F SIDE MARKER UNTIL IT CAN BE BROUGHT BACK IN TO REPLACE THE

Registration 237QXK Make KRUEGE Model ATM OVE

KRUEGER ATM OVER 4.5T

Rego Due 4.5T Engine # VIN

Next Service

30/10/2020 29/01/2021 Litres Trans

N/A Yes

6FH9079GAEM015086 **Air Cyl**

Cyl 0 Body TRAILER

Model Series Model Code Colour

BLUE BLUE Odometer

Build Date 2014 **Odometer** 55272

Prod 2014

Invoice No. Date Odometer Description Type

BRACKET