



Vehicle History

Vehicle Details

Registration	040QXV	Next Service	Litres	
Make	HAMMAR	Rego Due	Trans	N/A
Model	195S	Engine #	Air	No
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	SEMITRAILER
Colour		Odometer/Hr	Prod	2015

Invoice No.	Date	Odometer / Hours	Description	Type
61449	26/08/2025	303609/2860	DEFECTS	Invoice

Strip 2 crane extension cylinders and found excessive damage on the chrome rods and recommended replacing them with new ones. This was rejected and was asked to put them back together. Some seals were replaced, and it was reassembled and tested ok
Found 20-40 cam leaking - major
Test EBS/ABS fault on trailer
Connect Jaltest, found no power at first axle speed
Test wheel speed sensor

26/08/2025

Secured electrical cable along chassis
Secured ABS cable to axle
Secured Battery
Repaired air cleaner housing
Re-installed 20-40 rams with forklift
Supplied x2 circlips to hold eye of rams into pin
Fit x6 rear bolts into centre of rams as required
Test - all ok

*****PLEASE READ*****

WARRANTY ON PARTS ARE SUBJECT TO MANUFACTURERS TERMS AND CONDITIONS.

RECEIVE A \$25 DISCOUNT FOR ANY POSITIVE GOOGLE REVIEW ON OUR COMPANY GOOGLE WEBPAGE - HEAVY VEHICLE WORKSHOP

HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE THE STORE FOR PRICING ON - 07 3260 8950

61029	03/06/2025	298140/2860	EXCESS PAYMENT	Invoice
-------	------------	-------------	----------------	---------

REF: 3118124 CLAIM: 40289409

60847	22/04/2025	298140/2860	REPLACE BATTERY	Invoice
-------	------------	-------------	-----------------	---------

REPLACED BATTERY

HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND

Vehicle Details

Registration	040QXV	Next Service	Litres	
Make	HAMMAR	Rego Due	Trans	N/A
Model	195S	Engine #	Air	No
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	SEMITRAILER
Colour		Odometer/Hr	Prod	2015

Invoice No.	Date	Odometer / Hours	Description	Type
<u>PRICING.</u> <u>PHONE THE STORE FOR PRICING ON - 07 3260 8950</u> ***RECEIVE A \$25 DISCOUNT FOR ANY POSITIVE GOOGLE REVIEW ON OUR COMPANY GOOGLE WEBPAGE - HEAVY VEHICLE WORKSHOP***				

60681	13/03/2025	298140/2860	DEFECTS	Invoice
DROVE TO MEADOWBROOK INSPECTED DAMAGE CARRY OUT REPAIRS TO TRAILER DUE TO IMPACT DAMAGE, CARRY OUT WHEEL ALIGNMENT, REPLACEMENT OF 1 X RIM & 4 X TYRES ON FRONT AXLE, CARRY OUT REPLACEMENT OF OF LH FRONT GUARD AND STARIGHTENING OF GUARD POLES, CHECKED FOR AIRBAG FAULT REMOVED AIRBAG BYPASS HOSE TESTED OPERATION <u>HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.</u> <u>PHONE THE STORE FOR PRICING ON - 07 3260 8950</u> ***RECEIVE A \$25 DISCOUNT FOR ANY POSITIVE GOOGLE REVIEW ON OUR COMPANY GOOGLE WEBPAGE - HEAVY VEHICLE WORKSHOP***				

60536	12/02/2025	294451/2860	C SERVICE	Invoice
PARK TRAILER IN WORKSHOP CARRY OUT C SERVICE AS PER SERVICE SHEET APPLY AIR TO TRAILER TEST LIGHTING FUNCTION LIFT TRAILER WITH HOIST CHECK SUSPENSION COMPONENTS CHECK KING PIN BOLT TENSION CHECK SKID PLATE CHECK THE UNDERCARRIAGE OF THE TRAILER CARRY OUT GREASING OF AXLES CARRY OUT DE-ADJUSTMENT OF BRAKES REMOVE HUB CAPS AND REMOVE BEARING ADJUSTMENT NUTS REMOVE BEARINGS FROM HUBS CLEAN STUB AXLES AND APPLY NEW FILM OF GREASE TO STUB AXLES CLEAN BEARINGS IN TURBO WASH CLEAN HUBS OF GREASE AND REPACK HUBS AS REQUIRED REMOVED BEARINGS FROM PARTS WASHER BLOW OUT WITH AIR AND REPACK BEARINGS INSTALL BEARINGS TO HUBS INSTALL INNER HUB SEALS INSTALL HUBS TO THE TRAILER AND TENSION-BEARING ADJUSTMENT NUTS SECURE BEARING ADJUSTMENT NUTS WITH RETAINERS REINSTALL HUB CAPS TO AXLES AND TENSION HUB CAPS CARRY OUT ADJUSTMENT OF BRAKES LOWER TRAILER CHECK WHEEL NUT TENSION CHECK ALL LIVERY INCLUDING MUDFLAPS AND DECAL INSPECT MARKER PLATES INCLUDING CON SIGN, CHEVRONS, AND OVERTAKE SIGNAGE				

Vehicle Details

Registration	040QXV	Next Service	Litres	
Make	HAMMAR	Rego Due	Trans	N/A
Model	195S	Engine #	Air	No
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	SEMITRAILER
Colour		Odometer/Hr	Prod	2015

Invoice No.	Date	Odometer / Hours	Description	Type
			<p>CHECK TOP DECK OF TRAILER FOR ALL FUNCTIONALITY APPLY SERVICE STICKER COMPLETE PAPERWORK CLEAN WORK AREA MOVE TRAILER OUT OF WORKSHOP NOTE STRIP FRONT RIGHT BRAKES FOR SAMPLE REMOVE TANK BRACKETS FOR FABRICATOR TO WELD THEM REPAIRED DIESEL TANK BRACKETS CRACK REPAIRS ON SIDE LOADER CRACK REPAIRS ON SKID PLATE BACKING REPLACED THE TANK BRACKETS AFTER REPAIRS LUBRICATED CRANE SLIDES WITH GRAPHITE SPRAY REPLACED ALL AXLE BRAKE DRUMS AND BRAKE SHOES REPLACED REAR MARKER PLATES ADJUSTED FAN BELT REPAIRED RH TWIST LOCK HANDLE STRAIGHTENED MUDGUARD POLES SECURED AIRLINES AND ELECTRICAL CABLE @ CHASSIS AND CRANES REMOVED HYDRAULIC PUMP, ADAPTOR PLATE, DRIVE PLATE + FLYWHEEL REPLACED REAR MAIN SEAL FOUND BELL HOUSING CENTRE BOLTS LOOSE LOCTITE STUD IN BELL HOUSING AND TIGHTENED NUTS REFIT FLYWHEEL, DRIVE PLATE, ADAPTOR AND PUMP SECURE CRANE CHAIN GUARDS</p> <p><u>HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE COREY FOR PRICING ON - 07 3260 8950</u></p>	

60367	07/01/2025	291056/2667	DEFECTS	Invoice
			<p>LOOSEN MUDGUARD BRACKETS HIT GUARD POLES IN UNTIL IN CORRECT PLACE TIGHTEN CLAMP BOLTS ON BRACKET TESTED SOLENOID ON FRONT CRANE FOR UP TESTED AT 24K OHMS AND WHEN ACTIVATED GOES UP TO 87K OHMS TESTED ANOTHER AND DIDNT MOVE AT ALL WHEN OPERATING</p> <p><u>HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE COREY FOR PRICING ON - 07 3260 8950</u></p>	

60187	26/11/2024	285688/2667	DEFECTS	Invoice
			<p>CHECKED FOR AIR LEAK FOUND AIR LEAK IN LH #2 AXLE BRAKE BOOSTER TIGHTEN HOSE CLAMPS AND RE-CHECK - ALL OKAY RETURN TO SHED 24</p>	

Vehicle Details

Registration	040QXV	Next Service	Litres	
Make	HAMMAR	Rego Due	Trans	N/A
Model	195S	Engine #	Air	No
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	SEMITRAILER
Colour		Odometer/Hr	Prod	2015

Invoice No.	Date	Odometer / Hours	Description	Type
<u>HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE CHRIS FOR PRICING ON - 07 3260 8950</u>				

60144	14/11/2024	2775031/2667	test lifter chains	Invoice
-------	------------	--------------	--------------------	---------

SHOULD HAVE BEEN CHARGED TO JOB 59617

59864	02/10/2024	2775031/2667	A SERVICE	Invoice
-------	------------	--------------	-----------	---------

PARK TRAILER IN WORKSHOP CARRY OUT A SERVICE AS PER SERVICE SHEET APPLY AIR TO TRAILER TEST LIGHTING FUNCTION LIFT TRAILER WITH HOIST CHECK WHEEL BEARINGS FOR MOVEMENT CHECK SUSPENSION COMPONENTS CHECK KING PIN BOLT TENSION CHECK SKID PLATE CHECK THE UNDERCARRIAGE OF THE TRAILER CARRY OUT GREASING OF AXLES CARRY OUT ADJUSTMENT OF BRAKES LOWER TRAILER CHECK WHEEL TENSION CHECK WHEEL BEARING GREASE FOR CONTAMINANTS CHECK ALL LIVERY INCLUDING MUDFLAPS AND DECAL INSPECT MARKER PLATES INCLUDING CON SIGN, CHEVRONS, AND OVERTAKE SIGNAGE CHECK TOP DECK OF TRAILER FOR ALL FUNCTIONALITY APPLY SERVICE STICKER COMPLETE PAPERWORK CLEAN WORK AREA MOVE TRAILER OUT OF WORKSHOP NOTE REVERSE LIGHT LOOSE - ADJUSTED ENGINE REAR MAIN OIL SEAL - OIL LEAK ENGINE COOLANT LEVEL LOW - TOPPED UP R/S TAIL LIGHT BRACKET BROKEN REAR BUMPER SLIGHTL DENT L/S 2ND AND 3RD AXLE OUTER TYRE CUT TO CORD <u>HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE JEFF FOR PRICING ON - 07 3260 8950</u>				
--	--	--	--	--

59708	16/08/2024	271840/2667	BREAKDOWN	Invoice
-------	------------	-------------	-----------	---------

TRAVEL TO COOPERS PLAINS FOR BREAKDOWN INSPECT NOT RELEASING BRAKES CLAMPED BOOSTER LINES FOUND BACK FEEDING BOOSTER REMOVE AND REPLACE BOOSTER RETURN TO WORKSHOP COMPLETE PAPERWORK <u>HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD -</u>				
--	--	--	--	--

Vehicle Details

Registration	040QXV	Next Service	Litres	
Make	HAMMAR	Rego Due	Trans	N/A
Model	195S	Engine #	Air	No
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	SEMITRAILER
Colour		Odometer/Hr	Prod	2015

Invoice No.	Date	Odometer / Hours	Description	Type
<u>STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE JEFF FOR PRICING ON - 07 3260 8950</u>				

59668	06/08/2024	250693/2667	REMOVE AND REPLACE	Invoice
REMOVED AND REPLACED ALL AIRBAGS AS THEY WERE BADLY CRACKED. REMOVED AND REPLACED 6 WORN OUT SHOCKABSORBERS.				

59617	25/07/2024	250693/2667	B SERVICE	Invoice
--------------	-------------------	--------------------	------------------	----------------

PARK TRAILER IN WORKSHOP
CARRY OUT B SERVICE AS PER SERVICE SHEET
APPLY AIR TO TRAILER
TEST LIGHTING FUNCTION
LIFT TRAILER WITH HOIST
CHECK WHEEL BEARINGS FOR MOVEMENT
CHECK SUSPENSION COMPONENTS
CHECK KING PIN BOLT TENSION
CHECK SKID PLATE
CHECK THE UNDERCARRIAGE OF THE TRAILER
CARRY OUT GREASING OF AXLES
CARRY OUT ADJUSTMENT OF BRAKES
LOWER TRAILER
CHECK WHEEL TENSION
CHECK WHEEL BEARING GREASE FOR CONTAMINANTS
CHECK ALL LIVERY INCLUDING MUDFLAPS AND DECAL
INSPECT MARKER PLATES INCLUDING CON SIGN, CHEVRONS, AND OVERTAKE SIGNAGE
CHECK TOP DECK OF TRAILER FOR ALL FUNCTIONALITY
APPLY SERVICE STICKER
COMPLETE PAPERWORK
CLEAN WORK AREA
MOVE TRAILER OUT OF WORKSHOP
NOTE
FIXED LOOSE WIRES ON FRONT OF TRAILER
REMOVE CHAINS OFF TRAILER
REMOVE TWIST LOCK HANDLE
MAKE NEW HANDLE
WELD HANDLE ON, FIT AND PAINT
TRIED REMOVING COVER ON LEGS - CRIMPED ON
REMOVE COVER PLATE TO BE WELDED BACK ON
REMOVE AND REPLACE LANDING LEGS
TAKE NEW TWIST LOCKS TO ATTACH TO CHAINS
PREP LANDING LEGS FOR WELDING OF BRACKETS
BEND BRACKETS
ATTACH FITTINGS TO CHAINS
FIT CHAINS TO SWINGLIFT
FIT BOLTS TO PROTECTIVE COVER
TESTED OPERATION - ALL OKAY

HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE JEFF FOR PRICING ON - 07 3260 8950

Vehicle Details

Registration	040QXV	Next Service	Litres	
Make	HAMMAR	Rego Due	Trans	N/A
Model	195S	Engine #	Air	No
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	SEMITRAILER
Colour		Odometer/Hr	Prod	2015

Invoice No.	Date	Odometer / Hours	Description	Type
59007	02/04/2024	250693/2667	REPLACE REAR GUARD	Invoice
FITTED NEW MUDGUARD FITTED NEW BUCCINI MUD FLAP HAD TO CUT MUDFLAP TO SIT PROPERLY STRAIGHTENED THE POLE MOVED TRAILER TO SHED 24 <u>HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE JEFF FOR PRICING ON - 07 3260 8950</u>				
58897	13/03/2024	247738/2667	LIFTER NOT HITTING 2ND GEAR - NOT	Invoice
CHECKED / TIGHTENED LOOSE / SLIPPING ALTERNATOR BELT AND RE-CHECK - ALL OK CHECKED ENGINE REV'S HIGH NOT WORKING - FOUND TO BE WORKING NOW WAS ONLY LOW AIR FROM TRUCK SUPPLY - NEEDED TO ALLOW MORE TIME FOR TRUCK SUPPLY TO PUMP TRAILER UP ETC <u>HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.</u>				
58800	27/02/2024	245285/2667	LIFTER MOTOR ALTERNATOR BELT AND	Invoice
PARKED TRAILER IN WORKSHOP DRAINED COOLANT, REMOVED RADIATOR CAGE, FAN SHROUD, RADIATOR MOUNTS TOP AND BOTTOM AND RADIATOR REMOVED FAN, ALTERNATOR/FAN BELT AND WATER PUMP CLEANED ALL SURFACES RAISED TRAILER AND FITTED AXLE STANDS REMOVED WHEELS, SHOCK ABSORBERS AND TRAILER ARM PIVOT BOLTS ON 3RD AXLE REMOVED #3 AXLE TRAILING ARM BUSHES FITTED NEW WATER PUMP AND FAN BELT RE-FITTED FAN, RADIATOR, SHROUD AND GUARD ADJUSTED FAN BELT, FILLED WITH COOLANT STARTED ENGINE AND CHECKED FOR LEAKS FIT NEW SPRING EYE BUSHES AND BOLTS RE-FIT SPRING ARM BOLTS RE-FIT SHOCKIES AND WHEELS TENSIONED ALL WHEEL NUTS RETURNED TRAILER TO SHED 24 <u>HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.</u>				
58756	21/02/2024	244162/2352	C SERVICE	Invoice
PARK TRAILER IN WORKSHOP CARRY OUT C SERVICE AS PER SERVICE SHEET APPLY AIR TO TRAILER TEST LIGHTING FUNCTION				

Vehicle Details

Registration	040QXV	Next Service	Litres	
Make	HAMMAR	Rego Due	Trans	N/A
Model	195S	Engine #	Air	No
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	SEMITRAILER
Colour		Odometer/Hr	Prod	2015

Invoice No.	Date	Odometer / Hours	Description	Type
			LIFT TRAILER WITH HOIST CHECK SUSPENSION COMPONENTS CHECK KING PIN BOLT TENSION CHECK SKID PLATE CHECK THE UNDERCARRIAGE OF THE TRAILER CARRY OUT GREASING OF AXLES CARRY OUT DE-ADJUSTMENT OF BRAKES REMOVE HUB CAPS AND REMOVE BEARING ADJUSTMENT NUTS REMOVE BEARINGS FROM HUBS CLEAN STUB AXLES AND APPLY NEW FILM OF GREASE TO STUB AXLES CLEAN BEARINGS IN TURBO WASH CLEAN HUBS OF GREASE AND REPACK HUBS AS REQUIRED REMOVED BEARINGS FROM PARTS WASHER BLOW OUT WITH AIR AND REPACK BEARINGS INSTALL BEARINGS TO HUBS INSTALL INNER HUB SEALS INSTALL HUBS TO THE TRAILER AND TENSION-BEARING ADJUSTMENT NUTS SECURE BEARING ADJUSTMENT NUTS WITH RETAINERS REINSTALL HUB CAPS TO AXLES AND TENSION HUB CAPS CARRY OUT ADJUSTMENT OF BRAKES LOWER TRAILER CHECK WHEEL NUT TENSION CHECK ALL LIVERY INCLUDING MUDFLAPS AND DECAL INSPECT MARKER PLATES INCLUDING CON SIGN, CHEVRONS, AND OVERTAKE SIGNAGE CHECK TOP DECK OF TRAILER FOR ALL FUNCTIONALITY APPLY SERVICE STICKER COMPLETE PAPERWORK CLEAN WORK AREA ***** STRIP AND FIT 2 X NEW TYRES TENSIONED ALL WHEEL NUTS REPLACED FILTER AND OIL ON LIFTER MOTOR, TOPPED UP COOLANT REMOVED GUARD AROUND ALTERNATOR AND REMOVED BELT FROM ALTERNATOR, FOUND BELT WOULDN'T FIT PAST FAN. REMOVE GUARDS, SHROUD, RADIATOR BRACKETS, TOP RADIATOR HOSE AND FAN TO REMOVE BELT. PUT OLD BELT ON AS TRAILER WAS NEEDED IN THE MORNING AND DIDN'T HAVE TIME TO COMPLETE REPAIRS SPRAY MOLLY LUBE ON RUNNERS WHERE THE LIFTER SLIDES ON THE TRAILER SPRAY TWIST LOCKS AS THEY WERE A BIT TIGHT ***** NOTE- 3RD AXLE SPRING EYE BUSHES NEED REPLACING LIFTER MOTOR ALTERNATOR BELT AND WATER PUMP NEED REPLACING ***** <u>HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.</u>	

58207	27/11/2023	230255/2352	REMOVE AND REPLACE BATTERIES	Invoice
			REMOVE AND REPLACE FLAT BATTERY FIT NEW POSITIVE TERMINAL - ALL GOOD <u>HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.</u>	

Vehicle Details

Registration	040QXV	Next Service	Litres	
Make	HAMMAR	Rego Due	Trans	N/A
Model	195S	Engine #	Air	No
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	SEMITRAILER
Colour		Odometer/Hr	Prod	2015

Invoice No.	Date	Odometer / Hours	Description	Type
58044	08/11/2023	227690	B SERVICE	Invoice

COLLECTED TRAILER FROM SHED 24
 PARK TRAILER IN WORKSHOP
 CARRY OUT B SERVICE AS PER SERVICE SHEET
 APPLY AIR TO TRAILER
 TEST LIGHTING FUNCTION
 LIFT TRAILER WITH HOIST
 CHECK SUSPENSION COMPONENTS
 CHECK KING PIN BOLT TENSION
 CHECK SKID PLATE
 CHECK THE UNDERCARRIAGE OF THE TRAILER
 CARRY OUT GREASING OF AXLES
 CARRY OUT DE-ADJUSTMENT OF BRAKES
 REMOVE HUB CAPS AND REMOVE BEARING ADJUSTMENT NUTS
 REMOVE BEARINGS FROM HUBS
 CLEAN STUB AXLES AND APPLY NEW FILM OF GREASE TO STUB AXLES
 CLEAN BEARINGS IN TURBO WASH
 CLEAN HUBS OF GREASE AND REPACK HUBS AS REQUIRED
 REMOVED BEARINGS FROM PARTS WASHER BLOW OUT WITH AIR AND REPACK BEARINGS
 INSTALL BEARINGS TO HUBS
 INSTALL INNER HUB SEALS
 INSTALL HUBS TO THE TRAILER AND TENSION-BEARING ADJUSTMENT NUTS
 SECURE BEARING ADJUSTMENT NUTS WITH RETAINERS
 REINSTALL HUB CAPS TO AXLES AND TENSION HUB CAPS
 CARRY OUT ADJUSTMENT OF BRAKES
 LOWER TRAILER
 CHECK WHEEL NUT TENSION
 CHECK ALL LIVERY INCLUDING MUDFLAPS AND DECAL
 INSPECT MARKER PLATES INCLUDING CON SIGN, CHEVRONS, AND OVERTAKE SIGNAGE
 CHECK TOP DECK OF TRAILER FOR ALL FUNCTIONALITY
 APPLY SERVICE STICKER
 COMPLETE PAPERWORK
 CLEAN WORK AREA
 RETURNED TRAILER TO SHED 24

 REPLACED R/LEFT BRAKE BOOSTER
 REPLACED RADIATOR MOUNT
 FIXED AIR LEAKS

HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.

57977	30/10/2023	226116	BRAKES LOCKED UP	Invoice
-------	------------	--------	------------------	---------

PACK VAN
 TRAVELLED TO BUCCINI YARD, DIAGNOSED TRAILER NOT RELEASING BRAKES, FOUND AIRTANKS WERE EMPTY, FILL UP WITH THE VAN COMPRESSORS AIR
 TRAILER RELEASED BRAKES, DRIVER TESTED BRAKE
 LOCK UP TEST - ALL GOOD
 TRAVEL BACK TO WORKSHOP

Vehicle Details

Registration	040QXV	Next Service	Litres	
Make	HAMMAR	Rego Due	Trans	N/A
Model	195S	Engine #	Air	No
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	SEMITRAILER
Colour		Odometer/Hr	Prod	2015

Invoice No.	Date	Odometer / Hours	Description	Type
<u>HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.</u>				
57968	26/10/2023	225799	4 X NEW TYRES	Invoice
STRIP AND FIT 4 X NEW TYRES 255/70R22.5 TRAILER TYRES TYRE DISPOSAL X 4 TENSIONED ALL WHEEL NUTS <u>HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.</u>				
57767	05/10/2023	222199	2 NEW TYRES AND PUNCTURE	Invoice
BROUGHT VEHICLE INTO WORKSHOP TYRES SUPPLIED BY BT (ROADWAY BRAND 255/70R22.5) TRAVEL TO PARTS SUPPLIER TO COLLECT NEW PARTS REMOVE OLD GUARD BRACKETS DRILL AND FIT NEW BRACKETS FIT GUARD <u>HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.</u>				
57621	13/09/2023	217014	FLAT TYRE	Invoice
RH #1 AXLE OUTSIDE TYRE OFF BEAD RE-FITTED TYRE TO RIM INFLATED TYRES <u>HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.</u>				
57572	05/09/2023	214453	REPLACED LEAKING HYDRAULIC HOSES	Invoice
REPLACED LEAKING HYDRAULIC HOSES				
57464	23/08/2023	214453	A SERVICE	Invoice

Vehicle Details

Registration	040QXV	Next Service	Litres	
Make	HAMMAR	Rego Due	Trans	N/A
Model	195S	Engine #	Air	No
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	SEMITRAILER
Colour		Odometer/Hr	Prod	2015

Invoice No.	Date	Odometer / Hours	Description	Type
<p>CARRY OUT A SERVICE AS PER SERVICE SHEET PARK TRAILER IN WORKSHOP APPLY AIR TO TRAILER TEST LIGHTING FUNCTION LIFT TRAILER WITH HOIST CHECK WHEEL BEARINGS FOR MOVEMENT CHECK SUSPENSION COMPONENTS CHECK KING PIN BOLT TENSION CHECK SKID PLATE CHECK THE UNDERCARRIAGE OF THE TRAILER - FOUND LH 1ST AXLE BOOSTER LEAKING CARRIED OUT REPLACEMENT OF BOOSTER, FOUND OIL LEAK FROM HYDRAULIC PIPE AT PUMP CARRIED OUT TENSIONING OF HYDRAULIC FITTING TESTED ALL OK CARRY OUT GREASING OF AXLES CARRY OUT ADJUSTMENT OF BRAKES LOWER TRAILER CHECK WHEEL TENSION CHECK WHEEL BEARING GREASE FOR CONTAMINANTS CHECK ALL LIVERY INCLUDING MUDFLAPS AND DECAL INSPECT MARKER PLATES INCLUDING CON SIGN, CHEVRONS, AND OVERTAKE SIGNAGE CHECK TOP DECK OF TRAILER FOR ALL FUNCTIONALITY APPLY SERVICE STICKER COMPLETE PAPERWORK CLEAN WORK AREA MOVE TRAILER OUT OF WORKSHOP <u>HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.</u></p>				
57260	28/07/2023	212610	LIFTER JUMPING	Invoice
<p>SPRAYED GRAPHITE SPRAY ON LIFTER RAILS MOVED LIFTER AND FOUND IT WAS STILL JUMPY SPRAYED MORE GRAPHITE SPRAY ON RAILS MOVED LIFT AND FOUND ALL OK NOT JUMPY ANYMORE</p>				
57081	16/06/2023	204834	STRAIGHTEN SENSOR BRACKET AND	Invoice
<p>STRAIGHTEN SENSOR BRACKET JOIN WIRES TIGHTEN BRACKET</p>				
56298	27/03/2023	198288	A SERVICE AND REPAIRS	Invoice
<p>BROUGHT VEHICLE INTO WORKSHOP</p> <p>CARRIED OUT A SERVICE B SERVICE - ENINE OIL AND FILTGRS CHANGED REPLACED KING PIN AND BOLTS REPLACED LH FRONT AND RH REAR TWIST LOCK REPAIRED TWIST LOCK HANDLES REPLACED ALL SHOCK ABSORBERS REMOVED LH #1 AXLE TRAILING AM ALIGNMENT PLATES FITTED LIFT CHAINS AND NEW PINS</p>				

Vehicle Details

Registration	040QXV	Next Service	Litres	
Make	HAMMAR	Rego Due	Trans	N/A
Model	195S	Engine #	Air	No
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	SEMITRAILER
Colour		Odometer/Hr	Prod	2015

Invoice No.	Date	Odometer / Hours	Description	Type
REMOVE HYDRAULIC RAM FOR SWINGLIFT REMOVE TOP PIN REMOVE HYDRAULIC LINES AND CAP ENDS UNABLE TO REMOVE BOTTOM PIN, HIRED A 30 T HYDRAULIC PULLER AND THEN REMOVED THE PIN. GROUND REAR CRANE CONTAINER STOPPER PLATE IN PREPERATION FOR WELDING, WELDED NEW CONTAINER STOPPER PLATE STRAIGHTENED MOUNT WELDED CRACKS IN FRONT STOPPER PLATE MOUNT PAINTED STOPPERS REMOVE AND REPLACD RHS REAR GUARD REFIT REAR GUARD POLES AND FIX THE MOUNTING POLES MEASURE CUT AND WELD METAL FRAME TO SUPPORT LIFTER ARMS REMOVE MIDDLE RAMS TOP PIN BOTTOM SEIZED HEAT UP AND STRAIGHTEN LHF CONTAINER STOP REMOVE CHAINS REMOVE BOTTOM PIN FROM RAM REMOVE RAM SLIDE CHAINS INTO NEW COVERS REPLACED RHR MUDFLAP SHORTENED MUDFLAP FITTED LH #1 AXLE TRAILING ARM QUICK ALIGN KIT TENSIONED PIVOT BOLT PAINTER HANGER REFITTED MUDGUARD REMOVED CHASSIS STANDS SECURED LIFT CHAIN GUARDS/SOCKS FITTED REFLECTORS NOTE- TRAVELLED TO HYDRAULIC SHOP AT SUMNER PARK THROUGH PEAK HOUR TRAFFIC TO PICK UP RAM				
55660	09/01/2023	188742	REPLACED BATTERY	Invoice
REPLACED BATTERY WITH SECOND HAND BATTERY CHECKED ALTERNATOR BELT WAS TIGHT				
55723	05/01/2023	188740	C SERVICE	Invoice
PICKED UP TRAILER FROM BUCCINI YARD CHECKED BEARING GREASE - ALL GOOD RETURNED TRAILER TO BUCCINI YARD				
55257	02/11/2022	187921	B SERVICE	Invoice
BROUGHT VEHICLE INTO WORKSHOP CARRIED OUT B SERVICE NOTE- ALL AIR BAGS MIBNOR CRACKING - NO LEAKS - MONITOR 2nd AXLE RHS TYRE SCALLOPED				
55265	27/10/2022	183854	HYDRAULIC FITTINGS LEAK	Invoice

Vehicle Details

Registration	040QXV	Next Service	Litres	
Make	HAMMAR	Rego Due	Trans	N/A
Model	195S	Engine #	Air	No
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	SEMITRAILER
Colour		Odometer/Hr	Prod	2015

Invoice No.	Date	Odometer / Hours	Description	Type
PICKED UP TRAILER FROM SHED 24 DEGREASE HYDRAULIC FITTINGS LEAK CLEANED LEAK TO PIN POINT TIGHTENED FITTING, TESTED UNDER LOAD TESTED - ALL OK DROVE TRAILER BACK TO BUCCINI YARD				
55019	19/09/2022	178066	NO TRAILER LIGHTS	Invoice
CARRIED DIAGNOSIS FOUND PINS BENT STRAIGHTENED AND ADJUSTED TEST - ALL OK				
54900	02/09/2022	176384	TOPPED UP ENGINE OIL + TIGHTENED	Invoice
TOPPED UP ENGINE OIL TIGHTENED FAN BELT				
54650	01/08/2022	168924	FIT NEW TWIST LOCK	Invoice
BROUGHT VEHICLE INTO WORKSHOP REMOVED AND FITTED NEW TWIST LOCK				
54470	11/07/2022	0	STARTING PROBLEMS	Invoice
CHECKED STARTING PROBLEM - FOUND LIFTER BATTERY FLAT (ISOLATOR) BEEN LEFT ON OVER WEEKEND? REPLACED BATTERY WITH SPARE - RECHARGED BATTERY AND RECHECKED STARTING / CHARGING - ALL OK				
54307	13/05/2022	1859	HAMMER TRAILER WON'T START	Invoice
TRAVELED TO AND FROM SHED 24 CHECKED STARTING FAULTS ERRORS LOCATED / FIXED "PUSHED OUT" UNSEATED RELAY TERMINAL INSIDE REAR BOX AREA LOCATED / FIXED WATER AFFECTED BAD PLUG CONNECTOR NEAR ENGINE RECHECKED START/STOP/RUN/IGNITION AND CRANE FUNCTIONS - ALL OK				
54087	28/04/2022	0	OIL LEAK ON LIFTER ENGINE	Invoice
DIAGNOSED, DEGREASED AND REPAIRED OIL LEAK ON LIFTER MOTOR FOUND MINOR WEEP AT SUMP BELL HOUSING AND BREATHER HOSE CLEANED AND RECHECKED - ALL OK FOUND WEEP AT HYDRAULIC FITTING - DEGREASED PARKED TRAILER ON STREET				
53816	09/03/2022	158010	LANDING LEG ISSUES	Invoice
9/3/2022 DROVE TO SHED 24 INSPECTED TRAILER LANDING LEGS RAISED AND LOWERED LANDING LEGS CHECKED OPERATION				

Vehicle Details

Registration	040QXV	Next Service	Litres	
Make	HAMMAR	Rego Due	Trans	N/A
Model	195S	Engine #	Air	No
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	SEMITRAILER
Colour		Odometer/Hr	Prod	2015

Invoice No.	Date	Odometer / Hours	Description	Type
53738	01/02/2022	2352	NEW REMOTE	Invoice
18/2/2022 ADDED NEW REMOTE CONTROL & ADDED NEW RADIO REMOTE BOARD CHIPS TO RECIEVER & TRANSMITTER AS REQUIRED TEST - START/STOP - ALL OK				
53592	18/01/2022	155045	C SERVICE	Invoice
BROUGHT TRAILER INTO WORKSHOP CARRIED OUT C SERVICE ON VEHICLE NO FAULTS FOUND - DOESNT REQUIRE REPACK PARKED TRAILER ON STREET FOR COLLECTION				
53224	12/11/2021	153483	REPAIRS TO TWIST LOCKS	Invoice
REMOVED TWIST LOCKS FROM TRAILER REMOVED AND REPLACED DAMAGED BOLTS IN THE CONTAINER PINS REFIT TWIST LOCKS AND TESTED OPERATION - ALL OK				
53141	05/11/2021	142393	LANDING LEG HANDLE	Invoice
ATTEND BUCCINI YARD AND FIND TRAILER LANDING LEGS HANDLE MISSING TAKE OUT OLD SEAL SLEEVE STUCK IN THE JOINT REPLACE HANDLE AND BOLT UP TESTED OPERATION - ALL OK				
53114	18/10/2021	139296	AIR LEAK	Invoice
ATTEND TO BUCCINI YARD AND INSPECTED POSSIBLE AIR LEAK DIAGNOSED AND REPLACED FEMALE SUZI COIL AIR FITTING TESTED OPERATION - ALL OK				
52201	02/06/2021	1619	REPLACE STARTER MOTOR AND LIGHTS	Invoice
TRAVEL TO VEHICLE BROKEN DOWN AT ORMEAU - WOULD NOT START TESTED BATTERY VOLTAGE - 12.4 VOLTS ENSURED ALL ESTOPS WERE IN OFF POSITION TURNED ON IGNITION AND TESTED FROM BUTTON AT REAR OF VEHICLE - DIDNT START ENSURED VEHICLE WAS RECIEVING SIGNAL AT SOLINOID AND BATTERY - WORKING TAPPED STARTER MOTOR AND UNIT TURNED OVER DIAGNOSED STARTER MOTOR WORN OUT NEEDS OF REPLACING. STARTED VEHICLE SO CONTAINERS COULD BE UNLOADED VEHICLE CAME BACK TO WORKSHOP CHECKED FLOODLIGHTS NOT WORKING LOCATED AND REPAIRED CHAFFED WIRING AT TWO PLACES ALONG CAT TRACK - TESTED OK INSPECTED STARTING FAULT - CLEANED UP ALL BATTERY/STARTER CABLES AND WIRING CONNECTORS REMOVED AND REPLACED WORN STARTER MOTOR. BUCCINI SUPPLIED NEW STARTER MOTOR.				
51783	27/03/2021	108979	CARRY OUT REPAIRS	Invoice
BREAKDOWN, TRAILER WILL NOT BUILD UP AIR. DROVE TO WORKSHOP AND PICKED UP FREIGHTLINER, THEN DROVE TO TYRES 4 US AT REDBANK. DIAGNOSED THAT THE TRAILER PROTECTION VALVE IS FAULTY AND BACKFEEDING AIR THROUGH THE MAXI SIDE. TRAILER AND TRUCK DROVE TO WORKSHOP. DIAGNOSED AND REPLACED SEALED SPRING BRAKE VALVE - LEAKING AIR				

Vehicle Details

Registration	040QXV	Next Service	Litres	
Make	HAMMAR	Rego Due	Trans	N/A
Model	195S	Engine #	Air	No
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	SEMITRAILER
Colour		Odometer/Hr	Prod	2015

Invoice No.	Date	Odometer / Hours	Description	Type
REPLACED BATTERY - FAULTY CHECKED OPERATION - ALL OK				

51666	15/03/2021	2152	ELECTRICAL FAULTS	Invoice
-------	------------	------	-------------------	---------

CARRIED OUT TESTS/CHECKS TO ENSURE STARTING BUT NOT STOPPING.
FOUND FAULT TO 'E-STOP' MINI INTERNAL WIRING SHORTED OUT ACROSS TWO TERMINALS ON REMOTE CONTROL SWITCH.
FOUND THERE IS A FAULT TO CHARGING SYSTEM AS CHARGER LIGHT STAYS ON DIM AFTER STARTING. NO MANUAL CHECKING POSSIBLE FROM REAR BOX SWITCH.

CHECKED FOR INTERMITTENT CHARGING FAULT - FOUND INTERMITTENT PLUG/FEMALE TERMINAL INSIDE ALTERNATOR SENSOR PLUG. RESET ALL THREE FEMALE SPRING ENDS AND RECHECKED OK.
TRACED INTERMITTENT FAULT TO 24V POWER FUSE TO FRONT CRANES FAULTS TO EHAFFED WIRING INSIDE REAR CONTROL BOX.
CHECKED PENDANT CONTROL - RESECURED TWISTED CABLES/END GLAND FITTINGS. RECHECKED ALL TRAILER MODES AND FUNCTIONS.
DIAGNOSED MISSING BATTERY ADAPTER - SET UP UNIT FOR CORDED REMOTE USE AND TEST. FAULTS STILL PRESENT.
CHECKED FOR VARIOUS FAULTS - FOUND 5 PIN ON TRAILER PLUG INPUT WAS CORRODED TO TRAILER WORKLIGHTS.
LOCATED ON JUNCTION BOX ON TRAILER LHS MIDWAY ALONG CHASSIS WAS DISCONNECTED. REPAIRED ALL OK.
NO OTHER FAULTS FOUND.

51550	26/02/2021	103213	WELD ON HOOKS FOR LIFTER CHAINS	Invoice
-------	------------	--------	---------------------------------	---------

DATE WORK CARRIED OUT: 24/02/2021 - 26/02/2021
WORK CARRIED OUT:
WELDED ON NEW BOLTS FOR HOOKS FOR LIFTER CHAINS
CARRIED OUT COI INSPECTION
REMOVED OLD BOOSTER & TRANSFERRED FITTINGS ACROSS FROM THE OLD ONE, FITTED THE NEW BOOSTER, LOOSENED OFF THE HOLDING CLAMP AND SPUN THE BOOSTER SO THE FITTINGS LINED UP, TIGHTENED UP HOLDING CLAMP. CHECKED ALL OK.

51396	03/02/2021	2131	B SERVICE & LIFTER FAULTS	Invoice
-------	------------	------	---------------------------	---------

DATE WORK CARRIED OUT: 03/02/2021
WORK CARRIED OUT:
CARRIED OUT B SERVICE ON LIFTER MOTOR
REPAIRED ALL 4 CENTRE TWIST LOCK HANDLES
STRAIGHTENED ALL TWIST LOCK HANDLES

51347	28/01/2021	96410	TWIST LOCK REPAIR	Invoice
-------	------------	-------	-------------------	---------

DATE WORK CARRIED OUT: 28/01/2021
WORK CARRIED OUT:
REPLACED TWISTLOCK BOLT
REPLACED DETENT BALLS

Vehicle Details

Registration	040QXV	Next Service	Litres	
Make	HAMMAR	Rego Due	Trans	N/A
Model	195S	Engine #	Air	No
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	SEMITRAILER
Colour		Odometer/Hr	Prod	2015

Invoice No.	Date	Odometer / Hours	Description	Type
51194	13/01/2021	95178	A SERVICE	Invoice

DATE WORK CARRIED OUT: 13/01/2021

WORK CARRIED OUT:

CARRIED OUT A SERVICE
LIFTER OVERDUE FOR B SERVICE

DEFECTS NOTED

- F/R BRAKE BOOSTER LEAKING – MAXI SIDE
- MIDDLE LEFT SHOCK ABSORBER HAS A SLIGHT LEAK
- RIGHT REAR SHOCK ABSORBER HAS A SLIGHT LEAK
- FRONT RIGHT & MIDDLE RIGHT MUDGUARDS SLIGHTLY BENT UP
- FRONT TYRES U/S
- LIFTER MOTOR RADIATOR MOUNT BOLTS BROKEN

51164	30/12/2020	0	STARTING FAULT	Invoice
-------	------------	---	----------------	---------

DATE WORK CARRIED OUT: 30/12/2020

WORK CARRIED OUT:

CHECKED STARTING FAULT
FOUND WIRE OFF ON ALTERNATOR
REFITTED WIRE
TESTED OPERATION - OK

50944	23/11/2020	0	REPAIR - REAR 20/40 RAM TWISTED	Invoice
-------	------------	---	---------------------------------	---------

DATE WORK CARRIED OUT: 23/11/2020

WORK CARRIED OUT:

REAR 20/40 RAM - TWISTED WHICH RESULTS ON DAMAGED TO TOOLBOX. TWISTED RAM SO IT NO LONGER FOULS THE TOOLBOX LID.

Requirements for next service are -

REQUIRED NYLON WEAR PADS REPLACED FOR 20/40 SLIDES

50909	13/11/2020	0	TWIST LOCK REPAIR	Invoice
-------	------------	---	-------------------	---------

DATE WORK CARRIED OUT: 13/11/2020

WORK CARRIED OUT:

REPAIRED 2 X BROKEN OFF TWIST LOCKS
GRIND INTO SHAPE AND WELD UP BOLTS HOLES

50863	09/11/2020	80442	NOT STARTING	Invoice
-------	------------	-------	--------------	---------

Vehicle Details

Registration	040QXV	Next Service	Litres	
Make	HAMMAR	Rego Due	Trans	N/A
Model	195S	Engine #	Air	No
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	SEMITRAILER
Colour		Odometer/Hr	Prod	2015

Invoice No.	Date	Odometer / Hours	Description	Type
DATE WORK CARRIED OUT: 09/11/2020 WORK CARRIED OUT: INSPECTED LIFTER ENGINE NOT STARTING FOUND FLAT BATTERY REMOVED & REPLACED BATTERY				
50829	06/11/2020	0	CHAINS & BEARING REPACK & REPAIRS	Invoice
DATE WORK CARRIED OUT: 03/11/2020 – 06/11/2020 WORK CARRIED OUT: REMOVED LIFTING CHAINS FOR TESTING REFITTED CHAINS AFTER TESTING STRIPPED & CLEANED WHEEL END ASSEMBLIES, BEARINGS, HUBS, CAPS & AXLE END HARDWARE FITTED ALL HUBS WITH NEW GREASE, SEALS AND SPACERS FITTED WHEELS AND TENSIONED, ADJUSTED BRAKES REPAIRED OPEN CIRCUIT WIRING AT 2 PLACES FOR POWER SUPPLY INPUT & OUTPUT FOR INFRARED SENSORS RHS TESTED OPERATION – ALL OK				
50830	03/11/2020	80293	TWISTLOCK	Invoice
DATE WORK CARRIED OUT: 03/11/2020 WORK CARRIED OUT: REPLACED LH FRONT TWISTLOCK HANDLE & BOLTS REPLACED RH REAR TWISTLOCK HANDLE, BOLTS & DETENT				
50798	29/10/2020	79161	A & C SERVICES & REPAIRS	Invoice
<p>DATE WORK CARRIED OUT: 28/10/2020 - 29/10/2020</p> <p>WORK CARRIED OUT: CARRIED OUT A & C SERVICES AS PER HVW SERVICE SHEETS REPLACED BRAKE BOOSTER REPLACED FRONT REFLECTOR</p> <p>FURTHER ACTION REQUIRED -</p> <p>MIDDLE AXLE INSIDE TYRE U/S LHR INNER TYRE LOW</p> <p>FL TRAILING ARM BUSH HAS RUST CHECKED AND NO PLAY MONITOR FOR NEXT SERVICE RHR BRAKE BOOSTER LEAKING ON SUPPLY SIDE - REPLACED</p> <p>MISSING FRONT REFLECTOR - REPLACED</p>				

Vehicle Details

Registration	040QXV	Next Service	Litres	
Make	HAMMAR	Rego Due	Trans	N/A
Model	195S	Engine #	Air	No
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	SEMITRAILER
Colour		Odometer/Hr	Prod	2015

Invoice No.	Date	Odometer / Hours	Description	Type
LEAKING HYDRAULIC HOSE IN FRONT OF LIFTER MOTOR HUB OIL STARTING TO GO BROWN - RECOMMEND REPLACING SOON / NEXT SERVICE				

50453	16/09/2020	73085	RR - 16011 REPAIR TWIST LOCK	Invoice
DATE WORK CARRIED OUT: WORK CARRIED OUT: REMOVED TWIST LOCK HANDLES REPAIRED TWIST LOCK HANDLES RE-FIT TWIST LOCK HANDLES RR - 16011				

50267	19/08/2020	0	REPLACE FAN BELT	Invoice
DATE WORK CARRIED OUT: 19/08/2020 WORK CARRIED OUT: COLLECT TRAILER REPLACE FAN BELT WITH NEW SHORTER ONE TESTED - OK DELIVERED				

50240	17/08/2020	69641	LIFTER BATTERY ISSUE	Invoice
DATE WORK CARRIED OUT: 17/08/2020 WORK CARRIED OUT: DRIVER CAME IN WITH A FLAT LIFTER ENGINE BATTERY SWAPPED IN A SECOND HAND BUT CHARGED BATTERY - TESTED ALL GOOD PUT THE FLAT BATTERY ON CHARGE FOR LOAD TESTING LATER				

50155	30/07/2020	66813/1981	PRE MACHINERY INSPECTION & SERVICE	Invoice
DATE WORK CARRIED OUT: 29/07/2020 WORK CARRIED OUT: ANNUAL PRE MACHINERY INSPECTION & REPAIRS STRAIGHTENED BENT GUARD BRACKETS LHS DRILL HOLES & PLACE BOLTS IN LHS REAR MUD GUARD REPLACED 5 BROKEN OFF GREASE NIPPLES FURTHER ACTION REQUIRED - LHF OUTER TYRE CHUNK OUT OF SIDE WALL LH MIDDLE SHOCK SLIGHT LEAK				

Vehicle Details

Registration	040QXV	Next Service	Litres	
Make	HAMMAR	Rego Due	Trans	N/A
Model	195S	Engine #	Air	No
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	SEMITRAILER
Colour		Odometer/Hr	Prod	2015

Invoice No.	Date	Odometer / Hours	Description	Type
RH TOP SHOCK BOLT LOOSE MUDGUARD BRACKET BROKEN LHS (MISSING) SMALL LEAK ON LOWER HOSE ON FRONT MODULE				
50067	20/07/2020	0	STARTING ISSUES	Invoice
DATE WORK CARRIED OUT: 20/07/2020 WORK CARRIED OUT: INSPECT STARTING ISSUE - TESTED BATTERY ON LIFTER MOTOR FOUND TO ONLY HAVE 11.3 VOLT IN IT CHANGED OUT BATTERY AND STARTER MOTOR CHECKED CHARGE RATE ON MOTOR AND IS CHARGING OUT 14.4 VOLTS				
50216	14/07/2020	0	JUMP START	Invoice
DATE WORK CARRIED OUT: 14/07/2020 WORK CARRIED OUT: TRAVEL TO YARD TO JUMP START				