



Vehicle History

Vehicle Details

Registration	479QZK	Next Service	Litres	
Make	STEELBRO	Rego Due	Trans	N/A
Model	ATM OVER 4.5T	Engine #	Air	Yes
Model Series		VIN	Cyl	0
Model Code	SIDELIFTER	Build Date	Body	TRAILER
Colour	BLUE	Odometer/Hr	Prod	2014

Invoice No.	Date	Odometer / Hours	Description	Type
61120	23/06/2025	109718/2351	INDICATOR LIGHTS	Invoice

RH REAR INDICATOR FAULTY + LH REAR MARKER FAULTY
REPLACED LIGHTS AND TESTED - ALL OKAY

HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE THE STORE FOR PRICING ON - 07 3260 8950

RECEIVE A \$25 DISCOUNT FOR ANY POSITIVE GOOGLE REVIEW ON OUR COMPANY GOOGLE WEBPAGE - HEAVY VEHICLE WORKSHOP

60848	22/04/2025	98105/2351	REPLACE BATTERY	Invoice
-------	------------	------------	-----------------	---------

REPLACE BATTERY

HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE THE STORE FOR PRICING ON - 07 3260 8950

RECEIVE A \$25 DISCOUNT FOR ANY POSITIVE GOOGLE REVIEW ON OUR COMPANY GOOGLE WEBPAGE - HEAVY VEHICLE WORKSHOP

60697	18/03/2025	98105/2351	DEFECTS	Invoice
-------	------------	------------	---------	---------

DIAGNOSE CRANE FAULT
TESTED OPERATION OF CRANE AND DROP TRAILER BACK TO YARD
FILL DRUMS WITH HYDRAULIC OIL
TRAVEL TO PINKENBA
LIFTER LEGS NOT RETRACTING
FILL 15L HYDRAULIC OIL AS WAS LOW
RETRACT LEGS AND REMOVE BOX
TEST CRANE - FOUND CRANE HAS WALKED OFF SKID RAIL/RUNNER
NEEDS TO BE STRAIGHTENED TO SHIFT BACK TO 20
TRAVEL TO BT YARD
FIT HYDRAULIC CAP TO TRAILER
OPERATED SIDELoader TO CHECK FOR FAULTS
CHECKED SCREEN FOR FAULTS
FOUND HYDRAULICS BYPASSING OIL (no pressure in cranes)
REMOVED SOLENOIDS @ HYDRAULIC BANK, CLEANED STEMS + SOLENOID AND RETESTED
CHECKED WIRING FUSES AND RELAYS
REPLACED HYDRAULIC BANK STEM + SOLENOID, PRIMED SYSTEM
TESTED OPERATION
REPAIRED CONTROL BOX DOOR HINGE
STRAIGHTENED PINCH POINT FLAG/SIGN
RETURNED TO BUCCINI YARD

Vehicle Details

Registration	479QZK	Next Service	Litres	
Make	STEELBRO	Rego Due	Trans	N/A
Model	ATM OVER 4.5T	Engine #	Air	Yes
Model Series		VIN	Cyl	0
Model Code	SIDELIFTER	Build Date	Body	TRAILER
Colour	BLUE	Odometer/Hr	Prod	2014

Invoice No.	Date	Odometer / Hours	Description	Type
-------------	------	------------------	-------------	------

HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE THE STORE FOR PRICING ON - 07 3260 8950
 RECEIVE A \$25 DISCOUNT FOR ANY POSITIVE GOOGLE REVIEW ON OUR COMPANY GOOGLE WEBPAGE - HEAVY VEHICLE WORKSHOP

60375	08/01/2025	91064/2351	DEFECTS	Invoice
-------	------------	------------	---------	---------

DROVE TO BUCCINI YARD
 REPAIRED AIR LEAK @ #1 AXLE
 PARK TRAILER IN WORKSHOP
 CARRY OUT A SERVICE AS PER SERVICE SHEET
 APPLY AIR TO TRAILER
 TEST LIGHTING FUNCTION
 LIFT TRAILER WITH HOIST
 CHECK WHEEL BEARINGS FOR MOVEMENT
 CHECK SUSPENSION COMPONENTS
 CHECK KING PIN BOLT TENSION
 CHECK SKID PLATE
 CHECK THE UNDERCARRIAGE OF THE TRAILER
 CARRY OUT GREASING OF AXLES
 CARRY OUT ADJUSTMENT OF BRAKES
 LOWER TRAILER
 CHECK WHEEL TENSION
 CHECK WHEEL BEARING GREASE FOR CONTAMINANTS
 CHECK ALL LIVERY INCLUDING MUDFLAPS AND DECAL
 INSPECT MARKER PLATES INCLUDING CON SIGN, CHEVRONS, AND OVERTAKE SIGNAGE
 CHECK TOP DECK OF TRAILER FOR ALL FUNCTIONALITY
 APPLY SERVICE STICKER
 COMPLETE PAPERWORK
 CLEAN WORK AREA
 MOVE TRAILER OUT OF WORKSHOP

HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE COREY FOR PRICING ON - 07 3260 8950

60273	09/12/2024	87370/2351	LABOUR - BUCCINI	Invoice
-------	------------	------------	------------------	---------

HIT OLD ROLL PIN OUT OF TWIST LOCK
 RE FIT HANDLE AND FIT NEW ROLL PIN TO TWIST LOCK

HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE CHRIS FOR PRICING ON - 07 3260 8950

60180	25/11/2024	76952/2351	BATTERY DEAD	Invoice
-------	------------	------------	--------------	---------

Vehicle Details

Registration	479QZK	Next Service	Litres	
Make	STEELBRO	Rego Due	Trans	N/A
Model	ATM OVER 4.5T	Engine #	Air	Yes
Model Series		VIN	Cyl	0
Model Code	SIDELIFTER	Build Date	Body	TRAILER
Colour	BLUE	Odometer/Hr	Prod	2014

Invoice No.	Date	Odometer / Hours	Description	Type
<p>REMOVE AND CHARGE BATTERY FIT AND TEST OPERATION - ALL OKAY ISOLATE SYSTEM <u>HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE CHRIS FOR PRICING ON - 07 3260 8950</u></p>				
59954	10/10/2024	76952/2351	OIL LEAK	Invoice
<p>HYDRAULIC OIL LEAK FROM HYDRAULIC HOSE TIGHTENED HOSE CHECKED FOR LEAK - ALL OKAY <u>HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE JEFF FOR PRICING ON - 07 3260 8950</u></p>				
59822	10/09/2024	680301/2351	Trailer C service	Invoice
<p>PARK TRAILER IN WORKSHOP CARRY OUT C SERVICE AS PER SERVICE SHEET APPLY AIR TO TRAILER TEST LIGHTING FUNCTION LIFT TRAILER WITH HOIST CHECK SUSPENSION COMPONENTS CHECK KING PIN BOLT TENSION CHECK SKID PLATE CHECK THE UNDERCARRIAGE OF THE TRAILER CARRY OUT GREASING OF AXLES CARRY OUT DE-ADJUSTMENT OF BRAKES REMOVE HUB CAPS AND REMOVE BEARING ADJUSTMENT NUTS REMOVE BEARINGS FROM HUBS CLEAN STUB AXLES AND APPLY NEW FILM OF GREASE TO STUB AXLES CLEAN BEARINGS IN TURBO WASH CLEAN HUBS OF GREASE AND REPACK HUBS AS REQUIRED REMOVED BEARINGS FROM PARTS WASHER BLOW OUT WITH AIR AND REPACK BEARINGS INSTALL BEARINGS TO HUBS INSTALL INNER HUB SEALS INSTALL HUBS TO THE TRAILER AND TENSION-BEARING ADJUSTMENT NUTS SECURE BEARING ADJUSTMENT NUTS WITH RETAINERS REINSTALL HUB CAPS TO AXLES AND TENSION HUB CAPS CARRY OUT ADJUSTMENT OF BRAKES LOWER TRAILER CHECK WHEEL NUT TENSION CHECK ALL LIVERY INCLUDING MUDFLAPS AND DECAL INSPECT MARKER PLATES INCLUDING CON SIGN, CHEVRONS, AND OVERTAKE SIGNAGE CHECK TOP DECK OF TRAILER FOR ALL FUNCTIONALITY APPLY SERVICE STICKER COMPLETE PAPERWORK CLEAN WORK AREA MOVE TRAILER OUT OF WORKSHOP NOTE REPLACED ALL HOSES IN BOTH TRACKS ON TRAILER</p>				

Vehicle Details

Registration	479QZK	Next Service	Litres	
Make	STEELBRO	Rego Due	Trans	N/A
Model	ATM OVER 4.5T	Engine #	Air	Yes
Model Series		VIN	Cyl	0
Model Code	SIDELIFTER	Build Date	Body	TRAILER
Colour	BLUE	Odometer/Hr	Prod	2014

Invoice No.	Date	Odometer / Hours	Description	Type
			<p>ATTEMPTED TO FIT NEW CAT TRACK - HOSES WERE INCORRECT FROM REPLACEMENT REMOVE AND RE-REPLACE ALL HOSES CHECKED FOR EMERGENCY BRAKES NOT WORKING SPRING BRAKE VALVE FAULTY REMOVED AIRBAG HOSES AND DRAINED AIR TANK REPLACED SPRING BRAKE VALVE REFITTED AIR BRAKE HOSES AND FITTINGS FILLED AIR TANKS TESTED OPERATION - OKAY REPLACED RH SIDE MARKER LIGHT REPLACED RH SIDE REFLECTORS REPLACED KING PIN AND BOLT KIT REPLACED DO NOT OVERTAKE SIGN REMOVED CRANE LIFT CHAINS - REQUIRES NEW MOUNTING PINS REMOVED RH #3 AXLE DAMAGED MUDGUARD REPLACED BATTERY ENGINE OIL FILTER CHANGED RAISED TRAILER AND LIFTED #3 AXLE REMOVED WHEEL, BRAKE DRUMS AND BRAKE SHOES STRAIGHTENED BENT MUD GUARD BRACKETS WELDED CRACK ON CROSS BRACE STRAIGHTENED HANDLE FOR TRAILER FEET FITTED CRANE LIFT CHAINS FITTED NEW RH #3 AXLE MUDGUARD AND MUDFLAP REMOVED #3 AXLE AIRBAGS FITTED NEW AIRBAGS REMOVED EXHAUST MANIFOLD, EXHAUST PIPE AND FLEX CLEANED EXHAUST SURFACES REMOVED RADIATOR TO FIT NEW MOUNTS FIT #3 AXLE BRAKE SHOES AND BRAKE DRUM FIT TYRE AND TORQUE TO SPECS REMOVE STAND REPLACED FAN BELT ADJUSTED BELT FIT NEW EXHAUST MANIFOLD GASKET FITTED EXHAUST MANIFOLD, EXHAUST PIPE AND MUFFLER STARTED ENGINE AND CHECKED FOR LEAKS TESTED BOTH CRANES FOR MOVEMENT OF CAT TRACK CATTRACK AND HYDRAULIC HOSES POSITIONED INCORRECTLY TESTED FRONT AND REAR CRANES AFTER HYDRAULINK REPAIRED HOSES TOPPED UP HYDRAULIC OIL <u>HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE JEFF FOR PRICING ON - 07 3260 8950</u></p>	

59807	05/09/2024	76952/2351	LABOUR - BUCCINI	Invoice
-------	------------	------------	------------------	---------

MISSED PARTS AND LABOUR ON JOB 59822

TEST OPERATION OF CRANES
RECONNECT CAT TRACK
MODIFIED RH REAR PINCH POINT SIGN
TESTED REAR CRANE OPERATION

Vehicle Details

Registration	479QZK	Next Service	Litres	
Make	STEELBRO	Rego Due	Trans	N/A
Model	ATM OVER 4.5T	Engine #	Air	Yes
Model Series		VIN	Cyl	0
Model Code	SIDELIFTER	Build Date	Body	TRAILER
Colour	BLUE	Odometer/Hr	Prod	2014

Invoice No.	Date	Odometer / Hours	Description	Type
CHECKED CAT TRACK FAULT CLEANED REAR CRANE FROM SPILT HYDRAULIC OIL TEST LIFTER AND ASSIST WITH CAT TRACK <u>HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE JEFF FOR PRICING ON - 07 3260 8950</u>				
59751	26/08/2024	68490/2351	TEST LIFTER	Invoice
REPLACE ALL HOSES IN BOTH TRACKS ON TRAILER TEST LIFTER OPERATION - ALL OKAY <u>HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE JEFF FOR PRICING ON - 07 3260 8950</u>				
59608	24/07/2024	68490/2351	REPLACE DAMAGED MUDGUARDS	Invoice
14 BOLTS WERE SEIZED AND NEEDED TO BE CUT OFF WITH GRINDER TRAVELLED TO SUPPLIER AND RETRIEVED PARTS FIT MUDGUARD AND DRILLED HOLES TO SUIT BRACKETS RETURN TRAILER TO BUCCINI YARD <u>HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE JEFF FOR PRICING ON - 07 3260 8950</u>				
59571	18/07/2024	68490/2351	A SERVICE	Invoice
PARK TRAILER IN WORKSHOP CARRY OUT A SERVICE AS PER SERVICE SHEET APPLY AIR TO TRAILER TEST LIGHTING FUNCTION LIFT TRAILER WITH HOIST CHECK WHEEL BEARINGS FOR MOVEMENT CHECK SUSPENSION COMPONENTS CHECK KING PIN BOLT TENSION CHECK SKID PLATE CHECK THE UNDERCARRIAGE OF THE TRAILER CARRY OUT GREASING OF AXLES CARRY OUT ADJUSTMENT OF BRAKES LOWER TRAILER CHECK WHEEL TENSION CHECK WHEEL BEARING GREASE FOR CONTAMINANTS CHECK ALL LIVERY INCLUDING MUDFLAPS AND DECAL INSPECT MARKER PLATES INCLUDING CON SIGN, CHEVRONS, AND OVERTAKE SIGNAGE CHECK TOP DECK OF TRAILER FOR ALL FUNCTIONALITY APPLY SERVICE STICKER COMPLETE PAPERWORK CLEAN WORK AREA MOVE TRAILER OUT OF WORKSHOP <u>HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND</u>				

Vehicle Details

Registration	479QZK	Next Service	Litres	
Make	STEELBRO	Rego Due	Trans	N/A
Model	ATM OVER 4.5T	Engine #	Air	Yes
Model Series		VIN	Cyl	0
Model Code	SIDELIFTER	Build Date	Body	TRAILER
Colour	BLUE	Odometer/Hr	Prod	2014

Invoice No.	Date	Odometer / Hours	Description	Type
<u>MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE JEFF FOR PRICING ON - 07 3260 8950</u>				

59408	18/06/2024	65004/2351	JUMP START TRUCK	Invoice
TRAVEL TO BT YARD CARRY OUT JUMP START FOUND AFTER STARTING, BELT WAS SQUEELING ADJUSTED BELT SPRAYED BELT WITH SILICONE SPRAY TESTED OPERATION - ALL OKAY NOTE WILL REQUIRE NEW BELT AT NEXT SERVICE <u>HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE JEFF FOR PRICING ON - 07 3260 8950</u>				

59096	14/05/2024	60463/2351	B SERVICE	Invoice
PICKED UP VEHICLE FROM BUCCINI YARD REMOVED, AND REPLACED FILTERS AND OIL ON LIFTER MOTOR PARK TRAILER IN WORKSHOP CARRY OUT C SERVICE AS PER SERVICE SHEET APPLY AIR TO TRAILER TEST LIGHTING FUNCTION LIFT TRAILER WITH HOIST CHECK SUSPENSION COMPONENTS CHECK KING PIN BOLT TENSION CHECK SKID PLATE CHECK THE UNDERCARRIAGE OF THE TRAILER CARRY OUT GREASING OF AXLES CARRY OUT DE-ADJUSTMENT OF BRAKES REMOVE HUB CAPS AND REMOVE BEARING ADJUSTMENT NUTS REMOVE BEARINGS FROM HUBS CLEAN STUB AXLES AND APPLY NEW FILM OF GREASE TO STUB AXLES CLEAN BEARINGS IN TURBO WASH CLEAN HUBS OF GREASE AND REPACK HUBS AS REQUIRED REMOVED BEARINGS FROM PARTS WASHER BLOW OUT WITH AIR AND REPACK BEARINGS INSTALL BEARINGS TO HUBS INSTALL INNER HUB SEALS INSTALL HUBS TO THE TRAILER AND TENSION-BEARING ADJUSTMENT NUTS SECURE BEARING ADJUSTMENT NUTS WITH RETAINERS REINSTALL HUB CAPS TO AXLES AND TENSION HUB CAPS CARRY OUT ADJUSTMENT OF BRAKES LOWER TRAILER CHECK WHEEL NUT TENSION CHECK ALL LIVERY INCLUDING MUDFLAPS AND DECAL INSPECT MARKER PLATES INCLUDING CON SIGN, CHEVRONS, AND OVERTAKE SIGNAGE CHECK TOP DECK OF TRAILER FOR ALL FUNCTIONALITY APPLY SERVICE STICKER COMPLETE PAPERWORK CLEAN WORK AREA				

Vehicle Details

Registration	479QZK	Next Service	Litres	
Make	STEELBRO	Rego Due	Trans	N/A
Model	ATM OVER 4.5T	Engine #	Air	Yes
Model Series		VIN	Cyl	0
Model Code	SIDELIFTER	Build Date	Body	TRAILER
Colour	BLUE	Odometer/Hr	Prod	2014

Invoice No.	Date	Odometer / Hours	Description	Type
			REMOVE LH CONTAINER LOCK - HIT OUT ROLL PIN PUT LOCK IN VICE AND REMOVE ROLL PIN THAT WAS BENT MACHINED SLIGHTLY LONGER ROLL PIN DOWN TO FIT REFIT CONTAINER LOCK + HIT ROLL PIN IN TESTED - OKAY CHECKED FOR CONTROL BOX DOOR FAULT REMOVED RATCHET STRAP FOUND DOOR LATCH BROKEN REMOVED DOOR LATCH MOVED FRONT CRANE ARMS + BLOCKED STABILIZER LEG REMOVED FRONT STABILIZER LEG PIVOT PIN FOUND BUSH MOVED INSIDE LEG CLEANED SURFACE FITTED NEW BUSH WITH QUICK METAL REFITTED ORIGINAL PIN REPAIRED STOP ON REMOTE REPAIRED CONTROL BOX DOOR FITTED NEW DOOR LATCHES PARKED TRAILER AT SHED 24	
<u>HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE JEFF FOR PRICING ON - 07 3260 8950</u>				

58988	28/03/2024	54787/2351	ACCIDENT DAMAGE	Invoice
INSPECT TRAILER FOR DAMAGE. REMOVED BROKEN MARKER LIGHT AND FLOOD LIGHT. STRAIGHTEND OUT BENT MOUNTING BRACKETS. FITTED NEW LIGHTS AND TESTED ALL OK.				
<u>HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE JEFF FOR PRICING ON - 07 3260 8950</u>				

58987	28/03/2024	54787/2351	ATTEND TO AIR LEAK	Invoice
CHECKED OVER TRAILER - FOUND LEAKING BOOSTER REMOVE AND REPLACE LEAKING BRAKE BOOSTER CHECKED FOR AIR LEAKS ALL OK.				
<u>HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.</u>				

Vehicle Details

Registration	479QZK	Next Service	Litres	
Make	STEELBRO	Rego Due	Trans	N/A
Model	ATM OVER 4.5T	Engine #	Air	Yes
Model Series		VIN	Cyl	0
Model Code	SIDELIFTER	Build Date	Body	TRAILER
Colour	BLUE	Odometer/Hr	Prod	2014

Invoice No.	Date	Odometer / Hours	Description	Type
<i>PHONE JEFF FOR PRICING ON - 07 3260 8950</i>				
58731	19/02/2024	48262/2351	STARTING FAULT	Invoice
<p>BROUGHT VEHICLE INTO WORKSHOP CHECKED FOR STARTING FAULT - FOUND TO BE U/S BATTERY ISOLATOR SWITCH - WAS STUCK ON OFF POSITION GOT SWITCH TO MOVE (VERY TIGHT) - REPLACED SWITCH AND TEST - OK STARTING / CHARGING ALL OK CARRIED OUT WELDING REPAIRS TO STOP BLOCK SURFACES LH & RHR</p> <p><u>HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.</u></p>				
58528	16/01/2024	42915/2351	A SERVICE	Invoice
<p>PARK TRAILER IN WORKSHOP CARRY OUT A SERVICE AS PER SERVICE SHEET APPLY AIR TO TRAILER TEST LIGHTING FUNCTION LIFT TRAILER WITH HOIST CHECK WHEEL BEARINGS FOR MOVEMENT CHECK SUSPENSION COMPONENTS CHECK KING PIN BOLT TENSION CHECK SKID PLATE CHECK THE UNDERCARRIAGE OF THE TRAILER CARRY OUT GREASING OF AXLES CARRY OUT ADJUSTMENT OF BRAKES LOWER TRAILER CHECK WHEEL TENSION CHECK WHEEL BEARING GREASE FOR CONTAMINANTS CHECK ALL LIVERY INCLUDING MUDFLAPS AND DECAL INSPECT MARKER PLATES INCLUDING CON SIGN, CHEVRONS, AND OVERTAKE SIGNAGE CHECK TOP DECK OF TRAILER FOR ALL FUNCTIONALITY APPLY SERVICE STICKER COMPLETE PAPERWORK CLEAN WORK AREA MOVE TRAILER OUT OF WORKSHOP</p> <p>*****</p> <p>BEARING GREASE STARTING TO DISCOLOUR AND MAY NEED A RE-PACK AT NEXT SERVICE 3RD AXLE MAY NEED RE-LINE AT NEXT SERVICE</p> <p><u>HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.</u></p>				
58530	11/01/2024	41907/2351	2 NEW TYRES	Invoice

Vehicle Details

Registration	479QZK	Next Service	Litres	
Make	STEELBRO	Rego Due	Trans	N/A
Model	ATM OVER 4.5T	Engine #	Air	Yes
Model Series		VIN	Cyl	0
Model Code	SIDELIFTER	Build Date	Body	TRAILER
Colour	BLUE	Odometer/Hr	Prod	2014

Invoice No.	Date	Odometer / Hours	Description	Type
STRIP AND FIT 2 NEW TYRES UNBOLTED WHEELS CHECKED THE TYRE FOR ANY LEAKS BUT THERE WASNT LEAKING FROM WHERE THE SCREW WENT IN. BOLTED WHEELS BACK ON TENSIONED ALL WHEELS NUTS <u>HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.</u>				
58433	04/01/2024	30546/2351	REPLACE FAULTY ALTERNATOR	Invoice
PICK UP TRAILER FROM SHED 24 MOVE TRAILER INTO WORKSHOP MADE TESTS/CHECKS TO ASSESS LIFTER STARTING / RUNNING PROBLEMS FOUND ALTERNATOR U/S - ON ORDER REPLACED U/S ALTERNATOR, RECHARGED FLAT BATTERY REPAIRED SMALL SECTION OF CHAFFED WIRING NEAR STARTER MOTOR RE-CHECKED STARTING / CHARGING - ALL OK RE-CHECKED ALL LIFTER FUNCTIONS - ALL OK <u>HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.</u>				
58070	08/11/2023	0	TRAVEL TO ROCKLEA FOR BREAKDOWN	Invoice
PACK UP TRUCK AND TRAVEL TO ROCKLEA VEHICLE WITH FAULT - DRIVER MOVED RETURNED TO WORKSHOP <u>HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.</u>				
57952	17/10/2023	29617	FIT 6 NEW TYRES	Invoice
STRIP AND FIT 6 NEW TYRES 265/70R19.5 TYRES - TENSIONED ALL WHEEL NUTS				
57997	16/10/2023	30546	C SERVICE	Invoice
PARK TRAILER IN WORKSHOP CARRY OUT C SERVICE AS PER SERVICE SHEET APPLY AIR TO TRAILER TEST LIGHTING FUNCTION				

Vehicle Details

Registration	479QZK	Next Service	Litres	
Make	STEELBRO	Rego Due	Trans	N/A
Model	ATM OVER 4.5T	Engine #	Air	Yes
Model Series		VIN	Cyl	0
Model Code	SIDELIFTER	Build Date	Body	TRAILER
Colour	BLUE	Odometer/Hr	Prod	2014

Invoice No.	Date	Odometer / Hours	Description	Type
			<p>LIFT TRAILER WITH HOIST CHECK SUSPENSION COMPONENTS CHECK KING PIN BOLT TENSION CHECK SKID PLATE CHECK THE UNDERCARRIAGE OF THE TRAILER CARRY OUT GREASING OF AXLES CARRY OUT DE-ADJUSTMENT OF BRAKES REMOVE HUB CAPS AND REMOVE BEARING ADJUSTMENT NUTS REMOVE BEARINGS FROM HUBS CLEAN STUB AXLES AND APPLY NEW FILM OF GREASE TO STUB AXLES CLEAN BEARINGS IN TURBO WASH CLEAN HUBS OF GREASE AND REPACK HUBS AS REQUIRED REMOVED BEARINGS FROM PARTS WASHER BLOW OUT WITH AIR AND REPACK BEARINGS INSTALL BEARINGS TO HUBS INSTALL INNER HUB SEALS INSTALL HUBS TO THE TRAILER AND TENSION-BEARING ADJUSTMENT NUTS SECURE BEARING ADJUSTMENT NUTS WITH RETAINERS REINSTALL HUB CAPS TO AXLES AND TENSION HUB CAPS CARRY OUT ADJUSTMENT OF BRAKES LOWER TRAILER CHECK WHEEL NUT TENSION CHECK ALL LIVERY INCLUDING MUDFLAPS AND DECAL INSPECT MARKER PLATES INCLUDING CON SIGN, CHEVRONS, AND OVERTAKE SIGNAGE CHECK TOP DECK OF TRAILER FOR ALL FUNCTIONALITY APPLY SERVICE STICKER COMPLETE PAPERWORK CLEAN WORK AREA *****</p> <p>REPAIRED RH #3 AXLE SHOCK ABSORBER STRAP KIT REMOVED WOOD PLANKS FROM TOP OF CHASSIS REPLACED L/H SIDE MARKER AND R/H LICENCE PLATE LIGHT CUT SQUARE BAR TO SIZE, WELDED FOR SUPPORT, BOLTED RED PLATES BACK GRINDED CLEAN AREAS TO BE WELDED ON ENGINE SUPPORT ENGINE V-GROOVE ON CRACK OF SUPPORT WELDED SECTION ON ENGINE SUPPORT REPLACED RH FRONT AND RH #2 TWISTLOCK HANDLES</p> <p>REPLACE LH REAR TAILLIGHT BAR STRAIGHTENED TAILLIGHT MOUNTING PLATE</p> <p>MADE TESTS/CHECKS TO CONTAINER POSITION SENSOR NOR WORKING FOUND TO BE U/S SENSOR - PARTS ON ORDER</p> <p>FITTED RH REAR PINCH POINT DECAL REPLACED FRONT AND REAR CRANE TOP WEAR PADS REMOVED BROKEN BOLTS FOR WEAR PAD HOLDERS REPLACED FRONT AND REAR CRANE SIDE WEAR PAD TESTED OPERATION PARKED AT SHED 24</p> <p><u>HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.</u></p>	

Vehicle Details

Registration	479QZK	Next Service	Litres	
Make	STEELBRO	Rego Due	Trans	N/A
Model	ATM OVER 4.5T	Engine #	Air	Yes
Model Series		VIN	Cyl	0
Model Code	SIDELIFTER	Build Date	Body	TRAILER
Colour	BLUE	Odometer/Hr	Prod	2014

Invoice No.	Date	Odometer / Hours	Description	Type
BROUGHT VEHICLE INTO WORKSHOP HIT OUT WORN ROLL PIN RE-FIT TWIST LOCK AND HIT NEW ROLL PIN THROUGH POSITIONED WELDER NEAR TRAILER GRIND PAINT OFF FROM ALUMINIUM BRACKET TACKED AND WELDED BROKEN BRACKET TOGETHER USING TIG GRIND WELDED AREA - METAL FATIGUED PAINTED BRACKET CONNECTED LIGHTS - ALL OK <u>HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.</u>				
57195	24/07/2023	0	SUPPLY LIFTER REMOTE BATTERIES	Invoice
SUPPLY LIFTER REMOTE BATTERIES				
57223	17/07/2023	12448	TESTED BATTERY	Invoice
TESTED BATTERY FLAT DUE TO BEING LEFT ON OVER THE WEEKEND REPLACED BATTERY WITH SECONDHAND BATTERY ADJUSTED ALTERNATOR BELT AS REQUIRED NO CHARGE FOR THE BATTERY AS IT WAS SECONDHAND				
57108	11/07/2023	11566	A SERVICE	Invoice
GOT KEYS FOR 331WIF AND DISCONNECTED TRUCK FROM TRAILER RETURNED KEYS FOR 331WIF TO BUCCINI OFFICE MOVED TRAILER INTO WORKSHOP CARRIED OUT A SERVICE NOTE- FOUND 1 SHOCKY STRAP BROKEN RETURNED TRAILER TO SHED 24				
57240	04/07/2023	10434	REPAIR BROKEN BRACKET	Invoice
REMOVED INDICATOR LIGHTS, BRAKE LIGHTS AND REVERSE LIGHT FROM BROKEN BRACKET REMOVED BRACKET CLEANED BRACKET WELDED BROKEN BRACKET TOGETHER PAINTED BRACKET AND RE-ATTACHED TO TRAILER BOLTED LIGHTS ONTO BRACKET REPLACED DAMAGED BOLTS MOVED TRAILER FROM WORKSHOP TO BUCCINI YARD				
57030	26/06/2023	9021	NOT RELEASING BRAKES	Invoice
INSPECT TRAILER NOT RELEASING BRAKES FOUND RHF BOOSTER LEAKING REMOVE AND REPLACE RHF BOOSTER TEST OPERATION				
56921	21/06/2023	8796	BRAKES NOT RELEASING.	Invoice

Vehicle Details

Registration	479QZK	Next Service	Litres	
Make	STEELBRO	Rego Due	Trans	N/A
Model	ATM OVER 4.5T	Engine #	Air	Yes
Model Series		VIN	Cyl	0
Model Code	SIDELIFTER	Build Date	Body	TRAILER
Colour	BLUE	Odometer/Hr	Prod	2014

Invoice No.	Date	Odometer / Hours	Description	Type
			TRAVEL TO BUCCINI YARD PLUMB AIR INTO TRAILER FOUND RELAY VALVE LEAKING WENT TO CLAMP LINES, VALVE STOPPED LEAKING BRAKES RELEASED REMOVED LINES FROM BOOSTERS TO ENSURE NO BACK FEEDING BOOSTERS RETURN TO WORKSHOP	
56622	10/05/2023	0	STARTING ISSUES + HYDRAULICS	Invoice
			REPLACED BATTERY WITH 2ND HAND BATTERY DIDN'T START REPLACED WITH NEW BATTERY AND PUT JUMP STARTER ON AS WELL GOT DRIVER TO DROP CONTAINER OFF AND COME BACK CHECKED FOR STARTING FAULT CHECKED WIRING, FUSES, E STOPS AND REMOTE CLEARED EARTH TERMINAL FROM ENGINE TO CHASSIS CHECKED FOR HYDRAULIC LEAK AT ENGINE REMOVED HYDRAULIC FITTING FITTED NEW FITTING AND TESTED HOUSING STILL LEAKING REMOVED FILTER HOUSING - ALL OK	
56573	04/05/2023	2311	GREASED TRAILER	Invoice
			DRIVE TO BUCCINI YARD GREASED TRAILER REAR END OF CENTRE RAM LEAKING	
56558	03/05/2023	0	TRAILER NOT RELEASING BRAKES	Invoice
			DROVE TO SHED 24 PLUMB AIR INTO TRAILER FOUND RELAY VALVE EXHAUSTING REMOVE LINES FROM BOOSTERS FOUND RHR BOOSTER BACK FEEDING REMOVE RHR LIFT AXLE AIRBAG REMOVE AND REPLACE BOOSTER REFIT AIRBAG TEST BRAKE OPERATION FIX THE TWIST LOCKS - STRAIGHTENED ALL HANDLES AND REPLACED SPRINGS RE-SECURED RHR LOWER RAM PIN	
56455	18/04/2023	653	A SERVICE + CERTIFY CHAINS	Invoice
			COLLECTED TRAILER FROM SHED 24 BROUGHT TRAILER INTO WORKSHOP CARRIED OUT A SERVICE REMOVE CONTAINER CHAINS	

Vehicle Details

Registration	479QZK	Next Service	Litres	
Make	STEELBRO	Rego Due	Trans	N/A
Model	ATM OVER 4.5T	Engine #	Air	Yes
Model Series		VIN	Cyl	0
Model Code	SIDELIFTER	Build Date	Body	TRAILER
Colour	BLUE	Odometer/Hr	Prod	2014

Invoice No.	Date	Odometer / Hours	Description	Type
			CERTIFIED CHAINS REPLACED MARKER PLATES, MUDGUARD, REFLECTOR AND SIDE MARKER LIGHT REMOVE REAR BUMP STOPS STRAIGHTEN THEM UP RE-FIT BUMP STOPS FIT THE CHAIN COVERS AND THE CHAIN TO THE TRAILER REMOVE AND SWAP LIFTER MOTOR BATTERY FIT LIFT CHAINS TO CRANE RETURNED TRAILER TO SHED 24 NOTE- PINCH POINT STICKER DAMAGED ON REAR BUMP STOP	
55400	22/11/2022		C SERVICE AND REPAIRS	Invoice
			BROUGHT VEHICLE INTO WORKSHOP CARRIED OUT TEAR DOWN OF BEARINGS AND BRAKES CLEANED HUBS AND BEARINGS AND PLACED IN TURBO WASHER REMOVED FROM TURBO WASHER AND PLACED AT CORRECT AXLES REPLACED TWIST LOCK HANDLE ON RHS FRONT REPLACED ROLL PIN ON LHS FRONT, TWIST LOCK HANDLE - HAD TO DRILL OUT OLD ROLL PIN AS HAD TROUBLE GETTING IT OUT REPLACED HUBO REPLACED AIRBAG ON 3RD AXLE LHS FRONT STRIPPED DOWN 1ST AND 2ND AXLE FOR RE-LINE AND REPACK KNOCKED OUT ANCHOR PIN BUSHES CLEANED PARTS FOR RE-PACK RE-FIT INNER BEARINGS AND SEALS FIT BRAKE SHOES TO TRAILER ON LHS FILL HUBS WITH GREASE FIT HUB CAPS AND REFIT ALLEN KEY FILL POINT FIT RHS BRAKES REFIT DRUM REFIT WHEELS TENSIONED WHEEL NUTS CHECKED OIL IN LIFT MOTOR PARKED TRAILER AT SHED 24	
55362	16/11/2022		B SERVICE	Invoice
			BROUGHT TRAILER INTO WORKSHOP CARRIED OUT B SERVICE & LIFTER MOTOR TOPPED UP COOLANT RE-HOOKED TRUCK BACK TO TRAILER	
55316	09/11/2022	0	BROKEN TWIST LOCK	Invoice

Vehicle Details

Registration	479QZK	Next Service	Litres	
Make	STEELBRO	Rego Due	Trans	N/A
Model	ATM OVER 4.5T	Engine #	Air	Yes
Model Series		VIN	Cyl	0
Model Code	SIDELIFTER	Build Date	Body	TRAILER
Colour	BLUE	Odometer/Hr	Prod	2014

Invoice No.	Date	Odometer / Hours	Description	Type
REPAIRED RH REAR TWIST LOCK				
55053	29/09/2022	0	BROKEN MUDGUARD AND BRACKET LHS	Invoice
BROUGHT TRAILER INTO WORKSHOP CUT OFF LH #2 AXLE DAMAGED MUDGUARD, BRACKET AND BOLTS STRAIGHTENED MUDGUARD BRACKET AND RE-WELDED TO MOUNTING REPLACED MUDGUARD AND BOLTS PARKED TRAILER AT SHED 24				
54947	12/09/2022	179156	FIT RADIO REMOTE CONTROL RECEIVER	Invoice
DROVE TO BUCCINI YARD TO FIT RADIO REMOTE CONTROL RECEIVER ASSEMBLY AND ALSO FITTED SPARE BUCCINI LIFTER ENGINE RECHARGED BATTERY RECHECKED ENGINE START / RUN AND STOP OFF REMOTE CONTROL - ALL OK RECHECKED LIFTER / CRANE - ALL TRAVEL AND LIFT FUNCTIONS FULLY OPERATIONAL NOTE- REMOTE CONTROL NEEDS ANOTHER SPARE BATTERY				
54612	26/07/2022	174123	FUEL LEAK	Invoice
COLLECTED FROM BUCCINI YARD BROUGHT VEHICLE INTO WORKSHOP REPLACE 2 SPRINGS AND 2 BALLS ON CONTAINER LOCKING PINS REPLACE 1 BROKEN HANDLE ON LOCKING PIN REPLACE RUBBER FUEL LINE ON TRAILER MOTOR REWELD BROKEN BRACKET ON TRAILER MOTOR TRAILER LIFTER MOTOR WASN'T STARTING FOUND OUT FUEL FILTER BRACKET WAS BROKEN REMOVED FILTER AND HOUSING AND BRACKET WELDED BRACKET REFIT FILTER, HOUSING AND BRACKET BLED AIR THROUGH INJECTORS AND FILTER RETURN LINE ON COMMON RAIL HAD A CRACK IN IT REPLACED BATTERY INJECTOR 3 NOT SPRAYING FUEL REMOVED INJECTOR LINES, SPILL LINE AND NUTS REMOVED INJECTOR NOZZLE TO TAKE BROKEN PART FROM LAST NOZZLE TIGHTEN ALL AND PUT BACK TOGETHER - ALL OK KUBOTA V2403 #7EQ2595 INJECTOR PUMP RECALIBRATION CONTAINER LIFT TRAILER. HEAVY VEHICLE WORKSHOP Container lift trailer with Kubota V2403 dropped off with #3 delivery valve out of spec . Remove radiator and inlet manifold to access and remove injector pump. Send out for recalibration. Refit injector pump and removed parts. Check and adjust valve clearances. Fill with new coolant Bleed fuel system and run. runs better but #2 cylinder weak. Remove injectors and test. #2 leaking and spray pattern on #1,2,4 not good. Refer to Peter for ok to repair. Send for repair. Refit injectors and bleed. Start. Runs well. Bleed cooling system.				
54141	20/06/2022	0	CARRY OUT REPAIRS	Invoice

Registration	479QZK	Next Service	Litres	
Make	STEELBRO	Rego Due	Trans	N/A
Model	ATM OVER 4.5T	Engine #	Air	Yes
Model Series		VIN	Cyl	0
Model Code	SIDELIFTER	Build Date	Body	TRAILER
Colour	BLUE	Odometer/Hr	Prod	2014

Invoice No.	Date	Odometer / Hours	Description	Type
INSPECT FOR DAMAGE, TEST AND DIAGNOSE ELECTRICAL REMOVED FRONT ACCESSORY BAR STRAIGHTENED SKID PLATE, GUIDE PLATES AND ACCESSORY BAR MOUNTING PLATES REFITTED ACCESSORY BAR TRACED, LOCATED AND REPAIRED FRONT CRANE PRESSURE SWITCH WIRING AS WIRE WAS BROKEN REPLACE U/S CABLE AND TESTED				
STRAIGHTEN FRONT MOUNTING PLATE FOR ELECTRICAL PLUGS, AIR FITTING AND E STOP.				
54192	20/06/2022	159602	CUTTING OUT UNDER LOAD	Invoice
INSPECTED LIFTER FOUND THAT THE STARTER WAS DRAGGING, REMOVED AND REPLACED STARTER. STRIPPED OLD STARTER AND FOUND IT WAS WORN OUT. REPLACED LIFTER ENGINE MAIN BATTERY WITH A LARGER CCA RATING. FOUND MARKER LIGHTS WERE NOT WORKING ON TRAILER WITH LIGHT TESTER PLUGGED IN. ELECTRICAL SOCKET CHECKED & WAS MISSING CENTRE PIN REPLACED ELECTRICAL SOCKET				
54177	20/06/2022	157506	CARRY OUT REPAIRS	Invoice
STRAIGHTENED REAR LH CONTROL BOX, WELDED BASE OF LHS REAR CONTROL BOX. REFITTED DOOR AND ADJUSTED DOOR & CATCHERS. INCORRECT REAR DOOR LATCH PART FAULT FINDING FOR ECU VOLT CHECKING, SWITCH NOT WORKING FAULTED REALY INSIDE CONTROL BOX, REPLACED & FIXED TESTED NUMEROUS CIRCUITS FOR FAULTS MADE CHECKS & TESTS TO STARTING/CANKING & REMOTE CONTROL IGNITION FAULTS FOUND TO BE U/E ECU POWER SUPPLY MODULE & ALSO FITTED MORE CAPACITY/ HIGHER CRANKING RATE. BATTERY AS PER OEM SPECIFICATIONS. RECHECKED START/SLOW/STOP/RUN FUNCTIONS & ALSO ALL CRANK FUNCTIONS FRONT AND REAR ALL OKAY. APPLIED SHOP AIR TO THE TRAILER AND FOUND BOOSTERS AND RIDE HEIGHT CONTROL VALVE LEAKING, REMOVED AND REPLACED LEAKING BOOSTERS AND RIDE HEIGHT CONTROL VALVE. DIAGNOSE AIR LEAK & AXLE DUMPING AIR FOUND GUIDE HEIGHT VALVE NOT OPERATING CORRECTLY & MIDDLE AXLE LEFT SIDE BLOWN. REMOVE & REFIT NEW GUIDE HEIGHT VALVE & NEW BOOSTER				
54136	09/05/2022	164866	TWIST LOCK / STRAIGHTEN MUDGUARD	Invoice
INSPECTED DAMAGED/CRACKED MUDGUARD AND MOUNTING BRACKET MADE UP A STEEL PLATE REMOVED SEIZED BOLTS FROM BRACKETS BRACKET WASN'T PERFECTLY STRAIGHT, HAD TO MODIFY TO FIT DRILL OUT NEW HOLES TO FIT REAR OF MUDGUARD AND NEW MUDFLAP FOUND NEW NUTS, BOLTS AND WASHERS TIGHTEN ALL NUTS - ALL OK MUDGUARD BRACKET STRAIGHTENED MUDGUARD BRACKET				

Vehicle Details

Registration	479QZK	Next Service	Litres	
Make	STEELBRO	Rego Due	Trans	N/A
Model	ATM OVER 4.5T	Engine #	Air	Yes
Model Series		VIN	Cyl	0
Model Code	SIDELIFTER	Build Date	Body	TRAILER
Colour	BLUE	Odometer/Hr	Prod	2014

Invoice No.	Date	Odometer / Hours	Description	Type
REMOVED BROKEN TWIST LOCK AS THE DOWEL PIN SNAPPED REFIT TWIST LOCK WITH NEW DOWEL PIN				
54090	28/04/2022	153877	A SERVICE	Invoice
MOVED TRAILING INTO WORKSHOP CARRY OUT A SERVICE REPLACED TWO SIDE MARKER LIGHTS REPLACED MISSING REFLECTOR REPAIRED DAMAGED WIRING TO SENSING LIGHT ON SWING LIFTER RETURNED TRAILER TO CUSTOMERS YARD NOTE: REAR LHS LIGHT BAR BENT - MONITOR DEGREASE LIFTER MOTOR ENGINE				
53805	07/03/2022	143918	BREAKDOWN	Invoice
7/3/2022 TRAILER CAME IN WITH A FLAT BATTERY JUMP STARTED AND TESTED - ALL OK ADVISED TO KEEP RUNNING FOR A FEW MINUTES				
53796	04/03/2022	143694	LIFTER ON THE ENGINE	Invoice
4/3/2022 JUMP STARTED THE LIFTER ON THE ENGINE FOUND BATTERY WAS FLAT REPLACED WITH A NEW BATTERY				
53713	17/02/2022	141186/2351	START / RUN FAULTS.	Invoice
ATTEND BUCCINI YARD TO JUMP START VEHICLE - STARTED OK. BUCCINI CALLED SAYING THAT THE LIFTER WONT START ONSITE. RETURNED TO WORKSHOP AND INVESTIGATED. <ul style="list-style-type: none">• FOUND ALTERNATOR LOOSE / NEEDED ADJUSTMENT (WAS CHARGING OK)• FOUND BATTERY / STARTER OK• FOUND ENGINE STARTED / RAN OK AFTER RESET• 4 X ENGINE MOUNTS REQUIRED• 1 X ENGINE FAN REQUIRED. REMOVED AND REPLACED BROKEN ENGINE MOUNT, ENGINE FAN, COOLANT TANK ADDED WIRING CABLES FOR BATTERY ISOLATOR SWITCH AS REQUIRED CLEANED DRIED OIL, TIGHTENED HYDRAULIC FITTING REPAIRED BROKEN WIRES TO HORN CLEANED OUT GREASE AND DEBRIS AROUND HYDRAULIC FILTER AND SOLENOID AREAS LHS AND LOCATED HYDRAULIC OIL LEAK AT FITTING TIGHTENED UP SLIGHTLY LOOSE HYDRAULIC OIL HOSE FITTING -TEST - ALL OK REFITTED HORN WIRES - TEST OK TESTED LIFTER/Crane FUNCTIONS - TESTED ALL OK.				

Vehicle Details

Registration	479QZK	Next Service	Litres	
Make	STEELBRO	Rego Due	Trans	N/A
Model	ATM OVER 4.5T	Engine #	Air	Yes
Model Series		VIN	Cyl	0
Model Code	SIDELIFTER	Build Date	Body	TRAILER
Colour	BLUE	Odometer/Hr	Prod	2014

Invoice No.	Date	Odometer / Hours	Description	Type
53650	03/02/2022	138471	CARRY OUT REPAIRS	Invoice
REMOVE FRONT MUDGUARD MUDFLAPS REPLACE CRACKED MIDDLE GUARD ON RHS TIGHTEN UP LOOSE GUARD MOUNTING BRACKET ON LHS REPLACED WORK LIGHT ON THE FRONT JIB IN THE MIDDLE REATTACHED CHEVRON TO THE REAR, RIVITS HAD CORRODED. STRAIGHTEND LHR LIGHT BAR. STRAIGHTEND AND TIGHTEND UP LHS MIDDLE MUDGUARD BRACKET REPLACED TWIST LOCK HANDLE RHF. FIT BOLTS TO LHR TOOLBOX LID DOOR HINDGE, THEY WERE MISSING. WELDED UP CRACKED REAR CROSS MEMBER. STRAIGHTEND AND WELDED UP LANDING LEG BRACE BRACKET RHS. REPLACE MISSING WORK LIGHT FRONT JIB FRONT MUDGUARDS WERE WORN OUT, REMOVED GUARDS BOLTS THEY WERE CORRODED IN PLACE, ONCE REMOVED REMOVED MUDFLAPS, REATTACHED GUARD TO MOUNTING BRACKET USING NEW NUTS AND WASHERS.				
53640	02/02/2022	138471	CARRY OUT B SERVICE	Invoice
CARRIED OUT B SERVICE. LIFTER MOTOR WAS SERVICED ON INV 53031 DATED 03/11/21. PARKED TRAILER IN WORKSHOP CARRIED OUT B SERVICE AS PER SERVICE SHEET STRAIGHTENED LHS MIDDLE GUARD BRACKET WELDED CRACK IN CROSS MEMBER AT REAR STRAIGHTENED & WELDED LANDING LEG BRACE BRACKET ON RHS REPLACED TWIST LOCK HANDLE ON RHS FRONT REPLACED MISSING BOLT ON LHS REAR TOOLBOX LID RE-RIVETED REAR CHEVRON STRAIGHTENED REAR LEFT LIGHT BAR AS FAR AS IT WOULD GO FIT NEW WORK LIGHT AT FRONT SWING FIT BOLT TO LHS REAR TOOLBOX DOOR AS IT WAS MISSING BOLT ON HINGE REMOVE FRONT MUDFLAPS AS THEY WERE DAMAGED REPLACED 2ND AXLE RHS MUDGUARD STRAIGHTENED & WELDED LANDING LEGBRACE BRACKET ON RHS WELDED CRACK IN CROSS MEMBER AT REAR DEFECTS: BRAKES WILL NEED RELINE AT NEXT SERVICE				
53632	01/02/2022	0	OIL LEAK	Invoice
MOVED TRAILER OFF THE STREET AND PARKED ON FENCE LINE. OPERATE AND INSPECT REAR CRANE HOSES, FOUND ONE LEAKING AND ONE BADLY CRACKED, REMOVED AND REPLACED TWO HOSES CHECK OPERATION ALL OK. NOTE. INSPECTED FRONT CRANE AND ALL HOSES NEED REPLACING DUE TO CRACKS, BALANCE OF REAR HOSES ALSO NEED REPLACING.				
53554	18/01/2022	136432	REPLACE LIFTER BATTERY	Invoice
TESTED FLAT BATTERY ON LIFTER REMOVED AND REPLACED WITH SECOND HAND CHARGED BATTERY TESTED STARTING OF LIFTER MOTOR - ALL OK				
53422	22/12/2021	136423	OIL LEAK	Invoice

Vehicle Details

Registration	479QZK	Next Service	Litres	
Make	STEELBRO	Rego Due	Trans	N/A
Model	ATM OVER 4.5T	Engine #	Air	Yes
Model Series		VIN	Cyl	0
Model Code	SIDELIFTER	Build Date	Body	TRAILER
Colour	BLUE	Odometer/Hr	Prod	2014

Invoice No.	Date	Odometer / Hours	Description	Type
			BROUGHT TRAILER INTO WORKSHOP CHECKED FUEL / HYDRAULIC TANK FOR LEAK FOUND FUEL GUAGE ON OUTSIDE OF TANK LEAKING DRAINED FUEL FROM TANK AND CLEANED UP FUEL LEVEL GUAGE FOUND TANK HAS BEEN PUSHED IN AT FRONT PREVENTING PROPER SQUARE SEAL FIT BOLT TO SEAL AREA REFUELED AND CHECK FOR LEAKS - ALL OK REPLACED MISSING FUEL CAP	
53352	06/12/2021	134050	JUMP START	Invoice
			TRAILER CAME INTO WORKSHOP JUMP STARTED LIFTER MOTOR AND TESTED OPERATION - ALL OK	
53254	25/11/2021	132182	ELECTRICAL ISSUES	Invoice
			BROUGHT TRAILER INTO WORKSHOP CHECKED TRAILER FOR NOT STARTING FOUND TO BE LOOSE ARIAL CONNECTOR CARRIED OUT TESTING ON CRANES TO ASSES FOR POSSIBLE FAULTS ORGANISED AND SECURED VARIOUS WIRING ON CRANES AND CHASSIS AREA'S FOUND BATTERIES FOR REMOTE NOT HOLDING CHARGE - REPLACED WITH SPARE RECHECKED OPERATION - ALL OK	
53031	03/11/2021	125592	LIFTER MOTOR START	Invoice
			11/10/2021 - TOPPED UP ENGINE OIL AND COOLANT ON THE LIFTER MOTOR TIGHTENED UP FILTER HOUSING 20/10/2021 - MADE TESTS TO LIFTER MOTOR REMOTE FOUND E STOP SWITCH ON REMOTE DAMAGED REMOVED AND REPLACED ESTOP AND TESTED ALL OK 21/10/2021 - TRAILER CAME INTO WORKSHOP AS SIDE LOAD WOULDNT START REMOVED AND REPLACED BATTERY - TESTED ALL OK INSPECTED BURNT OUT WIRING AT ENGINE REMOVED EARTH WIRING FROM CHASSIS TO ENGINE FITTED NEW CABLE STARTED ENGINE AND CHECKED OPERATION - ALL OK 3/11/2021 - CHECKED FOR ENGINE NOT STARTING FAULT CHECKED BATTERIES, WIRING, FUSES AND RELAYS FOUND GLOW PLUG WIRING RUBBED THROUGH ON ENGINE BLOCK REPAIRED WIRING - ALL OK SECURED BROKEN FUEL FILTER BRACKET - USED ZIP TIE THROUGH HOUSING BOLT HOLE AND MOUNTING PLATE BOLT HOLE REPLACED MEGA FUSE AT STARTER MOTOR 4/11/2021 - CHECKED ENGINE NO START/RUN FAULT TIGHTENED LOOSE E STOP BUTTON ON CONTROL BOX AND ON CHASSIS RECHECKED WIRING AND SWITCHES - ALL OK SUPPLY SPARE BATTERY FOR REMOTE CONTROL 8/11/2021 - JUMP START SIDE LOAD AND TESTED OPERATION - ALL OK SIDELOADER CAME IN NOT STARTING	

Vehicle Details

Registration	479QZK	Next Service	Litres	
Make	STEELBRO	Rego Due	Trans	N/A
Model	ATM OVER 4.5T	Engine #	Air	Yes
Model Series		VIN	Cyl	0
Model Code	SIDELIFTER	Build Date	Body	TRAILER
Colour	BLUE	Odometer/Hr	Prod	2014

Invoice No.	Date	Odometer / Hours	Description	Type
REMOVED AND REPLACED BATTERY PLACED OLD BATTERY ON CHARGE INSPECTED BURNT WIRING AT ENGINE REMOVED EARTH WIRING FROM CHASSIS TO ENGINE AND REPLACED WITH NEW CABLE STARTED ENIGNE AND CHECKED OPERATION - ALL OK REMOVED AND REPLACED DAMAGED MUDGUARD AND MUDFLAP				
52892	23/09/2021	120202	TWIST LOCK REPAIRS	Invoice
TRAILER CAME IN WITH TWIST LOCKS FAILED CONTAINER LIFTED UP WITH LOCKS STILL ATTACHED SNAPPING ALL FOUR CONTAINER LOCKS OFF THEIR HANDLES KNOCKED ALL FOUR ROLL PINS OUT ASSESSED REUSABILTY OF THEM AND REPLACED ONE REFIT ALL CONTAINER LOCKING PINS BACK WITH NEW DETENT BALLS AND ROLL PINS INSPECTED TRAILER FOR ANY FURTHER DAMAGE - ALL OK LUBED UP CONTAINER LOCKS				
52884	13/09/2021	119807	TRAILER REPAIRS	Invoice
13/9/2021 - CHECKED TRAILER LIGHTING - FOUND AND RESET PINS ON TRAILER SOCKET AND TESTED - ALL OK 17/9/2021 - REPAIRED RHS CONTAINER PIN - HANDLE ROLL PIN HAS SNAPPED OFF HIT OUT OLD ROLL PIN AND REPLACED WITH NEW REASSEMBLED PIN INTO TRAILER 20/9/2021 - INVESTIAGED UNIT NOT LOADING CONTAINERS UNIT WAS OPERATING WHEN ARRIVED UNDID CHAINS WHEN UNIT WAS ON THE GROUND AND CHECKED OIL LEVEL TRAILER ALL OK				
52826	08/09/2021	116437	BATTERY REPLACEMENT	Invoice
TRAILER CAME IN WITH FLAT LIFTER BATTERY REMOVED AND REPLACED BATTERY TESTED LIFTER OPERATION - ALL OK				
52581	29/07/2021	109681	BRAKE ISSUES	Invoice
CHECKED FOR BRAKE FAULT CHECKED AIR FITTINGS, AIRLINES, BRAKE BOOSTERS AND SLACK ADJUSTER - ALL OK FOUND BOOSTER OVERSTROKE RE-ADJUSTED BRAKES AND TESTED OPERATION - ALL OK				
52413	05/07/2021	109213	C SERVICE AND REPAIRS	Invoice
CARRY OUT C SERVICE ON TRAILER LIFT VEHICLE UP AND REMOVE HUBS (COMPLETE INCLUDING WHEELS) CLEAN ALL BEARINGS AND HUBS AND INSPECT BEARINGS FOR WEAR - ALL OK REPACK WITH SEMI SYNTHETIC GREASE AND REPLACE HUB SEALS REFIT ALL WHEELS, TENSION TO SPEC AND ADJUST BRAKES REMOVED FRONT CRANE HYDRAULIC BLOCK PROTECTION PLATE STRAIGHTENED AND PAINTED BASH PLATE REMOVED RADIATOR MOUNTING BRACKETS AND FAN SHROUD LOOSEENED FAN BELT REMOVED BROKEN ENGINE FAN AND FITTED A NEW ONE.				

Vehicle Details

Registration	479QZK	Next Service	Litres	
Make	STEELBRO	Rego Due	Trans	N/A
Model	ATM OVER 4.5T	Engine #	Air	Yes
Model Series		VIN	Cyl	0
Model Code	SIDELIFTER	Build Date	Body	TRAILER
Colour	BLUE	Odometer/Hr	Prod	2014

Invoice No.	Date	Odometer / Hours	Description	Type
REPLACED FIVE WORKLIGHTS AND TESTED ALL OK REPAIRED TWO WORKLIGHTS AND TESTED REPLACED RHS FRONT MARKER LIGHT AND REPLACED TWO MISSING REFLECTORS REPLACED DAMAGED SENSOR CABLE ON FRONT CRACK AND CHECKED CRANE FUNCTION - ALL OK SERVICED MINI LIFTER MOTOR . TESTED MINI LIFTER AND TRAILER - ALL OK DEFECTS: REAR ENGINE MOUNTS CRACKED BUT NO MOVEMENT - MONITOR FRONT RHS SUPPLY HOSE TO BOOSTER CHAFFED DOWN TO BRAID NOT LEAKING - MARKED AIR BAGS HAVE CRACKS IN BASE - MONITOR - NOT LEAKING AIR FRONT 20/40 CYLINDER WEAPING - MONITOR FRONT RHS MUDGUARD MOUNTING TUBE BENT DOWNWARDS ANTISALE BRACKETS MISSING ON BOTH SIDES FRONT MUD FLAPS CHAFFED AGAINST TYRES				
52343	23/06/2021	106108	REPLACE TWIST LOCK	Invoice
VEHICLE CAME IN WITH A BROKEN TWIST LOCK REMOVED AND REPLACED TWIST LOCK AND TESTED - ALL OK				
52303	18/06/2021	10533	TRAILER LIGHT INTERMITTENT	Invoice
TRAILER CAME IN WITH LIGHTS WORKING INTERMITTENTLY INSPECTED PLUGS ON TRUCK AND TRAILER FOUND PINS ON TRAILER DAMAGED INWARDS ADJUSTED PINS AND CHECKED OPERATION OF LIGHTS ALL OK				
52160	26/05/2021	101818	A SERVICE & HYDRAULIC LEAK	Invoice
CARRY OUT A SERVICE ON TRAILER TOPPED UP ENGINE OIL TOPPED UP COOLANT INSPECTED HYDRAULIC TANK OIL LEAK CHECKED ALL FITTINGS FOR TIGHTNESS - ALL OK FOUND HYRDAULIC TANK CRACKED AT THE OUTLET BOSS DRAINED HYRDAULIC OIL FROM TANK REMOVED ALL FITTINGS, HYRAULIC HOSES, FILTER HOUSING AND FUEL HOSES REMOVED TANK FOR WELDING REPAIRS AND FITTED ONCE REPAIRED DEFECT: CRACK AT REAR OF CHASSIS ON CROSS BEAM - MARKED WITH PINK PAINT LANDING GEAR STABLISER LEGS CRACKED REAR AXLE TYRES WORN - NEED REPLACING OIL WEEP AT ENGINE OIL CAP - MONITOR				
52144	24/05/2021	101048	JUMP START VEHICLE	Invoice
ATTEND TO TRAILER MOTOR JUMP START BATTERY ISOLATOR WAS NOT TURNED OFF BATTERY VOLTAGE WAS AT 9 VOLTS TRIED TO START BUT DIDNT START THE FIRST TIME - DIAGNOSE AS AN INTERMITTENT STARTING ISSE WHEN BATTERIES ARE FLAT STARTED THE SECOND TIME AND CHARGING AT 14 VOLTS				

Vehicle Details

Registration	479QZK	Next Service	Litres	
Make	STEELBRO	Rego Due	Trans	N/A
Model	ATM OVER 4.5T	Engine #	Air	Yes
Model Series		VIN	Cyl	0
Model Code	SIDELIFTER	Build Date	Body	TRAILER
Colour	BLUE	Odometer/Hr	Prod	2014

Invoice No.	Date	Odometer / Hours	Description	Type
51955	30/04/2021	96691	CHECKED FOR DAMAGE	Invoice
INSPECTED TRAILER FOR DAMAGE AFTER BEING PICKED UP BY A FORKLIFT. VEHICLE CAME IN AFTER BEING LIFTED WHILST CONTAINER STILL ATTACHED INSPECTED VEHICLE FOR DAMAGE AND DIAGNOSED THAT THE 2 X SHOCKIE STRAPS HAVE BEEN SNAPPED AND THAT THE LHF TWIST LOCK RETAINING BOLT HAS SNAPPED. FITTED NEW TWIST LOCK DETENT BALL AND REFITTED TWIST LOCK. REFITTED TWIST LOCK HANDLE AND REPLACED BROKEN BOLT WITH A NEW ONE.				
51729	22/03/2021	88005/2074	BOOSTER AND BATTERY REPLACEMENT	Invoice
WORK CARRIED IUT ON THE 15/3/2021 DISASSEMBLED REAR RIGHT HUB FOR INSPECTION - REMOVED TYRES AND DRUM TO INSPECT BRAKE LINERS AND DRUM - NO FAULTS FOUND FOUND BOSTER FAILED - REMOVED AND REPLACED BOOSTER. ADJUSTED BRAKES ON COMPLETE UNIT TESTED BRAKES - CARRIED OUT BRAKE TEST - ALL PASSED AND OK. CHECKED STARTING FAULT - FOUND BATTERY UNUSABLE. REMOVED AND REPLACED BATTERY - TESTED OK CHECKED TRAILER AND CRANE - TESTED OK				
51720	19/03/2021	89430	HANDLE MISSING CAMLOCK	Invoice
CARRY OUT INSPECTION OF CAMLOCK HANDLE FAILURE - MISSING REMOVED CAMLOCK SHAFT AND BALL FITTED NEW CAMLOCK AD HANDLE ONTO VEHICLE REPLACED BOLTS LUBE UNIT AND TESTED - OK				
51656	15/03/2021	86981	ENGINE COOLANT	Invoice
DATE WORK CARRIED OUT: 10/03/2021 WORK CARRIED OUT: TOP UP LIFTER ENGINE WITH GREEN COOLANT DEFECTS NOTED • NONE NOTED				
51648	12/03/2021	87955	ATTEND BREAKDOWN BRAKES STUCK	Invoice

Vehicle Details

Registration	479QZK	Next Service	Litres	
Make	STEELBRO	Rego Due	Trans	N/A
Model	ATM OVER 4.5T	Engine #	Air	Yes
Model Series		VIN	Cyl	0
Model Code	SIDELIFTER	Build Date	Body	TRAILER
Colour	BLUE	Odometer/Hr	Prod	2014

Invoice No.	Date	Odometer / Hours	Description	Type
TRAILER BRAKES LOCKED UP RHS. CALL OUT TO ALABERTON RD at ALBERTON. LOCK IN RHR BRAKE BOOSTER AND WIND OFF SLACK ADJUSTER ENSURE UNIT RELEASED AND TEST UNIT				
51654	05/03/2021	84991	LIFT AXLE AIR BAG	Invoice
DATE WORK CARRIED OUT: 04/03/2021 WORK CARRIED OUT: REPLACE BLOWN LAZY AIR BAG FROM UNIT DEFECTS NOTED • NONE NOTED				
51297	19/01/2021	74773	A & C SERVICE & CHAINS	Invoice
DATE WORK CARRIED OUT: 08/01/2021 – 19/01/2021 WORK CARRIED OUT: CARRIED OUT A, B & C SERVICE REPLACED REAR ENGINE MOUNTS ON LIFTER ENGINE REPLACED HYDRAULIC FILTER REMOVED CHAINS TO SEND AWAY FOR TESTING CHAINS FAILED TESTING – NEED REPLACING FITTED NEW CHAINS FITTED CHAIN LOCKS TO NEW CHAINS REPLACED BATTERY TESTED – ALL OK				
51235	04/01/2021	73206	HYDRAULIC HOSE LEAK	Invoice
DATE WORK CARRIED OUT: 04/01/2021 WORK CARRIED OUT: INSPECTED BLOWN HYDRAULIC HOSE ON THE FRONT OF THE LIFTER REMOVED HOSE & TRAVELLED TO SUPPLIER TO GET NEW HOSE MADE UP REPLACED HOSE TO LIFTER PUT SPIRAL GUARD ON HOSES TIDED UP WIRING TESTED FOR LEAKS – ALL OK OIL LEVEL - OK				

Vehicle Details

Registration	479QZK	Next Service	Litres	
Make	STEELBRO	Rego Due	Trans	N/A
Model	ATM OVER 4.5T	Engine #	Air	Yes
Model Series		VIN	Cyl	0
Model Code	SIDELIFTER	Build Date	Body	TRAILER
Colour	BLUE	Odometer/Hr	Prod	2014

Invoice No.	Date	Odometer / Hours	Description	Type
51138	23/12/2020	71031	BOLTS IN MUDGUARD	Invoice

DATE WORK CARRIED OUT: 22/12/2020

WORK CARRIED OUT:

REPLACED BOLTS IN RHR MUDGUARD TO REPAIR AS BOLTS HAD BEEN PULLED OUT

50890	13/11/2020	62356	LHS LIGHTING	Invoice
-------	------------	-------	--------------	---------

DATE WORK CARRIED OUT: 13/11/2020

WORK CARRIED OUT:

REPLACED DAMAGED LHR SIDE TAIL LIGHTS & TEST - ALL OK

50878	12/11/2020	61964	TWISTLOCK	Invoice
-------	------------	-------	-----------	---------

DATE WORK CARRIED OUT: 12/11/2020

WORK CARRIED OUT:

INSPECTED BROKEN TWISTLOCK

RE-ASSEMBLED TWISTLOCK

CHECKED OPERATION – ALL OK

50767	28/10/2020	58939	REPAIR ENGINE CRADLE CRACK	Invoice
-------	------------	-------	----------------------------	---------

DATE WORK CARRIED OUT: 28/10/2020

WORK CARRIED OUT:

REPAIRED ENGINE CRADLE CRACK

FIT BOLTS TO ENGINE CRADLE

REMOVED AND REPLACED WORN KING PIN & BOLTS

50789	27/10/2020	58939	A SERVICE	Invoice
-------	------------	-------	-----------	---------

DATE WORK CARRIED OUT: 27/10/2020

WORK CARRIED OUT:

CARRIED OUT A SERVICE ON TRAILER AND LIFTER AS PER HVW SERVICE SHEET.

FURTHER ACTION REQUIRED -

REQUIRE TYRES RR U/S & LR U/S

LIFTER ENGINE CRADLE CRACKED

FR MUD FLAP TORN

KING PIN U/S

Vehicle Details

Registration	479QZK	Next Service	Litres	
Make	STEELBRO	Rego Due	Trans	N/A
Model	ATM OVER 4.5T	Engine #	Air	Yes
Model Series		VIN	Cyl	0
Model Code	SIDELIFTER	Build Date	Body	TRAILER
Colour	BLUE	Odometer/Hr	Prod	2014

Invoice No.	Date	Odometer / Hours	Description	Type
LIFTER ENGINE FRAME CRACKED				
50733	23/10/2020	58272	JUMPSTART - AND FUSE ISSUE	Invoice
DATE WORK CARRIED OUT: 23/10/2020 WORK CARRIED OUT: ATTEND BT YARD SWAPPED LIFTER ENGINE BATTERY WITH GOOD 2ND HAND ONE TEST OPERATION - TEST ALL OK DRIVER ADVISED MECHANIC THAT THE LIFTER LEGS STUCK DOWN. FOUND THE REMOTE BATTERY WAS FLAT, SWAPPED BATTERY TESTED - ALL GOOD. TRAILER CAME INTO THE WORKSHOP WITH A NO START ISSUE REMOVED THE FUSE BOX PANEL FOUND A WIRE FOR THE E-STOP HAD COME OUT - REFITTED AND TESTED - ALL GOOD.				
50513	23/09/2020	54277	JUMP START	Invoice
DATE WORK CARRIED OUT: 23/09/2020 WORK CARRIED OUT: ATTEMPTED TO JUMP START REPLACED FAULTY BATTERY STARTED ENGINE				
50424	23/09/2020	54274	CRANE STOPPER -	Invoice
WORK CARRIED OUT:16/09/2020 - 19/09/2020 RR - 15203 REPLACE R/S CRANE STOPPER ON THE REAR OF THE TRAILER REPAIR L/S CRANE STOPPER RR - 15205 REPLACED DAMAGED RR INDICATOR LIGHT RR - 15206 REPAIR RHM TWIST LOCK HANDLE RR - 15204 INSPECT AIR LEAK - FOUND SPLIT IN REAR LEFT AIR BAG HS BEEN REPLACED				
50329	25/08/2020	51879	COOLANT TOP UP	Invoice

Vehicle Details

Registration	479QZK	Next Service	Litres	
Make	STEELBRO	Rego Due	Trans	N/A
Model	ATM OVER 4.5T	Engine #	Air	Yes
Model Series		VIN	Cyl	0
Model Code	SIDELIFTER	Build Date	Body	TRAILER
Colour	BLUE	Odometer/Hr	Prod	2014

Invoice No.	Date	Odometer / Hours	Description	Type
DATE WORK CARRIED OUT: 25/08/2020				
WORK CARRIED OUT: TOPPED UP COOLANT IN LIFTER				
50272	03/08/2020	47529	A SERVICE & REPAIRS	Invoice
DATE WORK CARRIED OUT: 03/08/2020				
WORK CARRIED OUT: CARRIED OUT A SERVICE AS PER HVW SERVICE SHEET ADJUST LHF WHEEL BEARING REPLACE BROKEN GREASE NIPPLE ON TILT RAM REAR MODULE. FURTHER ACTION REQUIRED- FRONT AXLE RHS TYRE LOW HUB OIL IS STARTING TO SHOW WEAR LR SECOND AIR BAG SPLIT SLIGHT LEAKS ON FRONT 20/40 RAM				
50178	03/08/2020	47246	MISSING BOLT ON REMOTE DOORS	Invoice
DATE WORK CARRIED OUT: 03/08/2020				
WORK CARRIED OUT: REPLACED MISSING BOLT ON REMOTE DOORS. CHECKED DOORS CLOSE AND CLOSES FINE RR13854				
50139	28/07/2020	0	INSPECT DAMAGE - RR 106226	Invoice
DATE WORK CARRIED OUT: 28/07/2020				
WORK CARRIED OUT: INSPECT DAMAGE ON PROTECTION PLATE FOR CONTROL VALVES REMOVED PLATE AND CHECKED FOR OTHER DAMAGE RR: 106226				
50099	23/07/2020	45437	REPAIR BROKEN WIRING	Invoice

Vehicle Details

Registration	479QZK	Next Service	Litres	
Make	STEELBRO	Rego Due	Trans	N/A
Model	ATM OVER 4.5T	Engine #	Air	Yes
Model Series		VIN	Cyl	0
Model Code	SIDELIFTER	Build Date	Body	TRAILER
Colour	BLUE	Odometer/Hr	Prod	2014

Invoice No.	Date	Odometer / Hours	Description	Type
DATE WORK CARRIED OUT: 23/07/2020				
WORK CARRIED OUT: INSPECTED AND REPAIRED BROKEN WIRING HARNESS TO LIFTER REMOTE TESTED - OK				
50058	09/07/2020	1869	WIRELESS REMOTE	Invoice
DATE WORK CARRIED OUT: 9/07/2020				
WORK CARRIED OUT: CHECKED FOR WIRELESS REMOTE & TRANSMITTER CHECKED WIRING MODULES & REMOTES TEST ALL FUNCTIONS FOUND REMOTE FAULTY SUPPLIER TESTED AND ADVISED IT NEEDED TO BE SENT TO WA				