



## Vehicle History

### Vehicle Details

Registration	331WIF	Next Service	Litres	
Make	IVECO	Rego Due	Trans	N/A
Model	STRALIS	Engine #	Air	Yes
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	PRIMEMOVER
Colour	WHITE	Odometer	Prod	2016

Invoice No.	Date	Odometer	Description	Type
61277	23/07/2025	449549	OIL AND LIGHT ISSUE	Invoice
REPLACED PARK LIGHT BULB TESTED ALL LIGHTS - REVERSE LIGHTS INOP JACKED UP CAB AND TOPPED OIL UP WITH 9L REMOVED LHTAIL LIGHT LENS AND REPLACED BRAKE LIGHT GLOBE REFIT TAIL LIGHT LENS TESTED LIGHTS - ALL OKAY ***RECEIVE A \$25 DISCOUNT FOR ANY POSITIVE GOOGLE REVIEW ON OUR COMPANY GOOGLE WEBPAGE - HEAVY VEHICLE WORKSHOP*** <b><u>HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES &amp; MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING &amp; BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE THE STORE FOR PRICING ON - 07 3260 8950</u></b>				
60967	21/05/2025	441251	NO START	Invoice
TRAVEL TO BT YARD VEHICLE NO START TRIED JUMP STARTING - FAILED CHECKED FUSES - FOUND BLOWN 30A FUSE AT BATTERY REPLACED FUSE AND TESTED - FUSE BLEW AGAIN WAS INFORMED KEY BARREL REPLACED RECENTLY INSPECTED WIRING AROUND KEY BARREL- WIRING PINCHED PINCHED WIRES CAUSING SHORT FIXED WIRING AROUND KEY BARREL TESTED VEHICLE - ALL OKAY VEHICLE NOW STARTS <b><u>HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES &amp; MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING &amp; BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE THE STORE FOR PRICING ON - 07 3260 8950</u></b> ***RECEIVE A \$25 DISCOUNT FOR ANY POSITIVE GOOGLE REVIEW ON OUR COMPANY GOOGLE WEBPAGE - HEAVY VEHICLE WORKSHOP***				
60865	28/04/2025	441251	DASH SWITCH	Invoice
REPLACE DAMAGED FUEL SENDER DAMAGED DUE TO IMPACT REPLACE WORN A/C BELT REPLACE TORN INTAKE HOSE REPLACE BRAKE PEDAL RUBBER REPLACE FAULTY DIFF LOCK SWITCH REPLACE IGNITION BARREL AS KEY GETTING STUCK IN BARREL REPLACE DAMAGED REAR MUDGAURD BRACKETS AND MUDGUARD AND LH TAIL LIGHT DUE TO IMPACT DAMAGE REPLACE DAMAGED FUEL SENDER DAMAGED DUE TO IMPACT				

## Vehicle Details

Registration	331WIF	Next Service	Litres	
Make	IVECO	Rego Due	Trans	N/A
Model	STRALIS	Engine #	Air	Yes
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	PRIMEMOVER
Colour	WHITE	Odometer	Prod	2016

Invoice No.	Date	Odometer	Description	Type
-------------	------	----------	-------------	------

REPLACED DOOR LOCK KEY BARRELS  
REPLACED FAN BELT

PARK VEHICLE IN WORKSHOP  
CARRY OUT C SERVICE AS PER SERVICE SHEET  
CARRY OUT WALK AROUND VISUAL INSPECTION  
SECURE HOIST ON TRUCK  
CHECK ALL LIGHTS INCLUDING ALL REVERSE LAMPS AND BEEPERS  
CHECK WIPER AND WASHER OPERATION  
CHECK BATTERY LEVELS, TERMINALS AND CLAMPS  
LIFT CAB/BONNET TO ACCESS ENGINE BAY  
REPLACE CABIN AND ENGINE AIR FILTERS  
CHECK ALL BELTS AND MOUNTS  
LIFT TRUCK ON HOIST  
CARRY OUT VISUAL INSPECTION OF UNDERCARRIAGE (DRIVE LINE AND SUSPENSION COMPONENTS)  
DRAIN ENGINE OIL AND CHANGE FILTER  
ADJUST BRAKES AND CHECK BRAKE THICKNESSES  
CHECK AND ADJUST CLUTCH IF APPLICABLE  
CHECK GEARBOX OIL LEVEL AND QUALITY REPLACE IF REQUIRED  
CHECK DIFF OIL LEVEL AND QUALITY REPLACE IF REQUIRED  
CARRY OUT GREASING OF TRUCK  
LOWER TRUCK  
FIL ENGINE OIL AND CHECK ENGINE OIL  
TOP-UP COOLANT IF REQUIRED  
LOWER CAB/BONNET AND SECURE IN PLACE  
FIT SERVICE STICKER  
COMPLETE PAPERWORK  
REMOVE HOIST  
NOTE  
TOPPED UP ENGINE OIL  
TIGHTENED FUEL HOSE FITTINGS @ PUMP  
TIGHTENED P/STEERING HOSE CLAMP  
REMOVED LH #2 FIDD MUDGUARDS AND TAIL LIGHTS  
REPLACED TAIL LIGHT ASSEMBLY AND HOLDER  
STRAIGHTENED LH REAR MUDGUARD POLE  
ROAD TEST - OKAY  
RETURN TO BT YARD

**HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD -  
STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS  
WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.  
PHONE THE STORE FOR PRICING ON - 07 3260 8950**

\*\*\*RECEIVE A \$25 DISCOUNT FOR ANY POSITIVE GOOGLE REVIEW ON OUR COMPANY GOOGLE WEBPAGE -  
HEAVY VEHICLE WORKSHOP\*\*\*

## Vehicle Details

Registration	331WIF	Next Service	Litres	
Make	IVECO	Rego Due	Trans	N/A
Model	STRALIS	Engine #	Air	Yes
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	PRIMEMOVER
Colour	WHITE	Odometer	Prod	2016

Invoice No.	Date	Odometer	Description	Type
			TRAVEL TO BREAKDOWN AT PORT OF BRISBANE MOTORWAY FILL 40L DIESEL BLEED SYSTEM RETURN TO WORKSHOP <b><u>HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES &amp; MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING &amp; BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE THE STORE FOR PRICING ON - 07 3260 8950</u></b> ***RECEIVE A \$25 DISCOUNT FOR ANY POSITIVE GOOGLE REVIEW ON OUR COMPANY GOOGLE WEBPAGE - HEAVY VEHICLE WORKSHOP***	
60781	03/04/2025	437082	LABOUR - BUCCINI	Invoice
			TEST DROVE VEHICLE RETURNED TO BT YARD  <b><u>HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES &amp; MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING &amp; BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE THE STORE FOR PRICING ON - 07 3260 8950</u></b> ***RECEIVE A \$25 DISCOUNT FOR ANY POSITIVE GOOGLE REVIEW ON OUR COMPANY GOOGLE WEBPAGE - HEAVY VEHICLE WORKSHOP***	
60759	31/03/2025	437082	DEFECTS	Invoice
			DIAGNOSE AIRCON ISSUE GETS WARM WHEN DRIVING TEST DRIVE TO PORT AND BACK NEEDS REGAS NO APPARANT LEAKS REGAS SYSTEM  <b><u>HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES &amp; MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING &amp; BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE THE STORE FOR PRICING ON - 07 3260 8950</u></b>  ***RECEIVE A \$25 DISCOUNT FOR ANY POSITIVE GOOGLE REVIEW ON OUR COMPANY GOOGLE WEBPAGE - HEAVY VEHICLE WORKSHOP***	
60680	13/03/2025	437082	DEFECTS	Invoice
			JUMP STARTED VEHICLE MOVED INTO WORKSHOP CHECKED FOR FAN FAULT BLOWER FAN FAULTY REMOVED FRONT DASH PANELS TO ACCESS BLOWER MOTOR REMOVED ENTIRE DASH TO GET FAN MOTOR REMOVED FAN MOTOR AND RESISTOR	

**Vehicle Details**

<b>Registration</b>	331WIF	<b>Next Service</b>	<b>Litres</b>	
<b>Make</b>	IVECO	<b>Rego Due</b>	<b>Trans</b>	N/A
<b>Model</b>	STRALIS	<b>Engine #</b>	<b>Air</b>	Yes
<b>Model Series</b>		<b>VIN</b>	<b>Cyl</b>	0
<b>Model Code</b>		<b>Build Date</b>	<b>Body</b>	PRIMEMOVER
<b>Colour</b>	WHITE	<b>Odometer</b>	<b>Prod</b>	2016

Invoice No.	Date	Odometer	Description	Type
			FIT REPLACEMENT FAN MOTOR INSIDE CAB REFIT ALL PANELS TO DASH TESTED OPERATION CLEANED DASH RETURNED TO SHED 24 <b><u>HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES &amp; MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING &amp; BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE THE STORE FOR PRICING ON - 07 3260 8950</u></b> ***RECEIVE A \$25 DISCOUNT FOR ANY POSITIVE GOOGLE REVIEW ON OUR COMPANY GOOGLE WEBPAGE - HEAVY VEHICLE WORKSHOP***	

<b>60599</b>	<b>24/02/2025</b>	<b>436272</b>	<b>C SERVICE</b>	<b>Invoice</b>
			PARK VEHICLE IN WORKSHOP CARRY OUT C SERVICE AS PER SERVICE SHEET CARRY OUT WALK AROUND VISUAL INSPECTION SECURE HOIST ON TRUCK CHECK ALL LIGHTS INCLUDING ALL REVERSE LAMPS AND BEEPERS CHECK WIPER AND WASHER OPERATION CHECK BATTERY LEVELS, TERMINALS AND CLAMPS LIFT CAB/BONNET TO ACCESS ENGINE BAY REPLACE CABIN AND ENGINE AIR FILTERS CHECK ALL BELTS AND MOUNTS LIFT TRUCK ON HOIST CARRY OUT VISUAL INSPECTION OF UNDERCARRIAGE (DRIVE LINE AND SUSPENSION COMPONENTS) DRAIN ENGINE OIL AND CHANGE FILTER ADJUST BRAKES AND CHECK BRAKE THICKNESSES CHECK AND ADJUST CLUTCH IF APPLICABLE CHECK GEARBOX OIL LEVEL AND QUALITY REPLACE IF REQUIRED CHECK DIFF OIL LEVEL AND QUALITY REPLACE IF REQUIRED CARRY OUT GREASING OF TRUCK LOWER TRUCK FIL ENGINE OIL AND CHECK ENGINE OIL TOP-UP COOLANT IF REQUIRED LOWER CAB/BONNET AND SECURE IN PLACE FIT SERVICE STICKER COMPLETE PAPERWORK REMOVE HOIST NOTE REPLACED FAN BELT AND TIGHTENED FAN BLADE BOLTS REPLACE CONDENSOR - NEEDS REGAS START RUNNING FAN AND SHROUD SHROUD PLASTIC PINS SNAPPED OFF ON REMOVAL REPLACED WITH NUTS AND BOLTS TURBO HOSE LEAKING MINOR SPRING BUSH MOVEMENT P/S LOW PRESSURE HOSE LEAKING FUEL PUMP FITTING LEAKING FIT STRETCH BELT ON AIR CON COMPRESSOR OIL LIGHT WAS ON DUE TO OVERFILL DRAINED SMALL AMOUNT OF OIL REACHED CORRECT LEVEL - TESTED TRUCK - ALL OKAY  <b><u>HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES &amp; MORE ABOARD -</u></b>	

**Vehicle Details**

Registration	331WIF	Next Service	Litres	
Make	IVECO	Rego Due	Trans	N/A
Model	STRALIS	Engine #	Air	Yes
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	PRIMEMOVER
Colour	WHITE	Odometer	Prod	2016

Invoice No.	Date	Odometer	Description	Type
<b><u>STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING &amp; BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE JACOB FOR PRICING ON - 07 3260 8950</u></b>				
60584	19/02/2025	425921	RESEAL FUEL PUMP - BACK COVER	Invoice
RESEAL FUEL PUMP - BACK COVER LEAKING  FIT ORIGINAL FITTING TO NEW FUEL PUMP FIT NEW FUEL PUMP ATTACHED ALL FUEL HOSES, PRIMED FUEL SYSTEM STARTED ENGINE AND CHECKED FOR LEAKS CLEANED SIDE OF ENGINE FROM FUEL LEAK TEST DROVE VEHICLE AND RE-CHECKED LEAKS  <b><u>HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES &amp; MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING &amp; BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE THE STORE FOR PRICING ON - 07 3260 8950</u></b>				
60540	13/02/2025	436272	PLEASE REPLACE BLIND SPOT MIRROR	Invoice
PLEASE REPLACE BLIND SPOT MIRROR ON LHS AND BLUE AIR HOSE TRAILER CONNECTOR, CHECK FIRE EXTINGUISHER FITTED AND IN DATE. YARD TO COLLECT AM TOMORROW  BLUE AIR HOSE REPLACED CHECKED LIGHTS REPLACED RH FROND INDICATOR ASSEMBLY TOPPED UP COOLANT 2L X AC7 GREEN REMOVED FUEL LINES + PUMP FITTED SPOTTING MIRROR BRACKET REMOVED BROKEN BUNG FROM RADIATOR AND FITTED NEW ONE LIFTED CAB AND CHECKED FOR AIR CON FAULTS FITTED NEW D/G SIFN  <b><u>HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES &amp; MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING &amp; BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE JACOB FOR PRICING ON - 07 3260 8950</u></b>				
60527	12/02/2025	425921	AIRLINE REPLACE BULB	Invoice
REMOVE INDICATOR HOUSING REMOVED OLD BULB REPLACE WITH NEW BULB REFIT INDICATOR HOUSING <b><u>HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES &amp; MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND</u></b>				

**Vehicle Details**

Registration	331WIF	Next Service	Litres	
Make	IVECO	Rego Due	Trans	N/A
Model	STRALIS	Engine #	Air	Yes
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	PRIMEMOVER
Colour	WHITE	Odometer	Prod	2016

Invoice No.	Date	Odometer	Description	Type
<b><u>MACHINERY AS WELL AS FITTING &amp; BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE COREY FOR PRICING ON - 07 3260 8950</u></b>				
60436	21/01/2025	425921	DEFECTS	Invoice
CHECKED FOR RH WINDOW FAULT PARKED IN WORKSHOP REMOVED RH DOOR CARD 'FOUND WINDOW REGULATOR FAULT REMOVED OLD REGULATOR INSTALLED NEW WINDOW REGULATOR REFIT DOOR CARD CLEAN AREA COMPLETE PAPERWORK <b><u>HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES &amp; MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING &amp; BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE COREY FOR PRICING ON - 07 3260 8950</u></b>				
60397	14/01/2025	425921	DEFECTS	Invoice
PARK VEHICLE IN WORKSHOP CARRY OUT A SERVICE AS PER SERVICE SHEET CARRY OUT WALK AROUND VISUAL INSPECTION SECURE HOIST ON TRUCK CHECK ALL LIGHTS INCLUDING ALL REVERSE LAMPS AND BEEPERS CHECK WIPER AND WASHER OPERATION CHECK BATTERY LEVELS, TERMINALS AND CLAMPS LIFT CAB/BONNET TO ACCESS ENGINE BAY CHECK ALL BELTS AND MOUNTS LIFT TRUCK ON HOIST CARRY OUT VISUAL INSPECTION OF UNDER CARRIAGE (DRIVE LINE AND SUSPENSION COMPONENTS) ADJUST BRAKES AND CHECK BRAKE THICKNESSES CHECK AND ADJUST CLUTCH IF APPLICABLE CHECK GEAR BOX OIL LEVEL AND QUALITY CHECK DIFF OIL LEVEL AND QUALITY CARRY OUT GREASING OF TRUCK LOWER TRUCK CHECK ENGINE OIL TOP UP COOLANT IF REQUIRED LOWER CAB/BONNET AND SECURE IN PLACE FIT SERVICE STICKER COMPLETE PAPERWORK NOTE TOPPED UP COOLANT TOPPED UP ENGINE OIL REPLACED RH REAR PARK LIGHT BULB CHECKED FOR AIR DRYER FAULT STARTED ENGINE AND CHECKED AIR SYSTEM FOUND AIR DRYER GOVENOR FAULT PROTECTION VALVE LEAKING REMOVED BATTERIES + HOLD DOWN CLAMPS REMOVED AIRTANK, AIR LINES AND AIR DRYER FIT NEW AIR DRYER ASSEMBLY REFIT AIR TANK, AIR LINES, BATTERY AND HOLD DOWN CLAMPS				



**Vehicle Details**

Registration	331WIF	Next Service	Litres	
Make	IVECO	Rego Due	Trans	N/A
Model	STRALIS	Engine #	Air	Yes
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	PRIMEMOVER
Colour	WHITE	Odometer	Prod	2016

Invoice No.	Date	Odometer	Description	Type
TESTED OPERATION REPLACED LH REAR MUDGUARD HOLD DOWN STRAP REPLACED POWER STEERING RESERVOIR OIL LEVEL SENSOR CLEAN DOWN OIL LEAK  <b><u>HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES &amp; MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING &amp; BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE COREY FOR PRICING ON - 07 3260 8950</u></b>				
60387	10/01/2025	425921	DEFECTS	Invoice
CARRIED OUT INSPECTION OF TICKING NOISE FOUND NOISE COMING FROM AIR COMPRESSOR TILT CAB REMOVE ALL COMPONENTS AROUND + ON COMPRESSOR DRAIN COOLANT AND POWER STEERING OIL REMOVED COMPRESSOR + RING GEAR OFF THE FRONT OF THE COMPRESSOR WITH HEAT SWAP FITTINGS ONTO NEW COMPRESSOR REFIT COMPRESSOR AND ALL LINES, PUMPS AND POWER STEERING RESERVOIR FILL AND BLEED COOLING SYSTEM BLEED POWER STEERING FIT MAIN COMPRESSOR HOSE FIT HEAT SHIELD PACKED AWAY TOOLS  <b><u>HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES &amp; MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING &amp; BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE COREY FOR PRICING ON - 07 3260 8950</u></b>				
60345	31/12/2024	425921	DEFECTS	Invoice
CARRIED OUT DIAGNOSIS OF REAR FRAME COMPUTER FAULT ON DASH-  FOUND REAR EBS MODUEL LEAKING CAUSING FAULT ON DASH REPLACED VALVE AND TEST DROVE, TEST DROVE ALL OK, CONCERN NOW RECTIFIED				
59957	11/10/2024	425921	MISSING OFF INVOICE	Invoice
PRIME AND PAINT STEPS THAT WERE ON JOB 59863				
59863	02/10/2024	425921	A SERVICE	Invoice
PARK VEHICLE IN WORKSHOP CARRY OUT A SERVICE AS PER SERVICE SHEET CARRY OUT WALK AROUND VISUAL INSPECTION SECURE HOIST ON TRUCK CHECK ALL LIGHTS INCLUDING ALL REVERSE LAMPS AND BEEPERS CHECK WIPER AND WASHER OPERATION CHECK BATTERY LEVELS, TERMINALS AND CLAMPS				

**Vehicle Details**

<b>Registration</b>	331WIF	<b>Next Service</b>	<b>Litres</b>	
<b>Make</b>	IVECO	<b>Rego Due</b>	<b>Trans</b>	N/A
<b>Model</b>	STRALIS	<b>Engine #</b>	<b>Air</b>	Yes
<b>Model Series</b>		<b>VIN</b>	<b>Cyl</b>	0
<b>Model Code</b>		<b>Build Date</b>	<b>Body</b>	PRIMEMOVER
<b>Colour</b>	WHITE	<b>Odometer</b>	<b>Prod</b>	2016

Invoice No.	Date	Odometer	Description	Type
			LIFT CAB/BONNET TO ACCESS ENGINE BAY CHECK ALL BELTS AND MOUNTS LIFT TRUCK ON HOIST CARRY OUT VISUAL INSPECTION OF UNDER CARRIAGE (DRIVE LINE AND SUSPENSION COMPONENTS) ADJUST BRAKES AND CHECK BRAKE THICKNESSES CHECK AND ADJUST CLUTCH IF APPLICABLE CHECK GEAR BOX OIL LEVEL AND QUALITY CHECK DIFF OIL LEVEL AND QUALITY CARRY OUT GREASING OF TRUCK LOWER TRUCK CHECK ENGINE OIL TOP UP COOLANT IF REQUIRED LOWER CAB/BONNET AND SECURE IN PLACE FIT SERVICE STICKER COMPLETE PAPERWORK NOTE COLLECTED PARTS REPLACE RHS DRIVE AXLE BRAKE PADS FIT LH STEPS + TREADS REPLACED RH REAR PARK LIGHT BULB ADJUSTED TURNTABLE TOPPED UP ENGINE OIL TIGHTENED AIR COMPRESSOR HOSE AND AIR DRYER REPLACED #1 DIFF BRAKE PADS REPLACED #2 DIFF BRAKE PADS ADJUSTED BRAKES TEST DROVE VEHICLE  <b><u>HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES &amp; MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING &amp; BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE JEFF FOR PRICING ON - 07 3260 8950</u></b>	
59806	18/09/2024	423485	REPAIRS	Invoice
			REMOVED TINT FROM WINDOW CHECKED FOR WINDOW FAULT REMOVED DOOR CARD FOUND WINDOW REGULATOR BROKEN CHECKED FOR PARK BRAKE LIGHT FLASHING ON DASH WHEN MAXI BRAKES ARE RELEASED REMOVED STEERING COLUMN COVERS AND CHECKED AIR BRAKE SWITCH UNDER DASH REFITTED STEERING COLUMN COVERS REPLACED LH WINDOW REGULATOR NOTE SIDE STEP STILL TO BE REPLACED - PART IN OFFICE <b><u>HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES &amp; MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING &amp; BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE JEFF FOR PRICING ON - 07 3260 8950</u></b>	
59704	15/08/2024	419990	INDICATOR FAULT	Invoice
			REPLACED RHR INDICATOR BULB <b><u>HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES &amp; MORE ABOARD -</u></b>	



## Vehicle Details

Registration	331WIF	Next Service	Litres	
Make	IVECO	Rego Due	Trans	N/A
Model	STRALIS	Engine #	Air	Yes
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	PRIMEMOVER
Colour	WHITE	Odometer	Prod	2016

Invoice No.	Date	Odometer	Description	Type
<b><u>STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING &amp; BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE JEFF FOR PRICING ON - 07 3260 8950</u></b>				

59565	17/07/2024	412721	B SERVICE	Invoice
<p>PARK VEHICLE IN WORKSHOP            CARRY OUT B SERVICE AS PER SERVICE SHEET            CARRY OUT WALK AROUND VISUAL INSPECTION            SECURE HOIST ON TRUCK            CHECK ALL LIGHTS INCLUDING ALL REVERSE LAMPS AND BEEPERS            CHECK WIPER AND WASHER OPERATION            CHECK BATTERY LEVELS, TERMINALS AND CLAMPS            LIFT CAB/BONNET TO ACCESS ENGINE BAY            REPLACE CABIN AND ENGINE AIR FILTERS            CHECK ALL BELTS AND MOUNTS            LIFT TRUCK ON HOIST            CARRY OUT VISUAL INSPECTION OF UNDERCARRIAGE (DRIVE LINE AND SUSPENSION COMPONENTS)            DRAIN ENGINE OIL AND CHANGE FILTER            ADJUST BRAKES AND CHECK BRAKE THICKNESSES            CHECK AND ADJUST CLUTCH IF APPLICABLE            CHECK GEARBOX OIL LEVEL AND QUALITY REPLACE IF REQUIRED            CHECK DIFF OIL LEVEL AND QUALITY REPLACE IF REQUIRED            CARRY OUT GREASING OF TRUCK            LOWER TRUCK            FIL ENGINE OIL AND CHECK ENGINE OIL            TOP-UP COOLANT IF REQUIRED            LOWER CAB/BONNET AND SECURE IN PLACE            FIT SERVICE STICKER            COMPLETE PAPERWORK            REMOVE HOIST            NOTE            L/S FRONT FOOT STEP DAMAGE            2ND AXLE BALANCE ROD BUSH CHANGE            REPLACED COOLANT TANK            WASHED DOWN TRUCK</p> <p><b><u>HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES &amp; MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING &amp; BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE JEFF FOR PRICING ON - 07 3260 8950</u></b></p>				

59485	03/07/2024	412721	AIR LEAK BETWEEN COMPRESSOR AND	Invoice
<p>TILT CAB            INSPECT AIR LEAK            FOUND STEEL HOSE ON COMPRESSOR LEAKING            REMOVED HOSE            HAD TO REMOVE COOLANT HOSE FIRST            FIT NEW STEEL HOSE            TEST OPERATION            FILL COOLANT</p>				

## Vehicle Details

Registration	331WIF	Next Service	Litres	
Make	IVECO	Rego Due	Trans	N/A
Model	STRALIS	Engine #	Air	Yes
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	PRIMEMOVER
Colour	WHITE	Odometer	Prod	2016

Invoice No.	Date	Odometer	Description	Type
			CLEAN AREA COMPLETE PAPERWORK	
			<b><u>HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES &amp; MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING &amp; BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE JEFF FOR PRICING ON - 07 3260 8950</u></b>	

59423	20/06/2024	407498	BATTERY CONCERN	Invoice
			CHECKED BATTERY VOLTAGE WHEN NOT RUNNING - 24.7V CHECKED BATTERY WHEN RUNNING - 28.5V NO PROBLEMS WITH ALTERNATOR OR BATTERIES THAT ARE VISIBLE AT THIS CURRENT TIME	
			<b><u>HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES &amp; MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING &amp; BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE JEFF FOR PRICING ON - 07 3260 8950</u></b>	

59214	14/05/2024	407498	A SERVICE	Invoice
			PARK VEHICLE IN WORKSHOP CARRY OUT A SERVICE AS PER SERVICE SHEET CARRY OUT WALK AROUND VISUAL INSPECTION SECURE HOIST ON TRUCK CHECK ALL LIGHTS INCLUDING ALL REVERSE LAMPS AND BEEPERS CHECK WIPER AND WASHER OPERATION CHECK BATTERY LEVELS, TERMINALS AND CLAMPS LIFT CAB/BONNET TO ACCESS ENGINE BAY CHECK ALL BELTS AND MOUNTS LIFT TRUCK ON HOIST CARRY OUT VISUAL INSPECTION OF UNDER CARRIAGE (DRIVE LINE AND SUSPENSION COMPONENTS) ADJUST BRAKES AND CHECK BRAKE THICKNESSES CHECK AND ADJUST CLUTCH IF APPLICABLE CHECK GEAR BOX OIL LEVEL AND QUALITY CHECK DIFF OIL LEVEL AND QUALITY CARRY OUT GREASING OF TRUCK LOWER TRUCK CHECK ENGINE OIL TOP UP COOLANT IF REQUIRED LOWER CAB/BONNET AND SECURE IN PLACE FIT SERVICE STICKER COMPLETE PAPERWORK	
			TOPPED UP COOLENT TIGHTENED SUMP PLUG + CLEANED BOTTOM OF SUMP ADJUSTED TURNTABLE SECURED EXHAUST BRACKET + REPLACE MOUNTING BOLT TIGHTENED CROSS MEMBER BOLTS TIGHTENED INTAKE PIPE OSE CLAMP TIGHTENED ENGINE BREATHER HOUSING COVER BOLTS REPLACED NUMBER PLATE LIGHT BULB	

**Vehicle Details**

<b>Registration</b>	331WIF	<b>Next Service</b>	<b>Litres</b>	
<b>Make</b>	IVECO	<b>Rego Due</b>	<b>Trans</b>	N/A
<b>Model</b>	STRALIS	<b>Engine #</b>	<b>Air</b>	Yes
<b>Model Series</b>		<b>VIN</b>	<b>Cyl</b>	0
<b>Model Code</b>		<b>Build Date</b>	<b>Body</b>	PRIMEMOVER
<b>Colour</b>	WHITE	<b>Odometer</b>	<b>Prod</b>	2016

Invoice No.	Date	Odometer	Description	Type
			TILTED CAB REMOVED LH STEP TREAD PLATE REMOVED AIR INTAKE PIPE FROM AIR CLEANER HOUSING REFITTED TREAD PLATE + LOWERED CAB REPLACED TURBO OIL SUPPLY HOSE CLEANED AREA WITH BRAKE CLEAN STARTED ENGINE + CHECKED FOR LEAKS TIGHTENED AIR COMPRESSOR OUTLET PIPE FITTING TOPPED UP ENGINE OIL REMOVED BATTERY CLAMPS AND BATTERIES REMOVED AIRLINES, FITTINGS AND ELECTRICAL CABLES REMOVED AIR DRYER FILTER TO ACCESS AIR FITTINGS REMOVED AIR DRYER ASSEMBLY FITTED NEW AIR DRYER FITTED AIR FITTING TO AIR DRYER SECURED AIR DRYER + FITTED SUPPLY HOSE FITTED AND SECURED BATTERIES STARTED ENGINE AND CHECKED AIR DRYER OPERATION SECURED LH DAMAGED FRONT BUMPER BAR RETURNED VEHICLE TO BUCCINI YARD  <b><u>HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES &amp; MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING &amp; BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE JEFF FOR PRICING ON - 07 3260 8950</u></b>	

59212	13/05/2024	447255	SAFETY CHECK AND SCAN. DIAGNOSE	Invoice
			REMOVED GAS BOTTLE FROM TRUCK AND RETURN TO BUCCINI YARD CHECKED FOR AIR LEAK @ AIR DRYER FOUND "T" PIECE LEAKING @ HOUSING CHECKED FOR CLUTCH FAULT CONNECTED DIAGNOSTIC LAPTOP TO VEHICLE FOUND CLUTCH ACTUATOR FAULT - ERASED ALL FAULTS REMOVED CLUTCH COVER , CHECKED CLUTCH FORK AND THROW OUT REPLACED CLUTCH ACTUATOR TESTED OPERATION TILTED CAB, REMOVED FLYWHEEL SPEED SENSOR, CLEANED + REFITTED SENSOR FITTED LED LIGHTING AFTER CUSTOMISING TO MAKE WORK FITTED RUBBER (PINCH WELD) TO ALL SHORT EDGE OF ALUMINIUM AFTER WELDING ALL ALLOY DOWN TO FIT PINCH WELDER PIECES FITTED BROOM HOLDER MOUNTED ANGLE ABOVE TAILGATE VACCUMED ALL SHAVINGS OFF RUBBER MATS MOUNTED BRACKETS FOR LOADING LIGHTS RIVNUTTED RAMP STRAPS INTO RAMPS ADJUSTED RH DOOR HINGE FITTED LH DOOR COVER WINDOW BLIND TILTED CAB AND REPLACED FLYWHEEL SENSOR REMOVED AIR DRYER LEAKING FITTING (INCORRECT FITTINGS SUPPLIED) MEASURED UP FOR EXTRA FUEL TANK FOR CAR GENSET CLEANED FUEL TANK INLET + RETURN TUBES FITTED AND SECURED FUEL PUMP, DRAINED OLD FUEL TANK + SECURE HOSES FITTED NEW FUEL LINE TO NEW FUEL TANK	

**Vehicle Details**

<b>Registration</b>	331WIF	<b>Next Service</b>	<b>Litres</b>	
<b>Make</b>	IVECO	<b>Rego Due</b>	<b>Trans</b>	N/A
<b>Model</b>	STRALIS	<b>Engine #</b>	<b>Air</b>	Yes
<b>Model Series</b>		<b>VIN</b>	<b>Cyl</b>	0
<b>Model Code</b>		<b>Build Date</b>	<b>Body</b>	PRIMEMOVER
<b>Colour</b>	WHITE	<b>Odometer</b>	<b>Prod</b>	2016

Invoice No.	Date	Odometer	Description	Type
			SPIRAL WRAPPED FUEL LINES + SECURED WITH ZIPTIES + "P" CLAMPS STARTED ENGINE + CHECKED FOR LEAKS FITTED NEW AIR FITTINGS TO AIR DRYER CONNECTED AIR LINES TO AIR DRYER STARTED ENGINE AND CHECKED FOR LEAKS CHECKED AND MEASURED TOPOF TAILGATE FOR SUPRESSANT FITTED REAR TAIL GATE DUST SUPRESSANT REPOSITIONED GENSET IN CRADLE + SECURED MOUNTS REMOVED GENSET TOP COVER FABRICATED EXHAUST PIPE EXTENSION + CLAMPED TO PIPE REFITTED COVER FABRICATED EXHAUST PIPE TO GO OVER AND BEHIND GENSET COVER FABRICATED BRACKETS TO HOLD EXHAUST PIP UNDER BODY FITTED EXHAUST PIPE AND ELBOW + EXHAUST FLEX FITTED ALUMINIUM ANGLE TO TOP OF RAM TO SEAL ROOF FITTED FUEL LIFT PUMP ON GENERATOR  <b><u>HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES &amp; MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING &amp; BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE JEFF FOR PRICING ON - 07 3260 8950</u></b>	

59037	05/04/2024	398445	SQUEAK FROM ENGINE AREA	Invoice
			BRING VEHICLE INTO WORKSHOP TILT CAB INSPECT SQUEAK NOISE FOUND COIL PIG TAIL HOSE LEAKING AIR REMOVE THE PIG TAIL HOSE REMOVE THE ENGINE IN THE CONTAINER FIT THE HOSE TO 331WIF TESTED OPERATION  NOTE : SENT THE PHOTOS OF LEAKS TO PETER ***** REMOVE PCV HOUSING AND CLEAN ALL OIL OF IT REPLACE GASKET + PCV FILTER AND RE ATTACH TO HOUSING TRIED TO GET NEW GASKET BUT STILL IN SHOCK APPLIED 515 TO GASKET AND REFIT TO HOUSING FIT PCV FILTER HOUSING TO TRUCK AND TIGHTEN ALL BOLTS REMOVE LEAKING COOLANT PIPE FROM THE TOP OF THE COMPRESSOR. REMOVE HOSE OFF COMPRESSOR TO BLOCK FIT NEW HOSE TO BLOCK HAD TO SHAVE CROWS FOOT TO FIT FIT ALL OTHER HOSES FILL WUTH COOLANT TEST DRIVE VEHICLE CHECK HOSES FOR LEAKING - ALL OK WASHED TRUCK DOWN PUT CAP DOWN	

## Vehicle Details

Registration	331WIF	Next Service	Litres	
Make	IVECO	Rego Due	Trans	N/A
Model	STRALIS	Engine #	Air	Yes
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	PRIMEMOVER
Colour	WHITE	Odometer	Prod	2016

Invoice No.	Date	Odometer	Description	Type
-------------	------	----------	-------------	------

**HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE JEFF FOR PRICING ON - 07 3260 8950**

58950	19/03/2024	398445	RH ELECTRIC WINDOW + DOOR LOCK +	Invoice
-------	------------	--------	----------------------------------	---------

MADE MORE TESTS/CHECKS TO RH ELECTRIC WINDOW AND DOOR LOCK AND MIRROR CONTROLS ETC NOT WORKING  
LOCATED / REPAIRED CONCEALED BROKEN WIRING ON RHS DOOR HARNESS AS REQUIRED AT 4 PLACES / REFITTED DOOR SKINS / COVERS / TEST OPERATION - ALL OK

**HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.**

58834	05/03/2024	396939	C SERVICE AND REPAIRS	Invoice
-------	------------	--------	-----------------------	---------

WINDOW FAULT  
REMOVED WINDOW SWITCHES FROM DRIVER'S DOOR  
CHECKED POWER AT SWITCH - POWER THERE  
SWAP OVER SWITCHES  
WIPERS TURN ON  
SUSPECT WIRING FAULT  
\*\*\*\*\*  
PARK VEHICLE IN WORKSHOP  
CARRY OUT C SERVICE AS PER SERVICE SHEET  
CARRY OUT WALK AROUND VISUAL INSPECTION  
SECURE HOIST ON TRUCK  
CHECK ALL LIGHTS INCLUDING ALL REVERSE LAMPS AND BEEPERS  
CHECK WIPER AND WASHER OPERATION  
CHECK BATTERY LEVELS, TERMINALS AND CLAMPS  
LIFT CAB/BONNET TO ACCESS ENGINE BAY  
REPLACE CABIN AND ENGINE AIR FILTERS  
CHECK ALL BELTS AND MOUNTS  
LIFT TRUCK ON HOIST  
CARRY OUT VISUAL INSPECTION OF UNDERCARRIAGE (DRIVE LINE AND SUSPENSION COMPONENTS)  
DRAIN ENGINE OIL AND CHANGE FILTER  
ADJUST BRAKES AND CHECK BRAKE THICKNESSES  
CHECK AND ADJUST CLUTCH IF APPLICABLE  
CHECK GEARBOX OIL LEVEL AND QUALITY REPLACE IF REQUIRED  
CHECK DIFF OIL LEVEL AND QUALITY REPLACE IF REQUIRED  
CARRY OUT GREASING OF TRUCK  
LOWER TRUCK  
FIL ENGINE OIL AND CHECK ENGINE OIL  
TOP-UP COOLANT IF REQUIRED  
LOWER CAB/BONNET AND SECURE IN PLACE  
FIT SERVICE STICKER  
COMPLETE PAPERWORK  
REMOVE HOIST  
\*\*\*\*\*

"C" SERVICE - AS PER SERVICE SCHEDULE EXPECT WITHOUT OIL CHANGE AS IT WAS DONE @ 393525 ON 30/1/24  
CHECKED OVER VEHICLE ONLY

## Vehicle Details

Registration	331WIF	Next Service	Litres	
Make	IVECO	Rego Due	Trans	N/A
Model	STRALIS	Engine #	Air	Yes
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	PRIMEMOVER
Colour	WHITE	Odometer	Prod	2016

Invoice No.	Date	Odometer	Description	Type
			REFITTED NUMBER PLATE REPLACED RH TAIL LIGHT BULB REMOVED LH TAIL LIGHT + MOUNTING BRACKET STRAIGHTENED LH REAR MUDGUARD POLE + REPOSITIONED MUDGUARD. REPLACED TAIL LIGHT ASSEMBLY (LH) WITH NUMBER PLATE LUGHT PROVISION. CLEANED OUT PLUGS FROM CORROSION USING CONTACT CLEANER <b><u>HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING &amp; BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.</u></b>	

58886	04/03/2024	396939	RHS ELECTRIC WINDOW	Invoice
			CHECKED/MADE TESTS TO RHS ELECTRIC WINDOW NOT WORKING ETC - REMOVED VARIOUS PANELS RHS IN CAB AND CLEANED AWAY CORROSION IN PLUG CONNECTORS REMOVED RHS DOOR PANEL/SKIN TO EXPOSE/ACCESS WIRING/COMPONENTS PUT RHS WINDOW INTO ALL THE WAY UP POSITION AS REQUIRED AND DISCONNECTED RHS ELECTRIC WINDOW MOTOR SO TO ENABLE TRUCK TO BE USEABLE IN RAIN ETC RE-FITTED ALL PREVIOUSLY REMOVED COVERS/PANELS - TRUCK NEEDS TO COME BACK FOR FURTHER TESTING / REPAIRS ETC FOR WINDOW RAS AND CENTRAL LOCKING RHS ETC.  <b><u>HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING &amp; BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.</u></b>	

58772	23/02/2024	395289	BACK RIGHT TYRE HAS A SCREW IN IT -	Invoice
			TRUCK CAME IN WITH A SCREW IN BACK RIGHT TYRE 1 X PUNCTURE REPAIR  <b><u>HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING &amp; BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.</u></b>	

58614	01/02/2024	393786	AIR LEAK FROM RELAY VALVE	Invoice
			1/2/2024 CHECKED FOR AIR FAULT ON DASH FOUND RELAY VALVES LEAKING UNHOOKED VEHICLE FROM TRAILER HOOKED UP TRAILER WITH WORKSHOP TRUCK AND RETURNED TRAILER TO SHED 24 RETURNED TO WORKSHOP REMOVED HOSE FROM BOOSTERS TO CHECK FOR BACK FEEDING AIR TO VALVES REFITTED AIRLINES - ALL OK ***** 7/2/2024 REPLACED TRAILER CONTROL VALVE REPLACED REAR BRAKE CONTROL VALVE REPLACED PARK BRAKE CONTROL VALVE CARRIED OUT RE LINE OF BRAKES FOUND AIR BYPASSING THROUGH PARK CONTROL VALVE TRACED LINES SUSPECT FAULTY HAND PIECE IN CAB REPLACED AD BLUE FILTER	



Vehicle Details				
Registration	331WIF	Next Service	Litres	
Make	IVECO	Rego Due	Trans	N/A
Model	STRALIS	Engine #	Air	Yes
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	PRIMEMOVER
Colour	WHITE	Odometer	Prod	2016

Invoice No.	Date	Odometer	Description	Type
*****				
	8/2/2024		REPLACED ADBLUE FILTER	
*****				
	13/2/2024		CHECKED FOR PARK BRAKE LIGHT FAULT ON DASH CHECKED FOR FAULTY AIR SWITCH + WIRING ALONG CHASSIS + IN BEHIND DASH. REMOVED SWITCH FROM MANIFOLD AT FIREWALL FOUND SWITCH BLOCKED CLEANED OUT SWITCH REFITTED SWITCH + TESTED OPERATION TEST DROVE TRUCK, BRAKES WOULDN'T RELEASE TRUCK TOOK A LONG TIME TO BUILD UP AIR - FOUND AIR LEAKING FROM NEW VALVE, NEW VALVE BEHIND CAB IN CHASSIS RAIL	
*****				
	13/2/2024		CHECKED FOR PARK BRAKE LIGHT FAULT ON DASH CHECKED FOR FAULTY AIR SWITCH AND WIRING ALONG CHASSIS AND IN BEHIND DASH REMOVED SWITCH FROM MANIFOLD AT FIREWALL FOUND SWITCH BLOCKED CLEANED OUT SWITCH RE-FITTED SWITCH AND TESTED OPERATION CARRIED OUT EXTENSIVE SCANS TO ASSESS VARIOUS AIR/ADBLUE ERRORS FOUND ADBLUE WILL ONLY REACH 50% PUMP PRESSURE MUST HAVE RESTRICTION BETWEEN TANK AND MODULE (PARTLY BLOCKED) NEW ADBLUE FILTER HAS BEEN FITTED PUT EMULATOR FOR ADBLUE BACK INTO FITMENT AND REMOVED FUSES UNTIL LATER DATE FOUND U/S VALVE SWITCH BLOCKED FOR PARK BRAKE ALARM/LIGHT	
<b><u>HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING &amp; BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.</u></b>				

58597	30/01/2024	393524	B SERVICE	Invoice
PARK VEHICLE IN WORKSHOP CARRY OUT B SERVICE AS PER SERVICE SHEET CARRY OUT WALK AROUND VISUAL INSPECTION SECURE HOIST ON TRUCK CHECK ALL LIGHTS INCLUDING ALL REVERSE LAMPS AND BEEPERS CHECK WIPER AND WASHER OPERATION CHECK BATTERY LEVELS, TERMINALS AND CLAMPS LIFT CAB/BONNET TO ACCESS ENGINE BAY REPLACE CABIN AND ENGINE AIR FILTERS CHECK ALL BELTS AND MOUNTS LIFT TRUCK ON HOIST CARRY OUT VISUAL INSPECTION OF UNDERCARRIAGE (DRIVE LINE AND SUSPENSION COMPONENTS) DRAIN ENGINE OIL AND CHANGE FILTER ADJUST BRAKES AND CHECK BRAKE THICKNESSES CHECK AND ADJUST CLUTCH IF APPLICABLE CHECK GEARBOX OIL LEVEL AND QUALITY REPLACE IF REQUIRED CHECK DIFF OIL LEVEL AND QUALITY REPLACE IF REQUIRED CARRY OUT GREASING OF TRUCK LOWER TRUCK FIL ENGINE OIL AND CHECK ENGINE OIL				

**Vehicle Details**

Registration	331WIF	Next Service	Litres	
Make	IVECO	Rego Due	Trans	N/A
Model	STRALIS	Engine #	Air	Yes
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	PRIMEMOVER
Colour	WHITE	Odometer	Prod	2016

Invoice No.	Date	Odometer	Description	Type
TOP-UP COOLANT IF REQUIRED LOWER CAB/BONNET AND SECURE IN PLACE FIT SERVICE STICKER COMPLETE PAPERWORK REMOVE HOIST ***** NOTE- 1ST DRIVE AXLE SWAY BAR BUSHES WORN - REPLACE SOON OIL WEEPING FROM PVC FILTER HOUSING - MONITOR  <b><u>HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING &amp; BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.</u></b>				
58534	11/01/2024	389361	LIGHTS LEFT ON AT SHED 24	Invoice
WHEN AT SHED 24 I NOTICED TRUCK HAD LIGHTS LEFT ON AND NOTIFIED BT OFFICE TOOK A CALL FROM AB WHEN BACK AT THE WORKSHOP AS I COULDN'T UNLOCK THE VEHICLE DROVE TO BT YARD, CONFIRMED TRUCK WOULDN'T UNLOCK CHECKED BATTERY VOLTAGE - ALL GOOD GOT SPARE KEYS FROM OFFICE AND TRIED SPARES TRUCK UNLOCKED FINE TURNED LIGHTS OFF AND CHECKED TRUCKED STARTED - ALL OK CHECKED ORIGINAL KEYS WORKED - ALL OK AFTER TRUCK WAS UNLOCKED WITH SPARE DROVE BACK TO WORKSHOP  <b><u>HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING &amp; BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.</u></b>				
58476	11/01/2024	389189	FAULTY AIR TANK PRESSURISING PORT	Invoice
REMOVE AIR TANK PRESSURISING PORT FROM 331WIF - TEST PART NONE IN STOCK @ HVW, ON ORDER TOOK PART FROM 339SHS FITTED ONTO 331WIF AND TEST OPERATION - ALL OK  <b><u>HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING &amp; BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.</u></b>				
58415	02/01/2024	387840	STRIP AND FIT 2 TYRES	Invoice
BROUGHT VEHICLE INTO WORKSHOP STRIP AND FIT 2 NEW TYRES TENSIONED ALL WHEEL NUTS RETURN TRUCK TO BT YARD  <b><u>HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING &amp; BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.</u></b>				

**Vehicle Details**

Registration	331WIF	Next Service	Litres	
Make	IVECO	Rego Due	Trans	N/A
Model	STRALIS	Engine #	Air	Yes
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	PRIMEMOVER
Colour	WHITE	Odometer	Prod	2016

Invoice No.	Date	Odometer	Description	Type
58378	20/12/2023	386704	CODES ON DASH	Invoice

20/12/2023  
MADE TESTS/CHECKS TO TRUCK MANY / VARIOUS CODES ON DASH  
TOPPED UP LOW COOLANT AND ENGINE OIL AS REQUIRED  
NO LEAKS LOCATED  
FOUND EBS VALVE IS LEAKING AIR AT RHS CHASSIS REAR  
FOUND TIGHTENED UP LOOSE BATTERY SUPPLY CONNECTORS AS REQUIRED - TEST ALL OK  
DROVE TRUCK BACK TO BUCCINI YARD  
4/1/2024  
CHECKED FOR AIR LEAKS ON PRIME MOVER  
FOUND AIR LEAKS FROM ABS MODULE AND LEAKING FROM RELAY VALVE IN FRONT OF TURN TABLE  
FOUND SPLIT LINE AT RELAY VALVE, REMOVED DAMAGED ABS VALVE AND REPLACED RE-PACKAGED OLD VALVE FOR WARRANTY PURPOSES  
TESTED OPERATION, TESTED ALL OK  
RELAY VALVE DONE ON IVECO WARRANTY

**HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.**

58350	15/12/2023	385929	ACID SMELL COMING FROM THE REAR	Invoice
-------	------------	--------	---------------------------------	---------

INSPECT BATTERIES - ACID LEAKING AND U/S  
TRAVEL TO PICK UP BATTERIES FROM SUPPLIER AT CAPALABA  
RETURN TO WORKSHOP  
REMOVE AND FIT BATTERIES - ALL OK  
RETURNED TRUCK TO BUCCINI YARD

**HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.**

58341	13/12/2023	385456	REPLACE 1 X NEW TYRE	Invoice
-------	------------	--------	----------------------	---------

STRIP AND FIT NEW TYRE

**HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.**

58158	21/11/2023	382134	REPLACED HEADLIGHT GLOBE	Invoice
-------	------------	--------	--------------------------	---------

REMOVED SCREWS TO SWIVEL HEADLIGHT OUT  
REPLACED HEADLIGHT GLOBE

**HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.**

**Vehicle Details**

<b>Registration</b>	331WIF	<b>Next Service</b>	<b>Litres</b>	
<b>Make</b>	IVECO	<b>Rego Due</b>	<b>Trans</b>	N/A
<b>Model</b>	STRALIS	<b>Engine #</b>	<b>Air</b>	Yes
<b>Model Series</b>		<b>VIN</b>	<b>Cyl</b>	0
<b>Model Code</b>		<b>Build Date</b>	<b>Body</b>	PRIMEMOVER
<b>Colour</b>	WHITE	<b>Odometer</b>	<b>Prod</b>	2016

Invoice No.	Date	Odometer	Description	Type
58120	16/11/2023	380906	NO LIGHTS ON THE TRAILER	Invoice

DIAGNOSE NO LIGHTS ON THE TRAILER  
FOUND WIRE BROKEN IN THE TRAILER PLUG  
FIX TRAILER PLUG WIRE, GOT SOME OF THE LIGHTS WORKING  
CHECKED ALL FUSES - ALL OK  
FOUND SUZI LEAD WAS THE PROBLEM  
REPLACED ELECTRICAL SUZI LEAD

**HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.**

57955	25/10/2023	377290	ATTEND TO A/C NOT WORKING	Invoice
-------	------------	--------	---------------------------	---------

DRIVE TRUCK INTO THE WORKSHOP AND TILT THE CAB.  
CHECK THE HARD A/C GAS LINES AND LOCATED A LEAK ON THE DISCHARGE HOSE.  
ORDERED IN A NEW A/C HOSE.  
LOWERED THE CAB AND HANDED BACK TO BT UNTIL NEW PART ARRIVES.  
MADE TESTS/CHECKS TO A/C NOT COLD  
FOUND TO BE U/S LEAKY HIGH PRESSURE HOSE/PIPE ASSY  
RECLAIMED REMAININGS A/C GAS  
REMOVED / REPLACED A/C PIPE  
REGAS A/C TEST - ALL OK

**HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.**

57867	16/10/2023	375371	A SERVICE	Invoice
-------	------------	--------	-----------	---------

PARK VEHICLE IN WORKSHOP  
CARRY OUT A SERVICE AS PER SERVICE SHEET  
CARRY OUT WALK AROUND VISUAL INSPECTION  
SECURE HOIST ON TRUCK  
CHECK ALL LIGHTS INCLUDING ALL REVERSE LAMPS AND BEEPERS  
CHECK WIPER AND WASHER OPERATION  
CHECK BATTERY LEVELS, TERMINALS AND CLAMPS  
LIFT CAB/BONNET TO ACCESS ENGINE BAY  
CHECK ALL BELTS AND MOUNTS  
LIFT TRUCK ON HOIST  
CARRY OUT VISUAL INSPECTION OF UNDER CARRIAGE (DRIVE LINE AND SUSPENSION COMPONENTS)  
ADJUST BRAKES AND CHECK BRAKE THICKNESSES  
CHECK AND ADJUST CLUTCH IF APPLICABLE  
CHECK GEAR BOX OIL LEVEL AND QUALITY  
CHECK DIFF OIL LEVEL AND QUALITY  
CARRY OUT GREASING OF TRUCK  
LOWER TRUCK  
CHECK ENGINE OIL  
TOP UP COOLANT IF REQUIRED  
LOWER CAB/BONNET AND SECURE IN PLACE

**Vehicle Details**

Registration	331WIF	Next Service	Litres	
Make	IVECO	Rego Due	Trans	N/A
Model	STRALIS	Engine #	Air	Yes
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	PRIMEMOVER
Colour	WHITE	Odometer	Prod	2016

Invoice No.	Date	Odometer	Description	Type
FIT SERVICE STICKER COMPLETE PAPERWORK NOTE- REAR ENGINE COVER LEAKING BRAKES WILL NEED REPLACING NEXT SERVICE (10,000KMS) OUTPUT SHAFT - VERY MINOR MOVEMENT  <b><u>HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING &amp; BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.</u></b>				
57828	09/10/2023	373756	ATTEND TO WARNING LIGHT ON DASH	Invoice
BROUGHT VEHICLE INTO WORKSHOP CARRIED OUT FURTHER EXTENSIVE TESTS / SCANS TO TRACE / LOCATE AND REPAIR FURTHER WIRING NEAR RETARDER ON TRANSMISSION TO RETARDER TEMPERATURE SENSOR RESET/CLEARED RETARDER CODES AFTER REPAIRS / TEST - ALL OK  <b><u>HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING &amp; BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.</u></b>				
57728	04/10/2023	373756	FIT 2 NEW TYRES	Invoice
STRIP AND FIT 2 X NEW TYRES 2 NEW TYRES X 295/80R22.5 STEER 2 X BALANCING BAGS 2 X TYRE DISPOSAL  <b><u>HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING &amp; BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.</u></b>				
57751	03/10/2023	373756	RETARDER FAULTY AND NEW EXHAUST	Invoice
SCANNED AND CHECKED PARAMETERES WENT UNDERNEATH TRUCK TO CHECK INTARDER COOLANT TEMP SENSOR AND FOUND MELTED WIRING DUMP PIPE NEEDS TO BE REPAIRED AND RE-INSTALLED CUT SENSOR OFF DONOR MOTOR AND JOINED ONTO CURRENT WIRING GRINDED / CLEANED AREAS TO BE WELDED TACKED BROKEN PART OF EXHAUST WELDED STAINLESS STEEL EXHAUST CLEANED WELDED AREAS BROUGHT EXHAUST BACK TO MECHANIC FINISHED REPAIRING TEMP SENSOR FOR INTARDER REMOVED OLD SENSOR				

Registration	331WIF	Next Service		Litres	
Make	IVECO	Rego Due		Trans	N/A
Model	STRALIS	Engine #		Air	Yes
Model Series		VIN	WJMS2NTH40C323176	Cyl	0
Model Code		Build Date	2016	Body	PRIMEMOVER
Colour	WHITE	Odometer	449549	Prod	2016

Invoice No.	Date	Odometer	Description	Type
FITTED NEW SENSOR AND STARTED ATTACHING EXHAUST BACK ON FIT EXHAUST TO MUFFLER				
<b><u>HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING &amp; BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.</u></b>				
57727	03/10/2023	373756	SCAN FOR CODES ON DASH	Invoice
BROUGHT VEHICLE INTO WORKSHOP CHECKED RETARDER ERROR 25/05 ON DASH WARNING PANELS - CARRIED OUT SCAN TO ASSESS ERRORS FOUND ONLY 1 SERIOUS EOBD CODE PRESENT FOR ADBLUE PRESENT - MAYBE AUSING RETARDER ERROR FITTED NEW ADBLUE FILTER REMOVED OBD EMULATOR / REFITTED ADBLUE FUSES STICK HAS RETARDER AND ADBLUE CODES REMOVED ADBLUE FUSES AND REFITTED ADBLUE EMULATOR - FAULTS STILL PRESENT				
<b><u>HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING &amp; BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.</u></b>				
57717	28/09/2023	373137	BREAKDOWN	Invoice
TRAVEL TO BREAKDOWN INSPECT TRUCK FOR AIR LEAK FOUND SPLIT HOSE, WAIT FOR NEW JOINER TO BE DELIVERED TO ME FROM THE WORKSHOP FIT JOINER TEST OPERATION TRAVEL BACK TO WORKSHOP				
<b><u>HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING &amp; BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.</u></b>				
57351	08/08/2023	362940	REPLACE HEADLIGHT GLOBE	Invoice
DRIVER CAME IN TO THE WORKSHOP REPLACED THE HEADLIGHT GLOBE				
<b><u>HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS,</u></b>				



## Vehicle Details

<b>Registration</b>	331WIF	<b>Next Service</b>	<b>Litres</b>	
<b>Make</b>	IVECO	<b>Rego Due</b>	<b>Trans</b>	N/A
<b>Model</b>	STRALIS	<b>Engine #</b>	<b>Air</b>	Yes
<b>Model Series</b>		<b>VIN</b>	<b>Cyl</b>	0
<b>Model Code</b>		<b>Build Date</b>	<b>Body</b>	PRIMEMOVER
<b>Colour</b>	WHITE	<b>Odometer</b>	<b>Prod</b>	2016

Invoice No.	Date	Odometer	Description	Type
<b><u>BUSES, LIGHT VEHICLES, AND MACHINERY ASWELL AS FITTING &amp; BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.</u></b>				

<b>57264</b>	<b>01/08/2023</b>	<b>361691</b>	<b>B SERVICE</b>	<b>Invoice</b>
--------------	-------------------	---------------	------------------	----------------

CARRY OUT B SERVICE AS PER SERVICE SHEET

- PARK VEHICLE IN WORKSHOP
- CARRY OUT WALK AROUND VISUAL INSPECTION
- SECURE HOIST ON TRUCK
- CHECK ALL LIGHTS INCLUDING ALL REVERSE LAMPS AND BEEPERS
- CHECK WIPER AND WASHER OPERATION
- CHECK BATTERY LEVELS, TERMINALS AND CLAMPS
- LIFT CAB/BONNET TO ACCESS ENGINE BAY
- REPLACE CABIN AND ENGINE AIR FILTERS
- CHECK ALL BELTS AND MOUNTS
- LIFT TRUCK ON HOIST
- CARRY OUT VISUAL INSPECTION OF UNDER CARRIAGE (DRIVE LINE AND SUSPENSION

COMPONENTS)

- DRAIN ENGINE OIL AND CHANGE FILTER
- ADJUST BRAKES AND CHECK BRAKE THICKNESSES
- CHECK AND ADJUST CLUTCH IF APPLICABLE
- CHECK GEAR BOX OIL LEVEL AND QUALITY REPLACE IF REQUIRED
- CHECK DIFF OIL LEVEL AND QUALITY REPLACE IF REQUIRED
- CARRY OUT GREASING OF TRUCK
- LOWER TRUCK
- FILL ENGINE OIL AND CHECK ENGINE OIL
- TOP UP COOLANT IF REQUIRED
- TOP UP WASHER BOTTLE FLUID
- LOWER CAB/BONNET AND SECURE IN PLACE
- FIT SERVICE STICKER
- COMPLETE PAPERWORK
- REMOVE HOIST

FOUND COOLANT LEAKING FROM COOLANT PIPE ON TOP OF COMPRESSOR  
TIGHTENED COOLANT PIPE AND CLEANED WHERE COOLANT HAS LEAKED  
REPLACED RR REVERSE BULB  
REPLACED BLOWN REVERSE LIGHT BULB

## NOTE

CRANKCASE BREATHER HOUSING WILL NEED REPLACING (MONITOR)  
GEAR BOX OUTPUT SHAFT MINOR MOVEMENT (MONITOR)  
FL SPRING BUSH MINOR MOVEMENT - (MONITOR)

<b>57178</b>	<b>11/07/2023</b>	<b>358069</b>	<b>ATTEND TO AIR LEAK</b>	<b>Invoice</b>
--------------	-------------------	---------------	---------------------------	----------------

PICK TRUCK UP FROM BUCCINI YARD

**Vehicle Details**

<b>Registration</b>	331WIF	<b>Next Service</b>	<b>Litres</b>	
<b>Make</b>	IVECO	<b>Rego Due</b>	<b>Trans</b>	N/A
<b>Model</b>	STRALIS	<b>Engine #</b>	<b>Air</b>	Yes
<b>Model Series</b>		<b>VIN</b>	<b>Cyl</b>	0
<b>Model Code</b>		<b>Build Date</b>	<b>Body</b>	PRIMEMOVER
<b>Colour</b>	WHITE	<b>Odometer</b>	<b>Prod</b>	2016

Invoice No.	Date	Odometer	Description	Type
PARKED THE VEHICLE IN WORKSHOP PUT COLOUR ZIP TIES ON ALL HOSES AND WIRING CONNECTORS DISASSEMBLED HOSES AND ELECTRICAL CONNECTORS REMOVED THE OLD VALVE REMOVED AIR FITTINGS OFF THE OLD VALVE AND FITTED THEM TO THE NEW VALVE. ASSEMBLED NEW VALVE TO TRUCK REASSEMBLED ALL AIR HOSES AND ELECTRICAL CONNECTERS DRAINED AIR TANKS AND FOUND A LOT OF WATER INSIDE AIR TANKS STARTED UP TRUCK AND CHECKED VALVE - FOUND IT OK				
57177	07/07/2023	357664	ELECTRICAL PROBLEM WITH TRAILER	Invoice
BROUGHT VEHICLE INTO WORKSHOP DIAGNOSED ELECTRICAL PROBLEM WITH TRAILER LIGHT - BROKEN WIRING INSIDE TRAILER PLUG OPENED UP PLUG AND CUT 30MM OFF THE END OF THE LEAD REWIRED PLUG AND ASSEMBLED TESTED - ALL OK				
56957	30/06/2023	0	SUPPLY SERVICE FILTERS	Invoice
SUPPLY SERVICE FILTERS				
57104	13/06/2023	353939	A SERVICE	Invoice
UNLOCKED SHED 24 AND DISCONNECTED TRUCK FROM TRAILER AND RE-LOCK SHED 24 CARRIED OUT A SERVICE FIRST DRIVE DIFF OIL LOW - TOPPED UP AIR LEAK FROM REAR EBS MODULE REQUIRES FURTHER DIAGNOSIS, ORDERED IN A NEW MODULE WILL RECALL TRUCK WHEN IT ARRIVES. FOUND BOTH REAR TAILLIGHT LENSE REPLACED LH TAILLIGHT ASSEMBLY AS LENSE AND HOUSING WAS DAMAGED, REPLACED RH TAILLIGHT LENSE AS IT WAS CRACKED FOUND OIL LEAK PCV COVER PUT NEW BULBS IN AND CHANGED BULBS ON BRAKES AND REVERSE				
56852	07/06/2023	352530	INVESTIGATE AIR LEAK	Invoice
INVESTIGATE FOR AIR LEAK TRUCK NOT RELEASING BRAKES FOUND AIR LEAK COMING FROM EBS VALVE AT THE BACK OF THE TRUCK				
57080	07/06/2023	352530	TOPPED UP ENGINE OIL	Invoice
CHECKED / TOPPED UP ENGINE OIL LEVEL AS REQUIRED (POSSIBLY MAY REQUIRE NEW LEVEL SENSOR) FOUND LIGHT CODE WARNING ON DASH (ORANGE) STILL ON BUT NOW OIL IS AT CORRECT LEVEL				
56574	04/05/2023	0	GREASED TRUCK	Invoice
GREASED TRUCK				
56552	03/05/2023	344868	STARTER MOTOR STAYED ENGAGED	Invoice

**Vehicle Details**

<b>Registration</b>	331WIF	<b>Next Service</b>	<b>Litres</b>	
<b>Make</b>	IVECO	<b>Rego Due</b>	<b>Trans</b>	N/A
<b>Model</b>	STRALIS	<b>Engine #</b>	<b>Air</b>	Yes
<b>Model Series</b>		<b>VIN</b>	<b>Cyl</b>	0
<b>Model Code</b>		<b>Build Date</b>	<b>Body</b>	PRIMEMOVER
<b>Colour</b>	WHITE	<b>Odometer</b>	<b>Prod</b>	2016

Invoice No.	Date	Odometer	Description	Type
CHECKED FOR FAULTS ON STARTING SYSTEMS FOUND KEYSWITCH / LOCK U/S CAUSED STARTER TO STAY ON CRANKING AND BURNOUT ETC REPLACED STARTER AND IGNITION BARREL RE-CONNECTED UP BATTERIES AND TESTED - ALL OK				
56490	19/04/2023	342690	INSPECT VEHICLE FOR AIR LEAK	Invoice
INSPECT VEHICLE FOR AIR LEAK - NONE FOUND NO LEAK FOUND - SUSPECT CROSS LOCKS DISENGAGING				
56320	29/03/2023	340928	CARRIED OUT VEHICLE INSPECTION	Invoice
UNHOOK TRUCK FROM TRAILER AND BRING INTO WORKSHOP CARRIED OUT VEHICLE INSPECTION TOPPED UP ENGINE OIL REPLACED TURNTABLE TEFLON WEAR PADS CARRIED OUT TURNTABLE RE-KIT REMOVED ENGINE BREATHER COVER ADJUSTED TURNTABLE CARRIED OUT IVECO SCAN TOOL CHECK TO ASSESS VARIOUS DASH ERROR CODES AS REQUIRED INCLUDED EBS, SUSPENSION, BODY COMPUTER AND SCR / ADBLUE FAULTS FOUND REAR SUSPENSION SWITCH POSSIBLY U/S FOUND TRAILER SERVO DISTRIBUTOR PRESSURE SWITCH INTERMITTENT ( HAS BEEN REPLACED APPROX 3 WEEKS AGO PREVIOUSLY) FOUND/REPLACED DOOR LIGHT GLOBE RHS AND TEST - OK (BODY ERROR CODES) REMOVED ADBLUE EMULATOR AND RE-FITTED SCR / ADBLUE FUSES TO ENABLE ECU / CANBUS COMMUNICATIONS THIS TRUCK NEEDS ADBLUE SYSTEM FIXED / CHECKED BY IVECO CARRIED OUT FITTING OF BRAKE PEDAL RUBBER CARRIED OUT INSTALL OF REAR ENGINE PCV COVER CARRIED OUT REMOVAL AND INSTALL OF DRIVERS SEAT BASE				
56354	28/03/2023	0	BREAKDOWN AT BUCCINI YARD - TRUCK	Invoice
TRAVEL TO BUCCINI YARD TRUCK WON'T SELECT GEARS FOUND ADBLUE DELETE DISCONNECTED STILL NO GEARS DISCONNECT BATTERIES RECONNECT BATTERIES RECONNECT, START TRUCK TEST DRIVE TRUCK, BACK TO WORKSHOP				
54968	16/03/2023	318950	DAMAGED LHF GUARD AND AD BLUE	Invoice
BROUGHT VEHICLE INTO WORKSHOP FIFTED CAB , REMOVED/UNBOLTED ADBLUE TANK TO ALLOW ACCESS ETC TO THEN CARRY OUT STRAIGHTENING / HEATING UP PROCESS TO BEND DUAL LHS MUDGUARD SUPPORTS AS BEST CAN BE 95% BACK TO ORIGINAL REFITTED ADBLUE TANK, MUDGUARD AND CLEARANCE LAMP AND RECHECKED LHS WHEEL AND GUARDS CLEARANCE - ALL OK TRUCK DR-RATING DUE TO ADBLUE FAULT CONNECTED LAPTOP AND FOUND FAULT WAS ADBLUE PRESSURE LOW AT SYSTEM START UP CLEARED FAULT				

**Vehicle Details**

<b>Registration</b>	331WIF	<b>Next Service</b>	<b>Litres</b>	
<b>Make</b>	IVECO	<b>Rego Due</b>	<b>Trans</b>	N/A
<b>Model</b>	STRALIS	<b>Engine #</b>	<b>Air</b>	Yes
<b>Model Series</b>		<b>VIN</b>	<b>Cyl</b>	0
<b>Model Code</b>		<b>Build Date</b>	<b>Body</b>	PRIMEMOVER
<b>Colour</b>	WHITE	<b>Odometer</b>	<b>Prod</b>	2016

Invoice No.	Date	Odometer	Description	Type
CHECKED FUSES WERE ALL GOOD SENT TRUCK BACK OUT TO SEE IF FAULT WOULD COME BACK				
56088	28/02/2023	335150	CODES ON DASH	Invoice
CARRIED OUT IVECO EASY SCANTOOL ASSESSMENT INCLUDING INTERMITTMENT EBS TRAILER CONTROL WARNING SYSTEM / ERRORS FOUND TO BE U/S WATER AFFECTED PRESSURE SENSOR / SWITCH ON TRAILER CONTROL SERVO DISTRIBUTOR, REPLACED SWITCH / TEST OK RE-SET ECU / DASH WARNING CODES AS REQUIRED / TEST - OK				
56096	28/02/2023	340247	C SERVICE	Invoice
BROUGHT VEHICLE INTO WORKSHOP CARRIED OUT C SERVICE REPLACED #1 AND #2 DIFF OIL REPLACED TRANSMISSION OIL ADJUSTED TURNTABLE REPLACED LH FRONT BUMPER BAR INDICATOR LIGHT BULBS TIGHTENED TURNTABLE HANDLE BOLT REPAIRED ELECTRICAL SUZI COIL WIRING REPLACED ELECTRICAL SUZI COIL 7 PIN PLUG FITTED TURNTABLE HANDLE WIRE ROPE TO LATCH REPLACED MARKER PLATES REPLACED TIE ROD ENDS AND MANUALLY ADJUSTED ALIGNMENT RETURNED VEHICLE TO BUCCINI YARD				
55910	07/02/2023	339419	REPLACED	Invoice
REPLACED RHR DAMAGED TAIL LIGHT + HOLDER FITTED USED TAIL LIGHT HOLDER, TAIL LIGHT, COVER + MUDGUARD HOLD DOWN RUBBER TESTED ALL LIGHTS PRTS SUPPLIED FROM WRECK				
55796	20/01/2023	0	SUPPLY TAIL LIGHT LENS	Invoice
SUPPLY TAIL LIGHT LENS TO REPLACE THE CRACKED ONE ON THE TRUCK.				
55552	15/12/2022	335737	CARRY OUT REPAIRS - ATTEND TO AIR	Invoice
PARKED VEHICLE IN WORKSHOP CHECKED FOR DOOR FAULT REMOVED DOOR CARD REPLACED INNER DOOR LEVER RE-FITTED DOOR CARD CHECKED FOR RIDE HEIGHT ON DASH FAULT CHECKED COMPUTER FAULTS CHECKED RIDE HEIGHT REMOVED CROSS MEMBER ADAPTOR PLATE CUT OUT CRACKS AND RE-WELDED PLATE RE-FITTED PLATE AND DRILL EXTRA HOLES FOR BOLTS				
55353	15/11/2022	333310	CARRY OUT B SERVICE + FRONT RIGHT	Invoice
BROUGHT TRUCK INTO WORKSHOP CARRIED OUT B SERVICE				

**Vehicle Details**

<b>Registration</b>	331WIF	<b>Next Service</b>	<b>Litres</b>	
<b>Make</b>	IVECO	<b>Rego Due</b>	<b>Trans</b>	N/A
<b>Model</b>	STRALIS	<b>Engine #</b>	<b>Air</b>	Yes
<b>Model Series</b>		<b>VIN</b>	<b>Cyl</b>	0
<b>Model Code</b>		<b>Build Date</b>	<b>Body</b>	PRIMEMOVER
<b>Colour</b>	WHITE	<b>Odometer</b>	<b>Prod</b>	2016

Invoice No.	Date	Odometer	Description	Type
DRIVERS INNER DOOR HANDLE INOP FUEL FILTERS EXCESSIVELY TIGHT NOTE- WARNING LIGHT PRESENT FOR RIDE HEIGHT WILL REQUIRE FURTHER INVESTIGATION				
55283	03/11/2022	329478	TOP UP ENGINE OIL	Invoice
TILT CAB AND CHECKED ENGINE OIL LEVEL LOW TOPPED UP LEVEL TO CORRECT LEVEL - FOUND OIL ORANGE LEVEL LIGHT STAYS ON POSSIBLY NEEDS NEW LEVEL SENSOR FOR OIL LIGHT / LEVEL LOWER CAB - ALL OK				
55264	02/11/2022	293986	CALL OUT - NO GEARS	Invoice
DROVE DOWN TO SHED 24 CHECKED FOR TRANSMISSION FAULT ( NOT SELECTING GEARS ) STARTED ENGINE FILLED AIR TANKS WITH AIR CHECKED OPERATION TEST DRIVE VEHICLE TESTED - OK RETURNED TO WORKSHOP				
55137	13/10/2022	325257	PUMPED UP TYRES	Invoice
PUMPED UP LHR OUTER TYRE (TYRE WAS ONLY 20PSI) PUMPED UP TO 110PSI AND CHECKED FOR LEAKS - ALL APPEARED OK NEED TO MONITOR CLOSELY !!!				
55025	26/09/2022	320308	ECM FAULT + SERVICE IS DUE	Invoice
BROUGHT VEHICLE INTO WORKSHOP CARRIED OUT TRUCK SCAN ETC TO ASSESS INTERMITTENET DE-RATE AND OR ADBLUE ERRORS FOUND TO LOW START-UP PRE-PRESSURE OF ADBLUE SYSTEM (CODE 74) CARRIED OUT MORE TESTS / CHECKS / SCANS ETC FOR ADBLUE / DERATING PROBLEMS ELIMINATED VARIOUS POLLUTION CONTROL COMPONENTS AS POSSIBLE FAULTS ( PARTS FROM OLD XQ92EM ROLLOVER TRUCK) REMOVED ADBLUE DOSING UNIT AND COVER FROM VEHICLE REMOVED ADBLUE DOSING UNIT AND COVER FROM (WRECK/PARTS TRUCK) REMOVED / INTERCHANGED ADBLUE DOSING PUMP FROM OLD XQ92EM TO 331WIF TRUCK FITTED NEW ADBLUE INJECTOR AND THEN RECHECKED USING IVECO EASY AND RUN TRUCK TO TEMPERATURE FOUND UNSUCCESSFUL OUTCOME EXCEPT ADBLUE DOSING PUMP PRESSURE HAS IMPROVED SUBSTANTIALLY TRUCK ALSO HAS ECAS ERROR ON DASH AND ACCORDING TO EASY IVECO PROGRAMME NEEDS TO BE RESET FOR THE ECS ELECTRONIC MODULE CARRY OUT TEST DRIVE				
54955	12/09/2022	317585	TOPPED UP ENGINE OIL AND CHECKED	Invoice
JACK UP THE CAB TOPPED UP ENGINE OIL, IT WAS BELOW THE LOW LEVEL MARK CHECKED COOLANT				
54902	01/09/2022	314846	DRIVERS WINDOW DOESN'T MOVE +	Invoice
CARRIED OUT IVECO SCAN TOOL CHECK VARIOUS ISSUES / CODES ON DASH				

**Vehicle Details**

<b>Registration</b>	331WIF	<b>Next Service</b>	<b>Litres</b>	
<b>Make</b>	IVECO	<b>Rego Due</b>	<b>Trans</b>	N/A
<b>Model</b>	STRALIS	<b>Engine #</b>	<b>Air</b>	Yes
<b>Model Series</b>		<b>VIN</b>	<b>Cyl</b>	0
<b>Model Code</b>		<b>Build Date</b>	<b>Body</b>	PRIMEMOVER
<b>Colour</b>	WHITE	<b>Odometer</b>	<b>Prod</b>	2016

Invoice No.	Date	Odometer	Description	Type
UNABLE TO CLEAR SUSPENSION WARNING - ALL SUSPENSION FUNCTIONS ARE WORKING BUT LIGHT STAYS ON REPLACED U/S LHR TAIL LIGHT LENS AND SOME U/S TAIL LIGHT GLOBES REPLACED U/S GLOBES RHR GLOBES REMOVED / REPLACED RHS ELECTRIC WINDOW MOTOR ASSEMBLY AND SWITCH FROM XQ92EM TRUCK				
54671	01/08/2022	307685	REPLACE HEADER TANK	Invoice
BROUGHT TRUCK INTO WORKSHOP DRAIN HEADER TANK REMOVE HEATER TANK, STRIP FITTINGS AND SWAP OVER FIT NEW HEADER TANK FILL WITH COOLANT TEST DROVE AND CHECKED FOR LEAKS - ALL GOOD REPLACED BLOWN HEADLIGHT BULB CHECKED ALL OTHER LIGHTS DROVE TRUCK BACK TO BUCCINI YARD HEADER TANK PART # 37N0800 WAS CHARGED ON JOB# 54598 AS WE WERE WAITING FOR PART TO ARRIVE				
54598	19/07/2022	304278	TOP UP COOLANT	Invoice
TOP UP COOLANT FOUND HEADER TANK NEEDS REPLACEMENT AS IT'S LEAKING				
54488	05/07/2022	299169	DAMAGED TRAILER PLUG	Invoice
CARRIED OUT VARIOUS TESTS/ CHECKSTO LOCATE FAULTS (INTERMITTENT) TO TRAILER LIGHTING SUPPLY TEC FOUND TO BE U/S SUZI -LEAD - MADE UP SUZI LEAD AS REQUIRED MADE WIRING CHNGE OVER TO SUIT IVECO REVERSE LAMPS RECHECKED ALL LIGHTING TRUCK / TRAILER +- OK REFIT NEW TRAILER PLUG				
54399	22/06/2022	297460	CHECK LIGHTS AND HORN	Invoice
PARKED VEHICLE IN WORKSHOP CHECKED FOR HORN AND HEADLIGHT FAULT CHECKED ALL LIGHTS LH BRAKE LIGHT NOT WORKING - REPLACED BULB LH NUMBER PLATE LIGHT NOT WORKING REPLACED BULBS AND LIGHT STILL NOT WORKING CHECKED WIRING AND LIGHT HOUSING - NO POWER TO PLUG CHECKED FOR AIR HORN FAULT REMOVE AIR HORN / TRUMPETS CHECKED / REPAIRED RH HEADLIGHT / TEST OK CHECKED / REPAIRED RH TAIL LAMP WIRING AND TEST OK CHECKED / REPLACED U/S AIR HORN / TEST OK CHECKED / REPAIRED RFC - JAL TEST AND TEST - ALL OK				
54151	20/06/2022	289289	REPLACE ALTERNATOR	Invoice



**Vehicle Details**

<b>Registration</b>	331WIF	<b>Next Service</b>	<b>Litres</b>	
<b>Make</b>	IVECO	<b>Rego Due</b>	<b>Trans</b>	N/A
<b>Model</b>	STRALIS	<b>Engine #</b>	<b>Air</b>	Yes
<b>Model Series</b>		<b>VIN</b>	<b>Cyl</b>	0
<b>Model Code</b>		<b>Build Date</b>	<b>Body</b>	PRIMEMOVER
<b>Colour</b>	WHITE	<b>Odometer</b>	<b>Prod</b>	2016

Invoice No.	Date	Odometer	Description	Type
03/05 REMOVED ALL BATTERY CABLES/ TERMINALS / MAIN CHASSIS EARTH CABLE TO CARRY OUT EXTENSIVE CLEANING OFCORRODED CONNECTION, REFIT - TEST OK LOAD TESTED BATTERIES - ALL OK CHECKED STARTING / CHARGING - ALL OK 10/05 TRAVEL TO YARD TO INSPECT TRUCK BUT WASNT AVAILABLE CHECK / TEST CHARGE CIRCUIT FAULT REMOVED U/S ALTERNATOR AND REPLACED				
54109	20/06/2022	288144	REPAIRS	Invoice
REMOVED & REPLACED U/S TOP SUN VISOR CLEARANCE LAMP AS REQUIRED - TEST OK CHECKED AND TESTED FOR EBS INTERMITTENT TRAILER SUPPLY FOUND ERROR TO TRAILER SUPPLY SERVO DISTRIBUTOR VALVE REPLACED TRAILER CONTROL VALVE REPLACE AIR SWITCH @ CONTROL VALVE REPLACED TRAILER LOW AIR WARNING LIGHT SWITCH REPLACED SHORT TAIL SUZI COILS				
54312	09/06/2022	295522	CARRY OUT B SERVICE	Invoice
PICKED UP TRUCK FROM BUCCINI YARD CARRIED OUT B SERVICE STARTER MOTOR FAILED WHEN STARTING AFTER FILLINGWITH AIR. REMOVE STARTER MOTOR AFTER DISCONNECTING BATTERIES GO TO YARD AND SWAP 331WIF STARTER INTO XQ92EM AND BRING THE STARTER FROM XQ92EM AND FIT TO 331WIF CHECK RING GEAR ON TRUCK - OK TIGHTEN ALL BOLTS AND TERMINALS RECONNECT BATTERY START TRUCK - OK NOTE- OIL LEAK AT TURBO ON AIR INTAKE PIPE - MONITOR TURNABLE NO ADJUSTMENT LEFT A REKIT NEXT SVC. TIE ROD ENDS VERY MINOR MOVEMENT - MONITOR				
54281	03/06/2022	294844	LIGHTING FAULT	Invoice
MADE MANY TESTS/CHECKS TO TRACE / LOCATE SORT OUT RFC AND FFC ECU FAULTS FOUND TO BE U/S FOG LIGHT GLOBE FFC ECU - TSET - ALL OK FOUND TO BE U/S WATER AFFECTED REAR FRAME ECU AND WIRING PLUG TO SAME IS U/S ON LICENSE PLATE CIRCUIT ( USED RFC ECU OFF TRUCK XQ92EM ) AND TEST REPLACED LEAKING FEMALE AIR COUPLING ON SUZI COIL PULLED APART TAIL LIGHT DRIVERS SIDE TO FIND PARK LIGHT FAULT REPLACED 2 X BRAKE LIGHT GLOBES REPLACED 4 X PARK LIGHT GLOBES				
54085	28/04/2022	0	RHS LOWER STEP	Invoice

**Vehicle Details**

<b>Registration</b>	331WIF	<b>Next Service</b>	<b>Litres</b>	
<b>Make</b>	IVECO	<b>Rego Due</b>	<b>Trans</b>	N/A
<b>Model</b>	STRALIS	<b>Engine #</b>	<b>Air</b>	Yes
<b>Model Series</b>		<b>VIN</b>	<b>Cyl</b>	0
<b>Model Code</b>		<b>Build Date</b>	<b>Body</b>	PRIMEMOVER
<b>Colour</b>	WHITE	<b>Odometer</b>	<b>Prod</b>	2016

Invoice No.	Date	Odometer	Description	Type
D/S STEP DAMAGED 3/5/2022 ONCE PARTS ARRIVED PREPAIRED RHS STEP ASSEMBLY FOR PAINTING MASKED AREA PLASTIC PRIMED STEP AND PAINTED WHITE 4/5/2022 REMOVED AND REPLACED STEP				
54089	28/04/2022	288144	A SERVICE	Invoice
29/4/2022 - MOVED VEHICLE INTO WORKSHOP AND PLACE ON HOISTS CARRY OUT A SERVICE TOPPED UP ENGINE OIL AND COOLANT SUNVISOR LHS TOP LIGHT NOT WORKING - REMOVED AND REPLACED REMOVED ALL BATTERY CABLES/BATTERY TERMINALS AND MAIN CHASSIS EARTH CABLES TO CARRY OUT EXTENSIVE CLEANING OF CORRODED CONNECTIONS REFIT AND TESTED OPERATION - ALL OK LOAD TESTED ALL BATTERIES AND CHECK STARTING / CHARGING - ALL OK DEGREASED OIL WEEP OVER OIL FILTER HOUSING - CHECK AGAIN NEXT SERVICE AND MONITOR DEFECTS: DOOR STEP ON RHS BROKEN ADBLUE LEAKING FROM EXHAUST - THROUGH ADBLUE INJECTORS DRIVER SEAT CUSHION WORN SEATBELT RETRACTING SLOW				
54086	21/04/2022	286904	DIFF LOCK LIGHT ON DASH	Invoice
CHECKED AND LOCATED AIR LEAKS AT REAR OF TRUCK CAUSING DIFF LOCK LIGHT TO COME ON INTERMITTENTLY CUT OUT CHAFFED AIR LINES AREAS AND FITTED METRIC JOINERS ALSO FOUND ALL SEVEN AIR TANKS HAD EXCESSIVE MOISTURE - DRAINED ALL TANKS AND ADDED TIE/PULLS TO ALL TANKS AS REQUIRED RECHECKED FOR AIR LEAKS - ALL OK NOTE: FURTHER INVESTIGATION REQUIRED ON EBS WARNING ON DTC 42 / FMI OSI				
54013	06/04/2022	284137	TOPPED UP ENGINE OIL	Invoice
VEHICLE CAME IN TO WORKSHOP WITH LOW ENGINE OIL TOPPED UP ENGINE OIL AND CHECK VISUALLY FOR LEAKS VEHICLE ALL OK				
53912	23/03/2022	280373	TURNTABLE REPAIRS	Invoice
23/3/2022 REMOVED TEFLON WEAR PADS AND FITTED NEW ONES REMOVED BURRS FROM TOP OF TURNTABLE				
53854	14/03/2022	278722	LOW BEAM BULBS	Invoice
14/3/2022 REPLACED FRONT LEFT LOW BEAM BULB				

**Vehicle Details**

<b>Registration</b>	331WIF	<b>Next Service</b>	<b>Litres</b>	
<b>Make</b>	IVECO	<b>Rego Due</b>	<b>Trans</b>	N/A
<b>Model</b>	STRALIS	<b>Engine #</b>	<b>Air</b>	Yes
<b>Model Series</b>		<b>VIN</b>	<b>Cyl</b>	0
<b>Model Code</b>		<b>Build Date</b>	<b>Body</b>	PRIMEMOVER
<b>Colour</b>	WHITE	<b>Odometer</b>	<b>Prod</b>	2016

Invoice No.	Date	Odometer	Description	Type
53688	10/02/2022	27403	EBS LIGHT ON DASH	Invoice

10/2/2022

CHECKED EBS WARNING LIGHT ON DASH - FOUND W CODE NOT PRESENT BUT FOUND CANBUS ERROR PRESENT - NOT COMMUNICATING PROPERLY  
REMOVED VARIOUS PANELS, COMPONENTS, WIRING HARNESSSES, PLUGS AND SOCKETS ON LHS IN CAB  
FOUND WATER INTRUSION EVIDENT AND SHORT TRACKING ON VARIOUS PIN / SOCKET TERMINALS  
CLEANED UP AND RECHECKED - ALL OK

11/2/2022

FOUND AND REPOSITIONED SQUASHED CABLE WIRE ON LHS BEHIND RAIL AREA CONCEALED  
CARRIED OUT FURTHER CHECKS / TESTS / VISUAL INSPECTION OF MOST WIRING AND PLUG SETS LHS  
REASSEMBLED, REFITTED ALL PANELS / COVERS TO LHS  
RESTARTED ENGINE AND CHECKED EBS - NO CODES PRESENT

53662	07/02/2022	273996	REPLACE ADBLUE CAP	Invoice
-------	------------	--------	--------------------	---------

7/2/2022

DRIVER CAME IN WITH ADBLUE FILLER CAP LOCKED AND WOULD NOT UNLOCK  
ONCE REMOVED - NEW ONE ORDERED

8/2/2022

REPLACED LH BUMPER BAR INDICATOR ASSEMBLY  
FITTED NEW ADBLUE CAP AND SUPPLIED KEY  
PLACED SPARE KEY ASH TRAY  
TEST DROVE VEHICLE

53605	25/01/2022	273983	EBS LIGHT ON DASH	Invoice
-------	------------	--------	-------------------	---------

TRUCK CAME IN WITH LIGHT ON DASH  
MADE VARIOUS TESTS/SCANS TO TRY AND DIAGNOSE WHY EBS AMBER WARNING LIGHT IS ON  
AFTER COMPLETING ALL BASIC CHECKS OF CABLES AND ELECTRICAL COMPONENTS CONNECTED SCAN TOOL  
FAULTS PRESENT AND ACTIVE -  
TRAILER CONTROL SERVO DISTRIBUTOR  
ELECTRONIC CONTROL UNIT PRESSURE SENSOR VOLTAGE  
ELECTRONUMATIC REAR AXLE MODULATOR  
TRAILER CONTROL SERVO DISTRIBUTOR ELECTROVALVE  
CLEARED INTERMITTENT CODES BUT FIRST CODE ACTIVE WILL NOT CLEAR  
RECHECKED EBS WARNING AND FOUND WARNING LIGHT HAD GONE GREEN TO OK SYMBOL SINCE LAST TESTING  
RESCANNED AND FOUND CODE 48/OB EBS INTERMITTENT FAULT HAS BEEN UP TWICE  
LOCATED WIRING AT TRAILER SERVO CONTROL VALVE AND CHECKED INPUTS AT PINS - ALL TESTED OK  
MADE BASIC VISUAL CHECKS OF WIRING HARNESS AT BENDS/JUNCTIONS - ALL OK  
TEST DROVE VEHICLE - FAILED INTERMITTENTLY TWICE WHEN STOPPED AT LIGHTS - VALVE IS LOCATED AT REAR INSIDE OF CHASSIS RHS  
REMOVED EBS VALVE, AIRLINES AND ELECTRICAL PLUGS  
REMOVED EBS CHASSIS BRACKET  
FITTED BRACKET TO NEW VALVE  
FITTED NEW VALVE, AIR LINES AND ELECTRICAL PLUG TO VEHICLE AND TESTED OPERATION  
LOCATED AND REOMVED 6MM AIR LINE LEAKING BEHIND CENTRAL CROSS MEMEBER AND FIT JOINER AS REQUIRED - ALL OK  
REPLACED LHS LOWER INDICATOR LIGHT ASSEMBLY  
UNCLIPPED ABS / EBS WIRING HARNESS FROM REAR TO FRONT TO CHECK FOR ANY POSSIBLE DAMAGE OR CHAFFING  
CLEANED UP VARIOUS RELATED WIRING, COMPONENTS, PLUGS AND SOCKETS  
REASSEMBLED AND REFIT COVERS AND WIRING HARNESS - ALL OK  
RETURNED VEHICLE TO BUCCINI YARD

**Vehicle Details**

<b>Registration</b>	331WIF	<b>Next Service</b>	<b>Litres</b>	
<b>Make</b>	IVECO	<b>Rego Due</b>	<b>Trans</b>	N/A
<b>Model</b>	STRALIS	<b>Engine #</b>	<b>Air</b>	Yes
<b>Model Series</b>		<b>VIN</b>	<b>Cyl</b>	0
<b>Model Code</b>		<b>Build Date</b>	<b>Body</b>	PRIMEMOVER
<b>Colour</b>	WHITE	<b>Odometer</b>	<b>Prod</b>	2016

Invoice No.	Date	Odometer	Description	Type
53553	18/01/2022	273887	C SERVICE AND REPAIRS	Invoice
CARRY OUT REMAINDER OF C SERVICE ON VEHICLE REMOVED AND REPLACED CHECK VALVE AND SEALED WITH PIPE SEALANT - LEAKING REPOSITIONED PCV GASKET AND REFIT FILTERS STRAIGHTENED OUT REAR RHS MUDGUARD POLE RESECURED CROSS MEMBER BOLTS - LOOSE REPLACED ALL AIRBAGS - CRACKED REMOVED AND REPLACED SWAY BAR BUSHES ON FRONT SWAY BAR CHECKED AND RESEATED FOLDED AIRBAG ON LHS FRONT CHECKED LIGHT OPERATION - ALL OK				
53486	05/01/2022	273397	LIGHT REPAIRS	Invoice
JACKED UP CAB TO ENABLE ACCESS TO LHF FLASHER CLEANED UP AND RETENSIONED POOR GLOBE CONTRACTS DRILLED 3 SMALL HOLES IN BOTTOM OF LENSES TO RELEASE WATER RECHECKED ALL LIGHTS - ALL OK				
53400	20/12/2021	270731	HARD TO START	Invoice
DROVE TO PORT OF BRISBANE AND CHECKED TRUCK NOT STARTING DIAGNOSED THAT THE BATTERIES HAVE FAILED JUMP STARTED THE TRUCK AND RETURNED TO WORKSHOP. DRIVER DROPPED TRUCK OFF AT THE WORKSHOP TO HAVE BATTERIES REPLACED REMOVED AND REPLACED BOTH BATTERIES - LEAKING ACID AROUND NEGATIVE POSTS FABRICATED NEW BATTERY CABLE LINK LEAD AND CLEANED AWAY ALL CORROSION AND BATTERY ACID RECHECKED START/CHARGING - ALL OK FOUND CENTRE SUPPORT BRACKET OVER/ABOVE TRANSMISSION FOR CROSS MEMBER SUPPORT WAS BEGINNING TO CRACK REMOVED BRACKET ASSEMBLY DRILLED 3MM HOLES AT CRANK ENDS TO HELP STOP FURTHER CRACKING RESEATED ASSMEBLY REMOVED BROKEN FIRE EXTINGUISHER BRACKET WELD REPAIRED BRACKET AD REMOUNTED TO VEHICLE				
53384	15/12/2021	270246	CARRY OUT B SERVICE	Invoice
10/12/2021 - CHANGED LHS INDICATOR GLOBE 15/12/2021 - CARRIED OUT IVECO SCANNER TESTING TO BRAKE EBS FAULTS TRACED EBS WIRING AND TIGHTENED/RETENSIONED ALL REAR EBS PLUGS/SOCKETS TERMINALS RESECURED AND TESTED OPERATION - ALL OK CHECKED TRAILER VALVE SENSOR - ALL OK CARRIED OUT B SERVICE ON VEHICLE 16/12/2021 - REPLACED LHS SIDE MARKER LIGHT REPLACED BOTH FUEL FILTERS AND PRIMED FUEL SYSTEM REPLACED NUMBER PLATE LIGHT GLOBE REMOVED TURNTABLE FRONT SKID PLATE BOLTS CLEANED THREADS AND REFITTED BOLTS ADJUSTED TURNTABLE DEFECTS: THIRD AXLE AND SECOND AXLE RHS AIR BAGS CRACKED EXHAUST PIPE CRACKED NEXT TO ADBLUE INJECTOR ADBLUE WEEPING FROM CRACK				

**Vehicle Details**

<b>Registration</b>	331WIF	<b>Next Service</b>	<b>Litres</b>	
<b>Make</b>	IVECO	<b>Rego Due</b>	<b>Trans</b>	N/A
<b>Model</b>	STRALIS	<b>Engine #</b>	<b>Air</b>	Yes
<b>Model Series</b>		<b>VIN</b>	<b>Cyl</b>	0
<b>Model Code</b>		<b>Build Date</b>	<b>Body</b>	PRIMEMOVER
<b>Colour</b>	WHITE	<b>Odometer</b>	<b>Prod</b>	2016

Invoice No.	Date	Odometer	Description	Type
LHS FIRST DIFF FRONT MUDGUARD SIDE LIGHT NOT WORKING RHS SECOND DIFF REAR MUDGUARD POLE BENT RHS SEAT CUSHION TORN AND WORN TURNABLE JAWS WORN - REQUIRES REPLACING				
53355	07/12/2021	268429	REPLACE LIGHT ASSEMBLY	Invoice
REMOVED DAMAGED RHS LIGHT ASSEMBLY REPLACED LIGHT ASSEMBLY AND TESTED OPERATION - ALL OK				
53225	12/11/2021	264027	TOPPED UP ENGINE OIL	Invoice
LIFT UP CAB AND CHECKED ENGINE OIL LEEVEL TOPPED UP ENGINE OIL CHECKED FOR LEAKS - ALL OK				
53116	18/10/2021	258322	SUZI COIL REPAIRS	Invoice
ATTEND YARD INSPECT SUZI COILS AND FOUND ENDS TO HAVE BEEN CRUSHED/DAMAGED REMOVED AND REPLACED SUZI COILS TESTED FOR AIR LEAKS - ALL OK				
52955	07/10/2021	256949	SUZI COIL ISSUES	Invoice
6/10/2021 - CLOSED UP WORKSHOP AND PACKED VAN TO GO TO BREAKDOWN DROVE TO ACACIA RIDGE - TRAILER PLUG WAS DAMGED WAS UNABLE TO REPAIR TRAILER PLUG FOLLOWED TRUCK AND TRAILER BACK TO WORKSHOP 7/10/2021 - REMOVED DAMAGED ELECTRICAL SUZI COIL REMOVED TREAD PLATES REPAIRED AND WELDED THREAD PLATE BRACKETS REFITTED THREAD PLATE, BOLTS AND WASHERS FITTED NEW AIR LINES (SHORT TAIL) FITTED NEW ELECTRICAL SUZI COIL FITTED NEW POGO STICK 11/10/2021 - TOP UP THE ENGINE OIL IN THE TRUCK AND CHECKED FOR LEAKS - ALL OK REPLACED LHS REAR REVERSE LIGHT GLOBE AND TESTED OPERATION - ALL OK				
52895	23/09/2021	0	TRAILER LIGHT ISSUES	Invoice
CHECKED TRAILER LIGHTING NOT ALL WORKING FRONT SUZI COIL END RESET SUZI-PLUG PINS FOUND TRAILER SUPPLY VOLTAGE REDUCER TRIPPED OUT ON TWO CIRCUITS RESET AND RECHECKED TRAILER OUTPUT ON TRAILER ALL OK				
52670	16/08/2021	243995	CARRY OUT REPAIRS	Invoice
TRUCK CAME TO THE WORKSHOP WITH A BROKEN LHS TAIL LAMP ASSEMBLY AND DAMAGED LAMP GUARD MOUNT. FITTED A LENSE TO KEEP THE TRUCK MOBILE, SECURED IT WITH CABLE TIES AS THE SCREW HOLES DO NOT LINE UP. ORDERED A NEW LIGHT ASSEMBLY AND GUARD MOUNT FROM IVECO. ONCE PARTS ARRIVED, REPLACED LHS TAIL LIGHT ASSEMBLY				

## Vehicle Details

<b>Registration</b>	331WIF	<b>Next Service</b>	<b>Litres</b>	
<b>Make</b>	IVECO	<b>Rego Due</b>	<b>Trans</b>	N/A
<b>Model</b>	STRALIS	<b>Engine #</b>	<b>Air</b>	Yes
<b>Model Series</b>		<b>VIN</b>	<b>Cyl</b>	0
<b>Model Code</b>		<b>Build Date</b>	<b>Body</b>	PRIMEMOVER
<b>Colour</b>	WHITE	<b>Odometer</b>	<b>Prod</b>	2016

Invoice No.	Date	Odometer	Description	Type
SECURED AND TESTED ALL OK				
52626	05/08/2021	341743	REPAIRS	Invoice
TOPPED UP ENGINE OIL AS REQUIRED REPLACED RHS HEADLIGHT AND FOG LIGHT CHECKED AND TESTED - ALL OK				
52378	28/06/2021	232372	REPLACE PARKLIGHT GLOBE	Invoice
REPLACED BLOWN RHS PARK LIGHT GLOBE TOPPED UP ENGINE OIL				
52332	22/06/2021	0	RETHREAD AXLE	Invoice
REMOVED LHS 1ST AND 2ND DIFF HUBS REPAIRED DAMAGED STUB THREADS. NUTS BOUND UP ON STUB AXLES WHILST BEING REMOVED. HAND CUT NEW THREADS TO ALLOW NEW HUB NUTS TO SCREW ON. REFITTED HUBS AND TENSIONED HUB NUTS FITTED WHEELS AND RETENSIONED WHEEL NUTS TESTED VEHICLE- ALL OK				
52290	17/06/2021	225492	BRAKE LIGHT ON DASH	Invoice
CHECK BRAKE FAULT LIGHT ON DASH CONNECTED JALTEST AND ERASED ALL FAULTS INSPECTED VEHICLE AND FOUND RHS 2ND DIFF BRAKE PADS VERY LOW FOUND STEER AXLE PADS LOW LIFTED VEHICLE ONTO HOISTS AND REMOVED MIDDLE AXLE WHEELS REMOVED AND REPLACED BRAKE PADS UNPON INSPECTION FOUND BRAKE ROTORS WORN AND REQUIRED REPLACING REMOVED PADS, BRAKE BOOSTERS AND CALLIPERS FROM AXLE REPLACED ALL ROTORS AND TESTED - ALL OK CANBUS INTERMITTENET FAULTS DUE TO CORRODED BATTERY TERMINALS REMOVED AND CLEANED UP CORRODED POSTS AND BATTERY CABLE TERMINALS TESTED VEHICLE - ALL OK				
52194	01/06/2021	0	REPLACE REAR WINDOW	Invoice
REMOVE DAMAGED REAR WINDOW AND FIT A NEW MIDDLE WINDOW				
51942	22/04/2021	225492	REPLACE MISSOR GLASS	Invoice
REMOVE AND REPLACE BROKEN MIRROR GLASS				
51855	14/04/2021	0	ELECTRICAL FAULTS	Invoice
INSPECTED AND DIAGNOSED UHF AND 12 LIGHTER SOCKET NOT WORKING. REMOVED UPPER ROOF CONSOLE TO ACCESS VOLTAGE REDUCER MODULE - BURN OUT. REPLACED MODULE AND REFITTED COMPONENTS - TESTED OK. LIGHTING FAULT LIGHT ON DASH - FOUND FOG LIGHT LHS GLOBE BLOWN - REMOVED AND REPLACED - TESTED OK. REPLACED ALL FOUR INTERIOR LIGHTS - BLOWN - TESTED OK				
51812	31/03/2021	223640	CARRY OUT REPAIRS	Invoice
TRAVEL TO BREAKDOWN - TYRES 4 U @ REDBANK PLAINS REPLACED FAILED FUEL PIPE LINE WITH ANOTHER TRUCK UNTIL PART COULD BE SOURCED. REMOVED FITTING FROM PIPE A REQUIRED AND REMOVED AND REPLACED FUEL LINE - TESTED OK				



**Vehicle Details**

<b>Registration</b>	331WIF	<b>Next Service</b>	<b>Litres</b>	
<b>Make</b>	IVECO	<b>Rego Due</b>	<b>Trans</b>	N/A
<b>Model</b>	STRALIS	<b>Engine #</b>	<b>Air</b>	Yes
<b>Model Series</b>		<b>VIN</b>	<b>Cyl</b>	0
<b>Model Code</b>		<b>Build Date</b>	<b>Body</b>	PRIMEMOVER
<b>Colour</b>	WHITE	<b>Odometer</b>	<b>Prod</b>	2016

Invoice No.	Date	Odometer	Description	Type
51717	19/03/2021	221531	REPLACE BROKEN FUEL FILTER	Invoice
TRUCK PRESENTED WITH LEAKING FUEL - REMOVED FILTER TO SEE BOLTS BEHIND HAVE UNDONE. REPLACE BROKEN FUEL FILTER CAUSED FROM BOLT THAT CAME LOOSE AND PUNCTURED THE FILTER - CHECKED FOR LEAKS - TESTED OK				
51706	18/03/2021	221464	TOP UP ENGINE OIL AND TEST	Invoice
CHECKED ENGINE OIL AND COOLANT LEVELS TOP-UP ENGINE OIL - LOW FITTED AND TIGHTENED VGT AIRLINE CLAMP - CHECKED FOR LEAKS - TESTED OK FITTED RH H1 & H2 DIFF ORIGINAL MUDGUARDS, BRACKETS AND TAIL LIGHT ASSEMBLIES - TESTED OK.				
51623	10/03/2021	0	REPAIRS	Invoice
INSPECT VEHICLE AND DIAGNOSE WHY IT'S THROWING SERPENTINE BELTS. WHILST RUNNING THE ENGINE A COMPRESSED AIR NOISE WAS DETECTED. FOUND THAT THE VGT PIPE TO THE TURBO ACTUATOR WAS BROKEN. DIAGNOSED THAT THE IDLER AND BELT TENSIONERS ARE WORN OUT AND IN NEED OF REPLACEMENT. BELT TENSIONER EX SYDNEY. REMOVED WORN PARTS AND INSTALLED NEW ONES. REMOVED BROKEN VGT PIPE AND INSTALLED A NEW ONE. FITTED A NEW FAN BELT AND TESTED ALL OK.				
51642	04/03/2021	221163	TRAVEL TO PORT FOR BREAKDOWN	Invoice
<b>DATE WORK CARRIED OUT:</b> 04/03/2021 - 08/03/2021 <b>WORK CARRIED OUT:</b> DRIVE TO PORT FOR BREAKDOWN FAN BELT HAD FAILED  REPLACED FAN BELT INSPECT FUEL LEAK - FOUND FUEL LEAKING FROM FUEL FILTER ON ENGINE FOUND AIR LEAK FROM FAN ACTUATOR MOULDED TO HOSE DIAGNOSED NEW BELT DAMAGED - THE BELT TENSIONER HAS FAILED CAUSING THE BELT TO COME OFF PULLEY - REPLACED TENSIONER, FANBELT AND STRETCH BELT - TESTED OK INSPECTED FAN BELT IDLER - TESTED OK FIT HORTON FAN AIR-LINE - REPLACED SEALANT TO FITTINGS - TESTED OK				
51546	23/02/2021	219131	A & B SERVICE	Invoice
<b>DATE WORK CARRIED OUT:</b> 25/02/2021  <b>WORK CARRIED OUT:</b> CARRIED OUT A & B SERVICE REMOVED BROKEN STUD ON FRONT BUMPER DRILLED & FITTED BOLT & WASHER				

**Vehicle Details**

<b>Registration</b>	331WIF	<b>Next Service</b>	<b>Litres</b>	
<b>Make</b>	IVECO	<b>Rego Due</b>	<b>Trans</b>	N/A
<b>Model</b>	STRALIS	<b>Engine #</b>	<b>Air</b>	Yes
<b>Model Series</b>		<b>VIN</b>	<b>Cyl</b>	0
<b>Model Code</b>		<b>Build Date</b>	<b>Body</b>	PRIMEMOVER
<b>Colour</b>	WHITE	<b>Odometer</b>	<b>Prod</b>	2016

Invoice No.	Date	Odometer	Description	Type
INSPECTED BUMPER FOR MOVEMENT - OK				
<b>DEFECTS NOTED:</b> <ul style="list-style-type: none"><li>- SWAY BAR BUSHES WORN ON BOTH DRIVE AXLES</li><li>- SLIGHT PLAY IN TIE ROD ENDS</li><li>- REAR AXLE AIRBAGS ALL HAVE CRACKS IN THEM</li></ul>				
51368	02/02/2021	214917	TOP UP OIL & COOLANT	Invoice
<b>DATE WORK CARRIED OUT:</b> 02/02/2021 <b>WORK CARRIED OUT:</b> TOPPED UP ENGINE OIL & COOLANT				
51275	19/01/2021	212152	EBS MODULE	Invoice
<b>DATE WORK CARRIED OUT:</b> 19/01/2021 <b>WORK CARRIED OUT:</b> REMOVED & REPLACED LEAKING EBS/ABS MODULE CHECKED FOR FAULT CODES ON DASH – NONE FOUND TEST DROVE – ALL OK				
51277	15/01/2021	212152	A SERVICE	Invoice
<b>DATE WORK CARRIED OUT:</b> 15/01/2021 <b>WORK CARRIED OUT:</b> CARRIED OUT A SERVICE REPLACED PARK LIGHT BULB REPAIRED CRACKED FIRE EXTINGUISHER BRACKET CLEANED CORROSION ON BATTERY TERMINALS TEST DROVE – OK CHECKED A/C FOUND LEAKING @ COMPRESSOR HOSE FITTING FLANGES RECLAIMED A/C GAS CLEANED UP DIRT/DEBRIS FROM A/C COMPRESSOR AREA REMOVED A/C PIPE ENDS & REPLACED O-RINGS REFITTED A/C PIPE ENDS & EVACUATED A/C SYSTEM THEN REGASSED LEAK TESTED – ALL OK REPAIRED REAR LIGHTING FAULTS RESEATED ALL L & R TAIL LAMP GLOBES REPLACED U/S TAIL LAMP GLOBE TESTED - ALL OK  <b>DEFECTS NOTED</b> <ul style="list-style-type: none"><li>- FRONT PADS LOW</li><li>- REAR AIR BAGS CRACKED AT BASE</li><li>- ABS/EBS MODULATOR VALVE LEAKING</li><li>- SWAY BUSHES AT REAR WORN</li><li>- FRONT OF TURBO COMPRESSOR HOUSING WET WITH OIL</li></ul>				

**Vehicle Details**

<b>Registration</b>	331WIF	<b>Next Service</b>	<b>Litres</b>	
<b>Make</b>	IVECO	<b>Rego Due</b>	<b>Trans</b>	N/A
<b>Model</b>	STRALIS	<b>Engine #</b>	<b>Air</b>	Yes
<b>Model Series</b>		<b>VIN</b>	<b>Cyl</b>	0
<b>Model Code</b>		<b>Build Date</b>	<b>Body</b>	PRIMEMOVER
<b>Colour</b>	WHITE	<b>Odometer</b>	<b>Prod</b>	2016

Invoice No.	Date	Odometer	Description	Type
51207	08/01/2021	210572	RHS HEADLIGHT FAULT	Invoice

**DATE WORK CARRIED OUT:** 08/01/2021

**WORK CARRIED OUT:**

CHECKED / REPAIRED RH LOW BEAM HEADLIGHT  
TESTED – ALL OK

51158	30/12/2020	0	REMOVED & REPLACED TAIL LIGHT	Invoice
-------	------------	---	-------------------------------	---------

**DATE WORK CARRIED OUT:** 11/12/2020

**WORK CARRIED OUT:**

REMOVED AND REPLACED L/H/R TAIL LIGHT ASSEMBLY WITH GOOD SECOND HAND ONE

50881	16/11/2020	200002	CRACKED AIR INTAKE	Invoice
-------	------------	--------	--------------------	---------

**DATE WORK CARRIED OUT:** 16/11/2020

**WORK CARRIED OUT:**

ASSEMBLE ALL COMPONENTS  
AIR CLEANER HOUSING  
ADBLUE TANK  
STEP BRACKET  
AIR FILTER  
FRONT LEFT MUDGUARD  
FRONT LEFT LEAF SPRING (REAR SHACKLE)

50815	05/11/2020	201997	A SERVICE	Invoice
-------	------------	--------	-----------	---------

**DATE WORK CARRIED OUT:** 02/11/2020

**WORK CARRIED OUT:**

CARRIED OUT A SERVICE AS PER HVW SERVICE SHEET  
REPLACED FIRE EXTINGUISHER  
REPLACED WIPER BLADES  
TOPPED UP ENGINE OIL  
SIGNED O/S DEFECTS  
DRAINED AND REMOVED LHS FRONT HUB CAB AND INSPECT OIL FOR METAL - ALL GOOD.  
TIGHTENED HUB NUT TO SPEC (600NM)  
CHECKED FOR PLAY - ALL GOOD  
REFITTED HUB CAB FILLED WITH 85W140 GEAR OIL

**FURTHER ACTION REQUIRED -**

REAR DIFF PINION SEAL WEEPING OIL FILTER LOOSE (MONITOR)  
BRAKE LINING AROUND 30-40% (MONITOR)  
RADIATOR DRAIN PLUG LEAKING - WILL BREAK IF TIGHTENED ANY FURTHER  
2ND & 3RD SWAY BAR BUSHES U/S

**Vehicle Details**

<b>Registration</b>	331WIF	<b>Next Service</b>	<b>Litres</b>	
<b>Make</b>	IVECO	<b>Rego Due</b>	<b>Trans</b>	N/A
<b>Model</b>	STRALIS	<b>Engine #</b>	<b>Air</b>	Yes
<b>Model Series</b>		<b>VIN</b>	<b>Cyl</b>	0
<b>Model Code</b>		<b>Build Date</b>	<b>Body</b>	PRIMEMOVER
<b>Colour</b>	WHITE	<b>Odometer</b>	<b>Prod</b>	2016

Invoice No.	Date	Odometer	Description	Type
			LHS FONT SHACKLE PIN BUSH U/S (LOWER) CAB TILT RAM BUSHES WORN - HAVE MOVEMENT (CAUSES KNOCKING NOISE IN CAB) EXHAUST HAS A PIN HOLE IN IT (LEAKING ADBLUE) LHS FRONT WHEEL BEARING HAS PLAY IN IT	
50806	03/11/2020	202002	REPAIRS REQUIRED FOUND WHEN	Invoice
			REPLACE WORN 2END AND 3RD AXLE SWAY BAR BUSHES. REPLACE LHS WORN FRONT SHACKLE PIN BOLT, BOLT OBTAINED OFF ROLL OVER CHASSIS. REPLACE CAB TILT RAM BUSHES WORN OUT. UNABLE TO PURCHASES BUSHES SEPARATELY, CAUSING KNOCKING NOISE IN CAB, RAM FUNCTIONING OK. COOLANT LEAKING FROM DRAIN PLUG. FUTURE WORK. BRAKE PADS AT 30% WILL REQUIRE CHANGING NEXT SERVICE. REAR DIFF IS WEEPING OIL FROM THE PINNION MONITOR. EXHAUST HAS A PIN HOLE LEAK MONITOR.	
50616	08/10/2020	0	AIR LEAK	Invoice
			DATE WORK CARRIED OUT: 08/10/2020  WORK CARRIED OUT: REMOVE AND REPLACE AIR DRYER ASSEMBLY INSPECT FRONT BAR ALIGNMENT UNABLE TO ADJUST MAIN PART OF BAR S IT MOUNTED ON STUDS - CAN ADJUST STEPS ETC.	
50243	08/10/2020	198339	ACCIDENT DAMAGE	Invoice
			DATE WORK CARRIED OUT: 7/10 - 8/10/2020  WORK CARRIED OUT: PREPARED BUMPER BAR FOR PAINTING PREPARED STEPS FOR PAINTING MASKED ALL AREAS PRIMED & PAINTED BUMPER BAR AND STEPS 8/10/2020  INSPECT HEAD LIGHTS - FOUND HEIGHT BEAM ARM INCORRECT WERE ABLE TO ADJUST LHS TO CORRECT SETTING RHS COULD ONLY JUST A SMALL AMOUNT ONLY  NEED TO REMOVE AND INVESTIGATE RHS HEAD LIGHT FRAME ASSY WHEN TRUCK BECOMES AVAILABLE. FIT BUMPER BAR CAPS & D/G SIGN RE CHECKED ALL LIGHTS ON BAR REPLACED O-RING BETWEEN AIR DRYER & 6 WAY VALVE	

**Vehicle Details**

<b>Registration</b>	331WIF	<b>Next Service</b>	<b>Litres</b>	
<b>Make</b>	IVECO	<b>Rego Due</b>	<b>Trans</b>	N/A
<b>Model</b>	STRALIS	<b>Engine #</b>	<b>Air</b>	Yes
<b>Model Series</b>		<b>VIN</b>	<b>Cyl</b>	0
<b>Model Code</b>		<b>Build Date</b>	<b>Body</b>	PRIMEMOVER
<b>Colour</b>	WHITE	<b>Odometer</b>	<b>Prod</b>	2016

Invoice No.	Date	Odometer	Description	Type
TESTED OPERATION 6 WAY LEAKING @ EXHAUST				
50353	28/08/2020	193764	CARRY OUT B SERVICE	Invoice
DATE WORK CARRIED OUT: 28/08/2020  WORK CARRIED OUT: CARRIED OUT B SERVICE AS PER HVW SERVICE SHEET LH LEAD LIGHT BULB REPLACED  <b>FURTHER ACTION REQUIRED -</b>  AIR CLEANER HOUSING CRACKED BEFORE AIR FILTER. 3RD AXLE AIRBAG CRACKING				
50298	21/08/2020	0	REPLACE WINDSCREEN	Invoice
DATE WORK CARRIED OUT:  WORK CARRIED OUT: SUPPLY & FIT FRONT WINDSCREEN IH2075				
50362	20/08/2020		REMOVE AND REPLACE FRONT BUMPER	Invoice
DATE WORK CARRIED OUT: 20/08/2020  WORK CARRIED OUT: REPLACED FRONT BUMPER				
50250	10/08/2020	192791	CARRY OUT C SERVICE	Invoice
DATE WORK CARRIED OUT: 10/08/2020  WORK CARRIED OUT: CARRIED OUT C SERVICE ACCIDENT DAMAGE FRONT BAR P/S STEP ASSEMBLY & BRACKET P/S REAR OF FRONT WHEEL MUD GUARD & LIGHT				

**Vehicle Details**

<b>Registration</b>	331WIF	<b>Next Service</b>	<b>Litres</b>	
<b>Make</b>	IVECO	<b>Rego Due</b>	<b>Trans</b>	N/A
<b>Model</b>	STRALIS	<b>Engine #</b>	<b>Air</b>	Yes
<b>Model Series</b>		<b>VIN</b>	<b>Cyl</b>	0
<b>Model Code</b>		<b>Build Date</b>	<b>Body</b>	PRIMEMOVER
<b>Colour</b>	WHITE	<b>Odometer</b>	<b>Prod</b>	2016

Invoice No.	Date	Odometer	Description	Type
<b>FURTHER ACTION REQUIRED -</b>				
SLIGHT MOVEMENT TIE RODS 1ST DRIVE SWAY BAR BUSHES WORN POWER STEERING RES LEAKING - MINOR TURBO SEAL LEAKING - MINOR AIR BAGS BEGINNING TO CRACK				
<b>50206</b>	<b>05/08/2020</b>	<b>192400</b>	<b>DAMAGE INSPECTION REPAIRS - AK</b>	<b>Invoice</b>
DATE WORK CARRIED OUT: 05/08/2020				
WORK CARRIED OUT: SECURED D/G SIGN CHECKED FOR MUDGUARD , BOLTS MISSING				
<b>50198</b>	<b>30/07/2020</b>	<b>0</b>	<b>DAMAGE INSPECTION</b>	<b>Invoice</b>
DATE WORK CARRIED OUT: 30/07/2020				
WORK CARRIED OUT: INSPECT DAMAGE ON DRIVERS SIDE REAR PANEL ON CAB WILL EITHER NEED TO BE REPLACED OR PANEL BEATED OUT WINDSCREEN HAS A HUGE CHIP IN SCREEN IT IS UN ROADWORTHY. BOLTS MISSING OUT OF BOTH MUDGUARDS DG SIGN ON FRONT NEEDS TO BE POP RIVETED				
<b>50079</b>	<b>15/07/2020</b>	<b>190234</b>	<b>OIL &amp; COOLANT</b>	<b>Invoice</b>
DATE WORK CARRIED OUT: 15/07/2020				
WORK CARRIED OUT: TOPPED UP ENGINE OIL TOPPED UP COOLANT HAD TO JACK CAB UP AND DOWN INSPECTED LOW OIL PRESSURE SENSOR FAULT CLEARED CODE				
<b>50309</b>	<b>01/07/2020</b>	<b>0</b>	<b>RFC 21 FAULT - 29/04/2020</b>	<b>Invoice</b>
DATE WORK CARRIED OUT: 29/04/2020				
WORK CARRIED OUT: TEST DROVE VEHICLE FOR RFC 21 FAULT CHECKED WIRING HARNESS FOUND FAULT @ FRONT OF TURNTABLE				

Vehicle Details

Registration	331WIF	Next Service		Litres	
Make	IVECO	Rego Due		Trans	N/A
Model	STRALIS	Engine #		Air	Yes
Model Series		VIN	WJMS2NTH40C323176	Cyl	0
Model Code		Build Date	2016	Body	PRIMEMOVER
Colour	WHITE	Odometer	449549	Prod	2016

Invoice No.	Date	Odometer	Description	Type
FOUND TO BE FRONT DIFF BRAKES SENSOR RHS CABLE PLUG ENDS FEMALE TERMINALS NEEDED CLOSING UP TO REGAIN FIRM TENSION ACROSS PLUG MALE/FEMALE CONTACT ALSO CHECKED OTHER SENSOR PLUGS & TIGHTENED UP AS REQUIRED SECURED ALL CABLE AT REAR AS REQUIRED RECHECKED TRUCK FOR FAULTS AFTER ROAD TEST - ALL OK				