



Vehicle History

Vehicle Details

Registration	194UBY	Next Service	Litres	
Make	KRUEGER	Rego Due	Trans	N/A
Model	ST338	Engine #	Air	Yes
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	SEMITRAILER
Colour		Odometer	Prod	2015

Invoice No.	Date	Odometer	Description	Type
59596	22/07/2024	124323	A SERVICE	Invoice
<p>PARK TRAILER IN WORKSHOP CARRY OUT A SERVICE AS PER SERVICE SHEET APPLY AIR TO TRAILER TEST LIGHTING FUNCTION LIFT TRAILER WITH HOIST CHECK WHEEL BEARINGS FOR MOVEMENT CHECK SUSPENSION COMPONENTS CHECK KING PIN BOLT TENSION CHECK SKID PLATE CHECK THE UNDERCARRIAGE OF THE TRAILER CARRY OUT GREASING OF AXLES CARRY OUT ADJUSTMENT OF BRAKES LOWER TRAILER CHECK WHEEL TENSION CHECK WHEEL BEARING GREASE FOR CONTAMINANTS CHECK ALL LIVERY INCLUDING MUDFLAPS AND DECAL INSPECT MARKER PLATES INCLUDING CON SIGN, CHEVRONS, AND OVERTAKE SIGNAGE CHECK TOP DECK OF TRAILER FOR ALL FUNCTIONALITY APPLY SERVICE STICKER COMPLETE PAPERWORK CLEAN WORK AREA MOVE TRAILER OUT OF WORKSHOP NOTE L/S 2ND AXLE SHOCK ABSORBER REMOVED AND REPLACED 3 X SIDE MARKER LIGHTS REPLACED REPLACED LHR TAIL LIGHT 3RD AXLE ALL TYRES BELOW 2.5MM CONNECTED VEHICLE TO TRAILER TESTED LIGHTS REPLACED REAR STOP/TAILLIGHTS (INNER LH + RH)</p> <p><u>HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE JEFF FOR PRICING ON - 07 3260 8950</u></p>				
59258	22/05/2024	116982	REPAIR RHR MUDGUARD	Invoice

REMOVED LHS MUDGUARD AND MUDFLAP
CUT MUDFLAP TO LEGAL SIZE
FIT TO MUDGUARD WITH NEW BOLTS
REMOVED REAR MUDGUARD BRACKET/BAR - DAMAGED
REMOVED LH REAR MUDGUARD BOLTS
CUT, HEATED AND STRAIGHTENED MUDGUARD BENT BRACKET

Vehicle Details

Registration	194UBY	Next Service	Litres	
Make	KRUEGER	Rego Due	Trans	N/A
Model	ST338	Engine #	Air	Yes
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	SEMITRAILER
Colour		Odometer	Prod	2015

Invoice No.	Date	Odometer	Description	Type
-------------	------	----------	-------------	------

CUT SECTION OF REAR BAR TO BE ABLE TO STRAIGHTEN REWELDED SECTION OF BRACKET TO BAR
ALIGNED AND WELDED REAR BAR
PAINTED REAR BAR/BRACKET
FITTED REAR BAR AND ATTACHED LH REAR MUDGUARD
CUT RH REAR MUDFLAP TO SIZE
FITTED RH #3 AXLE NEW MUDGUARD AND BOLTS
FITTED MUDFLAP AND BOLTS
RETURNED TRAILER TO SHED 24

**HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD -
STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS
WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.
PHONE JEFF FOR PRICING ON - 07 3260 8950**

59090	16/04/2024	96264	C SERVICE	Invoice
--------------	-------------------	--------------	------------------	----------------

PARK TRAILER IN WORKSHOP

CARRY OUT C SERVICE AS PER SERVICE SHEET
APPLY AIR TO TRAILER
TEST LIGHTING FUNCTION
LIFT TRAILER WITH HOIST
CHECK SUSPENSION COMPONENTS
CHECK KING PIN BOLT TENSION
CHECK SKID PLATE
CHECK THE UNDERCARRIAGE OF THE TRAILER
CARRY OUT GREASING OF AXLES
CARRY OUT DE-ADJUSTMENT OF BRAKES
REMOVE HUB CAPS AND REMOVE BEARING ADJUSTMENT NUTS
REMOVE BEARINGS FROM HUBS
CLEAN STUB AXLES AND APPLY NEW FILM OF GREASE TO STUB AXLES
CLEAN BEARINGS IN TURBO WASH
CLEAN HUBS OF GREASE AND REPACK HUBS AS REQUIRED
REMOVED BEARINGS FROM PARTS WASHER BLOW OUT WITH AIR AND REPACK BEARINGS
INSTALL BEARINGS TO HUBS
INSTALL INNER HUB SEALS
INSTALL HUBS TO THE TRAILER AND TENSION-BEARING ADJUSTMENT NUTS
SECURE BEARING ADJUSTMENT NUTS WITH RETAINERS
REINSTALL HUB CAPS TO AXLES AND TENSION HUB CAPS
CARRY OUT ADJUSTMENT OF BRAKES
LOWER TRAILER
CHECK WHEEL NUT TENSION
CHECK ALL LIVERY INCLUDING MUDFLAPS AND DECAL
INSPECT MARKER PLATES INCLUDING CON SIGN, CHEVRONS, AND OVERTAKE SIGNAGE
CHECK TOP DECK OF TRAILER FOR ALL FUNCTIONALITY
APPLY SERVICE STICKER
COMPLETE PAPERWORK
CLEAN WORK AREA
MOVE TRAILER OUT OF WORKSHOP

HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD -

Vehicle Details

Registration	194UBY	Next Service	Litres	
Make	KRUEGER	Rego Due	Trans	N/A
Model	ST338	Engine #	Air	Yes
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	SEMITRAILER
Colour		Odometer	Prod	2015

Invoice No.	Date	Odometer	Description	Type
<u>STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.</u> <u>PHONE JEFF FOR PRICING ON - 07 3260 8950</u>				
58516	19/01/2024	96264	AIR LEAK FRONT OF TRAILER	Invoice
INSPECT AIR LEAK REMOVE AND REPLACE FRONT MALE AIR FITTING TEST - ALL OK <u>HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.</u>				
58012	02/11/2023	92004	A SERVICE	Invoice
PARK TRAILER IN WORKSHOP CARRY OUT A SERVICE AS PER SERVICE SHEET APPLY AIR TO TRAILER TEST LIGHTING FUNCTION LIFT TRAILER WITH HOIST CHECK WHEEL BEARINGS FOR MOVEMENT CHECK SUSPENSION COMPONENTS CHECK KING PIN BOLT TENSION CHECK SKID PLATE CHECK THE UNDERCARRIAGE OF THE TRAILER CARRY OUT GREASING OF AXLES CARRY OUT ADJUSTMENT OF BRAKES LOWER TRAILER CHECK WHEEL TENSION CHECK WHEEL BEARING GREASE FOR CONTAMINANTS CHECK ALL LIVERY INCLUDING MUDFLAPS AND DECAL INSPECT MARKER PLATES INCLUDING CON SIGN, CHEVRONS, AND OVERTAKE SIGNAGE CHECK TOP DECK OF TRAILER FOR ALL FUNCTIONALITY APPLY SERVICE STICKER COMPLETE PAPERWORK CLEAN WORK AREA MOVE TRAILER OUT OF WORKSHOP AND RETURNED TO SHED 24				
57746	04/10/2023	89451	INDICATOR FAULT	Invoice
INSPECT INDICATOR FAULT CHECK FOR POWER FROM TRUCK CHECK FPR POWER THROUGH LIGHT SOCKET NO POWER GOING THROUGH REMOVE AND REPLACE LIGHT SOCKET <u>HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.</u>				

Vehicle Details

Registration	194UBY	Next Service	Litres	
Make	KRUEGER	Rego Due	Trans	N/A
Model	ST338	Engine #	Air	Yes
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	SEMITRAILER
Colour		Odometer	Prod	2015

Invoice No.	Date	Odometer	Description	Type
57383	10/08/2023	84767	CARRY OUT GREASING OF TRUCK	Invoice

- GREASED & CHECKED OVER TRAILER

HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.

57265	01/08/2023	84042	SUPPLY AND FIT NEW LANDING LEGS	Invoice
-------	------------	-------	---------------------------------	---------

COLLECTED TRAILER FROM BUCCINI YARD
CHECKED TRAILER FOR LANDING LEG FAULT

PLACED TRAILER UNDER STANDS
LIFTED LEGS + FOUND TIGHT HALFWAY UP / DOWN
REMOVED LEG BENT INTERNALLY
REMOVED LANDING LEGS
FITTED LANDING LEGS
WELDED SUPPORT BRACKETS ON LEG
STRAIGHTENED SUPPORT BRACKETS
FITTED NEW HANDLE AND HOLDER
PAINTED WELDS
GREASED LEGS
TESTED OPERATION
RETURNED TRAILER TO SHED 24

57319	18/07/2023	83469	A SERVICE	Invoice
-------	------------	-------	-----------	---------

COLLECTED FROM SHED 24
PARKED IN THE WORKSHOP
CARRY OUT A SERVICE AS PER SERVICE SHEET

- APPLY AIR TO TRAILER
- TEST LIGHTING FUCTION
- LIFT TRAILER WITH HOIST
- CHECK WHEEL BEARINGS FOR MOVEMENT
- CHECK SUSPENSION COMPONENTS
- CHECK KING PIN BOLT TENSION
- CHECK SKID PLATE
- CHECK UNDERCARAGE OF TRAILER
- CARRY OUT GREASING OF AXLES
- CARRY OUT ADJUSTMENT OF BRAKES
- LOWER TRAILER
- CHECK WHEEL TENSION
- CHECK WHEEL BEARING GREASE FOR CONTAMINENTS
- CHECK ALL LIVERY INCLUDING MUDFLAPS AND DECAL
- INSPECT MARKER PLATES INCLUDING CON SIGN, CHEVERONS AND OVER TAKE SIGNAGE
- CHECK TOP DECK OF TRAILER FOR ALL FUNCTIONALITY
- APPLY SERVICE STICKER
- COMPLETE PAPER WORK
- CLEAN WORK AREA
- MOVE TRAILER OUT OF WORKSHOP

REPLACED LEAKING BOOSTER

Vehicle Details

Registration	194UBY	Next Service	Litres	
Make	KRUEGER	Rego Due	Trans	N/A
Model	ST338	Engine #	Air	Yes
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	SEMITRAILER
Colour		Odometer	Prod	2015

Invoice No.	Date	Odometer	Description	Type
			LANDING LEGS WHERE EXTREMELY TIGHT - PROBABLY BENT, RECOMMENDED REPLACING GREASED TRAILER TWIST LOCKS ADJUSTED BRAKES CHECKED LIGHTS, WHEEL BEARING FOUND FAULTY BREAK BOOSTER REMOVED OLD BOOSTER' REFIT NEW BOOSTER - ALL GOOD DROPPED BACK TO SHED 24	
56332	11/04/2023	0	C SERVICE	Invoice
			COLLECTED TRAILER FROM BUCCINI YARD CARRY OUT C SERVICE AS PER SERVICE SHEET CARRIED OUT RE-PACK <ul style="list-style-type: none">PARK TRAILER IN SHEDAPPLY AIR TO TRAILERTEST LIGHTING FUCTIONLIFT TRAILER WITH HOISTCHECK SUSPENSION COMPONENTSCHECK KING PIN BOLT TENSIONCHECK SKID PLATECHECK UNDERCARAGE OF TRAILERCARRY OUT GREASING OF AXLESCARRY OUT DE-ADJUSTMENT OF BRAKESREMOVE HUB CAPS AND REMOVE BEARING ADJUSTMENT NUTSREMOVE BEARINGS FROM HUBSCLEAN STUB AXLES AND APPLY NEW FILM OF GREASE TO STUB AXLESCLEAN BEARINGS IN TURBO WASHCLEAN HUBS OF GREASE AND REPACK HUBS AS REQUIREDREMOVED BEARINGS FROM PARTS WASHER BLOW OUT WITH AIR AND REPACK BEARINGSINSTALL BEARINGS TO HUBSINSTALL INNER HUB SEALSINSTALL HUBS TO TRAILER AND TENSION BEARING ADJUSTMENT NUTSSECURE BEARING ADJUSTMENT NUTS WITH RETAINERSREINSTALL HUB CAPS TO AXLES AND TENSION HUB CAPSCARRY OUT ADJUSTMENT OF BRAKESLOWER TRAILERCHECK WHEEL NUT TENSIONCHECK ALL LIVERY INCLUDING MUDFLAPS AND DECALINSPECT MARKER PLATES INCLUDING CON SIGN, CHEVERONS AND OVER TAKE SIGNAGECHECK TOP DECK OF TRAILER FOR ALL FUNCTIONALITYAPPLY SERVICER STICKERCOMPLETE PAPEERWORKCLEAN WORK AREAMOVE TRAILER OUT OF WORKSHOP REPLACED LEAKING #2 RHS BRAKE BOOSTER NOTE - #2 LHS INNER TYRE U/S REPLACED #2 RHS BRAKE BOOSTER	
55335	14/11/2022	61525	A SERVICE	Invoice
			COLLECTED FROM SHED 24 PARKED IN WORKSHOP CARRIED OUT A SERVICE	

Vehicle Details

Registration	194UBY	Next Service	Litres	
Make	KRUEGER	Rego Due	Trans	N/A
Model	ST338	Engine #	Air	Yes
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	SEMITRAILER
Colour		Odometer	Prod	2015

Invoice No.	Date	Odometer	Description	Type
CARRIED OUT TESTS / CHECKS TO WIRING AS REQUIRED REPAIRED 1 X RH SIDE LAMP LOOSE PLUG CONNECTORS / TEST FOUND NUMBER PLATE U/S DRILLED HOLES IN REAR BAR AND FITTED AND REPLACED NUMBER PLATE LIGHTS DROVE BACK TO SHED 24 AND PARKED				
55267	28/10/2022	60328	SEIZED TWIST LOCK	Invoice
FREED UP SEIZED TWIST LOCK				
54419	28/06/2022	51006	A SERVICE	Invoice
COLLECTED TRAILER FROM SHED 24 PARKED IN WORKSHOP CARRIED OUT A SERVICE REPLACED KING PIN AND BOLTS REPLACED RH REAR STOP TAIL LIGHT REPLACED LH SERVICE BRAKE RELAY VALVE REPLACED RH # 1 AXLE SHOCK ABSORBER STRAP REPLACED LH REAR STOP TAIL LIGHT RETURNED TRAILER TO SHED 24 NOTE- LANDING LEG TIGHT TO WIND UP OR DOWN				
53842	14/03/2022	0	C SERVICE AND REPAIRS	Invoice
14/3/2022 CARRIED OUT C SERVICE NOTE: REPLACED PARKSIDE TAIL LIGHT ASSEMBLY SIDE MARKER REPLACED 1ST AXLE RH SIDE SNAPPED SHOCKIE STRAP				
53773	25/02/2022	41482	REPLACE TRAILER PLUG	Invoice
25/2/2022 REPLACE AND FIT NEW TRAILER PLUG ON THE TRAILER				
53462	06/01/2022	35231	AIR LEAK	Invoice
DIAGNOSED THAT THE LHF BRAKE BOOSTER WAS LEAKING AIR, DRIVER TOOK TRAILER TO COMPLETE A DELIVERY. TRAILER DROPPED OFF AT THE WORKSHOP. REMOVED LHF BRAKE BOOSTER. PUT NEW BOOSTER INTO THE VICE AND CAGED, LOOSEND OFF BOOSTER CLAMP BOLTS AND CLOCKED BOOSTER TO MATCH UP WITH THE OLD ONE. TIGHTEND TO CLAMPING BOLTS AND THEN UNCAGED THE BOOSTER. FITTED NEW BOOSTER TO THE TRIALER AND CHECKED FOR LEAKS ALL OK.				
51640	05/03/2021	10176	CARRY OUT A SERVICE	Invoice

Vehicle Details

Registration	194UBY	Next Service	Litres	
Make	KRUEGER	Rego Due	Trans	N/A
Model	ST338	Engine #	Air	Yes
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	SEMITRAILER
Colour		Odometer	Prod	2015

Invoice No.	Date	Odometer	Description	Type
DATE WORK CARRIED OUT: 05/03/2021 WORK CARRIED OUT: CARRIED OUT A SERVICE ON TRAILER CONTAINER LOCKS WERE STICKY, CLEANED ALL LOCKS OUT AND LUBED - CHECKED & ALL OK BRAKE LININGS 90% LEFT FOUND 2ND AXLE RIGHT SIDE LOW TREAD ON OUTER TYRE				
51364	02/02/2021	6790	CARRIED OUT C SERVICE	Invoice
DATE WORK CARRIED OUT: 02/02/2021 WORK CARRIED OUT: CARRIED OUT C SERVICE DROPPED TRAILER BACK TO BT				
51175	31/12/2020	2799	A SERVICE	Invoice
DATE WORK CARRIED OUT: 31/12/2020 WORK CARRIED OUT: CARRIED OUT A SERVICE TIGHTENED LH #3 AXLE SHOCK ABSORBER STRAIGHTENED LH #3 AXLE MUDGUARD BRACKET DEFECTS NOTED - RH #3 AXLE TYRE TREAD LOW (POS 11 & 12)				
51047	07/12/2020	0	HUBOMETER	Invoice
DATE WORK CARRIED OUT: 03/12/2020 WORK CARRIED OUT: REMOVED & REPLACED BROKEN HUBOMETER				
50761	27/10/2020	198281	A SERVICE	Invoice
DATE WORK CARRIED OUT: 26/10/2020 WORK CARRIED OUT: CARRIED OUT A SERVICE AS PER HVW SERVICE SHEET FURTHER ACTION REQUIRED - LHR OUTER TYRE WORN DAMAGE TO LHS RIMS				

Vehicle Details

Registration	194UBY	Next Service		Litres	
Make	KRUEGER	Rego Due		Trans	N/A
Model	ST338	Engine #		Air	Yes
Model Series		VIN	6FH9079GAFM015779	Cyl	0
Model Code		Build Date	2015	Body	SEMITRAILER
Colour		Odometer	124323	Prod	2015

Invoice No.	Date	Odometer	Description	Type
50661	12/10/2020	182155	LEVELING ISSUE	Invoice
DATE WORK CARRIED OUT: 12/10/2020				
WORK CARRIED OUT:				
RR16017				
TRAILER WONT GO UP OR DOWN FOUND FAULTY RIDE HEIGHT VALVE & MANUAL RAISE LOWER HANDLE VALVE REPLACED DEFECTIVE VALVES.				
50468	17/09/2020	180560	TYRE & RIM REPLACEMENT	Invoice
DATE WORK CARRIED OUT: 17/09/2020				
WORK CARRIED OUT:				
ATTEND YARD REPLACED RH #1 AXLE OUTSIDE TYRE & RIM TENSIONED WHEEL NUTS REPLACED RH FRONT SIDE MARKER LIGHT				
50241	19/08/2020	180559	CARRY OUT A SERVICE	Invoice
DATE WORK CARRIED OUT:				
WORK CARRIED OUT:				
CARRIED OUT A SERVICE				
FURTHER ACTION REQUIRED-				
FR WHEEL TYRE REQUIRES REPLACING -WHEEL BUCKLED AND TYRE DEFLATED AND SIDEWALL SPLIT				
50261	19/08/2020	0	DAMAGED RIM	Invoice
DATE WORK CARRIED OUT: 19/08/2020				
WORK CARRIED OUT:				
CHECKED DAMAGED RIM FOUND NEW RIM FROM TYRE STACK NEEDS TO BE TAKEN TO TYRERIGHT TO BE CHANGED				

Vehicle Details

Registration	194UBY	Next Service	Litres	
Make	KRUEGER	Rego Due	Trans	N/A
Model	ST338	Engine #	Air	Yes
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	SEMITRAILER
Colour		Odometer	Prod	2015

Invoice No.	Date	Odometer	Description	Type
50054	17/07/2020	0	RHS INDICATOR NOT WORKING ON	Invoice
DATE WORK CARRIED OUT: 17/07/2020				
WORK CARRIED OUT: RHS INDICATOR LIGHT NOT WORKING RESET CHECKED- ALL GOOD				
50070	15/07/2020	0	BRAKE BOOSTER	Invoice
DATE WORK CARRIED OUT: 15/07/2020				
WORK CARRIED OUT: REPLACE BRAKE BOOSTER				