



## Vehicle History

### Vehicle Details

Registration	195UBY	Next Service		Litres	
Make	KRUEGER	Rego Due		Trans	N/A
Model	ST338	Engine #		Air	Yes
Model Series		VIN	6FH9079GAFM015780	Cyl	0
Model Code		Build Date	2015	Body	SEMITRAILER
Colour		Odometer	69663	Prod	2015

Invoice No.	Date	Odometer	Description	Type
61143	26/06/2025	69663	A SERVICE + REPAIRS	Invoice
<p>PARK TRAILER IN WORKSHOP CARRY OUT A SERVICE AS PER SERVICE SHEET APPLY AIR TO TRAILER TEST LIGHTING FUNCTION LIFT TRAILER WITH HOIST CHECK WHEEL BEARINGS FOR MOVEMENT CHECK SUSPENSION COMPONENTS CHECK KING PIN BOLT TENSION CHECK SKID PLATE CHECK THE UNDERCARRIAGE OF THE TRAILER CARRY OUT GREASING OF AXLES CARRY OUT ADJUSTMENT OF BRAKES LOWER TRAILER CHECK WHEEL TENSION CHECK WHEEL BEARING GREASE FOR CONTAMINANTS CHECK ALL LIVERY INCLUDING MUDFLAPS AND DECAL INSPECT MARKER PLATES INCLUDING CON SIGN, CHEVRONS, AND OVERTAKE SIGNAGE CHECK TOP DECK OF TRAILER FOR ALL FUNCTIONALITY APPLY SERVICE STICKER COMPLETE PAPERWORK CLEAN WORK AREA MOVE TRAILER OUT OF WORKSHOP NOTE REPLACED MR BOOSTER REPAIRED AIR LEAK ON RR BOOSTER REPLACED RHS MARKER LIGHT ADJUSTED BRAKES</p> <p><b><u>HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES &amp; MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING &amp; BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE THE STORE FOR PRICING ON - 07 3260 8950</u></b></p> <p>***RECEIVE A \$25 DISCOUNT FOR ANY POSITIVE GOOGLE REVIEW ON OUR COMPANY GOOGLE WEBPAGE - HEAVY VEHICLE WORKSHOP***</p>				
60704	19/03/2025	61666	DEFECTS - CHECK LIGHTS, AIR LEAK	Invoice

DEFECTS - CHECK LIGHTS, AIR LEAK AND TYRES (2 OFF)

HOOKED FREIGHT UP TO TRAILER  
MARKER LIGHT, PARK LIGHT AND BRAKE LIGHTS WORKING

## Vehicle Details

Registration	195UBY	Next Service	Litres	
Make	KRUEGER	Rego Due	Trans	N/A
Model	ST338	Engine #	Air	Yes
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	SEMITRAILER
Colour		Odometer	Prod	2015

Invoice No.	Date	Odometer	Description	Type
			2 TYRES FITTED NO AIR LEAKS FOUND ADJUSTED ALL BRAKES GREASE ALL NIPPLES CHECKED TAIL LIGHT AND CLEARANCE LIGHTS - ALL OKAY DROPPED TRAILER ON THE STREET <b><u>HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES &amp; MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING &amp; BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE THE STORE FOR PRICING ON - 07 3260 8950</u></b>	

60654	05/03/2025	60603	A SERVICE	Invoice
			PARK TRAILER IN WORKSHOP CARRY OUT A SERVICE AS PER SERVICE SHEET APPLY AIR TO TRAILER TEST LIGHTING FUNCTION - REPAIRED RH FRONT SIDE MAKER LIGHT, LIFT TRAILER WITH HOIST CHECK WHEEL BEARINGS FOR MOVEMENT CHECK SUSPENSION COMPONENTS CHECK KING PIN BOLT TENSION CHECK SKID PLATE CHECK THE UNDERCARRIAGE OF THE TRAILER CARRY OUT GREASING OF AXLES CARRY OUT ADJUSTMENT OF BRAKES LOWER TRAILER CHECK WHEEL TENSION CHECK WHEEL BEARING GREASE FOR CONTAMINANTS CHECK ALL LIVERY INCLUDING MUDFLAPS AND DECAL INSPECT MARKER PLATES INCLUDING CON SIGN, CHEVRONS, AND OVERTAKE SIGNAGE CHECK TOP DECK OF TRAILER FOR ALL FUNCTIONALITY - CARRIED FITTED LH FRONT TWIST LOCK BOLT, STRAIGHTENED FRONT MUDGUARD BRACKETS, REMOVED AND STRAIGHTENED MARKER PLATES, REPLACED DOCK RUBBERS, REFITTED AIR LINES TO REAR AIR TANK, AND REPLACED HOSE CLAMPS, REPLACED SEAL CO SPRING BRAKE VALVE APPLY SERVICE STICKER COMPLETE PAPERWORK CLEAN WORK AREA MOVE TRAILER OUT OF WORKSHOP	

59737	22/08/2024	30775	A SERVICE	Invoice
			PARK TRAILER IN WORKSHOP CARRY OUT A SERVICE AS PER SERVICE SHEET APPLY AIR TO TRAILER TEST LIGHTING FUNCTION LIFT TRAILER WITH HOIST CHECK WHEEL BEARINGS FOR MOVEMENT CHECK SUSPENSION COMPONENTS CHECK KING PIN BOLT TENSION CHECK SKID PLATE CHECK THE UNDERCARRIAGE OF THE TRAILER CARRY OUT GREASING OF AXLES CARRY OUT ADJUSTMENT OF BRAKES LOWER TRAILER CHECK WHEEL TENSION CHECK WHEEL BEARING GREASE FOR CONTAMINANTS	

## Vehicle Details

Registration	195UBY	Next Service	Litres	
Make	KRUEGER	Rego Due	Trans	N/A
Model	ST338	Engine #	Air	Yes
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	SEMITRAILER
Colour		Odometer	Prod	2015

Invoice No.	Date	Odometer	Description	Type
			<p>CHECK ALL LIVERY INCLUDING MUDFLAPS AND DECAL  INSPECT MARKER PLATES INCLUDING CON SIGN, CHEVRONS, AND OVERTAKE SIGNAGE  CHECK TOP DECK OF TRAILER FOR ALL FUNCTIONALITY  APPLY SERVICE STICKER  COMPLETE PAPERWORK  CLEAN WORK AREA  MOVE TRAILER OUT OF WORKSHOP  NOTE  4 X SIDE MARKERS REPLAACED  2 X REAR SIDE REFLECTORS REPLACED  1 X FRONT REFLECTOR REPLACED  R/S TAIL GATE LIGHT CONES BROKEN BUT WORKING  LANDING LEG HARD TO OPERATE  R/S 3RD AND 2ND AXLE SPRAY SUSPENSION - SLIGHT DAMAGE</p> <p><b><u>HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES &amp; MORE ABOARD -  STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS  WELL AS FITTING &amp; BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.  PHONE JEFF FOR PRICING ON - 07 3260 8950</u></b></p>	

59116	22/04/2024	30775	C SERVICE	Invoice
			<p>CARRIED OUT C SERVICE  REDUCED LENGTH OF AIR LINE ON 2ND-3RD AXLE  REPLACED CHEVRONS ON REAR</p> <p>PARK TRAILER IN WORKSHOP</p> <p>CARRY OUT C SERVICE AS PER SERVICE SHEET  APPLY AIR TO TRAILER  TEST LIGHTING FUNCTION  LIFT TRAILER WITH HOIST  CHECK SUSPENSION COMPONENTS  CHECK KING PIN BOLT TENSION  CHECK SKID PLATE  CHECK THE UNDERCARRIAGE OF THE TRAILER  CARRY OUT GREASING OF AXLES  CARRY OUT DE-ADJUSTMENT OF BRAKES  REMOVE HUB CAPS AND REMOVE BEARING ADJUSTMENT NUTS  REMOVE BEARINGS FROM HUBS  CLEAN STUB AXLES AND APPLY NEW FILM OF GREASE TO STUB AXLES  CLEAN BEARINGS IN TURBO WASH  CLEAN HUBS OF GREASE AND REPACK HUBS AS REQUIRED  REMOVED BEARINGS FROM PARTS WASHER BLOW OUT WITH AIR AND REPACK BEARINGS  INSTALL BEARINGS TO HUBS  INSTALL INNER HUB SEALS  INSTALL HUBS TO THE TRAILER AND TENSION-BEARING ADJUSTMENT NUTS  SECURE BEARING ADJUSTMENT NUTS WITH RETAINERS  REINSTALL HUB CAPS TO AXLES AND TENSION HUB CAPS  CARRY OUT ADJUSTMENT OF BRAKES  LOWER TRAILER  CHECK WHEEL NUT TENSION  CHECK ALL LIVERY INCLUDING MUDFLAPS AND DECAL</p>	

## Vehicle Details

Registration	195UBY	Next Service	Litres	
Make	KRUEGER	Rego Due	Trans	N/A
Model	ST338	Engine #	Air	Yes
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	SEMITRAILER
Colour		Odometer	Prod	2015

Invoice No.	Date	Odometer	Description	Type
			<p>INSPECT MARKER PLATES INCLUDING CON SIGN, CHEVRONS, AND OVERTAKE SIGNAGE</p> <p>CHECK TOP DECK OF TRAILER FOR ALL FUNCTIONALITY</p> <p>APPLY SERVICE STICKER</p> <p>COMPLETE PAPERWORK</p> <p>CLEAN WORK AREA</p> <p>MOVE TRAILER OUT OF WORKSHOP</p> <p><b><u>HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES &amp; MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING &amp; BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE JEFF FOR PRICING ON - 07 3260 8950</u></b></p>	
58699	15/02/2024	30775	C SERVICE	Invoice

PARK TRAILER IN WORKSHOP  
 CARRY OUT C SERVICE AS PER SERVICE SHEET  
 APPLY AIR TO TRAILER  
 TEST LIGHTING FUNCTION  
 LIFT TRAILER WITH HOIST  
 CHECK SUSPENSION COMPONENTS  
 CHECK KING PIN BOLT TENSION  
 CHECK SKID PLATE  
 CHECK THE UNDERCARRIAGE OF THE TRAILER  
 CARRY OUT GREASING OF AXLES  
 CARRY OUT DE-ADJUSTMENT OF BRAKES  
 REMOVE HUB CAPS AND REMOVE BEARING ADJUSTMENT NUTS  
 REMOVE BEARINGS FROM HUBS  
 CLEAN STUB AXLES AND APPLY NEW FILM OF GREASE TO STUB AXLES  
 CLEAN BEARINGS IN TURBO WASH  
 CLEAN HUBS OF GREASE AND REPACK HUBS AS REQUIRED  
 REMOVED BEARINGS FROM PARTS WASHER BLOW OUT WITH AIR AND REPACK BEARINGS  
 INSTALL BEARINGS TO HUBS  
 INSTALL INNER HUB SEALS  
 INSTALL HUBS TO THE TRAILER AND TENSION-BEARING ADJUSTMENT NUTS  
 SECURE BEARING ADJUSTMENT NUTS WITH RETAINERS  
 REINSTALL HUB CAPS TO AXLES AND TENSION HUB CAPS  
 CARRY OUT ADJUSTMENT OF BRAKES  
 LOWER TRAILER  
 CHECK WHEEL NUT TENSION  
 CHECK ALL LIVERY INCLUDING MUDFLAPS AND DECAL  
 INSPECT MARKER PLATES INCLUDING CON SIGN, CHEVRONS, AND OVERTAKE SIGNAGE  
 CHECK TOP DECK OF TRAILER FOR ALL FUNCTIONALITY  
 APPLY SERVICE STICKER  
 \*\*\*\*\*  
 SECURED AILINKS + ELECTRICAL CABLE AT #2 AXLE  
 REPLACED AIRBAG RIDE HEIGHT VALVE  
 ADJUSTED RIDE HEIGHT  
 REMOVE 3 SHOCKS  
 FIT NEW STRAPS TO SHOCKS  
 REFIT SHOCKS  
 HAD TO BEND BRACKETS BACK INTO POSITION

**Vehicle Details**

Registration	195UBY	Next Service	Litres	
Make	KRUEGER	Rego Due	Trans	N/A
Model	ST338	Engine #	Air	Yes
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	SEMITRAILER
Colour		Odometer	Prod	2015

Invoice No.	Date	Odometer	Description	Type
<b><u>HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING &amp; BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.</u></b>				
58498	17/01/2024	28698	REPAIR/REPLACE I BEAM	Invoice
PARKED TRAILER IN WORKSHOP ASSESS DAMAGE TO #5 TWIST LOCK BEAM MEASURED BEAM AND DIMENSIONS FOR REPLACEMENT REMOVED SAFETY ROPES, WIRING, MUDGUARDS AND OTHER COMPONENTS OXY CUT DAMAGED I BEAM GROUND OXY WELD FROM CHASSIS FITTED NEW TWISTLOCK BEAM MEASURED DISTANCES BETWEEN BEAMS AND TACKED INTO PLACE FITTED TWISTLOCK HOUSING TO BEAM CUT PLATES TO FIT ENDS OF TWIST LOCK BEAMS FABRICATED CHANNEL TO FIT UNDER TWISTLOCK BEAMS CLEANED WELDED AREAS PRIMED AND PAINTED RE-INSTALLED MUDGUARD SECURED AIRLINES UNDERNEATH TRAILER  <b><u>HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING &amp; BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.</u></b>				
57890	17/10/2023	18678	A SERVICE	Invoice
PARK VEHICLE IN WORKSHOP CARRY OUT A SERVICE AS PER SERVICE SHEET CARRY OUT WALK AROUND VISUAL INSPECTION SECURE HOIST ON TRUCK CHECK ALL LIGHTS INCLUDING ALL REVERSE LAMPS AND BEEPERS CHECK WIPER AND WASHER OPERATION CHECK BATTERY LEVELS, TERMINALS AND CLAMPS LIFT CAB/BONNET TO ACCESS ENGINE BAY CHECK ALL BELTS AND MOUNTS LIFT TRUCK ON HOIST CARRY OUT VISUAL INSPECTION OF UNDER CARRIAGE (DRIVE LINE AND SUSPENSION COMPONENTS) ADJUST BRAKES AND CHECK BRAKE THICKNESSES CHECK AND ADJUST CLUTCH IF APPLICABLE CHECK GEAR BOX OIL LEVEL AND QUALITY CHECK DIFF OIL LEVEL AND QUALITY CARRY OUT GREASING OF TRUCK LOWER TRUCK CHECK ENGINE OIL TOP UP COOLANT IF REQUIRED LOWER CAB/BONNET AND SECURE IN PLACE FIT SERVICE STICKER COMPLETE PAPERWORK ***NOTE*** REPLACED LH #1 AXLE BRAKE BOOSTER AND RHF MARKER LIGHT HOUSING <b><u>HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING &amp; BALANCING PLEASE ENQUIRE</u></b>				

**Vehicle Details**

<b>Registration</b>	195UBY	<b>Next Service</b>	<b>Litres</b>	
<b>Make</b>	KRUEGER	<b>Rego Due</b>	<b>Trans</b>	N/A
<b>Model</b>	ST338	<b>Engine #</b>	<b>Air</b>	Yes
<b>Model Series</b>		<b>VIN</b>	<b>Cyl</b>	0
<b>Model Code</b>		<b>Build Date</b>	<b>Body</b>	SEMITRAILER
<b>Colour</b>		<b>Odometer</b>	<b>Prod</b>	2015

Invoice No.	Date	Odometer	Description	Type
<b><u>TODAY FOR SIZING AND PRICING.</u></b>				
<b>56621</b>	<b>09/05/2023</b>		<b>A SERVICE + HUBOMETER</b>	<b>Invoice</b>
GOT CONTAINER UNLOADED OFF TRAILER CARRIED OUT "A" SERVICE INSTALLED NEW HUBO RESET AIR BAGS NOTE- GREASE IN GOOD CONDITION				
<b>56003</b>	<b>20/02/2023</b>	<b>0</b>	<b>C SERVICE</b>	<b>Invoice</b>
BROUGHT VEHICLE INTO WORKSHOP CARRIED OUT C SERVICE STRIP TRAILR FOR RE-PACK INNER NUTS ON LHS OF TRAILER WERE EXTREMELY TIGHT TO GET OFF INSPECTED BRAKES PUT BEARINGS IN TURBO WASHER REMOVE AND CLEAN CONES, BRAKE SHOES CLEAN STUB AXLES AND BACKING PLATES THOROUGHLY REMOVE PIN BUSHES CLEAN HUBS OUT, FIT INNER BEARINGS AND SEALS FIT NEW BRAKE SHOES FIT WHEELS, HUBS AND BEARINGS, TORQUE HUB NUTS TO SPEC REMOVE RHF WHEELS AND REMOVE SCREW IN ALLEN KEY FILL HUB WITH GREASE , FIT WHEELS TORQUE WHEEL NUTS ADJUST BRAKES, WELD BRACKET ONTO LHF FOR MARKER LIGHT REMOVE AN REPLACE MARKER PLATES REMOVE AND REPLACE DOCK RUBBERS MAADE UP/FITTED MARKER LAMP SUPPORT BRACKET AT LHF POSITION OUTSIDE REPLACED U/S FRONT LHS MARKER RECHECKED ALL LIGHTING - ALL OK FITTED NEW HUBO				
<b>55719</b>	<b>23/12/2022</b>	<b>103606</b>	<b>REMOVE AND REPLACE MUDFLAPS</b>	<b>Invoice</b>
BROUGHT TRAILER INTO WORKSHOP REMOVED OLD MUDFLAPS CUT 2 NEW MUDFLAPS TO SIZE AND DRILLED HOLES FIT MUDFLAPS PARKED TRAILER ON STREET				
<b>55367</b>	<b>16/11/2022</b>	<b>97250</b>	<b>REPLACE - LH OUTER TAILLIGHT INSERT</b>	<b>Invoice</b>
REPLACED LH OUTTER TAILLIGHT INSERT REPLACED 2 NUMBER PLATE LIGHTS REPLACED 1 LUCIDITY SIDE MARKER RED/AMBER				
<b>54418</b>	<b>28/06/2022</b>	<b>81193</b>	<b>A SERVICE</b>	<b>Invoice</b>
COLLECTED TRAILER FROM SHED 24 PARKED TRAILER IN WORKSHOP CARRIED OUT A SERVICE REPLACED AIR COUPLING AT FRONT OF TRAILER REPLACED KING PIN AND BOLTS				

**Vehicle Details**

<b>Registration</b>	195UBY	<b>Next Service</b>	<b>Litres</b>	
<b>Make</b>	KRUEGER	<b>Rego Due</b>	<b>Trans</b>	N/A
<b>Model</b>	ST338	<b>Engine #</b>	<b>Air</b>	Yes
<b>Model Series</b>		<b>VIN</b>	<b>Cyl</b>	0
<b>Model Code</b>		<b>Build Date</b>	<b>Body</b>	SEMITRAILER
<b>Colour</b>		<b>Odometer</b>	<b>Prod</b>	2015

Invoice No.	Date	Odometer	Description	Type
REPLACED RH #1 AXLE MUDGUARD RETURNED TRAILER TO SHED 24 SWAPPED LIGHT ONTO THIS TRAILER FROM 194UBY REPLACED 2 LIGHT HOUSINGS				
53691	11/02/2022	73310	C SERVICE AND REPAIRS	Invoice
11/2/2022 MOVED TRAILER INTO WORKSHOP 14/2/2022 CARRIED OUT C SERVICE BEARINGS REQUIRED REPACKING STARTED REMOVING HUBS FROM VEHICLE REPLACED CLEAR ROUND REFLECTOR AT FRONT LEFT 15/2/2022 REPLACED 2 SLEEVES IN LH 2ND & 3RD AXLE INSTALL NEW PADS LH 2ND AXLE ALL WHEEL NUTS TORQUED BRAKES ADJUSTED 15/2/2022 MOVED TRAILER ONTO STREET NOTE: NHVAS STICKER MISSING REAR BUMP STOPS DAMAGED REAR CHEVRONS DAMAGED REAR RHS SHOCK STRAP MISSING				
52744	25/08/2021	47056	BREAKDOWN	Invoice
ATTENDED BREAKDOWN AT TITANIUM STREET, CRESTMEAD REMOVED DAMAGED AIR BAG RIDE HEIGHT VALVE AND REPLACED WITH NEW TESTED OPERATION - ALL OK RETURNED TO WORKSHOP				
52678	17/08/2021	45700	CARRY OUT A SERVICE	Invoice
CARRIED OUT A SERVICE ON TRAILER REPLACED RHS FIRST AXLE BRAKE BOOSTER REPLACED 7 PIN TRAILER PLUG				
51659	11/03/2021	24865	A SERVICE	Invoice
<b>DATE WORK CARRIED OUT:</b> 11/03/2021  <b>WORK CARRIED OUT:</b> CARRIED OUT A SERVICE  <b>DEFECTS NOTED</b>  <ul style="list-style-type: none"><li>• REPLACE PASSENGER SIDE AIR TANK FITTING</li></ul>				
51195	08/01/2021	14806	A SERVICE	Invoice



**Vehicle Details**

<b>Registration</b>	195UBY	<b>Next Service</b>	<b>Litres</b>	
<b>Make</b>	KRUEGER	<b>Rego Due</b>	<b>Trans</b>	N/A
<b>Model</b>	ST338	<b>Engine #</b>	<b>Air</b>	Yes
<b>Model Series</b>		<b>VIN</b>	<b>Cyl</b>	0
<b>Model Code</b>		<b>Build Date</b>	<b>Body</b>	SEMITRAILER
<b>Colour</b>		<b>Odometer</b>	<b>Prod</b>	2015

Invoice No.	Date	Odometer	Description	Type
<b>DATE WORK CARRIED OUT:</b> 08/01/2021 <b>WORK CARRIED OUT:</b> CARRIED OUT A SERVICE				
50738	23/10/2020	0	A & C SERVICE & REPAIRS	Invoice
DATE WORK CARRIED OUT: 23/10/2020  WORK CARRIED OUT: CARRIED OUT A & C SERVICES AS PER HVW SERVICE SHEET REPLACED DOCK RUBBERS REPLACED RH 2ND AXLE BOOSTER FIT EXTENDED VALVE STEMS TOO ALL INNER WHEELS REMOVED DAMAGED MARKER PLATES, CLEANED OFF OFF TAPE AND RESIDUE. FIT NEW MARKER PLATES				
50280	20/08/2020	0	A SERVICE	Invoice
DATE WORK CARRIED OUT: 20/08/2020  WORK CARRIED OUT: CARRIED OUT A SERVICE AS PER HVW SERVICE SHEET TIGHTENED LH REAR MUD GUARD BRACKET REPLACED HUBO SECURED AIRLINES <b>FURTHER ACTION REQUIRED-</b>  LOW TREAD POSITION 1,2,3 & 4 NO TREAD POSITION 9 & 10				