



Vehicle History

Vehicle Details

Registration	332WIF	Next Service		Litres	10
Make	IVECO	Rego Due		Trans	N/A
Model	STRALIS AT	Engine #	CURSOR 10	Air	Yes
Model Series		VIN	WJMS2NTH40C323326	Cyl	6
Model Code		Build Date	2016	Body	PRIMEMOVER
Colour	White	Odometer	396979	Prod	

Invoice No.	Date	Odometer	Description	Type
61341	05/08/2025	396979	DEFECTS	Invoice
<p>CHECKED FOR BATTERY LIGHT ON DASH CHECKED BATTERIES FOR CHARGE RATE - 24V ONLY PARKED VEHICLE IN WORKSHOP RAISED CAB CHECKED ALTERNATOR AND BELT REMOVED ALTERNATOR BELT AND FOUND BEARING COLLAPSED IN ALTERNATOR REMOVED ALTERNATOR REPLACED ALTERNATOR REFITTED BELT AND BATTERY CABLE STARTED ENGINE CHECKED CHARGE RATE LOWERED CAB REMOVED RH DOOR PANEL CHECKED OVER WINDOW ELECTRICAL PLUGS TO CORRECT SWITCH TESTED WINDOW OPERATION CHECKED FOR RH SEAT BACK LUMBAR SUPPORT FAULT FOUND SWITCH TIGHT - LOOSEN SWITCH/BUTTON RETESTED VEHICLE - ALL OKAY *****PLEASE READ***** WARRANTY ON PARTS ARE SUBJECT TO MANUFACTURERS TERMS AND CONDITIONS. ***RECEIVE A \$25 DISCOUNT FOR ANY POSITIVE GOOGLE REVIEW ON OUR COMPANY GOOGLE WEBPAGE - HEAVY VEHICLE WORKSHOP*** <u>HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE THE STORE FOR PRICING ON - 07 3260 8950</u></p>				

Invoice No.	Date	Odometer	Description	Type
61329	01/08/2025	396536	LIGHT ON DASH	Invoice
<p>DIAGNOSED BATTERY LIGHT ON DASH CHECK CHARGE RATE OF ALTERNATOR - OKAY CHECK BATTERY CHARGE - LOW CARRIED OUT BATTERY TEST AND FAILED REPLACED WITH 2ND HAND BATTERIES FROM BUCCINI STOCK FIT BATTERIES AND BATTERY BRACKETS FIT LEADS AND TEST - OKAY COMPLETE PAPERWORK ***RECEIVE A \$25 DISCOUNT FOR ANY POSITIVE GOOGLE REVIEW ON OUR COMPANY GOOGLE WEBPAGE - HEAVY VEHICLE WORKSHOP*** <u>HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE THE STORE FOR PRICING ON - 07 3260 8950</u></p>				

Vehicle Details

Registration	332WIF	Next Service	Litres	10
Make	IVECO	Rego Due	Trans	N/A
Model	STRALIS AT	Engine #	Air	Yes
Model Series		VIN	Cyl	6
Model Code		Build Date	Body	PRIMEMOVER
Colour	White	Odometer	Prod	

Invoice No.	Date	Odometer	Description	Type
61214	14/07/2025	395103	REPLACED LENS, TURNTABLE REPAIRS -	Invoice

ADJUSTED TURNTABLE
TURNTABLE OUT OF ADJUSTMENT
JAW SET IS DAMAGED - NEEDS REKIT
POSSIBLY NEEDS NEW ADJUSTER BOLT
MAY NEED NEW TURNTABLE
REPLACED RHS TAILLIGHT LENS
REPLACED TURNTABLE JAW KIT
STRAIGHTENED ADJUSTING ROD
ADJUSTED TURNTABLE
TESTED OPERATION OF TURNTABLE
GREASED TURNTABLE
REPAIRED LH REAR PARK LIGHT FAULT
TIGHTENED TAIL LIGHT ASSEMBLY
RETURNED VEHICLE TO BT YARD

**HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD -
STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS
WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.
PHONE THE STORE FOR PRICING ON - 07 3260 8950**

***RECEIVE A \$25 DISCOUNT FOR ANY POSITIVE GOOGLE REVIEW ON OUR COMPANY GOOGLE WEBPAGE -
HEAVY VEHICLE WORKSHOP***

60923	12/05/2025	392848	REPLACE AIR DRYER	Invoice
-------	------------	--------	-------------------	---------

REMOVED BATTERIES AND AIR TANK
REPLACED AIR DRYER ASSEMBLY
REPLACED 8MM AIR FITTING
REFITTED BATTERIES AND AIR TANK
STARTED ENGINE AND CHECKED FOR LEAKS
GREASED TURNTABLE

**HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD -
STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS
WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.
PHONE THE STORE FOR PRICING ON - 07 3260 8950**

***RECEIVE A \$25 DISCOUNT FOR ANY POSITIVE GOOGLE REVIEW ON OUR COMPANY GOOGLE WEBPAGE -
HEAVY VEHICLE WORKSHOP***

60812	10/04/2025	389294	DEFECTS	Invoice
-------	------------	--------	---------	---------

REPLACED TAIL LIGHT LENS X2
GREASED TURNTABLE
LIFTED CAB + TOPPED UP ENGINE OIL
LOWERED CAB
TOPPED UP COOLANT
REMOVED RH TAILLIGHT BRACKET, STRAIGHTENED RH #2 DIFF MUDGUARD
REFITTED TAILLIGHT BRACKET

Vehicle Details

Registration	332WIF	Next Service	Litres	10
Make	IVECO	Rego Due	Trans	N/A
Model	STRALIS AT	Engine #	Air	Yes
Model Series		VIN	Cyl	6
Model Code		Build Date	Body	PRIMEMOVER
Colour	White	Odometer	Prod	

Invoice No.	Date	Odometer	Description	Type
REPAIR BUMPER AND MODIFY BUMPER BRACKET REFIT PASSENGER SIDE STEP				
60650	04/03/2025	384971	TRUCK STUCK IN GEAR	Invoice
TRUCK STUCK IN GEAR DROVE TOP BT YARD DISCONNECTED FROM TRAILER CHECKED FOR TRUCK NOT STARTING FILLED AIRTANKS JACKED UP #1 DIFF + ROTATED WHEELS TO NEUTRALIZE TRANSMISSION BYPASSED STARTER SOLENOID AND STARTED VEHICLE TURNED OFF VEHICLE AND STARTED WITH A KEY RETURNED TO WORKSHOP <u>HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE THE STORE FOR PRICING ON - 07 3260 8950</u>				
60525	12/02/2025	382486	GREASE TURNTABLE	Invoice
GREASED TURNTABLE <u>HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE COREY FOR PRICING ON - 07 3260 8950</u>				
60452	24/01/2025	381450	DEFECTS	Invoice
REMOVE DRIVERS SIDE SEAT BELT REPLACE DRIVERS SIDE SEAT BELT TEST OPERATION - OKAY SEAT BELT RETRACTS AND LOCKS TO BUCKLE CLEAN AREA PACK AWAY TOOLS COMPLETE PAPERWORK <u>HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE COREY FOR PRICING ON - 07 3260 8950</u>				
60342	30/12/2024	379404	DEFECTS	Invoice
FITTED THERMOSTAT ASSEMBLY AND HOUSING FITTED COOLANT HOSES AND CLAMPS FILLED WITH ORIGINAL COOLANT JUMP STARTED VEHICLE CHECKED COOLANT LEVEL TEST DROVE VEHICLE LIFTED CAB AND CHECKED FOR LEAKS LOWERED CAB PLACED BATTERIES ON CHARGE				

Registration	332WIF	Next Service		Litres	10
Make	IVECO	Rego Due		Trans	N/A
Model	STRALIS AT	Engine #	CURSOR 10	Air	Yes
Model Series		VIN	WJMS2NTH40C323326	Cyl	6
Model Code		Build Date	2016	Body	PRIMEMOVER
Colour	White	Odometer	396979	Prod	

Invoice No.	Date	Odometer	Description	Type
			REPLACED THERMOSTAT SEAL AND CLEANED HOUSING	
			DRAINED COOLANT	
			REMOVED THERMOSTAT HOUSING, FAN BLADE, FAN BELT AND WATER PUMP	
			CLEANED SURFACES	
			FIT NEW WATER PUMP AND O RING	
			FIT FAN BELT	
<p><u>HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD -</u> <u>STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS</u> <u>WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.</u> <u>PHONE COREY FOR PRICING ON - 07 3260 8950</u></p>				

60271	16/12/2024	379404	DEFECTS	Invoice
<p>CARRY OUT A SERVICE -</p> <p>FOUND 1ST DRIVE AIRBAGS SPLIT REQUIRES REPLACEMENT OF 1ST AXLE DRIVE AIR BAGS</p> <p>FOUND 1ST DRIVE SWAY BAR BUSINGS WORN</p> <p>FOUND TURBO OIL FEED LINE LEAKING REQUIRES REPLACEMENT</p> <p>FOUND OIL LEAK FROM REAR OF ENGINE REQUIRES REPLACEMENT OF REAR PCV COVER</p> <p>FOUND A/C BELT SNAPPED BELT REQUIRES REPLACEMENT, TRAVELLED TO SITE AND LOCATED VEHICLE.</p> <p>CHECKED PRESSURE AND SYSTEM. NOT COLD. TILTED CAB AND FOUND NO BELT ON COMPRESSOR.</p> <p>INFORMED SITE AND SITE STATED THEY WILL ORGANISE NEW BELT AND INSTALL, RETEST TO BE COMPLETED ONCE BELT IS INSTALLED. NO VISIBLE SIGNS WHY OLD BELT SNAPPED. TESTING AND INSPECTION OF BELT TO BE COMPLETED WHEN NEW BELT IS INSTALLED. PACKED TOOLING AND LEFT SITE.</p> <p>CARRY OUT REPLACEMENT OF DAMAGED BRAKE PEDAL RUBBER</p> <p>CARRY OUT REPLACEMENT OF FAILED DOG BOX SWITCH</p> <p>CARRY OUT REPLACEMENT OF NOX SENSOR DUE TO FAILURE</p> <p>CARRY OUT TEST DRIVE AND REPORT</p>				
<p>PARK VEHICLE IN WORKSHOP</p> <p>CARRY OUT A SERVICE AS PER SERVICE SHEET</p> <p>CARRY OUT WALK AROUND VISUAL INSPECTION</p> <p>SECURE HOIST ON TRUCK</p> <p>CHECK ALL LIGHTS INCLUDING ALL REVERSE LAMPS AND BEEPERS</p> <p>CHECK WIPER AND WASHER OPERATION</p> <p>CHECK BATTERY LEVELS, TERMINALS AND CLAMPS</p> <p>LIFT CAB/BONNET TO ACCESS ENGINE BAY</p> <p>CHECK ALL BELTS AND MOUNTS</p> <p>LIFT TRUCK ON HOIST</p> <p>CARRY OUT VISUAL INSPECTION OF UNDER CARRIAGE (DRIVE LINE AND SUSPENSION COMPONENTS)</p> <p>ADJUST BRAKES AND CHECK BRAKE THICKNESSES</p> <p>CHECK AND ADJUST CLUTCH IF APPLICABLE</p> <p>CHECK GEAR BOX OIL LEVEL AND QUALITY</p> <p>CHECK DIFF OIL LEVEL AND QUALITY</p> <p>CARRY OUT GREASING OF TRUCK</p> <p>LOWER TRUCK</p> <p>CHECK ENGINE OIL</p> <p>TOP UP COOLANT IF REQUIRED</p> <p>LOWER CAB/BONNET AND SECURE IN PLACE</p> <p>FIT SERVICE STICKER</p> <p>COMPLETE PAPERWORK</p>				

Vehicle Details

Registration	332WIF	Next Service	Litres	10
Make	IVECO	Rego Due	Trans	N/A
Model	STRALIS AT	Engine #	Air	Yes
Model Series		VIN	Cyl	6
Model Code		Build Date	Body	PRIMEMOVER
Colour	White	Odometer	Prod	

Invoice No.	Date	Odometer	Description	Type
<p><u>HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE COREY FOR PRICING ON - 07 3260 8950</u></p>				
60299	13/12/2024	379119	REPAIR GUARD	Invoice
<p>REPAIR LIGHT BROKEN OFF GUARD REPAIR LOOSE GUARD <u>HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE CHRIS FOR PRICING ON - 07 3260 8950</u></p>				
60161	19/11/2024	3729083		Invoice
<p>(04/11/2024) - Fault Description: Travel to site & locate vehicle. Check and repair - Inspect all lights are operational and working correctly (04/11/2024) - Work Note Check system pressure. Found to be low however compressor engaging. Recover gas from system, 200g present. Pressure test, found high side hose leaking near compressor. Several pinholes in rubber section. Submit order for new hose and desiccant bag. (12/11/2024) - Work Note Travel to site. Remove and replace high side line and desiccant cartridge. Replace damaged P-clamp and resecure low side line near condenser. Pressure test system okay. Evacuate, add oil and charge system. Performance and leak test okay. Return to workshop</p>				
60075	04/11/2024	3729083	A/C REPAIRS	Invoice
<p>SCANNED TRUCK - FOUND NOX CODES TEST DROVE NOX SENSOR VALVES OUT OF RANGE REPLACED NOX SENSOR WITH ONE FROM 331WIF, AND PUT NEW SENSOR IN 332WIF TEST DROVE - ALL GOOD <u>HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE CHRIS FOR PRICING ON - 07 3260 8950</u></p>				
60052	29/10/2024	3729083	DEFECTS	Invoice
CARRIED OUT COOLANT FLUSH				

Vehicle Details

Registration	332WIF	Next Service	Litres	10
Make	IVECO	Rego Due	Trans	N/A
Model	STRALIS AT	Engine #	Air	Yes
Model Series		VIN	Cyl	6
Model Code		Build Date	Body	PRIMEMOVER
Colour	White	Odometer	Prod	

Invoice No.	Date	Odometer	Description	Type
			AIR DRYER ASSEMBLY KEEPS AIR LEAKING	
			<u>HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE JEFF FOR PRICING ON - 07 3260 8950</u>	
60001	22/10/2024	3729083	ENGINE LIGHT ON DASH	Invoice
			ENGINE LIGHT WARNING ON DASH SCAN WITH LAPTOP DELETE ENGINE LIGHT WARNING CODE COMPLETE PAPERWORK <u>HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE JEFF FOR PRICING ON - 07 3260 8950</u>	
59882	26/09/2024	372634	REPAIRS	Invoice
			CARRY OUT REPLACEMENT OF LH STEP ASSY REPLACE DRIVERS SEAT CUSION REPLACE DRIVERS DUMP SWITCH DISCONNECTED VEHICLE FROM TRAILER COLLECTED VEHICLE FROM BT YARD REPLACED LH STEP AND FITTED TREADS TO STEPS REPLACED RH SEAT CUSHION - SUPPLIED BY CUSTOMER CHECKED FOR SEAT AIRLEAK REMOVED SEAT SWITCH REPLACED SEAT VALVE TESTED POWER TO START SOLENOID CHECKED FOR SEAT NOT RAISING FAULT <u>HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE JEFF FOR PRICING ON - 07 3260 8950</u>	
59790	18/09/2024	370306	ENGINE LIGHT FAULT	Invoice
			CHECKED FOR ENGINE LIGHT ON DASH FAULT ISOLATED VEHICLE AND RE-CHECKED SCANNED COMPUTER FOR FAULTS FOUND ADBLUE FAULT (HEATER COMPONENT) FITTED REAR SECTION OF MUDGUARD FITTED MARKER PLATE CHECKED FOR ADBLUE FAULT CONNECTED COMPUTER TO VEHICLE JALTEST REQUIRED UPDATE, DISCONNECTED FROM VEHICLE, PLACED COMPUTER ON CHARGE WHILE UPDATING	

Vehicle Details

Registration	332WIF	Next Service	Litres	10
Make	IVECO	Rego Due	Trans	N/A
Model	STRALIS AT	Engine #	Air	Yes
Model Series		VIN	Cyl	6
Model Code		Build Date	Body	PRIMEMOVER
Colour	White	Odometer	Prod	

Invoice No.	Date	Odometer	Description	Type
			REMOVED RH #2 DIFF REAR BROKEN GUARD REMOVED TAILLIGHT ASSEMBLY, STRAIGHTENED MUDGUARD POLE CONNECTED EASY LAPTOP TO VEHICLE CHECKED FOR COMPUTER FAULTS ADBLUE LONG TERM FAULT ERASED INTERMITTENT FAULTS NO ENGINE LIGHT ON DASH NOTE Located vehicle after arrived to workshop. Plugged in scan tool and scanned. No codes present nor any dash lights. Drove for 30 minutes, no faults or lights illuminated. Returned to site and re scanned. No codes across all systems nor engine lights illuminating. Packed tooling and invoiced. Left site. <u>HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE JEFF FOR PRICING ON - 07 3260 8950</u>	
59727	21/08/2024	372634	SUZI ISSUES	Invoice
			REMOVE AND REPLACED SUZI COIL CLEAN AREA PACK AWAY TOOLS COMPLETE PAPERWORK <u>HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE JEFF FOR PRICING ON - 07 3260 8950</u>	
59633	30/07/2024	368395	FUEL FILTER HOUSING LEAKING	Invoice
			LIFT CAB REMOVE AND REPLACE FUEL FILTER ASSEMBLY START VEHICLE AND MAKE SURE NOT LEAKING - ALL OKAY LOWER CAB AND CLOSE BONNETT CLEAN AREA PACK AWAY TOOLS COMPLETE PAPERWORK <u>HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE JEFF FOR PRICING ON - 07 3260 8950</u>	
59545	15/07/2024	367481	A SERVICE AND FIT NEW TURNTABLE	Invoice
			PARK VEHICLE IN WORKSHOP CARRY OUT A SERVICE AS PER SERVICE SHEET CARRY OUT WALK AROUND VISUAL INSPECTION	

Vehicle Details

Registration	332WIF	Next Service	Litres	10
Make	IVECO	Rego Due	Trans	N/A
Model	STRALIS AT	Engine #	Air	Yes
Model Series		VIN	Cyl	6
Model Code		Build Date	Body	PRIMEMOVER
Colour	White	Odometer	Prod	

Invoice No.	Date	Odometer	Description	Type
			<p> SECURE HOIST ON TRUCK CHECK ALL LIGHTS INCLUDING ALL REVERSE LAMPS AND BEEPERS CHECK WIPER AND WASHER OPERATION CHECK BATTERY LEVELS, TERMINALS AND CLAMPS LIFT CAB/BONNET TO ACCESS ENGINE BAY CHECK ALL BELTS AND MOUNTS LIFT TRUCK ON HOIST CARRY OUT VISUAL INSPECTION OF UNDER CARRIAGE (DRIVE LINE AND SUSPENSION COMPONENTS) ADJUST BRAKES AND CHECK BRAKE THICKNESSES CHECK AND ADJUST CLUTCH IF APPLICABLE CHECK GEAR BOX OIL LEVEL AND QUALITY CHECK DIFF OIL LEVEL AND QUALITY CARRY OUT GREASING OF TRUCK LOWER TRUCK CHECK ENGINE OIL TOP UP COOLANT IF REQUIRED LOWER CAB/BONNET AND SECURE IN PLACE FIT SERVICE STICKER COMPLETE PAPERWORK NOTE REPAIR TRAILER PLUG ON TRUCK SIDE REPLACE CRANK CASE BREATHER FILTER BRAKE CLEAN AROUND HOUSING - MONITOR FOR LEAKS CUT AND DRILL HOLES FOR NEW MUDFLAP RHS - MEASURE AND FIT TO TRUCK REMOVE TURNTABLE BOLTS REMOVE TURNTABLE ACCESS FITTING OF SLIDE MECHANISM REFITTED ORIGINAL TURNTABLE + RIPPLE PLATE TENSIONED BOLTS GREASED TOP OF TURNTABLE MOVED OLD ENGINE OUT OF THE WAY TO GET VEHICLE OUT OF WORKSHOP PLACED ENGINE WITH SPARE PARTS RETURNED VEHICLE TO BUCCINI YARD </p> <p> <u>HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE JEFF FOR PRICING ON - 07 3260 8950</u> </p>	

59501	05/07/2024	366463	ADBLUE FAULT ON DASH	Invoice
			<p> CARRIED OUT IVECO EASY SCAN RESET "INCORRECT" ADBLUE HEATER CODE (WAS BRINGING ENGINE LIGHT ON) REPLACED REAR NUMBER PLATE LAMP GLOBES <u>HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE JEFF FOR PRICING ON - 07 3260 8950</u> </p>	
59438	24/06/2024	366463	LABOUR - BUCCINI	Invoice

Vehicle Details

Registration	332WIF	Next Service	Litres	10
Make	IVECO	Rego Due	Trans	N/A
Model	STRALIS AT	Engine #	Air	Yes
Model Series		VIN	Cyl	6
Model Code		Build Date	Body	PRIMEMOVER
Colour	White	Odometer	Prod	

Invoice No.	Date	Odometer	Description	Type
			<p>REMOVED VALVE FROM 301VLR TO REPAIR 332WIF REMOVED LEAKING VALVE FROM 332WIF REPLACED WITH 301VLR VALVE TESTED OPERATION - ALL OKAY RETURNED VEHICLE TO BUCCINI YARD NEW PART WILL BE CHARGED AND FITTED TO 301VLR <u>HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE JEFF FOR PRICING ON - 07 3260 8950</u></p>	

59184	08/05/2024	360709	C SERVICE	Invoice
			<p>PARK VEHICLE IN WORKSHOP CARRY OUT C SERVICE AS PER SERVICE SHEET CARRY OUT WALK AROUND VISUAL INSPECTION SECURE HOIST ON TRUCK CHECK ALL LIGHTS INCLUDING ALL REVERSE LAMPS AND BEEPERS CHECK WIPER AND WASHER OPERATION CHECK BATTERY LEVELS, TERMINALS AND CLAMPS LIFT CAB/BONNET TO ACCESS ENGINE BAY REPLACE CABIN AND ENGINE AIR FILTERS CHECK ALL BELTS AND MOUNTS LIFT TRUCK ON HOIST CARRY OUT VISUAL INSPECTION OF UNDERCARRIAGE (DRIVE LINE AND SUSPENSION COMPONENTS) DRAIN ENGINE OIL AND CHANGE FILTER ADJUST BRAKES AND CHECK BRAKE THICKNESSES CHECK AND ADJUST CLUTCH IF APPLICABLE CHECK GEARBOX OIL LEVEL AND QUALITY REPLACE IF REQUIRED CHECK DIFF OIL LEVEL AND QUALITY REPLACE IF REQUIRED CARRY OUT GREASING OF TRUCK LOWER TRUCK FIL ENGINE OIL AND CHECK ENGINE OIL TOP-UP COOLANT IF REQUIRED LOWER CAB/BONNET AND SECURE IN PLACE FIT SERVICE STICKER COMPLETE PAPERWORK REMOVE HOIST PICKED UP PARTS FROM MULTISPARES EAGLE FARM PICKED UP TRUCK FROM BUCCINI YARD USED FILTERS IN OUR STOCK - ORDERED IN WHAT WE DIDNT HAVE RETURNED TRUCK TO BT YARD.</p> <p><u>HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE JEFF FOR PRICING ON - 07 3260 8950</u></p>	

59132	24/04/2024	358625	REPLACE BROKEN LENS AND GREASE	Invoice
-------	------------	--------	--------------------------------	---------

Vehicle Details

Registration	332WIF	Next Service	Litres	10
Make	IVECO	Rego Due	Trans	N/A
Model	STRALIS AT	Engine #	Air	Yes
Model Series		VIN	Cyl	6
Model Code		Build Date	Body	PRIMEMOVER
Colour	White	Odometer	Prod	

Invoice No.	Date	Odometer	Description	Type
REPLACE RHS TAIL LIGHT GREASE TURNABLE <u>HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE JEFF FOR PRICING ON - 07 3260 8950</u>				
59071	12/04/2024	358625	BREAK DOWN AT AMPOL HEMMANT	Invoice
ATTEND BRAKE DOWN @ AMPOL HEMMANT FOUND SUZI LEADS SNAPPED REPLACED SUZI AIR LINES TESTED - ALL OK <u>HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE JEFF FOR PRICING ON - 07 3260 8950</u>				
58740	20/02/2024	353033	REPLACE PRESSURE SENSOR SWITCH	Invoice
COLLECT TRUCK FROM ENV REMOVE FLOOR MOUNTING REMOVE DASH UNDER STEERING COLUMN, REPLACE PRESSURE SENSOR SWITCH RE-FIT DASH AND FIT NEW SCREWS AS A FEW WERE MISSING REPLACE TAILLIGHT GLOBE ON LR MADE TESTS/SCANS TO TRUCK TO ASSESS VARIOUS INTERMITTENT ERRORS COMING UP ON DASH - WIRING ALL TESTS OK FOUND/TOPPED UP LOW COOLANT LEVEL / TEST - OK FOUND TRUCK PARK/BRAKE WARNING LAMP AND BUZZER COMES ON UNTIL TRUCK IS IN GEAR EVEN WITH DOOR SHUT? (THIS IS THE SAME AS 331WIF IVECO TRUCK SO PERHAPS THIS IS NORMAL?? NEED TO CHECK WITH IVECO OEM PEOPLE) RE-CHECKED TRUCK CUTTING OUT ERROR - DID NOT FAIL IN WORKSHOP / OR TEST DRIVE/ NO CODES PRESENT OR HISTORY - MONITOR??? TEST DROVE TO PORT AND BACK - ALL GOOD RETURNED TRUCK TO BUCCINI YARD <u>HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.</u>				
58688	13/02/2024	352661	A SERVICE	Invoice
PARK VEHICLE IN WORKSHOP CARRY OUT A SERVICE AS PER SERVICE SHEET CARRY OUT WALK AROUND VISUAL INSPECTION SECURE HOIST ON TRUCK CHECK ALL LIGHTS INCLUDING ALL REVERSE LAMPS AND BEEPERS CHECK WIPER AND WASHER OPERATION CHECK BATTERY LEVELS, TERMINALS AND CLAMPS				

Vehicle Details

Registration	332WIF	Next Service	Litres	10
Make	IVECO	Rego Due	Trans	N/A
Model	STRALIS AT	Engine #	Air	Yes
Model Series		VIN	Cyl	6
Model Code		Build Date	Body	PRIMEMOVER
Colour	White	Odometer	Prod	

Invoice No.	Date	Odometer	Description	Type
LIFT CAB/BONNET TO ACCESS ENGINE BAY CHECK ALL BELTS AND MOUNTS LIFT TRUCK ON HOIST CARRY OUT VISUAL INSPECTION OF UNDER CARRIAGE (DRIVE LINE AND SUSPENSION COMPONENTS) ADJUST BRAKES AND CHECK BRAKE THICKNESSES CHECK AND ADJUST CLUTCH IF APPLICABLE CHECK GEAR BOX OIL LEVEL AND QUALITY CHECK DIFF OIL LEVEL AND QUALITY CARRY OUT GREASING OF TRUCK LOWER TRUCK CHECK ENGINE OIL TOP UP COOLANT IF REQUIRED LOWER CAB/BONNET AND SECURE IN PLACE FIT SERVICE STICKER *****TIE ROD ENDS HAVE A LITTLE MOVEMENT - MONITOR SMALL HOLE IN EXHAUST NEAR ADBLUE INJECTOR TAILSHAFT SLIP JOINT HAS A LITTLE MOVEMENT - MONITOR FOUND WATER IN AIR TANKS, RECOMMEND REPLACING AIR DRYER FILTER NEXT SERVICE. OIL LEAKING FROM PCV FILTER HOUSING ON REAR OF ENGINE <u>HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.</u>				
58518	29/01/2024	350047	ABS CODE ON DASH	Invoice
LOWER JACK FROM #2 DIFF MOVED VEHICLE OVER IN WORKSHOP FOUND 2 BLOWN TYRES - INNER LEFT AND INNER RIGHT NEEDS 4 DRIVE TYRES ABS SENSOR ON RH REAR AXLE NEEDS REPLACING, ORDERED A NEW ONE AND INSTALLED CARRIED OUT EXTENSIVE SCANTOOL ASSESSMENTS TO CHECK FOR POSSIBLE FAULTS / ERRORS ON DASH AFTER U/S RELAYS HAD BEEN CHANGED, CONCEALED RELAYS BEHIND DASH ETC RESET BRAKES CALIBRATIONS ADBLUE AND EBS SENSOR READINGS / TEST - ALL OK STRIP AND FIT 4 X REAR NEW DRIVE TYRES FIT NEW WHEEL SPEED SENSOR <u>HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.</u>				
58480	12/01/2024	348130	REPLACE BROKEN FUEL SENDER	Invoice
INSPECTED THE FUEL SENDER UNIT LOCATED ON THE RHS FUEL TANK. FOUND THAT THE PLUG FOR THE WIRING HAS BROKEN OFF ON THE SENDER UNIT SIDE. ORDERED IN A NEW SENDER UNIT. REMOVED THE FUEL LINES FROM THE OLD SENDER UNIT AND REMOVED THE SENDER FROM THE FUEL TANK. FITTED THE NEW SENDER UNIT AND FITTED THE FUEL LINES ON TO IT. STARTED THE TRUCK AND CHECKED ALL OK. RETURNED THE TRUCK TO THE BT YARD.				

Vehicle Details

Registration	332WIF	Next Service	Litres	10
Make	IVECO	Rego Due	Trans	N/A
Model	STRALIS AT	Engine #	Air	Yes
Model Series		VIN	Cyl	6
Model Code		Build Date	Body	PRIMEMOVER
Colour	White	Odometer	Prod	

Invoice No.	Date	Odometer	Description	Type
<u>HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.</u>				
58309	22/12/2023	347247	AIR BAG SENSOR + KEY BARREL	Invoice
PICKED UP TRUCK FROM BUCCINI YARD KEY WAS STUCK AND WOULDN'T TURN OFF PARKED TRUCK ON FENCE LINE JACKED UP CAB AND TURNED OFF FROM BUTTON NEXT TO ENGINE DISCONNECTED BATTERY SO IT WOULDN'T GO FLAT REMOVED KEY BARREL AND FIT NEW KEY BARREL REPLACED AIR PRESSURE SENSOR FOR AIR SUSPENSION ON BACK OF TRUCK RECONNECTED BATTERIES AND TESTED - ALL OK RETURNED TRUCK TO BUCCINI YARD <u>HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.</u>				
58301	07/12/2023	345150	FLAT TYRE	Invoice
RR INNER TYRE FLAT - PUMP UP TO 95 PSI <u>HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.</u>				
58273	05/12/2023	345328	DIFF LOCK LIGHT ON AND REPLACE	Invoice
INSPECTED MOST RELAYS AND FUSES FOR PROBLEMS WITH DIFF LOCK FOUND WATER IN ECU (REG) PLUG. MADE MORE EXTENSIVE TESTS, CHECKS TO LOCATE/REPAIR INTERMITTENT ERRORS ON DASH INCLUDING DIFFLOCK LIGHT STAYING ON FOUND TO BE WATER INTRUSION INSIDE REAR FRAME COMPUTER PLUGS ALSO FOUND 8 X VARIOUS RELAYS INCLUDING ALL A/C RELAYS ARE ALMOST WORN OUT ORDERED NEW PARTS AND FITTED RETURNED TRUCK TO BUCCINI <u>HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.</u>				
58256	04/12/2023	345150	AIR LINE PROBLEM	Invoice
CHECKED OVER RED SUZI COIL FOUND SUZI COIL KINKED REPLACED LONGTAIL SUZI COILS - ALL GOOD <u>HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE</u>				

Vehicle Details

Registration	332WIF	Next Service	Litres	10
Make	IVECO	Rego Due	Trans	N/A
Model	STRALIS AT	Engine #	Air	Yes
Model Series		VIN	Cyl	6
Model Code		Build Date	Body	PRIMEMOVER
Colour	White	Odometer	Prod	

Invoice No.	Date	Odometer	Description	Type
-------------	------	----------	-------------	------

TODAY FOR SIZING AND PRICING.

58215	28/11/2023	344390	CHECKED/REPLACED HEADLAMP GLOBE	Invoice
-------	------------	--------	---------------------------------	---------

CHECKED/REPLACED U/S HEADLAMP GLOBE RH/L LOW BEAM / TEST OK

HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.

58100	15/11/2023	342904	LHS INDICATOR GLOBE AND TRAILER	Invoice
-------	------------	--------	---------------------------------	---------

REPLACE 7 PIN TRAILER PLUG
REPLACE GLOBE ON LEFT TAILLIGHT

HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.

57993	20/10/2023	341779	OIL LEAK FROM BEHIND AIR	Invoice
-------	------------	--------	--------------------------	---------

MOVED TRUCK INTO WORKSHOP
TRIED JACKING OVER CAB BUT CAB JACK WASN'T WORKING
TRIED FILLING CAB RESERVOIR WITH OIL BUT STILL WASN'T WORKING
CHECKED RAM AND FOUND RAM HAD FAILED AND WAS DUMPING OIL
PUT 1ST AXLE ON STANDS
REMOVED LHS WHEEL ON 1ST AXLE
REMOVED WHEEL WELL GUARD TO ACCESS RAM
REMOVED RAM
FIT NEW CAB RAM
RE-FIT WHEEL WELL GUARD AND WHEEL
GOT TRUCK OFF STANDS
TORQUED WHEEL NUTS
FILLED CAB TILT SYSTEM WITH ATF FLUID AND GOT CAB OVER
CLEANED UP WHERE ATF FLUID HAD LEAKED FROM OLD RAMDRAINED COOLANT AND POWER STEERING FLUID
REMOVED COOLANT, POWER STEERING AND FUEL HOSES
REMOVED POWER STEERING AND FUEL PUMP
REMOVED AIR COMPRESSOR COVER PLATE AND AIR COMPRESSOR ASSEMBLY
FITTED DRIVE GEAR TO NEW AIR COMPRESSOR
FITTED NEW AIR COMPRESSOR TO VEHICLE
FITTED POWER STEERING PUMP AND FUEL PUMP TO AIR COMPRESSOR
FITTED SOME FUEL LINES AND POWER STEERING HOSES
FITTED AIR COMPRESSOR OUTER COVER PLATE
REPLACED RADIATOR DRAIN BUNG
FITTED AIRCOMPRESSOR INLET AND OUTLET HOSES
FITTED ALL COOLANT HOSES, POWER A STEERING RESERVOIR AND HOSES
FITTED RH SIDE STEP
FILLED POWER STEERING WITH OIL
FILLED RADIATOR WITH IT'S ORIGINAL COOLANT
**WAITING ON FUEL LINE

Vehicle Details

Registration	332WIF	Next Service		Litres	10
Make	IVECO	Rego Due		Trans	N/A
Model	STRALIS AT	Engine #	CURSOR 10	Air	Yes
Model Series		VIN	WJMS2NTH40C323326	Cyl	6
Model Code		Build Date	2016	Body	PRIMEMOVER
Colour	White	Odometer	396979	Prod	

Invoice No.	Date	Odometer	Description	Type
<p>**PRIME FUEL SYSTEM BEFORE STARTING CHECK POWER STEER OIL AND COOLANT LEVEL ONCE STARTED CARRIED OUT INSTALLOF FUEL SUPPLY LINE BLEED FUEL SYSTEM START AND TESTED TRUCK TESTED ALL OK PARKED AT SHED 24</p> <p>GAVE KEYS TO OFFICE AT BUCCINI <u>HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.</u></p>				
57905	19/10/2023	341644	B SERVICE	Invoice
<p>PARK VEHICLE IN WORKSHOP CARRY OUT B SERVICE AS PER SERVICE SHEET CARRY OUT WALK AROUND VISUAL INSPECTION SECURE HOIST ON TRUCK CHECK ALL LIGHTS INCLUDING ALL REVERSE LAMPS AND BEEPERS CHECK WIPER AND WASHER OPERATION CHECK BATTERY LEVELS, TERMINALS AND CLAMPS LIFT CAB/BONNET TO ACCESS ENGINE BAY REPLACE CABIN AND ENGINE AIR FILTERS CHECK ALL BELTS AND MOUNTS LIFT TRUCK ON HOIST CARRY OUT VISUAL INSPECTION OF UNDERCARRIAGE (DRIVE LINE AND SUSPENSION COMPONENTS) DRAIN ENGINE OIL AND CHANGE FILTER ADJUST BRAKES AND CHECK BRAKE THICKNESSES CHECK AND ADJUST CLUTCH IF APPLICABLE CHECK GEARBOX OIL LEVEL AND QUALITY REPLACE IF REQUIRED CHECK DIFF OIL LEVEL AND QUALITY REPLACE IF REQUIRED CARRY OUT GREASING OF TRUCK LOWER TRUCK FIL ENGINE OIL AND CHECK ENGINE OIL TOP-UP COOLANT IF REQUIRED LOWER CAB/BONNET AND SECURE IN PLACE FIT SERVICE STICKER COMPLETE PAPERWORK REMOVE HOIST *****</p> <p>REPLACED REAR TAILLIGHT ASSEMBLY FILLED WASHER BOTTLE NOTE- DRIVE AXLE SWAY BAR BUSHES CRACKED CAB RAM LEAKING COMPRESSOR LEAKING - A LOT REPLACED TURNTABLE HANDLE ADJUSTED TURNTABLE FILTERS ON JOB 56955 EOFY <u>HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.</u></p>				

Vehicle Details

Registration	332WIF	Next Service	Litres	10
Make	IVECO	Rego Due	Trans	N/A
Model	STRALIS AT	Engine #	Air	Yes
Model Series		VIN	Cyl	6
Model Code		Build Date	Body	PRIMEMOVER
Colour	White	Odometer	Prod	

Invoice No.	Date	Odometer	Description	Type
57868	17/10/2023	341387	LIGHTS ON TRAILER FLICKERING	Invoice
<p>FOUND LIGHTS ON TRAILER FLICKERING WHEN CONNECTED TO TRUCK TRIED SPREADING PIN, DIDN'T FIX FAULT PULLED APART TRAILER PLUG AND FOUND SCREW TO HOLD IN BROWN WIRE MISSING FOUND A SECOND HAND SCREW AND FIT TO TRAILER PLUG AND REASSEMBLE PLUG AND TESTED - ALL GOOD</p> <p><u>HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.</u></p>				
57806	10/10/2023	340521	REPLACED BATTERIES	Invoice
<p>REPLACED BATTERIES ON TRUCK</p> <p><u>HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.</u></p>				
57749	04/10/2023	339207	JUMP START AT SHED 24	Invoice
<p>LOCK UP WORKSHOP TRAVEL TO SHED 24 JUMP START THE TRUCK TRAVEL BACK TO THE WORKSHOP</p> <p><u>HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.</u></p>				
57710	27/09/2023	338783	BRAKES STICKING	Invoice
<p>DIAGNOSE BRAKES STICKING ON TRUCK/TRAILER - REPLACED ABS PLUG DRIVER SAID ONLY HAPPENS WHEN APPLYING FOOT BRAKE ADJUSTED TRAILER BRAKES - FELT BETTER DISCONNECTED TRUCK FROM TRAILER AND TESTED TRUCK ONLY - FELT BETTER PARKED ON STREET</p> <p><u>HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.</u></p>				
57635	13/09/2023	336136	TRAVEL TO BUCCINI TO INSPECT FOR AN	Invoice

Vehicle Details

Registration	332WIF	Next Service	Litres	10
Make	IVECO	Rego Due	Trans	N/A
Model	STRALIS AT	Engine #	Air	Yes
Model Series		VIN	Cyl	6
Model Code		Build Date	Body	PRIMEMOVER
Colour	White	Odometer	Prod	

Invoice No.	Date	Odometer	Description	Type
TRAVEL TO BUCCINI YARD INSPECT AIR LEAK FOUND AIR DRYER FILTER LEAKING REMOVE FILTER TRAVEL BACK TO WORKSHOP COLLECT NEW AIR DRYER FILTER TEST RETURN TO WORKSHOP <u>HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.</u>				
57545	31/08/2023	334000	REPLACE HEADER TANK	Invoice
CHECKED FOR COOLANT SLOW LEAK, DIAGNOSED THAT THE HEADER TANK WAS LEAKING. TRAVEL TO SUPPLIER AND COLLECT HEADER TANK RETURN TO WORKSHOP REPLACE HEADER TANK FILL COOLANT AND BLEED COOLING SYSTEM TEST OPERATION TESTED ALL OK CLEAN UP & COMPLETED PAPERWORK <u>HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.</u>				
57538	31/08/2023	333927	REPAIRS	Invoice
SOURCE ABS LEAD FOR UNIT FROM SUPPLIER AND FIT ABS LEAD ZIP TIE AND SECURE AS TO ENSURE ABS LEAD WOULD NOT RUB WHILST CONNECTED TO TRAILER CARRIED OUT TOPPING UP OF COOLANT <u>HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.</u>				
57532	30/08/2023	333988	REPLACE LHS UP AND DOWN WINDOW	Invoice
STRIPPED DRIVER'S DOOR, REMOVED BROKEN WINDOW & VACUUMED OUT ALL GLASS FROM DOOR, AND INSIDE TRUCK FIT NEW WINDOW & RE-ASSEMBLED DOOR CLEANED NEW WINDOW VACUUMED ALL BROKEN GLASS IN WORK AREA AND COMPLETED PAPERWORK RETURNED TRUCK TO BUCCINI YARD <u>HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.</u>				
57458	23/08/2023	332662	TRAILER BRAKES LOCKING ON	Invoice

Vehicle Details

Registration	332WIF	Next Service	Litres	10
Make	IVECO	Rego Due	Trans	N/A
Model	STRALIS AT	Engine #	Air	Yes
Model Series		VIN	Cyl	6
Model Code		Build Date	Body	PRIMEMOVER
Colour	White	Odometer	Prod	

Invoice No.	Date	Odometer	Description	Type
			<p>CARRY OUT A SERVICE AS PER THE SERVICE SHEET PARK VEHICLE IN WORKSHOP CARRY OUT WALK-AROUND VISUAL INSPECTION - THE CUSTOMER WAS CONCERNED ABOUT A TRAILER BRAKE FAULT, CARRIED OUT AN INSPECTION AND SCANNED THE VEHICLE WITH EZY, FOUND THE TRAILER CONTROL VALVE TO BE FAULTING, REMOVED THE VALVE CARRIED OUT A REPLACEMENT OF THE TRAILER CONTROL VALVE TESTED THE OPERATION, AND TESTED ALL OK CARRIED OUT ADJUSTMENT OF TURNTABLE SECURE HOIST ON TRUCK CHECK ALL LIGHTS INCLUDING ALL REVERSE LAMPS AND BEEPERS CHECK WIPER AND WASHER OPERATION CHECK BATTERY LEVELS, TERMINALS AND CLAMPS LIFT CAB/BONNET TO ACCESS ENGINE BAY CHECK ALL BELTS AND MOUNTS LIFT TRUCK ON HOIST CARRY OUT VISUAL INSPECTION OF UNDERCARRIAGE (DRIVE LINE AND SUSPENSION COMPONENTS) - RE- TENSIONED CHASSIS CROSS-MEMBER BOLTS ADJUST BRAKES AND CHECK BRAKE THICKNESSES CHECK AND ADJUST CLUTCH IF APPLICABLE CHECK GEARBOX OIL LEVEL AND QUALITY CHECK DIFF OIL LEVEL AND QUALITY CARRY OUT GREASING OF TRUCK LOWER TRUCK CHECK ENGINE OIL - TOPPED UP ENGINE OIL, FOUND OIL LEAK FROM PCV COVER AT BACK OF ENGINE, FOUND THREAD DAMAGED AND COVER DAMAGED, CARRIED OUT REPAIR TO DAMAGED THREAD AND REPLACED REAR ENGINE COVER & FITTED FILTER TESTED OPERATION TESTED ALL OK TOP-UP COOLANT IF REQUIRED - FOUND COOLANT LEAKING FROM GEARBOX RETARDER, CARRIED OUT DRAINING OF COOLANT INTO A CLEAN CONTAINER CARRIED OUT INSPECTION OF LEAKING HOSE FOR CRACKS OR BRAKES FOUND HOSE CLAMPS TO BE CAUSING LEAK CARRIED OUT REPLACEMENT OF HOSE CLAMPS AND REINSTALLED HOSE WITH NEW HOSE CLAMPS REFILLED SYSTEM WITH COOLANT FROM CLEAN CONTAINER AND TOPPED UP AS REQUIRED AND TESTED OPERATION TESTED ALL OK TOP UP WASHER BOTTLE FLUID LOWER CAB/BONNET AND SECURE IN PLACE FIT SERVICE STICKER COMPLETE PAPERWORK REMOVE HOIST</p> <p><u>HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.</u></p>	
57439	18/08/2023	332099	TRUCK AND TRAILER CAME IN WITH	Invoice
			<p>TRUCK AND TRAILER CAME WITH REVERSE LIGHT STUCK ON DIGNOSE ISSUE, FOUND IN TRUCK WIRING REMOVE TRAILER PLUG, SWITCHED WIRES ALL OK</p> <p><u>HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.</u></p>	

Vehicle Details

Registration	332WIF	Next Service	Litres	10
Make	IVECO	Rego Due	Trans	N/A
Model	STRALIS AT	Engine #	Air	Yes
Model Series		VIN	Cyl	6
Model Code		Build Date	Body	PRIMEMOVER
Colour	White	Odometer	Prod	

Invoice No.	Date	Odometer	Description	Type
57455	14/08/2023	332099	WELDED BROKEN BRACKETS	Invoice
POSITION TOOLS AND EQUIPMENT TO AREA GRINDED AREAS TO BE WELDED REMOVED BATTERY CONNECTION WELDED BROKEN BRACKETS PAINTED WEKDED AREAS				
57338	09/08/2023	330893	FIT POGO STICK AND REPLACE	Invoice
BROUGHT VEHICLE INTO WORKSHOP FOUND LIGHT FAULT ON DASH REPLACED NUMBER PLATE LIGHT BULB REPLACED RH BRAKE LIGHT BULB REMOVED AIRLINE SUZI COILS AND ELECTRICAL SUZI FROM POGO STICK RE-POSITIONED AND SECURED AIRLINE AND ELECTRICAL SUZI COILS TO POGO STICK <u>HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY ASWELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.</u>				
57228	26/07/2023	329391	REPLACE SUZI COIL	Invoice
REMOVED OLD, TANGLED AND DAMAGED SUZI COILS REPLACED WITH NEW SET OF LONG TAIL SUZI COILS				
56955	30/06/2023	0	SUPPLY SERVICE FILTERS	Invoice
SUPPLY SERVICE FILTERS				
57217	13/06/2023	324201	A SERVICE + INSPECTED AND ADJUSTED	Invoice
PARKED VEHICLE IN WORKSHOP CARRY OUT A SERVICE AS PER SERVICE SHEET <ul style="list-style-type: none"> • APPLY AIR TO TRAILER • TEST LIGHTING FUCTION • LIFT TRAILER WITH HOIST • CHECK WHEEL BEARINGS FOR MOVEMENT • CHECK SUSPENSION COMPONENTS • CHECK KING PIN BOLT TENSION • CHECK SKID PLATE • CHECK UNDERCARAGE OF TRAILER • CARRY OUT GREASING OF AXLES • CARRY OUT ADJUSTMENT OF BRAKES • LOWER TRAILER • CHECK WHEEL TENSION • CHECK WHEEL BEARING GREASE FOR CONTAMINENTS • CHECK ALL LIVERY INCLUDING MUDFLAPS AND DECAL • INSPECT MARKER PLATES INCLUDING CON SIGN, CHEVERONS AND OVER TAKE SIGNAGE • CHECK TOP DECK OF TRAILER FOR ALL FUNCTIONALITY 				

Vehicle Details

Registration	332WIF	Next Service	Litres	10
Make	IVECO	Rego Due	Trans	N/A
Model	STRALIS AT	Engine #	Air	Yes
Model Series		VIN	Cyl	6
Model Code		Build Date	Body	PRIMEMOVER
Colour	White	Odometer	Prod	

Invoice No.	Date	Odometer	Description	Type
			<ul style="list-style-type: none">• APPLY SERVICE STICKER• COMPLETE PAPER WORK• CLEAN WORK AREA• CHECKED FOR TURNTABLE FAULT FOUND HANDLE BENT REPLACED TURNTABLE HANDLE REPLACED SAFETY LATCH WIRE ROPES ADJUSTED TURNTABLE RESET DRIVE AIRBAGS REPLACED RIGHT HAND INDICATOR CHECKED LIGHTS FOR SERVICE ASSIST WITH TURNTABLE REPAIRS, REMOVE BENT HANDLE REPLACED AIR DRYER FILTER NOTE- SMALL ADBLUE LEAK IN EXHAUST NEAR INJECTOR - MONITOR TILT RAM LEAKING BADLY, REPLACE NEXT SERVICE BLOW-BY FILTER HOUSING WEEPING - RECOMMEND REPLACING WHOLE HOUSING AS HAS DISTORTED. ALL STEERING JOINTS HAVE A LITTLE MOVEMENT - MONITOR	
56785	31/05/2023	32624	REPLACE STARTER MOTOR	Invoice
			DROVE TO BUCCINI YARD CHECKED POWER AT STARTER MOTOR ALL OK, STARTER GOING INTO REMOVED BATTERY CONNECTIONS REMOVED AND REPLACED STARTER MOTOR WITH NEW STARTER RE-FIT BATTERY CONNECTIONS, TESTED WORKS OK	
56501	21/04/2023	318860	ELECTRICAL LEAD FOR TRAILER	Invoice
			FOUND ELECTRICAL LEAD FOR TRAILER BADLY DAMAGED FROM TAILSHAFT WAS TOLD 330WIF WASN'T BEING USED, SO TOOK LEAD FROM 330WIF AND FIT TO 332WIF RE-SET CIRCUIT BREAKERS ON TRUCK CHECKED LIGHTS - ALL GOOD ORDERED AND FITTED NEW LEADS TO 330WIF	
56477	19/04/2023	317706	REMOVE AND REPACE FEMALE TRAILER	Invoice
			REMOVE AND REPLACE FEMALE TRAILER COUPLING ON TRUCK	
56355	31/03/2023	0	AIR LEAK	Invoice
			BROUGHT VEHICLE INTO WORKSHOP REMOVED BATTERIES AND AIR TANK SWAPPED FITTINGS ONTO NEW AIR DRYER FIT NEW AIR DRYER RE-FIT AIR TANK RE-FIT BATTERIES TO THE TRUCK START UP TRUCK AND FOUND AIR LEAK REMOVED BATTERIES, AIR TANK AND THE AIR DRYER MOUNTING BOLTS AS IT WAS UNDER THE DRYER UNIT	

Vehicle Details

Registration	332WIF	Next Service	Litres	10
Make	IVECO	Rego Due	Trans	N/A
Model	STRALIS AT	Engine #	Air	Yes
Model Series		VIN	Cyl	6
Model Code		Build Date	Body	PRIMEMOVER
Colour	White	Odometer	Prod	

Invoice No.	Date	Odometer	Description	Type
INSTALL THE AIRLINE, RE-FIT DRYER AND BATTERIES START UP TRUC, TRUCK SLOWLY BUILDING UP AIR NEED TO SCAN TRUCK AS LOW AIR ISSUES FOUND REMOVE MAIN COMPRESSOR INLET AND OUTLET LINES, PRESSURE TESTED THE COMPRESSOR - ALL WORKING FINE REMOVED BATTERIES AGAIN AND REPLACED THE LEAKING FITTINGS CHECK FOR AIR LEAKS - ALL OK REMOVE DOOR CARD REMOVE AND REPLACE DOOR LOCK FIT DOOR CARD				
56321	29/03/2023	314271	C SERVICE	Invoice
COLLECTED TRUCK FROM BUCCINI YARD BROUGHT VEHICLE INTO WORKSHOP CARRIED OUT C SERVICE ADJUSTED TURNTABLE CHECKED FOR RH DOOR HARD TO OPEN FAULT ADJUSTED DOOR LATCH NOTE- DOOR LATCH FAULTY ENGINE BREATHER BOLTS STRIPPED X 3 - NEEDS REPLACING (WHOLE HOUSING) LF HEADLIGHT U/S				
56254	20/03/2023	314082	CRACKED TAILSHAFT TUBE	Invoice
INSPECTED TAILSHAFT AND FOUND IT TO BE CRACKED, CONTACTED THE DEALER NIL STOCK OF NEW SHAFTS IN THE COUNTRY, THE ONES WE HAVE IN OUR STOCK ARE DIFFERENT AND WILL NOT WORK. SENT TAILSHAFT OUT FOR REPAIRS TO ARUNDEL, SHAFT WAS REBUILT, STRAIGHTEND AND BALANCED. INSTALL TAILSHAFT AND TENSION BOLTS RETURN TO BUCCINI				
54814	16/03/2023	0	PARTS	Invoice
54121	16/03/2023	261938	STARTER MOTOR	Invoice
TRAVELLED TO BUCCINI YARD NEW STARTER MOTOR WAS REPLACED DROVE BACK TO THE WORKSHOP				
54236	16/03/2023	0	LHS MIRROR	Invoice
SUPPLIED AND FITTED MIRROR TO VEHICLE				
56028	17/02/2023	311240	EPOXY FUEL TANK	Invoice
SAND FUEL TANK AND APPLY EPOXY TO PIN HOLE LEAK TEST OPERATION - TESTED ALL OK DROP BACK TO BUCCINI YARD				
55979	15/02/2023	311240	AIR TANK PUSHED INTO FUEL TANK	Invoice

Vehicle Details

Registration	332WIF	Next Service	Litres	10
Make	IVECO	Rego Due	Trans	N/A
Model	STRALIS AT	Engine #	Air	Yes
Model Series		VIN	Cyl	6
Model Code		Build Date	Body	PRIMEMOVER
Colour	White	Odometer	Prod	

Invoice No.	Date	Odometer	Description	Type
VEHICLE CAME IN WITH FUEL LEAK DRAIN FUEL REMOVE FUEL TANK FROM TRUCK WELDING REPAIRS TO FUEL TANK INSTALL FUEL TANK FILL TANK WITH DIESEL DROP BACK TO BUCCINI YARD				
55726	05/01/2023	307181	REMOVE AND REPLACE DRIVERS SIDE	Invoice
REMOVE AND REPLACE DRIVERS SIDE WIPER BLADE				
55541	12/12/2022	3059989	SUNVISOR REPLACE	Invoice
BROUGHT VEHICLE INTO WORKSHOP CARRIED OUT A TEMP REPAIR BY SECURING THE SUNVISOR USING ZIP TIES. TRUCK WAS TAKEN BACK TO THE YARD. NEW SUNVISOR ON ORDER, WHEN IT ARRIVED CONTACTED THE FLEET CO-ORDINATOR AND HAD THE VEHICLE BROUGHT TO THE WORKSHOP. REMOVE OLD SUNVISOR AND FITTED NEW ONE. GREASED TURNABLE. NOTE SUNVISOR BREAKAGE WAS FAIR WEAR AND TEAR.				
55368	16/11/2022	297202	TOP UP OIL	Invoice
JACK UP CAB TOP UP ENGINE OIL				
55354	15/11/2022	299537	CARRY OUT B SERVICE	Invoice
BROUGHT VEHICLE INTO WORKSHOP CARRIED OUT B SERVICE ADJUSTED TURNABLE REPLACED LR PARK LIGHT NOTE- TIE ROD ENDS - MINOR MOVEMENT 1ST DRIVE SWAY BAR BUSHES ARE WORN 1ST DRIVE REAR AIR BAG OUTER CASING HAS PEELED OFF				
55150	14/10/2022	290586	NO CLEARANCE LIGHT ON TRAILER	Invoice
NO CLEARANCE LIGHT ON TRAILER TEST TRAILER LIGHTS - ALL OK CHECKED PRIME MOVER SUZI LEAD DAMAGED CHECKED STOCK - NIL STOCK MADE NEW LEAD - TESTED OPERATION - ALL OK NOTE ++FITTED LEAD OF WRITE OFF BUCCINI TRUCK++				
55117	10/10/2022	0	BENT TRAILER LOCK BAR	Invoice

Vehicle Details

Registration	332WIF	Next Service	Litres	10
Make	IVECO	Rego Due	Trans	N/A
Model	STRALIS AT	Engine #	Air	Yes
Model Series		VIN	Cyl	6
Model Code		Build Date	Body	PRIMEMOVER
Colour	White	Odometer	Prod	

Invoice No.	Date	Odometer	Description	Type
REMOVED TURNTABLE HANDLE AND BAR AS IT WAS COMPLETELY BENT FIT NEW HANDLE AND BAR ON THE TURNTABLE				
55082	05/10/2022	288520	CRACKED SUNVISOR	Invoice
STITCHED UP CRACKED SUNVISOR WITH ZIPTIES				
54860	23/08/2022	279499	TOPPED UP COOLANT	Invoice
TOPPED UP COOLANT				
54692	08/08/2022	0	REPLACE BATTERY	Invoice
REMOVED AND REPLACED FAULTY BATTERY				
54566	15/07/2022	299906	REPLACE HEADLIGHTS	Invoice
BROUGHT VEHICLE INTO WORKSHOP REPLACED U/S FUSES BLOWN AND RHS HEADLAMP / TEST - ALL OK REMOVED LHS HEADLAMP READY FOR NEW ONE 19/7/2022 FIT NEW HEADLIGHT ASSEMBLIES CHECKED FAULT CODES FOR VARIOUS ISSUES ON DASH WARNING CODES INCLUDING FRONT HEAD AND DAYTIME RUNNING LIGHTS ERRORS FOUND TO BE U/S LED HEADLAMP ASSEMBLIES BOTH LEFT AND RIGHT SIDES LOCATED / RE-FITTED WIRING FOR FUEL SOLENOID (AFTER AIR COMPRESSOR REPLACEMENT) ASSISTED FITTING DRIVE BELTS TOP UP ATF TOP UP COOLANT RE-FIT FAN BELT BLED FUEL SYSTEM REPLACED U/S FUSES (BLOWN) & RHS HEADLAMP / TEST OK REMOVED LHS HEADLAMP READY FOR NEW ONE 19/7/2022 REPLACED U/S LH HEADLAMP ASSEMBLY AND TEST - ALL OK SORTED OUT LOOSE LH REAR TAIL LAMP ASSEMBLY SUPPORT AS REQUIRED AND TEST - OK				
54550	14/07/2022	0	REPLACE LHS STEP	Invoice
PREPPED STEP FOR PAINTING MASKED STEP TREAD PLASTIC PRIMED STEP PAINTED STEP WHITE REMOVED MASKING TAPE FROM STEP TREAD				
54490	06/07/2022	299806	OIL LEAK	Invoice
DRIVER CAME UP WITH LOW ENGINE OIL LIGHT ON TOPPED UP ENGINE OL FOUND OIL FILTER HOUSING LEAKING ASKED DRIVER TO DROP TRAILER AT YARD AND BRING TRUCK BACK INTO THE WORKSHOP AND INFORMED JUSTIN AT BUCCINI YARD INSPECT TRAILER RH INDICATORS NOT WORKING CONNECTED LIGHT TESTER ON TRAILER, FOUND ALL LIGHTS WORKING				

Vehicle Details

Registration	332WIF	Next Service	Litres	10
Make	IVECO	Rego Due	Trans	N/A
Model	STRALIS AT	Engine #	Air	Yes
Model Series		VIN	Cyl	6
Model Code		Build Date	Body	PRIMEMOVER
Colour	White	Odometer	Prod	

Invoice No.	Date	Odometer	Description	Type
FOUND FAULT IN THE ELCTRICAL LEAD REPLACED ELECTRICAL LEADS - SUZI COILS AND 7 PIN PLUG REMOVE HEADLIGHTS AND LH VISOR LIGHT FROM XQ92EM REPLACE HEADLIGHTS, TESTED NOT WORKING PROPERLY COULD NOT FIT VISOR LIGHT AS DAMAGED BUT USED IT TO TEST OLD ONE NOT WORKING REMOVED FUEL LIFT PUMP, POWER STEERING AND COMPRESSOR SWAPPED ALL FITTINGS FROM OLD COMPRESSOR TO NEW COMPRESSOR SWAPPED DRIVE GEAR FROM OLD COMPRESSOR TO NEW COMPRESSOR USED PULLER AND OXY TO GET GEAR OFF CHECKED FOR LEAK AROUND ENGINE REPLACED REAR PARK LIGHT BULBS REPLACED NUMBER PLATE LIGHT BULB CHECKED FOR LH SUNVISOR LIGHT FAULT (LED LIGHT FAULTY) TIGHTENED FUEL PUMP HOSES AND DOWDY SEALS CLEANED FUEL PUMP REPLACED OIL FILTER TOPPED UP ENGINE OIL REMOVE FAN BELT AND REMOVE BELT TENSIONER REFIT THE NEW BELT TENSIONER REMOVED / REPLACED AND TESTED TOP / ROOF MOUNTED LEFT SIDE CLEARANCE LAMP - ALL OK RE-FIT COMPRESSOR PIPES, HOSES, WIRING, POWER STEERING PUMP AND RESERVOIR AND FUEL LIFT PUMP REMOVE FAN BELT AND BELT TENSIONER REFIT THE NEW BELT TENSIONER RE-FILLED COOLANT AND POWER STEERING FLUID CHECKED FOR OIL LEAKS VEHICLE REQUIRES A DEGREASE RAISE CAB REPLACED LH STRIP ASSEMBLY FITTED TREADS LOWERED CAB DEGREASED UNDERNEATH COMPRESSOR TEST DROVE TRUCK UNTIL IT GOT TO RUNNING TEMP				
54311	20/06/2022	263690	REPLACE HEADLIGHT BULB	Invoice
REPLACED FRONT LHS HEADLIGHT BULB				
54425	15/06/2022	269500	LHR TAILLIGHT / FUEL TANK STRAP	Invoice
REMOVE LR TAIL LIGHT ASSEMBLY REMOVE LR TAIL LIGHT FROM ROLL OVER TRUCK AND FIT TO 332WIF CHECKED CHARGE SYSTEM - ALL OK RESET ECU TO TURN FALSE WARNING OFF AND THEN RECHECKED AFTER BATTERY RESET - ALL OK REPLACED 1 X PARK LIGHT GLOBE FIT NEW LENS ON THE TAIL LIGHT FUEL TANK STRAP CAME LOOSE, TIGHTENED TANK STRAP BOLT - ALL OK				
54341	08/06/2022	268212	CARRY OUT B SERVICE	Invoice

Vehicle Details

Registration	332WIF	Next Service	Litres	10
Make	IVECO	Rego Due	Trans	N/A
Model	STRALIS AT	Engine #	Air	Yes
Model Series		VIN	Cyl	6
Model Code		Build Date	Body	PRIMEMOVER
Colour	White	Odometer	Prod	

Invoice No.	Date	Odometer	Description	Type
			CARRY OUT B SERVICE NOTE- FRONT DISCS MINOR WEAR FUEL PUMP FITTINGS WEEP - MONITOR TOP RIGHT CLEARANCE LIGHT OUT UNDERNEATH NEEDS TO BE WASHED AND OIL LEAK INSPECTED	
54223	24/05/2022	265540	REPAIR LIGHTS AND SUZI COILS	Invoice
			MADE VARIOUS ADJUSTMENTS AND VERY TEMPORARY EMERGENCY REPAIRS TO DAMAGED LHR TAIL LAMP ASSEMBLY WIRING MADE TESTS / CHECKS TO SUZI LEAD POWER SUPPLY CIRCUITS MAINS LH FLASHER NOT WORKING FOUND SUZI LEAD CABLE AT FAR END U/S AND PLUG ALSO U/S CHOPPED BACK CABLE END AND FITTED NEW PLUG / TEST WITH TRAILER - ALL OK REPLACED PARKSIDE REAR LENS ON TAIL LIGHT IT REQUIRES A WHOLE ASSEMBLY BUT ONLY HAD LENS ON HAND MADE ALL LIGHTS WORK THEN PUT NEW LENS ON REMOVED BLOWN HEADLIGHT BULB, AND FITTED A 2ND HAND ONE WE HAD HERE	
54053	21/04/2022	260048	REPLACE LHS TAIL LIGHT ASSEMBLY	Invoice
			REMOVED AND REPLACED LHS REAR TAIL LIGHT ASSEMBLY REPLACED BLOWN GLOBES IN RHS REAR TAIL LIGHT REPLACED BLOWN GLOBE AT RHS SIDE LIGHT RECHECKED ALL LIGHT OPERATION - ALL OK	
53958	30/03/2022	257936	TURNTABLE ISSUES	Invoice
			30/3/2022 - INSPECTED TURNTABLE FOR MOVEMENT FOUND MOVEMENT IN JAW PIN CASING IT NOT TO RESET, THE TURNTABLE PIN IS WORN AND NOW ALLOWING THE SLIDE BAR TO MOVE TURNTABLE REQUIRES REPLACING 6/4/2022 - REMOVED OLD TURNTABLE ASSEMBLY FROM VEHICLE REPLACED TURNTABLE ASSEMBLY WITH NEW JOST TURNTABLE TENSIONED MOUNTING BOLTS TO SPEC AND ADJUSTED TURNTABLE GREASED AND CHECK OPERATION - ALL OK	
53923	21/03/2022	254165	REPAIRS	Invoice
			21/3/2022 REPLACE LEAKING REAR AXLE FRONT AIR BAGS, NO AFTERMARKET BAGS AVAILABLE. LIFT UP THE CAB TIGHTEN UP INTERCOOLER HOSE AND DEGREASE THE AREA GREASED THE AREA AROUND THE COMPRESSOR REPAIRED #2 DIFF V STAY MOUNTING THREADS IN DIFF FITTED NEW V STAY SECURED AIRLINK ON STAY REPLACED LH TURNTABLE TEFLON PAD (SUPPLIED) CHECKED FOR TRANSMISSION FAULT	

Vehicle Details

Registration	332WIF	Next Service	Litres	10
Make	IVECO	Rego Due	Trans	N/A
Model	STRALIS AT	Engine #	Air	Yes
Model Series		VIN	Cyl	6
Model Code		Build Date	Body	PRIMEMOVER
Colour	White	Odometer	Prod	

Invoice No.	Date	Odometer	Description	Type
REMOVED REAR ENGINE COVER STEPS CHECKED COMPUTER FAULTS REPLACED AIR FITTINGS AT REAR OF GEARBOX STARTED ENGINE AND CHECKED FOR LEAKS REFITTED COVERS AND STEPS				
53889	18/03/2022	255968	A SERVICE	Invoice
18/3/2022 CARRIED OUT A SERVICE FOUND FRONT AIRBAGS ON REAR AXLE NEED REPLACING FOUND SMALL ADBLUE LEAK FROM EXHAUST PIPE NEXT TO ADBLUE INJECTOR OIL LEAK FROM INTERCOOLER HOSE NEXT TO TURBO FUEL LEAK NEAR COMPRESSOR REFITTING BATTERIES REMOVE V STAY OFF BREAK DOWN TRUCK, REMOVE BROKEN V STAY				
53901	17/03/2022	255968	BREAKDOWN -BATTERIES OVER HEATED	Invoice
17/3/2022 DROVE TO BUCCINI YARD TO JUMP START TRUCK FOUND BATTERIES WERE SMELLING LIKE SULPHUR AND VERY HOT JUMP STARTED TRUCK ANF ASKED DRIVER TO BRING THE TRUCK TO THE WORKSHOP TO REPLACE THE BATTERIES REPLACED BATTERIES, CLEANED TERMINALS AND CHASSIS EARTH SPRAYED BATTERY TERMINAL PROTECTOR ON THEM CHECKED - NAME TESTS TO START CHARGE / DASH CODES / FAULTS / ERRORS REPLACED U/S BATTERIES CLEANED UP BAD EARTHING RHS TEST - CLEARED ALL CHECKED CHARGING - ALL OK				
53829	09/03/2022	254165	SUZI COILS	Invoice
9/3/2022 REPLACED SUZI COILS				
53797	04/03/2022	252888	ETC CODE ON DASH	Invoice
4/3/2022 CALLED TO BUCCINI YARD TO SCAN TRUCK FOR POSSIBLE CODES FOUND 3 CODES PRESENT - CLUTCH ACTUATOR DTC OX 77 / CLUTCH ACTUATOR DTC OX 75 TACHOMETER DTC OX 64 BUILT UP AIR TANKS DRS AND FUEL PRESSURE OK - RELEASED PARKBRAKE AND SELECTED FORWARD AND REVERSE - ALL OK - NO AIR LEAKSPRESENT AND TRIED GEAR SHIFT 15 TIMES - ALL OK RESUCURED LOOSE FUEL SENSOR PLUG				

Vehicle Details

Registration	332WIF	Next Service	Litres	10
Make	IVECO	Rego Due	Trans	N/A
Model	STRALIS AT	Engine #	Air	Yes
Model Series		VIN	Cyl	6
Model Code		Build Date	Body	PRIMEMOVER
Colour	White	Odometer	Prod	

Invoice No.	Date	Odometer	Description	Type
53765	01/03/2022	252188	ENGINE LIGHT ON DASH	Invoice
1/3/2022 DROVE TO BUCCINI YARD CHECKED FOR TRANSMISSION FAULTS AND COMPUTER FAULTS FOUND TACHO SIGNAL FAULTY CAB HYDRAULIC HOSE BURST, RETURNED TO WORKSHOP REMOVED RH STEP REMOVED BROKEN CAB HYDRAULIC PIPE AND GOT A NEW ONE MADE UP. FITTED NEW CAB TILT PIPE TO TRUCK AND REFILLED WITH ATF, CHECK OPERATION ALL OK. LOAD TESTED BATTERIES - ALL OK CHECKED FOR POSSIBLE CODES - ALL OK				
53757	18/02/2022	0	AFTER HOURS CALLOUT	Invoice
GOT CALLED OUT AFTER HOURS TO PORT OF BRISBANE TO BREAKDOWN DROVE TO WORKSHOP TO PACK VAN RECIEVED A CALL TO SAY TRUCK MANAGED TO GET MOVING, JOB CANCELLED RETURNED HOME				
53654	04/02/2022	244833	REPAIRS	Invoice
DRIVER CAME IN WITH PROBLEM OF TURNTABLE NOT LOCKING OR RELEASING DIAGNOSED AND FOUND TURNTABLE NEED TO BE REKITTED AND LOCKING BAR NEEDED TO BE REPLACED RE-KIT TURNTABLE AND REPLACE LOCKING BAR REMOVE AND REPLACE NYLON PLATES READJUSTED TURNTABLE AND TESTED OPERATION - ALL OK REMOVED AND REPLACED WORN AIR BAGS - CRACKED AT BASE RESET AIR BAGS				
53641	02/02/2022	243928	REPLACE TAIL LIGHT LENSE	Invoice
2/2/2022 REPLACED RH TAIL LIGHT LENSE ONCE ADBLUE CAP ARRIVED GAVE TO BUCCINI DRIVER TO FIT				
53615	21/01/2022	241972	LIGHTING REPAIRS	Invoice
CHECKED LIGHTING FAULTS ON DASH CASUING RHS HEADLIGHT TO NOT WORK REPLACED TWO SIDE MARKER LIGHT GLOBES REPLACED RHS HEADLIGHT LOW BEAM GLOBE REPLACED RHS TAIL LIGHT GLOBE CHECKED OPERATION OF LIGHTS - ALL OK REPAIRED ALL FOUR INTERIOR LIGHTS ON ROOF - CONSOLE NOT WORKING REPAIRED BAD GLOBE HOLDER CONNECTORS AND REPLACED ALL GLOBES TESTED OPERATION OF DOOR TRIGGERS - ALL OK				
53444	29/12/2021	238554	CARRY OUT B SERVICE	Invoice
CHECKED TURNTABLE FAULT REPLACED TURNTABLE HANDLE REPAIRED TURNTABLE LATCH CHECKED OPERATION - ALL OK REMOVED AND REPLACED DAMAGED TRAILER LIGHTING SUPPLY SOCKET ON VOLTAGE REDUCER AS REQUIRED TESTED OPERATION - ALL OK CHECKED OUTPUTS THROUGH SUZI-LEADS - ALL OK REPLACED LHS REAR TAIL LAMP ASSY FOR PRK AND CLEARANCE LAMPS				

Vehicle Details

Registration	332WIF	Next Service	Litres	10
Make	IVECO	Rego Due	Trans	N/A
Model	STRALIS AT	Engine #	Air	Yes
Model Series		VIN	Cyl	6
Model Code		Build Date	Body	PRIMEMOVER
Colour	White	Odometer	Prod	

Invoice No.	Date	Odometer	Description	Type
			TIGHTENED, CLEANED AND RETENSIONED LOOSE CONTACT SPRING TERMINALS CHECKED ALL OTHER TRUCK LIGHTING - ALL OK CARRIED OUT C SERVICE CLEANED OUT AIR DRIER HOUSING TOPPED UP COOLANT AND WINDSCREEN WASHER BOTTLE REMOVED TURNTABLE TEFLON PADS, JAW AND WEAR PINS FIT NEW JAW KIT AND ADJUSTED TURNTABLE DEFECTS: MINOR MOVEMENT IN LHS FRONT KING PIN - MONITOR BOTH LHS 2ND DRIVE AIR BAGS ARE CRACKING AT BASE	
53440	17/12/2021	237276	REPAIRS	Invoice
			TOPPED UP ENGINE OIL INSPECTED TURN TABLE HANDLE LOCKING TAB - DOESNT ALWAYS LOCK IN PLACE WHEN HOOKING UP TO TRAILER ELECTRICAL PLUG ON TRUCK SIDE HAS BEEN PULLED OUT OF HOUSING - REQUIRES REPLACING	
53269	29/11/2021	232865	DOOR MODULE	Invoice
			26/11/2021 - VEHICLE CAME IN WITH DRIVER SIDE DOOR SWITCHES NOT WORKING REPLACED DOOR FUSES - STILL FAULTING 29/11/2021 - CONNECTED IVECO SCAN TOOL TO ASSESS RHS DOOR FAULTS FOUND WATER INTRUSTION RHS AS GROMMET WAS DISLOGED AND HAD GOTTEN WATER IN DOOR MODULE CLEANED UP CONNECTIONS AND REPLACED DOOR MODULE - TESTED ALL OK REFIT DOOR SKIN BACK TO RHS DOOR REPAIRED PUSHED IN LHS DOOR SWITCH AND TESTED OPERATION - ALL OK RECHECKED ALL MIRROR /WINDOW AND CENTRAL LOCKING FUNCTIONS ON DOORS - ALL OK REPLACED LHS REAR TAIL LAMP LENS AND BLOCKED OFF SMALL GAP ON SIDE OF LAMP RESECURED LOOSE RHS FUEL SENDER PLUG AND WIRING AND TESTED OPERATION - ALL OK	
53212	22/11/2021	231014	FRONT BRAKE PADS	Invoice
			CONNECTED JALTEST TO CHECK SUSPENSION CODES FOUND CORRUPTED/ERRATIC CANBUS INFO DUE TO POOR/CORRODED EARTH SIDE OF BATTERY TERMINALS AND TESTED OPERATION - ALL OK ALSO CODE PRESENT ON DASH FOR FRONT LHS WHEEL/BRAKE SENSOR CLEARED CODES AND TOOK VEHICLE FOR A TEST DRIVE CODE CAME UP FOR LOW FRONT BRAKE PADS JACKED UP FRONT OF VEHICLE AND INSPECTED BRAKE PADS - FOUND THEM TO BE LOW REMOVED FRONT WHEELS DISASSEMBLE BRAKE CALIPERS TO ACCESS BRAKE PADS WIND BRAKES ALL THE WAY OFF REMOVED AND REPLACD FRONT BRAKE PADS REFIT COMPONENTS AND WHEELS RETORQUED WHEEL NUTS AND ADJUSTED WHEEL BEARINGS TESTED OPERATION - ALL OK	
53101	03/11/2021	227500	WINDOW REG RHS AND TRAILER PLUG	Invoice
			CHECKED TRAILER CLEARANCE LIGHTS NOT WORKING CHECKED TRAILER PLUG AND FOUND PINS DAMAGED REMOVED AND REPLACED TRAILER PLUG TESTED OPERATION - ALL OK	

Vehicle Details

Registration	332WIF	Next Service	Litres	10
Make	IVECO	Rego Due	Trans	N/A
Model	STRALIS AT	Engine #	Air	Yes
Model Series		VIN	Cyl	6
Model Code		Build Date	Body	PRIMEMOVER
Colour	White	Odometer	Prod	

Invoice No.	Date	Odometer	Description	Type
REMOVED AND REPLACED RHS WINDOW REGULATOR REPLACED SUZI COILS AND TESTED OPERATION - ALL OK				
53122	25/10/2021	0	STUCK IN GEAR	Invoice
TRUCK STUCK IN GEAR AND SHOWING FAULT CODES ETC 75 AND 77 TRAVEL TO BUCCINI YARD AND INSPECT UNIT VEHICLE WAS STUCK IN REVERSE ATTEMPTED TO SHIFT OUT OF GEAR - ALL OK FAULT CODES STILL ON DASH TURNED OFF IGNITION FOR 5 MINS TO CLEAR CODES - FAILED TRAVELLED BACK TO WORKSHOP FOR JALTEST AND TOOK TO BUCCINI YARD CONNECTED JALTEST AND INVESTIGATE FAULT CODES ETC 75 - RELATED TO LOSS OF AIR PRESSURE ETC 77 - GEAR ACTUATOR WAS NOT DISENGAGING AS A RESULT OF ATTEMPTING TO SELECT WITH NO AIR IN SYSTEM CLEARED FAULT CODES AND RECHECKED - ALL OK				
53117	18/10/2021	225426	TRANSMISSION FAULTS	Invoice
18/10/2021 - VEHICLE STUCK IN GEAR INSPECTED VEHICLE - DASH NOTIFIED THAT VEHICLE WAS STUCK IN GEAR ATTEMPTED TO REMOVE FROUND AIR WAS NOT CHARGING THE TRANSMISSION TANK CAUSING IT TO BE STUCK IN REVERSE LUBED UP ORING AND RECONNECTED ON AIR TANK TESTED OPERATION - ALL OK 19/10/2021 - CLEANED UP CONTACTS TO MALE AND FEMALE FITTINGS ON TRAILER PLUG TESTED OPERATION OF SUZI COILS - ALL OK				
52899	23/09/2021	221679	AIR LINE REPAIRS	Invoice
ATTENDED BUCCINI YARD AND INVESTIGATE FAILED SUZI COILS ONCE ARRIVED UNIT WAS STILL ATTACHED TO TRAILER REMOVED OLD SUZI COILS AND INSPECTED LIGHT CABLE AS IT WAS STILL INTACT FITTED NEW SUZI COILS AND TEST - ALL OK				
52847	14/09/2021	232865	MIRROR BROKEN	Invoice
REMOVED AND REPLACED LHS MIRROR ASSEMBLY ADJUSTED AND CHECKED - ALL OK				
52830	09/09/2021	219962	REPLACE ELECTRICAL PLUG	Invoice
CHECKED TRAILER LIGHT FAULT REPLACED ELECTRICAL SUZI COIL 7 PIN SOCKET TRUCK DOES NOT HAVE PROVISION FOR A POGO STICK, NEVER HAD ONE. REPLACED LHS LOW BEAM HEADLIGHT GLOBE SECURED LHS MIRROR ASSEMBLY - DAMAGED - NEW MIRROR ORDERED				
52757	26/08/2021	218501	D/S DOOR LOCK DAMAGED	Invoice
RH DOOR LOCK DAMAGED REMOVED RHS DOOR CARD REMOVED AND REPLACED RHS DOOR LATCH AND INSIDE DOOR LEVERS REFITTED DOOR CARD AND TESTED OPERATION ALL OK				

Vehicle Details

Registration	332WIF	Next Service	Litres	10
Make	IVECO	Rego Due	Trans	N/A
Model	STRALIS AT	Engine #	Air	Yes
Model Series		VIN	Cyl	6
Model Code		Build Date	Body	PRIMEMOVER
Colour	White	Odometer	Prod	

Invoice No.	Date	Odometer	Description	Type
52707	18/08/2021	216705	CARRY OUT REPAIRS	Invoice
D/S WIPER BALDESX ASSEMBLY BROKEN. REMOVED AND REPLACED WIPER BLADE ASSEMBLY'S ALL OK				
52693	11/08/2021	215115	TAIL LIGHT REPAIRS	Invoice
REASSAMBLE RHS REAR TAILLIGHT HOUSING - BOLTS HAD BEEN PULLED THROUGH AND THE LIGHT WAS HANDING DOWN REMOVED AND REPLACED BOLTS TO RHR REAR TAIL LIGHT ASSEMBLY TESTED LIGHTS - ALL OK				
52457	09/07/2021	0	AIR DRIER ASSEMBLY	Invoice
REPLACE AIR DIRER - FAILED DRAIN AIR TANKS AND DICONNECT BATTERIES REMOVE BATTERYA DN BATTERY BOX SURROUND LOOSEN OFF AIR TANK AND START TO REMOVE AIR DRIER MOUNT DICONNECT AIR LINES AND DISMANTLE AIR DRIER REASSEMBLE NEW AIR DRIER AND FIT TO VEHICLE TIGHTEN UP AIR LINES AND REFIT AIR TANK REFIT BATTERIES, BATTERY BOX AND CONNECT TERMINALS TEST DRIVE VEHICLE - ALL OK				
52398	01/07/2021	205938	CARRY OUT B SERVICE	Invoice
CARRY OUT A AND B SERVICES ON EVHICLE RESET AIRBAGS ON UNIT ADJSUTED TURN TABLE RESECURED FUEL PUMP OUTLET HOSE REMOVED AND REPLACED ADBLUE FILTER AND WIPER BLADES DEFECTS: REAR UPPER V BAR HAS EXCESSIVE PLAY IN BALL JOINT - QUOTING TO REPLACE PASSENGER SIDE WINDOW TINT PERISHED PASSENGER SIDE MIRROR BASE CRACKED LHS REAR TYRES BALD - NEED REPLACING				
52269	14/06/2021	205936	REPLACED TURBO	Invoice
REMOVED PIPES OFF TURBO CHARGE AND DIAGNOSED THE THE SHAFT CONNECTING THE EXHAUST FAN TO THE BLOWER FAN HAS SNAPPED. TURBO IS IN NEED OF REPLACEMENT. INSPECTED PIPE WORK AND FOUND THAT THERE ARE TRACES OF METAL IN THE INTERCOOLER, IT WILL NEED TO BE REMOVED AND FLUSHED BEFORE REASSEMBLY. DRAINED COOLANT AND REMOVED AIRCON CONDENSER AND RADIATOR REMOVED INTERCOOLER AND TURBO (THE BOLTS WERE SEIZED AT THE MANIFOLD) REPLACED TURBO ASSEMBLY REFITTED RADIATOR AND INTERCOOLER REFITTED INTAKE HOSES AND RADIATOR HOSES REFILLED COOLANT REPLACED RADIATOR FAN SHROUD AND COWLING REFITTED TAIL SHAFT AFTER BEING TOWED IN FITTED TWO NUTS TO TURBO TO SECURE AND TENSIONED UPON TEST DRIVE OF VEHICLE, TRUCK BLEW EXCESSIVE AMOUNTS OF OIL OUT OF EXHAUST AND BLEW SMOKE				

Vehicle Details

Registration	332WIF	Next Service	Litres	10
Make	IVECO	Rego Due	Trans	N/A
Model	STRALIS AT	Engine #	Air	Yes
Model Series		VIN	Cyl	6
Model Code		Build Date	Body	PRIMEMOVER
Colour	White	Odometer	Prod	

Invoice No.	Date	Odometer	Description	Type
REMOVED OLD MUFFLER AND TAIL PIPE AND REPLACED REFIT EXHAUST TO MUFFLER AND FIT SENSORS DEGREASED ENGINE AND TESTED DROVE - ALL OK				
52264	12/06/2021	205936	BREAKDOWN	Invoice
ATTENDED BREAKDOWN ON THE FREEWAY HEADING NORTH NEAR THE OLD CLEVELAND ROAD. CONNECTED UP THE DIAGNOSTIC EQUIPMENT AND FOR A CODE FOR THE TURBO SENSOR. INSPECTED THE TURBO AND FOUND DIAGNOSED IT HAD FAILED. REMOVED THE TAILSHAFT AND WAITED FOR THE TOW TRUCK TO ARRIVE, WE WERE UNABLE TO LEAVE THE TRUCK UNATTENDED ON THE FREEWAY. ONCE THE TOW TRUCK ARRIVED WE PROCEEDED BACK TO THE WORKSHOP AND DIRECTED THE TOW DRIVER ON WHERE TO PARK UP THE TRUCK.				
52155	26/05/2021	201249	CARRY OUT REPAIRS	Invoice
VEHICLE CAME IN WITH LOW COOLANT ALARM ON INSPECTED VEHICLE AND CHECKED TIGHTNESS OF COLLANT PIPES AND CAPS - ALL OK TOPPED UP COOLANT				
52130	21/05/2021	201058	EXPANSION TANK	Invoice
COOLANT OVERFLOWING FROM TANK FOUND ON SERVICE REMOVED AND REPLACED COOLANT TANK ON THE FRONT OF THE VEHICLE - LEAKING COOLANT REPLACED COOLANT HOSE AT HEADER TANK - CRACKED TESTED DROVE - VEHICLE ALL OK				
52112	19/05/2021	201000	CARRY OUT B SERVICE	Invoice
CARRIED OUT B SERVICE. REPLACED ENGINE BREATHER FILTER. REPAIRED OIL LEAK FROM REAR OF THE ENGINE, REAR COVER BOLTS WERE LOOSE, TIGHTEND UP BOLTS. GREASED CAB MOUNTS DEFECTS: LHR DUAL TYRES WORN DOWN - WILL NEED REPLACING FRONT SWAY BAR BUSHES STARTING TO WEAR TIGHTENED BOLTS TO TIMING COVER - MONITOR LEAK				
52003	10/05/2021	197251	ELECTRICAL REPAIRS	Invoice
VEHICLE CAME IN WITH TRAILER LIGHTS FLICKERING TIGHTENED ELECTRICAL PLUG WIRING AT VOLTAGE REDUCER BOX				
51776	15/04/2021	194882	CARRY OUT REPAIRS	Invoice
REPLACED RHS SEAT VALVE ASSEMBLY				
51708	18/03/2021	194882	TREDDLE VALVE	Invoice
CHECK AND REPORT ON LEAKING TREADLE VALVE. DROVE VEHICLE FROM YARD TO WORKSHOP INSPECTED AND CONFIRMED IT IS LEAKING AIR. REMOVED VALVE AND CHECKED, IT IS NOT REPAIRABLE AND REQUIRES REPLACING. TO REMOVE TREDLE VALVE HAD TO REMOVE AIR FITTINGS FROM THE VALVE. REMOVED LOWER SECTION OF DASH AND STEERING COLUMN TO GAIN AACCESS TO AREA. REMOVED MOUNTING BOLTS AND VALVE OK. SUPPLY AND FIT NEW VALVE ASSEMBLY AND AIR DRIER FILTER. CHECKED TAIL LIGHT OPERATION - REPLACED REAR TAIL LIGHT ASSEMBLIES (AS TAKEN OFF AND FITTED TO 331WIF)				

Vehicle Details

Registration	332WIF	Next Service	Litres	10
Make	IVECO	Rego Due	Trans	N/A
Model	STRALIS AT	Engine #	Air	Yes
Model Series		VIN	Cyl	6
Model Code		Build Date	Body	PRIMEMOVER
Colour	White	Odometer	Prod	

Invoice No.	Date	Odometer	Description	Type
51649	12/03/2021	193736	CARRY OUT REPAIRS	Invoice
CALLED OUT TO MT GRAVATT/CAPALABA HIGHWAY EXIT. REMOVED REAR MUDGUARD POLES AND PICKED UP THE REMAINS OF THE MUDGUARDS OFF THE ROAD. RHS REAR AXLE TYRES EXPLODED DAMAGING GUARDS STRIP OFF DAMAGED PARTS AND ACCESS THE RHS REAR. REPLACE DAMAGED RHS MUDGUARDS THAT WERE DAMAGED WHEN THE TYRE EXPLODED. FITTED REAR MUDGUARD POLE AND REAR MUDFLAP, INSTALLED NEW MUDGUARDS, BRACKETS AND COVERS. INFLATED RH 2ND DIFF TYRE - LOW AIR AND INSTALLED NEW REFLECTOR SIGN. STRAIGHTENED OUT RH FRONT STEP - DAMAGED				
51583	05/03/2021	189462	A SERVICE	Invoice
DATE WORK CARRIED OUT: 19/02/2021 WORK CARRIED OUT: CARRIED OUT A SERVICE REPLACED OIL FILTER AS IT WAS LEAKING TOPPED UP ENGINE OIL DEFECTS NOTED: <ul style="list-style-type: none">- POWERSTEERING LEAK AT BOTTOM HOSE UNDER RESERVOIR- BLOW BY COVER LEAKING – GASKET??, BROKEN COVER- FR INTERCOOLER BOLT LOOSE CONNECTING TO RADIATOR- LEAKING TURBO SEAL- FRONT DRIVE SWAY BAR BUSHES IN NEED OF REPLACEMENT- CRACK IN FRONT BUMPER				
51477	15/02/2021	0	RETORQUED SIGNAL SUZI COIL OLIVE	Invoice
DATE WORK CARRIED OUT: 15/02/2021 WORK CARRIED OUT: RE-TORQUED SIGNAL SUZI COIL OLIVE REMOVED UNIT, ADJUSTED OLIVE & REINSPECTED RE-TORQUED & TESTED				
51424	11/02/2021	188208	TRAILER CONTROL VALVE	Invoice
DATE WORK CARRIED OUT: 10/02/2021 – 11/02/2021 WORK CARRIED OUT: DIAGNOSED WARNING LIGHT ON DASH CONNECTED UP DIAGNOSTIC SCANNER AND LOCATED FAULT TO THE BRAKE CONTROLLER VALVE REMOVED SENSORS AND TESTED - SENSORS TESTED OK DIAGNOSED BRAKE CONTROL VALVE IS FAULTY REMOVED TRAILER BRAKE VALVE IN CHASSIS REPLACED VALVE AND CLEARED CODES TEST DROVE AND DROPPED TRUCK BACK TO BT YARD				
51449	05/02/2021	0	UHF FAULT	Invoice

Vehicle Details

Registration	332WIF	Next Service	Litres	10
Make	IVECO	Rego Due	Trans	N/A
Model	STRALIS AT	Engine #	Air	Yes
Model Series		VIN	Cyl	6
Model Code		Build Date	Body	PRIMEMOVER
Colour	White	Odometer	Prod	

Invoice No.	Date	Odometer	Description	Type
DATE WORK CARRIED OUT: 27/01/2021 – 05/02/2021 WORK CARRIED OUT: INSPECTED UHF NOT WORKING FOUND NO POWER TO PLUG – COULDN'T FIND ANY BLOWN FUSES SUSPECT POSSIBLE 24/12V CONVERTER U/S MADE TESTS TO POWER SUPPLY REMOVED TOP CENTRE & RHS CONSOLE PANELS TO ACCESS POWER SUPPLY / VOLTAGE REDUCER / WIRING COMPONENTS FOUND VOLTAGE REDUCER U/S REPLACED & TESTED VOLTAGE REDUCER REFITTED REMOVED PANELS TOP CENTRE DASH CONSOLE				
51239	07/01/2021	0	EBS SYSTEM FAULT	Invoice
DATE WORK CARRIED OUT: 07/01/2021 WORK CARRIED OUT: INSPECTED EBS SYSTEM FAULT GOT DRIVER TO PRESS PEDAL AS MECHANIC INSPECTED ALL HUB BRAKE OPERATION LIGHT WENT OUT & DIDN'T RETURN DRIVER NOTED BRAKES WERE VERY SPONGY AND FELT GOOD AFTER PRESSING BRAKE PEDAL A FEW TIMES				
51238	07/01/2021	185359	BREAKDOWN - SUZI COIL	Invoice
DATE WORK CARRIED OUT: 07/01/2021 WORK CARRIED OUT: ATTENDED BREAKDOWN @ BT YARD TRUCK FAILING TO BUILD UP AIR DIAGNOSED MAJOR AIR LEAK @ SUPPLY OF RED SUZI OIL REMOVED & INSPECTED JOINT CLEANED & RE-FITTED TO TRUCK TESTED – ALL OK CHECKED CONTROL LINE SUZI FOR SAME ISSUE – ALL OK				
51231	05/01/2021	0	SUZI COIL REPAIRS	Invoice
DATE WORK CARRIED OUT: 05/01/2021 WORK CARRIED OUT: TRAVELLED TO BT YARD REPLACED SUZI LEADS & FITTINGS RETURNED TO WORKSHOP				
51148	29/12/2020	184249	LABOUR \$100.00 / HR	Invoice
DATE WORK CARRIED OUT: 24/12/2020 – 29/12/2020 WORK CARRIED OUT: LOADED TURNTABLE ONTO THE FORK LIFT AND LOWERED ONTO THE NEW CHASSIS ANGLE				

Vehicle Details

Registration	332WIF	Next Service	Litres	10
Make	IVECO	Rego Due	Trans	N/A
Model	STRALIS AT	Engine #	Air	Yes
Model Series		VIN	Cyl	6
Model Code		Build Date	Body	PRIMEMOVER
Colour	White	Odometer	Prod	

Invoice No.	Date	Odometer	Description	Type
			HOLES DO NOT LINE UP THEY HAVE BEEN DRILLED INCORRECTLY BOLT TURNABLE ON USING FOUR MOUNTING BOLTS ON THE RHS TO ENABLE SAFE TRANSPORTATION AND RETURNED TRUCK TO IVECO FOR REWORK TRUCK DRIVEN TO IVECO - ATTENTION LUKE IN SERVICE FITTED LHS MIRROR LOWER COVER ASSY SUNVISOR FITTED ALUMINIZE PLATES OVER CRACKS IN THE CENTRE OF THE VISOR TO STOP THEM SPREADING TAPED OFF SUNVISOR IN PREPARATION FOR SPRAY PAINTING ALLOY REPAIR ONCE SPRAYED REFIT SUNVISOR TO VEHICLE ALL OK	

51049	07/12/2020	184095	FOLLOW UP SERVICE AFTER ENGINE	Invoice
DATE WORK CARRIED OUT: 19/11/2020 – 24/11/2020 WORK CARRIED OUT: CARRIED OUT FOLLOW UP A SERVICE AFTER ENGINE REPAIRS PULLED OFF WINDSCREEN VISOR TO REPAIR REPLACED BROKEN LHS MIRROR REPLACED OIL FILTER AND ENGINE OIL DEFECTS NOTED <ul style="list-style-type: none">- OIL LEAK FROM POWERSTEERING PUMP MONITOR- AIR TANKS WERE FULL OF WATER/OIL- FRONT DRIVE AXLE UPPER SWAY BAR BUSHES WORN- SMALL PLAY IN DRAGLINK ROD ENDS- CRACK IN OUTER CHASSIS RH OF TURNTABLE BASE PLATE- TEFLON PADS ON TURNTABLE NEEDS REPLACING U/S				

50989	27/11/2020	0	CHASSIS RAIL	Invoice
DATE WORK CARRIED OUT: 27/11/2020 WORK CARRIED OUT: MOVED TRUCK INTO THE WASH BAY WASHED CHASSIS UNBOLTED AND REMOVED THE TURNTABLE TO INSPECT CRACKED CHASSIS RAILS				

50921	18/11/2020	183217	BREAKDOWN ACACIA RIDGE	Invoice
DATE WORK CARRIED OUT: 18/11/2020 WORK CARRIED OUT: TRAVELED TO BREAKDOWN @ INGRAM ST ACACIA RIDGE FOUND ADBLUE TANK EMPTY TOPPED UP ADBLUE WITH 20L CONNECTED LAPTOP CHECK CODES ERASED FAULT CODES COMMENCE ADBLUE SYSTEM PURGE - OK ENGINE RE-RATE OFF				

Vehicle Details

Registration	332WIF	Next Service	Litres	10
Make	IVECO	Rego Due	Trans	N/A
Model	STRALIS AT	Engine #	Air	Yes
Model Series		VIN	Cyl	6
Model Code		Build Date	Body	PRIMEMOVER
Colour	White	Odometer	Prod	

Invoice No.	Date	Odometer	Description	Type
TRAVELED BACK TO WORKSHOP				

50607	08/10/2020	179348	CARRY OUT B SERVICE	Invoice
--------------	-------------------	---------------	----------------------------	----------------

DATE WORK CARRIED OUT: 02/10/2020 - 08/10/2020

WORK CARRIED OUT:

CARRIED OUT B SERVICE AS PER HVW SERVICE SHEET
CHANGE ADBLUE FILTER
CHANGE FUEL/WATER SEPARATOR FILTER

CLEAN OUT AIR DRYER HOUSING AS IT WAS BLOCKED WITH OIL AND GREASE
REMOVED AND REPLACE LEAKING ABS BRAKE RELAY VALVE, PART IS UNDER 12 MONTHS OLD SO BEING
REPLACED UNDER IVECO WARRANTY.

50326	08/10/2020	179348	ENGINE REPAIRS	Invoice
--------------	-------------------	---------------	-----------------------	----------------

DATE WORKED CARRIED OUT: 21/08/2020 - 8/10/2020

WORK CARRIED OUT:

REMOVE CYLINDER HEAD AND INSPECT PISTONS & LINERS

FOUND EXCESSIVE WEAR ON LINERS
REMOVED SUMP * NO:1 BIG END BEARING FOR SAMPLE
REMOVED ALL PISTONS , RODS AND LINERS.
CLEANED BLOCK THOROUGHLY AND INSTALLED NEW LINERS USING DIAL GAUGE TO ENSURE CORRECT
HEIGHT
FIT NEW PISTONS TO RODS & FIT NEW BEARINGS

FIT RECONDITIONED CYLINDER HEAD AND ALL ASSOCIATED PARTS
SET UP TIMING GEARS AS PER IVECO MANUAL ADJUST VALVE AND INJECTOR PRE LOAD
FIT NEW REAR TIMING BREATHER COVER
FILLED WITH COOLANT AND TEST (RAN ENGINE) - ALL GOOD
BUMPER TO BE FITTED
REPLACE FAULTY GEAR SELECTOR SWITCH
TEST DRIVE VEHICLE AFTER REBUILD AND CHECKED ALL FAULTS
ALL GOOD
MODIFIED BATTERY HOLD DOWN BRACKET TO SUIT NEW BATTERIES
REMOVED ABS VALVE

FIT WIRING TO BUMPER BAR
FIT LH STEP
REPLACED LH STEER MUDGUARD LIGHT
REPLACED RH #1 DIFF MUDGUARD LIGHT

VEHICLE REQUIREMENT-

Vehicle Details

Registration	332WIF	Next Service	Litres	10
Make	IVECO	Rego Due	Trans	N/A
Model	STRALIS AT	Engine #	Air	Yes
Model Series		VIN	Cyl	6
Model Code		Build Date	Body	PRIMEMOVER
Colour	White	Odometer	Prod	

Invoice No.	Date	Odometer	Description	Type
VEHICLE NEED TO BE RETURNED TO THE WORKSHOP @ 5000KMSOR 3 MONTHS FOR OIL & FILTER CHANGE				
50707	08/10/2020	0	REPAIRS	Invoice
DATE WORK CARRIED OUT: 08/10/2020 WORK CARRIED OUT: FITTED WIRING TO BUMPER BAR FITTED LH STEP REPLACED LH STEER MUDGUARD LIGHT REPLACED RH #1 DIFF MUDGUARD LIGHT				
50316	24/08/2020	178713	TURBO	Invoice
DATE WORK CARRIED OUT: WORK CARRIED OUT: CHECKED AND TOPPED UP OIL ZIP TIED ON A/C PIPE THAT WAS RUBBING ON A CLAMP FOUND AN OIL LEAK AROUND THE TURBO. FURTHER ACTION REQUIRED - NEED TO COME INFO FURTHER INSPECTION AND TO BE REPAIRED EXHAUST V-BAND CLAMP WAS BROKEN AT THE TURBO WILL REQUIRE A NEW ONE. - ORDERED				
50249	17/08/2020	178892	DRIVERS WINDOW - RR 106227	Invoice
DATE WORK CARRIED OUT: 17/08/2020 WORK CARRIED OUT: INSPECT DRIVER WINDOW N/W STRIP DOOR CARD AND FOUND BROKEN CLIP THAT HOLD THE WINDOW TO RAIL REPLACED CLIP FIT CLIP AND REASSEMBLE DOOR CARD TESTED - OK RR106227				
50127	24/07/2020	177179	HEAD LIGHT GLOBES	Invoice
DATE WORK CARRIED OUT: 24/07/2020				

Vehicle Details

Registration	332WIF	Next Service	Litres	10
Make	IVECO	Rego Due	Trans	N/A
Model	STRALIS AT	Engine #	Air	Yes
Model Series		VIN	Cyl	6
Model Code		Build Date	Body	PRIMEMOVER
Colour	White	Odometer	Prod	

Invoice No.	Date	Odometer	Description	Type
WORK CARRIED OUT: REPLACED R/H/F HEAD LIGHT GLOBE				
50074	22/07/2020	176371	TOP UP ENGINE OIL	Invoice
DATE WORK CARRIED OUT: 21/07/2020 WORK CARRIED OUT: TOPPED UP ENGINE OIL				
50103	20/07/2020	0	INSPECT TRAILER LIGHT	Invoice
DATE WORK CARRIED OUT: 20/07/2020 WORK CARRIED OUT: INSPECT TRAILER LIGHT FOUND LIGHT LEAD HAD BEEN RUBBING ON THE TAIL SHAFT AND ARCHED OUT TAPED UP BARE WIRES AND TEST - FOUND OK Requirements for next service are - WIRING WILL NEED TO BE REPLACED				
50034	06/07/2020	173970	BRAKE VALVE	Invoice
DATE WORK CARRIED OUT: 06/07/2020 WORK CARRIED OUT: REMOVED & REPLACED REAR BRAKE VALVE MODULE TESTED OPERATION - ALL OK CHECKED FOR AIR LEAK - ALL OK				
50360	01/07/2020		TURBO REPAIRS	Invoice
DATE WORK CARRIED OUT: 03/06/2020 - 29/06/2020 WORK CARRIED OUT: DRAINED COOLANT REMOVED TURBO REMOVED FRONT BUMPER BAR, RADIATOR, INTER COOLER FIT RADIATOR ACCESSORIES CLEANED OUT AIR COMPRESSOR INTAKE MANIFOLDS				

Vehicle Details

Registration	332WIF	Next Service		Litres	10
Make	IVECO	Rego Due		Trans	N/A
Model	STRALIS AT	Engine #	CURSOR 10	Air	Yes
Model Series		VIN	WJMS2NTH40C323326	Cyl	6
Model Code		Build Date	2016	Body	PRIMEMOVER
Colour	White	Odometer	396979	Prod	

Invoice No.	Date	Odometer	Description	Type
FIT BUMPER FILLED WITH COOLANT FIT NEW TURBO CLEANED HOSES AND PIPES REMOVED LHS TOP STEP PLATE REMOVED THE TOP OF THE AIR FILTER HOUSING, INTAKE PIPE CRACKED FIT RADIATOR AND INTER COOLER AS AN ASSEMBLY FIT TURBO OUTLET & CLAMP SECURED THE PIPE TO ENGINE				