



Vehicle History Summary

Fleet #	
Registration	
Make	Shepherd
Model	BTRI-350T
VIN / Chassis #	6V9T25STEP075002
Build Date	2023

Date	Reading / Units	Type / Repairer Notes	Repairer
20/01/2026		B - 50K S-2036 Conduct a full trailer service in accordance with the attached Blue Collar Diesel service sheet, ensuring all maintenance, inspection, and safety requirements are met. This includes a comprehensive assessment of the braking system, suspension, electrical and lighting components, tires, and overall structural integrity as outlined in the service sheet. Identify and address any issues, perform necessary adjustments or repairs, and document all findings to maintain compliance with operational and safety standards. Repairs carried out Brake relined position 1, 2, 3 and 6 due to being well below wear limit NOTE: Wheel Bearing Grease Excessively worn suggest repack at next available time Rego - YN93RA Kilometers - No Hubbo Conduct a full trailer service in accordance with the attached Blue Collar Diesel service sheet, ensuring all maintenance, inspection, and safety requirements are met. This includes a comprehensive assessment of the braking system, suspension, electrical and lighting components, tires, and overall structural integrity as outlined in the service sheet. Identify and address any issues, perform necessary adjustments or repairs, and document all findings to maintain compliance with operational and safety standards. Repairs carried out Position 4 brake had to be relined due to brakes locking on excessive heat on drum, booster had Excessively play in back end of booster, when attempting to back off slack adjuster it wouldn't allow me to back off had to be removed and replaced Replaced 1 x Spring brake Valve 1 x 2 way Relay valve due to brakes coming on while driving causing set to lock up Replaced 2 x height control valves due to on air supply ride height valve exhaust air continuously	Blue Collar Diesel
03/10/2025		tyres R-3521 fitted 2nd hand trailer tyres	Internal Workshop
13/09/2025	366,213 kms	brake R-3565 put new brake shoes for drums	Internal Workshop
30/06/2025	332,481 kms	Trailer Tyre T-500 Removed wheels, stripped and fit runout. Re-fit wheels and torqued wheel nuts to specification.	Internal Workshop

Signed: _____
Name: _____
Date: _____