

Plant Service Checklist

Benjamin Bentley
Created Fri, 29 Aug 2025, 8:40 AM (UTC+10:30)

Date: Fri, 29 Aug 2025

Technician: Kaleb O'Brien

Plant: LFC 303 - 236D3 CAT Skid Steer

hrs:	1736
------	------

1.0 - SERVICE CHECKLIST

Type of service required: Tyred Plant

Action	Compliant ?	Comments
Check Daily Plant Inspections for faults	N/A	
Check inside cabin for seatbelt, cleanliness and damage	YES	
Check operation of air conditioning, UHF and horn	YES	
Check operation and attachment of all lights	NO	
Check operation of wipers and washers (and top up fluid)	YES	
Inspect condition of plant numbers	YES	
Check condition of Trimble plugs and leads	N/A	
Check operation of reversing beeper	YES	
Check all glass and mirrors for damage and attachment	YES	
Lubricate all hinges and latches	YES	
Check operation and condition of E-Stops	YES	
Change / clean cab air filters (fresh and recirculated)	YES	replaced
Check movement in all pins and ball joints	YES	
Check circle gear for excess movement	N/A	
Change / clean engine air filters (inner, outer)	YES	replaced
Check battery level and condition	YES	
Check condition of cutting edge and ripper boots	N/A	bucket blade was ok
Check fan and belt condition	YES	
Replace fuel filters	YES	
Replace fuel water separator	N/A	

Action	Compliant ?	Comments
Check grease gun is in tool box with a spare cartridge and rags	N/A	
Grease machine (pins, ball joints, circle)	YES	
Hydraulic filter changed every 500 hours	YES	
Hydraulic oil level inspected and sampled	YES	topped up hydraulic oil
Check hydraulic hoses for cracks, rubbing and damage	YES	
Check all cylinders for leaks	YES	
Check hydraulic pump mount and condition	YES	
Engine oil sampled and changed	YES	
Engine oil filters changed	YES	
Inspect coolant level and quality (top up if required)	YES	
Inspect radiator, header tank and overflow bottle	YES	
Check condition of engine mounts	YES	
Check tyres for wear and damage	YES	
Check roller drum mounts	N/A	
Check / replace tandem chain box oil	N/A	
Replace service sticker	YES	

Filters Used

Brand	Parts No.	Quantity	Comments

Filters Required

Brand	Parts No.	Quantity	Comments

2.0 - GPS MONITORING DEVICE

GPS monitoring device fitted?		Yes
Is the GPS monitoring device operational?	YES	

3.0 - COMMENTS

Comments:	RHR stop/tail light not working - diagnosed to be a blown globe and replaced it. all lights now working as intended.
-----------	--

4.0 - PHOTOS

No.	Photo	Comments

5.0 - ADDITIONAL WORK

Is additional work required for the item of mobile plant?

NO

6.0 - SIGN OFF

Technician:

Maintenance Manager:

Benjamin Bentley

Benjamin Bentley, Tue, 23 Sep 2025, 6:14 am

Form Template Revision No.: 05