



Vehicle Standards and Inspection

Semi-Trailer Inspection Certificate

This Certificate is issued under the authority of the Province of Saskatchewan

Decal # P281439

Station #: [REDACTED]

Station Name: [REDACTED]

Technician #: [REDACTED]

Technician Name: [REDACTED]

Signing Officer #: [REDACTED]

Signing Officer Name: [REDACTED]

Customer Details:

Name: [REDACTED]

Address: [REDACTED]

Inspection Completed Date: 08Apr2026

Inspection Expiry Date: 30Apr2027

Vehicle Details:

VIN: 1TDH48030RB184244

Hubometer Reading:

Year: 2024

Vehicle Make/Model: TIMPTE TRAILER/TRAILER

Plate: [REDACTED]

Jurisdiction: Saskatchewan

Unit: [REDACTED]

Message(s): VIN has been validated.

This certificate does not warranty or guarantee the condition of this vehicle's components and systems for any period of time.



Vehicle Standards and Inspection

Semi-Trailer Record of Inspection

The Record of Inspection must be given to the customer regardless of whether the vehicle passes or fails.

Station #: [REDACTED]

Station Name: [REDACTED]

Technician #: [REDACTED]

Technician Name: [REDACTED]

Signing Officer #: [REDACTED]

Signing Officer Name: [REDACTED]

Customer Details:

Name: [REDACTED]

Address: [REDACTED]

Vehicle Details:

VIN: 1TDH48030RB184244

Hubometer Reading:

Year: 2024

Vehicle Make/Model: TIMPTE TRAILER TRAILER

Inspection Details:

Pass	Rejected	Corrected	Req Attn	DRIVERS COMPARTMENT	Comments
x				Vehicle Identification (5)	
x				Fire Extinguisher (5)	
x				Auxiliary Controls/Equip (5)	

Pass	Rejected	Corrected	Req Attn	BODY EXTERIOR	Comments
x				Lamps (6)	
x				Reflex Reflectors (6)	
x				Retro Reflective Markings (6)	
x				Trailer Hitch (10)	
x				Attached Equipment (8)	
x				Cargo Bodies/Vessels (8)	
x				Mud Flaps/Fenders (8)	
x				Landing Gear (8)	
x				Rear Impact Guard (8)	
x				Trailer Power Cord (7)	

Pass	Rejected	Corrected	Req Attn	ENGINE COMPARTMENT	Comments
x				Fuel System (1)	
x				Battery/Wiring Condition (7)	

Pass	Rejected	Corrected	Req Attn	CHASSIS	Comments
x				Hyd Brake System/Components (3.1)	
x				Air Brake System/Components (3.2)	
x				Elec Brake System/Components (3.1)	
x				Wheel Bearings (9)	
x				Tires/Wheels (9)	
x				Self-Steering Axle (2&4)	
x				Frame/Crossmembers/Mounts (8)	
x				Suspension/Axles (2)	
x				Exhaust/Emission System (1)	
x				Sliding Axle Assembly (if equipped) (8)	

Brake/Tire Measurements

Axle 1-Pass

Wheel1 : Tire Tread Depth: 7/32 in

Brake(1): No Brake

N/A

Wheel2-On : Tire Tread Depth: 7/32 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 3/4 in • Cam Rotation: 48 degrees • Brake Stroke: 1.5 in

Wheel3-On : Tire Tread Depth: 10/32 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 3/4 in • Cam Rotation: 48 degrees • Brake Stroke: 1.5 in

Wheel4 : Tire Tread Depth: 10/32 in

Brake(1): No Brake

N/A

Axle 2-Pass

Wheel1 : Tire Tread Depth: 8/32 in

Brake(1): No Brake

N/A

Wheel2-On : Tire Tread Depth: 8/32 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 3/4 in • Cam Rotation: 50 degrees • Brake Stroke: 1.5 in

Wheel3-On : Tire Tread Depth: 18/32 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 3/4 in • Cam Rotation: 52 degrees • Brake Stroke: 1.5 in

Wheel4 : Tire Tread Depth: 18/32 in

Brake(1): No Brake

N/A

Axle 3-Pass

Wheel1 : Tire Tread Depth: 12/32 in

Brake(1): No Brake

N/A

Wheel2-On : Tire Tread Depth: 12/32 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 3/4 in • Cam Rotation: 52 degrees • Brake Stroke: 1.5 in

Wheel3-On : Tire Tread Depth: 12/32 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 3/4 in • Cam Rotation: 50 degrees • Brake Stroke: 1.5 in

Wheel4 : Tire Tread Depth: 12/32 in

Brake(1): No Brake

N/A

PASS - vehicle passes inspection

Decal # P281439

Inspection Completed Date: 08Apr2026