

03998419

PERIODIC MANDATORY VEHICLE INSPECTION CERTIFICATE

Manitoba

Vehicle Standards and Inspection
Box 45064 Regent Postal Outlet
Winnipeg, MB, R2C 5C7
1-204-985-0920

2026646 A01-13
Manitoba
A983156

Date Inspection Started: 03 DAY, 11 MO, 25 YR.
Date Inspection Completed: 01 DAY, 11 MO, 25 YR.
Inspection Expiry Date: 30 DAY, 11 MO, 26 YR.

Station Number: A1880
Station Name: DOLA Bros Trucking LTD
City: [blank]
Mechanic Number: M3466
Mechanic Signature: [Signature]
Station Phone Number: 886-3000

Vehicle Owner: BOCHURKA Bros 1979 LTD
City: LpG BEACH
Province: MB
Postal Code: R0C360
Phone: [blank]

Address: [blank]

License Number: S69082
Prov: MB
NSC #: [blank]
Odometer Reading: [blank]
Odom. Type: [blank] km [blank] mi

Vehicle Identification Number: 4LFES1302173528601
Make: FONTANA
Model: 2007
Year: 2007
Unit #: [blank]

☒ Pass/Safe Vehicle
☐ Fail/Unsafe Vehicle
☐ Fail/Hazardous

☒ Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

Truck GVWR KGS Truck Tractor Trailer Semi-Trailer Bus School Bus Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section																																																																							
X		Section 1 - Power Train: Defects (if any)																																																																							
X		Section 2 Suspension: Defects (if any) X - SE air line leaky at R Front																																																																							
X		Section 3 - Brake Systems: Defects (if any) 3H 3A Circle Brake Type																																																																							
		Brake Inspection Type: A B C D E Circle appropriate Letter for Internal Brake Component Inspection																																																																							
		<table border="1"><thead><tr><th rowspan="2">Axle</th><th colspan="2">Lining</th><th colspan="2">Drum/Rotor</th><th colspan="2">Stroke</th></tr><tr><th>L</th><th>R</th><th>L</th><th>R</th><th>L</th><th>R</th></tr></thead><tbody><tr><td>1</td><td>7/8</td><td>7/8</td><td>16.565</td><td>16.560</td><td>28</td><td>29</td></tr><tr><td>2</td><td>5/8</td><td>5/8</td><td>16.562</td><td>16.590</td><td>29</td><td>29</td></tr><tr><td>3</td><td>5/8</td><td>5/8</td><td>16.571</td><td>16.569</td><td>28</td><td>28</td></tr><tr><td>4</td><td></td><td></td><td></td><td></td><td></td><td></td></tr><tr><td>5</td><td></td><td></td><td></td><td></td><td></td><td></td></tr></tbody></table>	Axle	Lining		Drum/Rotor		Stroke		L	R	L	R	L	R	1	7/8	7/8	16.565	16.560	28	29	2	5/8	5/8	16.562	16.590	29	29	3	5/8	5/8	16.571	16.569	28	28	4							5																													
Axle	Lining			Drum/Rotor		Stroke																																																																			
	L	R	L	R	L	R																																																																			
1	7/8	7/8	16.565	16.560	28	29																																																																			
2	5/8	5/8	16.562	16.590	29	29																																																																			
3	5/8	5/8	16.571	16.569	28	28																																																																			
4																																																																									
5																																																																									
		Final Measurement																																																																							
X		Section 4 - Steering: Defects (if any)																																																																							
X		Section 5 - Instruments & Auxiliary Equipment: Defects (if any)																																																																							
X	X	Section 6 - Lamps: Defects (if any) X - (H) ALL Marker lights new																																																																							
X		Section 7 - Electrical System: Defects (if any)																																																																							
X		Section 8 - Body: Defects (if any)																																																																							
X		Section 9 - Tire & Wheel: Defects (if any)																																																																							
		<table border="1"><thead><tr><th rowspan="2">Axle</th><th colspan="4">Tread Depth</th><th colspan="4">Air Pressure</th></tr><tr><th colspan="2">Initial</th><th colspan="2">Corrected</th><th colspan="2">Initial</th><th colspan="2">Corrected</th></tr><tr><th></th><th>L</th><th>R</th><th>L</th><th>R</th><th>L</th><th>R</th><th>L</th><th>R</th></tr></thead><tbody><tr><td>1</td><td>10</td><td>7</td><td>10</td><td>10</td><td>100</td><td>100</td><td>100</td><td>100</td></tr><tr><td>2</td><td>8</td><td>6</td><td>13</td><td>13</td><td>100</td><td>100</td><td>100</td><td>100</td></tr><tr><td>3</td><td>6</td><td>7</td><td>12</td><td>12</td><td>100</td><td>100</td><td>100</td><td>100</td></tr><tr><td>4</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr><tr><td>5</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr></tbody></table>	Axle	Tread Depth				Air Pressure				Initial		Corrected		Initial		Corrected			L	R	L	R	L	R	L	R	1	10	7	10	10	100	100	100	100	2	8	6	13	13	100	100	100	100	3	6	7	12	12	100	100	100	100	4									5								
Axle	Tread Depth				Air Pressure																																																																				
	Initial		Corrected		Initial		Corrected																																																																		
	L	R	L	R	L	R	L	R																																																																	
1	10	7	10	10	100	100	100	100																																																																	
2	8	6	13	13	100	100	100	100																																																																	
3	6	7	12	12	100	100	100	100																																																																	
4																																																																									
5																																																																									
X		Section 10 - Coupling Devices: Defects (if any)																																																																							

- THIS INSPECTION IS NOT A WARRANTY -
This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: [blank] Date: [blank]

Signature: [blank]

2025 | 2026 | 2027

Manitoba

SAFETY
INSPECTED

A983156

INSPECTION
DE SÉCURITÉ

EXPIRES ON LAST DAY OF MONTH SHOWN ON CERTIFICATE.
EXPIRE LE DERNIER JOUR DU MOIS INDIQUÉ SUR LE CERTIFICAT.

1311-21-B8 MG-3303 (R-11/19)

JAN/JANV.

JULY/JUILL.

FEB/FÉVR.

AUG/AOÛT

MAR/MARS

SEPT/SEPT.

APR/AVR.

OCT/OCT.

MAY/MAI

NOV/NOV.

JUNE/JUIN

DEC/DÉC.