



Woolies Diesel Repairs

ABN: 35335445002

Mobile: 0438768466

Email: wooliesdiesel@gmail.com

Address: 750 Zillmere Rd Aspley, 4034

Service Report Prepared For:

INVOICE NUMBER:	433-23
DATE OF REPAIR	31-7-23
MACHINE DETAIL	Kenworth K200 XB15GU
ENGINE HOURS/ KMS	
SERVICE REQUEST	Carry out repairs requested by customer

SERVICE NOTES	- Travel to job - Customer complained of brake pedal not working correctly, remove floor mats and clean dirt and mud from around pedal assembly and refit floor mats - Remove and replace 4 air bags on rear 2 axles on truck - Remove and replace right hand side cab shock absorber - Replace 2nd axle right side shock absorber - Adjust brakes - Fit spot lights to bulbar - Replace faulty window regulator on passenger side - Repair wiring to light in mirror on drivers side - Replace marker light on right side of rear of truck - Wire up 175amp Anderson plug through suzi coil for trailer power - -
WORK REQUIRED	