

PARTS REQUISITION FORM GP 4108

Requested By: Charles		Date: Marc	h22-24
Unit #: RT-001	Hours / Km:		
Model #: DA30-5USIO - DOOSAN	Serial #: DINO DA30EJO	741257	
Notes: FOR Inspection Only and	Dussan locktruck	۵	
	Inv	1 w360	85-1
Rantes - Timber			
Norrally Repair on Tueso - 0	Verall Inspection on	RT-001	8
Quantity Descript		Unit Price	Total
Inspection on Ro	aktruce RT-001		
As per Levinis.			
Notes:			
Rebillable: 🗆 Yes 🗆 No	SUB TOTAL	4	70648

Work Order

Rentco Equipment Ltd.

9601 117 St

Grande Prairie, Alberta T8W 0C7

780-539-7860 Phone 780-532-2230 Fax

Status: Closed

Work Order #: w36285-1 Invoice Date: Fri 6/14/2024

Expected Date: Fri 4/ 5/2024 5:00PM

Operator: Timber H

www.rentcoequipment.com

Customer #: 54061

BIG STICK RENTALS

Phone 780-830-4115

9619 116 Street

Grande Prairie, AB T8V 5W3

Job Descr: TURBO CODES

PO#: 4108

Job No. RT-001

{Complaint}

Unit has tore off mud flap, hood doesn't latch and leaking line at L/H steer cylinder

NOTE-QUOTED COMPLETE SERVICE TO CUSTOMER-SERVICE DENIED CUSTOMER WILL COMPLETE SERVICE

NOTE-PARTS ORDERED FOR REAR DIFF LOCK WILL BE UNDER WARRANTY PARTS COMING FROM KOREA WILL CONTACT CUSTOMER ONCE PARTS ARRIVE

{Correction}

March 20 2024

Bring unit into shop

Hook up to engine and check codes

2 active codes, 1 for intake pressure below normal and 1 for turbo unable to calibrate

Test turbo actuator and is above 120% load in all positions, turbo vanes seized

Codes for grease system no pressure

Remove grease lines from rear block and bleed out as reservoir is full

Mar 28 2024

Bring unit back into shop

Drain coolant

Remove intake, oil lines, coolant line from turbo

Remove turbo, found turbo is actually seized and missing a couple turbine vanes

Swap fittings to new turbo

Lift cab and pull inlet of DOC and remove parts of turbo in DOC housing, no damage to DOC

Reassemble exhaust and bolt cab back down

Install new turbo and hook up coolant and oil lines, reinstall intake

Turbo replacement on warranty

{Other Comments}

*ITEM: ROCK TRUCK

*MODEL: DA30

*HOURS:3457.6

*SN#: DIN0DA30EJ0741257

*MFG: DOOSAN

*CUST PH #: KEVIN

*CUSTOMER CONCERN: CODES FOR TURBO

Qty	Key	Items	Ser#	Status	Returned Date	Price
1	WO54061-007	BIG STICK-ROCK TRUCK	DIN0DA30EJ0741257	Repaired		\$0.00
2	BRAD-REG Begin at:	LABOUR, MECHANICAL Wed 3/20/2024 9:00:00AM		Labor		\$300.00
1	2003505-1	FUEL FILTER KIT		Sold		\$233.57
1	MX506980-1	FILTER, OUTER AIR		Sold		\$318.00

Thank you for your Business



Work Order #: w36285 BIG STICK RENTALS Page 2 of 2

72							
-1	TO SECOND PROPERTY OF THE PROP						
- 5	t e e e e e e e e e e e e e e e e e e e		(The state of the s	Section and additional contraction and additional additional and additional addit	
į	Transmi		Sales:			V .	
Ì			COE4 57				
1	1		\$851.57				
ſ	Control of the second	- 1987 on Barrier - 1990 (1987) (1982) (1982) (1982) ETTE TO BEST BASED on 1984 (1984) AND AND SERVICE OF THE PARTY OF THE	The China is the China demonstrate about the SET CHINADERS SEEMS TO THE CONTRACT AND ADDRESS SEEMS SEEMS AND ADDRESS SEEMS SEEMS AND ADDRESS SEEMS SEE	Committee and the region of the committee of the committe	production of the state of the contraction of the state of the contraction of the state of the s	The state of the second control of the state of the second control of the state of the second control of the s	
	Subtotal:	Enviro Fee:	GST:	Total:	Paid:	Amount Due:	
1	1				i alai	Amount buc.	
ı	\$851.57	\$11.74	\$43.17	£006.40	00.00		
ł	Ψ001.01	Ψ11.17	φ43.1 <i>1</i>	\$906.48	\$0.00	\$906.48	

Signature:

BIG STICK RENTALS

GST: R104479027 PST: PST-1000-8940