Allclass

Postville Pty Ltd T/As Allclass ABN 23 057 201 626

Address: 16 Parade Ground Place, Wacol QLD 4076
Postal: PO Box 347 Mt Ommaney QLD 4074
Phone: 07 3279 3300
Email: admin@allclass.com.au
Web: www.allclass.com.au

SERVICE TAX INVOICE

Customer Account No.:

Deliver To:

Document No.:	***01 - 2332706***
Document Date:	21/02/2025
Repair Order No.:	581500
Rego No.:	9222C0
Make:	Kubota
Model:	KX080-3SGLA
Serial No.:	28371
Stock No.:	
Hrs/Bales	2219
Delivery Date:	20/06/2022
Warranty Expiry:	20/06/2022
P/Order No.:	
Page:	1 of 2
Payment Type/Terms:	Account - 30 Days EOM

KX080-3S1000

Inv. Hrs: 4.00

$580.00

Carry out 2000 hr Service
Change engine oil & filter
Change fuel filter
Clean fuel/water seperator
Change fuel/water seperator o-ring
Change final drive oils
Change inner & outer air filters
Change fan belt
Change air con belt
Change air con filters
Change coolant
Change hydraulic oil
Change hydraulic filters
Change hyd return tank o-ring
Blow out radiator
Jack up machine
Check tracks & rollers
Adjust track tensions
Check over machine
Greased machine
Next service is due at 2250 hrs

Part Number	Part Description	Quantity	Nett Value	Total Cost
1G772-97010	V-BELT	1.00	43.86	43.86
3A111-19130	ELEMENT (INNER)	1.00	78.37	78.37
859800-26110	ELEMENT OUTER AIR	1.00	57.61	57.61
CON	CONSUMABLES	1.00	20.00	20.00
COOLANT	XEREX G05 RTU VAL-940-28	10.50	10.00	105.00
ENVIRO	ENVIRONMENTAL LEVY	1.00	17.00	17.00

Allclass

Postville Pty Ltd T/As Allclass ABN 23 057 201 626

Address: 16 Parade Ground Place, Wacol QLD 4076
Postal: PO Box 347 Mt Ommaney QLD 4074
Phone: 07 3279 3300
Email: admin@allclass.com.au
Web: www.allclass.com.au

SERVICE TAX INVOICE

Customer Account No.:

Deliver To:

Document No.:	***01 - 2332706***
Document Date:	21/02/2025
Repair Order No.:	581500
Rego No.:	9222C0
Make:	Kubota
Model:	KX080-3SGLA
Serial No.:	28371
Stock No.:	
Hrs/Bales	2219
Delivery Date:	20/06/2022
Warranty Expiry:	20/06/2022
P/Order No.:	
Page:	2 of 2
Payment Type/Terms:	Account - 30 Days EOM

HH166-43560	"""ELEMENT-FUEL FILTER"""	1.00	44.17	44.17	
HH1C0-32430	CARTRIDGE (OIL FILTER)	1.00	25.17	25.17	
OIL1	HYDRAULIC OIL 68	75.00	7.00	525.00	
OIL2A	CJ-4 DIESELOIL VAL-	11.00	9.50	104.50	
OIL3	1376IBC 80/90 GEAR OIL	3.00	10.38	31.14	
R1411-64930	ELEMENT	1.00	106.28	106.28	
RD451-51930	O RING """ASSY-	1.00	7.63	7.63	
RD809-62130	FILTER(SUCTION)""" O RING	1.00	292.22	292.22	
RD809-62150	"""CARTRIDGE-FILTER""" V-	1.00	22.40	22.40	
RD809-62240	BELT	1.00	261.38	261.38	
RD819-42790	FILTER	1.00	74.67	74.67	
T0270-67060		1.00	124.35	124.35	
		18.00			***$1,940.75***

TRAVEL — Inv. Hrs: 0.50
Travel to site on 20/2/25 — ***$72.50***
973 Fairfield Road, Yerongpilly

#REPAIR01 — Inv. Hrs: 0.00
Fit new mirror
Quote for boom cylinder guard as old one wont fit

Part Description	Quantity	Nett Value	Total Cost
"""CAP-CYLINDER COVER"""	2.00	6.24	12.48
MIRROR- ASSY (SR1000)	1.00	255.78	255.78
	2.00		***$268.26***

Part Number
RD809-67550
RD83941390

Sub Total for All:	$2,861.51
Rounding:	$0.00
GST:	$286.15
Total:	$3,147.66

Bank Account Details for Direct Payments: Advisor: LANCE BIBBIE
Bank: Westpac Branch: Mt Ommaney
BSB: 034108 Account No.: 751696 Account Name: Postville Pty Ltd T/A Allclass
Please reference this bank deposit by Invoice Number

Our Standard Terms of Business apply.Please refer to our standard terms of business which are available upon request and/or on allclass.com.au. Without limiting our standard terms of business, title in goods sold by us remains vested with us until such goods have been paid for in full in cleared funds. Please also note: (1) A person should not use, or allow another person to use, plant supplied by Allclass: (a) prior to receiving and having understood the applicable operator manuals, and any other information about how to safely and correctly use the plant; (b) if they are not suitably competent to use the plant; (c) without ensuring a thorough risk assessment has been carried out which has regard to all aspects of the plant including any modifications made to the plant; (d) without ensuring they are familiar with all modifications made to the plant; (e) if the plant has a fault and/or defect; and (f) in a manner that is not in accordance with applicable laws and the applicable manufacturer requirements; and (2) Used/ second-hand plant supplied by Allclass is supplied in an “as is condition".