

Vehicle History Summary

Fleet #	XW32FU	
Registration	XW32FU	
Make	Kenworth	
Model	K200	
VIN / Chassis #	6F500000DA449396	
Build Date	2013	

1			
Date	Reading / Units	Type / Repairer Notes	Repairer
06/02/2025	163,871 kms	Electrical R-1601	Daimler Trucks Wagga
		REPLACED TRAILER 7 PIN Fit new ele	ectrical suzi lead supply an adapter for the plug.
14/01/2025	153,695 kms	Air Conditioner R-1567	Bennys Diesel services & repairs
		there was no gas in the system. Perform	worth Model: K200 KMs: 153,095 Labour to diagnose & repair AC. Check & found ned a pressure test, and located a leak at the liquid line fitting(very hard to follow up pressure test now ok, vac ok, recharge & overall test now ok. Including
05/12/2024		Suspension R-1471	Bennys Diesel services & repairs
03/12/2024		Air intake R-1502	Bennys Diesel services & repairs
		Loosen brackets on cab, panel beat bac into plate bolt air intake pipe back on, d	ck off cab flat, pul interior piece back, make up aluminium plate and tap threads rop truck and trailer back at yard
25/10/2024	150,095 kms	B S-629	Bennys Diesel services & repairs
		dervice and check over vehicle, replace engine oil and filter, fuel filters. Inspected air filter change if required. Check all iff oils and gear box oil. Check and top up washer fluid. Check all steering, suspension, brakes, cab chassis and drive the components and adjust when requited. Grease king pins, shackle pins, drive line and all moving greaseable parts including auxiliary body parts. Test drive and clean up. Fit service sticker. Replace headlight globe All air bags perished and cracked Needs all rear shock absorber rubbers Rocker cover leaking Power steering hose leaking Turntable jaws from Rear cab mounts worn Rear brakes at 12mm Front brakes at 7mm (needs front brakes be for next service) Steer frees at 10mm Drive tyres at 16mm Jack up front axel, remove wheels, remove drums. Remove brake shoes. Filter new rake shoes and drums, wheels on, tension wheels, adjust brakes. Jack cab up, unbolt rh cab mount, replace with new ne, unbolt/cut cab latch off, use oxy to get seized bolt out of cab latch, unbolt Lh cab mount, replace with new one, bolt ab latch on with new bolt, test drive, cleanup, do paper work	
21/10/2024		Wheel studs R-1430	Bennys Diesel services & repairs
		Replace all 10	
10/10/2024		Engine R-1397	Bennys Diesel services & repairs
		Diagnose Fault and Repair	
30/09/2024	138,148 kms	Wheel studs R-1366	Bennys Diesel services & repairs
		Replaced	
04/09/2024	132,749 kms	Air leaks R-1339	Bradys truck and automotive
Signed:			
Name:			
Date:			

Page 1 of 1 Thursday 31 July 2025 www.gearbox.com.au