



## Vehicle History Summary

Fleet #	XB23NL
Registration	XB23NL
Make	Kenworth
Model	K200
VIN / Chassis #	6F5000000MA475986
Build Date	2021

Date	Reading / Units	Type / Repairer Notes	Repairer
25/06/2025		<b>Rotate Tyres</b> T-561 STRIP & RE-FIT TRUCK STEEL/ALLOY 4 FITTING TRUCK 4	Goodyear Autocare Leongatha
02/05/2025	548,924 kms	<b>Alternator</b> R-1727  Purchase Order (1727) Vehicle Details Vehicle - Kenworth K200 Rego No - XB-23NL Kms - 548924 Serial No - 5986 - Assessed alternator charging fault, found alternator or to be faulty, supplied and installed new High output 190A alternator - Assessed Icepack fault, found system to be low on gas, degassed system and pressure tested system, couldn't locate any leaks, regassed icepack and found condenser fan not to be coming in due to faulty fan, ordered in new fan. All tested fine	Amos Auto Electrical (P)
29/04/2025	547,648 kms 7,289 hrs	<b>B S-846</b>  Air cleaner to be replaced AF1969M. Rear suspension lower torque rod bushes worn. Rear shocker bushes worn. Front engine mounts worn. Clutch grease line in bell housing split. Intake pipe mounting rubbers worn. RHS driving light takes a while for all LEDs to work. Front mudflaps cracked. Batteries go flat after 24 hours, battery load test ok, alternator 14+ volts. At night alternator light sometimes comes on momentarily, charge voltage approx 11v - suggest replacing alternator. Ice pack to be regassed.	Moama Workshop
20/02/2025		<b>New</b> T-445	Bridgestone Albury
12/02/2025	515,000 kms	<b>B S-746</b>  Dip stick Needs replacing , ( on order )	Moama Workshop
11/12/2024	480,103 kms	<b>B S-675</b>  B Service Service and check over vehicle, replace engine oil and filter, fuel filters. Inspected air filter change if required. Check all diff oils and gear box oil. Check and top up washer fluid. Check all steering, suspension, brakes , cab chassis and drive line components and adjust when requited. Grease king pins, shackle pins, drive line and all moving greaseable parts including auxiliary body parts. Test drive and clean up. Fit service sticker. Drop back at yard.	Bennys Diesel services & repairs
03/12/2024		<b>Dovetail</b> R-1496  Remove dovetail , lower intake and exhaust *Remove dove tail and seal and re-fit bolts to roof, remove and cut down stack and exhaust pipe. *Wash roof, replace air filter and clean out housing.	AJT Truck Repairs (P)
22/11/2024		<b>External Vehicle wash</b> O-60	Tranzwash
18/10/2024	450,197 kms	<b>B S-612</b>	AJT Truck Repairs (P)
14/10/2024		<b>External Vehicle wash</b> O-43	Tranzwash
26/08/2024	421,613 kms	<b>Electrical</b> R-1345	Amos Auto Electrical (P)
12/08/2024	418,256 kms	<b>C S-952</b>	
12/08/2024		<b>NHVAS and WAHVA Annual Inspection</b> I-66	

Signed: \_\_\_\_\_

Name: \_\_\_\_\_

Date: \_\_\_\_\_