



23 Boolcarrol Rd Wee Waa NSW 2388
 Ph. (02) 6795 8000
 Air Conditioning Licence AU35668

PO Box 5485 Wagga Wagga NSW 2650
 Email: accounts@hutcheonandpearce.com.au
 www.hutcheonandpearce.com.au
 ABN 68 169 674 033 ACN 169 674 033

*** DOCUMENT COPY ***



SERVICE TAX INVOICE

| | |
|----------------------|-------------------|
| Document No.: | 3383141 |
| Document Date: | 19/12/2022 |
| Repair Order No.: | 358617 |
| Rego No.: | A200381 |
| Make/Model: | JOHN DEERE 8R 230 |
| Vehicle ID No.: | 1RW8230DCNA200381 |
| Fleet No.: | 8R 230 #6 |
| Odometer: | 201 |
| Delivery Date: | 08/06/2022 |
| Invoice To: | |
| Customer ABN: | |
| Tax Exempt No.: | |
| P/Order No.: | |
| Page: | 1 of 3 |

8R First Service Labour + Travel Only

1. Cab Inspection
 - : Check Light operation and condition
 - : Check Wiper operation and condition
 - : Check Stereo operation
 - : Check transmission linkages and controls
 - : Check PTO operation
 - : Check loader operation (if applicable)
 - : Clean windscreen and wipe out cab floor
 - : Check heater and A/C operation
 - : Reset service reminder
2. Maintenance
 - : Change engine oil and filter
 - : Change primary and final fuel filter
 - : Change transmission/hydraulic filters and top up oil
 - : Inspect engine air filter (s)
 - : Inspect cab air and recirculation filters
 - : Check hitch components for wear and lubricate
 - : Lubricate steering and suspension components
 - : Clean suspension compressor & filter & air bag. (8RT)
 - : Lubricate Track tension cylinders (8RT)
3. Drawbar & 3PL & PTO
 - : Test operation (external controls)
 - : Check for leaks
 - : Check condition of linkages
 - : Check shaft condition
 - : Check guards are in place
4. Front & Rear Axle
 - : Test drive and test operation of suspension and steering
 - : Check suspension and steering components damaged e.g Pivot bushes, suspension cylinders ball joint boots
 - : Check for leaks
 - : Check tyre pressures. (check pressures are set evenly)
 - : Check rim and weight condition (were fitted)

LABOUR
\$1,050.00

www.hutcheonandpearce.com.au



23 Boolcarrol Rd Wee Waa NSW 2388
 Ph. (02) 6795 8000
 Air Conditioning Licence AU35668

PO Box 5485 Wagga Wagga NSW 2650
 Email: accounts@hutcheonandpearce.com.au
 www.hutcheonandpearce.com.au
 ABN 68 169 674 033 ACN 169 674 033

*** DOCUMENT COPY ***



SERVICE TAX INVOICE

| | |
|----------------------|-------------------|
| Document No.: | 3383141 |
| Document Date: | 19/12/2022 |
| Repair Order No.: | 358617 |
| Rego No.: | A200381 |
| Make/Model: | JOHN DEERE 8R 230 |
| Vehicle ID No.: | 1RW8230DCNA200381 |
| Fleet No.: | 8R 230 #6 |
| Odometer: | 201 |
| Delivery Date: | 08/06/2022 |
| Invoice To: | |
| Customer ABN: | |
| Tax Exempt No.: | |
| P/Order No.: | |
| Page: | 2 of 3 |

- : Tighten wheel and wheel weight bolts
- 5. Transmission
 - : Test drive and test operation
 - : Check manual brakes.
 - : Check for leaks
 - : Check neutral start system
- 6. Selective Control Valves
 - : Test operation – external and electronically
 - : Check for leaks
 - : Check covers are installed
 - : Check drains aren't blocked and are fitted
 - : Check and empty drain reservoir
- 7. Engine
 - : Check water pump and fan bearing
 - : Check fan belt and pulleys / idler bearings
 - : Check for coolant leaks and condition of hoses
 - : Check for oil and fuel leaks
- 8. Track Machines
 - : Check Track alignment & track wear.
 - : Check Mid-Roller, Drive wheel sleeve, wedges and Idler wheels
 - : Check Track trash build-up
 - : Check Walking beam suspension system (8RT)

Technician Labour Postings

| Technician | Job Description | Type | Clocked In Date | Start Time | Finish Time | Hours Worked | Hours Invoiced |
|------------|-----------------|------|-----------------|------------|-------------|--------------|----------------|
| YOUNGALEX | FIRSTSERV7&8* | S | 15/12/2022 | 10:30:00 | 13:30:00 | 3.000000 | 3.103400 |
| YOUNGALEX | FIRSTSERV7&8* | S | 15/12/2022 | 16:00:00 | 18:30:00 | 2.500000 | 2.586200 |

www.hutcheonandpearce.com.au



23 Boolcarrol Rd Wee Waa NSW 2388
 Ph. (02) 6795 8000
 Air Conditioning Licence AU35668

PO Box 5485 Wagga Wagga NSW 2650
 Email: accounts@hutcheonandpearce.com.au
 www.hutcheonandpearce.com.au
 ABN 68 169 674 033 ACN 169 674 033

*** DOCUMENT COPY ***



SERVICE TAX INVOICE

| | |
|----------------------|-------------------|
| Document No.: | 3383141 |
| Document Date: | 19/12/2022 |
| Repair Order No.: | 358617 |
| Rego No.: | A200381 |
| Make/Model: | JOHN DEERE 8R 230 |
| Vehicle ID No.: | 1RW8230DCNA200381 |
| Fleet No.: | 8R 230 #6 |
| Odometer: | 201 |
| Delivery Date: | 08/06/2022 |
| Invoice To: | |
| Customer ABN: | |
| Tax Exempt No.: | |
| P/Order No.: | |
| Page: | 3 of 3 |

| | | | | | |
|---------------------------|------------|----------|----------|----------|----------|
| YOUNGALEX FIRSTSERV7&8* S | 15/12/2022 | 06:00:00 | 07:30:00 | 1.500000 | 1.551700 |
|---------------------------|------------|----------|----------|----------|----------|

| | |
|---------------------------|------------|
| Sub Total for All: | \$1,050.00 |
| Rounding: | \$0.00 |
| GST: | \$0.00 |
| Total: | \$1,050.00 |

PAYMENT OPTIONS:
 PayID: 68169674033
 Bank Details: WESTPAC WAGGA WAGGA BSB: 032769 A/C No: 624222
 PLEASE QUOTE YOUR HP ACCOUNT NUMBER IN THE REFERENCE

Our goods come with guarantees that cannot be excluded under the Australian Consumer Law. You are entitled to a replacement or refund for a major failure and for compensation for any other reasonably foreseeable loss or damage. You are also entitled to have the goods repaired or replaced if the goods fail to be of acceptable quality and the failure does not amount to a major failure. Payment Terms strictly cash unless terms authorized.

11 Zora Street Warren NSW 2824
Ph. (02) 6847 3522
Air Conditioning Licence AU35668

PO Box 5485 Wagga Wagga NSW 2650
Email: accounts@hutcheonandpearce.com.au
www.hutcheonandpearce.com.au
ABN 68 169 674 033 ACN 169 674 033

*** DOCUMENT COPY ***

SERVICE TAX INVOICE

| | |
|----------------------|-------------------|
| Document No.: | 3600800 |
| Document Date: | 17/04/2024 |
| Repair Order No.: | 405431 |
| Rego No.: | A200381 |
| Make/Model: | JOHN DEERE 8R 230 |
| Vehicle ID No.: | 1RW8230DCNA200381 |
| Fleet No.: | 8R 230 #6 |
| Odometer: | 1463 |
| Delivery Date: | 08/06/2022 |
| Invoice To: | |
| Customer ABN: | |
| Tax Exempt No.: | |
| P/Order No.: | |
| Page: | 1 of 3 |

Service Plan Calculator V2.9

1. Cab Inspection
 - :Check Light operation and condition
 - :Check Wiper operation and condition
 - :Check Stereo operation
 - :Check transmission linkages and controls
 - :Check PTO operation
 - :Check loader operation (if applicable)
 - :Clean windscreen and wipe out cab floor
 - :Check heater and A/C operation
 - :Reset service reminder
2. Maintenance
 - :Change engine oil and filter element
 - :Change primary, final fuel filter & Water separator
 - :Change fuel tank vent filter (s)
 - :Change transmission and hydraulic oil and oil filters
 - :Change front axle and final drive oils
 - :Check air intake system
 - :Inspect engine air, cab air and recirculation filters (s)
 - :Check hitch components for wear and lubricate
 - :Lubricate VARI-COOL fan drive
 - :Lubricate steering and suspension components
 - :Clean hydraulic oil suction screen
 - :Change Differential oil (8RT, 8RX)
 - :Change suspension compressor filter, clean air bag. (8RT)
 - :Lubricate Track tension cylinders (8RT)
 - :Change SCV Pilot (8RX) & Hydraulic Steering filter (8RT)
3. Drawbar & 3PL & PTO
 - :Test operation (external controls) and check for leaks
 - :Check condition of linkages
 - :Check shaft & guard condition
 - :Lubricate draft link support shaft bushing4. Front & Rear Axle
 - :Test drive and test operation of suspension and steering

LABOUR

\$1,733.97

11 Zora Street Warren NSW 2824
Ph. (02) 6847 3522
Air Conditioning Licence AU35668

PO Box 5485 Wagga Wagga NSW 2650
Email: accounts@hutcheonandpearce.com.au
www.hutcheonandpearce.com.au
ABN 68 169 674 033 ACN 169 674 033

*** DOCUMENT COPY ***

SERVICE TAX INVOICE

| | |
|----------------------|-------------------|
| Document No.: | 3600800 |
| Document Date: | 17/04/2024 |
| Repair Order No.: | 405431 |
| Rego No.: | A200381 |
| Make/Model: | JOHN DEERE 8R 230 |
| Vehicle ID No.: | 1RW8230DCNA200381 |
| Fleet No.: | 8R 230 #6 |
| Odometer: | 1463 |
| Delivery Date: | 08/06/2022 |
| Invoice To: | |
| Customer ABN: | |
| Tax Exempt No.: | |
| P/Order No.: | |
| Page: | 2 of 3 |

4. Check suspension and steering components damaged e.g Pivot bushes, suspension cylinders ball joint boots
- :Check for leaks
 - :Check tyre pressures. (check pressures are set evenly)
 - :Check rim and weight condition (were fitted)
 - :Tighten wheel and wheel weight bolts
5. Transmission
- :Test drive and test operation, check for leaks.
 - :Check manual brakes
 - :Check neutral start system
6. Selective Control Valves
- :Test operation – external and electronically and check for leaks
 - :Check covers are installed
 - :Check drains aren't blocked and are fitted
 - :Check and empty drain reservoir
7. Engine
- :Check water pump and fan bearing
 - :Check fan belt and pulleys / idler bearings
 - :Check for coolant leaks and condition of hoses
 - :Check for oil and fuel leaks
 - :Check auxiliary drive belt
8. Track Machines
- :Check Track alignment & track wear.
 - :Check Mid-Roller, Drive wheel sleeve, wedges and Idler wheels
 - :Check Track trash build-up
 - :Check Walking beam suspension system (8RT)
 - :Check Mid roller oil level (Optional oil change additional cost)
 - :Change MFWD Axle Housing & Hub oil (8RX)
 - :Check upper track roller and idler wheel hub oil (8RX)

| | | | | |
|----------|--------------------|------|--------|--------|
| FREIGHT | FREIGHT & HANDLING | 1.00 | 30.00 | 30.00 |
| DZ110558 | Filter Element | 1.00 | 213.45 | 213.45 |



11 Zora Street Warren NSW 2824
 Ph. (02) 6847 3522
 Air Conditioning Licence AU35668

PO Box 5485 Wagga Wagga NSW 2650
 Email: accounts@hutcheonandpearce.com.au
 www.hutcheonandpearce.com.au
 ABN 68 169 674 033 ACN 169 674 033

*** DOCUMENT COPY ***

SERVICE TAX INVOICE



| | |
|----------------------|-------------------|
| Document No.: | 3600800 |
| Document Date: | 17/04/2024 |
| Repair Order No.: | 405431 |
| Rego No.: | A200381 |
| Make/Model: | JOHN DEERE 8R 230 |
| Vehicle ID No.: | 1RW8230DCNA200381 |
| Fleet No.: | 8R 230 #6 |
| Odometer: | 1463 |
| Delivery Date: | 08/06/2022 |
| Invoice To: | |
| Customer ABN: | |
| Tax Exempt No.: | |
| P/Order No.: | |
| Page: | 3 of 3 |

Service Plan Calculator V2.9

| | | | | | <u>LABOUR</u> |
|----------------------|-----------------------------|--------------|----------|----------|-------------------|
| CP6658 | PLUS 50 ENGINE OIL-20LITRES | 2.00 | 174.89 | 349.78 | |
| RE539465 | Filter Element | 1.00 | 221.91 | 221.91 | |
| CP1566 | HY-GARD - 20lt | 1.00 | 159.89 | 159.89 | |
| CP1567 | HY-GARD - 205lts | 1.00 | 1,471.72 | 1,471.72 | |
| RE269061 | FILTER KIT | 1.00 | 74.84 | 74.84 | |
| RE284091 | Air Filter | 1.00 | 152.57 | 152.57 | |
| RE509672 | FILTER ELE | 1.00 | 57.79 | 57.79 | |
| CP1226 | JD GL5 85W/140 - 20L | 2.00 | 182.00 | 364.00 | |
| RE593819 | AIR FILTER | 1.00 | 80.49 | 80.49 | |
| RE596661 | FILTER ELE | 1.00 | 215.65 | 215.65 | |
| H216169 | BREATHER | 1.00 | 61.94 | 61.94 | |
| Parts Totals: | | 15.00 | | | \$3,454.03 |

Technician Labour Postings

| Technician | Job Description | Type | Clocked In Date | Start Time | Finish Time | Hours Worked | Hours Invoiced |
|-------------|-----------------|------|-----------------|------------|-------------|--------------|----------------|
| FITZ-ROYJAI | MP8R1500HRS* | S | 08/02/2024 | 07:10:08 | 11:00:48 | 3.830000 | 5.925100 |
| MAXWELLR\ | MP8R1500HRS* | S | 08/02/2024 | 07:10:58 | 11:04:38 | 3.900000 | 6.033400 |

Miscellaneous Charges

Consumables **\$200.00**

| | |
|---------------------------|-------------------|
| Sub Total for All: | \$5,388.00 |
| Rounding: | \$0.00 |
| GST: | \$0.00 |
| Total: | \$5,388.00 |

PAYMENT OPTIONS:

PayID: 68169674033
 Bank Details: WESTPAC WAGGA WAGGA BSB: 032769 A/C No: 624222
 PLEASE QUOTE YOUR HP ACCOUNT NUMBER IN THE REFERENCE

Our goods come with guarantees that cannot be excluded under the Australian Consumer Law. You are entitled to a replacement or refund for a major failure and for compensation for any other reasonably foreseeable loss or damage. You are also entitled to have the goods repaired or replaced if the goods fail to be of acceptable quality and the failure does not amount to a major failure. Payment Terms strictly cash unless terms authorized.



23 Boolcarrol Rd Wee Waa NSW 2388
 Ph. (02) 6795 8000
 Air Conditioning Licence AU35668

PO Box 5485 Wagga Wagga NSW 2650
 Email: accounts@hutcheonandpearce.com.au
 www.hutcheonandpearce.com.au
 ABN 68 169 674 033 ACN 169 674 033

*** DOCUMENT COPY ***



SERVICE TAX INVOICE

| | |
|----------------------|-------------------|
| Document No.: | 3606603 |
| Document Date: | 26/04/2024 |
| Repair Order No.: | 403652 |
| Rego No.: | A200381 |
| Make/Model: | JOHN DEERE 8R 230 |
| Vehicle ID No.: | 1RW8230DCNA200381 |
| Fleet No.: | 8R 230 #6 |
| Odometer: | 1655 |
| Delivery Date: | 08/06/2022 |
| Invoice To: | 2022138 |
| Customer ABN: | 56144208761 |
| Tax Exempt No.: | |
| P/Order No.: | 2-1366 |
| Page: | 1 of 2 |

REPLACE FRONT HUB BEARINGS AND SEALS

LABOUR

RAISED MACHINE
 REMOVED FRONT WHEELS
 DISASSEMBLED HUBS
 FOUND HUB BEARINGS DAMAGED ON RHS
 REPLACED BEARINGS
 REPLACED HUB SEALS
 REPLACED DRIVESHAFT SEAL AND BEARINGS
 ON LHS FOUND THAT BEARING HAD FAILED DAMAGING ALL PLANETARY GEARS, BEARINGS
 ASSEMBLED HUBS
 FILLED WITH OIL
 INSTALLED WHEELS

\$3,375.00

| <u>Part Number</u> | <u>Part Description</u> | <u>Serial No</u> | <u>Quantity</u> | <u>Nett Value</u> | <u>Total Cost</u> |
|--------------------|-------------------------|------------------|-----------------|-------------------|-------------------|
| JD9346 | BALL BEARI | | 2.00 | 85.67 | 171.34 |
| JD9115 | BEARING CU | | 4.00 | 162.99 | 651.96 |
| R87047 | RING | | 2.00 | 18.44 | 36.88 |
| RE65591 | Seal | | 2.00 | 57.75 | 115.50 |
| R554713 | Ring Gear | | 2.00 | 2,677.36 | 5,354.72 |
| JD9050 | BEARING CO | | 4.00 | 396.75 | 1,587.00 |
| R539188 | Thrust Washer | | 3.00 | 8.15 | 24.45 |
| R228144 | PLANET PIN | | 6.00 | 910.64 | 5,463.84 |
| R135866 | Hub | | 1.00 | 1,842.91 | 1,842.91 |
| R121362 | BEARING RA | | 6.00 | 67.56 | 405.36 |
| R542093 | Pinion | | 2.00 | 1,564.26 | 3,128.52 |
| R121283 | NEEDLE ROL | | 200.00 | 2.72 | 544.00 |

www.hutcheonandpearce.com.au



23 Boolcarrol Rd Wee Waa NSW 2388
 Ph. (02) 6795 8000
 Air Conditioning Licence AU35668

PO Box 5485 Wagga Wagga NSW 2650
 Email: accounts@hutcheonandpearce.com.au
 www.hutcheonandpearce.com.au
 ABN 68 169 674 033 ACN 169 674 033

*** DOCUMENT COPY ***



SERVICE TAX INVOICE

| | |
|----------------------|-------------------|
| Document No.: | 3606603 |
| Document Date: | 26/04/2024 |
| Repair Order No.: | 403652 |
| Rego No.: | A200381 |
| Make/Model: | JOHN DEERE 8R 230 |
| Vehicle ID No.: | 1RW8230DCNA200381 |
| Fleet No.: | 8R 230 #6 |
| Odometer: | 1655 |
| Delivery Date: | 08/06/2022 |
| Invoice To: | 2022138 |
| Customer ABN: | 56144208761 |
| Tax Exempt No.: | |
| P/Order No.: | 2-1366 |
| Page: | 2 of 2 |

REPLACE FRONT HUB BEARINGS AND SEALS

LABOUR

| Part Number | Part Description | Quantity | Unit Price | Total Price |
|----------------------|--------------------|---------------|------------|--------------------|
| FREIGHT | FREIGHT & HANDLING | 8.00 | 25.00 | 200.00 |
| RE154869 | SEAL | 2.00 | 116.81 | 233.62 |
| RE193099 | SEAL | 2.00 | 48.43 | 96.86 |
| R91842 | Screw | 2.00 | 5.08 | 10.16 |
| Parts Totals: | | 248.00 | | \$19,867.12 |

ZONE 9 ONSITE CHARGE - 200-250km - Two Travel Events Required

LABOUR

ZONE 9 ONSITE CHARGE - 200-250km

Includes travel labour costs, vehicle km costs & fuel costs

| Part Number | Part Description | Serial No | Quantity | Nett Value | Total Cost |
|----------------------|---------------------------------|-----------|-------------|------------|-------------------|
| Z9 | ZONE 9 ONSITE CHARGE (KM & LAB) | | 2.00 | 900.00 | 1,800.00 |
| Parts Totals: | | | 2.00 | | \$1,800.00 |

Miscellaneous Charges

Consumables **\$125.00**

| | |
|---------------------------|--------------------|
| Sub Total for All: | \$25,167.12 |
| Rounding: | \$0.00 |
| GST: | \$2,516.71 |
| Total: | \$27,683.83 |

PAYMENT OPTIONS:

PayID: 68169674033
 Bank Details: WESTPAC WAGGA WAGGA BSB: 032769 A/C No: 624222

****PLEASE QUOTE YOUR HP ACCOUNT NUMBER IN THE REFERENCE****

Our goods come with guarantees that cannot be excluded under the Australian Consumer Law. You are entitled to a replacement or refund for a major failure and for compensation for any other reasonably foreseeable loss or damage. You are also entitled to have the goods repaired or replaced if the goods fail to be of acceptable quality and the failure does not amount to a major failure. Payment Terms strictly cash unless terms authorized.

11 Zora Street Warren NSW 2824
Ph. (02) 6847 3522
Air Conditioning Licence AU35668

PO Box 5485 Wagga Wagga NSW 2650
Email: accounts@hutcheonandpearce.com.au
www.hutcheonandpearce.com.au
ABN 68 169 674 033 ACN 169 674 033

*** DOCUMENT COPY ***

SERVICE TAX INVOICE

| | |
|----------------------|-------------------|
| Document No.: | 3625969 |
| Document Date: | 3/06/2024 |
| Repair Order No.: | 419896 |
| Rego No.: | A200381 |
| Make/Model: | JOHN DEERE 8R 230 |
| Vehicle ID No.: | 1RW8230DCNA200381 |
| Fleet No.: | 8R 230 #6 |
| Odometer: | 1894 |
| Delivery Date: | 08/06/2022 |
| Invoice To: | |
| Customer ABN: | |
| Tax Exempt No.: | |
| P/Order No.: | WAYNE |
| Page: | 1 of 4 |

Service Plan Calculator V2.9

1. Cab Inspection
 - Check Light operation and condition
 - Check Wiper operation and condition
 - Check Stereo operation
 - Check transmission linkages and controls
 - Check PTO operation
 - Check loader operation (if applicable)
 - Clean windscreen and wipe out cab floor
 - Check heater and A/C operation
 - Reset service reminder
 - Inspect seat belt(s)
 - Check cab suspension components/ bushings. (8RT)
2. Maintenance
 - Change engine oil and filter element
 - Change primary and final fuel filter
 - Check air intake system
 - Change engine air filter (s)
 - Change cab air and recirculation filters
 - Check hitch components for wear and lubricate
 - Lubricate VARI-COOL fan drive
 - Lubricate steering and suspension components
 - Check battery electrolyte level and tighten terminals
 - Check valve clearance (T2 Machines Only)
 - Clean suspension compressor & filter & air bag. (8RT)
 - Lubricate Track tension cylinders (8RT)
3. Drawbar & 3PL & PTO
 - Test operation (external controls)

LABOUR

\$564.77

11 Zora Street Warren NSW 2824
Ph. (02) 6847 3522
Air Conditioning Licence AU35668

PO Box 5485 Wagga Wagga NSW 2650
Email: accounts@hutcheonandpearce.com.au
www.hutcheonandpearce.com.au
ABN 68 169 674 033 ACN 169 674 033

*** DOCUMENT COPY ***

SERVICE TAX INVOICE

| | |
|----------------------|-------------------|
| Document No.: | 3625969 |
| Document Date: | 3/06/2024 |
| Repair Order No.: | 419896 |
| Rego No.: | A200381 |
| Make/Model: | JOHN DEERE 8R 230 |
| Vehicle ID No.: | 1RW8230DCNA200381 |
| Fleet No.: | 8R 230 #6 |
| Odometer: | 1894 |
| Delivery Date: | 08/06/2022 |
| Invoice To: | |
| Customer ABN: | |
| Tax Exempt No.: | |
| P/Order No.: | WAYNE |
| Page: | 2 of 4 |

Service Plan Calculator V2.9

LABOUR

- Check for leaks
- Check condition of linkages
- Check shaft condition
- Check guards are in place
- 4. Front & Rear Axle
- Test drive and test operation of suspension and steering
- Check suspension and steering components damaged e.g Pivot bushes, suspension cylinders ball joint boots
- Check for leaks
- Check tyre pressures. (check pressures are set evenly)
- Check rim and weight condition (were fitted)
- Tighten wheel and wheel weight bolts
- 5. Transmission
- Test drive and test operation
- Check manual brakes
- Check for leaks
- Check neutral start system
- 6. Selective Control Valves
- Test operation – external and electronically
- Check for leaks
- Check covers are installed
- Check drains aren't blocked and are fitted
- Check and empty drain reservoir
- 7. Engine
- Check water pump and fan bearing
- Check fan belt and pulleys / idler bearings
- Check for coolant leaks and condition of hoses
- Check for oil and fuel leaks



11 Zora Street Warren NSW 2824
 Ph. (02) 6847 3522
 Air Conditioning Licence AU35668

PO Box 5485 Wagga Wagga NSW 2650
 Email: accounts@hutcheonandpearce.com.au
 www.hutcheonandpearce.com.au
 ABN 68 169 674 033 ACN 169 674 033

*** DOCUMENT COPY ***



SERVICE TAX INVOICE

| | |
|----------------------|-------------------|
| Document No.: | 3625969 |
| Document Date: | 3/06/2024 |
| Repair Order No.: | 419896 |
| Rego No.: | A200381 |
| Make/Model: | JOHN DEERE 8R 230 |
| Vehicle ID No.: | 1RW8230DCNA200381 |
| Fleet No.: | 8R 230 #6 |
| Odometer: | 1894 |
| Delivery Date: | 08/06/2022 |
| Invoice To: | |
| Customer ABN: | |
| Tax Exempt No.: | |
| P/Order No.: | WAYNE |
| Page: | 3 of 4 |

Service Plan Calculator V2.9

LABOUR

8. Track Machines

- Check Track alignment & track wear.
- Check Mid-Roller, Drive wheel sleeve, wedges and Idler wheels
- Check Track trash build-up.
- Check Walking beam suspension system & bumper stops. (8RT)
- Clean MFWD axle vent breather (8RX)
- Change Air Brake Dryer Filter (8RX) 2yrs or 1000hrs

ADDITIONAL SERVICE NOTES:

DURING INSPECTION FOUND THE BATTERIES HADN'T BEEN RESECURED AFTER FITMENT OF NEW BATTERIES.
 FOUND EXHAUST MANIFOLD JOIN STARTING TO LEAK. CONFIRMED BY SOOT FOUND UNDER JOIN AND VERY LIGHT AIR ESCAPING.

ALSO FOUND THE STEERING RAMS LEAKING AT SEAL END

| <u>Part Number</u> | <u>Part Description</u> | <u>Serial No</u> | <u>Quantity</u> | <u>Nett Value</u> | <u>Total Cost</u> |
|---------------------|-------------------------------------|------------------|-----------------|-------------------|-------------------|
| SERVICE PLAN TRAVEL | SERVICE PLAN TRAVEL | | 1.00 | 100.00 | 100.00 |
| STPLUS50 | PLUS 50 II (PER LTR) (1L of CP6660) | | 26.00 | 8.74 | 227.24 |
| RE596318 | AIR FILTER | | 1.00 | 133.39 | 133.39 |
| RE596317 | AIR FILTER | | 1.00 | 242.04 | 242.04 |
| RE593819 | AIR FILTER | | 1.00 | 80.49 | 80.49 |
| RE539465 | Filter Element | | 1.00 | 221.91 | 221.91 |
| RE509672 | FILTER ELE | | 1.00 | 57.79 | 57.79 |
| RE284091 | Air Filter | | 1.00 | 152.57 | 152.57 |



11 Zora Street Warren NSW 2824
 Ph. (02) 6847 3522
 Air Conditioning Licence AU35668

PO Box 5485 Wagga Wagga NSW 2650
 Email: accounts@hutcheonandpearce.com.au
 www.hutcheonandpearce.com.au
 ABN 68 169 674 033 ACN 169 674 033

*** DOCUMENT COPY ***

SERVICE TAX INVOICE



| | |
|----------------------|-------------------|
| Document No.: | 3625969 |
| Document Date: | 3/06/2024 |
| Repair Order No.: | 419896 |
| Rego No.: | A200381 |
| Make/Model: | JOHN DEERE 8R 230 |
| Vehicle ID No.: | 1RW8230DCNA200381 |
| Fleet No.: | 8R 230 #6 |
| Odometer: | 1894 |
| Delivery Date: | 08/06/2022 |
| Invoice To: | |
| Customer ABN: | |
| Tax Exempt No.: | |
| P/Order No.: | WAYNE |
| Page: | 4 of 4 |

Service Plan Calculator V2.9

| | | | | | |
|----------------------|------------|------|--------------|-------------------|---------------|
| DZ112919 | FILTER ELE | 1.00 | 200.60 | 200.60 | <u>LABOUR</u> |
| Parts Totals: | | | 34.00 | \$1,416.03 | |

Technician Labour Postings

| <u>Technician</u> | <u>Job Description</u> | <u>Type</u> | <u>Clocked In Date</u> | <u>Start Time</u> | <u>Finish Time</u> | <u>Hours Worked</u> | <u>Hours Invoiced</u> |
|-------------------|------------------------|-------------|------------------------|-------------------|--------------------|---------------------|-----------------------|
| ROBERTSSJ | MP8R2000HRS* | S | 29/05/2024 | 05:49:35 | 08:20:39 | 2.516700 | 3.895000 |

Miscellaneous Charges

| | |
|--------------------|----------------|
| Environmental Levy | \$5.00 |
| Consumables | \$95.00 |

| | |
|---------------------------|-------------------|
| Sub Total for All: | \$2,080.80 |
| Rounding: | \$0.00 |
| GST: | \$0.00 |
| Total: | \$2,080.80 |

PAYMENT OPTIONS:

PayID: 68169674033
 Bank Details: WESTPAC WAGGA WAGGA BSB: 032769 A/C No: 624222
 PLEASE QUOTE YOUR HP ACCOUNT NUMBER IN THE REFERENCE

Our goods come with guarantees that cannot be excluded under the Australian Consumer Law. You are entitled to a replacement or refund for a major failure and for compensation for any other reasonably foreseeable loss or damage. You are also entitled to have the goods repaired or replaced if the goods fail to be of acceptable quality and the failure does not amount to a major failure. Payment Terms strictly cash unless terms authorized.

11 Zora Street Warren NSW 2824
 Ph. (02) 6847 3522
 Air Conditioning Licence AU35668

PO Box 5485 Wagga Wagga NSW 2650
 Email: accounts@hutcheonandpearce.com.au
www.hutcheonandpearce.com.au
 ABN 68 169 674 033 ACN 169 674 033

*** DOCUMENT COPY ***

SERVICE TAX INVOICE

| | |
|----------------------|-------------------|
| Document No.: | 3668314 |
| Document Date: | 13/09/2024 |
| Repair Order No.: | 432405 |
| Rego No.: | A200381 |
| Make/Model: | JOHN DEERE 8R 230 |
| Vehicle ID No.: | 1RW8230DCNA200381 |
| Fleet No.: | 8R 230 #6 |
| Odometer: | 2486 |
| Delivery Date: | 08/06/2022 |
| Invoice To: | |
| Customer ABN: | |
| Tax Exempt No.: | |
| P/Order No.: | |
| Page: | 1 of 3 |

Service Plan Calculator V2.9

1. Cab Inspection
 - Check Light operation and condition
 - Check Wiper operation and condition
 - Check Stereo operation
 - Check transmission linkages and controls
 - Check PTO operation
 - Check loader operation (if applicable)
 - Clean windscreen and wipe out cab floor
 - Check heater & AC operation
2. Maintenance
 - Change engine oil and filter
 - Change primary and final fuel filter
 - Inspect engine air filter (s)
 - Inspect cab air and recirculation filters
 - Check air intake system
 - Check hitch components for wear and lubricate
 - Lubricate VARI-COOL fan drive
 - Lubricate steering and suspension components
 - Clean suspension compressor & filter & air bag. (8RT)
 - Lubricate Track tension cylinders (8RT)
3. Drawbar & 3PL & PTO
 - Test operation (external controls)
 - Check for leaks
 - Check condition of linkages
 - Check shaft condition
 - Check guards are in place
4. Front & Rear Axle

LABOUR
\$592.98

11 Zora Street Warren NSW 2824
Ph. (02) 6847 3522
Air Conditioning Licence AU35668

PO Box 5485 Wagga Wagga NSW 2650
Email: accounts@hutcheonandpearce.com.au
www.hutcheonandpearce.com.au
ABN 68 169 674 033 ACN 169 674 033

*** DOCUMENT COPY ***

SERVICE TAX INVOICE

| | |
|----------------------|-------------------|
| Document No.: | 3668314 |
| Document Date: | 13/09/2024 |
| Repair Order No.: | 432405 |
| Rego No.: | A200381 |
| Make/Model: | JOHN DEERE 8R 230 |
| Vehicle ID No.: | 1RW8230DCNA200381 |
| Fleet No.: | 8R 230 #6 |
| Odometer: | 2486 |
| Delivery Date: | 08/06/2022 |
| Invoice To: | |
| Customer ABN: | |
| Tax Exempt No.: | |
| P/Order No.: | |
| Page: | 2 of 3 |

Service Plan Calculator V2.9

LABOUR

Test drive and test operation of suspension and steering
Check suspension and steering components damaged e.g Pivot bushes, suspension cylinders ball joint boots
Check for leaks Check tyre pressures. (check pressures are set evenly)
Check rim and weight condition (were fitted)
Tighten wheel and wheel weight bolts

5. Transmission
Test drive and test operation
Check manual brakes.
Check for leaks
Check neutral start system

6. Selective Control Valves
Test operation – external and electronically
Check for leaks
Check covers are installed
Check drains aren't blocked and are fitted
Check and empty drain reservoir

7. Engine
Check water pump and fan bearing
Check fan belt and pulleys / idler bearings
Check for coolant leaks and condition of hoses
Check for oil and fuel leaks

8. Track Machines
Check Track alignment & track wear.
Check Mid-Roller, Drive wheel sleeve, wedges and Idler wheels
Check Track trash build-up
Check Walking beam air suspension system. (8RT)

ADDITIONAL SERVICE NOTES:




11 Zora Street Warren NSW 2824
 Ph. (02) 6847 3522
 Air Conditioning Licence AU35668

PO Box 5485 Wagga Wagga NSW 2650
 Email: accounts@hutcheonandpearce.com.au
 www.hutcheonandpearce.com.au
 ABN 68 169 674 033 ACN 169 674 033

*** DOCUMENT COPY ***

SERVICE TAX INVOICE

| | |
|----------------------|-------------------|
| Document No.: | 3668314 |
| Document Date: | 13/09/2024 |
| Repair Order No.: | 432405 |
| Rego No.: | A200381 |
| Make/Model: | JOHN DEERE 8R 230 |
| Vehicle ID No.: | 1RW8230DCNA200381 |
| Fleet No.: | 8R 230 #6 |
| Odometer: | 2486 |
| Delivery Date: | 08/06/2022 |
| Invoice To: | |
| Customer ABN: | |
| Tax Exempt No.: | |
| P/Order No.: | |
| Page: | 3 of 3 |



Service Plan Calculator V2.9

LABOUR

CARRIED OUT SERVICE AS PER SCHEDULE
 FOUND BOTH FRONT STEER CYLINDERS WEARING RECOMMEND NEW SEAL KIT
 FOUND MINOR MOVEMENT ON THE TENSIONER PULLEY. RECOMMEND REPLACING NEXT SERVICE WITH IDLERS
 FOUND BATTERY RETAINER STILL MISSING AS NOTED IN THE LAST SERVICE REQUIRES NEW RETAINER.

| <u>Part Number</u> | <u>Part Description</u> | <u>Serial No</u> | <u>Quantity</u> | <u>Nett Value</u> | <u>Total Cost</u> |
|----------------------|-------------------------------------|------------------|-----------------|-------------------|-------------------|
| STPLUS50 | PLUS 50 II (PER LTR) (1L of CP6660) | | 27.00 | 7.33 | 197.91 |
| RE539465 | Filter Element | | 1.00 | 218.73 | 218.73 |
| RE509672 | FILTER ELE | | 1.00 | 46.23 | 46.23 |
| DZ112919 | FILTER ELE | | 1.00 | 209.58 | 209.58 |
| Parts Totals: | | | 30.00 | | \$672.45 |

Technician Labour Postings

| <u>Technician</u> | <u>Job Description</u> | <u>Type</u> | <u>Clocked In Date</u> | <u>Start Time</u> | <u>Finish Time</u> | <u>Hours Worked</u> | <u>Hours Invoiced</u> |
|-------------------|------------------------|-------------|------------------------|-------------------|--------------------|---------------------|-----------------------|
| ROBERTSSJ | MP8R2500HRS* | S | 12/09/2024 | 06:07:20 | 08:25:34 | 2.300000 | 4.089500 |

Miscellaneous Charges

| | |
|--------------------|-----------------|
| Environmental Levy | \$50.00 |
| Consumables | \$150.00 |

| | |
|---------------------------|-------------------|
| Sub Total for All: | \$1,465.43 |
| Rounding: | \$0.00 |
| GST: | \$0.00 |
| Total: | \$1,465.43 |

PAYMENT OPTIONS:
 PayID: 68169674033
 Bank Details: WESTPAC WAGGA WAGGA BSB: 032769 A/C No: 624222
 PLEASE QUOTE YOUR HP ACCOUNT NUMBER IN THE REFERENCE

Our goods come with guarantees that cannot be excluded under the Australian Consumer Law. You are entitled to a replacement or refund for a major failure and for compensation for any other reasonably foreseeable loss or damage. You are also entitled to have the goods repaired or replaced if the goods fail to be of acceptable quality and the failure does not amount to a major failure. Payment Terms strictly cash unless terms authorized.

11 Zora Street Warren NSW 2824
 Ph. (02) 6847 3522
 Air Conditioning Licence AU35668

PO Box 5485 Wagga Wagga NSW 2650
 Email: accounts@hutcheonandpearce.com.au
www.hutcheonandpearce.com.au
 ABN 68 169 674 033 ACN 169 674 033

*** DOCUMENT COPY ***

SERVICE TAX INVOICE

| | |
|----------------------|-------------------|
| Document No.: | 3726163 |
| Document Date: | 17/12/2024 |
| Repair Order No.: | 441955 |
| Rego No.: | A200381 |
| Make/Model: | JOHN DEERE 8R 230 |
| Vehicle ID No.: | 1RW8230DCNA200381 |
| Fleet No.: | 8R 230 #6 |
| Odometer: | 2818 |
| Delivery Date: | 08/06/2022 |
| Invoice To: | |
| Customer ABN: | |
| Tax Exempt No.: | |
| P/Order No.: | |
| Page: | 1 of 5 |

Service Plan Calculator V2.9

1. Cab Inspection
 - Check Light operation and condition
 - Check Wiper operation and condition
 - Check Stereo operation
 - Check transmission linkages and controls
 - Check PTO operation
 - Check loader operation (if applicable)
 - Clean windscreen and wipe out cab floor
 - Check heater and A/C operation
 - Check cab suspension components/ bushings. (8RT)
2. Maintenance
 - Change engine oil and filter element
 - Change primary, final fuel filter & Water separator
 - Change fuel tank vent filter (s)
 - Change transmission and hydraulic oil and oil filters
 - Change front axle and final drive oils
 - Change Coolant
 - Check air intake system
 - Change engine air filter (s) cab air and recirculation filters
 - Check hitch components for wear and lubricate
 - Lubricate VARI-COOL fan drive
 - Lubricate steering and suspension components
 - Clean hydraulic oil suction screen
 - Check valve clearance (8RX, T3 & FT4 Machines Only)
 - Change Differential oil (8RT, 8RX)
 - Change suspension compressor filter, clean air bag. (8RT)
 - Lubricate Track tension cylinders (8RT)

LABOUR

\$2,415.33

11 Zora Street Warren NSW 2824
Ph. (02) 6847 3522
Air Conditioning Licence AU35668

PO Box 5485 Wagga Wagga NSW 2650
Email: accounts@hutcheonandpearce.com.au
www.hutcheonandpearce.com.au
ABN 68 169 674 033 ACN 169 674 033

*** DOCUMENT COPY ***

SERVICE TAX INVOICE

| | |
|----------------------|-------------------|
| Document No.: | 3726163 |
| Document Date: | 17/12/2024 |
| Repair Order No.: | 441955 |
| Rego No.: | A200381 |
| Make/Model: | JOHN DEERE 8R 230 |
| Vehicle ID No.: | 1RW8230DCNA200381 |
| Fleet No.: | 8R 230 #6 |
| Odometer: | 2818 |
| Delivery Date: | 08/06/2022 |
| Invoice To: | |
| Customer ABN: | |
| Tax Exempt No.: | |
| P/Order No.: | |
| Page: | 2 of 5 |

Service Plan Calculator V2.9

- Change SCV Pilot (8RX) & Hydraulic Steering filter (8RT)
- 3. Drawbar & 3PL & PTO
 - Test operation (external controls) & check for leaks
 - Check condition of linkages
 - Check shaft & guard condition
 - Lubricate draft link support shaft bushing
 - 4. Front & Rear Axle
 - Test drive and test operation of suspension and steering
 - Check suspension and steering components damaged e.g Pivot bushes, suspension cylinders ball joint boots
 - Check for leaks
 - Check tyre pressures. (check pressures are set evenly)
 - Check rim and weight condition (were fitted)
 - Tighten wheel and wheel weight bolts
- 5. Transmission
 - Test drive and test operation. Check for leaks.
 - Check manual brakes
 - Check neutral start system
- 6. Selective Control Valves
 - Test operation – external and electronically and check for leaks
 - Check covers are installed
 - Check drains aren't blocked and are fitted. Drain reservoir.
- 7. Engine
 - Check water pump and fan bearing
 - Check fan belt and pulleys / idler bearings & auxiliary drive belt.
 - Check for coolant leaks and condition of hoses
 - Check for oil and fuel leaks
- 8. Track Machines
 - Check Track alignment & track wear.

LABOUR

11 Zora Street Warren NSW 2824
 Ph. (02) 6847 3522
 Air Conditioning Licence AU35668

PO Box 5485 Wagga Wagga NSW 2650
 Email: accounts@hutcheonandpearce.com.au
www.hutcheonandpearce.com.au
 ABN 68 169 674 033 ACN 169 674 033

*** DOCUMENT COPY ***

SERVICE TAX INVOICE

| | |
|----------------------|-------------------|
| Document No.: | 3726163 |
| Document Date: | 17/12/2024 |
| Repair Order No.: | 441955 |
| Rego No.: | A200381 |
| Make/Model: | JOHN DEERE 8R 230 |
| Vehicle ID No.: | 1RW8230DCNA200381 |
| Fleet No.: | 8R 230 #6 |
| Odometer: | 2818 |
| Delivery Date: | 08/06/2022 |
| Invoice To: | |
| Customer ABN: | |
| Tax Exempt No.: | |
| P/Order No.: | |
| Page: | 3 of 5 |

Service Plan Calculator V2.9

LABOUR

Check Mid-Roller, Drive wheel sleeve, wedges and Idler wheels
 Check Track trash build-up
 Check Walking beam air suspension system. (8RT)
 Check Drive wheel hub & Mid roller oil level.(Optional oil change additional cost)
 Change Air Brake Dryer Filter (8RX) 2yrs or 1000hrs
 Change MFWD Axle Housing & Hub oil, clean breather (8RX)
 Check upper track roller and idler wheel hub oil (8RX)
 ADDITIONAL SERVICE NOTES
 CARRIED OUT SERVICE AS PER SCHEDULE
 CARRIED OUT ALL SOFTWARE UPDATES.
 REMOVED ALL SCREENS AND MINIMAL MATERIAL FOUND ON SCREENS
 WHILST DRAINING FINAL DRIVES OILS THE PLUGS WERE HEAVILY CONTAMINATED AND THE OIL SMELT VERY BURNT.
 FOUND SCV 1 MISSING COVER
 FOUND RIGHT SIDE STEERING CYLINDER LEAKING
 FOUND BATTERY'S HAVE BEEN REPLACED AND FITTED THE WRONG WAY ROUND AND NO CLAMP HAS BEEN FITTED TO HOLD BATTERIES IN PLACE.
 FOUND MULTIPLE FAULT CODES STORED IN THE SYSTEM. ALL CODES CLEARED AND DIDN'T COME BACK.
 FOUND EXCESS MOVEMENT IN TENSIONER RECOMMEND REPLACEMENT OF BELT TENSIONER AND IDLER PULLEYS.

| <u>Part Number</u> | <u>Part Description</u> | <u>Serial No</u> | <u>Quantity</u> | <u>Nett Value</u> | <u>Total Cost</u> |
|------------------------|--------------------------------------|------------------|-----------------|-------------------|-------------------|
| SERVICE PLAN TRAVEL | SERVICE PLAN TRAVEL | | 1.00 | 100.00 | 100.00 |
| STHY-GARD | HY-GARD TRANS/HYD.OIL (1L of CP2103) | | 150.00 | 6.64 | 996.00 |
| STCOOLANT | COOLANT PER L (1L of CP8278) | | 35.00 | 6.43 | 225.05 |
| STPLUS50 | PLUS 50 II (PER LTR) (1L of CP6660) | | 26.00 | 7.33 | 190.58 |
| RE596318 | AIR FILTER | | 1.00 | 131.48 | 131.48 |
| RE596317 | AIR FILTER | | 1.00 | 252.87 | 252.87 |

11 Zora Street Warren NSW 2824
 Ph. (02) 6847 3522
 Air Conditioning Licence AU35668

PO Box 5485 Wagga Wagga NSW 2650
 Email: accounts@hutcheonandpearce.com.au
www.hutcheonandpearce.com.au
 ABN 68 169 674 033 ACN 169 674 033

*** DOCUMENT COPY ***

SERVICE TAX INVOICE

| | |
|----------------------|-------------------|
| Document No.: | 3726163 |
| Document Date: | 17/12/2024 |
| Repair Order No.: | 441955 |
| Rego No.: | A200381 |
| Make/Model: | JOHN DEERE 8R 230 |
| Vehicle ID No.: | 1RW8230DCNA200381 |
| Fleet No.: | 8R 230 #6 |
| Odometer: | 2818 |
| Delivery Date: | 08/06/2022 |
| Invoice To: | |
| Customer ABN: | |
| Tax Exempt No.: | |
| P/Order No.: | |
| Page: | 4 of 5 |

Service Plan Calculator V2.9

| | | | | <u>LABOUR</u> |
|-----------------|---------------------------------|------|--------|---------------|
| RE593819 | AIR FILTER | 1.00 | 101.09 | 101.09 |
| RE509672 | FILTER ELE | 1.00 | 146.23 | 146.23 |
| RE284091 | Air Filter | 1.00 | 138.34 | 138.34 |
| RE269061 | FILTER KIT | 1.00 | 178.18 | 178.18 |
| DZ130550 | FILTER ELE | 1.00 | 286.82 | 286.82 |
| RE596661 | FILTER ELE | 2.00 | 225.30 | 450.60 |
| DZ112919 | FILTER ELE | 1.00 | 209.58 | 209.58 |
| AT365869 | FILTER ELE | 1.00 | 191.32 | 191.32 |
| R526607 | SEAL | 1.00 | 180.54 | 180.54 |
| STGEAROIL80W/90 | gear oil per ltr (1L of CP8221) | 7.00 | 9.37 | 65.59 |
| H216169 | BREATHER | 1.00 | 161.66 | 161.66 |
| R26543 | O-RING | 2.00 | 18.85 | 37.70 |

Parts Totals: 234.00 \$4,043.63

Technician Labour Postings


| <u>Technician</u> | <u>Job Description</u> | <u>Type</u> | <u>Clocked In Date</u> | <u>Start Time</u> | <u>Finish Time</u> | <u>Hours Worked</u> | <u>Hours Invoiced</u> |
|-------------------|------------------------|-------------|------------------------|-------------------|--------------------|---------------------|-----------------------|
| ROBERTSSJ | MP8R3000HRS* | S | 10/12/2024 | 14:30:20 | 16:01:50 | 1.516700 | 2.898400 |



11 Zora Street Warren NSW 2824
 Ph. (02) 6847 3522
 Air Conditioning Licence AU35668

PO Box 5485 Wagga Wagga NSW 2650
 Email: accounts@hutcheonandpearce.com.au
 www.hutcheonandpearce.com.au
 ABN 68 169 674 033 ACN 169 674 033

*** DOCUMENT COPY ***



SERVICE TAX INVOICE

Document No.: 3726163
Document Date: 17/12/2024
Repair Order No.: 441955
Rego No.: A200381
Make/Model: JOHN DEERE 8R 230
Vehicle ID No.: 1RW8230DCNA200381
Fleet No.: 8R 230 #6
Odometer: 2818
Delivery Date: 08/06/2022
Invoice To:
Customer ABN:
Tax Exempt No.:
P/Order No.:
Page: 5 of 5

ROBERTSSJ MP8R3000HRS* S 10/12/2024 06:49:45 14:01:03 7.200000 13.759000

Miscellaneous Charges

Environmental Levy \$100.00
 Consumables \$750.00

Sub Total for All: \$7,308.96
Rounding: \$0.00
GST: \$0.00
Total: \$7,308.96

PAYMENT OPTIONS:
 PayID: 68169674033
 Bank Details: WESTPAC WAGGA WAGGA BSB: 032769 A/C No: 624222
 PLEASE QUOTE YOUR HP ACCOUNT NUMBER IN THE REFERENCE

Our goods come with guarantees that cannot be excluded under the Australian Consumer Law. You are entitled to a replacement or refund for a major failure and for compensation for any other reasonably foreseeable loss or damage. You are also entitled to have the goods repaired or replaced if the goods fail to be of acceptable quality and the failure does not amount to a major failure. Payment Terms strictly cash unless terms authorized.

11 Zora Street Warren NSW 2824
 Ph. (02) 6847 3522
 Air Conditioning Licence AU35668

PO Box 5485 Wagga Wagga NSW 2650
 Email: accounts@hutcheonandpearce.com.au
www.hutcheonandpearce.com.au
 ABN 68 169 674 033 ACN 169 674 033

*** DOCUMENT COPY ***

SERVICE TAX INVOICE

| | |
|----------------------|-------------------|
| Document No.: | 3747341 |
| Document Date: | 6/02/2025 |
| Repair Order No.: | 448915 |
| Rego No.: | A200381 |
| Make/Model: | JOHN DEERE 8R 230 |
| Vehicle ID No.: | 1RW8230DCNA200381 |
| Fleet No.: | 8R 230 #6 |
| Odometer: | 3228 |
| Delivery Date: | 08/06/2022 |
| Invoice To: | |
| Customer ABN: | |
| Tax Exempt No.: | |
| P/Order No.: | |
| Page: | 1 of 4 |

Service Plan Calculator V2.9

1. Cab Inspection
 - Check Light operation and condition
 - Check Wiper operation and condition
 - Check Stereo operation
 - Check transmission linkages and controls
 - Check PTO operation
 - Check loader operation (if applicable)
 - Clean windscreen and wipe out cab floor
 - Check heater & AC operation
2. Maintenance
 - Change engine oil and filter
 - Change primary and final fuel filter
 - Inspect engine air filter (s)
 - Inspect cab air and recirculation filters
 - Check air intake system
 - Check hitch components for wear and lubricate
 - Lubricate VARI-COOL fan drive
 - Lubricate steering and suspension components
 - Clean suspension compressor & filter & air bag. (8RT)
 - Lubricate Track tension cylinders (8RT)
3. Drawbar & 3PL & PTO
 - Test operation (external controls)
 - Check for leaks
 - Check condition of linkages
 - Check shaft condition
 - Check guards are in place
4. Front & Rear Axle

LABOUR
\$596.24

11 Zora Street Warren NSW 2824
Ph. (02) 6847 3522
Air Conditioning Licence AU35668

PO Box 5485 Wagga Wagga NSW 2650
Email: accounts@hutcheonandpearce.com.au
www.hutcheonandpearce.com.au
ABN 68 169 674 033 ACN 169 674 033

*** DOCUMENT COPY ***

SERVICE TAX INVOICE

| | |
|----------------------|-------------------|
| Document No.: | 3747341 |
| Document Date: | 6/02/2025 |
| Repair Order No.: | 448915 |
| Rego No.: | A200381 |
| Make/Model: | JOHN DEERE 8R 230 |
| Vehicle ID No.: | 1RW8230DCNA200381 |
| Fleet No.: | 8R 230 #6 |
| Odometer: | 3228 |
| Delivery Date: | 08/06/2022 |
| Invoice To: | |
| Customer ABN: | |
| Tax Exempt No.: | |
| P/Order No.: | |
| Page: | 2 of 4 |

Service Plan Calculator V2.9

LABOUR

Test drive and test operation of suspension and steering
Check suspension and steering components damaged e.g Pivot bushes, suspension cylinders ball joint boots
Check for leaks Check tyre pressures. (check pressures are set evenly)
Check rim and weight condition (were fitted)
Tighten wheel and wheel weight bolts

5. Transmission
Test drive and test operation
Check manual brakes.
Check for leaks
Check neutral start system

6. Selective Control Valves
Test operation – external and electronically
Check for leaks
Check covers are installed
Check drains aren't blocked and are fitted
Check and empty drain reservoir

7. Engine
Check water pump and fan bearing
Check fan belt and pulleys / idler bearings
Check for coolant leaks and condition of hoses
Check for oil and fuel leaks

8. Track Machines
Check Track alignment & track wear.
Check Mid-Roller, Drive wheel sleeve, wedges and Idler wheels
Check Track trash build-up
Check Walking beam suspension system. (8RT)

ADDITIONAL SERVICE NOTES:

11 Zora Street Warren NSW 2824
 Ph. (02) 6847 3522
 Air Conditioning Licence AU35668

PO Box 5485 Wagga Wagga NSW 2650
 Email: accounts@hutcheonandpearce.com.au
www.hutcheonandpearce.com.au
 ABN 68 169 674 033 ACN 169 674 033

*** DOCUMENT COPY ***

SERVICE TAX INVOICE

| | |
|----------------------|-------------------|
| Document No.: | 3747341 |
| Document Date: | 6/02/2025 |
| Repair Order No.: | 448915 |
| Rego No.: | A200381 |
| Make/Model: | JOHN DEERE 8R 230 |
| Vehicle ID No.: | 1RW8230DCNA200381 |
| Fleet No.: | 8R 230 #6 |
| Odometer: | 3228 |
| Delivery Date: | 08/06/2022 |
| Invoice To: | |
| Customer ABN: | |
| Tax Exempt No.: | |
| P/Order No.: | |
| Page: | 3 of 4 |

Service Plan Calculator V2.9

LABOUR

CARRIED OUT SERVICE AS PER SCHEDULE
 FOUND MULTIPLE FAULTS CODES LOGGED CODES LOGGED SEE PHOTOS FOR REFERENCE
 ALL CODES CLEARED.
 FOUND BOTH STEERING CYLINDERS LEAKING.
 FOUND IDLER PULLEY AND TENSIONER HAS MOVEMENT AND EXCESSIVE HEAT AFTER MINIMAL RUN TIME.
 RECOMMEND BELT IDLERS AND TENSIONER
 FOUND BATTERY STILL MISSING RETAINER THIS HAS BEEN NOTED THE LAST 3 SERVICES
 FOUND EXHAUST MANIFOLD STILL LEAKING AT JOIN IN THE MIDDLE OF MANIFOLD.
 FOUND AC CONDENSER HAS BOTH RETAINER CLIPS BROKEN AND IS CURRENTLY BEING HELD IN BY CABLE TIES
 RECOMMEND REPLACEMENT OF CLAMPS FOR SECURE FITMENT AND EASE OF SERVICING AND MAINTENANCE

| <u>Part Number</u> | <u>Part Description</u> | <u>Serial No</u> | <u>Quantity</u> | <u>Nett Value</u> | <u>Total Cost</u> |
|----------------------|-------------------------------------|------------------|-----------------|-------------------|-------------------|
| SERVICE PLAN TRAVEL | SERVICE PLAN TRAVEL | | 1.00 | 100.00 | 100.00 |
| STPLUS50 | PLUS 50 II (PER LTR) (1L of CP6660) | | 26.50 | 7.33 | 194.25 |
| RE509672 | FILTER ELE | | 1.00 | 48.54 | 48.54 |
| DZ130550 | FILTER ELE | | 1.00 | 286.82 | 286.82 |
| DZ112919 | FILTER ELE | | 1.00 | 209.58 | 209.58 |
| Parts Totals: | | | 30.50 | | \$839.19 |

Technician Labour Postings

| <u>Technician</u> | <u>Job Description</u> | <u>Type</u> | <u>Clocked In Date</u> | <u>Start Time</u> | <u>Finish Time</u> | <u>Hours Worked</u> | <u>Hours Invoiced</u> |
|-------------------|------------------------|-------------|------------------------|-------------------|--------------------|---------------------|-----------------------|
| ROBERTSSJ | MP8R3500HRS* | S | 05/02/2025 | 09:19:26 | 11:16:00 | 1.950000 | 2.038600 |
| ROBERTSSJ | MP8R3500HRS* | S | 05/02/2025 | 07:52:34 | 09:19:26 | 1.450000 | 1.515900 |



11 Zora Street Warren NSW 2824
 Ph. (02) 6847 3522
 Air Conditioning Licence AU35668

PO Box 5485 Wagga Wagga NSW 2650
 Email: accounts@hutcheonandpearce.com.au
 www.hutcheonandpearce.com.au
 ABN 68 169 674 033 ACN 169 674 033

*** DOCUMENT COPY ***



SERVICE TAX INVOICE

| | |
|----------------------|-------------------|
| Document No.: | 3747341 |
| Document Date: | 6/02/2025 |
| Repair Order No.: | 448915 |
| Rego No.: | A200381 |
| Make/Model: | JOHN DEERE 8R 230 |
| Vehicle ID No.: | 1RW8230DCNA200381 |
| Fleet No.: | 8R 230 #6 |
| Odometer: | 3228 |
| Delivery Date: | 08/06/2022 |
| Invoice To: | |
| Customer ABN: | |
| Tax Exempt No.: | |
| P/Order No.: | |
| Page: | 4 of 4 |

ROBERTSSJ MP8R3500HRS* S 03/02/2025 15:10:25 15:42:22 0.533300 0.557500

Miscellaneous Charges

| | |
|--------------------|----------------|
| Environmental Levy | \$5.00 |
| Consumables | \$25.00 |

| | |
|---------------------------|-------------------|
| Sub Total for All: | \$1,465.43 |
| Rounding: | \$0.00 |
| GST: | \$0.00 |
| Total: | \$1,465.43 |

PAYMENT OPTIONS:
 PayID: 68169674033
 Bank Details: WESTPAC WAGGA WAGGA BSB: 032769 A/C No: 624222
 PLEASE QUOTE YOUR HP ACCOUNT NUMBER IN THE REFERENCE

Our goods come with guarantees that cannot be excluded under the Australian Consumer Law. You are entitled to a replacement or refund for a major failure and for compensation for any other reasonably foreseeable loss or damage. You are also entitled to have the goods repaired or replaced if the goods fail to be of acceptable quality and the failure does not amount to a major failure. Payment Terms strictly cash unless terms authorized.

11 Zora Street Warren NSW 2824
 Ph. (02) 6847 3522
 Air Conditioning Licence AU35668

PO Box 5485 Wagga Wagga NSW 2650
 Email: accounts@hutcheonandpearce.com.au
www.hutcheonandpearce.com.au
 ABN 68 169 674 033 ACN 169 674 033

*** DOCUMENT COPY ***

SERVICE TAX INVOICE

| | |
|----------------------|-------------------|
| Document No.: | 3802204 |
| Document Date: | 30/05/2025 |
| Repair Order No.: | 461114 |
| Rego No.: | A200381 |
| Make/Model: | JOHN DEERE 8R 230 |
| Vehicle ID No.: | 1RW8230DCNA200381 |
| Fleet No.: | 8R 230 #6 |
| Odometer: | 3750 |
| Delivery Date: | 08/06/2022 |
| Invoice To: | |
| Customer ABN: | |
| Tax Exempt No.: | |
| P/Order No.: | |
| Page: | 1 of 5 |

Service Plan Calculator V2.9

1. Cab Inspection
 - Check Light operation and condition
 - Check Wiper operation and condition
 - Check Stereo operation
 - Check transmission linkages and controls
 - Check PTO operation
 - Check loader operation (if applicable)
 - Clean windscreen and wipe out cab floor
 - Check heater and A/C operation
 - Reset service reminder
 - Inspect seat belt(s)
 - Check cab suspension components/ bushings. (8RT)
2. Maintenance
 - Change engine oil and filter element
 - Change primary and final fuel filter
 - Check air intake system
 - Change engine air filter (s)
 - Change cab air and recirculation filters
 - Check hitch components for wear and lubricate
 - Lubricate VARI-COOL fan drive
 - Lubricate steering and suspension components
 - Check battery electrolyte level and tighten terminals
 - Check valve clearance (T2 Machines Only)
 - Clean suspension compressor & filter & air bag. (8RT)
 - Lubricate Track tension cylinders (8RT)
3. Drawbar & 3PL & PTO
 - Test operation (external controls)

LABOUR

\$453.57

11 Zora Street Warren NSW 2824
Ph. (02) 6847 3522
Air Conditioning Licence AU35668

PO Box 5485 Wagga Wagga NSW 2650
Email: accounts@hutcheonandpearce.com.au
www.hutcheonandpearce.com.au
ABN 68 169 674 033 ACN 169 674 033

*** DOCUMENT COPY ***

SERVICE TAX INVOICE

| | |
|----------------------|-------------------|
| Document No.: | 3802204 |
| Document Date: | 30/05/2025 |
| Repair Order No.: | 461114 |
| Rego No.: | A200381 |
| Make/Model: | JOHN DEERE 8R 230 |
| Vehicle ID No.: | 1RW8230DCNA200381 |
| Fleet No.: | 8R 230 #6 |
| Odometer: | 3750 |
| Delivery Date: | 08/06/2022 |
| Invoice To: | |
| Customer ABN: | |
| Tax Exempt No.: | |
| P/Order No.: | |
| Page: | 2 of 5 |

Service Plan Calculator V2.9

- Check for leaks
- Check condition of linkages
- Check shaft condition
- Check guards are in place
- 4. Front & Rear Axle
- Test drive and test operation of suspension and steering
- Check suspension and steering components damaged e.g Pivot bushes, suspension cylinders ball joint boots
- Check for leaks
- Check tyre pressures. (check pressures are set evenly)
- Check rim and weight condition (were fitted)
- Tighten wheel and wheel weight bolts
- 5. Transmission
- Test drive and test operation
- Check manual brakes
- Check for leaks
- Check neutral start system
- 6. Selective Control Valves
- Test operation – external and electronically
- Check for leaks
- Check covers are installed
- Check drains aren't blocked and are fitted
- Check and empty drain reservoir
- 7. Engine
- Check water pump and fan bearing
- Check fan belt and pulleys / idler bearings
- Check for coolant leaks and condition of hoses
- Check for oil and fuel leaks

LABOUR

11 Zora Street Warren NSW 2824
 Ph. (02) 6847 3522
 Air Conditioning Licence AU35668

PO Box 5485 Wagga Wagga NSW 2650
 Email: accounts@hutcheonandpearce.com.au
www.hutcheonandpearce.com.au
 ABN 68 169 674 033 ACN 169 674 033

*** DOCUMENT COPY ***

SERVICE TAX INVOICE

| | |
|----------------------|-------------------|
| Document No.: | 3802204 |
| Document Date: | 30/05/2025 |
| Repair Order No.: | 461114 |
| Rego No.: | A200381 |
| Make/Model: | JOHN DEERE 8R 230 |
| Vehicle ID No.: | 1RW8230DCNA200381 |
| Fleet No.: | 8R 230 #6 |
| Odometer: | 3750 |
| Delivery Date: | 08/06/2022 |
| Invoice To: | |
| Customer ABN: | |
| Tax Exempt No.: | |
| P/Order No.: | |
| Page: | 3 of 5 |

Service Plan Calculator V2.9

LABOUR

8. Track Machines

Check Track alignment & track wear.

Check Mid-Roller, Drive wheel sleeve, wedges and Idler wheels

Check Track trash build-up.

Check Walking beam suspension system & bumper stops. (8RT)

Clean MFWD axle vent breaker (8RX)

Change Air Brake Dryer Filter (8RX) 2yrs or 1000hrs

ADDITIONAL SERVICE NOTES:

CARRIED OUT SERVICE AS PER SCHEDULE

ATTEMPTED TO CARRY OUT SCREEN SOFTWARE UPDATES. DUE TO A LACK OF STORAGE IN THE SCREEN THIS WAS NOT ABLE TO BE CARRIED OUT.

FOUND MULTIPLE FAULTS CODES LOGGED IN THE SYSTEM. 2 CODES THAT CAUSE CONCERN ARE. FAN SPED TO LOW AND CLUTCH SLIPPING CODE. THIS WILL NEED TO BE MONITORED.

CARRIED OUT INSPECTION OF THE FAN AND FEELS LIKE THE VISCOUS HUB HAS EXCESSIVE FREE PLAY. AND VERY LITTLE RESISTANCE FROM GREASE.

FOUND BOTH LOWER COOLER CLAMPS HAVE FAILED AND MISSING HELD TOGETHER BY CABLE TIES. RECOMMEND NEW CLAMPS.

FOUND EXHAUST LEAK COMING FROM THE JOIN IN THE EXHAUST MANIFOLD QUITE HEAVILY UNDER HIGHER RPM

FOUND BATTERIES INSTALLED BACK TO FRONT AND ALSO MISSING CLAMP THIS HAS BEEN NOTED FOR THE LAST THREE SERVICES. REQUIRE A NEW BATTERY CLAMP

FOUND SENSOR AT REAR OF THE RIGHT SIDE OF THE MOTOR WEEPING RECOMMEND NEW SEAL

FOUND SENSOR UNDER INJECTOR PUMP STARTING TO WEEP RECOMMEND NEW SEAL.

FOUND DIAL ON THE SCREEN BROKEN

AND REAR PTO SWITCH HAS FAILED AND IS STICKY WON'T ACTIVATE OR DEACTIVATE PTO

| <u>Part Number</u> | <u>Part Description</u> | <u>Serial No</u> | <u>Quantity</u> | <u>Nett Value</u> | <u>Total Cost</u> |
|--------------------|--------------------------------------|------------------|-----------------|-------------------|-------------------|
| STHY-GARD | HY-GARD TRANS/HYD.OIL (1L of CP2103) | | 8.00 | 6.88 | 55.04 |
| STCOOLANT | COOLANT PER L (1L of CP8278) | | 1.50 | 6.72 | 10.08 |

www.hutcheonandpearce.com.au

11 Zora Street Warren NSW 2824
 Ph. (02) 6847 3522
 Air Conditioning Licence AU35668

PO Box 5485 Wagga Wagga NSW 2650
 Email: accounts@hutcheonandpearce.com.au
www.hutcheonandpearce.com.au
 ABN 68 169 674 033 ACN 169 674 033

*** DOCUMENT COPY ***

SERVICE TAX INVOICE

| | |
|----------------------|-------------------|
| Document No.: | 3802204 |
| Document Date: | 30/05/2025 |
| Repair Order No.: | 461114 |
| Rego No.: | A200381 |
| Make/Model: | JOHN DEERE 8R 230 |
| Vehicle ID No.: | 1RW8230DCNA200381 |
| Fleet No.: | 8R 230 #6 |
| Odometer: | 3750 |
| Delivery Date: | 08/06/2022 |
| Invoice To: | |
| Customer ABN: | |
| Tax Exempt No.: | |
| P/Order No.: | |
| Page: | 4 of 5 |

Service Plan Calculator V2.9

| STPLUS50 | PLUS 50 II (PER LTR) (1L of CP6660) | 27.00 | 7.56 | 204.12 | |
|----------------------|-------------------------------------|--------------|--------|--------|--|
| RE596318 | AIR FILTER | 1.00 | 131.48 | 131.48 | |
| RE596317 | AIR FILTER | 1.00 | 252.87 | 252.87 | |
| RE593819 | AIR FILTER | 1.00 | 84.09 | 84.09 | |
| RE509672 | FILTER ELE | 1.00 | 103.78 | 103.78 | |
| DZ130550 | FILTER ELE | 1.00 | 286.82 | 286.82 | |
| DZ112919 | FILTER ELE | 1.00 | 209.58 | 209.58 | |
| SERVICE PLAN TRAVEL | SERVICE PLAN TRAVEL | 1.00 | 100.00 | 100.00 | |
| TA32591 | AIR FILTER | 1.00 | 150.37 | 150.37 | |
| Parts Totals: | | 44.50 | | | |

LABOUR

\$1,588.23

Technician Labour Postings

| <u>Technician</u> | <u>Job Description</u> | <u>Type</u> | <u>Clocked In Date</u> | <u>Start Time</u> | <u>Finish Time</u> | <u>Hours Worked</u> | <u>Hours Invoiced</u> |
|-------------------|------------------------|-------------|------------------------|-------------------|--------------------|---------------------|-----------------------|
| GOWERCHA | MP8R4000HRS* | S | 29/05/2025 | 07:54:39 | 08:12:31 | 0.300000 | 0.418700 |
| GOWERCHA | MP8R4000HRS* | S | 29/05/2025 | 07:54:30 | 07:54:33 | 0 | 0 |
| ROBERTSSJ | MP8R4000HRS* | S | 29/05/2025 | 06:30:50 | 07:54:09 | 1.400000 | 1.953800 |



11 Zora Street Warren NSW 2824
 Ph. (02) 6847 3522
 Air Conditioning Licence AU35668

PO Box 5485 Wagga Wagga NSW 2650
 Email: accounts@hutcheonandpearce.com.au
 www.hutcheonandpearce.com.au
 ABN 68 169 674 033 ACN 169 674 033

*** DOCUMENT COPY ***



SERVICE TAX INVOICE

Document No.: 3802204
Document Date: 30/05/2025
Repair Order No.: 461114
Rego No.: A200381
Make/Model: JOHN DEERE 8R 230
Vehicle ID No.: 1RW8230DCNA200381
Fleet No.: 8R 230 #6
Odometer: 3750
Delivery Date: 08/06/2022
Invoice To:
Customer ABN:
Tax Exempt No.:
P/Order No.:
Page: 5 of 5

ROBERTSSJ MP8R4000HRS* S 23/05/2025 17:23:42 17:51:05 0.466700 0.651300

Miscellaneous Charges

Environmental Levy \$5.00
 Consumables \$34.00

Sub Total for All: \$2,080.80
Rounding: \$0.00
GST: \$0.00
Total: \$2,080.80

PAYMENT OPTIONS:
 PayID: 68169674033
 Bank Details: WESTPAC WAGGA WAGGA BSB: 032769 A/C No: 624222
 PLEASE QUOTE YOUR HP ACCOUNT NUMBER IN THE REFERENCE

Our goods come with guarantees that cannot be excluded under the Australian Consumer Law. You are entitled to a replacement or refund for a major failure and for compensation for any other reasonably foreseeable loss or damage. You are also entitled to have the goods repaired or replaced if the goods fail to be of acceptable quality and the failure does not amount to a major failure. Payment Terms strictly cash unless terms authorized.



22R Narromine Road, Dubbo NSW 2830
 Ph. (02) 6885 3300
 Air Conditioning Licence AU35668

PO Box 5485 Wagga Wagga NSW 2650
 Email: accounts@hutcheonandpearce.com.au
 www.hutcheonandpearce.com.au
 ABN 68 169 674 033 ACN 169 674 033

*** DOCUMENT COPY ***



SERVICE TAX INVOICE

| | |
|----------------------|-------------------|
| Document No.: | 3862615 |
| Document Date: | 27/10/2025 |
| Repair Order No.: | 475754 |
| Rego No.: | A200381 |
| Make/Model: | JOHN DEERE 8R 230 |
| Vehicle ID No.: | 1RW8230DCNA200381 |
| Fleet No.: | 8R 230 #6 |
| Odometer: | 4123 |
| Delivery Date: | 08/06/2022 |
| Invoice To: | 2022138 |
| Customer ABN: | |
| Tax Exempt No.: | |
| P/Order No.: | 2-3912 |
| Page: | 1 of 1 |

SEAT R&R

Replace seat shocks and air bag

Disconnect battery.

Disconnect:

-Seat raise/lower switch.

-Operator presence switch.

-Command arm harness.

Loosen lower boot to access mounting screws.

Remove & replace seat.

Assemble in reverse order & test operation.

LABOUR

\$862.50

| <u>Part Number</u> | <u>Part Description</u> | <u>Serial No</u> | <u>Quantity</u> | <u>Nett Value</u> | <u>Total Cost</u> |
|--------------------|-------------------------|------------------|-----------------|-------------------|-------------------|
| AL210889 | Spring | | 1.00 | 454.26 | 454.26 |
| TA22080 | Seat Shock Absorber Kit | | 1.00 | 759.09 | 759.09 |

Parts Totals: 2.00 \$1,213.35

Miscellaneous Charges

Environmental Levy

\$5.00

Consumables

\$64.69

| | |
|---------------------------|-------------------|
| Sub Total for All: | \$2,145.54 |
| Rounding: | \$0.00 |
| GST: | \$214.55 |
| Total: | \$2,360.09 |

PAYMENT OPTIONS:
 PayID: 68169674033
 Bank Details: WESTPAC WAGGA WAGGA BSB: 032769 A/C No: 624222
 PLEASE QUOTE YOUR HP ACCOUNT NUMBER IN THE REFERENCE

Our goods come with guarantees that cannot be excluded under the Australian Consumer Law. You are entitled to a replacement or refund for a major failure and for compensation for any other reasonably foreseeable loss or damage. You are also entitled to have the goods repaired or replaced if the goods fail to be of acceptable quality and the failure does not amount to a major failure. Payment Terms strictly cash unless terms authorized.

11 Zora Street Warren NSW 2824
Ph. (02) 6847 3522
Air Conditioning Licence AU35668

PO Box 5485 Wagga Wagga NSW 2650
Email: accounts@hutcheonandpearce.com.au
www.hutcheonandpearce.com.au
ABN 68 169 674 033 ACN 169 674 033

*** DOCUMENT COPY ***

SERVICE TAX INVOICE

| | |
|----------------------|-------------------|
| Document No.: | 3961655 |
| Document Date: | 5/06/2026 |
| Repair Order No.: | 481739 |
| Rego No.: | A200381 |
| Make/Model: | JOHN DEERE 8R 230 |
| Vehicle ID No.: | 1RW8230DCNA200381 |
| Fleet No.: | 8R 230 #6 |
| Odometer: | 4863 |
| Delivery Date: | 08/06/2022 |
| Invoice To: | |
| Customer ABN: | |
| Tax Exempt No.: | |
| P/Order No.: | |
| Page: | 1 of 4 |

Service Plan Calculator V2.9

1. Cab Inspection

- :Check Light operation and condition
- :Check Wiper operation and condition
- :Check Stereo operation
- :Check transmission linkages and controls
- :Check PTO operation
- :Check loader operation (if applicable)
- :Clean windscreen and wipe out cab floor
- :Check heater and A/C operation
- :Reset service reminder

2. Maintenance

- :Change engine oil and filter element
- :Change primary, final fuel filter & Water separator
- :Change fuel tank vent filter (s)
- :Change transmission and hydraulic oil and oil filters
- :Change front axle and final drive oils
- :Check air intake system
- :Inspect engine air filter, cab and recirculation filters (s)
- :Check hitch components for wear and lubricate
- :Lubricate VARI-COOL fan drive
- :Lubricate steering and suspension components
- :Clean hydraulic oil suction screen
- :Change Differential oil (8RT, 8RX)
- :Change suspension compressor filter, clean air bag. (8RT)
- :Lubricate Track tension cylinders (8RT)
- :Change SCV Pilot (8RX) & Hydraulic Steering filter (8RT)
- :Change fan drive housing oil (8RX)

LABOUR

\$2,415.75

11 Zora Street Warren NSW 2824
Ph. (02) 6847 3522
Air Conditioning Licence AU35668

PO Box 5485 Wagga Wagga NSW 2650
Email: accounts@hutcheonandpearce.com.au
www.hutcheonandpearce.com.au
ABN 68 169 674 033 ACN 169 674 033

*** DOCUMENT COPY ***

SERVICE TAX INVOICE

| | |
|----------------------|-------------------|
| Document No.: | 3961655 |
| Document Date: | 5/06/2026 |
| Repair Order No.: | 481739 |
| Rego No.: | A200381 |
| Make/Model: | JOHN DEERE 8R 230 |
| Vehicle ID No.: | 1RW8230DCNA200381 |
| Fleet No.: | 8R 230 #6 |
| Odometer: | 4863 |
| Delivery Date: | 08/06/2022 |
| Invoice To: | |
| Customer ABN: | |
| Tax Exempt No.: | |
| P/Order No.: | |
| Page: | 2 of 4 |

Service Plan Calculator V2.9

LABOUR

3. Drawbar & 3PL & PTO

- :Test operation (external controls)
- :Check for leaks
- :Check condition of linkages
- :Check shaft & guard condition
- :Lubricate draft link support shaft bushing
- 4. Front & Rear Axle
- :Test drive and test operation of suspension and steering
- :Check suspension and steering components damaged e.g Pivot bushes, suspension cylinders ball joint boots
- :Check for leaks
- :Check tyre pressures. (check pressures are set evenly)
- :Check rim and weight condition (were fitted)
- :Tighten wheel and wheel weight bolts

5. Transmission

- :Test drive and test operation and check for leaks
- :Check manual brakes
- :Check neutral start system

6. Selective Control Valves

- :Test operation – external and electronically and check for leaks
- :Check covers are installed
- :Check drains aren't blocked and are fitted
- :Check and empty drain reservoir

7. Engine

- :Check water pump and fan bearing
- :Check fan belt and pulleys / idler bearings
- :Check for coolant leaks and condition of hoses
- :Check for oil and fuel leaks
- :Check auxiliary drive belt

11 Zora Street Warren NSW 2824
 Ph. (02) 6847 3522
 Air Conditioning Licence AU35668

PO Box 5485 Wagga Wagga NSW 2650
 Email: accounts@hutcheonandpearce.com.au
www.hutcheonandpearce.com.au
 ABN 68 169 674 033 ACN 169 674 033

*** DOCUMENT COPY ***

SERVICE TAX INVOICE

| | |
|----------------------|-------------------|
| Document No.: | 3961655 |
| Document Date: | 5/06/2026 |
| Repair Order No.: | 481739 |
| Rego No.: | A200381 |
| Make/Model: | JOHN DEERE 8R 230 |
| Vehicle ID No.: | 1RW8230DCNA200381 |
| Fleet No.: | 8R 230 #6 |
| Odometer: | 4863 |
| Delivery Date: | 08/06/2022 |
| Invoice To: | |
| Customer ABN: | |
| Tax Exempt No.: | |
| P/Order No.: | |
| Page: | 3 of 4 |

Service Plan Calculator V2.9

LABOUR

8. Track Machines

- :Check Track alignment & track wear.
- :Check Mid-Roller, Drive wheel sleeve, wedges and Idler wheels
- :Check Track trash build-up
- :Check Walking beam suspension system. (8RT)
- :Check Mid roller oil level (Optional oil change additional cost)
- :Change MFWD Axle Housing & Hub oil. (8RX)
- :Check upper track roller and idler wheel hub oil (8RX)

ADDITIONAL SERVICE NOTES:

Found during service
 Multiple fault codes logged in the system.
 All codes cleared nil returned
 Found wing indicators missing LEDs
 Found paint peeling off the bonnet
 Found rear pto switch inop
 Found battery's missing clamp
 Found exhaust manifold leaking
 Found oil leak from oil filter aux port
 Found oil leak from right rear of motor sensor
 Found heavy debris on left final drive drain plug further diagnosis required
 Found lower cooler holder missing and being held in by cable ties
 Removed both transmission and hydraulic screens and found very minimal material on either cleaned and refitted
 Found moderate movement in tensioner pulley
 Found multiple cabin air vents broken

| <u>Part Number</u> | <u>Part Description</u> | <u>Serial No</u> | <u>Quantity</u> | <u>Nett Value</u> | <u>Total Cost</u> |
|--------------------|-------------------------------------|------------------|-----------------|-------------------|-------------------|
| STGEAROIL80W/90 | gear oil per ltr (1L of CP8221) | | 8.00 | 12.48 | 99.84 |
| STPLUS50 | PLUS 50 II (PER LTR) (1L of CP6660) | | 27.50 | 8.90 | 244.75 |

www.hutcheonandpearce.com.au



11 Zora Street Warren NSW 2824
 Ph. (02) 6847 3522
 Air Conditioning Licence AU35668

PO Box 5485 Wagga Wagga NSW 2650
 Email: accounts@hutcheonandpearce.com.au
 www.hutcheonandpearce.com.au
 ABN 68 169 674 033 ACN 169 674 033

*** DOCUMENT COPY ***

SERVICE TAX INVOICE

| | |
|----------------------|-------------------|
| Document No.: | 3961655 |
| Document Date: | 5/06/2026 |
| Repair Order No.: | 481739 |
| Rego No.: | A200381 |
| Make/Model: | JOHN DEERE 8R 230 |
| Vehicle ID No.: | 1RW8230DCNA200381 |
| Fleet No.: | 8R 230 #6 |
| Odometer: | 4863 |
| Delivery Date: | 08/06/2022 |
| Invoice To: | |
| Customer ABN: | |
| Tax Exempt No.: | |
| P/Order No.: | |
| Page: | 4 of 4 |

Service Plan Calculator V2.9

| | | | | <u>LABOUR</u> |
|----------------------|--------------------------------------|--------|---------------|-------------------|
| RE596661 | FILTER ELE | 2.00 | 240.02 | 480.04 |
| RE509672 | FILTER ELE | 1.00 | 50.96 | 50.96 |
| RE269061 | FILTER KIT | 1.00 | 83.31 | 83.31 |
| DZ130550 | FILTER ELE | 1.00 | 270.56 | 270.56 |
| DZ112919 | FILTER ELE | 1.00 | 223.25 | 223.25 |
| STHY-GARD | HY-GARD TRANS/HYD.OIL (1L of CP2103) | 152.00 | 8.83 | 1,342.16 |
| AT365869 | FILTER ELE | 1.00 | 110.26 | 110.26 |
| R26543 | O-RING | 2.00 | 18.56 | 37.12 |
| Parts Totals: | | | 196.50 | \$2,942.25 |

Technician Labour Postings

| <u>Technician</u> | <u>Job Description</u> | <u>Type</u> | <u>Clocked In Date</u> | <u>Start Time</u> | <u>Finish Time</u> | <u>Hours Worked</u> | <u>Hours Invoiced</u> |
|-------------------|------------------------|-------------|------------------------|-------------------|--------------------|---------------------|-----------------------|
| ROBERTSSJ | MP8R4500HRS* | S | 04/06/2026 | 12:30:58 | 16:55:00 | 4.416700 | 7.160700 |
| ROBERTSSJ | MP8R4500HRS* | S | 04/06/2026 | 12:11:31 | 12:30:58 | 0.316700 | 0.513500 |
| ROBERTSSJ | MP8R4500HRS* | S | 04/06/2026 | 07:55:01 | 11:41:05 | 3.766700 | 6.106900 |
| ROBERTSSJ | MP8R4500HRS* | S | 04/06/2026 | 06:29:50 | 07:55:00 | 1.433400 | 2.323900 |

Miscellaneous Charges

| | |
|--------------------|----------------|
| Environmental Levy | \$5.00 |
| Consumables | \$25.00 |

| | |
|---------------------------|-------------------|
| Sub Total for All: | \$5,388.00 |
| Rounding: | \$0.00 |
| GST: | \$0.00 |
| Total: | \$5,388.00 |

PAYMENT OPTIONS:

PayID: 68169674033
 Bank Details: WESTPAC WAGGA WAGGA BSB: 032769 A/C No: 624222
 PLEASE QUOTE YOUR HP ACCOUNT NUMBER IN THE REFERENCE

Our goods come with guarantees that cannot be excluded under the Australian Consumer Law. You are entitled to a replacement or refund for a major failure and for compensation for any other reasonably foreseeable loss or damage. You are also entitled to have the goods repaired or replaced if the goods fail to be of acceptable quality and the failure does not amount to a major failure. Payment Terms strictly cash unless terms authorized.