

11 Zora Street Warren NSW 2824
 Ph. (02) 6847 3522
 Air Conditioning Licence AU35668

PO Box 5485 Wagga Wagga NSW 2650
 Email: accounts@hutcheonandpearce.com.au
www.hutcheonandpearce.com.au
 ABN 68 169 674 033 ACN 169 674 033

*** DOCUMENT COPY ***

Invoice To:

SERVICE TAX INVOICE

Document No.:	3702248
Document Date:	11/11/2024
Repair Order No.:	437443
Rego No.:	A200408
Make/Model:	JOHN DEERE 8R 230
Vehicle ID No.:	1RW8230DLNA200408
Fleet No.:	3
Odometer:	3069
Delivery Date:	08/06/2022
Invoice To:	
Customer ABN:	
Tax Exempt No.:	
P/Order No.:	
Page:	1 of 5

Service Plan Calculator V2.9

1. Cab Inspection
 - Check Light operation and condition
 - Check Wiper operation and condition
 - Check Stereo operation
 - Check transmission linkages and controls
 - Check PTO operation
 - Check loader operation (if applicable)
 - Clean windscreen and wipe out cab floor
 - Check heater and A/C operation
 - Check cab suspension components/ bushings. (8RT)
2. Maintenance
 - Change engine oil and filter element
 - Change primary, final fuel filter & Water separator
 - Change fuel tank vent filter (s)
 - Change transmission and hydraulic oil and oil filters
 - Change front axle and final drive oils
 - Change Coolant
 - Check air intake system
 - Change engine air filter (s) cab air and recirculation filters
 - Check hitch components for wear and lubricate
 - Lubricate VARI-COOL fan drive
 - Lubricate steering and suspension components
 - Clean hydraulic oil suction screen
 - Check valve clearance (8RX, T3 & FT4 Machines Only)
 - Change Differential oil (8RT, 8RX)
 - Change suspension compressor filter, clean air bag. (8RT)
 - Lubricate Track tension cylinders (8RT)

LABOUR

\$1,537.00

11 Zora Street Warren NSW 2824
Ph. (02) 6847 3522
Air Conditioning Licence AU35668

PO Box 5485 Wagga Wagga NSW 2650
Email: accounts@hutcheonandpearce.com.au
www.hutcheonandpearce.com.au
ABN 68 169 674 033 ACN 169 674 033

*** DOCUMENT COPY ***

Invoice To:

SERVICE TAX INVOICE

Document No.:	3702248
Document Date:	11/11/2024
Repair Order No.:	437443
Rego No.:	A200408
Make/Model:	JOHN DEERE 8R 230
Vehicle ID No.:	1RW8230DLNA200408
Fleet No.:	3
Odometer:	3069
Delivery Date:	08/06/2022
Invoice To:	
Customer ABN:	
Tax Exempt No.:	
P/Order No.:	
Page:	2 of 5

Service Plan Calculator V2.9

LABOUR

- Change SCV Pilot (8RX) & Hydraulic Steering filter (8RT)
- 3. Drawbar & 3PL & PTO
 - Test operation (external controls) & check for leaks
 - Check condition of linkages
 - Check shaft & guard condition
 - Lubricate draft link support shaft bushing
 - 4. Front & Rear Axle
 - Test drive and test operation of suspension and steering
 - Check suspension and steering components damaged e.g Pivot bushes, suspension cylinders ball joint boots
 - Check for leaks
 - Check tyre pressures. (check pressures are set evenly)
 - Check rim and weight condition (were fitted)
 - Tighten wheel and wheel weight bolts
- 5. Transmission
 - Test drive and test operation. Check for leaks.
 - Check manual brakes
 - Check neutral start system
- 6. Selective Control Valves
 - Test operation – external and electronically and check for leaks
 - Check covers are installed
 - Check drains aren't blocked and are fitted. Drain reservoir.
- 7. Engine
 - Check water pump and fan bearing
 - Check fan belt and pulleys / idler bearings & auxiliary drive belt.
 - Check for coolant leaks and condition of hoses
 - Check for oil and fuel leaks
- 8. Track Machines
 - Check Track alignment & track wear.

11 Zora Street Warren NSW 2824
 Ph. (02) 6847 3522
 Air Conditioning Licence AU35668

PO Box 5485 Wagga Wagga NSW 2650
 Email: accounts@hutcheonandpearce.com.au
www.hutcheonandpearce.com.au
 ABN 68 169 674 033 ACN 169 674 033

*** DOCUMENT COPY ***

SERVICE TAX INVOICE

Document No.:	3702248
Document Date:	11/11/2024
Repair Order No.:	437443
Rego No.:	A200408
Make/Model:	JOHN DEERE 8R 230
Vehicle ID No.:	1RW8230DLNA200408
Fleet No.:	3
Odometer:	3069
Delivery Date:	08/06/2022
Invoice To:	
Customer ABN:	
Tax Exempt No.:	
P/Order No.:	
Page:	3 of 5

Service Plan Calculator V2.9

LABOUR

Check Mid-Roller, Drive wheel sleeve, wedges and Idler wheels
 Check Track trash build-up
 Check Walking beam air suspension system. (8RT)
 Check Drive wheel hub & Mid roller oil level.(Optional oil change additional cost)
 Change Air Brake Dryer Filter (8RX) 2yrs or 1000hrs
 Change MFWD Axle Housing & Hub oil, clean breather (8RX)
 Check upper track roller and idler wheel hub oil (8RX)
 ADDITIONAL SERVICE NOTES:
 CARRIED OUT SERVICE AS PER SCHEDULE
 CARRIED OUT VALVE ADJUSTMENT
 REMOVED BOTH SCREENS VERY MINIMAL CONTAMINANTS ON SCREENS.
 FOUND HEAVY MATERIAL ON AXLE AND FINAL DRIVE DRAIN PLUGS.
 FOUND RIGHT REAR LOWER CAB WORK LIGHT INOP
 FOUND LEFT STEERING RAM WEEPING
 FOUND WATER IN FUEL CONRCTIR BROKEN
 FOUND COOLANT DRAIN ON MOTOR BROKEN WILL NEED TO BE REPLACED AT NEXT COOLANT SERVICE
 FOUND EXHAUST MANIFOLD LEAKING AT CENTRE JOIN.
 REQUIRES A FULL SET OF SCV O RINGS AS THEY ARE LEAKING
 CARRIED OUT SOFTWARE UPDATES
 CARRIED OUT TEST DRIVE ALL OKAY

<u>Part Number</u>	<u>Part Description</u>	<u>Serial No</u>	<u>Quantity</u>	<u>Nett Value</u>	<u>Total Cost</u>
SERVICE PLAN TRAVEL	SERVICE PLAN TRAVEL		1.00	100.00	100.00
STHY-GARD	HY-GARD TRANS/HYD.OIL (1L of CP2103)		150.00	6.64	996.00
STPLUS50	PLUS 50 II (PER LTR) (1L of CP6660)		26.00	7.33	190.58
RE596661	FILTER ELE		2.00	225.30	450.60

www.hutcheonandpearce.com.au



11 Zora Street Warren NSW 2824
 Ph. (02) 6847 3522
 Air Conditioning Licence AU35668

PO Box 5485 Wagga Wagga NSW 2650
 Email: accounts@hutcheonandpearce.com.au
 www.hutcheonandpearce.com.au
 ABN 68 169 674 033 ACN 169 674 033

*** DOCUMENT COPY ***



SERVICE TAX INVOICE

Document No.:	3702248
Document Date:	11/11/2024
Repair Order No.:	437443
Rego No.:	A200408
Make/Model:	JOHN DEERE 8R 230
Vehicle ID No.:	1RW8230DLNA200408
Fleet No.:	3
Odometer:	3069
Delivery Date:	08/06/2022
Invoice To:	
Customer ABN:	
Tax Exempt No.:	
P/Order No.:	
Page:	4 of 5

Service Plan Calculator V2.9

				<u>LABOUR</u>
RE596318	AIR FILTER	1.00	235.44	235.44
RE596317	AIR FILTER	1.00	252.87	252.87
RE593819	AIR FILTER	1.00	284.09	284.09
RE509672	FILTER ELE	1.00	246.23	246.23
RE284091	Air Filter	1.00	169.82	169.82
RE269061	FILTER KIT	1.00	278.18	278.18
DZ130550	FILTER ELE	1.00	386.82	386.82
DZ112919	FILTER ELE	1.00	309.58	309.58
STCOOLANT	COOLANT PER L (1L of CP8278)	33.00	6.43	212.19
AT365869	FILTER ELE	1.00	291.32	291.32
R526607	SEAL	1.00	280.54	280.54
R26543	O-RING	2.00	118.85	237.70

Parts Totals: 224.00 \$4,921.96

Technician Labour Postings

<u>Technician</u>	<u>Job Description</u>	<u>Type</u>	<u>Clocked In Date</u>	<u>Start Time</u>	<u>Finish Time</u>	<u>Hours Worked</u>	<u>Hours Invoiced</u>
ROBERTSSJ	MP8R3000HRS*	S	06/11/2024	09:21:15	13:15:57	3.900000	4.477200



11 Zora Street Warren NSW 2824
 Ph. (02) 6847 3522
 Air Conditioning Licence AU35668

PO Box 5485 Wagga Wagga NSW 2650
 Email: accounts@hutcheonandpearce.com.au
 www.hutcheonandpearce.com.au
 ABN 68 169 674 033 ACN 169 674 033

*** DOCUMENT COPY ***

SERVICE TAX INVOICE

Invoice To:

Document No.:	3702248
Document Date:	11/11/2024
Repair Order No.:	437443
Rego No.:	A200408
Make/Model:	JOHN DEERE 8R 230
Vehicle ID No.:	1RW8230DLNA200408
Fleet No.:	3
Odometer:	3069
Delivery Date:	08/06/2022
Invoice To:	
Customer ABN:	
Tax Exempt No.:	
P/Order No.:	
Page:	5 of 5

ROBERTSSJ MP8R3000HRS* S 05/11/2024 16:22:40 21:42:45 5.333300 6.122800

Miscellaneous Charges

Environmental Levy	\$100.00
Consumables	\$750.00

Sub Total for All:	\$7,308.96
Rounding:	\$0.00
GST:	\$0.00
Total:	\$7,308.96

PAYMENT OPTIONS:
 PayID: 68169674033
 Bank Details: WESTPAC WAGGA WAGGA BSB: 032769 A/C No: 624222
 PLEASE QUOTE YOUR HP ACCOUNT NUMBER IN THE REFERENCE

Our goods come with guarantees that cannot be excluded under the Australian Consumer Law. You are entitled to a replacement or refund for a major failure and for compensation for any other reasonably foreseeable loss or damage. You are also entitled to have the goods repaired or replaced if the goods fail to be of acceptable quality and the failure does not amount to a major failure. Payment Terms strictly cash unless terms authorized.



23 Boolcarrol Rd Wee Waa NSW 2388
 Ph. (02) 6795 8000
 Air Conditioning Licence AU35668

PO Box 5485 Wagga Wagga NSW 2650
 Email: accounts@hutcheonandpearce.com.au
 www.hutcheonandpearce.com.au
 ABN 68 169 674 033 ACN 169 674 033

*** DOCUMENT COPY ***

SERVICE TAX INVOICE

Document No.:	3747795
Document Date:	6/02/2025
Repair Order No.:	441845
Rego No.:	A200408
Make/Model:	JOHN DEERE 8R 230
Vehicle ID No.:	1RW8230DLNA200408
Fleet No.:	3
Odometer:	
Delivery Date:	08/06/2022
Invoice To:	2022138
Customer ABN:	
Tax Exempt No.:	
P/Order No.:	2-2738
Page:	1 of 1



Check steer code

Checked steering code
 Found wheel angle sensor harness faulty
 Ordered a new harness
 Removed old harness
 Installed new harness
 Tested
 Working correctly

LABOUR
\$480.00

<u>Part Number</u>	<u>Part Description</u>	<u>Serial No</u>	<u>Quantity</u>	<u>Nett Value</u>	<u>Total Cost</u>
RWA11025	Misc		5.00	10.54	52.70
RE593639	Misc		1.00	319.67	319.67
RE577560	BREAKAWAY		4.00	262.44	1,049.76
RE186599	SEAL		4.00	20.12	80.48
R222761	O-RING		4.00	8.28	33.12
57M9789	Elec. Connector Housing		1.00	11.61	11.61
Parts Totals:			19.00		\$1,547.34

Miscellaneous Charges

Consumables **\$20.00**

Sub Total for All:	\$2,047.34
Rounding:	\$0.00
GST:	\$204.73
Total:	\$2,252.07

PAYMENT OPTIONS:

PayID: 68169674033
 Bank Details: WESTPAC WAGGA WAGGA BSB: 032769 A/C No: 624222

****PLEASE QUOTE YOUR HP ACCOUNT NUMBER IN THE REFERENCE****

Our goods come with guarantees that cannot be excluded under the Australian Consumer Law. You are entitled to a replacement or refund for a major failure and for compensation for any other reasonably foreseeable loss or damage. You are also entitled to have the goods repaired or replaced if the goods fail to be of acceptable quality and the failure does not amount to a major failure. Payment Terms strictly cash unless terms authorized.

11 Zora Street Warren NSW 2824
Ph. (02) 6847 3522
Air Conditioning Licence AU35668

PO Box 5485 Wagga Wagga NSW 2650
Email: accounts@hutcheonandpearce.com.au
www.hutcheonandpearce.com.au
ABN 68 169 674 033 ACN 169 674 033

*** DOCUMENT COPY ***

Invoice To:

SERVICE TAX INVOICE

Document No.:	3571542
Document Date:	19/02/2024
Repair Order No.:	405434
Rego No.:	A200408
Make/Model:	JOHN DEERE 8R 230
Vehicle ID No.:	1RW8230DLNA200408
Fleet No.:	3
Odometer:	1995
Delivery Date:	08/06/2022
Invoice To:	
Customer ABN:	
Tax Exempt No.:	
P/Order No.:	
Page:	1 of 3

Service Plan Calculator V2.9

1. Cab Inspection
 - :Check Light operation and condition
 - :Check Wiper operation and condition
 - :Check Stereo operation
 - :Check transmission linkages and controls
 - :Check PTO operation
 - :Check loader operation (if applicable)
 - :Clean windscreen and wipe out cab floor
 - :Check heater and A/C operation
 - :Reset service reminder
 - :Inspect seat belt(s)
 - :Check cab suspension components/ bushings. (8RT)
2. Maintenance
 - :Change engine oil and filter element
 - :Change primary and final fuel filter
 - :Check air intake system
 - :Change engine air filter (s)
 - :Change cab air and recirculation filters
 - :Check hitch components for wear and lubricate
 - :Lubricate VARI-COOL fan drive
 - :Lubricate steering and suspension components
 - :Check battery electrolyte level and tighten terminals
 - :Check valve clearance (T2 Machines Only)
 - :Clean suspension compressor & filter & air bag. (8RT)
 - :Lubricate Track tension cylinders (8RT)
3. Drawbar & 3PL & PTO
 - :Test operation (external controls)
 - :Check for leaks
 - :Check condition of linkages
 - :Check shaft condition
 - :Check guards are in place
4. Front & Rear Axle

LABOUR
\$842.44

11 Zora Street Warren NSW 2824
 Ph. (02) 6847 3522
 Air Conditioning Licence AU35668

PO Box 5485 Wagga Wagga NSW 2650
 Email: accounts@hutcheonandpearce.com.au
www.hutcheonandpearce.com.au
 ABN 68 169 674 033 ACN 169 674 033

*** DOCUMENT COPY ***



SERVICE TAX INVOICE

Document No.:	3571542
Document Date:	19/02/2024
Repair Order No.:	405434
Rego No.:	A200408
Make/Model:	JOHN DEERE 8R 230
Vehicle ID No.:	1RW8230DLNA200408
Fleet No.:	3
Odometer:	1995
Delivery Date:	08/06/2022
Invoice To:	
Customer ABN:	
Tax Exempt No.:	
P/Order No.:	
Page:	2 of 3

- :Test drive and test operation of suspension and steering
- :Check suspension and steering components damaged e.g Pivot bushes, suspension cylinders ball joint boots
- :Check for leaks
- :Check tyre pressures. (check pressures are set evenly)
- :Check rim and weight condition (were fitted)
- :Tighten wheel and wheel weight bolts
- 5. Transmission
 - :Test drive and test operation
 - :Check manual brakes
 - :Check for leaks
 - :Check neutral start system
- 6. Selective Control Valves
 - :Test operation – external and electronically
 - :Check for leaks
 - :Check covers are installed
 - :Check drains aren't blocked and are fitted
 - :Check and empty drain reservoir
- 7. Engine
 - :Check water pump and fan bearing
 - :Check fan belt and pulleys / idler bearings
 - :Check for coolant leaks and condition of hoses
 - :Check for oil and fuel leaks
- 8. Track Machines
 - :Check Track alignment & track wear.
 - :Check Mid-Roller, Drive wheel sleeve, wedges and Idler wheels
 - :Check Track trash build-up.
 - :Check Walking beam suspension system & bumper stops. (8RT)
 - :Clean MFWD axle vent breather (8RX)
 - :Change Air Brake Dryer Filter (8RX) 2yrs or 1000hrs

DZ110558	Filter Element	1.00	213.45	213.45
----------	----------------	------	--------	--------

11 Zora Street Warren NSW 2824
 Ph. (02) 6847 3522
 Air Conditioning Licence AU35668

PO Box 5485 Wagga Wagga NSW 2650
 Email: accounts@hutcheonandpearce.com.au
 www.hutcheonandpearce.com.au
 ABN 68 169 674 033 ACN 169 674 033

*** DOCUMENT COPY ***

SERVICE TAX INVOICE

Document No.:	3571542
Document Date:	19/02/2024
Repair Order No.:	405434
Rego No.:	A200408
Make/Model:	JOHN DEERE 8R 230
Vehicle ID No.:	1RW8230DLNA200408
Fleet No.:	3
Odometer:	1995
Delivery Date:	08/06/2022
Invoice To:	
Customer ABN:	
Tax Exempt No.:	
P/Order No.:	
Page:	3 of 3

Service Plan Calculator V2.9

				<u>LABOUR</u>
RE509672	FILTER ELE	1.00	57.79	57.79
RE539465	Filter Element	1.00	221.91	221.91
RE596317	AIR FILTER	1.00	242.04	242.04
RE596318	AIR FILTER	1.00	128.28	128.28
CP6658	PLUS 50 ENGINE OIL-20LITRES	1.00	174.89	174.89
Parts Totals:		6.00		\$1,038.36

Technician Labour Postings

<u>Technician</u>	<u>Job Description</u>	<u>Type</u>	<u>Clocked In Date</u>	<u>Start Time</u>	<u>Finish Time</u>	<u>Hours Worked</u>	<u>Hours Invoiced</u>
ROBERTSSJ	MP8R2000HRS*	S	13/02/2024	07:27:00	11:00:00	3.550000	5.809900

Miscellaneous Charges

Consumables **\$200.00**

Sub Total for All:	\$2,080.80
Rounding:	\$0.00
GST:	\$0.00
Total:	\$2,080.80

PAYMENT OPTIONS:

PayID: 68169674033
 Bank Details: WESTPAC WAGGA WAGGA BSB: 032769 A/C No: 624222

****PLEASE QUOTE YOUR HP ACCOUNT NUMBER IN THE REFERENCE****

Our goods come with guarantees that cannot be excluded under the Australian Consumer Law. You are entitled to a replacement or refund for a major failure and for compensation for any other reasonably foreseeable loss or damage. You are also entitled to have the goods repaired or replaced if the goods fail to be of acceptable quality and the failure does not amount to a major failure. Payment Terms strictly cash unless terms authorized.

11 Zora Street Warren NSW 2824
 Ph. (02) 6847 3522
 Air Conditioning Licence AU35668

PO Box 5485 Wagga Wagga NSW 2650
 Email: accounts@hutcheonandpearce.com.au
www.hutcheonandpearce.com.au
 ABN 68 169 674 033 ACN 169 674 033

*** DOCUMENT COPY ***

SERVICE TAX INVOICE

Document No.:	3780872
Document Date:	16/04/2025
Repair Order No.:	454413
Rego No.:	A200408
Make/Model:	JOHN DEERE 8R 230
Vehicle ID No.:	1RW8230DLNA200408
Fleet No.:	3
Odometer:	3471
Delivery Date:	08/06/2022
Invoice To:	
Customer ABN:	
Tax Exempt No.:	
P/Order No.:	
Page:	1 of 2

Service Plan Calculator V2.9

LABOUR

\$544.11

ADDITIONAL SERVICE NOTES:

CARRIED OUT SERVICE AS PER SCHEDULE DURING
 WSS UNABLE TO CHECK FOR UPDATES DUE TO POOR SERVICE.
 FOUND WATER IN FUEL SENSOR CONNECTOR RETAINER BROKEN REQUIRED A NEW PLUG.
 FOUND RIGHT REAR LOWER CAB LIGHT INOP
 FOUND BOTH TAILLIGHTS INOP
 FOUND ENGINE AIR FILTER EXCESSIVELY BLOCKED THESE NEED TO BE BLOWN OUT REGULARLY
 FOUND FRONT LEFT STEER CYLINDER LEAKING.
 REQUIRES RESEAL.
 NO FURTHER FAULTS FOUND SEE PHOTOS OF FAULTS FOUND
 ESTIMATE REQUIRED: Y
 CUSTOMER URGENCY: LOW

<u>Part Number</u>	<u>Part Description</u>	<u>Serial No</u>	<u>Quantity</u>	<u>Nett Value</u>	<u>Total Cost</u>
DZ130550	FILTER ELE		1.00	286.82	286.82
DZ112919	FILTER ELE		1.00	209.58	209.58
SERVICE PLAN TRAVEL	SERVICE PLAN TRAVEL		1.00	100.00	100.00
STHY-GARD	HY-GARD TRANS/HYD.OIL (1L of CP2103)		7.50	6.64	49.80
STPLUS50	PLUS 50 II (PER LTR) (1L of CP6660)		27.50	7.33	201.58
RE509672	FILTER ELE		1.00	48.54	48.54
Parts Totals:			39.00		\$896.32

Technician Labour Postings

<u>Technician</u>	<u>Job Description</u>	<u>Type</u>	<u>Clocked In Date</u>	<u>Start Time</u>	<u>Finish Time</u>	<u>Hours Worked</u>	<u>Hours Invoiced</u>
ROBERTSSJ	MP8R3500HRS*	S	11/04/2025	11:20:19	11:26:00	0.100000	0.105700

11 Zora Street Warren NSW 2824
 Ph. (02) 6847 3522
 Air Conditioning Licence AU35668

PO Box 5485 Wagga Wagga NSW 2650
 Email: accounts@hutcheonandpearce.com.au
www.hutcheonandpearce.com.au
 ABN 68 169 674 033 ACN 169 674 033

*** DOCUMENT COPY ***

SERVICE TAX INVOICE

Invoice To:

Document No.:	3780872
Document Date:	16/04/2025
Repair Order No.:	454413
Rego No.:	A200408
Make/Model:	JOHN DEERE 8R 230
Vehicle ID No.:	1RW8230DLNA200408
Fleet No.:	3
Odometer:	3471
Delivery Date:	08/06/2022
Invoice To:	
Customer ABN:	
Tax Exempt No.:	
P/Order No.:	
Page:	2 of 2

ROBERTSSJ MP8R3500HRS* S 11/04/2025 06:26:05 09:53:00 3.450000 3.646800

Miscellaneous Charges

Environmental Levy
 Consumables

\$5.00
\$20.00

PAYMENT OPTIONS:

PayID: 68169674033
 Bank Details: WESTPAC WAGGA WAGGA BSB: 032769 A/C No: 624222

****PLEASE QUOTE YOUR HP ACCOUNT NUMBER IN THE REFERENCE****

Sub Total for All:	\$1,465.43
Rounding:	\$0.00
GST:	\$0.00
Total:	\$1,465.43

Our goods come with guarantees that cannot be excluded under the Australian Consumer Law. You are entitled to a replacement or refund for a major failure and for compensation for any other reasonably foreseeable loss or damage. You are also entitled to have the goods repaired or replaced if the goods fail to be of acceptable quality and the failure does not amount to a major failure. Payment Terms strictly cash unless terms authorized.

11 Zora Street Warren NSW 2824
Ph. (02) 6847 3522
Air Conditioning Licence AU35668

PO Box 5485 Wagga Wagga NSW 2650
Email: accounts@hutcheonandpearce.com.au
www.hutcheonandpearce.com.au
ABN 68 169 674 033 ACN 169 674 033

*** DOCUMENT COPY ***

Invoice To:

SERVICE TAX INVOICE

Document No.:	3811856
Document Date:	25/06/2025
Repair Order No.:	462028
Rego No.:	A200408
Make/Model:	JOHN DEERE 8R 230
Vehicle ID No.:	1RW8230DLNA200408
Fleet No.:	3
Odometer:	4068
Delivery Date:	08/06/2022
Invoice To:	
Customer ABN:	
Tax Exempt No.:	
P/Order No.:	
Page:	1 of 4

Service Plan Calculator V2.9

1. Cab Inspection
 - Check Light operation and condition
 - Check Wiper operation and condition
 - Check Stereo operation
 - Check transmission linkages and controls
 - Check PTO operation
 - Check loader operation (if applicable)
 - Clean windscreen and wipe out cab floor
 - Check heater and A/C operation
 - Reset service reminder
 - Inspect seat belt(s)
 - Check cab suspension components/ bushings. (8RT)
2. Maintenance
 - Change engine oil and filter element
 - Change primary and final fuel filter
 - Check air intake system
 - Change engine air filter (s)
 - Change cab air and recirculation filters
 - Check hitch components for wear and lubricate
 - Lubricate VARI-COOL fan drive
 - Lubricate steering and suspension components
 - Check battery electrolyte level and tighten terminals
 - Check valve clearance (T2 Machines Only)
 - Clean suspension compressor & filter & air bag. (8RT)
 - Lubricate Track tension cylinders (8RT)
3. Drawbar & 3PL & PTO
 - Test operation (external controls)

LABOUR

\$475.01

11 Zora Street Warren NSW 2824
Ph. (02) 6847 3522
Air Conditioning Licence AU35668

PO Box 5485 Wagga Wagga NSW 2650
Email: accounts@hutcheonandpearce.com.au
www.hutcheonandpearce.com.au
ABN 68 169 674 033 ACN 169 674 033

*** DOCUMENT COPY ***

SERVICE TAX INVOICE

Document No.:	3811856
Document Date:	25/06/2025
Repair Order No.:	462028
Rego No.:	A200408
Make/Model:	JOHN DEERE 8R 230
Vehicle ID No.:	1RW8230DLNA200408
Fleet No.:	3
Odometer:	4068
Delivery Date:	08/06/2022
Invoice To:	
Customer ABN:	
Tax Exempt No.:	
P/Order No.:	
Page:	2 of 4

Service Plan Calculator V2.9

LABOUR

- Check for leaks
- Check condition of linkages
- Check shaft condition
- Check guards are in place
- 4. Front & Rear Axle
- Test drive and test operation of suspension and steering
- Check suspension and steering components damaged e.g Pivot bushes, suspension cylinders ball joint boots
- Check for leaks
- Check tyre pressures. (check pressures are set evenly)
- Check rim and weight condition (were fitted)
- Tighten wheel and wheel weight bolts
- 5. Transmission
- Test drive and test operation
- Check manual brakes
- Check for leaks
- Check neutral start system
- 6. Selective Control Valves
- Test operation – external and electronically
- Check for leaks
- Check covers are installed
- Check drains aren't blocked and are fitted
- Check and empty drain reservoir
- 7. Engine
- Check water pump and fan bearing
- Check fan belt and pulleys / idler bearings
- Check for coolant leaks and condition of hoses
- Check for oil and fuel leaks

11 Zora Street Warren NSW 2824
 Ph. (02) 6847 3522
 Air Conditioning Licence AU35668

PO Box 5485 Wagga Wagga NSW 2650
 Email: accounts@hutcheonandpearce.com.au
www.hutcheonandpearce.com.au
 ABN 68 169 674 033 ACN 169 674 033

*** DOCUMENT COPY ***

SERVICE TAX INVOICE

Document No.:	3811856
Document Date:	25/06/2025
Repair Order No.:	462028
Rego No.:	A200408
Make/Model:	JOHN DEERE 8R 230
Vehicle ID No.:	1RW8230DLNA200408
Fleet No.:	3
Odometer:	4068
Delivery Date:	08/06/2022
Invoice To:	
Customer ABN:	
Tax Exempt No.:	
P/Order No.:	
Page:	3 of 4

Service Plan Calculator V2.9

LABOUR

8. Track Machines

Check Track alignment & track wear.

Check Mid-Roller, Drive wheel sleeve, wedges and Idler wheels

Check Track trash build-up.

Check Walking beam suspension system & bumper stops. (8RT)

Clean MFWD axle vent breaker (8RX)

Change Air Brake Dryer Filter (8RX) 2yrs or 1000hrs

ADDITIONAL SERVICE NOTES:

CARRIED OUT SERVICE AS PER SCHEDULE

FOUND MULTIPLE FAULTS CODES LOGGED IN THE SYSTEM.

FOUND REAR RIGHT LOWER CAB LIGHT INOP

FOUND LEFT FRONT TIE ROD BOOT MISSING AND WAS UNABLE TO GET ANY GREASE INTO IT RECOMMEND REPLACEMENT ASAP

FOUND LEFT AND RIGHT STEERING RAM LEAKING AROUND GLAND NUT. RECOMMEND RESEALING.

FOUND SCV O RINGS POTENTIALLY LEAKING DID HAVE ATTACHMENT FITTED NEED TO TEST ALL COUPLERS.

FOUND COOLANT LEAK COMING FROM RADIATOR TOP HOSE TO THERMOSTAT. RECOMMEND REPLACEMENT OF HOSE AND CLAMPS.

FOUND SENSOR ON RIGHT REAR OF THE MOTOR LEAKING.

FOUND CONNECTOR ON WATER IN FUEL SENSOR BROKEN IS STILL HOLDING BUT RETAINER IS BROKEN WILL NEED NEW CONNECTOR

NO FURTHER FAULTS FOUND

<u>Part Number</u>	<u>Part Description</u>	<u>Serial No</u>	<u>Quantity</u>	<u>Nett Value</u>	<u>Total Cost</u>
RE596318	AIR FILTER		1.00	140.07	140.07
RE596317	AIR FILTER		1.00	269.37	269.37
RE593819	AIR FILTER		1.00	89.60	89.60
RE509672	FILTER ELE		1.00	56.00	56.00

11 Zora Street Warren NSW 2824
 Ph. (02) 6847 3522
 Air Conditioning Licence AU35668

PO Box 5485 Wagga Wagga NSW 2650
 Email: accounts@hutcheonandpearce.com.au
 www.hutcheonandpearce.com.au
 ABN 68 169 674 033 ACN 169 674 033

*** DOCUMENT COPY ***

SERVICE TAX INVOICE

Document No.:	3811856
Document Date:	25/06/2025
Repair Order No.:	462028
Rego No.:	A200408
Make/Model:	JOHN DEERE 8R 230
Vehicle ID No.:	1RW8230DLNA200408
Fleet No.:	3
Odometer:	4068
Delivery Date:	08/06/2022
Invoice To:	
Customer ABN:	
Tax Exempt No.:	
P/Order No.:	
Page:	4 of 4

Service Plan Calculator V2.9

				<u>LABOUR</u>
DZ130550	FILTER ELE	1.00	320.81	320.81
DZ112919	FILTER ELE	1.00	223.25	223.25
STPLUS50	PLUS 50 II (PER LTR) (1L of CP6660)	27.00	7.56	204.12
TA32591	AIR FILTER	1.00	252.57	252.57
Parts Totals:		34.00		\$1,555.79

Technician Labour Postings

<u>Technician</u>	<u>Job Description</u>	<u>Type</u>	<u>Clocked In Date</u>	<u>Start Time</u>	<u>Finish Time</u>	<u>Hours Worked</u>	<u>Hours Invoiced</u>
LEWISTRIST	MP8R4000HRS*	S	23/06/2025	11:45:00	13:30:00	1.750000	1.750000
ROBERTSSJ	MP8R4000HRS*	S	23/06/2025	11:35:54	13:00:26	1.416700	1.416700

Miscellaneous Charges

Environmental Levy **\$5.00**
 Consumables **\$45.00**

Sub Total for All:	\$2,080.80
Rounding:	\$0.00
GST:	\$0.00
Total:	\$2,080.80

PAYMENT OPTIONS:

PayID: 68169674033
 Bank Details: WESTPAC WAGGA WAGGA BSB: 032769 A/C No: 624222
 PLEASE QUOTE YOUR HP ACCOUNT NUMBER IN THE REFERENCE

Our goods come with guarantees that cannot be excluded under the Australian Consumer Law. You are entitled to a replacement or refund for a major failure and for compensation for any other reasonably foreseeable loss or damage. You are also entitled to have the goods repaired or replaced if the goods fail to be of acceptable quality and the failure does not amount to a major failure. Payment Terms strictly cash unless terms authorized.

11 Zora Street Warren NSW 2824
Ph. (02) 6847 3522
Air Conditioning Licence AU35668

PO Box 5485 Wagga Wagga NSW 2650
Email: accounts@hutcheonandpearce.com.au
www.hutcheonandpearce.com.au
ABN 68 169 674 033 ACN 169 674 033

*** DOCUMENT COPY ***

SERVICE TAX INVOICE

Document No.:	3837728
Document Date:	8/09/2025
Repair Order No.:	471063
Rego No.:	A200408
Make/Model:	JOHN DEERE 8R 230
Vehicle ID No.:	1RW8230DLNA200408
Fleet No.:	3
Odometer:	4452
Delivery Date:	08/06/2022
Invoice To:	
Customer ABN:	
Tax Exempt No.:	
P/Order No.:	
Page:	1 of 5

Service Plan Calculator V2.9

1. Cab Inspection
 - Check Light operation and condition
 - Check Wiper operation and condition
 - Check Stereo operation
 - Check transmission linkages and controls
 - Check PTO operation
 - Check loader operation (if applicable)
 - Clean windscreen and wipe out cab floor
 - Check heater and A/C operation
 - Reset service reminder
2. Maintenance
 - Change engine oil and filter element
 - Change primary, final fuel filter & Water separator
 - Change fuel tank vent filter (s)
 - Change transmission and hydraulic oil and oil filters
 - Change front axle and final drive oils
 - Check air intake system
 - Inspect engine air filter, cab and recirculation filters (s)
 - Check hitch components for wear and lubricate
 - Lubricate VARI-COOL fan drive
 - Lubricate steering and suspension components
 - Clean hydraulic oil suction screen
 - Change Differential oil (8RT, 8RX)
 - Change suspension compressor filter, clean air bag. (8RT)
 - Lubricate Track tension cylinders (8RT)
 - Change SCV Pilot (8RX) & Hydraulic Steering filter (8RT)
 - Change fan drive housing oil (8RX)

LABOUR

\$2,568.26

11 Zora Street Warren NSW 2824
 Ph. (02) 6847 3522
 Air Conditioning Licence AU35668

PO Box 5485 Wagga Wagga NSW 2650
 Email: accounts@hutcheonandpearce.com.au
www.hutcheonandpearce.com.au
 ABN 68 169 674 033 ACN 169 674 033

*** DOCUMENT COPY ***

SERVICE TAX INVOICE

Document No.:	3837728
Document Date:	8/09/2025
Repair Order No.:	471063
Rego No.:	A200408
Make/Model:	JOHN DEERE 8R 230
Vehicle ID No.:	1RW8230DLNA200408
Fleet No.:	3
Odometer:	4452
Delivery Date:	08/06/2022
Invoice To:	
Customer ABN:	
Tax Exempt No.:	
P/Order No.:	
Page:	2 of 5

Service Plan Calculator V2.9

LABOUR

3. Drawbar & 3PL & PTO

Test operation (external controls)
 Check for leaks

Check condition of linkages
 Check shaft & guard condition

Lubricate draft link support shaft bushing4. Front & Rear Axle

Test drive and test operation of suspension and steering

Check suspension and steering components damaged e.g Pivot bushes, suspension cylinders ball joint boots

Check for leaks

Check tyre pressures. (check pressures are set evenly)

Check rim and weight condition (were fitted)

Tighten wheel and wheel weight bolts

5. Transmission

Test drive and test operation and check for leaks

Check manual brakes

Check neutral start system

6. Selective Control Valves

Test operation – external and electronically and check for leaks

Check covers are installed

Check drains aren't blocked and are fitted

Check and empty drain reservoir

7. Engine

Check water pump and fan bearing

Check fan belt and pulleys / idler bearings

Check for coolant leaks and condition of hoses

Check for oil and fuel leaks

Check auxiliary drive belt

11 Zora Street Warren NSW 2824
Ph. (02) 6847 3522
Air Conditioning Licence AU35668

PO Box 5485 Wagga Wagga NSW 2650
Email: accounts@hutcheonandpearce.com.au
www.hutcheonandpearce.com.au
ABN 68 169 674 033 ACN 169 674 033

*** DOCUMENT COPY ***

SERVICE TAX INVOICE

Document No.:	3837728
Document Date:	8/09/2025
Repair Order No.:	471063
Rego No.:	A200408
Make/Model:	JOHN DEERE 8R 230
Vehicle ID No.:	1RW8230DLNA200408
Fleet No.:	3
Odometer:	4452
Delivery Date:	08/06/2022
Invoice To:	
Customer ABN:	
Tax Exempt No.:	
P/Order No.:	
Page:	3 of 5

Service Plan Calculator V2.9

8. Track Machines

- Check Track alignment & track wear.
- Check Mid-Roller, Drive wheel sleeve, wedges and Idler wheels
- Check Track trash build-up
- Check Walking beam suspension system. (8RT)
- Check Mid roller oil level (Optional oil change additional cost)
- Change MFWD Axle Housing & Hub oil. (8RX)
- Check upper track roller and idler wheel hub oil (8RX)

ADDITIONAL SERVICE NOTES:

DURING SERVICE FOUND MULTIPLE FAULT CODES LOGGED IN SYSTEM ALL CODES CLEARED AND NIL RETURNED.
FOUND LEFT REAR CAB VENT BROKEN
FOUND LEFT ARMREST HAS BEEN BROKEN AND FLOPPING AROUND NUT IS TIGHT INTERNAL PART OF ARMREST HAS BROKEN.
FOUND REAR INDICATOR MISSING LEDS
FOUND RIGHT REAR LOWER CAB WORK LIGHT INOP.
FOUND COOLERS HEAVILY CONTAMINATED THESE NEED TO BE CLEANED REGULARLY
FOUND OIL LEAK COMING FROM OIL FILTER HOUSING AUXILIARY PORT. TIGHTENED AND WILL NEED TO BE RECHECKED POSSIBLE O RING FAILING.
ALSO FOUND SIGNS OF A LEAK COMING FROM AROUND CAP OF OIL FILTER HOUSING. INSPECTED CAP AND WAS UNABLE TO FIND AND SIGNS OF CRACKING AND O RING WAS INTACT. WILL NEED FURTHER INSPECTION.
FOUND RIGHT REAR ENGINE SENSOR O RING HAD FAILED AND LEAKING WILL NEED NEW O RING.
FOUND BOTH STEERING CYLINDERS LEAKING.
FOUND EXHAUST MANIFOLD LEAKING HEAVILY AT SPLIT JOIN
FOUND BOTH TIE RODS ON STEERING ARM HAVE EXCESSIVE MOVEMENT AND BOOT TORN ON RIGHT SIDE.
FOUND OIL LEAK COMING FROM INJECTOR HARNESS WHERE GOES INTO THE HEAD.
FOUND WATER IN FUEL SENSOR HARNESS CONNECTOR BROKEN WILL REQUIRE NEW PLUG.
FOUND FUEL TAP LEAKING AT AUX FILTER P

LABOUR

11 Zora Street Warren NSW 2824
 Ph. (02) 6847 3522
 Air Conditioning Licence AU35668

PO Box 5485 Wagga Wagga NSW 2650
 Email: accounts@hutcheonandpearce.com.au
www.hutcheonandpearce.com.au
 ABN 68 169 674 033 ACN 169 674 033

*** DOCUMENT COPY ***

SERVICE TAX INVOICE

Document No.:	3837728
Document Date:	8/09/2025
Repair Order No.:	471063
Rego No.:	A200408
Make/Model:	JOHN DEERE 8R 230
Vehicle ID No.:	1RW8230DLNA200408
Fleet No.:	3
Odometer:	4452
Delivery Date:	08/06/2022
Invoice To:	
Customer ABN:	
Tax Exempt No.:	
P/Order No.:	
Page:	4 of 5

Service Plan Calculator V2.9

LABOUR

THE SUCTION SCREEN PIPE WAS SEIZED WITH BUILD UP OF DEBRIS AROUND PIPE AND JOIN WAS UNABLE TO REMOVE WITHOUT POSSIBLE DAMAGE TO PIPE
 RECOMMEND CLEANING AREA THOROUGHLY AND ATTEMPTING TO FREE UP OR NEW PIPE WILL BE REQUIRED.
 FOUND DOOR SEAL STARTING TO TEAR AT BOTTOM OF SEAL.
 FOUND OUTER DOOR HANDLE HAD EXCESSIVE MOVEMENT AND IS MAKING IT HARD TO OPEN THE DOOR UP.
 FOUND BATTERY COVER MISSING. RECOMMEND REINSTALLING OR A NEW COVER SUPPLIED TO PREVENT BUILD UP OF DEBRIS ON BATTERY AND CONNECTORS
 FOUND LOWER STEP BRACKET BENT

<u>Part Number</u>	<u>Part Description</u>	<u>Serial No</u>	<u>Quantity</u>	<u>Nett Value</u>	<u>Total Cost</u>
STGEAROIL80W/90	gear oil per ltr (1L of CP8221)		7.50	10.32	77.40
STHY-GARD	HY-GARD TRANS/HYD.OIL (1L of CP2103)		152.00	6.88	1,045.76
STCOOLANT	COOLANT PER L (1L of CP8278)		2.00	6.72	13.44
STPLUS50	PLUS 50 II (PER LTR) (1L of CP6660)		26.50	7.56	200.34
RE596661	FILTER ELE		2.00	240.02	480.04
RE509672	FILTER ELE		1.00	48.54	48.54
RE269061	FILTER KIT		1.00	83.31	83.31
DZ130550	FILTER ELE		1.00	305.53	305.53
DZ112919	FILTER ELE		1.00	223.25	223.25
AT365869	FILTER ELE		1.00	105.01	105.01
SERVICE PLAN TRAVEL	SERVICE PLAN TRAVEL		1.00	100.00	100.00



11 Zora Street Warren NSW 2824
 Ph. (02) 6847 3522
 Air Conditioning Licence AU35668

PO Box 5485 Wagga Wagga NSW 2650
 Email: accounts@hutcheonandpearce.com.au
 www.hutcheonandpearce.com.au
 ABN 68 169 674 033 ACN 169 674 033

*** DOCUMENT COPY ***

SERVICE TAX INVOICE

Document No.:	3837728
Document Date:	8/09/2025
Repair Order No.:	471063
Rego No.:	A200408
Make/Model:	JOHN DEERE 8R 230
Vehicle ID No.:	1RW8230DLNA200408
Fleet No.:	3
Odometer:	4452
Delivery Date:	08/06/2022
Invoice To:	
Customer ABN:	
Tax Exempt No.:	
P/Order No.:	
Page:	5 of 5



Service Plan Calculator V2.9

R26543	O-RING	2.00	18.56	37.12	<u>LABOUR</u>
		Parts Totals:	198.00	\$2,719.74	

Technician Labour Postings

<u>Technician</u>	<u>Job Description</u>	<u>Type</u>	<u>Clocked In Date</u>	<u>Start Time</u>	<u>Finish Time</u>	<u>Hours Worked</u>	<u>Hours Invoiced</u>
GOWERCHA	MP8R4500HRS*	S	04/09/2025	18:06:00	20:08:00	2.033300	2.268000
GOWERCHA	MP8R4500HRS*	S	04/09/2025	13:56:00	18:06:00	4.166700	4.647600
GOWERCHA	MP8R4500HRS*	S	04/09/2025	11:56:00	13:25:00	1.483400	1.654600
ROBERTSSJ	MP8R4500HRS*	S	04/09/2025	18:06:31	20:07:00	2.016700	2.249500
ROBERTSSJ	MP8R4500HRS*	S	04/09/2025	13:56:01	18:06:31	4.166700	4.647600
ROBERTSSJ	MP8R4500HRS*	S	04/09/2025	11:56:44	13:25:00	1.483400	1.654600

Miscellaneous Charges

Environmental Levy	\$25.00
Consumables	\$75.00

Sub Total for All:	\$5,388.00
Rounding:	\$0.00
GST:	\$0.00
Total:	\$5,388.00

PAYMENT OPTIONS:

PayID: 68169674033
 Bank Details: WESTPAC WAGGA WAGGA BSB: 032769 A/C No: 624222
 PLEASE QUOTE YOUR HP ACCOUNT NUMBER IN THE REFERENCE

Our goods come with guarantees that cannot be excluded under the Australian Consumer Law. You are entitled to a replacement or refund for a major failure and for compensation for any other reasonably foreseeable loss or damage. You are also entitled to have the goods repaired or replaced if the goods fail to be of acceptable quality and the failure does not amount to a major failure. Payment Terms strictly cash unless terms authorized.

11 Zora Street Warren NSW 2824
Ph. (02) 6847 3522
Air Conditioning Licence AU35668

PO Box 5485 Wagga Wagga NSW 2650
Email: accounts@hutcheonandpearce.com.au
www.hutcheonandpearce.com.au
ABN 68 169 674 033 ACN 169 674 033

*** DOCUMENT COPY ***

SERVICE TAX INVOICE

Document No.:	3879111
Document Date:	21/11/2025
Repair Order No.:	424433
Rego No.:	A200408
Make/Model:	JOHN DEERE 8R 230
Vehicle ID No.:	1RW8230DLNA200408
Fleet No.:	3
Odometer:	2456
Delivery Date:	08/06/2022
Invoice To:	
Customer ABN:	
Tax Exempt No.:	
P/Order No.:	
Page:	1 of 3

Service Plan Calculator V2.9

1. Cab Inspection
 - :Check Light operation and condition
 - :Check Wiper operation and condition
 - :Check Stereo operation
 - :Check transmission linkages and controls
 - :Check PTO operation
 - :Check loader operation (if applicable)
 - :Clean windscreen and wipe out cab floor
 - :Check heater & AC operation
2. Maintenance
 - :Change engine oil and filter
 - :Change primary and final fuel filter
 - :Inspect engine air filter (s)
 - :Inspect cab air and recirculation filters
 - :Check air intake system
 - :Check hitch components for wear and lubricate
 - :Lubricate VARI-COOL fan drive
 - :Lubricate steering and suspension components
 - :Clean suspension compressor & filter & air bag. (8RT)
 - :Lubricate Track tension cylinders (8RT)
3. Drawbar & 3PL & PTO
 - :Test operation (external controls)
 - :Check for leaks
 - :Check condition of linkages
 - :Check shaft condition
 - :Check guards are in place
4. Front & Rear Axle
 - :Test drive and test operation of suspension and steering
 - :Check suspension and steering components damaged e.g Pivot bushes, suspension cylinders ball joint boots
 - :Check for leaks :Check tyre pressures. (check pressures are set evenly)
 - :Check rim and weight condition (were fitted)
 - :Tighten wheel and wheel weight bolts

LABOUR

\$412.50

11 Zora Street Warren NSW 2824
 Ph. (02) 6847 3522
 Air Conditioning Licence AU35668

PO Box 5485 Wagga Wagga NSW 2650
 Email: accounts@hutcheonandpearce.com.au
www.hutcheonandpearce.com.au
 ABN 68 169 674 033 ACN 169 674 033

*** DOCUMENT COPY ***

SERVICE TAX INVOICE

Document No.:	3879111
Document Date:	21/11/2025
Repair Order No.:	424433
Rego No.:	A200408
Make/Model:	JOHN DEERE 8R 230
Vehicle ID No.:	1RW8230DLNA200408
Fleet No.:	3
Odometer:	2456
Delivery Date:	08/06/2022
Invoice To:	
Customer ABN:	
Tax Exempt No.:	
P/Order No.:	
Page:	2 of 3

5. Transmission
 :Test drive and test operation
 :Check manual brakes.
 :Check for leaks
 :Check neutral start system
6. Selective Control Valves
 :Test operation – external and electronically
 :Check for leaks
 :Check covers are installed
 :Check drains aren't blocked and are fitted
 :Check and empty drain reservoir
7. Engine
 :Check water pump and fan bearing
 :Check fan belt and pulleys / idler bearings
 :Check for coolant leaks and condition of hoses
 :Check for oil and fuel leaks
8. Track Machines
 :Check Track alignment & track wear.
 :Check Mid-Roller, Drive wheel sleeve, wedges and Idler wheels
 :Check Track trash build-up

CRONJESTSTAFF42 20/11/25: MACHINE HOURS: 5049 hrs
 OIL USED:
 HY-GARD:
 PLUS50II: 26.867 liters
 TORQ-GARD:
 80/90:
 85/140:
 COOLANT:
 ANY PARTS TO RETURN: none
 ADDITIONAL SERVICE NOTES: steering ram leaking see photo



11 Zora Street Warren NSW 2824
 Ph. (02) 6847 3522
 Air Conditioning Licence AU35668

PO Box 5485 Wagga Wagga NSW 2650
 Email: accounts@hutcheonandpearce.com.au
 www.hutcheonandpearce.com.au
 ABN 68 169 674 033 ACN 169 674 033

*** DOCUMENT COPY ***



SERVICE TAX INVOICE

Document No.: 3879111
Document Date: 21/11/2025
Repair Order No.: 424433
Rego No.: A200408
Make/Model: JOHN DEERE 8R 230
Vehicle ID No.: 1RW8230DLNA200408
Fleet No.: 3
Odometer: 2456
Delivery Date: 08/06/2022
Invoice To:
Customer ABN:
Tax Exempt No.:
P/Order No.:
 Page: 3 of 3

Service Plan Calculator V2.9

LABOUR

ESTIMATE REQUIRED: (Y/N)

CUSTOMER URGENCY: (HIGH/MEDIUM/LOW)

Part Number	Part Description	Serial No	Quantity	Nett Value	Total Cost
SERVICE PLAN TRAVEL	SERVICE PLAN TRAVEL		1.00	100.00	100.00
RE539465	Filter Element		1.00	218.73	218.73
RE509672	FILTER ELE		1.00	46.23	46.23
DZ112919	FILTER ELE		1.00	209.58	209.58
Parts Totals:			4.00		\$574.54

Technician Labour Postings

Technician	Job Description	Type	Clocked In Date	Start Time	Finish Time	Hours Worked	Hours Invoiced
CRONJESTS	MP8R2500HRS*	S	20/11/2025	14:21:44	17:06:00	2.750000	2.750000

Miscellaneous Charges

Environmental Levy \$5.00
 Consumables \$473.39

Sub Total for All: \$1,465.43
Rounding: \$0.00
GST: \$0.00
Total: \$1,465.43

PAYMENT OPTIONS:

PayID: 68169674033
 Bank Details: WESTPAC WAGGA WAGGA BSB: 032769 A/C No: 624222
 PLEASE QUOTE YOUR HP ACCOUNT NUMBER IN THE REFERENCE

Our goods come with guarantees that cannot be excluded under the Australian Consumer Law. You are entitled to a replacement or refund for a major failure and for compensation for any other reasonably foreseeable loss or damage. You are also entitled to have the goods repaired or replaced if the goods fail to be of acceptable quality and the failure does not amount to a major failure. Payment Terms strictly cash unless terms authorized.

11 Zora Street Warren NSW 2824
 Ph. (02) 6847 3522
 Air Conditioning Licence AU35668

PO Box 5485 Wagga Wagga NSW 2650
 Email: accounts@hutcheonandpearce.com.au
www.hutcheonandpearce.com.au
 ABN 68 169 674 033 ACN 169 674 033

*** DOCUMENT COPY ***

SERVICE TAX INVOICE

Document No.:	3879145
Document Date:	21/11/2025
Repair Order No.:	478685
Rego No.:	A200408
Make/Model:	JOHN DEERE 8R 230
Vehicle ID No.:	1RW8230DLNA200408
Fleet No.:	3
Odometer:	5049
Delivery Date:	08/06/2022
Invoice To:	
Customer ABN:	
Tax Exempt No.:	
P/Order No.:	
Page:	1 of 3

Service Plan Calculator V2.9

1. Cab Inspection
 - :Check Light operation and condition
 - :Check Wiper operation and condition
 - :Check Stereo operation
 - :Check transmission linkages and controls
 - :Check PTO operation
 - :Check loader operation (if applicable)
 - :Clean windscreen and wipe out cab floor
 - :Check heater and A/C operation
 - :Reset service reminder
 - :Check cab suspension components/ bushings. (8RT)
2. Maintenance
 - :Change engine oil and filter element
 - :Change primary and final fuel filter
 - :Check air intake system
 - :Change engine air filter (s)
 - :Change cab air and recirculation filters
 - :Check hitch components for wear and lubricate
 - :Lubricate VARI-COOL fan drive
 - :Lubricate steering and suspension components
 - :Check battery electrolyte level and tighten terminals
 - :Clean suspension compressor & filter & air bag. (8RT)
 - :Lubricate Track tension cylinders (8RT)
3. Drawbar & 3PL & PTO
 - :Test operation (external controls)
 - :Check for leaks
 - :Check condition of linkages
 - :Check shaft condition
 - :Check guards are in place
4. Front & Rear Axle
 - :Test drive and test operation of suspension and steering :Check suspension and steering components damaged e.g Pivot bushes, suspension cylinders ball joint boots

LABOUR

\$517.88

11 Zora Street Warren NSW 2824
 Ph. (02) 6847 3522
 Air Conditioning Licence AU35668

PO Box 5485 Wagga Wagga NSW 2650
 Email: accounts@hutcheonandpearce.com.au
www.hutcheonandpearce.com.au
 ABN 68 169 674 033 ACN 169 674 033

*** DOCUMENT COPY ***

SERVICE TAX INVOICE

Document No.:	3879145
Document Date:	21/11/2025
Repair Order No.:	478685
Rego No.:	A200408
Make/Model:	JOHN DEERE 8R 230
Vehicle ID No.:	1RW8230DLNA200408
Fleet No.:	3
Odometer:	5049
Delivery Date:	08/06/2022
Invoice To:	
Customer ABN:	
Tax Exempt No.:	
P/Order No.:	
Page:	2 of 3

- :Check for leaks
- :Check tyre pressures. (check pressures are set evenly)
- :Check rim and weight condition (were fitted)
- :Tighten wheel and wheel weight bolts
- 5. Transmission
 - :Test drive and test operation
 - :Check manual brakes
 - :Check for leaks
 - :Check neutral start system
- 6. Selective Control Valves
 - :Test operation – external and electronically
 - :Check for leaks
 - :Check covers are installed
 - :Check drains aren't blocked and are fitted
 - :Check and empty drain reservoir
- 7. Engine
 - :Check water pump and fan bearing
 - :Check fan belt and pulleys / idler bearings
 - :Check for coolant leaks and condition of hoses
 - :Check for oil and fuel leaks
- 8. Track Machines
 - :Check Track alignment & track wear.
 - :Check Mid-Roller, Drive wheel sleeve, wedges and Idler wheels
 - :Check Track trash build-up
 - :Check Walking beam suspension system & bumper stops. (8RT)
 - :Clean MFWD axle vent breaker (8RX)

ADDITIONAL SERVICE NOTES

STEERING RAM LEAKING

<u>Part Number</u>	<u>Part Description</u>	<u>Serial No</u>	<u>Quantity</u>	<u>Nett Value</u>	<u>Total Cost</u>
STPLUS50	PLUS 50 II (PER LTR) (1L of CP6660)		27.00	7.37	198.99



11 Zora Street Warren NSW 2824
 Ph. (02) 6847 3522
 Air Conditioning Licence AU35668

PO Box 5485 Wagga Wagga NSW 2650
 Email: accounts@hutcheonandpearce.com.au
 www.hutcheonandpearce.com.au
 ABN 68 169 674 033 ACN 169 674 033

*** DOCUMENT COPY ***



SERVICE TAX INVOICE

Document No.: 3879145
Document Date: 21/11/2025
Repair Order No.: 478685
Rego No.: A200408
Make/Model: JOHN DEERE 8R 230
Vehicle ID No.: 1RW8230DLNA200408
Fleet No.: 3
Odometer: 5049
Delivery Date: 08/06/2022
Invoice To:
Customer ABN:
Tax Exempt No.:
P/Order No.:
 Page: 3 of 3

Service Plan Calculator V2.9

		<u>LABOUR</u>		
DZ130550	FILTER ELE	1.00	305.53	305.53
DZ112919	FILTER ELE	1.00	223.25	223.25
RE596317	AIR FILTER	1.00	269.37	269.37
TA32591	AIR FILTER	1.00	152.57	152.57
RE596318	AIR FILTER	1.00	140.07	140.07
RE593819	AIR FILTER	1.00	89.60	89.60
SERVICE PLAN TRAVEL	SERVICE PLAN TRAVEL	1.00	100.00	100.00
RE509672	FILTER ELE	1.00	48.54	48.54
Parts Totals:		35.00		\$1,527.92

Technician Labour Postings

Technician	Job Description	Type	Clocked In Date	Start Time	Finish Time	Hours Worked	Hours Invoiced
CRONJESTS	MP8R5000HRS*	S	20/11/2025	10:55:03	13:40:24	2.750000	3.452500

Miscellaneous Charges

Environmental Levy **\$5.00**
 Consumables **\$30.00**

Sub Total for All: \$2,080.80
Rounding: \$0.00
GST: \$0.00
Total: \$2,080.80

PAYMENT OPTIONS:

PayID: 68169674033
 Bank Details: WESTPAC WAGGA WAGGA BSB: 032769 A/C No: 624222
 PLEASE QUOTE YOUR HP ACCOUNT NUMBER IN THE REFERENCE

Our goods come with guarantees that cannot be excluded under the Australian Consumer Law. You are entitled to a replacement or refund for a major failure and for compensation for any other reasonably foreseeable loss or damage. You are also entitled to have the goods repaired or replaced if the goods fail to be of acceptable quality and the failure does not amount to a major failure. Payment Terms strictly cash unless terms authorized.