



TANK WASH AND PURGE TEST

Date: June 22/25 Time: 1625

Location: Long Harbor, NL

Tank Unit# 791113

Meter Used: Ventis Mx4

Reading:

% LEL Level: 0 %O₂: 21.0% CO: 0 H₂S: 0

Tested Clean? (Y) N

Comments: _____

Printed Name: Evan Ticeo

Signature*: 

*this signature verifies that this tanker has been washed out and purged

Title: Supervisor

Contact Phone Number: 709-771-3392