EquipmentName	Workshop	CodeAndSubCode	Description	Schedule	CompletionComments	DateDone	Worktype	Workstate	EquipmentOwner	MaintenanceGroup	Location	Division	Rego	Supplier	EquipmentType
LOAD28	Myrtleford - Workshop	Engine\HOUSEKEEP	Jump start & move truck			25/05/2018	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR		Myrtleford Workshop	LOADER
LOAD28	Myrtleford - Workshop	DrivLine\GEARBOX	Fit gear stick linkage			17/05/2018	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR		Myrtleford Workshop	LOADER
LOAD28	Myrtleford - Workshop	Engine\HOUSEKEEP	jump start			17/05/2018	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR		Myrtleford Workshop	LOADER
LOAD28	Myrtleford - Workshop	Elect\BATTERY	fit 2x second hand batteries			17/05/2018	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR		Myrtleford Workshop	LOADER
LOAD28	Wodonga - Workshop	Body\DAMAGE	replaced broken hinges modify new hinges to fit			20/10/2017	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR		Wodonga Workshop	LOADER
LOAD28	Wodonga - Workshop	Body\DAMAGE	fit door latches to both doors			20/10/2017	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR		Wodonga Workshop	LOADER
LOAD28	Wodonga - Workshop	Body\DAMAGE	got tools together fueled up green ute drove to Logic removed and secured LH door came back to yard			19/10/2017	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR		Wodonga Workshop	LOADER
LOAD28	Myrtleford - Workshop	Insp\ANN INSP	annual inspection as per check list	Insp\ANN INSP		17/02/2016	PreventativeMaintenance	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR		Myrtleford Workshop	LOADER
LOAD28	Myrtleford - Workshop	DriCabRep\WINDSCREEN	supply & fit rear cab window (part of r/worthy)			17/02/2016	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR		Myrtleford Workshop	LOADER