EquipmentName	Workshop	CodeAndSubCode	Description	Schedule	CompletionComments	DateDone	DistanceDone	Worktype	Workstate	EquipmentOwner	MaintenanceGroup	Location	Division	Rego	Supplier	EquipmentType
T431	Wodonga - Workshop	Body\TANK COMP	leak in front tank underside above light bar of A trailer outside right hand side chassis		Inspected tank for damage	24/09/2026	469137	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Brakes\DAMAGE	Lhf booster mount broken needs replacing			13/08/2026	469137	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Susp\DAMAGE	Rear airbag mounts need welding			13/08/2026	469137	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Driv\ine\WHEEL BRGS	Replace rear axle bearings			13/08/2026	469137	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Driv\ine\WHEEL BRGS	Replace grease in all hubs			13/08/2026	469137	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Insp\INT INSP	Insp\INT INSP Quarterly internal inspection	Insp\INT INSP		08/08/2026	469137	PreventativeMaintenance	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS	Jamie was on service	08/08/2026	469137	Service	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Brakes\BRAKE ADJ	brakes require attention			06/07/2026	469137	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		06/07/2026	469137	Service	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Insp\ANN INSP	Insp\ANN INSP	Insp\ANN INSP		06/07/2026	469137	PreventativeMaintenance	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Tyres\TP31+12	Tyres\TP31+12 (31-32)		CALL OUT - TYRES DISPOSED	31/01/2026	469137	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	BORDER BANDAG PTY LTD	TRAILER
T431	Wodonga - Workshop	Elect\TAIL LIGHT	NO INDICATORS ON TRAILER. FAULT LAYS STILL IN THE PLUG.			20/01/2026	469137	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		20/01/2026	469137	Service	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Tyres\TP3+4	Tyres\TP3+4 (23-24)			09/12/2025	469137	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	BORDER BANDAG PTY LTD	TRAILER
T431	Wodonga - Workshop	Tyres\TP9+10	Tyres\TP9-10 (29-30)			09/12/2025	469137	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	BORDER BANDAG PTY LTD	TRAILER
T431	Wodonga - Workshop	Tyres\TP1+2	Tyres\TP1+2 (21-22)			09/12/2025	469137	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	BORDER BANDAG PTY LTD	TRAILER
T431	Wodonga - Workshop	Tyres\TP11+12	Tyres\TP11+12 (31-32)			09/12/2025	469137	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	BORDER BANDAG PTY LTD	TRAILER
T431	Wodonga - Workshop	Susp\SHOCK ABS	Replace left middle shockabsorber.			08/12/2025	469137	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		08/12/2025	469137	Service	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TANK COMP	LEAKS IN FRONT COMPARTMENT OF TRAILER (431) ON LEFT HAND SIDE. CRACK IN EXISTING WELD. (Australian Tank Engineering P/O:			20/10/2025	469137	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	AUSTRALIAN TANK ENGINEERING	TRAILER
T431	Wodonga - Workshop	Body\TANK COMP	LEAK IN FLOOR OF RESIN TANKER ON BOTH SIDES OF SKID PLATE. BEHIND KING PIN. RIGHT HAND SIDE CRACK HAS WORSENED SINCE LAST REPORT. 130778 ON (04.08.25) PHOTOS ATTACHED. (Australian Tank Engineering P/O:			20/10/2025	469137	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	AUSTRALIAN TANK ENGINEERING	TRAILER
T431	Wodonga - Workshop	Body\PANELS	FLOOR OVER SKID PLATE BOTH SIDES. (Australian Tank Engineering P/O:			20/10/2025	469137	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	AUSTRALIAN TANK ENGINEERING	TRAILER
T431	Wodonga - Workshop	Body\TRL FLOOR	FLOOR OVER SKID PLATE BOTH SIDES.		Front of tank needs to be blocked off	26/09/2025	469137	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TANK COMP	LEAKS IN FRONT COMPARTMENT OF TRAILER (431) ON LEFT HAND SIDE CRACK IN EXISTING WELD.		Put a patch over leaking weld	26/09/2025	469137	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TANK COMP	RESIN TANK NOW LEAKING ON BOTH RIGHT & LEFT SIDE UNDERNEATH AT SKID PLATE.		The tank needs. To be sectioned out over skid plate to stop leaking	26/09/2025	469137	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Susp\SHOCK ABS	Replace left middle lower shock mount/bolt.			05/09/2025	469137	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		05/09/2025	469137	Service	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TRL REPS	REAR ROOF SUPPORT- UNSERVICEABLE.			05/09/2025	469137	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Elect\INDICATORS	Wiring fault affecting both indicators on B trailer			09/08/2025	469137	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\DAMAGE	Leak in front tank on RHS.		If that patch is to leak again the old patch will need to be cut off and replaced	02/08/2025	469137	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		01/08/2025	469137	Service	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Tyres\Punct	Tyres\Puncture POS 24			29/07/2025	469137	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	BORDER BANDAG PTY LTD	TRAILER
T431	Wodonga - Workshop	Body\TANK COMP	Repair Resin Tank Crack		Found Tank Leaks/Cracks, Prepped Area Needing Repairs, Welded Cracks, Tested All Good, Painted Repairs, Moved Trailer Out Of Workshop.	19/07/2025	469137	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TANK COMP	ball valve leaking on rear tank breather. Needs replacing before tank can be loaded with resin.		Inspected ball valves and butterfly valves found no valves to be faulty	14/07/2025	469137	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TANK COMP	-REQUIRES WELDING ON TWO PATCHES THAT ARE LEAKING AT 3 POINTS IN TOTAL AND WORSENING. (MARKED WITH TEXTA)			09/07/2025	469137	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Tyres\Punct	Tyres\Puncture POS 27			08/07/2025	469137	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	BORDER BANDAG PTY LTD	TRAILER
T431	Wodonga - Workshop	Brakes\AIR LEAK	-LOSING AIR. BRAKES SLOW TO RELEASE.			07/07/2025	469137	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		07/07/2025	469137	Service	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TANK MANI	CAM LOCK OUTLET COVERS REQUIRED x(2)		Cam lock caps previously fitted.	04/07/2025	469137	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Brakes\AIR LEAK	Repair air leak at R-12 valve. -TAGS IN PIPE CAPS FOR FILLER & DISCHARGE BROKEN OFF x1 ON EACH END CAP. CAPS STILL WORK, JUST HARDER TO SHUT.			20/06/2025	469137	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Prod Hose\n\Fittings	(Parts Supplied By Rapid Hydraulics P/O: WW095098) & (P/O: WW095306)		Cam lock caps previously fitted	20/06/2025	469137	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		20/06/2025	469137	Service	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\DAMAGE	Repair leaks in tank @ patches.			20/06/2025	469137	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TANK COMP	2 pinhole leaks front patch low left hand side & centre patch top left hand side missed in rewelding. small crack below 3rd weld pass.		WELDED UP CRACKS.	29/05/2025	469137	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TRL REPS	roof post right handside rear. Keeps dislodging and falling on floor. maybe new rollers would stop this.			09/05/2025	469137	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		09/05/2025	469137	Service	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TANK COMP	WELDED CRACKS IN RHS UNDER BELLY TANK.			01/05/2025	469137	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TRL REPS	Body\TRL REPS		1 Repair to passenger side 40 inches re-weld section of curtain on oassenaer side	28/04/2025	469137	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	PIX TRUCK CURTAINS	TRAILER
T431	Wodonga - Workshop	Body\TRL WALL	REPAIR CRACKS IN RESIN TANK.		S.MCCABE.	17/04/2025	469137	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		10/04/2025	469137	Service	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TANK CIP	right hand side on front tank of trailer 2 evident leaks - (as per photo) - getting worse right hand side rear tank has developed a leak			10/04/2025	469137	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Insp\INT INSP	Insp\INT INSP	Insp\INT INSP		10/04/2025	469137	PreventativeMaintenance	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\PANELS	Repair holes/leaks in resin tank.			10/04/2025	469137	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Chassis\AIR LEAK	Check For Air Leak/s & Repair		Pending	29/03/2025	469137	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TRL REPS	Top left rear Palmet Rubber Damaged.		Pending	29/03/2025	469137	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TRL REPS	Left hand side,between BB/6th curtain buckles, curtain is Damaged.			29/03/2025	469137	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	VehService\DS	VehService\DS Wash Out Tank So It Can Be Repaired. (Tank Washed Out By Tank Services Australia).	VehService\DS	Left hand side curtain to be repaired at Sign Effects.	19/03/2025	469137	Service	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TANK CIP	ITank Reaained Bv ATE P/O: WW092704 Repair Leaks In Resin Tank.			11/03/2025	469137	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\DAMAGE	IATE P/O: WW092704)		Pressurised tank to find out where leaf is and found it to be up in behind the chassis	27/02/2025	469137	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TANK COMP	Repair Crack's in Resin Tank.			22/02/2025	469137	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Insp\ANN INSP	Annual Inspection	Insp\ANN INSP		05/02/2025	469137	PreventativeMaintenance	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	VehService\DS	VehService\DS	VehService\DS		05/02/2025	469137	Service	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Brakes\BRK RELINE	Brake Reline.			08/01/2025	469137	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
					Complete ATE risk assessment for hotworks, confined space and workshop entry											
					Pressure test tanker to locate leak											
					Leak detected above skid plate area (unable to pin point)											
					Set up for confined space entry											
					Internal inspection found crack in area on driver side, unable to access with repair equipment internally											
					Cut out section of lead in plate for access											
					Cut out cross member above skid plate for access											
					Cut out section of side wall for access to toe of tank											
					Gouge out crack and weld repair											
					Complete pressure test and leak through dye penetrant test to ensure repair											
					Weld in section of side wall											
					Cut and fit new cross member and weld in position											
					Cut and fit new section of lead in plate, weld in position											
					Reinstate paint to all repaired areas, raw material primed prior to weld with zinc coat											
					Replace mroken swing hatch/ cover lock											
			Repair Leaks In Resin Tank.		Complete RTS checks											
T431	Wodonga - Workshop	Body\TANK COMP	(ATE P/O: WW091339)		Confined space spotter for all internal works	20/12/2024	469137	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	AUSTRALIAN TANK ENGINEERING	TRAILER
T431	Wodonga - Workshop	VehService\DS	VehService\DS	VehService\DS	Needs a reline asap	18/12/2024	469137	Service	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Brakes\BRAKE ADJ	grease brake check (last in october)			18/12/2024	469137	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TRL WALL	CRACK INTERNALLY AND EXTERNAL. SEE PHOTOS PROVIDED FOR LOCATION AND DISTANCE FROM FRONT OF TRAILER. (UNDERCARRIAGE)		Trailer loaded unable to fix	18/12/2024	469137	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Tyres\FAILURE	RIGHT REAR OUTER TYRE DAMAGE. (WALL/ TREAD) RUN OUT FITTED ON 7 & 12			24/10/2024	469137	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	BEAUREPAIRES	TRAILER
T431	Wodonga - Workshop	Tyres\TP9-10	Tyres\TP9-10			24/10/2024	469137	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	BEAUREPAIRES	TRAILER
T431	Wodonga - Workshop	Tyres\PRES CHECK	Tyres\PRES CHECK 1-12			24/10/2024	469137	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	BEAUREPAIRES	TRAILER
T431	Wodonga - Workshop	Tyres\TP5+6	Tyres\TP5+6			24/10/2024	469137	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	BEAUREPAIRES	TRAILER
T431	Wodonga - Workshop	Elect\ELECT P&W	CLEARANCE LIGHTS NEED REPLACING LHS (ZIP TIED IN)			21/10/2024	469137	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	VServLab	SERVICE REQUIRED.			21/10/2024	469137	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Elect\INDICATORS	INDICATOR LEFT CENTRE NOT WORKING.			21/10/2024	469137	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Elect\ELECT P&W	REAR RIGHT NUMBER PLATE LIGHT HANGING OFF.			21/10/2024	469137	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	VehService\DS	VehService\DS	VehService\DS	Will need reline done asap	21/10/2024	469137	Service	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	VehService\DS	VehService\DS	VehService\DS	Will need reline very soon	26/09/2024	469137	Service	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Brakes\BRAKE ADJ	GREASE SERVICE BRAKES.			26/09/2024	469137	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Tyres\FITMENT	SPARE TYRE NEEDS REPLACING.			27/08/2024	469137	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	BEAUREPAIRES	TRAILER
T431	Wodonga - Workshop	VehService\DS	VehService\DS	VehService\DS		26/08/2024	469137	Service	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Tyres\Punct	Spare Tyre Needs Replacing		Replaced by Beurepairs.	26/08/2024	469137	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TRL DOORS	Rear Spare Door Damaged By Unknown Person When At Wodonga Last Needs Attention Can't Use Top Pad Bolt			26/08/2024	469137	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\PANELS	leak in resin tank - left hand side just below breather on front tank (marked with texter 2 pin holes			20/07/2024	469137	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TRL REPS	RHS pole (roof support rear) jumping track			20/07/2024	469137	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	VehService\DS	service and brakes			20/07/2024	469137	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	VehService\DS	VehService\DS	VehService\DS		20/07/2024	469137	Service	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Brakes\BRAKE ADJ	Brakes Check			20/07/2024	469137	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TRL REPS	CURTAIN TORN LH SIDE.		Curtain to be repaired at twin city graphics.	21/06/2024	469137	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	VehService\DS	SERVICE.			21/06/2024	469137	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	VehService\DS	D Service	VehService\DS		21/06/2024	469137	Service	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TRL REPS	REAR ROOF SUPPORT RIGHT HAND SIDE. BACK TWO ROLLERS ARE JUMPING OFF RAIL AND DISLODGING.			21/06/2024	469137	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Insp\INT INSP	Internal & External Inspections	Insp\INT INSP	Global factory maintenance are to do internal inspection.	21/06/2024	469137	PreventativeMaintenance	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		02/05/2024	343467	Service	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			02/05/2024	343467	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TRL REPS	REAR R.H.S TAUTLINER POLE- NEEDS TOP CORNER OF TRAILER TO BE REFURBISHED. Repair existing patch repair bottom weld. ***Test tank for vapour before welding*** Vent tanker Pressure test tank to confirm extent of leak Repair existing patch repair on bottom weld. Back grind weld and reinstate with new weld Pressure test tank to confirm repairs			02/05/2024	343467	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TANK PANEL	Reinstate paint to repaired area			25/04/2024	465137	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Albury Workshop	TRAILER
T431	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			10/04/2024	343467	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Comp\Truck Safe	REPLACE NHVAS STICKER. ON ORDER.			10/04/2024	343467	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Susp\SUSPENSION	REPLACE SPRING EYE BUSHES.		CHECKED. OK.	10/04/2024	343467	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TANK MANI	FIT PADLOCKS TO CAMLOCKS.			10/04/2024	343467	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Comp\Truck Safe	FIT NHVAS STICKER.			10/04/2024	343467	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TRL REPS	REAR R.H.S TAUTLINER POLE- NEEDS TOP CORNER OF TRAILER TO BE REFURBISHED.			10/04/2024	343467	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		10/04/2024	343467	Service	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Elect\TRL LIGHTS	RENEW 1x SIDE MARKER LAMP			23/03/2024	343467	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Albury Workshop	TRAILER
T431	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			14/03/2024	336620	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TRL REPS	REPAIR LH UPRIGHT.			14/03/2024	336620	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Comp\Truck Safe	REPLACE NHVAS STICKER.			14/03/2024	336620	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Susp\SUSPENSION	REPLACE SPRING EYE BUSHES. ADJUSTED RM WHEEL BEARING (INCLUDING TRAINING FOR EMPLOYEES)			14/03/2024	336620	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	WELDING REPAIRS.	14/03/2024	336620	Service	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Unknown	SERVICE & BRAKES.			14/03/2024	336620	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TRL REPS	REAR R.H.S TAUTLINER POLE- NEEDS TOP CORNER OF TRAILER TO BE REFURBISHED.			14/03/2024	336620	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\HOUSEKEEP	HOLDING RESIN NEEDS TO INTERNAL CLEAN			14/03/2024	336620	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TANK MANI	FIT PADLOCKS TO CAMLOCKS.			14/03/2024	336620	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Comp\Truck Safe	FIT NHVAS STICKER.			14/03/2024	336620	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			07/02/2024	325331	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Comp\Truck Safe	REPLACE NHVAS STICKER.			07/02/2024	325331	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Susp\SUSPENSION	REPLACE SPRING EYE BUSHES.			07/02/2024	325331	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Brakes	BRAKE CHECK.		completed during service	07/02/2024	325331	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		07/02/2024	325331	Service	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Unknown	REQUIRES SERVICE.			07/02/2024	325331	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			22/12/2023		Repair	Completed	FL Green Distribution	ResinTline	Wodonga	R

T431	Wodonga - Workshop	Insp\INT INSP	Quarterly inspection in conjunction with Global Factory Maintenance	Insp\INT INSP			22/12/2023		PreventativeMaintenance	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				25/11/2023	302289	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Elect\ELECT P&W	TOP LIGHTS AT REAR.				25/11/2023	302289	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TRL REPS	REPAIR LH PELMET RUBBER BRACKET.				25/11/2023	302289	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TRL REPS	REPAIR TOP LIGHT ON REAR WALL.				25/11/2023	302289	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Elect\INDICATORS	TOP INDICATOR LIGHT L.H.S. INOPERATIVE.				25/11/2023	302289	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Elect	LHS CENTRAL INDICATOR- BROKEN WIRES.				25/11/2023	302289	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Elect\ELECT P&W	RHS 2ND CLEARANCE LIGHT- NOT WORKING.				25/11/2023	302289	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Chassis\AIR LEAK	AIR LEAKS.				25/11/2023	302289	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TRL REPS	ROOF SUPPORT POLE (RHS) REQUIRES REFITTING.				25/11/2023	302289	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	REPLACED TOP INDICATOR AND LF CLEARANCE LIGHT. ADJUSTED LM RF WHEEL BEARINGS.		25/11/2023	302289	Service	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Unknown	SERVICE & BRAKE CHECK REQUIRED.				25/11/2023	302289	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TANK COMP	Pin Hole In Tank In First Patch On R.H.S - Hole Is In Lead Vertical Weld (Just Above Horizontal Line On Tank (Bird Mark)				25/11/2023	302289	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Tyres\TP1+12	Rear Axle Right Hand Inside Tyre Requires Replacing		BEAUREPAIRS.		25/11/2023	302289	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Unknown	Service Due				25/11/2023	302289	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Tyres\TP1+2	Tyre Position 1 + 2				15/10/2023		Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Albury Workshop	TRAILER
T431	Wodonga - Workshop	Tyres\TP3+4	Tyre Position 3 + 4				15/10/2023		Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Albury Workshop	TRAILER
T431	Wodonga - Workshop	Elect\INDICATORS	TOP INDICATOR LIGHT L.H.S. INOPERATIVE.				15/10/2023	326276	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			15/10/2023	326276	Service	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				15/10/2023	326276	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Elect\ELECT P&W	CENTRE TURN LAMP ON LEFT HAND SIDE- INOPERATIVE- BROKEN WIRE BEFORE TURN SIGNAL LAMP.				15/10/2023	326276	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Tyres\TP12	FLAT TYRE REAR OUTER ON TRL(REAR AXLE) R.H.S.				15/10/2023	326276	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Elect\ELECT P&W	NO LEFT HAND INDICATOR AND TOP LIGHTS AT REAR.				15/10/2023	326276	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Chassis\STRAPS	REQUIRES LOAD BINDER STRAP & BARREL REPLACEMENT- ALL FAULTY ONES ARE MARKED ON THE BARREL & STRAPS.				15/10/2023	326276	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\HOUSEKEEP	WORK AS PREVIOUS R&R NOTICE. RE LEAKS & ROOF SUPPORT.				15/10/2023	326276	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	Insp\ANN INSP			15/10/2023	326276	PreventativeMaintenance	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Unknown	SERVICE REQUIRED.				15/10/2023	326276	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TRL REPS	REPAIR LH PELMET RUBBER BRACKET.				15/10/2023	326276	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TRL REPS	REPAIR TOP LIGHT ON REAR WALL.				15/10/2023	326276	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Unknown	REQUIRES SERVICE, BRAKE & TYRE CHECK.				15/10/2023	326276	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Wash\WASH	internal tank wash				29/09/2023		Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
					Complete ATE risk assessment for confined space entry												
					Pressure test tank to locate leaks												
					Internal inspection located leak beside previous repair												
					Balc grind crack and weld repair												
					Fabricate and fit internal doubling pad to add additional strength to fatigued area												
					Pressure test tank to test repairs												
					Additional leaks found												
					Internal inspection located additional crack to rear compartment panel												
					Back grind and weld repair crack, fabricate and fit doubling pad												
					Pressure test compartment , all ok												
					Reinsate paint to repaired areas												
T431	Wodonga - Workshop	Body\TANK COMP	Leak to belly tanker - again.		Confined space scotter for all internal works		01/07/2023		Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Albury Workshop	TRAILER
			Complete ATE risk assessment for factory entry and confined space entry														
			Cut off front lead in plate section														
			Cut out Channel support cross member														
			Locate leak above channel on plug welds to support cross member														
			Weld repair areas and test, all ok														
			Refit new cross member and wel in position														
			Laser cut and fit new lead in plate section														
			Weld in new section and clean weld face, reinstate paint														
			Pressure test tanker in both compartment areas to locate external leaks														
			Grind out and weld prep external areas														
			Complete external weld repairs														
			Internal inspection to locate crack on driver side in front of 1st axle														
			Grind out and weld repair cracked area														
			Pressure test to ensure repairs														
			Reinstate paint to repaired area														
T431	Wodonga - Workshop	Body\TANK PANEL	Confined space scotter for all internal works				01/06/2023		Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Albury Workshop	TRAILER
			SMALL LEAK IN RESIN TANK. FRONT COMPARTMENT L.H.S. PIN HOLE IN WELD OF A PATCH.														
T431	Wodonga - Workshop	Body\TRL WALL	SENT TO ATE FOR REPAIRS. SMALL LEAK IN RESIN TANK. FRONT COMPARTMENT L.H.S. PIN HOLE IN WELD OF A PATCH.				02/05/2023		Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TRL WALL	LEAK REAR COMPARTMENT R.H.S. AT CHASSIS RAIL AT REAR OF TANK ON OUTER SIDE.		REFER JOB # 410782.		02/05/2023		Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
			Replace multiple tyres														
			Beaurepairs Somerton														
T431	Wodonga - Workshop	Tyres\FITMENT	PO# WW079595				28/02/2023	469137	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				29/12/2022		Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			29/12/2022		Service	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				23/11/2022		Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			23/11/2022		Service	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Unknown	DUE FOR SERVICE.				23/11/2022		Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
			TEAR IN CURTAIN.														
T431	Wodonga - Workshop	Body\TRL REPS	Trailer sent to TC Graphix for repairs.				22/11/2022		Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TRL REPS	TEAR IN CURTAIN.		CABLE TIED TEAR. TEMPORARY REPAIR.		17/11/2022		Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
			Trailer Curtain Repair														
			Curtain Damaged														
T431	Wodonga - Workshop	Body\DAMAGE	Sent to TC Graphics for repair.				16/11/2022	469137	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
			ATTENDED REPORTED BREAKDOWN FOR NO LIGHTS ON														
			TRAILERS.														
			LOCATED TRAILERS, TESTED AND INSPECTED ALL LIGHTS, NO														
			FAULTS FOUND.														
T431	Wodonga - Workshop	Elect\TRL LIGHTS	RETURN TO WORKSHOP.				22/09/2022		Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Brakes\AIR LEAK	INSPECTED ENTIRE AIR SYSTEM FOR LEAKS. NONE FOUND.				18/09/2022	207743	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Tyres\TP9+10	supply and fit 2tyres				24/08/2022		Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Myrtleford - Workshop	Insp\INT INSP	Quarterly inspection in conjunction with Global Factory Maintenance	Insp\INT INSP			24/08/2022	199613	PreventativeMaintenance	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Myrtleford Workshop	TRAILER
T431	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				24/08/2022	199013	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Myrtleford Workshop	TRAILER
					adjust LHF & RHR wheel bearings												
					made up new trailer supports												
T431	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	reolaced x3 winch strap binders		24/08/2022	199013	Service	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Myrtleford Workshop	TRAILER
T431	Wodonga - Workshop	Tyres\TP11+12	supply and fit 2tyres				26/07/2022		Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				12/07/2022	185433	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Myrtleford Workshop	TRAILER
T431	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			12/07/2022	185433	Service	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Myrtleford Workshop	TRAILER
T431	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				28/05/2022	173919	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TRL REPS	poor condition				28/05/2022	173919	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TRL REPS	poor condition CURTAINS BEYOND REPAIR				28/05/2022	173919	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TRL REPS	Rips & holes in curtains - recommend replacement				28/05/2022	173919	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TRL REPS	need replacing				28/05/2022	173919	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TRL REPS	u/s				28/05/2022	173919	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TRL REPS	RHS CURTAIN TORN AND MISSING BUCKLE				28/05/2022	173919	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Elect\ELECT P&W	MISSING CLEARANCE LIGHT ON P/SIDE FRONT.				28/05/2022	173919	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			28/05/2022	173919	Service	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
			L/H FRONT RATCHET HANDLE BROKEN.														
T431	Wodonga - Workshop	Body\STRAPS	R/H FRONT WON'T RATCHET ANYMORE.		REPLACED.		28/05/2022	173919	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
			Repair Crack in Tank Compartment.														
			Works done by ATE.														
T431	Wodonga - Workshop	Body\TANK COMP	PO# WW071762				13/05/2022		Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				20/04/2022	160585	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			20/04/2022	160585	Service	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
			Repair Crack in Tank														
			Conducted by ATE														
T431	Wodonga - Workshop	Body\TANK COMP	PO# WW071095				01/04/2022		Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TRL REPS	Supply & install truck curtain straight deck digital print and clear coated				25/03/2022		Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TRL REPS	REPAIRED RIPPED RH CURTAIN. WASHED				24/02/2022	144158	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				17/02/2022	144157	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TRL REPS	poor condition				17/02/2022	144157	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TRL REPS	poor condition				17/02/2022	144157	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TRL REPS	Rips & holes in curtains - recommend replacement				17/02/2022	144157	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TRL REPS	need replacing				17/02/2022	144157	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TRL REPS	u/s				17/02/2022	144157	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TRL REPS	RHS CURTAIN TORN AND MISSING BUCKLE				17/02/2022	144157	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TANK COMP	LEAKING RESIN TANK				17/02/2022	144157	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Chassis\STRAPS	Binders are starting to split.		REPLACED 12 BINDER STRAPS.		17/02/2022	144157	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TRL REPS	Tears in curtains need attending to (Drivers Side)		#372758		17/02/2022	144157	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\STRAPS	CURTAINS JAMMING		#372758		17/02/2022	144157	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\STRAPS	TORN CURTAINS		#372758		17/02/2022	144157	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\STRAPS	BUCKLES MISSING		#372758		17/02/2022	144157	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\STRAPS	BUCKLES KEEP COMING LOOSE				17/02/2022	144157	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TRL REPS	CURTAINS JAMMING		#372758		17/02/2022	144157	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TRL REPS	TORN CURTAINS.		#372758		17/02/2022	144157	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TRL REPS	BUCKLES MISSING		#372758		17/02/2022	144157	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TRL REPS	BUCKLES KEEP COMING LOOSE				17/02/2022	144157	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			17/02/2022	144157	Service	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Brakes\BRK RELINE	PREP HUBS. RELINE				17/02/2022	144157	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TANK COMP	REPAIRED PATCH ON RESIN TANKER				01/02/2022	139203	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				31/12/2021	130697	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TRL REPS	Rips & holes in curtains - recommend replacement				31/12/2021	130697	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TRL REPS	need replacing				31/12/2021	130697	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TRL REPS	u/s				31/12/2021	130697	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Chassis\FIRE EXTIN	in truck				31/12/2021	130697	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TRL REPS	RHS CURTAIN TORN AND MISSING BUCKLE				31/12/2021	130697	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TANK COMP	LEAKING RESIN TANK				31/12/2021	130697	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Chassis\STRAPS	Binders are starting to split.				31/12/2021	130697	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TRL REPS	Tears in curtains need attending to (Drivers Side)		NEEDS PELMET RUBBER AS WELL		31/12/2021	130697	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Drive\re\WHL HUB	Hub Seal cap broken.				31/12/2021	130697	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\STRAPS	CURTAINS JAMMING				31/12/2021	130697	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\STRAPS	TORN CURTAINS				31/12/2021	130697	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\STRAPS	BUCKLES MISSING				31/12/2021	130697	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\STRAPS	BUCKLES KEEP COMING LOOSE				31/12/2021	130697	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Elect\ELECT P&W	REPLACED LIGHT.				31/12/2021	130697	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TRL REPS	SPRAYED CURTAIN ROLLER WITH DRY CLEANER (AS PER ORDER)				31/12/2021	130697	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	ADJUSTED LF RF WHEEL BEARINGS.		31/12/2021	130697	Service	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	Insp\ANN INSP			31/12/2021	130697	PreventativeMaintenance	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				31/12/2021	162879	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Susp\SHOCK ABS	RHR SHOCKER BOLT SNAPPED				31/12/2021	162879	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\STRAPS	CURTAINS JAMMING		Refer Job # 368416		31/12/2021	162879	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\STRAPS	CURTAINS RIPPED				31/12/2021	162879	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\STRAPS	BUCKLES MISSING				31/12/2021	162879	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\STRAPS	BUCKLES KEEP COMING LOOSE				31/12/2021	162879	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			31/12/2021	162879	Service	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Tyres	LM RM LF TYRE NEED REPLACING.				31/12/2021	162879	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TANK COMP	RESIN TANKER IS LEAKING NEAR FRONTY AXLE.				31/12/2021	162879	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\HOUSEKEEP	MISSING FIRE EXTINGUISHER.				31/12/2021	162879	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER

T431	Wodonga - Workshop	Body\REFLECTORS	NEEDS NEW REFLECTORS.				31/12/2021	162879	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TRL REPS	SPRAYED CURTAIN ROLLER AND TRACKS WITH DRY CLEANER (AS PER ORDER)		Refer Job # 368416		31/12/2021	162879	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\STRAPS	CUTAINS JAMMING		Refer Job # 368416		31/12/2021	162879	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TRL REPS	Curtains hard to pull back and forth on both trailers.		Refer Job # 368416		31/12/2021	162879	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TRL REPS	SPRAYED CURTAIN ROLLER AND TRACKS WITH DRY CLEANER (AS PER ORDER)		Refer Job # 368416		31/12/2021	162879	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	Insp\ANN INSP			31/12/2021	162879	PreventativeMaintenance	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Tyres\TP7+8	supply and fit 2 tyres				19/10/2021		Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				18/10/2021	106119	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Myrtleford Workshop	TRAILER
T431	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	Replaced 4x buckles		18/10/2021	106119	Service	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Myrtleford Workshop	TRAILER
T431	Wodonga - Workshop	Body\WHL HUB	REPLACE DAMAGED HUB CAP O/S AXLE 3				09/10/2021	103509	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				12/08/2021	83208	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Myrtleford Workshop	TRAILER
T431	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			12/08/2021	83208	Service	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Myrtleford Workshop	TRAILER
					Robinsons truck and coach to carry out repairs														
					REPAIRED SUZI COIL WIRE FOR B TRAILER														
T431	Wodonga - Workshop	Chassis\SUZI COIL	no clearance lights		RECOMMEND REPLACING SUZI COILS		22/07/2021		Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TANK COMP	repair crack in tank				16/07/2021		Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TRL REPS	Measure curtains for Dean.				09/07/2021		Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TANK COMP	repair cracks in tanks		ATE tankers completed		08/07/2021		Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				08/07/2021		Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TANK COMP	Repair crack in tank.				08/07/2021		Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			08/07/2021		Service	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\STRAPS	REPLACED CURTAIN STRAPS				08/07/2021		Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Myrtleford - Workshop	Chassis\WHEEL BRGS	RF, LM hub seals leaking		check while serviced all ok		10/06/2021		Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Myrtleford Workshop	TRAILER
T431	Myrtleford - Workshop	Elect\TAIL LIGHT	rear tail light not working		check while serviced all ok		10/06/2021		Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Myrtleford Workshop	TRAILER
T431	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				09/06/2021		Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Myrtleford Workshop	TRAILER
T431	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			09/06/2021		Service	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Myrtleford Workshop	TRAILER
T431	Myrtleford - Workshop	Body\MUDGUARDS	replace LHF mudguard				23/05/2021		Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Myrtleford Workshop	TRAILER
T431	Wodonga - Workshop	Tyres\TP05	Puncture repair				18/05/2021	58100	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TANK COMP	found leak in tank		ATE tankers to repair		12/05/2021		Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Myrtleford - Workshop	Body\TRL REPS	RHSCURTAIN TORN AND MISSING BUCKEL				11/05/2021		Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Myrtleford Workshop	TRAILER
T431	Myrtleford - Workshop	Body\TANK COMP	LEAKING RESIN TANK				11/05/2021		Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Myrtleford Workshop	TRAILER
T431	Wodonga - Workshop	Tyres\TP1+2	Supply and fit 2 tyres				08/05/2021	56757	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				08/05/2021	56757	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Myrtleford Workshop	TRAILER
T431	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	replaced LHR booster		08/05/2021	56757	Service	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Myrtleford Workshop	TRAILER
T431	Wodonga - Workshop	Insp\HYDRO	Cracks in tank body		ATE Tankers to repair and perform Hydrostatic test		20/04/2021		Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
					Global Factory Maintenance														
T431	Wodonga - Workshop	Body\TANK COMP	repair resin leaks in tank x2		emergency crack repair on resin tanker Emergency crack repair on resin tanker as requested by Dean on 8.4.21		07/04/2021	47481	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Myrtleford - Workshop	Body\TANK COMP	Resin tank leaking				19/03/2021		Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Myrtleford Workshop	TRAILER
T431	Myrtleford - Workshop	Brakes\SLACK ADJ	Replace LHM Slack Adjusters				19/03/2021		Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Myrtleford Workshop	TRAILER
T431	Myrtleford - Workshop	Body\TRL REPS	RHS Curtain has a tear				19/03/2021		Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Myrtleford - Workshop	Body\STRAPS	Supply Bottom Strap				19/03/2021		Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				18/03/2021	41539	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Myrtleford Workshop	TRAILER
T431	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	needs 3x curtain straps		18/03/2021	41539	Service	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Myrtleford Workshop	TRAILER
T431	Wodonga - Workshop	Tyres\TP3+4	replace 2 tyres				14/02/2021	29688	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				06/01/2021		Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	move trailers and clean up		06/01/2021		Service	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Chassis\FIRE EXTIN	in truck				06/01/2021		Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TRL REPS	poor condition				06/01/2021		Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TRL REPS	poor condition				06/01/2021		Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Chassis\WHEEL BRGS	RF, LM hub seals leaking				06/01/2021		Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\DAMAGE	hole in RHS tank				06/01/2021		Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				19/11/2020		Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	trailer hasn't mowed since last service		19/11/2020		Service	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Insp\INT INSP	Quarterly inspection in conjunction with Global Factory Maintenance	Insp\INT INSP			17/11/2020		PreventativeMaintenance	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body	Assess roof lifting at front wall		roof track mounting bracket slightly bent has not effect on roof		17/11/2020	1191	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\RWC COMP	poor condition and all mixed up				13/11/2020	1189	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
			front roof lifting from front wall																
T431	Wodonga - Workshop	Body\TRL WALL	Andrew to Inspect best way to repair		inspected roof hooked trailers together move back to fence		13/11/2020	1189	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TRL FLOOR	soft in spots and rusting		previously done		13/11/2020	1189	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
			drop off at Globe Engineering Albury																
T431	Wodonga - Workshop	Workshop\MOVE ASSET	sick up 718071181				07/11/2020		Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Workshop\MOVE ASSET	drop at Albury - globe maintenance				05/11/2020		Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice				30/10/2020	493500	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Tyres\CLEANSKIN	Job Added From Invoice				30/10/2020	493500	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Insp\RWC COMP	repairs as per annual inspection		replce hubbo		22/10/2020		Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TRL WALL	silicone up front wall to roof cap and roof repairs				22/10/2020		Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Workshop\MOVE ASSET	hook up set and move and park				22/10/2020		Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Workshop\CLEAN	clean up from repairs				22/10/2020		Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\MUDGUARDS	replace lh side guards and damaged drain fittings for tank		replace guards remove and remount outriggers and repairs to bent outriggers		22/10/2020		Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				22/10/2020		Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			22/10/2020		Service	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	Insp\ANN INSP	done with service		22/10/2020		PreventativeMaintenance	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\HOUSEKEEP	cut of old tank fittings, clean old thread and replace				22/10/2020		Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TRL WALL	inspect roof damage and silicone up and paint				22/10/2020		Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Workshop\CLEAN	clean up after job				22/10/2020		Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Tyres	R rear inner tyre blown				22/10/2020		Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TANK MANI	broken valve fittings				22/10/2020		Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\RWC COMP	poor condition and all mixed up				22/10/2020		Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
			front roof lifting from front wall																
T431	Wodonga - Workshop	Body\TRL WALL	Andrew to Inspect best way to repair				22/10/2020		Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Chassis\MUDGUARDS	LH u/s x3				22/10/2020		Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TRL FLOOR	soft in spots and rusting				22/10/2020		Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TRL REPS	need replacing				22/10/2020		Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TRL REPS	u/s				22/10/2020		Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\DAMAGE	carry out repairs from damage		transpower to supply parts P/O WWO58989		22/10/2020		Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice				27/09/2020	492952	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Tyres\CLEANSKIN	Job Added From Invoice				27/09/2020	492952	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body	Repair crack in resin tank				13/09/2020	490120	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Elect\INDICATORS	REPLACE N/S REAR IMMOCATOR ASSEMBLY				05/09/2020		Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		Previously completed		23/08/2020		Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Chassis\TRL LEGS	Landing legs hard to wind		Inspected - ok		23/08/2020		Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Susp\AIR BAG	6x C21800 Hendrikson - pin holes		Inspected - ok		23/08/2020		Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TRL REPS	Rips & holes in curtains				23/08/2020		Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Chassis\WHEEL SEAL	LHR hub leaking		Inspected - ok		23/08/2020		Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\AIR LEAK	small leak behind dump valve		Inspected - no leak		23/08/2020		Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TRL LEGS	stick at top and hard to move		Gearbox needs a cleanout		23/08/2020		Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TRL REPS	poor condition and rips and holes, pellmet rubber damaged at rear- pending		As per #302031		23/08/2020		Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TRL REPS	Rollers grab, track / mocby- pending		As per #302031		23/08/2020		Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Chassis\WHEEL SEAL	LHM & LHR hub seals leaking		Inspected - ok		23/08/2020		Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	Previously completed		23/08/2020		Service	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Elect\TRL LIGHTS	trailer lights inoprative		Hallum Truck Centre to carry out repairs P/O WWO57122		15/08/2020		Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Driv\Inr\WHL HUB	Job Added From Invoice				08/08/2020	0	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				02/08/2020	473795	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			02/08/2020	473795	Service	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Chassis\WHEEL SEAL	LHM & LHR hub seals leaking				02/08/2020	473795	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Brakes\BOOSTER	replace booster and lines				01/08/2020	473795	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				05/07/2020	46329	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TRL REPS	buckle straps u/s and missing-pending				05/07/2020	46329	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			05/07/2020	46329	Service	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Insp\RWC COMP	RESIN TANKER INSPECTION AS PER ATTACHED RUNSHEET				06/06/2020		Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\BREAKDOWN	ATTEND AFTERHOURS CALL OUT TO ALPINE		RESIN TANK VENT TAPS LEAKING AT THREADS. REMOVE TAPS, DISASSEMBLE AND REASSEMBLE WITH THREAD SEALANT, RETURN TO WORKSHOP		23/05/2020		Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\HOSES	Supply and fit new breather hoses		Rapid to supply parts PO WWO54515		16/05/2020		Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				15/05/2020	446326	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Chassis\TRL LEGS	Landing legs hard to wind		pending		15/05/2020	446326	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Susp\AIR BAG	6x C21800 Hendrikson - pin holes		pending- very small leaks		15/05/2020	446326	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TRL REPS	rollers jamming up		ok		15/05/2020	446326	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TRL REPS	Rips & holes in curtains		pending		15/05/2020	446326	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Chassis\WHEEL SEAL	LHR hub leaking				15/05/2020	446326	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TRL REPS	tarp has small rips cone need attention		done		15/05/2020	446326	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TRL REPS	one upright missing on right hand side, curtain torn right top back		upright previously done		15/05/2020	446326	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			15/05/2020	446326	Service	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\PAINT/REST	prep- rail and ladder for paint, paint rails and ladder, finish RNR repairs				15/05/2020	446326	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Workshop\MOVE ASSET	move trailers				15/05/2020	446326	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Workshop\CLEAN	clean up from job				15/05/2020	446326	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\AIR LEAK	small leak behind dump valve-pending				15/05/2020	446326	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TRL REPS	buckle straps u/s and missing-pending				15/05/2020	446326	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Driv\Inr\WHEEL BRGS	LHM adjusted				15/05/2020	446326	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TRL LEGS	stick at top and hard to move				15/05/2020	446326	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TRL REPS	poor condition and rips and holes, pellmet rubber damaged at rear- pending				15/05/2020	446326	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\CHN/RUR/MN	Rollers grab, track / mocby- pending				15/05/2020	446326	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
					Cold wash														
					Wash for workshop														
					Internal clean														
T431	Wodonga - Workshop	Bulk Wash\Inter Wash	Bulk tanker internal wash		Hot air drv		12/05/2020		Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice				26/04/2020	1234	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Tyres\CLEANSKIN	Job Added From Invoice				26/04/2020	1234	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice				26/04/2020	438679	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Tyres\CLEANSKIN	Job Added From Invoice				26/04/2020	438679	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Tyres\AH Callout	Job Added From Invoice				26/04/2020	438679	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				18/04/2020	438679	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			18/04/2020	438679	Service	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TANK COMP	repair pin hole in tank RHS				20/03/2020		Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	VehService\DS	Service	VehService\DS			20/03/2020		Service	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				20/03/2020	426089	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			20/03/2020	426089	Service	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TRL REPS	Rips & holes in curtains				20/03/2020	426089	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Chassis\WHEEL SEAL	LHR hub leaking				20/03/2020	426089	Repair	Completed	FL Green Distribution	Resin

T431	Wodonga - Workshop	VehService\DS	D:Service As Per Attached Checklist		VehService\DS		04/01/2020	399194	Service	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice				22/11/2019	383945	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Tyres\CLEANSKIN	Job Added From Invoice				22/11/2019	383945	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TANK COMP	Crack in resin tank above spare tyre				03/11/2019		Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TANK COMP	Repair Resin Tank Cracks Above Spare Tyre At Rear				03/11/2019		Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TANK COMP	Repair Crack In Tank In Front Of RH Axle At Bottom Of Tank				03/11/2019		Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Insp\3NT INSP	Global Engineering to inspect internally & externally and report			Carry out repairs as per report, repair tank leaks found general surface corrosion in tank lubricate T handles tank seal to be replaced next service.	03/11/2019		Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Susp\AIR BAG	Replaced 4x airbags			Top nuts were difficult to remove due to lack of room to move	30/10/2019		Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Insp\3NT INSP	Job Added From Invoice				28/10/2019	0	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Susp\AIR BAG	all bags leak C-21800				24/10/2019		Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				24/10/2019		Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TANK COMP	Crack in resin tank above spare tyre				24/10/2019		Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TRL REPS	tarp has small rips cone need attention				24/10/2019		Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TANK COMP	Repair Resin Tank Cracks Above Spare Tyre At Rear				24/10/2019		Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TANK COMP	Repair Crack In Tank In Front Of RH Axle At Bottom Of Tank				24/10/2019		Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	VehService\DS	D:Service As Per Attached Checklist		VehService\DS	Danger lock tab Centre left was not engaged	24/10/2019		Service	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Chassis\TRL LEGS	Landing legs hard to wind				24/10/2019		Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Susp\AIR BAG	6x C21800 Hendrikson - pin holes				24/10/2019		Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Myrtleford - Workshop	Body\TANK COMP	Crack in resin tank above spare tyre				02/10/2019		Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Myrtleford Workshop	TRAILER
T431	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				20/09/2019	372566	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Myrtleford Workshop	TRAILER
T431	Myrtleford - Workshop	VehService\DS	D:Service As Per Attached Checklist		VehService\DS		20/09/2019	372566	Service	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Myrtleford Workshop	TRAILER
T431	Wodonga - Workshop	Body\TANK PANEL	holes in tanker				05/09/2019	367437	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Myrtleford - Workshop	Elect\INDICATORS	replace side indicator on trailer				22/08/2019		Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Myrtleford Workshop	TRAILER
T431	Wodonga - Workshop	Tyres\CASE STOCK	Job Added From Invoice				11/08/2019	355073	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice				11/08/2019	355073	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Tyres\RETREAD	Job Added From Invoice				11/08/2019	355073	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TANK COMP	Repair tank leaks				03/08/2019	355073	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				02/08/2019	354457	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Myrtleford Workshop	TRAILER
T431	Myrtleford - Workshop	VehService\DS	D:Service As Per Attached Checklist		VehService\DS	adjust suspension ride height	02/08/2019	354457	Service	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Myrtleford Workshop	TRAILER
T431	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice				20/07/2019	343864	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Tyres\CLEANSKIN	Job Added From Invoice				20/07/2019	343864	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist		Insp\ANN INSP		12/07/2019	346605	PreventativeMaintenance	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Susp\AIR BAG	all bags leak C-21800				12/07/2019	346605	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TANK COMP	check for cracks			very minor cracks - ok	12/07/2019	346605	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Insp\RWC COMP	need one ordered u/s above spare and air tank cracked			previously done	12/07/2019	346605	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Chassis\CHAS CRACK	oin hole at LH ladder weld oatch			full tank inspection	12/07/2019	346605	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TRL LEGS	both creased and LH drops when winding down			ok - still work fine	12/07/2019	346605	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Myrtleford - Workshop	Susp\HCV	Check Ride Height Valve & Suspension Fo Leaks				06/07/2019		Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Myrtleford Workshop	TRAILER
T431	Myrtleford - Workshop	Body\TANK COMP	Leaks On RHS At Old Repair				06/07/2019		Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Myrtleford Workshop	TRAILER
T431	Myrtleford - Workshop	Body\DAMAGE	Replace LHR Curtain Ratchet 1 padlock on load valve failing to lock				06/07/2019		Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Myrtleford Workshop	TRAILER
T431	Myrtleford - Workshop	Hydraulics\VALVES	need new one and new spare				06/07/2019		Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Myrtleford Workshop	TRAILER
T431	Myrtleford - Workshop	Body\DAMAGE	metal on metal noise at rear of trailer				06/07/2019		Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Myrtleford Workshop	TRAILER
T431	Myrtleford - Workshop	Elect\TRL LIGHTS	Check Loose & Broken Clearance Lights				06/07/2019		Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Myrtleford Workshop	TRAILER
T431	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				05/07/2019	343865	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Myrtleford Workshop	TRAILER
T431	Myrtleford - Workshop	VehService\DS	D:Service As Per Attached Checklist		VehService\DS	resin leak need fixing asap. Card in system for this job and I aslo sent emails about resin leak (WD)	05/07/2019	343865	Service	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Myrtleford Workshop	TRAILER
T431	Wodonga - Workshop	Tyres\PRES CHECK	Job Added From Invoice				18/06/2019	10	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				01/06/2019	331847	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	VehService\DS	D:Service As Per Attached Checklist		VehService\DS		01/06/2019	331847	Service	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Tyres\Punct	Job Added From Invoice				09/05/2019	320996	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				28/04/2019	316472	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	VehService\DS	D:Service As Per Attached Checklist above spare and air tank cracked		VehService\DS		28/04/2019	316472	Service	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Chassis\CHAS CRACK	oin hole at LH ladder weld oatch				28/04/2019	316472	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TRL LEGS	both creased and LH drops when winding down				28/04/2019	316472	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice				28/03/2019	302516	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Tyres\CLEANSKIN	Job Added From Invoice				28/03/2019	302516	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice				21/03/2019	300898	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Tyres\CLEANSKIN	Job Added From Invoice				21/03/2019	300898	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Tyres\AH Callout	Job Added From Invoice				21/03/2019	300898	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Tyres\SCRAP TYRE	Job Added From Invoice				21/03/2019	300898	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				17/03/2019	299706	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Insp\RWC COMP	NHVAS sticker is faded				17/03/2019	299706	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	VehService\DS	D:Service As Per Attached Checklist		VehService\DS		17/03/2019	299706	Service	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Driv\Inv\WHL HUB	Job Added From Invoice Greenfreight resin trailer quartely inspection				06/02/2019	0	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Insp\3NT INSP	Comoleted 2nd February 2019				03/02/2019		Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				03/02/2019	284450	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\MUDGUARDS	mudguards loose on left side			previously done	03/02/2019	284450	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Chassis\CHAS CRACK	LH side at steps, small crack pending				03/02/2019	284450	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\DH&S	needs to be sorted (pending), no extinguisher (pending)				03/02/2019	284450	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Susp\AIR BAG	6 bags perished C-21800				03/02/2019	284450	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TANK COMP	weld/patch leaks on resin tanks				03/02/2019	284450	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	VehService\DS	D:Service As Per Attached Checklist		VehService\DS		03/02/2019	284450	Service	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Myrtleford - Workshop	Elect\TRL LIGHTS	clearance light - RHS				09/01/2019		Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Myrtleford Workshop	TRAILER
T431	Myrtleford - Workshop	Body\MOUNTS	poles on trailer broken				09/01/2019		Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Myrtleford Workshop	TRAILER
T431	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				09/01/2019	275119	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Myrtleford Workshop	TRAILER
T431	Myrtleford - Workshop	VehService\DS	D:Service As Per Attached Checklist		VehService\DS		09/01/2019	275119	Service	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Myrtleford Workshop	TRAILER
T431	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				13/12/2018	267272	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Myrtleford Workshop	TRAILER
T431	Myrtleford - Workshop	VehService\DS	D:Service As Per Attached Checklist		VehService\DS		13/12/2018	267272	Service	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Myrtleford Workshop	TRAILER
T431	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice				06/12/2018	263087	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Tyres\CLEANSKIN	Job Added From Invoice				06/12/2018	263087	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				28/10/2018	251634	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	VehService\DS	D:Service As Per Attached Checklist		VehService\DS	smoko included	28/10/2018	251634	Service	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Chassis\WINCH/STRP	Job Added From Invoice				29/09/2018	0	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\MOUNTS	prep/ fabricate/modify mounting brackets				18/09/2018	242542	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\MOUNTS	prep and paint before fitting				18/09/2018	242542	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TOOLBOX	fit finished toolbox				18/09/2018	242542	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Steering\WHEEL ALIGN	Wheel alignment				15/09/2018		Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Driv\Inv\BRK RELINE	Prep hubs for reline				14/09/2018		Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Workshop\MOVE ASSET	remove from shed				13/09/2018		Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Workshop\MOVE ASSET	drop T431 at HTT and pick up T430				13/09/2018		Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Workshop\MOVE ASSET	pick up T431 from HTT				13/09/2018		Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TRL REPS	Curtains on both sides need repairing				11/09/2018	242527	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Chassis\WINCH/STRP	Replace missing curtain straps x 4			replaced missing curtain straps on T430 and T431 and go over other repairs	11/09/2018	242527	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\DAMAGE	fork driver knocked roof support out left front, needs to be fitted back in reline completed				11/09/2018	242527	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Brakes\BRK RELINE	Reline as required			bearing adjustments checked by Deans	11/09/2018	242527	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Workshop\CLEAN	clean work area				11/09/2018	242527	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Brakes\BOOSTER	replace RHR booster and airlines as required				11/09/2018	242527	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TOOLBOX	remove RH toolbox repair LH tool box				11/09/2018	242527	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TRL REPS	fit lid locks				11/09/2018	242527	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TRL REPS	fit curtains and stoppers				11/09/2018	242527	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TRL REPS	curtain repairs look on back				11/09/2018	242527	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	VehService\DS	Service		VehService\DS		07/09/2018		Service	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job basic inspection for customer.				07/09/2018		Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Comp	Hexian				31/08/2018		Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Elect	Job Added From Invoice				18/07/2018	0	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				12/07/2018	219987	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Myrtleford Workshop	TRAILER
T431	Myrtleford - Workshop	VehService\DS	D:Service As Per Attached Checklist		VehService\DS		12/07/2018	219987	Service	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Myrtleford Workshop	TRAILER
T431	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice				26/06/2018	0	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Tyres\CLEANSKIN	Job Added From Invoice				26/06/2018	0	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Insp\ANN INSP	annual inspection				26/06/2018		Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				09/06/2018	207353	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Myrtleford Workshop	TRAILER
T431	Myrtleford - Workshop	VehService\DS	D:Service As Per Attached Checklist		VehService\DS		09/06/2018	207353	Service	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Myrtleford Workshop	TRAILER
T431	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				10/05/2018	194554	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Myrtleford Workshop	TRAILER
T431	Myrtleford - Workshop	VehService\DS	D:Service As Per Attached Checklist		VehService\DS		10/05/2018	194554	Service	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Myrtleford Workshop	TRAILER
T431	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				12/04/2018	184260	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Myrtleford Workshop	TRAILER
T431	Myrtleford - Workshop	VehService\DS	D:Service As Per Attached Checklist		VehService\DS		12/04/2018	184260	Service	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Myrtleford Workshop	TRAILER
T431	Wodonga - Workshop	Driv\Inv\BREAKDOWN	Hub leaking				15/03/2018		Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				15/03/2018	174815	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Myrtleford Workshop	TRAILER
T431	Myrtleford - Workshop	VehService\DS	D:Service As Per Attached Checklist		VehService\DS		15/03/2018	174815	Service	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Myrtleford Workshop	TRAILER
T431	Wodonga - Workshop	Body\TRL REPS	tarp has small rips cone need attention			do not have any patch for 3rd month now - could not do	15/02/2018	165544	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\TRL GATES	poles on left side don't slide very well			lube rollers and straighten out small section of hook patch seb head due to no patch re-patched old patch	15/02/2018	165544	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
			tarp has small rips one needs attn dowy rear axle drivers side outer front trp on front tank need replacing			tyre fitters to be look at wheels											
T431	Wodonga - Workshop	Body\TRL REPS	residue driss out onto side of tank			chaneed broken and missine curtain buckles	15/02/2018	165544	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Workshop\MOVE ASSET	bring trailer set into shed for service. Already serviced (9/2/18) saw Byron for advice.				15/02/2018	165544	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Body\REFLECTORS	reflectors				15/02/2018	165544	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Workshop\CLEAN	clean service bay after job				15/02/2018	165544	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				10/02/2018	164351	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Myrtleford Workshop	TRAILER
T431	Myrtleford - Workshop	VehService\DS	D:Service As Per Attached Checklist		VehService\DS	repair trailer plug (lights)	10/02/2018	164351	Service	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Myrtleford Workshop	TRAILER
T431	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				17/01/2018		Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Myrtleford Workshop	TRAILER
T431	Myrtleford - Workshop	VehService\DS	D:Service As Per Attached Checklist		VehService\DS		17/01/2018		Service	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Myrtleford Workshop	TRAILER
T431	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice				30/12/2017	0	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Tyres\CLEANSKIN	Job Added From Invoice				30/12/2017	0	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				19/12/2017	144929	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Myrtleford Workshop	TRAILER
T431	Myrtleford - Workshop	VehService\DS	D:Service As Per Attached Checklist		VehService\DS	LHM tyres are low on tread	19/12/2017	144929	Service	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Myrtleford Workshop	TRAILER
T431	Wodonga - Workshop	Tyres	Job Added From Invoice				14/12/2017	0	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Tyres\CLEANSKIN	freplace pos 31/32				29/11/2017		Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Myrtleford - Workshop	Steering\TRL REPS	straighten panel at tarp ratchet on tautliner				24/11/2017	136461	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Myrtleford Workshop	TRAILER
T431	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				23/11/2017	135920	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Myrtleford Workshop	TRAILER
T431	Myrtleford - Workshop	VehService\DS	D:Service As Per Attached Checklist		VehService\DS		23/11/2017	135920	Service	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Myrtleford Workshop	TRAILER
T431	Wodonga - Workshop	Tyres	Job Added From Invoice				24/10/2017	0	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Tyres	Job Added From Invoice				21/10/2017	0	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice				21/10/2017	0	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER
T431	Wodonga - Workshop	Tyres\CLEANSKIN	Job Added From Invoice				21/10/2017	0	Repair	Completed

T431	Wodonga - Workshop	Elect\ELECT P&W	FL top light is out				22/08/2017	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	Body\TRL REPS	RB curtain at top is reaped				22/08/2017	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	Elect\ELECT P&W	LHF top light o/s				22/08/2017	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	Body\TRL REPS	curtains need patching			completed	22/08/2017	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	DrivLine\WHEEL BRGS	bearing adjustment			could not fault	22/08/2017	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
						inspect for leaks													
						booster & service lines rubbed through													
T431	Wodonga - Workshop	Body\AIR BAG	S airbags o/s			chanaed lines and stopped up loose lines	22/08/2017	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				06/08/2017 9835	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	Insp\RWC COMP	NHVAS sticker is faded				06/08/2017 9835	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	moving trailers		06/08/2017 9835	Service	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	Elect\ELECT P&W	LHF top light o/s				06/08/2017 9835	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	Insp\RWC COMP	need one ordered o/s				06/08/2017 9835	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	Body\TRL REPS	curtains need patching				06/08/2017 9835	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	DrivLine\WHEEL BRGS	bearing adjustment				06/08/2017 9835	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	Body\AIR BAG	S airbags o/s				06/08/2017 9835	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				09/07/2017 87249	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			09/07/2017 87249	Service	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	Body\HOSES	replace guard				16/06/2017 766323	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	Workshop\MOVE ASSET	move trailer 3x's, parked up hooked up T495 with yard truck				16/06/2017 766323	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	Body\HOSES	replace guard				16/06/2017 766323	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	Workshop\MOVE ASSET	move trailer 3x's, parked up hooked up T495 with yard truck				16/06/2017 766323	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				30/05/2017 71392	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Myrtleford Workshop	TRAILER			
T431	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			30/05/2017 71392	Service	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Myrtleford Workshop	TRAILER			
						completed													
T431	Wodonga - Workshop	Chassis\CHAS CRACK	repair damaged crack			*replaced rear tank valve	07/05/2017 62542	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	Susp\SHOCK ABS	bushes look worn o/s				20/04/2017	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	Susp\AIR BAG	S air bags perished o/s				20/04/2017	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	Brakes\BRK RELINE	reline mid axle brakes				20/04/2017	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	Susp\SUSPENSION	helped Darren with spring arm bushes				20/04/2017	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	Susp\AXLES	Centre axle bearing cups				20/04/2017	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	Body\TRL REPS	repaired curtains and holes in roof with Joel				20/04/2017	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	Susp\SPRING HANG	weld hanger cracks				20/04/2017	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	Body\MUDGUARDS	removed RHM/R wheels and guard and outriggers, ready to get welding done on tank				20/04/2017	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	Chassis\WINCH/STRP	Repair leaking tank, straighten RH front corner, repair RH front curtain ratchet and straithen air inlet and outlet				20/04/2017	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				19/04/2017	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	Elect\ELECT P&W	LHF top clearance light o/s				19/04/2017	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			19/04/2017	Service	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	Elect\ELECT P&W	FL top light is out				19/04/2017	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	Insp\RWC COMP	NHVAS sticker is faded				19/04/2017	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	Body\TRL REPS	RB curtain at top is reaped				19/04/2017	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
			Split trailers																
T431	Wodonga - Workshop	Body\MUDGUARDS	Removed RHM/R wheels and auards and outrieaers. ready to eet weldine done on tank				19/04/2017	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				19/03/2017	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	Body\TRL REPS	2 right side upright poles need to be fixed			All four uprights repaired	19/03/2017	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	Chassis\WINCH/STRP	buckle needs replace left side			strap replaced	19/03/2017	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	Insp\ANN INSP	perform annual inspection				19/03/2017	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	Insp\INT INSP	pressure test tanks				19/03/2017	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			19/03/2017	Service	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	Tyres\TP11	Job Added From Invoice				09/02/2017 25992	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
			weld leaks & fit hatch cam locks, rego stickers																
T431	Wodonga - Workshop	Body\HOSES	emotiv tanks of water				08/02/2017	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	Body\TANK PANEL	Repair cracks				07/02/2017	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				02/02/2017 24808	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Myrtleford Workshop	TRAILER			
T431	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			02/02/2017 24808	Service	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Myrtleford Workshop	TRAILER			
T431	Wodonga - Workshop	Tyres\TP11	Job Added From Invoice				31/12/2016 12109	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	Tyres\TP15	Job Added From Invoice				31/12/2016 12109	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			30/12/2016	Service	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				30/12/2016	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	Susp\SHOCK ABS	bushes look worn o/s				30/12/2016	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	Susp\AIR BAG	S air bags perished o/s				30/12/2016	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	Bulk Wash\Inter Wash	Tank clean			worksheet number - 17386	21/12/2016	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				11/12/2016	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			11/12/2016	Service	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	Elect\ELECT P&W	LHF top clearance light o/s				11/12/2016	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Myrtleford - Workshop	DrivLine\WHL HUB	Replace digital hubometer				15/11/2016	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Myrtleford Workshop	TRAILER			
T431	Wodonga - Workshop	DrivLine	Job Added From Invoice				15/11/2016 0	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			12/11/2016	Service	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Myrtleford Workshop	TRAILER			
T431	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				12/11/2016	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Myrtleford Workshop	TRAILER			
T431	Wodonga - Workshop	Body\DAMAGE	repair rear bar (Bent Back)				15/09/2016	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				11/09/2016	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	VehService	service				11/09/2016	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	Body	FRH top strap o/s				11/09/2016	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			11/09/2016	Service	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	Tyres\TP19	Job Added From Invoice				10/09/2016 0	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				17/08/2016	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			17/08/2016	Service	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	Elect\TRL LIGHTS	RH number plate light o/s			done TCTC vic roads insp job 30041	17/08/2016	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	Body\PAINT/REST	needs repairs			Done " TCTC vic roads insp job 30041	17/08/2016	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	Brakes\BRK RELINE	needs reline			done " TCTC part of insp VicRoads job 30041	17/08/2016	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	Insp\DEFECT	Carry out road worthy and repair			tyres replaced lights fixed brakes repaired & cross member fixed	17/08/2016	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				14/08/2016	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	Elect	RH number plate light o/s				14/08/2016	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	Body	needs repairs				14/08/2016	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	Brakes	needs reline				14/08/2016	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			14/08/2016	Service	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	Body\TRL REPS	repair R/H curtain				19/06/2016	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
			replace hub cap screen																
T431	Wodonga - Workshop	DrivLine\WHEEL BRGS	insoect and replace arease as reauired				19/06/2016	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	Tyres\TP11	Job Added From Invoice				09/06/2016 0	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				27/05/2016	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			27/05/2016	Service	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	Elect	replace c/light				08/05/2016	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	Elect\TRL LIGHTS	clearance light o/s				08/05/2016	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	Tyres\TP16	Job Added From Invoice				03/05/2016 0	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				01/05/2016	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			01/05/2016	Service	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	Tyres\TP11	Job Added From Invoice				01/04/2016 116149	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	Brakes\AIR LEAK	air leak			none found	30/03/2016	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	Brakes\BRK O/HAUL	brakes holding after release brake			found no problem	30/03/2016	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	Body\TRL REPS	drivers side curtain front			done	30/03/2016	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	Tyres	1x tyre drives side rear			done	30/03/2016	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				25/03/2016	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			25/03/2016	Service	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	Brakes\AIR LEAK	air leak				23/03/2016 683477	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	Brakes\BRK O/HAUL	brakes holding after release brake				23/03/2016 683477	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	Body\TRL REPS	drivers side curtain front				23/03/2016 683477	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	Tyres	1x tyre drives side rear				23/03/2016 683477	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	Tyres\TP22	Job Added From Invoice				22/03/2016 0	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			19/02/2016	Service	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				23/02/2016	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	Body	Leaking resin			job previously done	31/12/2015	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	VehService	due for service			completed	22/12/2015	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	Body	leaking resin bottom B weld again			job previously done	22/12/2015	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	Body\AIR LEAK	slight air leak			could not find one	22/12/2015	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	VehService	missed two services due to work load			complete service	19/12/2015	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	Brakes	brakes valves			inspected. Brakes ok. Valves ok	19/12/2015	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	Body	buckles			replaced 2x buckles	19/12/2015	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	Tyres\TP11	Job Added From Invoice				08/12/2015 0	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			26/11/2015	Service	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				26/11/2015	Repair	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	VehService\DS	Past 2 services	VehService\DS			21/11/2015	Service	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	Brakes	Trailor brakes holding on after pedal is released				21/11/2015	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	Brakes	Brakes holding on				21/11/2015	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
			Breaks are holding on after brakes are released																
T431	Wodonga - Workshop	Brakes	Air leak				21/11/2015	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	Brakes	trailor breaks holding on after pedal is released				21/11/2015	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	Brakes	brakes holding on				21/11/2015	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
			breakes holding on after pedal is releaded																
T431	Wodonga - Workshop	Brakes	air leak				21/11/2015	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	Brakes\BRAKE ADJ	Brakes grabing				21/11/2015	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	Body\TRL REPS	2 X Buckles				21/11/2015	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	Body\FIFTH WHEE	Pins need to be checked lots of movement				21/11/2015	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	Body	resin leaking				21/11/2015	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	VehService	due for service				21/11/2015	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	Body	drivers side upright will not lock in back one				21/11/2015	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	Body	leaking resin				21/11/2015	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	Chassis\AIR LEAK	leaking air at rear				21/11/2015	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	Body	valve hard to open at rear stiff				21/11/2015	Fault	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			
T431	Wodonga - Workshop	VehService\DS	needs service	VehService\DS			21/11/2015	Service	Completed	FL Green Distribution	ResinTline	Wodonga	RES	742765	Wodonga Workshop	TRAILER			