EquipmentName	Workshop	CodeAndSubCode	Description	Schedule	CompletionComments	DateDone	DistanceDone	Workstate	EquipmentOwner	MaintenanceGroup	Location	Division	Rego	Supplier	EquipmentType
					CLEAN AD BLUE INJECTOR REPLACE HYD FILTER & TOP UP HYD OIL REPLACE WIPER BLADES REPAIR DASH LIGHTS REPLACE POLLAND FILTER COVER KLM AT TIME OF SERVICE 446903										
			VehService\AS A Service												
1077	Myrtleford - Workshop	VehService\AS	REPLACE LH & RH TOP BONNET SURPORTS	VehService\AS		02/06/2026	446903	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Myrtleford Workshop	P/MOVER
					SERVICED AT 446903 KMS CLEAN AD BLUE INJECTOR WASH 1077 T384 T239										
			VehService\AS A Service												
1077	Albury - Workshop	VehService\AS		VehService\AS	DOUBLE UP ON SERVICE SHEET ORIGINAL ONE COMPLETED ON JOB NUMBER 206718 CHECK FRONT DIFF HOUSING FOR LEAKS ALL OK	02/06/2026	446903	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Myrtleford Workshop	P/MOVER
1077	Albury - Workshop	DriveLine\DIFF OIL	Front diff leaking at housing		CHECKED AT 446903 KMS 1/6/26 CHECK AIR COMPRESSOR FOR OIL LEAKS ALL OK	02/06/2026	441092	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Albury Workshop	P/MOVER
1077	Albury - Workshop	Engine	Compressor leak oil		DONE AT 446903 KMS	01/06/2026	441092	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Myrtleford Workshop	P/MOVER
1077	Albury - Workshop	DrCabElect\RADIO	UHF's are not working correctly, both radio set's are cutting out and have NO distance.		FIT 2 X NEW FIBREGLASS ANTENNES	01/06/2026	441092	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Myrtleford Workshop	P/MOVER
1077	Albury - Workshop	DrCabRep\HOUSEKEEP	NEED A NEW R&R BOOK		PUT NEW R/R BOOK IN CAB CHECK POWER STEER PUMP FOR OIL LEAKS ALL OK	01/06/2026	441092	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Myrtleford Workshop	P/MOVER
			power steering pump mount gasket leaking		DONE AT 446903 KMS										
1077	Albury - Workshop	Steering\PWR STEER				01/06/2026	441092	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Myrtleford Workshop	P/MOVER
					CHECK PTO FOR LEAKS AT G/BOX & HOSES ALL OK										
1077	Albury - Workshop	DriveLine	PTO leak		DONE AT 446903 KMS CHANGE CTI FILTER & TEST CTI	01/06/2026	441092	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Myrtleford Workshop	P/MOVER
1077	Albury - Workshop	Susp\AIR LEAK	CTI will Not hold air at 80psi.		ALSO ADJUST GOVERNOR PRESSURE TO 8.5 CUT OFF	01/06/2026	446903	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Myrtleford Workshop	P/MOVER
1077	Albury - Workshop	Elect\HEAD LIGHT	-L/H DRIVING LIGHT NOT WORKING		REPLACE LH DRIVING LIGHT PLUG UNDER BONNET	01/06/2026	446903	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Myrtleford Workshop	P/MOVER
1077	Albury - Workshop	DriveLine\DRIVES	ADJUST POWER DIVIDER END FLOAT TO SPEC		KLM AT TIME OF ADJUSTMENT 446903	01/06/2026	446903	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Myrtleford Workshop	P/MOVER
1077	Albury - Workshop	Engine\AIR LEAK	RESET AIR DRIER		KLM AT TIME OF RESET 446903	01/06/2026	446903	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Myrtleford Workshop	P/MOVER
			VehService\AS A Service												
1077	Albury - Workshop	VehService\AS	T133982	VehService\AS		23/05/2026	441092	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	TWIN CITY TRUCK CENTRE - 4	P/MOVER
					inspected ok										
1077	Albury - Workshop	Engine	Power steering pump to compressor oil leak		JS	13/05/2026	400000	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Albury Workshop	P/MOVER
1077	Albury - Workshop	Body\ELECT P&W	Work light's on Headache Rack are not Working.		put fuse in now working	13/05/2026	400000	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Albury Workshop	P/MOVER
1077	Albury - Workshop	Chassis	Cab guard rar		completed JS	13/05/2026	400000	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Albury Workshop	P/MOVER
1077	Albury - Workshop	Body\ELECT P&W	No work light's on Cab Guard.		completed put new globes in	13/05/2026	400000	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Albury Workshop	P/MOVER
1077	Albury - Workshop	DrCabElect\INST/GAUGE	Dash Warning Lights Not Working, Engine Brake, Cruise Control & Diff Lock		JS	13/05/2026	400000	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Albury Workshop	P/MOVER
1077	Albury - Workshop	Susp\SHOCK ABS	RH FRONT TOP SHOCKER RUBBERS NEE REPLACING		inspected ok	13/05/2026	400000	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Albury Workshop	P/MOVER
			VehService\B1 Svc B 1 Service, Jack up steer axle check bearings and king pins.												
1077	Albury - Workshop	VehService\B1 Svc	Reslace cabin filter.	VehService\B1 Svc	completed by JS	13/05/2026	400000	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Albury Workshop	P/MOVER
1077	Albury - Workshop	Brakes\BACK PLATE	RH REAR AND LH FRONT DRIVE BACKING PLATES MISSING NEED REPLACING		completed by JS	13/05/2026	400000	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Albury Workshop	P/MOVER
1077	Albury - Workshop	Tyres\TP11+12	Tyres\TP11+12		LOW	01/05/2026	376100	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	BORDER BANDAG PTY LTD - 4	P/MOVER
1077	Albury - Workshop	Tyres\TP5+6	Tyres\TP5+6		LOW	01/05/2026	376100	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	BORDER BANDAG PTY LTD - 4	P/MOVER
1077	Albury - Workshop	Tyres\TP9+10	Tyres\TP9+10		LOW	01/05/2026	376100	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	BORDER BANDAG PTY LTD - 4	P/MOVER
1077	Albury - Workshop	Tyres\TP7+8	Tyres\TP7+8		LOW CUSTOMER REPORTS CTI IS NOT WORKING SINCE WE REPLACED CLUTCH * Inspected control panel in dash & confirmed not operating * Inspected wiring & powers in box on chassis & found all ok * Inspected fuse behind dash - All ok * Removed panel on overhead console to gain access to wiring on control panel * Checked powers - All ok * Found bad earth present * Inspected earth terminal & found faulty contact * Removed terminal * Cut back wires & extended * Soldered in replacement terminal * Refit earth wire * Refit all removed components * Aligned, adjusted & tensioned all components * Test operations - All ok, fault no lonner prese	01/05/2026	376100	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	BORDER BANDAG PTY LTD - 4	P/MOVER
1077	Albury - Workshop	DriveLine\CTI Drive	DriveLine\CTI Drive		completed by JS TP	24/04/2026	376100	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	TWIN CITY TRUCK CENTRE - 4	P/MOVER
			VehService\AS A Service												
1077	Albury - Workshop	VehService\AS		VehService\AS	brake measurement unknown	24/04/2026	376100	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Albury Workshop	P/MOVER
1077	Albury - Workshop	Body\MUDGUARDS	Replace L/H rear Guard.			23/04/2026	376100	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Albury Workshop	P/MOVER
1077	Albury - Workshop	Body\MUDGUARDS	Replace Drive Guard and tighten outrigger.			15/04/2026	376100	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Albury Workshop	P/MOVER
1077	Albury - Workshop	DriveLine\CLUTCH	No Clutch Brake. Diagnose and repair. C Service		Tctc for clutch	02/04/2026	376100	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Albury Workshop	P/MOVER
1077	Albury - Workshop	VehService\CS	Serviced 415,452 Kms	VehService\CS		30/03/2026	376100	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Albury Workshop	P/MOVER
1077	Albury - Workshop	Tyres\RUN OUT	Tyres\RUN OUT POS 6-7			29/03/2026	376100	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	BORDER BANDAG PTY LTD - 4	P/MOVER
1077	Albury - Workshop	Brakes\BRAKE ADJ	Brake's not holding on hill's,need adjusting.			25/03/2026	376100	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Albury Workshop	P/MOVER
1077	Albury - Workshop	VehService\AS	VehService\AS A Service	VehService\AS	SMc TP	21/03/2026	376100	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Wodonga Workshop	P/MOVER
1077	Albury - Workshop	Tyres\TP1+2	Tyres\TP1+2		CALL OUT	17/03/2026	376100	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	BORDER BANDAG PTY LTD - 4	P/MOVER
1077	Wodonga - Workshop	DrCabRep\ELECT P&W	CTI Screen has gone blank.		swapped out of 1071	14/03/2026	376100	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Wodonga Workshop	P/MOVER
1077	Albury - Workshop	Workshop\MOVE ASSET	disconnect trailer's 505/506 and hook up to trailer's 396/397.		Driver completed	13/03/2026	375143	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Albury Workshop	P/MOVER
1077	Myrtleford - Workshop	DriveLine	Bell crank bearingsb		AS ABOVE	11/03/2026	376100	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Myrtleford Workshop	P/MOVER
1077	Myrtleford - Workshop	DriveLine	Bell crank bearingsb		AS ABOVE	11/03/2026	376100	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Myrtleford Workshop	P/MOVER
1077	Myrtleford - Workshop	Engine	Compressor leak Compressor leak		INSPECTED ALL GOOD LEAKING FROM POWER STEERING MOUNT GASKET	11/03/2026	376100	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Myrtleford Workshop	P/MOVER
1077	Myrtleford - Workshop	Engine	Bell. Crank bearinas		AS ABOVE KLM AT TIME OF REPLACEMENT 401613	11/03/2026	376100	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Myrtleford Workshop	P/MOVER
1077	Myrtleford - Workshop	DriveLine	Top and bottom Bell crank bearings n/s		REPLACED TOP AND BOTTOM BEARINGS AND ADJUSTED CLUTCH	11/03/2026	376100	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Myrtleford Workshop	P/MOVER
			VehService\B1 Svc B 1 Service, Jack up steer axle check bearings and king pins.												
1077	Albury - Workshop	VehService\B1 Svc	Reslace cabin filter.	VehService\B1 Svc	KLM AT TIME OF SERVICE 401613	11/03/2026	376100	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Myrtleford Workshop	P/MOVER
1077	Albury - Workshop	Tyres\RUN OUT	Tyres\RUN OUT POS 9-10			23/02/2026	375143	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	BORDER BANDAG PTY LTD - 4	P/MOVER
1077	Albury - Workshop	VehService\AS	VehService\AS A Service	VehService\AS		21/02/2026	375143	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Wodonga Workshop	P/MOVER
1077	Albury - Workshop	Engine\FAULT CODE	Driver Reported Truck Has Low Power.		Met driver at yard. oluased comouter into truck. checked for fault codes. found no active fault codes in system all faults in system were inactive and old faults. lowered bull bar a	12/02/2026	375143	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Wodonga Workshop	P/MOVER
1077	Albury - Workshop	Engine\FAULT CODE	Check Eng, light keep's coming ON.			09/02/2026	375143	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Albury Workshop	P/MOVER
1077	Albury - Workshop	Engine\FAULT CODE	After Treat light starting to come on. Oil leak @ compressor			09/02/2026	375143	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Albury Workshop	P/MOVER
1077	Albury - Workshop	Engine	Cab air filter lid missing			08/02/2026	377794	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Wodonga Workshop	P/MOVER
1077	Albury - Workshop	VehService\AS	VehService\AS A Service	VehService\AS		08/02/2026	377794	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Wodonga Workshop	P/MOVER
					tightened up loose bolts										
1077	Albury - Workshop	Engine	Oil leak @ compressor		SMc	08/02/2026	377794	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Wodonwa Workshop	P/MOVER
1077	Albury - Workshop	Body\MUDGUARDS	both front mud guards need rep[lacing			04/02/2026	375143	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Albury Workshop	P/MOVER
1077	Albury - Workshop	Tyres\TP06	Tyres\TP06		CALL OUT	03/02/2026	375143	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	BORDER BANDAG PTY LTD - 4	P/MOVER
1077	Albury - Workshop	Tyres\RUN OUT	Tyres\RUN OUT POS 11 - 12			31/01/2026	375143	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	BORDER BANDAG PTY LTD - 4	P/MOVER
1077	Albury - Workshop	Tyres\Punct	Tyres\Punct POS 5 + 8			31/01/2026	375143	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	BORDER BANDAG PTY LTD - 4	P/MOVER
1077	Albury - Workshop	VehService\B5	VehService\B5 B Service	VehService\B5		30/01/2026	365431	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Albury Workshop	P/MOVER
1077	Albury - Workshop	Engine\COMPRESSOR	Air drop's and driver's seat goes down constantly.		Tyre leaking, tyre fitter replaced	30/01/2026	365431	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Albury Workshop	P/MOVER
1077	Albury - Workshop	VehService\AS	VehService\AS A Service	VehService\AS		22/01/2026	365431	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Albury Workshop	P/MOVER
1077	Albury - Workshop	VehService\AS	VehService\AS A Service	VehService\AS		10/01/2026	350513	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Wodonga Workshop	P/MOVER
1077	Albury - Workshop	Tyres\TP7+8	Tyres\TP7+8			24/12/2025	350513	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	BORDER BANDAG PTY LTD - 4	P/MOVER
1077	Albury - Workshop	Tyres\TP1+2	Tyres\TP1+2			24/12/2025	350513	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	BORDER BANDAG PTY LTD - 4	P/MOVER
1077	Albury - Workshop	Tyres\TP5+6	Tyres\TP5+6			24/12/2025	350513	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	BORDER BANDAG PTY LTD - 4	P/MOVER
1077	Albury - Workshop	Steering\STEER UNI	Middle Steering uni has movement		INSPECTED. OK.	20/12/2025	350513	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Wodonga Workshop	P/MOVER
1077	Albury - Workshop	VehService\AS	VehService\AS A Service	VehService\AS		20/12/2025	350513	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Wodonga Workshop	P/MOVER
			VehService\B1 Svc B 1 Service, Jack up steer axle check bearings and king pins.												
1077	Albury - Workshop	VehService\B1 Svc	Reslace cabin filter. B Service	VehService\B1 Svc		20/12/2025	350513	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Wodonwa Workshop	P/MOVER
1077	Albury - Workshop	VehService\B5	Serviced @ 330,893 Kkms A Service	VehService\B5	Mitch Newlev 2.5 Hrs	25/11/2025	311190	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Wodonwa Workshop	P/MOVER
1077	Albury - Workshop	VehService\AS	Serviced @ 325.000 Kkms	VehService\AS		18/11/2025	325485	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Wodonwa Workshop	P/MOVER
1077	Albury - Workshop	CTI\CTI Drive	CTI TAKING A LONG TIME TO PUMP UP. A Service Serviced @ 320,232 Kkms.		Replaced PPV On Air Tank.	11/11/2025	311190	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Wodonga Workshop	P/MOVER
1077	Albury - Workshop	VehService\AS	VehService\AS A Service	VehService\AS		11/11/2025	311190	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Wodonwa Workshop	P/MOVER
1077	Albury - Workshop	DriveLine\GEARBOX	OIL LEAK RHS OF GEARBOX-WARRANTY. TCTC REPAIRING.		Oil Leak Repaired By TCTC.	11/11/2025	311190	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Wodonga Workshop	P/MOVER
					check all fan speeds & vibration all ok										
1077	Albury - Workshop	Air Con\AIR CON	TCTC-WARRANTY- REPAIR/ REPLACE VIBRATING HVAC FAN. *CAB FAN LOOSE & RATTLES.		checked 1/6/26 at 446903 kms	11/11/2025	441092	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Wodonga Workshop	P/MOVER
1077	Albury - Workshop	Air Con\AIR CON	WARRANTY REPAIR.		check all fan speeds & vibration all ok checked 1/6/26 at 446903 kms (WO) check all fan speeds & vibration all ok checked 1/6/26 at 446903 kms (WO)	11/11/2025	441092	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Wodonga Workshop	P/MOVER
1077	Albury - Workshop	DrCabRep\ELECT P&W	Fan in dash is still noisy most of the time.			11/11/2025	441092	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Wodonwa Workshop	P/MOVER
1077	Albury - Workshop	DriveLine\DAMAGE	Front diff power divider slipping		SPLIT IN SIDE WALL - IMPACT DAMAGE	11/11/2025	311190	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Albury Workshop	P/MOVER
1077	Albury - Workshop	Tyres\TP1+2	Tyres\TP1+2		SHAUN INSPECTED	09/11/2025	311190	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	BORDER BANDAG PTY LTD - 4	P/MOVER
1077	Albury - Workshop	Tyres\TP9+10	Tyres\TP9+10			09/11/2025	311190	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	BORDER BANDAG PTY LTD - 4	P/MOVER
1077	Albury - Workshop	Tyres\TP11+12	Tyres\TP11+12			09/11/2025	311190	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	BORDER BANDAG PTY LTD - 4	P/MOVER
			VehService\B1 Svc B 1 Service, Jack up steer axle check bearings and king pins.												
1077	Albury - Workshop	VehService\B1 Svc	Reslace cabin filter.	VehService\B1 Svc	S.McCABE	29/10/2025	311190	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Wodonwa Workshop	P/MOVER
1077	Albury - Workshop	Chassis\BULLBAR	WELDED NUT IN BULLBAR A Service			23/10/2025	311190	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Wodonga Workshop	P/MOVER
1077	Albury - Workshop	VehService\AS	Serviced @ 306,101 Kkms	VehService\AS		21/10/2025	311190	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Wodonga Workshop	P/MOVER
1077	Albury - Workshop	Chassis\AIR LEAK	Repair Air Leak At Air Dryer			21/10/2025	311190	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Wodonga Workshop	P/MOVER
1077	Albury - Workshop	DrCabRep\ELECT P&W	Remounting of tablet still has'nt been Done.			21/10/2025	311190	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Wodonga Workshop	P/MOVER
1077	Albury - Workshop	DrCabRep\DAMAGE	Rattles in bottom left of dash still hasn't been Done.			21/10/2025	311190	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Wodonga Workshop	P/MOVER
1077	Albury - Workshop	Elect\BATTERY	Batteries swollen			21/10/2025	311190	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Wodonga Workshop	P/MOVER
1077	Albury - Workshop	Steering	PULLING TO THE LEFT.			21/10/2025	311190	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Wodonga Workshop	P/MOVER
1077	Albury - Workshop	Engine\COMPRESSOR	TCTC-DIAGNOSED BROKEN COMPRESSOR SHAFT. REPLACED UNDER WARRANTY		PICKED UP FROM TCTC. HOOKED UP T505/506. REPLACED ABS PLUG	21/10/2025	210389	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Wodonga Workshop	P/MOVER
1077	Albury - Workshop	VehService\AS	VehService\AS A Service	VehService\AS		11/10/2025	210389	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Wodonga Workshop	P/MOVER
1077	Albury - Workshop	Steering\WHEEL ALGN	Steering pulling to the left.			11/10/2025	210389	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Wodonga Workshop	P/MOVER
1077	Albury - Workshop	Steering\WHEEL ALGN	Truck Pulling To The left Still			11/10/2025	210389	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Wodonga Workshop	P/MOVER
1077	Albury - Workshop	Steering\PWR STEER	Steering box endfloat requires adjustment			11/10/2025	210389	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Wodonga Workshop	P/MOVER
1077	Albury - Workshop	DriveLine\DIL LEAK	Front Diff Oil Leak			11/10/2025	210389	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Wodonga Workshop	P/MOVER
1077	Albury - Workshop	DriveLine\DIFF OIL	DriveLine\DIFF OIL Replace Diff oils	DriveLine\DIFF OIL	Diff Oils Changed When Warranty Diff Repairs Were Done By TCTC. WHILST CARRYING OUT WARRANTY REPAIRS, REPLACED DIFF OIL	07/10/2025	296023	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	TWIN CITY TRUCK CENTRE - 4 - OLD	P/MOVER
			DriveLine\DIFF OIL CHANGE		* Drain differential oil * Installed differential lubricant levels to specification										
1077	Albury - Workshop	DriveLine\DIFF OIL	T09728D		* Re torcue all fittings & fixtures Perform laser wheel alignment on T659 prime mover. Recent tie rod end replacement . Castor change to front axle as required	07/10/2025	296023	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	TWIN CITY TRUCK CENTRE - 4 - OLD	P/MOVER
1077	Albury - Workshop	Steering\WHEEL ALGN	Needs Front End Wheel Alignment			07/10/2025	210389	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	HUME TRUCK TECHNICSP/L-4	P/MOVER

			B Service														
1077	Albury - Workshop	VehService\BS	Serviced @ 296,011 Kms.	VehService\BS		26/09/2025	210389	Completed	Greenfreight Loxeine NSW	KWX15LOG	Albury	ATK	XW19NG	Wodonwa Workshop	P/MOVER
					the tyres were changed early on 1077 because they were wearing abnormally so they changed them out so they could be used as run outs on trailers										
1077	Albury - Workshop	Tyres\TP1+2	Tyres\TP1+2			19/09/2025	210389	Completed	Greenfreight Loxeine NSW	KWX15LOG	Albury	ATK	XW19NG	BORDER BANDAG PTY LTD - 4	P/MOVER
			A Service												
			Serviced @ 285,500 Kms												
1077	Albury - Workshop	VehService\AS	B Service Due @ 290,000 Kms	VehService\AS		15/09/2025	210389	Completed	Greenfreight Loxeine NSW	KWX15LOG	Albury	ATK	XW19NG	Wodonwa Workshop	P/MOVER
			CRUISE/ HIGH IDLE NOT WORKING.												
1077	Albury - Workshop	DrCabElect\CRUISE CON	ITCTC Warranty Reasel		TCTC Reolaced Cruise Control Hobbs Switch Under Warrantv	05/09/2025	210389	Completed	Greenfreight Loxeine NSW	KWX15LOG	Albury	ATK	XW19NG	Wodonwa Workshop	P/MOVER
			Brake Pedal Cruise Cut Not working												
1077	Albury - Workshop	DrCabElect\CRUISE CON	ITCTC Warrantv Reasel		TCTC Reolaced Cruise Control Hobbs Switch Under Warrantv	05/09/2025	210389	Completed	Greenfreight Loxeine NSW	KWX15LOG	Albury	ATK	XW19NG	Wodonwa Workshop	P/MOVER
			A Service.												
1077	Albury - Workshop	VehService\AS	Serviced @ 280,553 Kms	VehService\AS		05/09/2025	210389	Completed	Greenfreight Loxeine NSW	KWX15LOG	Albury	ATK	XW19NG	Wodonwa Workshop	P/MOVER
1077	Albury - Workshop	Chassis	Umbilical arm bearings need replacing			05/09/2025	210389	Completed	Greenfreight Loxeine NSW	KWX15LOG	Albury	ATK	XW19NG	Wodonwa Workshop	P/MOVER
1077	Albury - Workshop	VehService\AS	VehService\AS A Service	VehService\AS		28/08/2025	210389	Completed	Greenfreight Loxeine NSW	KWX15LOG	Albury	ATK	XW19NG	Wodonwa Workshop	P/MOVER
			VehService\B1 Svc B 1 Service,												
			Jack up steer axle check bearings and king pins.												
1077	Albury - Workshop	VehService\B1 Svc	Reolace cabin filter.	VehService\B1 Svc		28/08/2025	210389	Completed	Greenfreight Loxeine NSW	KWX15LOG	Albury	ATK	XW19NG	Wodonwa Workshop	P/MOVER
1077	Albury - Workshop	Workshop\MOVE ASSET	DROPPED OFF- PICKED UP FROM TCTC.			23/08/2025	210389	Completed	Greenfreight Logging NSW	KWX15LOG	Albury	ATK	XW19NG	Wodonwa Workshop	P/MOVER
1077	Albury - Workshop	VehService\AS	VehService\AS A Service	VehService\AS		19/08/2025	266964	Completed	Greenfreight Logging NSW	KWX15LOG	Albury	ATK	XW19NG	Wodonwa Workshop	P/MOVER
1077	Albury - Workshop	Body\AIR LEAK	Drivers Door Letting In A Shit Load Of Air From Top Corner			19/08/2025	266964	Completed	Greenfreight Logging NSW	KWX15LOG	Albury	ATK	XW19NG	Wodonwa Workshop	P/MOVER
1077	Albury - Workshop	Engine\OIL LEAK	Front of rocker cover gasket weeping			19/08/2025	266964	Completed	Greenfreight Logging NSW	KWX15LOG	Albury	ATK	XW19NG	Wodonwa Workshop	P/MOVER
1077	Albury - Workshop	Tyres\TP1+2	Tyres\TP1+2			11/08/2025	210389	Completed	Greenfreight Logging NSW	KWX15LOG	Albury	ATK	XW19NG	BORDER BANDAG PTY LTD - 4	P/MOVER
			A Service												
			Serviced 256670 Kms												
1077	Albury - Workshop	VehService\AS		VehService\AS		02/08/2025	210389	Completed	Greenfreight Logging NSW	KWX15LOG	Albury	ATK	XW19NG	Wodonwa Workshop	P/MOVER
1077	Albury - Workshop	VehService\BS	VehService\BS B Service	VehService\BS		26/07/2025	210389	Completed	Greenfreight Logging NSW	KWX15LOG	Albury	ATK	XW19NG	Wodonwa Workshop	P/MOVER
					Opened Fuse Box, Checked EBS Fuse's Were In Correct Positions Found Trailer ABS Power Fuse Blown, Closed Fuse Box, Checked EBS Leads Were Connected To Trailer's.										
					Truck Had Dead Short In EBS Circuit, Truck Sent To TCTC For Repair Under Warranty.										
1077	Albury - Workshop	Brakes\EBS FAULTS	ENSURE TRAILER ABS FUSES ARE FITTED AND WORKING		TCTC Found Rubbed Wire In Chassis. Reapired & Tested.	24/07/2025	210389	Completed	Greenfreight Logging NSW	KWX15LOG	Albury	ATK	XW19NG	Wodonwa Workshop	P/MOVER
1077	Albury - Workshop	Brakes\AIR TANKS	drain for air tank stuck open		Breakdown. drove to work. Guided truck onto pit. Inspected air leak. Found air dryer purge tank drain cock was stuck open. Seated drain cock to stop air leak. Drove back home	21/07/2025	210389	Completed	Greenfreight Logging NSW	KWX15LOG	Albury	ATK	XW19NG	Wodonwa Workshop	P/MOVER
1077	Albury - Workshop	Tyres\TP7+8	Tyres\TP7+8			17/07/2025	210389	Completed	Greenfreight Logging NSW	KWX15LOG	Albury	ATK	XW19NG	BORDER BANDAG PTY LTD - 4	P/MOVER
1077	Albury - Workshop	Tyres\TP5+6	Tyres\TP5+6			17/07/2025	210389	Completed	Greenfreight Logging NSW	KWX15LOG	Albury	ATK	XW19NG	BORDER BANDAG PTY LTD - 4	P/MOVER
1077	Albury - Workshop	Workshop\MOVE ASSET	Move truck up to tyre bay			16/07/2025	210389	Completed	Greenfreight Logging NSW	KWX15LOG	Albury	ATK	XW19NG	Albury Workshop	P/MOVER
					Replaced blown engine brake dash globe. Broke rear air gauge air line fitting. Replaced										
1077	Albury - Workshop	VehService\AS	VehService\AS A Service	VehService\AS	Tightened loose rocker cover breather hose	15/07/2025	210389	Completed	Greenfreight Loxeine NSW	KWX15LOG	Albury	ATK	XW19NG	Wodonwa Workshop	P/MOVER
			VehService\TRANS OIL Replace Synthetic Transmision oil												
1077	Albury - Workshop	VehService\TRANS OIL	ITCTC P/O: T0947331	VehService\TRANS OIL		02/07/2025	210389	Completed	Greenfreight Loxeine NSW	KWX15LOG	Albury	ATK	XW19NG	PACCAR PARTS FLEET SERVICES - 4	P/MOVER
1077	Albury - Workshop	Insp\ANN INSP	Insp\ANN INSP	Insp\ANN INSP		02/07/2025	210389	Completed	Greenfreight Logging NSW	KWX15LOG	Albury	ATK	XW19NG	PACCAR PARTS FLEET SERVICES - 4	P/MOVER
1077	Albury - Workshop	VehService\CS	VehService\CS (PO #T094731)	VehService\CS	Fluid analysis completed due to vibration issues in diff.	02/07/2025	210389	Completed	Greenfreight Logging NSW	KWX15LOG	Albury	ATK	XW19NG	PACCAR PARTS FLEET SERVICES - 4	P/MOVER
			DriveLine\DIFF OIL Replace Diff oils												
1077	Albury - Workshop	DriveLine\DIFF OIL	ITCTC P/O: T0947331	DriveLine\DIFF OIL		02/07/2025	210389	Completed	Greenfreight Loxeine NSW	KWX15LOG	Albury	ATK	XW19NG	PACCAR PARTS FLEET SERVICES - 4	P/MOVER
1077	Albury - Workshop	Tyres\TP1+2	Tyres\TP1+2			02/07/2025	208270	Completed	Greenfreight Logging NSW	KWX15LOG	Albury	ATK	XW19NG	BORDER BANDAG PTY LTD - 4	P/MOVER
			VehService\B1 Svc B 1 Service,												
			Jack up steer axle check bearings and king pins.												
1077	Albury - Workshop	VehService\B1 Svc	Reolace cabin filter.	VehService\B1 Svc		01/07/2025	208270	Completed	Greenfreight Loxeine NSW	KWX15LOG	Albury	ATK	XW19NG	Wodonwa Workshop	P/MOVER
1077	Albury - Workshop	VehService\AS	VehService\AS A Service	VehService\AS		24/06/2025	208270	Completed	Greenfreight Logging NSW	KWX15LOG	Albury	ATK	XW19NG	Wodonwa Workshop	P/MOVER
1077	Albury - Workshop	Workshop\MOVE ASSET	Pickup from TCTC			23/06/2025	208270	Completed	Greenfreight Logging NSW	KWX15LOG	Albury	ATK	XW19NG	Wodonwa Workshop	P/MOVER
1077	Albury - Workshop	Workshop\MOVE ASSET	Drop off to TCTC			21/06/2025	208270	Completed	Greenfreight Logging NSW	KWX15LOG	Albury	ATK	XW19NG	Wodonwa Workshop	P/MOVER
			Brakes\BRK RELINE												
1077	Albury - Workshop	Brakes\BRK RELINE	(Reline Done By TCTC Under Warranty @ 148,000 Kms)			20/06/2025	210389	Completed	Greenfreight Loxeine NSW	KWX15LOG	Albury	ATK	XW19NG	Wodonwa Workshop	P/MOVER
1077	Albury - Workshop	Chassis\FIFTH WHEE	Connect Truck Up To Trailers T180/181			20/06/2025	208270	Completed	Greenfreight Logging NSW	KWX15LOG	Albury	ATK	XW19NG	Wodonwa Workshop	P/MOVER
			Brake Reline Rear Drive Axle.												
			TCTC Doing Brake Reline Under Warranty @ 208,000 Kms)												
1077	Albury - Workshop	Brakes\BRK RELINE			Drive Brake Reline Done By TCTC	20/06/2025	208270	Completed	Greenfreight Loxeine NSW	KWX15LOG	Albury	ATK	XW19NG	TWIN CITY TRUCK CENTRE - OLD	P/MOVER
1077	Albury - Workshop	Tyres\TP9+10	Tyres\TP9+10		Previously changed in March 25, quality of Tyres were poor and needed to be changed again.	19/06/2025	208270	Completed	Greenfreight Logging NSW	KWX15LOG	Albury	ATK	XW19NG	BORDER BANDAG PTY LTD - 4	P/MOVER
1077	Albury - Workshop	Tyres\TP11+12	Tyres\TP11+12			19/06/2025	208270	Completed	Greenfreight Logging NSW	KWX15LOG	Albury	ATK	XW19NG	BORDER BANDAG PTY LTD - 4	P/MOVER
					inspected steering check king pins / drag link ends / steering box and mound bolts found problem possible to be RH tie rod end seized up										
					T.C.T.C traveled to m/ford w/shop to replace due to been warranty										
1077	Albury - Workshop	Steering\TIE ROD	steering locking up from rh down back to left		(KLM at time of reasir 208270)	04/06/2025	208270	Completed	Greenfreight Logging NSW	KWX15LOG	Albury	ATK	XW19NG	Myrtleford Workshop	P/MOVER
1077	Albury - Workshop	Tyres	Tyres NO PO PROVIDED			29/05/2025	189488	Completed	Greenfreight Logging NSW	KWX15LOG	Albury	ATK	XW19NG	BEAUREPAIRES - 4	P/MOVER
1077	Albury - Workshop	DrCabRep\HOUSEKEEP	*CUP HOLDER TO BE PUT BACK ON PROPERLY.		OK.	27/05/2025	189488	Completed	Greenfreight Logging NSW	KWX15LOG	Albury	ATK	XW19NG	Albury Workshop	P/MOVER
1077	Albury - Workshop	Engine\MOUNTS	rear engine mounts bolts loose - tightened (mounts)		INSPECTED. OK.	27/05/2025	189488	Completed	Greenfreight Logging NSW	KWX15LOG	Albury	ATK	XW19NG	Albury Workshop	P/MOVER
1077	Albury - Workshop	DriveLine\OIL LEAK	front diff leaking - possible pump fitting		INSPECTED. OK.	27/05/2025	189488	Completed	Greenfreight Logging NSW	KWX15LOG	Albury	ATK	XW19NG	Albury Workshop	P/MOVER
1077	Albury - Workshop	Engine\FAULT CODE	sensor in bullbar coming up with fault			27/05/2025	189488	Completed	Greenfreight Logging NSW	KWX15LOG	Albury	ATK	XW19NG	Albury Workshop	P/MOVER
1077	Albury - Workshop	Engine\ENG FAN	Horton fan starting to wear (monitor)		CHECKED. OK.	27/05/2025	189488	Completed	Greenfreight Logging NSW	KWX15LOG	Albury	ATK	XW19NG	Albury Workshop	P/MOVER
1077	Albury - Workshop	DriveLine\PTO	PTO leaking		INSPECTED. OK.	27/05/2025	189488	Completed	Greenfreight Logging NSW	KWX15LOG	Albury	ATK	XW19NG	Albury Workshop	P/MOVER
1077	Albury - Workshop	VehService\AS	VehService\AS A Service	VehService\AS	I	27/05/2025	189488	Completed	Greenfreight Logging NSW	KWX15LOG	Albury	ATK	XW19NG	Albury Workshop	P/MOVER
1077	Albury - Workshop	Susp\SUSPENSION	Lower bellcrank bearing worn		INSPECTED. OK.	27/05/2025	189488	Completed	Greenfreight Logging NSW	KWX15LOG	Albury	ATK	XW19NG	Albury Workshop	P/MOVER
1077	Albury - Workshop	DriveLine\UNI JOINTS	steering unis starting to have play (monitor)		INSPECTED. OK.	27/05/2025	189488	Completed	Greenfreight Logging NSW	KWX15LOG	Albury	ATK	XW19NG	Albury Workshop	P/MOVER
1077	Albury - Workshop	DrCabElect\RADIO	-TOP UHF RADIO NOT WORKING. POSSIBLE HAND PIECE.		TESTED. OK.	27/05/2025	189488	Completed	Greenfreight Logging NSW	KWX15LOG	Albury	ATK	XW19NG	Albury Workshop	P/MOVER
1077	Albury - Workshop	Susp\SUSPENSION	-FELT MOVEMENT WHEN TAKING OFF IN FRONT LEFT SIDE OF PRIME MOVER. FELT LIKE POSSIBLY U-BOLTS? LOOSE.		CHECKED. NOTHING LOOSE. OK.	27/05/2025	189488	Completed	Greenfreight Logging NSW	KWX15LOG	Albury	ATK	XW19NG	Albury Workshop	P/MOVER
1077	Albury - Workshop	DrCabElect\RADIO	replace extension cable between uhf and hand piece - top set - right hand piece			27/05/2025	189488	Completed	Greenfreight Logging NSW	KWX15LOG	Albury	ATK	XW19NG	Albury Workshop	P/MOVER
1077	Albury - Workshop	DriveLine\DRV LN SER	*VIBRATION IN DRIVE LINE GETTING WORSE.		INSPECTED. NO FAULT FOUND.	27/05/2025	189488	Completed	Greenfreight Logging NSW	KWX15LOG	Albury	ATK	XW19NG	Albury Workshop	P/MOVER
1077	Albury - Workshop	DriveLine\GEARBOX	*GOT A CLUNK IN EITHER GEARBOX? OR DIFF UNDER LOAD. GETTING WORSE.		INSPECTED. OK.	27/05/2025	189488	Completed	Greenfreight Logging NSW	KWX15LOG	Albury	ATK	XW19NG	Albury Workshop	P/MOVER
1077	Albury - Workshop	DrCabRep\HOUSEKEEP	*DASH ALL LOOSE.		INSPECTED. OK.	27/05/2025	189488	Completed	Greenfreight Logging NSW	KWX15LOG	Albury	ATK	XW19NG	Albury Workshop	P/MOVER
1077	Albury - Workshop	Tyres\TP1+2	Tyres\TP1+2			21/05/2025	189488	Completed	Greenfreight Logging NSW	KWX15LOG	Albury	ATK	XW19NG	BEAUREPAIRES - 4	P/MOVER
1077	Albury - Workshop	Air Con\AIR CON	CHECKED FAN. CHECKED DFUSES. CLEANED FAN. STILL VIBRATING. WARRANTY REPAIR AT TCTC REQUIRED.			16/05/2025	189488	Completed	Greenfreight Logging NSW	KWX15LOG	Albury	ATK	XW19NG	Albury Workshop	P/MOVER
1077	Albury - Workshop	VehService\AS	VehService\AS A Service	VehService\AS		13/05/2025	189488	Completed	Greenfreight Logging NSW	KWX15LOG	Albury	ATK	XW19NG	PACCAR PARTS FLEET SERVICES - 4	P/MOVER
			VehService\B1 Svc B 1 Service,												
			Jack up steer axle check bearings and king pins.												
1077	Albury - Workshop	VehService\B1 Svc	Reolase cabin filter.	VehService\B1 Svc	Booked TCTC 10/5 PO created #T094069	13/05/2025	189488	Completed	Greenfreight Loxeine NSW	KWX15LOG	Albury	ATK	XW19NG	PACCAR PARTS FLEET SERVICES - 4	P/MOVER
1077	Albury - Workshop	DrCabRep\SEAT	seat dropping air smashing back base off seat is hard an flat		Monitor	03/05/2025	171713	Completed	Greenfreight Logging NSW	KWX15LOG	Albury	ATK	XW19NG	Wodonwa Workshop	P/MOVER
1077	Albury - Workshop	VehService\AS	VehService\AS A Service	VehService\AS		03/05/2025	171713	Completed	Greenfreight Logging NSW	KWX15LOG	Albury	ATK	XW19NG	Wodonwa Workshop	P/MOVER
1077	Albury - Workshop	Hydraulics\OIL/FILTER	TOPPED UP HYDRAULIC OIL. 15L.			01/05/2025	171713	Completed	Greenfreight Logging NSW	KWX15LOG	Albury	ATK	XW19NG	Albury Workshop	P/MOVER
1077	Albury - Workshop	Elect\ELECT P&W	PICKED UP COMBINATION FROM TCTC. CLEARANCE LIGHTS PLAYING UP. REPAIRED AT DEPOT. PARKED IN LOG YARD.		K.RYAN 'S HOUR LABOUR.	16/04/2025	171713	Completed	Greenfreight Logging NSW	KWX15LOG	Albury	ATK	XW19NG	Albury Workshop	P/MOVER
1077	Albury - Workshop	VehService\AS	VehService\AS A Service	VehService\AS		14/04/2025	1714604	Completed	Greenfreight Logging NSW	KWX15LOG	Albury	ATK	XW19NG	PACCAR PARTS FLEET SERVICES - 4	P/MOVER
1077	Albury - Workshop	VehService\AS	VehService\AS A Service	VehService\AS		08/04/2025	168577	Completed	Greenfreight Logging NSW	KWX15LOG	Albury	ATK	XW19NG	Albury Workshop	P/MOVER
1077	Albury - Workshop	VehService\AS	VehService\AS A Service	VehService\AS		28/03/2025	163000	Completed	Greenfreight Logging NSW	KWX15LOG	Albury	ATK	XW19NG	Wodonwa Workshop	P/MOVER
			GPS tracking stopped working 3 days ago												
			*Not tracking												
			Unit ref: 701000427. Checked and confirmed fault.												
			Checked power ignition and ground on the unit.												
			Only the light for power on but got ignition and got satellite on the tablet.												
			Disconnected unit and let it drain for one hour, came back but unit still												
			got battery. Tried reset with companion app, nothing happened. Called												
			MT Data and conduct a series of test and hard reset, finally got the unit												
			back online. Tested with mtdata technician.												
1077	Albury - Workshop	DrCabElect\GPS				26/03/2025	151899	Completed	Greenfreight Logging NSW	KWX15LOG	Albury	ATK	XW19NG	ARMON AUTO ELECTRICAL - 4	P/MOVER
1077	Albury - Workshop	Tyres\TP9+10	Tyres\TP9+10			24/03/2025	151899	Completed	Greenfreight Logging NSW	KWX15LOG	Albury	ATK	XW19NG	BEAUREPAIRES - 4	P/MOVER
1077	Albury - Workshop	Tyres\TP7+8	Tyres\TP7+8			24/03/2025	151899	Completed	Greenfreight Logging NSW	KWX15LOG	Albury	ATK	XW19NG	BEAUREPAIRES - 4	P/MOVER
1077	Albury - Workshop	VehService\AS	KWX15LOGMG PM Kenworth Cummins Log MG	VehService\AS		20/03/2025	160046	Completed	Greenfreight Logging NSW	KWX15LOG	Albury	ATK	XW19NG	Wodonwa Workshop	P/MOVER
1077	Albury - Workshop	Elect\ELECT P&W	FOUND BURNT WIRING- SHORT IN EBS HARNESS. REPLACED EBS PLUG. INSPECT WIRING FOR DAMAGE.			20/03/2025	151899	Completed	Greenfreight Logging NSW	KWX15LOG	Albury	ATK	XW19NG	Albury Workshop	P/MOVER
1077	Albury - Workshop	Tyres\IMPACT	L/H/S front drive tyre Staked Repair/replace.		Previously completed	13/03/2025	311190	Completed	Greenfreight Logging NSW	KWX15LOG	Albury	ATK	XW19NG	Wodonwa Workshop	P/MOVER
1077	Albury - Workshop	Tyres\CLEARSKIN	Need's steer tyres.		Previously completed	13/03/2025	311190	Completed	Greenfreight Logging NSW	KWX15LOG	Albury	ATK	XW19NG	Wodonwa Workshop	P/MOVER
1077	Albury - Workshop	DrCabElect\RADIO	Replace RH/Top UHF Extension for Microphone-Plug Faulty at back of UHF.		Wasn't on the job	13/03/2025	311190	Completed	Greenfreight Logging NSW	KWX15LOG	Albury	ATK	XW19NG	Wodonwa Workshop	P/MOVER
1077	Albury - Workshop	VehService\AS	KWX15LOGMG PM Kenworth Cummins Log MG	VehService\AS		13/03/2025	311190	Completed	Greenfreight Logging NSW	KWX15LOG	Albury	ATK	XW19NG	Wodonwa Workshop	P/MOVER
1077	Albury - Workshop	Brakes\EBS FAULTS	Truck abs light on		Replaced blown fuses	13/03/2025	311190	Completed	Greenfreight Logging NSW	KWX15LOG	Albury	ATK	XW19NG	Wodonwa Workshop	P/MOVER
1077	Albury - Workshop	Brakes\EBS FAULTS	Trailer abs light on			13/03/2025	311190	Completed	Greenfreight Logging NSW	KWX15LOG	Albury	ATK	XW19NG	Wodonwa Workshop	P/MOVER
1077	Albury - Workshop	Elect\DRV LIGHT	RHS Driving Light Has A Short/Loose Wire		Previously completed	13/03/2025	311190	Completed	Greenfreight Logging NSW	KWX15LOG	Albury	ATK	XW19NG	Wodonwa Workshop	P/MOVER
1077	Albury - Workshop	Body\WIPERS	RHS Windscreen Washer Not Working			13/03/2025	311190	Completed	Greenfreight Logging NSW	KWX15LOG	Albury	ATK	XW19NG	Wodonwa Workshop	P/MOVER
1077	Albury - Workshop	Chassis\AIR LEAK	Chassis\AIR LEAK		Wasn't on the job	13/03/2025	311190	Completed	Greenfreight Logging NSW	KWX15LOG	Albury	ATK	XW19NG	Wodonwa Workshop	P/MOVER
1077	Albury - Workshop	Brakes\AIR LEAK	truck not holding air		Repaired airdryer	04/03/2025	141432	Completed	Greenfreight Logging NSW	KWX15LOG	Albury	ATK	XW19NG	PACCAR PARTS FLEET SERVICES - 4	P/MOVER
			KWX15LOGMG PM Kenworth Cummins Log MG												
1077	Albury - Workshop	VehService\AS	booked IN AT tctc 24/2	VehService\AS		04/03/2025	146732	Completed	Greenfreight Loxeine NSW	KWX15LOG	Albury	ATK	XW19NG	PACCAR PARTS FLEET SERVICES - 4	P/MOVER
1077	Albury - Workshop	Chassis\BULLBAR	CALL OUT TO 1077 FOR AIR LEAK. FOUND BLOWN AIR DRYER GASKET. ATTEMPTED TO REPAIR. SPOKE WITH MANAGER. TWIN CITY TRUCK CENTRE ATTENDING TO REPAIR. BROUGHT DRIVER B			04/03/2025	311190	Completed	Greenfreight Logging NSW	KWX15LOG	Albury	ATK	XW19NG	Albury Workshop	P/MOVER
1077	Albury - Workshop	VehService\BS	VehService\BS	VehService\BS		03/03/2025	150000	Completed	Greenfreight Logging NSW	KWX15LOG	Albury	ATK	XW19NG	Wodonwa Workshop	P/MOVER
1077	Albury - Workshop	Body\MUDGUARDS	R/H DRV outrigger Loose.		Previously completed	03/03/2025	145432	Completed	Greenfreight Logging NSW	KWX15LOG	Albury	ATK	XW19NG	Wodonwa Workshop	P/MOVER
1077	Albury - Workshop	Body\MUDGUARDS	R/H/F outrigger loose		Previously completed	03/03/2025	145432	Completed	Greenfreight Logging NSW	KWX15LOG	Albury	ATK	XW19NG	Wodonwa Workshop	P/MOVER
1077	Albury - Workshop	Body\MUDGUARDS	Tighten R/H/S front guard outrigger.		Previously completed	03/03/2025	145432	Completed	Greenfreight Logging NSW	KWX15LOG	Albury	ATK	XW19NG	Wodonwa Workshop	P/MOVER
1077	Albury - Workshop	DrCabRep\SEAT	Seat Still Dropping Down		Seat drops due to truck losing air. Seat itself is fine	03/03/2025	145432	Completed	Greenfreight Logging NSW	KWX15LOG	Albury	ATK	XW19NG	Wodonwa Workshop	P/MOVER
1077	Albury - Workshop	Body\MUDGUARDS	R/H Drive Mudguard Outrigger loose, (tyre is damaging clamp's)		Previously completed	03/03/2025	145432	Completed	Greenfreight Logging NSW	KWX15LOG	Albury	ATK	XW19NG	Wodonwa Workshop	P/MOVER
1077	Albury - Workshop	Body\MUDGUARDS	R/H Front Guard Outrigger Loose.		Previously completed	03/03/2025	145432	Completed	Greenfreight Logging NSW	KWX15LOG	Albury	ATK	XW19NG	Wodonwa Workshop	P/MOVER
1077	Albury - Workshop	Brakes\BRAKE ADJ	Check/Adjust Brakes (Excessive pedal pressure Needed to STOP Normally)			03/03/2025	145432	Completed	Greenfreight Logging NSW	KWX15LOG	Albury	ATK	XW19NG	Wodonwa Workshop	P/MOVER
					Air leaking from gaskey blowout between bottom and top bowles										
1077	Albury - Workshop	Susp\AIR LEAK	Air Leak, near tank's.		Sent to work not reasired ill ex to tctc for warranty reasir	19/02/2025	106833	Completed	Greenfreight Logging NSW	KWX15LOG	Albury	ATK	XW19NG	Wodonwa Workshop	P/MOVER
1077	Albury - Workshop	Tyres\TP3+4	Tyres\TP3+4			18/02/2025	106833	Completed	Greenfreight Logging NSW	KWX15LOG	Albury	ATK	XW19NG	BEAUREPAIRES - 4	P/MOVER
1077	Albury - Workshop	Tyres\TP5+6	Tyres\TP5+6			18/02/2025	106833	Completed	Greenfreight Logging NSW	KWX15LOG	Albury	ATK	XW19NG	BEAUREPAIRES - 4	P/MOVER
1077	Albury - Workshop	Tyres\STEER TYRE	Tyres\STEER TYRE 1-2			18/02/2025	106833	Completed	Greenfreight Logging NSW	KWX15LOG	Albury	ATK	XW19NG	BEAUREPAIRES - 4	P/MOVER
1077	Wodonga - Workshop	VehService\AS	VehService\AS	VehService\AS		15/02/2025	106833	Completed	Greenfreight Logging NSW	KWX15LOG	Albury	ATK	XW19NG	Wodonwa Workshop	P/MOVER
1077	Wodonga - Workshop	Brakes\BRAKE ADJ	Drv Brake Adjustment,(Rolling On Hill !)		All drive brakes have been adjusted	15/02/2025	106833	Completed	Greenfreight Logging NSW	KWX15LOG	Albury	ATK	XW19NG	Wodonwa Workshop	P/MOVER
1077	Wodonga - Workshop	Engine\CATUNDUP	B-Service way over Due.		No check items list	31/01/2025	106833	Completed	Greenfreight Logging NSW	KWX15LOG	Albury	ATK	XW19NG	Wodonwa Workshop	P/MOVER
1077	Wodonga - Workshop	DrCabRep\AIR LEAK	Still not holding air in tank, seat dropping.		Cheryah tested the seat and it did not drop air over a period of 1 hour	31/01/2025	106833	Completed	Greenfreight Logging NSW	KWX15LOG	Albury	ATK	XW19NG	Wodonwa Workshop	P/MOVER
1077	Wodonga - Workshop	VehService\BS	VehService\BS	VehService\BS	1315886s	31/01/2025	106833	Completed	Greenfreight Logging NSW	KWX15LOG	Albury	ATK	XW19NG	Wodonwa Workshop	P/MOVER
1077	Wodonga - Workshop	DriveLine\WHEEL SEAL	Right/Hand Steer Leaking Hub Seal.		Duplicate job	22/01/2025	106833	Completed	Greenfreight Logging NSW	KWX15LOG	Albury	ATK	XW19NG	Wodonwa Workshop	P/MOVER
					The right hand steer wheel shows no indication of a damaged hub seal.										
1077	Wodonga - Workshop	Steering\WHEEL SEAL	R/H Steer Leaking Hub Seal		The brakes as seen through the insoection hole are drv at too and bottom	22/01/2025	106833	Completed	Greenfreight Logging NSW	KWX15LOG	Albury	ATK	XW19NG	Wodonwa Workshop	P/MOVER
1077	Wodonga - Workshop	Engine\ADBLUE	miss fire after treat light		CHECK INSPECTED NO ACTIVE FAULT CODE DRIVER TO MONITOR	22/01/2025	106833	Completed	Greenfreight Logging NSW	KWX15LOG	Albury	ATK	XW19NG	Wodonwa Workshop	P/MOVER
1077	Wodonga - Workshop	Engine\ALT2 DR	alternator Diods		Previously completed	22/01/2025	106833	Completed	Greenfreight Logging NSW	KWX15LOG	Albury	ATK	XW19NG	Wodonwa Workshop	P/MOVER
1077	Wodonga - Workshop	DrCabElect\RADIO	2 Way Right Side Fix ASAP Can Not Hear People Talking To Quiet Also No Range Dangrous !		Duplicate job	22/01/2025	106833	Completed	Greenfreight Logging NSW	KWX15LOG	Albury	ATK	XW19NG	Wodonwa Workshop	P/MOVER
1077	Wodonga - Workshop	VSenLab	SERVICE		Duplicate job	22/01/2025	106833	Completed	Greenfreight Logging NSW	KWX15LOG	Albury	ATK	XW19NG	Wodonwa Workshop	P/MOVER
1077	Wodonga - Workshop	Elect\ELECT P&W	Scales Need Calibrating			22/01/2025	106833	Completed	Greenfreight Logging NSW	KWX15LOG	Albury	ATK	XW19NG	Wodonwa Workshop	P/MOVER
1077	Wodonga - Workshop	Body\FIFTH WHEE	Table Holder Not Tight.		Duplicate job	22/01/2025	106833	Completed	Greenfreight Logging NSW	KWX15LOG	Albury	ATK	XW19NG	Wodonwa Workshop	P/MOVER
1077	Wodonga - Workshop	DrCabElect\SEAT	air leak causing driver's seat to drop constantly - seems to be rear air gauge dropping		Duplicate job	22/01/2025	106833	Completed	Greenfreight Logging NSW	KWX15LOG	Albury	ATK	XW19NG	Wodonwa Workshop	P/MOVER
1077	Wodonga - Workshop	DrCabElect\UNIT/GAUGE	Main trans temp guage light Out.		Previously comBleted	22/01/2025	106833	Completed	Greenfreight Logging NSW	KWX15LOG	Albury	ATK	XW19NG	Wodonwa Workshop	P/MOVER
1077	Wodonga - Workshop	Body\ELECT P&W	Trailer ABS Lights Flashing.		This is due to a trailer fault nOt a truck fault	22/01/2025	106833	Completed	Greenfreight Logging NSW	KWX15LOG	Albury	ATK	XW19NG	Wodonwa Workshop	P/MOVER
1077	Wodonga - Workshop	DriveLine\CLUTCH	CLUTCH NEXT TO NO FREE PLAY ON PEDAL.		/free play adjusted	22/01/2025	106833	Completed	Greenfreight Logging NSW	KWX15LOG	Albury	ATK	XW19NG	Wodonwa Workshop	P/MOVER
1077	Wodonga - Workshop	DrCabElect\RADIO	UHF RIGHT NO BUTTONS HAND PEICE REPLACE.		Duplicate job	22/01/2025	106833	Completed	Greenfreight Logging NSW	KWX15LOG	Albury	ATK	XW19NG	Wodonwa Workshop	P/MOVER
1077	Wodonga - Workshop	DrCabElect\RADIO	HAND PIECE 2 WAY NEEDS BUTTONS ON IT.			22/01/2025	106833	Completed	Greenfreight Logging NSW	KWX15LOG	Albury	ATK	XW19NG	Wodonwa Worksh

1077	Wodonga - Workshop	DrCabElect\RADIO	2 ways not working right		Duplicate job	22/01/2025	106833	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Wodonga Workshop	P/MOVER
1077	Wodonga - Workshop	DrCabElect\RADIO	Button R/H UHF handpiece have stopped working again			22/01/2025	106833	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Wodonga Workshop	P/MOVER
1077	Wodonga - Workshop	DrCabElect\RADIO	2 Way Hand Peace Buttons Not Working Again			22/01/2025	106833	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Wodonga Workshop	P/MOVER
1077	Wodonga - Workshop	Chassis\AIR LEAK	LOSING AIR PRESSURE		Repaired an air leak at an air tank fitting	22/01/2025	106833	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Wodonga Workshop	P/MOVER
1077	Wodonga - Workshop	Engine\ADBLUE	AFTER TREAT LIGHT.		Previously comElleted	22/01/2025	106833	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Wodonga Workshop	P/MOVER
1077	Wodonga - Workshop	VehService\AS	VehService\AS	VehService\AS		22/01/2025	106833	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Wodonga Workshop	P/MOVER
					Previously comElleted										
1077	Wodonga - Workshop	DrCabRep\SEAT	Drivers Seat Has No Lumber Support Working My Back Is Jacked From It Needs To Be Fixed ASAP Please		Lumbers suscort is workine	22/01/2025	106833	Comsleted	Greenfreight Loweine NSW	KW315LOG	Albury	ATK	XW19NG	Wodonaw Workshop	P/MOVER
1077	Wodonga - Workshop	DrCabRep\SEAT	SEAT/ AIR DROPPING.		Previously completed	22/01/2025	106833	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Wodonga Workshop	P/MOVER
1077	Wodonga - Workshop	DrCabRep\ELECT P&W	Loose Tablet Holder.		Tablet holder itself is tight and correctly adjusted	22/01/2025	106833	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Wodonga Workshop	P/MOVER
1077	Wodonga - Workshop	Engine\ANR BRAKE	ENGINE BRAKE LAG IS TOO LONG- 6KM/H OVER CRUISE SPEED.		Warranty item	22/01/2025	106833	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Wodonga Workshop	P/MOVER
1077	Wodonga - Workshop	DrivLine\GEARBOX	Clutch Adjustment very hard to select reverse.		Checked clutch adjustment, adjusted clutch free travel, checked & tested all good sent truck back to work.	21/01/2025	106833	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Wodonga Workshop	P/MOVER
1077	Wodonga - Workshop	DrCabRep\HOUSEKEEP	New R&R book please		New book given to logging for 1077 by Kristen	17/01/2025	106833	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Wodonga Workshop	P/MOVER
1077	Wodonga - Workshop	DrCabElect\AP	I PAD IS LOOSE. FALLING OFF BRACKET.			13/12/2024	106833	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Wodonga Workshop	P/MOVER
1077	Wodonga - Workshop	DrCabElect\ELECT P&W	Engine Oil Temp Light Globe BLOWN.			13/12/2024	106833	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Wodonga Workshop	P/MOVER
1077	Wodonga - Workshop	DrivLine\CONSUMABLE	missing drivers hub cap			13/12/2024	106833	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Wodonga Workshop	P/MOVER
1077	Wodonga - Workshop	DrCabElect\ELECT P&W	Engine Oil Temp Light Out.		Duplicate job	13/12/2024	106833	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Wodonga Workshop	P/MOVER
1077	Wodonga - Workshop	Hydraulics\OIL LEAK	Low Hydraulic Oil.		Tank has been filled	13/12/2024	106833	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Wodonga Workshop	P/MOVER
1077	Wodonga - Workshop	VehService\AS	VehService\AS	VehService\AS		13/12/2024	106833	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Wodonga Workshop	P/MOVER
1077	Wodonga - Workshop	Susp\AIR LEAK	Check Hot Pipe, Loosing Air at Idle with no Audible Leak - will Not Maintain Pressure			11/12/2024	106833	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Wodonga Workshop	P/MOVER
1077	Myrtleford - Workshop	Body\AIR LEAK	truck loosing air (air leak)		replaced governor valve adjusted to correct pressure inspected for leaks and unable to find leaks any at fault (KLM at time of repair 106833)	05/12/2024	106833	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Myrtleford Workshop	P/MOVER
1077	Wodonga - Workshop	Brakes\BRAKE ADJ	Adjust Brakes (Rolling With Black Button IN)			03/12/2024	96948	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Wodonga Workshop	P/MOVER
1077	Wodonga - Workshop	VehService\AS	Service Due			03/12/2024	96948	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Wodonga Workshop	P/MOVER
1077	Wodonga - Workshop	VehService\AS	VehService\AS	VehService\AS	t	03/12/2024	96948	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Wodonga Workshop	P/MOVER
1077	Wodonga - Workshop	VehService\AS	VehService\AS	VehService\AS		24/11/2024	96948	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Wodonga Workshop	P/MOVER
1077	Wodonga - Workshop	Chassis\HOUSEKEEP	BAD KNOCK IN REAR END- FIRE EXTINGUISHER BEHIND CAB LOOSE.			14/11/2024	73846	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Wodonga Workshop	P/MOVER
1077	Wodonga - Workshop	Brakes\BRAKE ADJ	BRAKES NEED ADJUSTING.			14/11/2024	73846	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Wodonga Workshop	P/MOVER
1077	Wodonga - Workshop	VServLab	SERVICE.		Duplicate wintry	14/11/2024	73846	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Wodonga Workshop	P/MOVER
1077	Wodonga - Workshop	Prevent\CONSUMABLE	Fill Up Washer Bottle.		Done by keith	14/11/2024	73846	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Wodonga Workshop	P/MOVER
1077	Wodonga - Workshop	Brakes\AIR LEAK	Air Leak Drivers Side Area maybe Booster?		Keith looked for this has been previously completed	14/11/2024	73846	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Wodonga Workshop	P/MOVER
			NEED x8 DRIVE TYRES.												
1077	Wodonga - Workshop	Tyres\FITMENT	NEED x2 STEER TYRES.		Previously comElleted	14/11/2024	73846	Comsleted	Greenfreight Loweine NSW	KW315LOG	Albury	ATK	XW19NG	Wodonaw Workshop	P/MOVER
					This is not a b wc list many items are missing										
1077	Wodonga - Workshop	VehService\BS	VehService\BS	VehService\BS	The b wc has been comsleted to the full extent	14/11/2024	73846	Comsleted	Greenfreight Loweine NSW	KW315LOG	Albury	ATK	XW19NG	Wodonaw Workshop	P/MOVER
1077	Wodonga - Workshop	DrCabElect\INST/GAUGE	ENGINE OIL TEMP LIGHT OUT.		Duplicate entry	14/11/2024	73846	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Wodonga Workshop	P/MOVER
1077	Wodonga - Workshop	Cooling\COOL LEAKS	CHECK FOR COOLANT LEAK.		No leak apparent when checked	14/11/2024	73846	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Wodonga Workshop	P/MOVER
1077	Wodonga - Workshop	DrCabRep\SEAT	AIR LEAK IN SEAT.		Previously completed	14/11/2024	73846	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Wodonga Workshop	P/MOVER
1077	Wodonga - Workshop	DrCabElect\INST/GAUGE	Engine oil temp light out.		Duplicate entry	14/11/2024	73846	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Wodonga Workshop	P/MOVER
					No leak found										
1077	Wodonga - Workshop	Cooling\COOL LEAKS	Repair Coolant leak		Tightened all clamps and water ourno bolts and thermostat housine	11/11/2024	73846	Completed	Greenfreight Loweine NSW	KW315LOG	Albury	ATK	XW19NG	Wodonga Workshop	P/MOVER
1077	Wodonga - Workshop	Engine\BREATHER	Truck is Dripping oil out of breather		Job for tctc	09/11/2024	73846	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Wodonga Workshop	P/MOVER
1077	Wodonga - Workshop	Steering\OIL LEAK	R/Front Wheel Hub Leaking Since New		Previously completed	09/11/2024	73846	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Wodonga Workshop	P/MOVER
1077	Wodonga - Workshop	Steering\CONSUMABLE	Missing Wheel Nut Covers x3 Steers.			09/11/2024	73846	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Wodonga Workshop	P/MOVER
1077	Wodonga - Workshop	DrCabRep\AIR LEAK	splitter on gear stick air leak		Duplicate job	09/11/2024	73846	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Wodonga Workshop	P/MOVER
1077	Wodonga - Workshop	DrivLine\AIR LEAK	Gear Stick Splitter Air Leak		Warranty	09/11/2024	73846	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Wodonga Workshop	P/MOVER
1077	Wodonga - Workshop	Steering\OIL LEAK	Front RH wheel seal leak		Previously completed	09/11/2024	73846	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Wodonga Workshop	P/MOVER
1077	Wodonga - Workshop	Chassis\WHL HUB	Wheel/Hubseal leak		Duplicate job	09/11/2024	73846	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Wodonga Workshop	P/MOVER
1077	Wodonga - Workshop	Chassis\AIR LEAK	Hall splits button leaking air		Duplicate job	09/11/2024	73846	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Wodonga Workshop	P/MOVER
1077	Wodonga - Workshop	VehService\AS	VehService\AS	VehService\AS	B657Oks	09/11/2024	73846	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Wodonga Workshop	P/MOVER
			A Service												
1077	Wodonga - Workshop	VehService\AS	Serviced @ 80533 Klms	VehService\AS		31/10/2024	73846	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Wodonga Workshop	P/MOVER
1077	Albury - Workshop	Tyres\RUN OUT	Tyres\RUN OUT 9			24/10/2024	73846	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	BEAUREPAIRES - 4	P/MOVER
			B1 Service, A Service With Jack Up Front End & Check & Replace Pollen Filter.												
1077	Wodonga - Workshop	VehService\AS	Serviced @ 73846 Klms	VehService\AS		22/10/2024	73846	Comsleted	Greenfreight Loweine NSW	KW315LOG	Albury	ATK	XW19NG	Wodonaw Workshop	P/MOVER
1077	Wodonga - Workshop	VehService\BS	VehService\BS	VehService\BS	528S6ks	19/09/2024	40785	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Wodonga Workshop	P/MOVER
1077	Wodonga - Workshop	VehService\AS	Service 500Ken Over			19/09/2024	40785	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Wodonga Workshop	P/MOVER
1077	Wodonga - Workshop	VehService\AS	Service Due			19/09/2024	40785	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Wodonga Workshop	P/MOVER
1077	Wodonga - Workshop	VehService\AS	VehService\AS	VehService\AS		19/09/2024	40785	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Wodonga Workshop	P/MOVER
1077	Wodonga - Workshop	VehService\AS	Service due			05/09/2024	40785	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Wodonga Workshop	P/MOVER
1077	Wodonga - Workshop	DrivLine\OIL LEAK	RF wheel hub oil leak			05/09/2024	40785	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Wodonga Workshop	P/MOVER
			VehService\AS												
1077	Wodonga - Workshop	VehService\AS	Serviced @ 40785 Klms	VehService\AS		05/09/2024	40785	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Wodonga Workshop	P/MOVER
1077	Wodonga - Workshop	VehService\AS	SERVICE.			23/08/2024	38018	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Wodonga Workshop	P/MOVER
1077	Wodonga - Workshop	VehService\AS	VehService\AS	VehService\AS		23/08/2024	38018	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Wodonga Workshop	P/MOVER
1077	Wodonga - Workshop	VehService\Unknown	Pre-Delivery Inspection			22/08/2024	20206	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Wodonga Workshop	P/MOVER
1077	Wodonga - Workshop	VehService\AS	VehService\AS			13/08/2024	20206	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Wodonga Workshop	P/MOVER
1077	Albury - Workshop	VehService\CS	First Service (Change All Oils) (TCTC P/O: TQ87744)			27/07/2024	7040	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	TWIN CITY TRUCK CENTRE - OLD	P/MOVER
1077	Albury - Workshop	Tyres\TP9+10	Tyres\TP9+10			27/07/2024	7040	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	BEAUREPAIRES - 4	P/MOVER
1077	Albury - Workshop	Tyres\TP3+4	Tyres\TP3+4			27/07/2024	7040	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	BEAUREPAIRES - 4	P/MOVER
1077	Albury - Workshop	Tyres\TP7+8	Tyres\TP7+8			27/07/2024	7040	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	BEAUREPAIRES - 4	P/MOVER
1077	Albury - Workshop	Tyres\TP5+6	Tyres\TP5+6			27/07/2024	7040	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	BEAUREPAIRES - 4	P/MOVER
					REPLACED BOLT AND TIGHTENED BONNET BLOCK.										
1077	Wodonga - Workshop	Body\PANELS	Adjust Bonnet Blocks		RUBY H ¼ HOUR LABOUR.	26/07/2024	7040	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	Wodonga Workshop	P/MOVER
1077	Albury - Workshop	Tyres\TP04	Tyres\TP04			25/07/2024	1144	Completed	Greenfreight Logging NSW	KW315LOG	Albury	ATK	XW19NG	BEAUREPAIRES - 4	P/MOVER